

**ENVIRONMENTAL
SERVICES FOR
A GREENER
TOMORROW...
ONE STEP AT
A TIME.**



Completion Report for

Kitchen Hood & Exhaust System Cleaning & Degreasing

Date: **12 November 2019**
Client Name: **CAPITAL MOTION**
Contact Person: **Diana Stegarescu**
Designation: **Restaurant Manager**
Site Detail: **Pacifico Tiki Lounge & Dining, Al
Bandar, Abu Dhabi.**





CRYSTALLINE ENVIROMENTAL SERVICES

KITCHEN EXHAUST SYSTEM - AFTER SERVICE REPORT

1335

CUSTOMER: <u>TIKI RESTARANT</u>	CONTACT PERSON: <u>MR-DNIS</u>
SITE DETAILS: <u>CAPITAL MOTION-AD</u>	CONTACT NUMBER: <u>058-9468835</u>
NAME OF KITCHEN: <u>TIKI KITCHEN</u>	LOCATION: <u>AL BANDAR</u>
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL <input type="checkbox"/> HOTEL <input type="checkbox"/> RESIDENCIAL <input checked="" type="checkbox"/> RESTAURANT	
Type & Size of Hood: <u>HORIZONTAL & VERTICAL DUCT CLEANED. 3MT - SINGLE HOOD</u>	
Cooking Volume:	<input type="checkbox"/> Very High <input type="checkbox"/> High <input checked="" type="checkbox"/> Medium <input type="checkbox"/> Low
Type of Filters:	<input checked="" type="checkbox"/> Mesh <input checked="" type="checkbox"/> Baffle <input type="checkbox"/> N/A
Filters in Place:	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> N/A
Filter Cleaning Freq.	<input type="checkbox"/> Daily <input type="checkbox"/> Weekly <input type="checkbox"/> Monthly <input checked="" type="checkbox"/> Not Known

Comments: PLEASE NOTE! HOOD INSIDE UV LIGHTS NOT WORKING & THE EXAHUST FAN SWITCH CONTROL NEED TO KITCHEN INSIDE YOUR EXAHUST FAN CONTROL ROOF HAVE.

FIRE PROTECTION SYSTEM

Kitchen:	<input checked="" type="checkbox"/> Powder <input checked="" type="checkbox"/> CO2 <input type="checkbox"/> Foam <input type="checkbox"/> Other
Cooker Hoods:	<input type="checkbox"/> CO2 <input checked="" type="checkbox"/> Sprinkler <input type="checkbox"/> Dry Powder <input type="checkbox"/> Other
Fire Dampers:	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No Fusible Links: <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No

DUCTWORK

Duct Made of:	<input checked="" type="checkbox"/> Galvanized Steel <input type="checkbox"/> Stainless Steel <input type="checkbox"/> Other
Physical Entry:	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Partly
Access with Tools only:	<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Partly
Vertical Access:	<input type="checkbox"/> Rope access <input checked="" type="checkbox"/> Safety Harness <input type="checkbox"/> N/A
Entire System Cleaned	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No if No, give details

Comments

Doors/Plates Present:	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> No. of doors <input type="checkbox"/> No of Panels
Doors/Plates Installed:	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> No. of doors <input type="checkbox"/> No of Panels

Where Installed:

Duct Size & Approx. Length: <u>15 MT</u>	Insulated: <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No
Condition of Ducts: <input checked="" type="checkbox"/> Clean <input type="checkbox"/> Dirty <input type="checkbox"/> Very Dirty	
Damaged: <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Where <input type="checkbox"/> N/A	
Exhaust Fans: <input type="checkbox"/> Upblast <input checked="" type="checkbox"/> Inline <input type="checkbox"/> Utility <input type="checkbox"/> Others	

Location: 2nd Floor Condition of Roof: NORMAL

LAST CLEANING DATE	CURRENT CLEANING DATE	NEXT CLEANING DATE
	<u>16-11-2019</u>	<u>15-02-2020</u>

CHEMICALS AND EQUIPMENTS USED

<input type="checkbox"/> JETTING MACHINE <input type="checkbox"/> INLET WATER HOSE <input checked="" type="checkbox"/> EXTENTION CORDS <input type="checkbox"/> VACCUM CLEANER
<input checked="" type="checkbox"/> LED LIGHTS <input checked="" type="checkbox"/> PLASTICS ROLL/BAGS <input checked="" type="checkbox"/> SUITABLE PPE <input checked="" type="checkbox"/> DEGREASER CHEMICAL <input checked="" type="checkbox"/> LADDER

COMMENTS AND RECOMMENDATION:
ONE HOOD CLEANING & DISINFECTION COMPLETED. & DUCT CLEANING, SANITIZING AND ESP SYSTEM CLEANED. 3 NOS MESS FILTER CLEANED.

Crystalline Representative: <u>K. ANBAR</u>		Signature: <u>[Signature]</u>
Customer Representative:		Signature: <u>[Signature]</u>

CLEANER WATER GREENER TOMORROW


Web: www.crystalline-uae.com
 E-mail: info@crystalline-uae.com
 Tel.: +971 55 7167017

Kitchen Hood Cleaning- Tiki Kitchen

Before Photo



After Photo



Before Photo




After Photo




Kitchen Hood Cleaning- Tiki Kitchen


Before Photo



After Photo



Before Photo



After Photo





CRYSTALLINE ENVIROMENTAL SERVICES

KITCHEN EXHAUST SYSTEM - AFTER SERVICE REPORT

1336

CUSTOMER: <u>ORNINA RESTARANT</u>		CONTACT PERSON: <u>MR-ANIS</u>	
SITE DETAILS: <u>CAPITAL MOTION-AD</u>		CONTACT NUMBER: <u>058-9468835</u>	
NAME OF KITCHEN: <u>ORNINA KITCHEN</u>		LOCATION: <u>AL BANDAR</u>	
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL <input type="checkbox"/> HOTEL <input type="checkbox"/> RESIDENCIAL <input checked="" type="checkbox"/> RESTAURANT			
Type & Size of Hood: <u>HORIZONTAL & VERTICAL DUCT CLEANED. 3MT SINGLE HOOD & DOUBLE HOOD 1MT</u>			
Cooking Volume:	<input type="checkbox"/> Very High	<input type="checkbox"/> High	<input checked="" type="checkbox"/> Medium <input type="checkbox"/> Low
Type of Filters:	<input checked="" type="checkbox"/> Mesh	<input type="checkbox"/> Baffle	<input type="checkbox"/> N/A
Filters in Place:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input type="checkbox"/> N/A
Filter Cleaning Freq.	<input type="checkbox"/> Daily	<input type="checkbox"/> Weekly	<input type="checkbox"/> Monthly <input checked="" type="checkbox"/> Not Known
Comments: <u>ALL HOODS INSIDE VX LIGHTS NOT WORKING</u>			

FIRE PROTECTION SYSTEM

Kitchen:	<input checked="" type="checkbox"/> Powder	<input checked="" type="checkbox"/> CO2	<input type="checkbox"/> Foam	<input type="checkbox"/> Other
Cooker Hoods:	<input type="checkbox"/> CO2	<input checked="" type="checkbox"/> Sprinkler	<input type="checkbox"/> Dry Powder	<input type="checkbox"/> Other
Fire Dampers:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	Fusible Links:	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No

DUCTWORK

Duct Made of:	<input checked="" type="checkbox"/> Galvanized Steel	<input type="checkbox"/> Stainless Steel	<input type="checkbox"/> Other
Physical Entry:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input type="checkbox"/> Partly
Access with Tools only:	<input type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Partly
Vertical Access:	<input type="checkbox"/> Rope access	<input checked="" type="checkbox"/> Safety Harness	<input type="checkbox"/> N/A
Entire System Cleaned	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No if No, give details	
Comments <u>ESP SYSTEM AND FILTERS CLEANED.</u>			

Doors/Plates Present:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	<input type="checkbox"/> No. of doors	<input type="checkbox"/> No of Panels
Doors/Plates Installed:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	<input type="checkbox"/> No. of doors	<input type="checkbox"/> No of Panels
Where Installed:				

Duct Size & Approx. Length: <u>10 MT</u>	Insulated:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Condition of Ducts:	<input checked="" type="checkbox"/> Clean	<input type="checkbox"/> Dirty	<input type="checkbox"/> Very Dirty
Damaged:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	<input type="checkbox"/> Where <input type="checkbox"/> N/A
Exhaust Fans:	<input type="checkbox"/> Upblast	<input checked="" type="checkbox"/> Inline	<input type="checkbox"/> Utility <input type="checkbox"/> Others
Location: <u>2nd Floor</u>	Condition of Roof: <u>NORMAL</u>		

LAST CLEANING DATE	CURRENT CLEANING DATE	NEXT CLEANING DATE
	<u>17-11-2019</u>	<u>16-02-2020</u>

CHEMICALS AND EQUIPMENTS USED

<input type="checkbox"/> JETTING MACHINE	<input type="checkbox"/> INLET WATER HOSE	<input checked="" type="checkbox"/> EXTENTION CORDS	<input type="checkbox"/> VACCUM CLEANER
<input checked="" type="checkbox"/> LED LIGHTS	<input checked="" type="checkbox"/> PLASTICS ROLL/BAGS	<input checked="" type="checkbox"/> SUITABLE PPE	<input checked="" type="checkbox"/> DEGREASER CHEMICAL
<input checked="" type="checkbox"/> LADDER			

COMMENTS AND RECOMMENDATION: 2 NOS KITCHEN HOODS CLEANED HORIZONTAL & VERTICAL DUCT CLEANED. ALL FILTERS CLEANED.

Pacifico Tiki
 Goods Received
 Verified & Invoice Corrected
 By:.....
 Date:.....

Crystalline Representative: <u>KANSARI</u>	Signature: <u>[Signature]</u>
Customer Representative:	Signature: <u>[Signature]</u>

Kitchen Hood Cleaning- Ornina Kitchen

Before Photo



After Photo



Before Photo




After Photo




Kitchen Hood Cleaning- Ornina Kitchen

Before Photo




After Photo



Before Photo



After Photo





CRYSTALLINE ENVIROMENTAL SERVICES

KITCHEN EXHAUST SYSTEM - AFTER SERVICE REPORT

1337

CUSTOMER: <u>ORNINA RESTARANT</u>	CONTACT PERSON: <u>MR. ANIS</u>
SITE DETAILS: <u>CAPITAL MOTION-AD</u>	CONTACT NUMBER: <u>058-9468835</u>
NAME OF KITCHEN: <u>ORNINA KITCHEN</u>	LOCATION: <u>1ST FLOOR</u>
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL <input type="checkbox"/> HOTEL <input type="checkbox"/> RESIDENCIAL <input checked="" type="checkbox"/> RESTAURANT	
Type & Size of Hood: <u>3MT SINGLE HOOD AND 1MT DOUBLE HOOD</u>	
Cooking Volume:	<input type="checkbox"/> Very High <input type="checkbox"/> High <input checked="" type="checkbox"/> Medium <input type="checkbox"/> Low
Type of Filters:	<input checked="" type="checkbox"/> Mesh <input checked="" type="checkbox"/> Baffle <input type="checkbox"/> N/A
Filters in Place:	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> N/A
Filter Cleaning Freq.	<input type="checkbox"/> Daily <input type="checkbox"/> Weekly <input type="checkbox"/> Monthly <input checked="" type="checkbox"/> Not Known
Comments: <u>ESP SYSTEM AND ESP FILTERS CLEANED - MESS FILTERS CLEANED -</u>	

FIRE PROTECTION SYSTEM

Kitchen:	<input checked="" type="checkbox"/> Powder <input checked="" type="checkbox"/> CO2 <input type="checkbox"/> Foam <input type="checkbox"/> Other
Cooker Hoods:	<input type="checkbox"/> CO2 <input checked="" type="checkbox"/> Sprinkler <input type="checkbox"/> Dry Powder <input type="checkbox"/> Other
Fire Dampers:	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No Fusible Links: <input type="checkbox"/> Yes <input type="checkbox"/> No

DUCTWORK

Duct Made of:	<input checked="" type="checkbox"/> Galvanized Steel <input type="checkbox"/> Stainless Steel <input type="checkbox"/> Other
Physical Entry:	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Partly
Access with Tools only:	<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Partly
Vertical Access:	<input type="checkbox"/> Rope access <input checked="" type="checkbox"/> Safety Harness <input type="checkbox"/> N/A
Entire System Cleaned	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No if No, give details

Comments VERTICAL & HORIZONTAL DOCT CLEANED.

Doors/Plates Present:	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> No. of doors <input type="checkbox"/> No of Panels
Doors/Plates Installed:	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> No. of doors <input type="checkbox"/> No of Panels

Where Installed:

Duct Size & Approx. Length: <u>10MT</u>	Insulated: <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No
Condition of Ducts: <input checked="" type="checkbox"/> Clean	<input type="checkbox"/> Dirty <input type="checkbox"/> Very Dirty
Damaged: <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	<input type="checkbox"/> Where <input type="checkbox"/> N/A
Exhaust Fans: <input type="checkbox"/> Upblast <input checked="" type="checkbox"/> Inline	<input type="checkbox"/> Utility <input type="checkbox"/> Others

Location: Condition of Roof:

LAST CLEANING DATE	CURRENT CLEANING DATE	NEXT CLEANING DATE
	<u>18-11-2019</u>	<u>17-02-2020</u>

CHEMICALS AND EQUIPMENTS USED

<input type="checkbox"/> JETTING MACHINE	<input type="checkbox"/> INLET WATER HOSE	<input checked="" type="checkbox"/> EXTENTION CORDS	<input type="checkbox"/> VACCUM CLEANER
<input checked="" type="checkbox"/> LED LIGHTS	<input checked="" type="checkbox"/> PLASTICS ROLL/BAGS	<input checked="" type="checkbox"/> SUITABLE PPE	<input checked="" type="checkbox"/> DEGREASER CHEMICAL
<input checked="" type="checkbox"/> LADDER			

COMMENTS AND RECOMMENDATION: ALL HOODS & DUCTS CLEANED. ESP SYSTEM AND FILTERS CLEANED. MESS FILTERS CLEANED.

Crystalline Representative: <u>K. ANSARI</u>	Signature: <u>[Signature]</u>
Customer Representative:	Signature: <u>[Signature]</u>



Kitchend Exhaust System Cleaning

Before Photo



After Photo



Before Photo



After Photo




Kitchend Exhaust System Cleaning

Before Photo



After Photo



Before Photo



After Photo



Kitchend Exhaust System Cleaning

Before Photo



After Photo



Before Photo



After Photo



Kitchend Exhaust System Cleaning

Before Photo



After Photo



Before Photo



After Photo



CRYSTALLINE CLEANING & ENVIRONMENTAL SERVICES

KITCHEN HOOD CLEANING AND DEGREASING

CLIENT NAME : CAPITAL MOTION
CONTACT PERSON : DIANA STEGARESCU
DESIGNATION : RESTAURANT MANAGER
SITE DETAILS : PACIFICO TIKI LOUNGE & DINING, AL BANDAR, ABU DHABI.
DETAILS : KITCHEN HOOD & EXHAUST SYSTEM CLEANING & DEGREASING
DATE OF CLEANING : 16-18 NOVEMBER 2019
FREQUENCY OF CLEANING : HALF YEARLY
DATE OF NEXT CLEANING : 16 MAY 2020

The above kitchen were cleaned in accordance with NFPA 96 Standard for Ventilation Control and Fire Protection of Commercial Cooking Operations.

The kitchen exhaust systems must be cleaned and degreased every Six-Monthly.



Tasman Pinto

CRYSTALLINE CLEANING AND ENVIRONMENTAL SERVICES