

SEWAGE SUMP PIT TANK & GREASE TRAP CLEANING

COMPLETION REPORT

For



Client : EMRILL FACILITY MGT.
Contact Person: Mr. Sulfikkar A. Salam
Asst. Manager - Facilities
Site Details : The Wave Tower, Abu Dhabi
Date : 15 January 2019

Crystalline environmental Services
P.O. Box 131463, Abu Dhabi, U.A.E.
Tel: 02 6508930 Fax: 02 6508942
info@crystalline-uac.com
www.crystalline-uac.com



CRYSTALLINE
ENVIRONMENTAL SERVICES



CRYSTALLINE ENVIRONMENTAL SERVICES

1106

MANHOLE, GULLY TRAP, DRAINAGE - AFTER SERVICE REPORT

CUSTOMER: <u>EMRILL</u>	CONTACT PERSON: <u>Mr IMRAN</u>
SITE DETAILS: <u>WAVE TOWER</u>	CONTACT NUMBER: <u>055 409 8909</u>
NAME OF MANHOLE: <u>GREASE TRAP</u>	LOCALISATION: <u>GROUND FLOOR</u>
TYPE OF BUILDING: <input checked="" type="checkbox"/> COMMERCIAL <input type="checkbox"/> EDUCATIONAL <input type="checkbox"/> RESIDENCIAL <input type="checkbox"/> INDUSTRIAL	

PART OF DRAINAGE

MANHOLE UNDERGROUND DRAINAGE PIPE GULLY TRAP GREASE TRAP

DRAINAGE PIPE APPARENT DRAINAGE PIPE EMBEDDED DRAINAGE PIPE

CONDITION OF MANHOLE, GULLY TRAP, DRAINAGE BEFORE CLEANING

LITTLE DIRTY DIRTY VERY DIRTY RUST SEDIMENTS MUD

BIOFILMS SLIME GREASE ROOT SAND MOULDS

OBSTRUCT BLOCK FLUENT FLOW LOW FLOW ANOTHER: TISSUS

MANHOLE BLOCKED	GULLY TRAP BLOCKED	DRAINAGE BLOCKED	ALL BLOCKED
<input type="checkbox"/> YES <input type="checkbox"/> NO			

COMMENTS: We found the pieces of tissues inside the grease trap.

MANHOLE AND GULLY TRAP COVER: COVERED DAMAGED BLOCKED ADAPTED

CONDITION OF MANHOLE, GULLY TRAP, DRAINAGE AFTER CLEANING

LITTLE CLEAN CLEAN VERY CLEAN FLUENT FLOW LOW FLOW UNBLOCK

	MANHOLE	GULLY TRAP	STORM WATER	DRAINAGE	TOTAL
NUMBER OF MANHOLE CLEANED	<u>01</u>	<u>-</u>	<u>-</u>	<u>-</u>	<u>01</u>
NUMBER OF MANHOLE BLOCKED	<u>-</u>	<u>-</u>	<u>-</u>	<u>-</u>	<u>-</u>

ACCESS

LADDER IN NO LADDER

MANHOLE CLEANED	GULLY TRAP CLEANED	DRAINAGE CLEANED	ALL DISINFECTED
<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES <input type="checkbox"/> NO	<input type="checkbox"/> YES <input type="checkbox"/> NO

SERVICES OF DATES

LAST CLEANING DATE	LAST CLEANING DATE	LAST CLEANING DATE
	<u>12-01-2019</u>	<u>12-07-2019</u>

CHEMICALS AND EQUIPMENTS USED

PRESSURE MACHINE JETTING MACHINE MULTIGAS DETECTEUR INLET WATER HOSE

EXTENTION CORDS VACCUM CLEANER VENTILATION FAN CLEANING MAT

LED LIGHTS PLASTICS ROLL PLASTICS BAGS SUITABLE PPE

TRIPOD AIR REPAIR 7D-A DEGREASER CHEMICAL LADDER

COMMENTS AND RECOMMENDATION:

Grease trap has been cleaned

Crystalline representative: <u>Patrick</u>	Signature:
Customer/Customer representative: <u>Patrick</u>	Signature:

Date of Cleaning: 12-01-2019

PHOTOGRAPHS
GREASE TRAP CLEANING – 01 WAVE TOWER

BEFORE CLEANING



AFTER CLEANING





CRYSTALLINE ENVIRONMENTAL SERVICES

1107

MANHOLE, GULLY TRAP, DRAINAGE - AFTER SERVICE REPORT

CUSTOMER: <u>EMRILL</u>	CONTACT PERSON: <u>Mr IMRAN</u>
SITE DETAILS: <u>WAVE TOWER</u>	CONTACT NUMBER: <u>055 109 89 02</u>
NAME OF MANHOLE: <u>GREASE TRAP</u>	LOCALISQTION: <u>GROUND FLOOR</u>
TYPE OF BUILDING: <input checked="" type="checkbox"/> COMMERCIAL <input type="checkbox"/> EDUCATIONAL <input type="checkbox"/> RESIDENCIAL <input type="checkbox"/> INDUSTRIAL	

PART OF DRAINAGE

MANHOLE UNDERGROUND DRAINAGE PIPE GULLY TRAP GREASE TRAP

DRAINAGE PIPE APPARENT DRAINAGE PIPE EMBEDDED DRAINAGE PIPE

CONDITION OF MANHOLE, GULLY TRAP, DRAINAGE BEFORE CLEANING

LITTLE DIRTY DIRTY VERY DIRTY RUST SEDIMENTS MUD

BIOFILMS SLIME GREASE ROOT SAND MOULDS

OBSTRUCT BLOCK FLUENT FLOW LOW FLOW ANOTHER: TISSUS

MANHOLE BLOCKED	GULLY TRAP BLOCKED	DRAINAGE BLOCKED	ALL BLOCKED
<input type="checkbox"/> YES <input type="checkbox"/> NO			

COMMENTS:

We found some tissues inside the grease trap.

MANHOLE AND GULLY TRAP COVER: COVERED DAMAGED BLOCKED ADAPTED

CONDITION OF MANHOLE, GULLY TRAP, DRAINAGE AFTER CLEANING

LITTLE CLEAN CLEAN VERY CLEAN FLUENT FLOW LOW FLOW UNBLOCK

	MANHOLE	GULLY TRAP	STORM WATER	DRAINAGE	TOTAL
NUMBER OF MANHOLE CLEANED	<u>01</u>	<u>-</u>	<u>-</u>	<u>-</u>	<u>01</u>
NUMBER OF MANHOLE BLOCKED	<u>-</u>	<u>-</u>	<u>-</u>	<u>-</u>	<u>-</u>

ACCESS

LADDER IN NO LADDER

MANHOLE CLEANED	GULLY TRAP CLEANED	DRAINAGE CLEANED	ALL DISINFECTED
<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES <input type="checkbox"/> NO	<input type="checkbox"/> YES <input type="checkbox"/> NO

SERVICES OF DATES

LAST CLEANING DATE	LAST CLEANING DATE	LAST CLEANING DATE
	<u>12-01-2019</u>	<u>12-07-2019</u>

CHEMICALS AND EQUIPMENTS USED

PRESSURE MACHINE JETTING MACHINE MULTIGAS DETECTEUR INLET WATER HOSE

EXTENTION CORDS VACCUM CLEANER VENTILATION FAN CLEANING MAT

LED LIGHTS PLASTICS ROLL PLASTICS BAGS SUITABLE PPE

TRIPOD AIR REPAIR 7D-A DEGREASER CHEMICAL LADDER

COMMENTS AND RECOMMENDATION:

Grease trap has been cleaned

Crystalline representative: <u>Patrick</u>	Signature:
Customer/Customer representative: <u>Nithin K</u>	Signature:

Date of Cleaning: 12-01-2019

PHOTOGRAPHS
GREASE TRAP CLEANING – 02

BEFORE CLEANING



AFTER CLEANING





CRYSTALLINE ENVIRONMENTAL SERVICES

1109

MANHOLE, GULLY TRAP, DRAINAGE - AFTER SERVICE REPORT

CUSTOMER: <u>EMRILL</u>	CONTACT PERSON: <u>Mr IMRAN</u>
SITE DETAILS: <u>WAVE TOWER</u>	CONTACT NUMBER: <u>055 109 8902</u>
NAME OF MANHOLE: <u>SEWAGE</u>	LOCALISQTION: <u>BASEMENT #02</u>
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL <input type="checkbox"/> EDUCATIONAL <input type="checkbox"/> RESIDENCIAL <input type="checkbox"/> INDUSTRIAL	

PART OF DRAINAGE

MANHOLE UNDERGROUND DRAINAGE PIPE GULLY TRAP GREASE TRAP

DRAINAGE PIPE APPARENT DRAINAGE PIPE EMBEDDED DRAINAGE PIPE

CONDITION OF MANHOLE, GULLY TRAP, DRAINAGE BEFORE CLEANING

LITTLE DIRTY DIRTY VERY DIRTY RUST SEDIMENTS MUD

BIOFILMS SLIME GREASE ROOT SAND MOULDS

OBSTRUCT BLOCK FLUENT FLOW LOW FLOW ANOTHER: _____

MANHOLE BLOCKED	GULLY TRAP BLOCKED	DRAINAGE BLOCKED	ALL BLOCKED
<input type="checkbox"/> YES <input type="checkbox"/> NO			

COMMENTS: the Pipe of the pump No 01 it's either crack or screwed incorrectly. it rejects the water.

MANHOLE AND GULLY TRAP COVER: COVERED DAMAGED BLOCKED ADAPTED

CONDITION OF MANHOLE, GULLY TRAP, DRAINAGE AFTER CLEANING

LITTLE CLEAN CLEAN VERY CLEAN FLUENT FLOW LOW FLOW UNBLOCK

	MANHOLE	GULLY TRAP	STORM WATER	DRAINAGE	TOTAL
NUMBER OF MANHOLE CLEANED	<u>01</u>	<u>/</u>	<u>/</u>	<u>/</u>	<u>01</u>
NUMBER OF MANHOLE BLOCKED	<u>/</u>	<u>/</u>	<u>/</u>	<u>/</u>	<u>/</u>

ACCESS

LADDER IN NO LADDER

MANHOLE CLEANED	GULLY TRAP CLEANED	DRAINAGE CLEANED	ALL DISINFECTED
<input type="checkbox"/> YES <input type="checkbox"/> NO			

SERVICES OF DATES

LAST CLEANING DATE	LAST CLEANING DATE	LAST CLEANING DATE
	<u>12-01-2019</u>	<u>12-07-2019</u>

CHEMICALS AND EQUIPMENTS USED

<input checked="" type="checkbox"/> PRESSURE MACHINE	<input checked="" type="checkbox"/> JETTING MACHINE	<input checked="" type="checkbox"/> MULTIGAS DETECTEUR	<input checked="" type="checkbox"/> INLET WATER HOSE
<input checked="" type="checkbox"/> EXTENTION CORDS	<input checked="" type="checkbox"/> VACCUM CLEANER	<input checked="" type="checkbox"/> VENTILATION FAN	<input checked="" type="checkbox"/> CLEANING MAT
<input checked="" type="checkbox"/> LED LIGHTS	<input checked="" type="checkbox"/> PLASTICS ROLL	<input checked="" type="checkbox"/> PLASTICS BAGS	<input checked="" type="checkbox"/> SUITABLE PPE
<input checked="" type="checkbox"/> TRIPOD	<input checked="" type="checkbox"/> AIR REPAIR 7D-A	<input checked="" type="checkbox"/> DEGREASER CHEMICAL	<input checked="" type="checkbox"/> LADDER

COMMENTS AND RECOMMENDATION:

We mention that the sewage has been cleaned

Crystalline representative: <u>Patrick</u>	Signature:
Customer/Customer representative: <u>Nithin-k</u>	Signature:


Date of Cleaning: 12-01-2019

**PHOTOGRAPHS
SEWAGE CLEANING**

BEFORE CLEANING



AFTER CLEANING





CRYSTALLINE ENVIRONMENTAL SERVICES

1108

MANHOLE, GULLY TRAP, DRAINAGE - AFTER SERVICE REPORT

CUSTOMER: <u>EMRILL</u>	CONTACT PERSON: <u>Mr IRAN</u>
SITE DETAILS: <u>WAVE TOWER</u>	CONTACT NUMBER: <u>055 109 89 02</u>
NAME OF MANHOLE: <u>SUMP PIT</u>	LOCALISQTION: <u>BASEMENT#01</u>
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL <input type="checkbox"/> EDUCATIONAL <input type="checkbox"/> RESIDENCIAL <input type="checkbox"/> INDUSTRIAL	

PART OF DRAINAGE

MANHOLE UNDERGROUND DRAINAGE PIPE GULLY TRAP GREASE TRAP

DRAINAGE PIPE APPARENT DRAINAGE PIPE EMBEDDED DRAINAGE PIPE

CONDITION OF MANHOLE, GULLY TRAP, DRAINAGE BEFORE CLEANING

LITTLE DIRTY DIRTY VERY DIRTY RUST SEDIMENTS MUD

BIOFILMS SLIME GREASE ROOT SAND MOULDS

OBSTRUCT BLOCK FLUENT FLOW LOW FLOW ANOTHER: _____

MANHOLE BLOCKED	GULLY TRAP BLOCKED	DRAINAGE BLOCKED	ALL BLOCKED
<input type="checkbox"/> YES <input type="checkbox"/> NO			

COMMENTS:

Very dirty.

MANHOLE AND GULLY TRAP COVER: COVERED DAMAGED BLOCKED ADAPTED

CONDITION OF MANHOLE, GULLY TRAP, DRAINAGE AFTER CLEANING

LITTLE CLEAN CLEAN VERY CLEAN FLUENT FLOW LOW FLOW UNBLOCK

	MANHOLE	GULLY TRAP	STORM WATER	DRAINAGE	TOTAL
NUMBER OF MANHOLE CLEANED	<u>01</u>	<u>/</u>	<u>/</u>	<u>/</u>	<u>01</u>
NUMBER OF MANHOLE BLOCKED	<u>/</u>	<u>/</u>	<u>/</u>	<u>/</u>	<u>/</u>

ACCESS

LADDER IN NO LADDER

MANHOLE CLEANED	GULLY TRAP CLEANED	DRAINAGE CLEANED	ALL DISINFECTED
<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES <input type="checkbox"/> NO	<input type="checkbox"/> YES <input type="checkbox"/> NO

SERVICES OF DATES

LAST CLEANING DATE	LAST CLEANING DATE	LAST CLEANING DATE
	<u>12-01-2019</u>	<u>12-07-2019</u>

CHEMICALS AND EQUIPMENTS USED

PRESSURE MACHINE JETTING MACHINE MULTIGAS DETECTEUR INLET WATER HOSE

EXTENTION CORDS VACCUM CLEANER VENTILATION FAN CLEANING MAT

LED LIGHTS PLASTICS ROLL PLASTICS BAGS SUITABLE PPE

TRIPOD AIR REPAIR 7D-A DEGREASER CHEMICAL LADDER

COMMENTS AND RECOMMENDATION:


Sump Pit has been cleaned

Crystalline representative: <u>Patrick</u>	Signature:
Customer/Customer representative: <u>Althina</u>	Signature:

Date of Cleaning: 12-01-2019

PHOTOGRAPHS
SUMP PIT CLEANING

BEFORE CLEANING



AFTER CLEANING



CLEANER WATER GREENER TOMORROW

CRYSTALLINE CLEANING & ENVIRONMENTAL SERVICES

CLEANING & DISINFECTION CERTIFICATE

CLIENT NAME : EMRILL FACILITY MANAGEMENT.
CLIENT ADDRESS : P.O. BOX: 108388, ABU DHABI, UAE.
CONTACT PERSON : MR. SULFIKKAR A. SALAM.
SITE DETAILS : THE WAVE TOWER, ABU DHABI, UAE.
DETAILS : SEWAGE & GREASE TRAP CLEANING
DATE OF CLEANING : 12 JANUARY 2019
FREQUENCY OF CLEANING : EVERY SIX (6) MONTHS
DATE OF NEXT CLEANING : 12 JULY 2019

The procedures employed in this cleaning and disinfection comply with Abu Dhabi Municipality guidelines

The entire Sewage & Grease Trap should be cleaned and disinfected minimum every six (6) months depending upon the condition.



CRYSTALLINE CLEANING AND ENVIRONMENTAL SERVICES