

SEWAGE SUMP PIT TANK CLEANING

COMPLETION REPORT

For



Client : COFELY BESIX FACILITY
MANAGEMENT
Contact Person: Mr. Brilliant Skaria
MEP Team Leader
Site Details : Emirates Sky Cargo,
Dubai, UAE
Date : 10 JANUARY 2019



CRYSTALLINE
ENVIRONMENTAL SERVICES

Crystalline environmental Services

P.O. Box 131463, Abu Dhabi, U.A.E.

Tel: 02 6508930 Fax: 02 6508942

info@crystalline-uae.com

www.crystalline-uae.com



CRYSTALLINE ENVIRONMENTAL SERVICES

1105

MANHOLE, GULLY TRAP, DRAINAGE - AFTER SERVICE REPORT

CUSTOMER: COFELY BESIX	CONTACT PERSON: Mr BRILLIANT
SITE DETAILS: SKY CARGO DUBAI	CONTACT NUMBER: 050 550 0473
NAME OF MANHOLE: SEWAGE	LOCALISQTION: UNDERGROUND
TYPE OF BUILDING: <input checked="" type="checkbox"/> COMMERCIAL <input type="checkbox"/> EDUCATIONAL <input type="checkbox"/> RESIDENCIAL <input type="checkbox"/> INDUSTRIAL	

PART OF DRAINAGE

MANHOLE UNDERGROUND DRAINAGE PIPE GULLY TRAP GREASE TRAP

DRAINAGE PIPE APPARENT DRAINAGE PIPE EMBEDDED DRAINAGE PIPE

CONDITION OF MANHOLE, GULLY TRAP, DRAINAGE BEFORE CLEANING

LITTLE DIRTY DIRTY VERY DIRTY RUST SEDIMENTS MUD

BIOFILMS SLIME GREASE ROOT SAND MOULDS

OBSTRUCT BLOCK FLUENT FLOW LOW FLOW ANOTHER: TISSUES

MANHOLE BLOCKED	GULLY TRAP BLOCKED	DRAINAGE BLOCKED	ALL BLOCKED
<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input type="checkbox"/> YES <input type="checkbox"/> NO	<input type="checkbox"/> YES <input type="checkbox"/> NO	<input type="checkbox"/> YES <input type="checkbox"/> NO

COMMENTS:

Sewage has been Flow Because submersible pump didn't work

MANHOLE AND GULLY TRAP COVER: COVERED DAMAGED BLOCKED ADAPTED

CONDITION OF MANHOLE, GULLY TRAP, DRAINAGE AFTER CLEANING

LITTLE CLEAN CLEAN VERY CLEAN FLUENT FLOW LOW FLOW UNBLOCK

	MANHOLE	GULLY TRAP	STORM WATER	DRAINAGE	TOTAL
NUMBER OF MANHOLE CLEANED	01	/	/	/	01
NUMBER OF MANHOLE BLOCKED	01	/	/	/	01

ACCESS

LADDER IN NO LADDER

MANHOLE CLEANED	GULLY TRAP CLEANED	DRAINAGE CLEANED	ALL DISINFECTED
<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input type="checkbox"/> YES <input type="checkbox"/> NO	<input type="checkbox"/> YES <input type="checkbox"/> NO	<input type="checkbox"/> YES <input type="checkbox"/> NO

SERVICES OF DATES

LAST CLEANING DATE	LAST CLEANING DATE	LAST CLEANING DATE
	03-01-19	03-07-19

CHEMICALS AND EQUIPMENTS USED

PRESSURE MACHINE JETTING MACHINE MULTIGAS DETECTEUR INLET WATER HOSE

EXTENTION CORDS VACCUM CLEANER VENTILATION FAN CLEANING MAT

LED LIGHTS PLASTICS ROLL PLASTICS BAGS SUITABLE PPE

TRIPOD AIR REPAIR 7D-A DEGREASER CHEMICAL LADDER

COMMENTS AND RECOMMENDATION:

Sewage has been cleaned properly

Crystalline representative: Patrick	Signature:
Customer/Customer representative: Brilliant Skaria	Signature:

Date of Cleaning: 03-01-2019

PHOTOGRAPHS
SEWAGE CLEANING – EMIRATES SKY CARGO

BEFORE CLEANING



AFTER CLEANING





CRYSTALLINE
ENVIRONMENTAL SERVICES

Date of Cleaning: 03-01-2019

PHOTOGRAPHS
SEWAGE CLEANING – EMIRATES SKY CARGO

BEFORE CLEANING



AFTER CLEANING



CLEANER WATER GREENER TOMORROW

CRYSTALLINE CLEANING & ENVIRONMENTAL SERVICES

CLEANING & DISINFECTION CERTIFICATE

SUMP PIT TANKS

CLIENT NAME : COFELY BESIX FACILITY MANAGEMENT.
CLIENT ADDRESS : P.O. BOX: 391055, DUBAI, UAE.
CONTACT PERSON : MR. BRILLIANT SKARIA.
SITE DETAILS : EMIRATES SKY CARGO, DUBAI, UAE.
DETAILS : SEWERAGE SUMP PIT CLEANING
DATE OF CLEANING : 03 JANUARY 2019
FREQUENCY OF CLEANING : EVERY SIX MONTHS
DATE OF NEXT CLEANING : 03 JULY 2019

The procedures employed in this cleaning and disinfection comply with HS (G) 70 health and safety guidelines for prevention of legionella as well as BS6700 and CARELA BIO PLUS method statement.

The entire Sewerage Sump Pit tank should be cleaned and disinfected minimum every six (6) months depending upon the condition.



CRYSTALLINE CLEANING AND ENVIRONMENTAL SERVICES