

# EMERGENCY WATER SUPPLY

At

# HEALTHPOINT HOSPITAL

Client : EFS Facility Management

Contact Person : Mr. Anjaneyamoorthi  
Operation Engineer

Site Details : Healthpoint Hospital Abu Dhabi

Month : Nov 2020



**CRYSTALLINE**  
ENVIRONMENTAL SERVICES

## Crystalline Environmental Services

P.O. Box 131463, Abu Dhabi, U.A.E.

Tel: 02 6508930 Fax: 02 6508942

[info@crystalline-uae.com](mailto:info@crystalline-uae.com)

[www.crystalline-uae.com](http://www.crystalline-uae.com)






**Statement of Work:**

<b>Activity</b>	<b>Date &amp; Timing</b>	<b>Comments &amp; Taken action</b>
Healthpoint Requisition	26/Nov/20 08:15 AM	We (Crystalline) received a request from Healthpoint facility management for providing water as an emergency; because they face water lack on the time.
Portable water arrangement	26/Nov/20 08:25 AM	We arranged water delivery by portable water tanker (5000 US gallon). Ref Picture#1
Onsite Water test	26/Nov/20 08:30 AM	Before filling the portable water from tanker to main tank; we tested the tanker water quality at onsite. The chlorine test results are in acceptable range and they confirm us to fill the water to main tanks. Ref Picture#2
Laboratory water test	26/Nov/20 08:35 AM	We collected the water samples for Microbiological test at laboratory house. Ref Picture#3 & Ref Picture#4
Water sample transport	26/Nov/20 08:40 AM	We stored the collected samples in the container and sent it our laboratory house. Ref Picture#4
Pre-work of water transfer	26/Nov/20 08:50 AM	We set of the tanker as much nearer to the ADDC source point (Manhole) and extended the tanker's connection hose for water flushing. Ref Picture#5
Water flushing	26/Nov/20 08:55 AM	We flushed 10 minutes continuously from the tanker hose at before connecting the tanker's hose to main water line. Ref Picture#6
Water hose connection with Mainline	26/Nov/20 09:05 AM	We close the ADDC main water valve and then connected the portable water with ADDC mainline from tanker by the tanker's hose. 5000 gallon of water is transferred to main water tank – 3 & 4. Ref Picture#7
Hose Disconnection	26/Nov/20 09:10 AM	We removed the connected tanker's hose from the mainline and restore the ADDC water supply. Ref Picture#8
End of Session	26/Nov/20 09:15 AM	We confirmed the water supply from the ADDC main water source with presence of Healthpoint team and closed the water manhole properly. Ref Picture#9



**CRYSTALLINE**  
ENVIRONMENTAL SERVICES

PICTURE # 1 (Water tanker parked at designated area)



PICTURE # 02 (Onsite Chlorine Test)



P.O. Box 131463, Abu Dhabi, U.A.E  
Tel: 02 6508930 Fax: 02 6508942

**CLEANER WATER GREENER TOMORROW**

PICTURE # 3(Water Sample taken)



PICTURE # 04 (Water Sample Collected)






**CRYSTALLINE**  
ENVIRONMENTAL SERVICES

PICTURE # 4 (Collected Sample kept in cool box)



PICTURE # 05 (Discharge Hose Connected)



---

P.O. Box 131463, Abu Dhabi, U.A.E  
Tel: 02 6508930 Fax: 02 6508942

**CLEANER WATER GREENER TOMORROW**




**CRYSTALLINE**  
ENVIRONMENTAL SERVICES

PICTURE # 6 (Discharge hose flushed with water)



PICTURE# 07 (Hose Connected for supply of Water)



---

P.O. Box 131463, Abu Dhabi, U.A.E  
Tel: 02 6508930 Fax: 02 6508942

**CLEANER WATER GREENER TOMORROW**



**CRYSTALLINE**  
ENVIRONMENTAL SERVICES

PICTURE # 08 (Water Meter)



PICTURE # 09 (After Water Supply)



---

P.O. Box 131463, Abu Dhabi, U.A.E  
Tel: 02 6508930 Fax: 02 6508942

**CLEANER WATER GREENER TOMORROW**