



# CRYSTALLINE ENVIRONMENTAL SERVICES

## CONSULTING TEST REPORT

Client Name: Serco Middle East, Abudhabi			
Site Name:	Rihan Heights	Visit Date:	01-05-2021
Source Of Sample	Swimming Pool	Sample Point	Main Swimming Pool

### SWIMMING POOL ANALYSIS

No	Parameter	Control limits	Test Results
1	pH at 25°C	7.2 - 7.6	7.40
2	Conductivity at 25°C, µs/cm	---	1157
3	TDS, ppm	Max 1500	752
4	Alkalinity	80 - 120	96
5	Calcium Hardness	200 - 500	242
6	Residual Chlorine	1.0 - 3.0	1.36
7	Cyanuric Acid	20 - 60	22
8	Dip slide	<10 <sup>3</sup>	ND

\*\*\* All test results expressed in parts per million (ppm) as CaCO<sub>3</sub> except pH and conductivity (µmhos).

### COMMENTS AND RECOMMENDATIONS

- All Parameters are within control limit – No action Recommended.

Reported By,

Murugaraaj  
Service Engineer

