

**ENVIRONMENTAL
SERVICES FOR
A GREENER
TOMORROW...
ONE STEP AT
A TIME.**



Completion Report for
Water Tank Cleaning & Disinfection

Date: **13 December 2019**
Client Name: **EFS Facilities Services**
Contact Person: **Manjunath Prabhu**
Designation: **Supervisor**
Site Detail: **Crew Briefing Center**



Address: PO BOX 131463, Abu Dhabi, UAE | Phone: +971 2 650 8930, +971 55 716 7017
E-mail: info@crystalline-uae.com | Website: www.crystalline-uae.com

Customer: EFS Facilities Services		Contact Person: Manjunath Prabhu	
Site: Crew Briefing Center/ Etihad Airways Lounge		Contact Number: 0528735384	
Description: GRP Water Tank 1		Location: Airside, Ground level	
Type Of Building :		<input checked="" type="checkbox"/> Commercial	<input type="checkbox"/> Residential <input type="checkbox"/> Others
Type Of Tank			
<input type="checkbox"/> Concrete	<input checked="" type="checkbox"/> GRP Panel	<input type="checkbox"/> FRP Tank	<input type="checkbox"/> Galvanized
<input type="checkbox"/> Steel Panel	<input type="checkbox"/> Plastic	<input type="checkbox"/> Concrete Coated	<input type="checkbox"/> Polyurethane
<input type="checkbox"/> Others			
Condition before cleaning		Condition after cleaning	
<input type="checkbox"/> Clean	<input checked="" type="checkbox"/> Dirty	<input type="checkbox"/> Very Dirty	<input checked="" type="checkbox"/> Clean
<input type="checkbox"/> Biofilms	<input type="checkbox"/> Moulds	<input type="checkbox"/> Slime	<input type="checkbox"/> Dirty
<input type="checkbox"/> Sediments	<input type="checkbox"/> Mud & Sand	<input type="checkbox"/> Rust	<input type="checkbox"/> Very Dirty
			<input type="checkbox"/> Biofilms
			<input type="checkbox"/> Moulds
			<input type="checkbox"/> Slime
			<input type="checkbox"/> Sediments
			<input type="checkbox"/> Mud & Sand
			<input type="checkbox"/> Rust
Size of Tank			
M3:		USG:	L*B*H:
Quantity Of Water		Manhole	
<input type="checkbox"/> Full	<input checked="" type="checkbox"/> Half	<input type="checkbox"/> Empty	<input type="checkbox"/> Covered
			<input type="checkbox"/> Damaged
			<input checked="" type="checkbox"/> NA
Ladder In		Ladder Out	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Drain Line		Valves	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Tank Cleaned		Tank Disinfected	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
		Pipes Disinfected	
		<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Chemicals Used			
Chemical: Carela bio		Quantity: 250ml	
Chemical: Carela plus		Quantity: 250ml	
Equipments Used			
<input checked="" type="checkbox"/> Submersibel Pump	<input checked="" type="checkbox"/> High/low Pressure Jet	<input checked="" type="checkbox"/> Extension Cords	<input checked="" type="checkbox"/> LED Lights
<input checked="" type="checkbox"/> Foot Bath	<input checked="" type="checkbox"/> Ladder	<input checked="" type="checkbox"/> Ventilating Fan	<input checked="" type="checkbox"/> Oxygen Meter
<input checked="" type="checkbox"/> Vacuum Cleaner	<input checked="" type="checkbox"/> Cleaning Materials	<input checked="" type="checkbox"/> Suction/Discharge Hoses	
Last Cleaning Date		Current Cleaning Date	
-		12 December 2019	
		Next Cleaning Date	
		12 June 2020	
Crystalline Representative		Customer Representative	
			

GRP Water Tank 1

Before Photo



After Photo



Before Photo



After Photo



Mentioned tank has been cleaned & disinfected

CRYSTALLINE CLEANING & ENVIRONMENTAL SERVICES

WATER TANK CLEANING & DISINFECTION

CLIENT NAME : EFS FACILITIES SERVICES

CONTACT PERSON : MANJUNATH PRABHU

DESIGNATION : SUPERVISOR

SITE DETAILS : CREW BRIEFING CENTER

DETAILS : WATER TANK CLEANING & DISINFECTION

DATE OF CLEANING : 12 DECEMBER 2019

FREQUENCY OF CLEANING : HALF YEARLY

DATE OF NEXT CLEANING : 12 JUNE 2020

The above water tanks were cleaned and disinfected in accordance with the Code of Practice for the inspection and cleaning of customer water storage tanks.



Ismanpinto

CRYSTALLINE CLEANING AND ENVIRONMENTAL SERVICES