

**ENVIRONMENTAL
SERVICES FOR
A GREENER
TOMORROW...
ONE STEP AT
A TIME.**




Completion Report for
Water Tank Cleaning & Disinfection

Date: **15 September 2020**
Client Name: **Inspire Integrated Services**
Contact Person: **Mr. Vishnudeth Pamideth**
Designation: **Facilities Manager**
Site Detail: **Sheikh Zayed Desert Learning Center
- Al Ain**



Address: PO BOX 131463, Abu Dhabi, UAE | Phone: +971 2 650 8930, +971 55 716 7017
E-mail: info@crystalline-uae.com | Website: www.crystalline-uae.com

Customer: Inspire Integrated Services		Contact Person: Mr. Vishnudeth Pamideth	
Site: Sheikh Zayed Desert Learning Centre, Al Ain		Contact Number: 056 417 2552	
Description: FLSS Drainage Water Tank Cleaning		Location: Pump room UAEWD	
Type Of Building :		<input checked="" type="checkbox"/> Commercial	<input type="checkbox"/> Residential <input type="checkbox"/> Others
Type Of Tank			
<input checked="" type="checkbox"/> Concrete	<input type="checkbox"/> GRP Panel	<input type="checkbox"/> FRP Tank	<input type="checkbox"/> Galvanized
<input type="checkbox"/> Steel Panel	<input type="checkbox"/> Plastic	<input type="checkbox"/> Concrete Coated	<input type="checkbox"/> Polyurethane
<input type="checkbox"/> Others			
Condition before cleaning		Condition after cleaning	
<input type="checkbox"/> Clean	<input checked="" type="checkbox"/> Dirty	<input checked="" type="checkbox"/> Clean	<input type="checkbox"/> Dirty
<input type="checkbox"/> Biofilms	<input type="checkbox"/> Moulds	<input type="checkbox"/> Biofilms	<input type="checkbox"/> Moulds
<input type="checkbox"/> Sediments	<input checked="" type="checkbox"/> Mud & Sand	<input type="checkbox"/> Sediments	<input type="checkbox"/> Mud & Sand
<input type="checkbox"/> Very Dirty	<input type="checkbox"/> Slime	<input type="checkbox"/> Very Dirty	<input type="checkbox"/> Slime
<input type="checkbox"/> Rust		<input type="checkbox"/> Rust	
Size of Tank			
M3: 30		USG:	L*B*H:
Quantity Of Water		Manhole	
<input type="checkbox"/> Full	<input checked="" type="checkbox"/> Half	<input checked="" type="checkbox"/> Covered	<input type="checkbox"/> Damaged <input type="checkbox"/> NA
<input type="checkbox"/> Empty			
Ladder In		Ladder Out	
<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Drain Line		Valves	
<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Tank Cleaned		Tank Disinfected	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
		Pipes Disinfected	
		<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Chemicals Used			
Chemical: Carela Bio Plus		Quantity: 500ML	
Chemical:		Quantity:	
Equipments Used			
<input checked="" type="checkbox"/> Submersibel Pump	<input checked="" type="checkbox"/> High/low Pressure Jet	<input checked="" type="checkbox"/> Extension Cords	<input checked="" type="checkbox"/> LED Lights
<input checked="" type="checkbox"/> Foot Bath	<input checked="" type="checkbox"/> Ladder	<input checked="" type="checkbox"/> Ventilating Fan	<input checked="" type="checkbox"/> Oxygen Meter
<input type="checkbox"/> Vacuum Cleaner	<input checked="" type="checkbox"/> Cleaning Materials	<input checked="" type="checkbox"/> Suction/Discharge Hoses	
Last Cleaning Date		Current Cleaning Date	
-		12 September 2020	
		Next Cleaning Date	
		11 March 2021	
Crystalline Representative		Customer Representative	
		 Shamsbur Rahman 23/09/2020	

Arsad Ali Ansari
 Arsad Ali Ansari
 BMX-3775

Mohammad Waqas
 22/09/2020

FLSS Drainage Water Tank Cleaning

Before Photo



After Photo



Before Photo



After Photo



Cleaned and disinfected

Customer: Inspire Integrated Services		Contact Person: Mr. Vishnudeth Pamideth	
Site: Sheikh Zayed Desert Learning Centre, Al Ain		Contact Number: 056 417 2552	
Description: Concrete Holding Water Tank		Location: Level - 10	
Type Of Building :		<input checked="" type="checkbox"/> Commercial	<input type="checkbox"/> Residential <input type="checkbox"/> Others
Type Of Tank			
<input checked="" type="checkbox"/> Concrete	<input type="checkbox"/> GRP Panel	<input type="checkbox"/> FRP Tank	<input type="checkbox"/> Galvanized
<input type="checkbox"/> Steel Panel	<input type="checkbox"/> Plastic	<input type="checkbox"/> Concrete Coated	<input type="checkbox"/> Polyurethane
<input type="checkbox"/> Others			
Condition before cleaning		Condition after cleaning	
<input type="checkbox"/> Clean	<input checked="" type="checkbox"/> Dirty	<input checked="" type="checkbox"/> Clean	<input type="checkbox"/> Dirty
<input type="checkbox"/> Biofilms	<input type="checkbox"/> Moulds	<input type="checkbox"/> Biofilms	<input type="checkbox"/> Moulds
<input type="checkbox"/> Sediments	<input type="checkbox"/> Mud & Sand	<input checked="" type="checkbox"/> Very Dirty	<input type="checkbox"/> Very Dirty
	<input checked="" type="checkbox"/> Rust	<input type="checkbox"/> Slime	<input type="checkbox"/> Slime
		<input type="checkbox"/> Sediments	<input type="checkbox"/> Mud & Sand
		<input type="checkbox"/> Rust	<input type="checkbox"/> Rust
Size of Tank			
M3: 170		USG:	L*B*H:
Quantity Of Water		Manhole	
<input type="checkbox"/> Full	<input checked="" type="checkbox"/> Half	<input type="checkbox"/> Empty	<input checked="" type="checkbox"/> Covered
			<input type="checkbox"/> Damaged <input type="checkbox"/> NA
Ladder In		Ladder Out	
<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Drain Line		Valves	
<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Tank Cleaned		Tank Disinfected	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
		Pipes Disinfected	
		<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Chemicals Used			
Chemical: Carela Bio Plus		Quantity: 500 ml	
Chemical:		Quantity:	
Equipments Used			
<input checked="" type="checkbox"/> Submersibel Pump	<input checked="" type="checkbox"/> High/low Pressure Jet	<input checked="" type="checkbox"/> Extension Cords	<input checked="" type="checkbox"/> LED Lights
<input checked="" type="checkbox"/> Foot Bath	<input checked="" type="checkbox"/> Ladder	<input checked="" type="checkbox"/> Ventilating Fan	<input checked="" type="checkbox"/> Oxygen Meter
<input type="checkbox"/> Vacuum Cleaner	<input checked="" type="checkbox"/> Cleaning Materials	<input checked="" type="checkbox"/> Suction/Discharge Hoses	
Last Cleaning Date	Current Cleaning Date	Next Cleaning Date	
-	12 September 2020	11 March 2021	
Crystalline Representative		Customer Representative	
		 Shamshur Rahman 23/09/2020	


 Arsal Ali Ansari
 BMX-3775
 Mohammad Waqas
 22/09/2020

Concrete Holding Water Tank

Before Photo



After Photo



Before Photo



After Photo



Cleaned and disinfected

Customer: Inspire Integrated Services		Contact Person: Mr. Vishnudeth Pamideth	
Site: Sheikh Zayed Desert Learning Centre, Al Ain		Contact Number: 056 417 2552	
Description: Fire Tank and Funnel Water Tank (A & B)		Location: Level-10	
Type Of Building :		<input checked="" type="checkbox"/> Commercial	<input type="checkbox"/> Residential <input type="checkbox"/> Others
Type Of Tank			
<input checked="" type="checkbox"/> Concrete	<input type="checkbox"/> GRP Panel	<input type="checkbox"/> FRP Tank	<input type="checkbox"/> Galvanized
<input type="checkbox"/> Steel Panel	<input type="checkbox"/> Plastic	<input type="checkbox"/> Concrete Coated	<input type="checkbox"/> Polyurethane
<input type="checkbox"/> Others			
Condition before cleaning		Condition after cleaning	
<input type="checkbox"/> Clean	<input checked="" type="checkbox"/> Dirty	<input checked="" type="checkbox"/> Clean	<input type="checkbox"/> Dirty
<input type="checkbox"/> Biofilms	<input type="checkbox"/> Moulds	<input type="checkbox"/> Biofilms	<input type="checkbox"/> Moulds
<input type="checkbox"/> Sediments	<input type="checkbox"/> Mud & Sand	<input checked="" type="checkbox"/> Very Dirty	<input type="checkbox"/> Very Dirty
	<input checked="" type="checkbox"/> Rust	<input type="checkbox"/> Slime	<input type="checkbox"/> Slime
		<input type="checkbox"/> Sediments	<input type="checkbox"/> Mud & Sand
		<input type="checkbox"/> Rust	<input type="checkbox"/> Rust
Size of Tank			
M3: 100 & 75		USG:	L*B*H:
Quantity Of Water		Manhole	
<input type="checkbox"/> Full	<input checked="" type="checkbox"/> Half	<input checked="" type="checkbox"/> Covered	<input type="checkbox"/> Damaged <input type="checkbox"/> NA
<input type="checkbox"/> Empty			
Ladder In		Ladder Out	
<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Drain Line		Valves	
<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Tank Cleaned		Tank Disinfected	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
		Pipes Disinfected	
		<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Chemicals Used			
Chemical: Carela bio plus		Quantity: 500ml	
Chemical:		Quantity:	
Equipments Used			
<input checked="" type="checkbox"/> Submersibel Pump	<input checked="" type="checkbox"/> High/low Pressure Jet	<input checked="" type="checkbox"/> Extension Cords	<input checked="" type="checkbox"/> LED Lights
<input checked="" type="checkbox"/> Foot Bath	<input checked="" type="checkbox"/> Ladder	<input checked="" type="checkbox"/> Ventilating Fan	<input checked="" type="checkbox"/> Oxygen Meter
<input type="checkbox"/> Vacuum Cleaner	<input checked="" type="checkbox"/> Cleaning Materials	<input checked="" type="checkbox"/> Suction/Discharge Hoses	
Last Cleaning Date	Current Cleaning Date	Next Cleaning Date	
-	12 September 2020	11 March 2021	 Arsad Ali Ansari BMX-3775
Crystalline Representative		Customer Representative	
		Shamshur Rahman  23/09/2020	

Fire Tank and Funnel Water Tank (A & B)

Before Photo



After Photo



Before Photo



After Photo



Cleaned and disinfected

Fire Tank and Funnel Water Tank (A & B)


Before Photo



After Photo



Before Photo



After Photo



Cleaned and disinfected

Fire Tank and Funnel Water Tank (A & B)

Before Photo



After Photo



Before Photo



After Photo



Cleaned and disinfected

CRYSTALLINE CLEANING & ENVIRONMENTAL SERVICES

WATER TANK CLEANING & DISINFECTION

CLIENT NAME : **INSPIRE INTEGRATED SERVICES**

CONTACT PERSON : **MR. VISHNUDETH PAMIDETH**

DESIGNATION : **FACILITIES MANAGER**

SITE DETAILS : **SHEIKH ZAYED DESERT LEARNING CENTER**
- AL AIN

DETAILS : **WATER TANK CLEANING & DISINFECTION**

DATE OF CLEANING : **12 SEPTEMBER 2020**

FREQUENCY OF CLEANING : **HALF YEARLY**

DATE OF NEXT CLEANING : **12 MARCH 2021**

The above water tanks were cleaned and disinfected in accordance with the Code of Practice for the inspection and cleaning of customer water storage tanks.



Insmanpinto

CRYSTALLINE CLEANING AND ENVIRONMENTAL SERVICES