

**ENVIRONMENTAL
SERVICES FOR
A GREENER
TOMORROW...
ONE STEP AT
A TIME.**



Completion Report for

AC Duct Cleaning & Sanitization


Date: **16 February 2021**
Client Name: **Tafawuq facility management**
Contact Person: **Udayakumar Kannappan**
Designation: **FM Coordinator**
Site Detail: **VILLA -149 - KRV**



Address: PO BOX 131463, Abu Dhabi, UAE | Phone: +971 2 650 8930, +971 55 716 7017
E-mail: info@crystalline-uae.com | Website: www.crystalline-uae.com

Service Report



Customer: Tafawuq facility management		Contact Person: Mr. Udayakumar Kannappan	
Site: KRV Villa - 149 Abu Dhabi		Contact Number: -	
Description: Ac duct cleaning & sanitizing		Location: Villa 149 KRV compount	
Type Of Building: <input type="checkbox"/> Commercial <input checked="" type="checkbox"/> Residential <input type="checkbox"/> Others			
AIR CONDITIONING MACHINE			
Tilted Correctly <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No		Drip Tray Accessible <input type="checkbox"/> Yes <input type="checkbox"/> No	
Drip Tray <input type="checkbox"/> Yes <input type="checkbox"/> No		Direct Drain <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	
Type Of AC <input checked="" type="checkbox"/> Package Unit <input type="checkbox"/> AHU <input type="checkbox"/> Fan Coil/Split unit		Condition of Drip Tray Cleaned <input type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Slime <input type="checkbox"/> mould <input type="checkbox"/> Rusty <input type="checkbox"/> Damage	
FILTERS		DUCT WORK	
Filters <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No		Physical Entry <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Partly	
Location of Filters <input type="checkbox"/> Duct <input checked="" type="checkbox"/> Machine		Access with Tools only <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Partly	
SUPPLY GRILLS			
Type of Grill <input checked="" type="checkbox"/> Square <input type="checkbox"/> Rectangle <input type="checkbox"/> Slot <input type="checkbox"/> Round		Fresh Air Inlet <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Open <input type="checkbox"/> Closed	
Return Air <input type="checkbox"/> Ducts <input checked="" type="checkbox"/> Cavity		Flow Dumpers <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	
Damaged <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		Sensors <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	
Internal Acoustic Insulat <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No		External Insulation <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	
		Sanitization of Ducts <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	
		Type <input checked="" type="checkbox"/> Polystyrene <input type="checkbox"/> Rockwood <input type="checkbox"/> Foam	
Covering Insulation <input type="checkbox"/> Canvas <input type="checkbox"/> Aluminum <input checked="" type="checkbox"/> Others		Door / Plates Present <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No How Many: 07	
Door / Plates Fitted <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No How Many: 07		Entire System Cleaned <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No If NO details:	
Ducts Damaged <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No Where:		Where Installed	
		Duct Size and Approximate Length 05 mtr	
Chemicals Used Chemical: Oxine Quantity: Limited			
Last Cleaning Date -		Current Cleaning Date 16 February 2021	
		Next Cleaning Date 16 February 2022	
Crystalline Representative 		Customer Representative 	

Ac duct cleaning & sanitizing

Before Photo



After Photo



Before Photo



After Photo



Above mentioned ac duct cleaned & sanitized

Ac duct cleaning & sanitizing

Before Photo




After Photo



Before Photo



After Photo



Above mentioned ac duct cleaned & sanitized

Ac duct cleaning & sanitizing

Before Photo




After Photo



Before Photo



After Photo



Above mentioned ac duct cleaned & sanitized

Ac duct cleaning & sanitizing

Before Photo



After Photo



Above mentioned ac duct cleaned & sanitized

Address: PO BOX 131463, Abu Dhabi, UAE | Phone: +971 2 650 8930, +971 55 716 7017
E-mail: info@crystalline-uae.com | Website: www.crystalline-uae.com

CRYSTALLINE CLEANING & ENVIRONMENTAL SERVICES

AC DUCT CLEANING & SANITIZATION

CLIENT NAME : TAFAWUQ FACILITY MANAGEMENT
CONTACT PERSON : UDAYAKUMAR KANNAPPAN
DESIGNATION : FM COORDINATOR
SITE DETAILS : VILLA -149 - KRV
DETAILS : AC DUCT CLEANING & SANITIZATION
DATE OF CLEANING : 16 FEB 2021
FREQUENCY OF CLEANING : YEARLY
DATE OF NEXT CLEANING : 16 FEBRUARY 2022

The HVAC system was cleaned and sanitized in accordance with NADCA ACR 2013 Standards for the HVAC Inspection, Cleaning and Restoration Association.



Tasmansinto

CRYSTALLINE CLEANING AND ENVIRONMENTAL SERVICES