

No. 1759

Prime Envirotech Cleaning Services

SERVICE REPORT

CUSTOMER INFORMATION		WORK ORDER INFORMATION	
Customer : _____		Customer Ref No : _____	
Building : <u>Moorpau's Camp</u>		Site In-Charge : <u>MR: A. Alwadi</u>	
Address : <u>Fujairah</u>		Makani Number : _____	
Mobile Number : <u>056514413</u>			
Type of Tank & Quantity:	<input type="checkbox"/> GRP Tank	Size of Tank:	(3) <u>Granite tank 25000 + 5000 +</u>
	<input checked="" type="checkbox"/> Fiber Tank		(2) <u>other site (2000) usg</u>
	<input checked="" type="checkbox"/> Polyurathene Tank		(2) <u>Roof top (500) usg</u>
	<input type="checkbox"/> RCC Tank		(5) <u>Polygon tank</u>
	<input type="checkbox"/> Other		(2) <u>Fiber tank</u>
Nature of Job:	<input checked="" type="checkbox"/> Water Tank Cleaning	Location	<input checked="" type="checkbox"/> Roof Top
	<input type="checkbox"/> Microbiological / Legionella Lab report		<input checked="" type="checkbox"/> Ground
	<input type="checkbox"/> Water tank repair		<input type="checkbox"/> Basement
	<input type="checkbox"/> Car park cleaning		<input type="checkbox"/> Floor / Podium
Start Date:	<u>4/07/2021</u>	Completed Date:	<u>4/07/2021</u>
Time In:		Time Out:	
Travel Time:		Total (Hrs/Mins):	

Defects found, Rectifications / Action Taken:

Chemical Used:	<u>Hygmax Chemical</u>	<u>one tank damaged in Roof top</u>	
Date of Cleaning:	<u>4/07/2021</u>		
Next Cleaning Date:	<u>3/10/2021</u>		
Gas level finding:	<u>Normal</u>		
Job Completed:	<input checked="" type="checkbox"/> Yes	Further action required	
	<input type="checkbox"/> Partial		
Technicians Name:	<u>Aftab Javed Imam Farhad</u>	Team Leader Name & Signature:	

For Customer use

If any comments:

A. Alwadi
Name in block letters:

056514413
Mobile number


Signature and Date