

**ENVIRONMENTAL
SERVICES FOR
A GREENER
TOMORROW...
ONE STEP AT
A TIME.**



Completion Report for

AC Duct Cleaning & Sanitization

Date: **14 February 2021**
Client Name: **Tafawuq facility management**
Contact Person: **Udayakumar Kannappan**
Designation: **FM Coordinator**
Site Detail: **VILLA-69- KRV**



Service Report




| | | | |
|--|--|--|--|
| Customer: Tafawuq facility management | | Contact Person: Mr. Udayakumar Kannappan | |
| Site: KRV Villa - 69 Abu Dhabi | | Contact Number: - | |
| Description: Ac duct cleaning & sanitizing | | Location: Villa 69 KRV compount | |
| Type Of Building: <input type="checkbox"/> Commercial <input checked="" type="checkbox"/> Residential <input type="checkbox"/> Others | | | |
| AIR CONDITIONING MACHINE | | | |
| Tilted Correctly <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No | | Drip Tray Accessible <input type="checkbox"/> Yes <input type="checkbox"/> No | |
| Drip Tray <input type="checkbox"/> Yes <input type="checkbox"/> No | | Direct Drain <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No | |
| Type Of AC <input checked="" type="checkbox"/> Package Unit <input type="checkbox"/> AHU <input type="checkbox"/> Fan Coil/Split unit | | Condition of Drip Tray Cleaned <input type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Slime <input type="checkbox"/> mould <input type="checkbox"/> Rusty <input type="checkbox"/> Damage | |
| FILTERS | | DUCT WORK | |
| Filters <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No | | Location of Filters <input type="checkbox"/> Duct <input checked="" type="checkbox"/> Machine | |
| Physical Entry <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Partly | | Access with Tools only <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Partly | |
| SUPPLY GRILLS | | | |
| Type of Grill <input checked="" type="checkbox"/> Square <input type="checkbox"/> Rectangle <input type="checkbox"/> Slot <input type="checkbox"/> Round | | Fresh Air Inlet <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Open <input type="checkbox"/> Closed | |
| Return Air <input type="checkbox"/> Ducts <input checked="" type="checkbox"/> Cavity | | Flow Dumpers <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No | |
| Damaged <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | | Sensors <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No | |
| Internal Acoustic Insulat <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No | | External Insulation <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No | |
| | | Sanitization of Ducts <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No | |
| | | Type <input checked="" type="checkbox"/> Polystyrene <input type="checkbox"/> Rockwood <input type="checkbox"/> Foam | |
| Covering Insulation <input type="checkbox"/> Canvas <input type="checkbox"/> Aluminum <input checked="" type="checkbox"/> Others | | Door / Plates Present <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No How Many: 07 | |
| Door / Plates Fitted <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No How Many: 07 | | Entire System Cleaned <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No If NO details: | |
| Ducts Damaged <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No Where: | | Where Installed | |
| | | Duct Size and Approximate Length 05 mtr | |
| Chemicals Used Chemical: Oxine Quantity: Limited | | | |
| Last Cleaning Date - | | Current Cleaning Date 14 February 2021 | |
| | | Next Cleaning Date 14 February 2022 | |
| Crystalline Representative  | | Customer Representative  | |




Ac duct cleaning & sanitizing

Before Photo



After Photo



Before Photo



After Photo



Above mentioned ac duct cleaned & sanitized




Ac duct cleaning & sanitizing

Before Photo



After Photo



Before Photo



After Photo



Above mentioned ac duct cleaned & sanitized

Ac duct cleaning & sanitizing

Before Photo




After Photo



Before Photo



After Photo



Above mentioned ac duct cleaned & sanitized

Ac duct cleaning & sanitizing

Before Photo



After Photo



Above mentioned ac duct cleaned & sanitized

Address: PO BOX 131463, Abu Dhabi, UAE | Phone: +971 2 650 8930, +971 55 716 7017
E-mail: info@crystalline-uae.com | Website: www.crystalline-uae.com

CRYSTALLINE CLEANING & ENVIRONMENTAL SERVICES

AC DUCT CLEANING & SANITIZATION

CLIENT NAME : TAFAWUQ FACILITY MANAGEMENT
CONTACT PERSON : UDAYAKUMAR KANNAPPAN
DESIGNATION : FM COORDINATOR
SITE DETAILS : VILLA-69- KRV
DETAILS : AC DUCT CLEANING & SANITIZATION
DATE OF CLEANING : 14 FEB 2021
FREQUENCY OF CLEANING : YEARLY
DATE OF NEXT CLEANING : 14 FEBRUARY 2022

The HVAC system was cleaned and sanitized in accordance with NADCA ACR 2013 Standards for the HVAC Inspection, Cleaning and Restoration Association.



Tasmanpinto

CRYSTALLINE CLEANING AND ENVIRONMENTAL SERVICES