

**ENVIRONMENTAL
SERVICES FOR
A GREENER
TOMORROW...
ONE STEP AT
A TIME.**




Completion Report for
Water Tank Cleaning & Disinfection

Date: **04 March 2020**
Client Name: **Al Raha Village**
Contact Person: **Mr. Bashar Abu Salim**
Designation: **QHSE**
Site Detail: **Al Raha Village - Baniyas, Abu Dhabi**



Address: PO BOX 131463, Abu Dhabi, UAE | Phone: +971 2 650 8930, +971 55 716 7017
E-mail: info@crystalline-uae.com | Website: www.crystalline-uae.com

Customer: Al Raha Village		Contact Person: Mr. Barshar Abu Salim			
Site: Al Raha Village		Contact Number: 0504886406			
Description: RCC Water Tank Cleaning		Location: Beside Diner 5, Underground			
Type Of Building : <input type="checkbox"/> Commercial <input checked="" type="checkbox"/> Residential <input type="checkbox"/> Others					
Type Of Tank					
<input checked="" type="checkbox"/> Concrete	<input type="checkbox"/> GRP Panel	<input type="checkbox"/> FRP Tank	<input type="checkbox"/> Galvanized		
<input type="checkbox"/> Steel Panel	<input type="checkbox"/> Plastic	<input type="checkbox"/> Concrete Coated	<input type="checkbox"/> Polyurethane		
<input type="checkbox"/> Others					
Condition before cleaning		Condition after cleaning			
<input type="checkbox"/> Clean	<input type="checkbox"/> Dirty	<input checked="" type="checkbox"/> Clean	<input type="checkbox"/> Dirty		
<input type="checkbox"/> Biofilms	<input type="checkbox"/> Moulds	<input type="checkbox"/> Biofilms	<input type="checkbox"/> Moulds		
<input type="checkbox"/> Sediments	<input type="checkbox"/> Mud & Sand	<input type="checkbox"/> Sediments	<input type="checkbox"/> Mud & Sand		
<input checked="" type="checkbox"/> Very Dirty	<input type="checkbox"/> Slime	<input type="checkbox"/> Very Dirty	<input type="checkbox"/> Slime		
<input type="checkbox"/> Rust		<input type="checkbox"/> Rust			
Size of Tank					
M3:		USG:			
		L*B*H:			
Quantity Of Water		Manhole			
<input type="checkbox"/> Full	<input checked="" type="checkbox"/> Half	<input type="checkbox"/> Empty	<input type="checkbox"/> Covered		
<input type="checkbox"/> Damaged	<input checked="" type="checkbox"/> NA				
Ladder In		Ladder Out		Leaks	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Drain Line		Valves		Float Valve	
<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Tank Cleaned		Tank Disinfected		Pipes Disinfected	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Chemicals Used					
Chemical: Carela bio				Quantity: 500ml	
Chemical: Carela plus				Quantity: 500ml	
Equipments Used					
<input checked="" type="checkbox"/> Submersibel Pump	<input checked="" type="checkbox"/> High/low Pressure Jet	<input checked="" type="checkbox"/> Extension Cords	<input checked="" type="checkbox"/> LED Lights		
<input checked="" type="checkbox"/> Foot Bath	<input checked="" type="checkbox"/> Ladder	<input checked="" type="checkbox"/> Ventilating Fan	<input checked="" type="checkbox"/> Oxygen Meter		
<input checked="" type="checkbox"/> Vacuum Cleaner	<input checked="" type="checkbox"/> Cleaning Materials	<input checked="" type="checkbox"/> Suction/Discharge Hoses			
Last Cleaning Date		Current Cleaning Date		Next Cleaning Date	
-		10 February 2020		10 August 2020	
Crystalline Representative			Customer Representative		
					

RCC Water Tank Cleaning


Before Photo



After Photo



Before Photo



After Photo



Water tank has been Cleaned & disinfected

CRYSTALLINE CLEANING & ENVIRONMENTAL SERVICES

CLEANING & DISINFECTION CERTIFICATE

POTABLE WATER TANKS

CLIENT NAME : AL RAHA VILLGAE PROPERTIES LLC.

CLIENT ADDRESS : P.O. BOX: 6634, ABU DHABI, UAE.

CONTACT PERSON : MR. BEJOY THOMAS ZACHARIAH.

SITE DETAILS : AL RAHA VILLAGE, ABU DHABI.

DETAILS : GROUND RCC WATER TANK - DINER '05'

DATE OF CLEANING : 10 FEBRUARY 2020

FREQUENCY OF CLEANING : EVERY SIX MONTHS

DATE OF NEXT CLEANING : 10 AUGUST 2020

The procedures employed in this cleaning and disinfection comply with HSE (G) 70 health and safety guidelines for prevention of legionella as well as BS6700 and CARELA BIO PLUS method statement.

The entire water storage tank should be disinfected minimum every Six (6) month depending upon the condition.



CRYSTALLINE CLEANING AND ENVIRONMENTAL SERVICES

Customer: Al Raha Village		Contact Person: Mr. Barshar Abu Salim	
Site: Al Raha Village		Contact Number: 0504886406	
Description: RCC Water Tank Cleaning		Location: Beside Diner 6, Underground	
Type Of Building : <input type="checkbox"/> Commercial <input checked="" type="checkbox"/> Residential <input type="checkbox"/> Others			
Type Of Tank			
<input checked="" type="checkbox"/> Concrete	<input type="checkbox"/> GRP Panel	<input type="checkbox"/> FRP Tank	<input type="checkbox"/> Galvanized
<input type="checkbox"/> Steel Panel	<input type="checkbox"/> Plastic	<input type="checkbox"/> Concrete Coated	<input type="checkbox"/> Polyurethane
<input type="checkbox"/> Others			
Condition before cleaning		Condition after cleaning	
<input type="checkbox"/> Clean	<input type="checkbox"/> Dirty	<input checked="" type="checkbox"/> Clean	<input type="checkbox"/> Dirty
<input type="checkbox"/> Biofilms	<input type="checkbox"/> Moulds	<input type="checkbox"/> Biofilms	<input type="checkbox"/> Moulds
<input type="checkbox"/> Sediments	<input type="checkbox"/> Mud & Sand	<input type="checkbox"/> Sediments	<input type="checkbox"/> Mud & Sand
<input checked="" type="checkbox"/> Very Dirty	<input type="checkbox"/> Slime	<input type="checkbox"/> Very Dirty	<input type="checkbox"/> Slime
<input type="checkbox"/> Rust		<input type="checkbox"/> Rust	
Size of Tank			
M3:	USG:	L*B*H:	
Quantity Of Water		Manhole	
<input type="checkbox"/> Full	<input checked="" type="checkbox"/> Half	<input type="checkbox"/> Covered	<input type="checkbox"/> Damaged
<input type="checkbox"/> Empty		<input checked="" type="checkbox"/> NA	
Ladder In	Ladder Out	Leaks	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> Yes	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
<input type="checkbox"/> No	<input checked="" type="checkbox"/> No	<input type="checkbox"/> No	<input type="checkbox"/> No
Drain Line	Valves	Float Valve	
<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> Yes	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
<input checked="" type="checkbox"/> No	<input type="checkbox"/> No	<input type="checkbox"/> No	<input type="checkbox"/> No
Tank Cleaned	Tank Disinfected	Pipes Disinfected	
<input checked="" type="checkbox"/> Yes	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
<input type="checkbox"/> No	<input type="checkbox"/> No	<input type="checkbox"/> No	<input type="checkbox"/> No
Chemicals Used			
Chemical: Carela bio		Quantity: 500ml	
Chemical: Carela plus		Quantity: 500ml	
Equipments Used			
<input checked="" type="checkbox"/> Submersibel Pump	<input checked="" type="checkbox"/> High/low Pressure Jet	<input checked="" type="checkbox"/> Extension Cords	<input checked="" type="checkbox"/> LED Lights
<input checked="" type="checkbox"/> Foot Bath	<input checked="" type="checkbox"/> Ladder	<input checked="" type="checkbox"/> Ventilating Fan	<input checked="" type="checkbox"/> Oxygen Meter
<input checked="" type="checkbox"/> Vacuum Cleaner	<input checked="" type="checkbox"/> Cleaning Materials	<input checked="" type="checkbox"/> Suction/Discharge Hoses	
Last Cleaning Date	Current Cleaning Date	Next Cleaning Date	
-	09 February 2020	09 August 2020	
Crystalline Representative		Customer Representative	
			

RCC Water Tank Cleaning

Before Photo




After Photo



Before Photo



After Photo



Water tank has been Cleaned & disinfected

CRYSTALLINE CLEANING & ENVIRONMENTAL SERVICES

CLEANING & DISINFECTION CERTIFICATE

POTABLE WATER TANKS

CLIENT NAME : AL RAHA VILLAGAE PROPERTIES LLC.

CLIENT ADDRESS : P.O. BOX: 6634, ABU DHABI, UAE.

CONTACT PERSON : MR. BASHAR ABU SALIM.

SITE DETAILS : AL RAHA VILLAGE, ABU DHABI.

DETAILS : GROUND RCC WATER TANK - DINER '06'

DATE OF CLEANING : 09 FEBRUARY 2020

FREQUENCY OF CLEANING : EVERY SIX MONTHS

DATE OF NEXT CLEANING : 09 AUGUST 2020

The procedures employed in this cleaning and disinfection comply with HS (G) 70 health and safety guidelines for prevention of legionella as well as BS6700 and CARELA BIO PLUS method statement.

The entire water storage tank should be disinfected minimum every Six (6) month depending upon the condition.



CRYSTALLINE CLEANING AND ENVIRONMENTAL SERVICES

Customer: Al Raha Village		Contact Person: Mr. Barshar Abu Salim	
Site: Al Raha Village		Contact Number: 0504886406	
Description: RCC Water Tank Cleaning		Location: Diner#7 Underground	
Type Of Building :		<input checked="" type="checkbox"/> Commercial	<input type="checkbox"/> Residential <input type="checkbox"/> Others
Type Of Tank			
<input checked="" type="checkbox"/> Concrete	<input type="checkbox"/> GRP Panel	<input type="checkbox"/> FRP Tank	<input type="checkbox"/> Galvanized
<input type="checkbox"/> Steel Panel	<input type="checkbox"/> Plastic	<input type="checkbox"/> Concrete Coated	<input type="checkbox"/> Polyurethane
<input type="checkbox"/> Others			
Condition before cleaning		Condition after cleaning	
<input type="checkbox"/> Clean	<input type="checkbox"/> Dirty	<input checked="" type="checkbox"/> Very Dirty	<input type="checkbox"/> Dirty <input type="checkbox"/> Very Dirty
<input type="checkbox"/> Biofilms	<input type="checkbox"/> Moulds	<input type="checkbox"/> Slime	<input type="checkbox"/> Biofilms <input type="checkbox"/> Moulds <input type="checkbox"/> Slime
<input type="checkbox"/> Sediments	<input type="checkbox"/> Mud & Sand	<input type="checkbox"/> Rust	<input type="checkbox"/> Sediments <input type="checkbox"/> Mud & Sand <input type="checkbox"/> Rust
Size of Tank			
M3:		USG:	
		L*B*H:	
Quantity Of Water		Manhole	
<input type="checkbox"/> Full	<input checked="" type="checkbox"/> Half <input type="checkbox"/> Empty	<input checked="" type="checkbox"/> Covered	<input type="checkbox"/> Damaged <input type="checkbox"/> NA
Ladder In		Ladder Out	
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Leaks	
Drain Line		Valves	
<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Float Valve	
Tank Cleaned		Tank Disinfected	
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Pipes Disinfected	
<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	
Chemicals Used			
Chemical: Carela bio		Quantity: 2l	
Chemical: Carela bio plus		Quantity: 2l	
Equipments Used			
<input checked="" type="checkbox"/> Submersibel Pump	<input type="checkbox"/> High/low Pressure Jet	<input checked="" type="checkbox"/> Extension Cords	<input checked="" type="checkbox"/> LED Lights
<input checked="" type="checkbox"/> Foot Bath	<input checked="" type="checkbox"/> Ladder	<input checked="" type="checkbox"/> Ventilating Fan	<input checked="" type="checkbox"/> Oxygen Meter
<input checked="" type="checkbox"/> Vacuum Cleaner	<input checked="" type="checkbox"/> Cleaning Materials	<input checked="" type="checkbox"/> Suction/Discharge Hoses	
Last Cleaning Date		Current Cleaning Date	
-		02 March 2020	
		Next Cleaning Date	
		02 September 2020	
Crystalline Representative		Customer Representative	
			

RCC Water Tank Cleaning


Before Photo



After Photo



Before Photo



After Photo



Water tank has been Cleaned and disinfected

CRYSTALLINE CLEANING & ENVIRONMENTAL SERVICES

CLEANING & DISINFECTION CERTIFICATE

POTABLE WATER TANKS

CLIENT NAME : AL RAHA VILLAGAE PROPERTIES LLC.

CLIENT ADDRESS : P.O. BOX: 6634, ABU DHABI, UAE.

CONTACT PERSON : MR. BASHAR ABU SALIM.

SITE DETAILS : AL RAHA VILLAGE, ABU DHABI.

DETAILS : U/G RCC WATER TANK - DINER '07'

DATE OF CLEANING : 02 MARCH 2020

FREQUENCY OF CLEANING : EVERY SIX MONTHS

DATE OF NEXT CLEANING : 05 SEPTEMBER 2020

The procedures employed in this cleaning and disinfection comply with HS (G) 70 health and safety guidelines for prevention of legionella as well as BS6700 and CARELA BIO PLUS method statement.

The entire water storage tank should be disinfected minimum every Six (6) month depending upon the condition.



CRYSTALLINE CLEANING AND ENVIRONMENTAL SERVICES


Customer: Al Raha Village		Contact Person: Mr. Barshar Abu Salim	
Site: Al Raha Village		Contact Number: 0504886406	
Description: RCC Water Tank Cleaning		Location: Mosque A, Underground	
Type Of Building : <input type="checkbox"/> Commercial <input checked="" type="checkbox"/> Residential <input type="checkbox"/> Others			
Type Of Tank			
<input checked="" type="checkbox"/> Concrete	<input type="checkbox"/> GRP Panel	<input type="checkbox"/> FRP Tank	<input type="checkbox"/> Galvanized
<input type="checkbox"/> Steel Panel	<input type="checkbox"/> Plastic	<input type="checkbox"/> Concrete Coated	<input type="checkbox"/> Polyurethane
<input type="checkbox"/> Others			
Condition before cleaning		Condition after cleaning	
<input type="checkbox"/> Clean	<input type="checkbox"/> Dirty	<input checked="" type="checkbox"/> Very Dirty	<input type="checkbox"/> Clean
<input type="checkbox"/> Biofilms	<input type="checkbox"/> Moulds	<input type="checkbox"/> Slime	<input type="checkbox"/> Dirty
<input type="checkbox"/> Sediments	<input type="checkbox"/> Mud & Sand	<input type="checkbox"/> Rust	<input type="checkbox"/> Very Dirty
Size of Tank			
M3:	USG:	L*B*H:	
Quantity Of Water		Manhole	
<input type="checkbox"/> Full	<input checked="" type="checkbox"/> Half	<input type="checkbox"/> Empty	<input type="checkbox"/> Covered
		<input type="checkbox"/> Damaged	<input checked="" type="checkbox"/> NA
Ladder In		Ladder Out	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Drain Line		Valves	
<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Tank Cleaned		Tank Disinfected	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
		Pipes Disinfected	
		<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Chemicals Used			
Chemical: Carela bio		Quantity: 500ml	
Chemical: Carela plus		Quantity: 500ml	
Equipments Used			
<input checked="" type="checkbox"/> Submersibel Pump	<input checked="" type="checkbox"/> High/low Pressure Jet	<input checked="" type="checkbox"/> Extension Cords	<input checked="" type="checkbox"/> LED Lights
<input checked="" type="checkbox"/> Foot Bath	<input checked="" type="checkbox"/> Ladder	<input checked="" type="checkbox"/> Ventilating Fan	<input checked="" type="checkbox"/> Oxygen Meter
<input checked="" type="checkbox"/> Vacuum Cleaner	<input checked="" type="checkbox"/> Cleaning Materials	<input checked="" type="checkbox"/> Suction/Discharge Hoses	
Last Cleaning Date		Current Cleaning Date	
-		18 February 2020	
		Next Cleaning Date	
		18 August 2020	
Crystalline Representative		Customer Representative	
			

RCC Water Tank Cleaning

Before Photo



After Photo



Before Photo



After Photo



Mentioned tank has been Cleaned & disinfected

CRYSTALLINE CLEANING & ENVIRONMENTAL SERVICES

CLEANING & DISINFECTION CERTIFICATE

POTABLE WATER TANKS

CLIENT NAME : AL RAHA VILLAGAE PROPERTIES LLC.

CLIENT ADDRESS : P.O. BOX: 6634, ABU DHABI, UAE.

CONTACT PERSON : MR. BASHAR ABU SALIM.

SITE DETAILS : AL RAHA VILLAGE, ABU DHABI.

DETAILS : U/G RCC WATER TANK MOSQUE – 'A'

DATE OF CLEANING : 18 FEBRUARY 2020

FREQUENCY OF CLEANING : EVERY SIX MONTHS

DATE OF NEXT CLEANING : 18 AUGUST 2020

The procedures employed in this cleaning and disinfection comply with HS (G) 70 health and safety guidelines for prevention of legionella as well as BS6700 and CARELA BIO PLUS method statement.

The entire water storage tank should be disinfected minimum every Six (6) month depending upon the condition.




CRYSTALLINE CLEANING AND ENVIRONMENTAL SERVICES

Customer: Al Raha Village		Contact Person: Mr. Barshar Abu Salim			
Site: Al Raha Village		Contact Number: 0504886406			
Description: RCC Water Tank Cleaning		Location: Mosque B, Underground			
Type Of Building : <input type="checkbox"/> Commercial <input checked="" type="checkbox"/> Residential <input type="checkbox"/> Others					
Type Of Tank					
<input checked="" type="checkbox"/> Concrete	<input type="checkbox"/> GRP Panel	<input type="checkbox"/> FRP Tank	<input type="checkbox"/> Galvanized		
<input type="checkbox"/> Steel Panel	<input type="checkbox"/> Plastic	<input type="checkbox"/> Concrete Coated	<input type="checkbox"/> Polyurethane		
<input type="checkbox"/> Others					
Condition before cleaning		Condition after cleaning			
<input type="checkbox"/> Clean	<input type="checkbox"/> Dirty	<input checked="" type="checkbox"/> Very Dirty			
<input type="checkbox"/> Biofilms	<input type="checkbox"/> Moulds	<input type="checkbox"/> Slime			
<input type="checkbox"/> Sediments	<input type="checkbox"/> Mud & Sand	<input type="checkbox"/> Rust			
Condition after cleaning		Condition after cleaning			
<input checked="" type="checkbox"/> Clean	<input type="checkbox"/> Dirty	<input type="checkbox"/> Very Dirty			
<input type="checkbox"/> Biofilms	<input type="checkbox"/> Moulds	<input type="checkbox"/> Slime			
<input type="checkbox"/> Sediments	<input type="checkbox"/> Mud & Sand	<input type="checkbox"/> Rust			
Size of Tank					
M3:		USG:			
L*B*H:					
Quantity Of Water		Manhole			
<input type="checkbox"/> Full	<input checked="" type="checkbox"/> Half	<input type="checkbox"/> Empty			
<input type="checkbox"/> Covered	<input type="checkbox"/> Damaged	<input checked="" type="checkbox"/> NA			
Ladder In		Ladder Out		Leaks	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Drain Line		Valves		Float Valve	
<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Tank Cleaned		Tank Disinfected		Pipes Disinfected	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Chemicals Used					
Chemical: Carela bio				Quantity: 500ml	
Chemical: Carela plus				Quantity: 500ml	
Equipments Used					
<input checked="" type="checkbox"/> Submersibel Pump	<input checked="" type="checkbox"/> High/low Pressure Jet	<input checked="" type="checkbox"/> Extension Cords	<input checked="" type="checkbox"/> LED Lights		
<input checked="" type="checkbox"/> Foot Bath	<input checked="" type="checkbox"/> Ladder	<input checked="" type="checkbox"/> Ventilating Fan	<input checked="" type="checkbox"/> Oxygen Meter		
<input checked="" type="checkbox"/> Vacuum Cleaner	<input checked="" type="checkbox"/> Cleaning Materials	<input checked="" type="checkbox"/> Suction/Discharge Hoses			
Last Cleaning Date		Current Cleaning Date		Next Cleaning Date	
-		12 February 2020		12 August 2020	
Crystalline Representative			Customer Representative		
					

RCC Water Tank Cleaning


Before Photo



After Photo



Before Photo



After Photo



Water tank has been Cleaned & disinfected

CRYSTALLINE CLEANING & ENVIRONMENTAL SERVICES

CLEANING & DISINFECTION CERTIFICATE

POTABLE WATER TANKS

CLIENT NAME : AL RAHA VILLAGAE PROPERTIES LLC.

CLIENT ADDRESS : P.O. BOX: 6634, ABU DHABI, UAE.

CONTACT PERSON : MR. BASHAR ABU SALIM.

SITE DETAILS : AL RAHA VILLAGE, ABU DHABI.

DETAILS : U/G RCC WATER TANK MOSQUE – 'B'

DATE OF CLEANING : 12 FEBRUARY 2020

FREQUENCY OF CLEANING : EVERY SIX MONTHS

DATE OF NEXT CLEANING : 12 AUGUST 2020

The procedures employed in this cleaning and disinfection comply with HS (G) 70 health and safety guidelines for prevention of legionella as well as BS6700 and CARELA BIO PLUS method statement.

The entire water storage tank should be disinfected minimum every Six (6) month depending upon the condition.




CRYSTALLINE CLEANING AND ENVIRONMENTAL SERVICES

Customer: Al Raha Village		Contact Person: Mr. Barshar Abu Salim	
Site: Al Raha Village		Contact Number: 0504886406	
Description: GRP Water Tank 1 Cleaning		Location: Between Hopital & Mosque	
Type Of Building : <input type="checkbox"/> Commercial <input checked="" type="checkbox"/> Residential <input type="checkbox"/> Others			
Type Of Tank			
<input type="checkbox"/> Concrete	<input checked="" type="checkbox"/> GRP Panel	<input type="checkbox"/> FRP Tank	<input type="checkbox"/> Galvanized
<input type="checkbox"/> Steel Panel	<input type="checkbox"/> Plastic	<input type="checkbox"/> Concrete Coated	<input type="checkbox"/> Polyurethane
<input type="checkbox"/> Others			
Condition before cleaning		Condition after cleaning	
<input type="checkbox"/> Clean	<input checked="" type="checkbox"/> Dirty	<input type="checkbox"/> Very Dirty	
<input type="checkbox"/> Biofilms	<input type="checkbox"/> Moulds	<input type="checkbox"/> Slime	
<input type="checkbox"/> Sediments	<input type="checkbox"/> Mud & Sand	<input type="checkbox"/> Rust	
<input checked="" type="checkbox"/> Clean		<input type="checkbox"/> Dirty	
<input checked="" type="checkbox"/> Biofilms		<input type="checkbox"/> Moulds	
<input checked="" type="checkbox"/> Sediments		<input type="checkbox"/> Mud & Sand	
<input type="checkbox"/> Very Dirty		<input type="checkbox"/> Very Dirty	
<input type="checkbox"/> Slime		<input type="checkbox"/> Slime	
<input type="checkbox"/> Rust		<input type="checkbox"/> Rust	
Size of Tank			
M3:		USG:	
		L*B*H:	
Quantity Of Water		Manhole	
<input type="checkbox"/> Full	<input checked="" type="checkbox"/> Half	<input type="checkbox"/> Empty	
<input type="checkbox"/> Covered		<input type="checkbox"/> Damaged	
<input checked="" type="checkbox"/> NA			
Ladder In		Ladder Out	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Leaks		<input type="checkbox"/> Yes	
<input checked="" type="checkbox"/> No			
Drain Line		Valves	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Float Valve		<input checked="" type="checkbox"/> Yes	
<input type="checkbox"/> No			
Tank Cleaned		Tank Disinfected	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Pipes Disinfected		<input type="checkbox"/> Yes	
<input checked="" type="checkbox"/> No			
Chemicals Used			
Chemical: Carela bio		Quantity: 500ml	
Chemical: Carela plus		Quantity: 500ml	
Equipments Used			
<input checked="" type="checkbox"/> Submersibel Pump	<input checked="" type="checkbox"/> High/low Pressure Jet	<input checked="" type="checkbox"/> Extension Cords	<input checked="" type="checkbox"/> LED Lights
<input checked="" type="checkbox"/> Foot Bath	<input checked="" type="checkbox"/> Ladder	<input checked="" type="checkbox"/> Ventilating Fan	<input checked="" type="checkbox"/> Oxygen Meter
<input checked="" type="checkbox"/> Vacuum Cleaner	<input checked="" type="checkbox"/> Cleaning Materials	<input checked="" type="checkbox"/> Suction/Discharge Hoses	
Last Cleaning Date		Current Cleaning Date	
-		16 February 2020	
		Next Cleaning Date	
		16 August 2020	
Crystalline Representative		Customer Representative	
			

GRP Water Tank 1 Cleaning


Before Photo



After Photo



Before Photo



After Photo



Mentioned tank has been Cleaned & disinfected

CRYSTALLINE CLEANING & ENVIRONMENTAL SERVICES

CLEANING & DISINFECTION CERTIFICATE

POTABLE WATER TANKS

CLIENT NAME : AL RAHA VILLAGAE PROPERTIES LLC.

CLIENT ADDRESS : P.O. BOX: 6634, ABU DHABI, UAE.

CONTACT PERSON : MR. BASHAR ABU SALIM

SITE DETAILS : AL RAHA VILLAGE, ABU DHABI.

DETAILS : GRP WATER TANK – 01 (B/W HOSPITAL & MOSQUE)

DATE OF CLEANING : 16 FEBRUARY 2020

FREQUENCY OF CLEANING : EVERY SIX MONTHS

DATE OF NEXT CLEANING : 16 AUGUST 2020

The procedures employed in this cleaning and disinfection comply with HS (G) 70 health and safety guidelines for prevention of legionella as well as BS6700 and CARELA BIO PLUS method statement.

The entire water storage tank should be disinfected minimum every Six (6) month depending upon the condition.




CRYSTALLINE CLEANING AND ENVIRONMENTAL SERVICES


Customer: Al Raha Village		Contact Person: Mr. Barshar Abu Salim	
Site: Al Raha Village		Contact Number: 0504886406	
Description: GRP Water Tank 2 Cleaning		Location: Between Hopital & Mosque	
Type Of Building : <input type="checkbox"/> Commercial <input checked="" type="checkbox"/> Residential <input type="checkbox"/> Others			
Type Of Tank			
<input type="checkbox"/> Concrete	<input checked="" type="checkbox"/> GRP Panel	<input type="checkbox"/> FRP Tank	<input type="checkbox"/> Galvanized
<input type="checkbox"/> Steel Panel	<input type="checkbox"/> Plastic	<input type="checkbox"/> Concrete Coated	<input type="checkbox"/> Polyurethane
<input type="checkbox"/> Others			
Condition before cleaning		Condition after cleaning	
<input type="checkbox"/> Clean	<input checked="" type="checkbox"/> Dirty	<input type="checkbox"/> Very Dirty	
<input type="checkbox"/> Biofilms	<input type="checkbox"/> Moulds	<input type="checkbox"/> Slime	
<input type="checkbox"/> Sediments	<input type="checkbox"/> Mud & Sand	<input type="checkbox"/> Rust	
<input checked="" type="checkbox"/> Clean		<input type="checkbox"/> Dirty	
<input checked="" type="checkbox"/> Biofilms		<input type="checkbox"/> Moulds	
<input checked="" type="checkbox"/> Sediments		<input type="checkbox"/> Mud & Sand	
<input type="checkbox"/> Very Dirty		<input type="checkbox"/> Slime	
<input type="checkbox"/> Slime		<input type="checkbox"/> Rust	
<input type="checkbox"/> Rust			
Size of Tank			
M3:		USG:	
		L*B*H:	
Quantity Of Water		Manhole	
<input type="checkbox"/> Full	<input checked="" type="checkbox"/> Half	<input type="checkbox"/> Empty	
<input type="checkbox"/> Covered		<input type="checkbox"/> Damaged	
<input checked="" type="checkbox"/> NA			
Ladder In		Ladder Out	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Leaks		Float Valve	
<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Drain Line		Valves	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Tank Cleaned		Tank Disinfected	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Pipes Disinfected			
<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No		
Chemicals Used			
Chemical: Carela bio		Quantity: 500ml	
Chemical: Carela plus		Quantity: 500ml	
Equipments Used			
<input checked="" type="checkbox"/> Submersibel Pump	<input checked="" type="checkbox"/> High/low Pressure Jet	<input checked="" type="checkbox"/> Extension Cords	<input checked="" type="checkbox"/> LED Lights
<input checked="" type="checkbox"/> Foot Bath	<input checked="" type="checkbox"/> Ladder	<input checked="" type="checkbox"/> Ventilating Fan	<input checked="" type="checkbox"/> Oxygen Meter
<input checked="" type="checkbox"/> Vacuum Cleaner	<input checked="" type="checkbox"/> Cleaning Materials	<input checked="" type="checkbox"/> Suction/Discharge Hoses	
Last Cleaning Date		Current Cleaning Date	
-		16 February 2020	
		Next Cleaning Date	
		16 August 2020	
Crystalline Representative		Customer Representative	
			

GRP Water Tank 2 Cleaning

Before Photo




After Photo



Before Photo



After Photo



Water tank has been Cleaned & disinfected

CRYSTALLINE CLEANING & ENVIRONMENTAL SERVICES

CLEANING & DISINFECTION CERTIFICATE

POTABLE WATER TANKS

CLIENT NAME : AL RAHA VILLAGAE PROPERTIES LLC.

CLIENT ADDRESS : P.O. BOX: 6634, ABU DHABI, UAE.

CONTACT PERSON : MR. BASHAR ABU SALIM

SITE DETAILS : AL RAHA VILLAGE, ABU DHABI.

DETAILS : GRP WATER TANK – 02 (B/W HOSPITAL & MOSQUE)

DATE OF CLEANING : 16 FEBRUARY 2020

FREQUENCY OF CLEANING : EVERY SIX MONTHS


DATE OF NEXT CLEANING : 16 AUGUST 2020

The procedures employed in this cleaning and disinfection comply with HS (G) 70 health and safety guidelines for prevention of legionella as well as BS6700 and CARELA BIO PLUS method statement.

The entire water storage tank should be disinfected minimum every Six (6) month depending upon the condition.



CRYSTALLINE CLEANING AND ENVIRONMENTAL SERVICES


Customer: Al Raha Village		Contact Person: Mr. Barshar Abu Salim	
Site: Al Raha Village		Contact Number: 0504886406	
Description: GRP Water Tank 3 Cleaning		Location: Between Hopital & Mosque	
Type Of Building : <input type="checkbox"/> Commercial <input checked="" type="checkbox"/> Residential <input type="checkbox"/> Others			
Type Of Tank			
<input type="checkbox"/> Concrete	<input checked="" type="checkbox"/> GRP Panel	<input type="checkbox"/> FRP Tank	<input type="checkbox"/> Galvanized
<input type="checkbox"/> Steel Panel	<input type="checkbox"/> Plastic	<input type="checkbox"/> Concrete Coated	<input type="checkbox"/> Polyurethane
<input type="checkbox"/> Others			
Condition before cleaning		Condition after cleaning	
<input type="checkbox"/> Clean	<input checked="" type="checkbox"/> Dirty	<input type="checkbox"/> Very Dirty	
<input type="checkbox"/> Biofilms	<input type="checkbox"/> Moulds	<input type="checkbox"/> Slime	
<input type="checkbox"/> Sediments	<input type="checkbox"/> Mud & Sand	<input type="checkbox"/> Rust	
<input checked="" type="checkbox"/> Clean		<input type="checkbox"/> Dirty	
<input type="checkbox"/> Biofilms		<input type="checkbox"/> Moulds	
<input type="checkbox"/> Sediments		<input type="checkbox"/> Slime	
<input type="checkbox"/> Mud & Sand		<input type="checkbox"/> Rust	
Size of Tank			
M3:		USG:	
		L*B*H:	
Quantity Of Water		Manhole	
<input type="checkbox"/> Full	<input checked="" type="checkbox"/> Half	<input type="checkbox"/> Empty	
<input type="checkbox"/> Covered		<input type="checkbox"/> Damaged	
<input checked="" type="checkbox"/> NA			
Ladder In		Ladder Out	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Leaks		<input type="checkbox"/> Yes	
<input checked="" type="checkbox"/> No			
Drain Line		Valves	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Float Valve		<input checked="" type="checkbox"/> Yes	
<input type="checkbox"/> No			
Tank Cleaned		Tank Disinfected	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Pipes Disinfected		<input type="checkbox"/> Yes	
<input checked="" type="checkbox"/> No			
Chemicals Used			
Chemical: Carela bio		Quantity: 500ml	
Chemical: Carela plus		Quantity: 500ml	
Equipments Used			
<input checked="" type="checkbox"/> Submersibel Pump	<input checked="" type="checkbox"/> High/low Pressure Jet	<input checked="" type="checkbox"/> Extension Cords	<input checked="" type="checkbox"/> LED Lights
<input checked="" type="checkbox"/> Foot Bath	<input checked="" type="checkbox"/> Ladder	<input checked="" type="checkbox"/> Ventilating Fan	<input checked="" type="checkbox"/> Oxygen Meter
<input checked="" type="checkbox"/> Vacuum Cleaner	<input checked="" type="checkbox"/> Cleaning Materials	<input checked="" type="checkbox"/> Suction/Discharge Hoses	
Last Cleaning Date		Current Cleaning Date	
-		16 February 2020	
		Next Cleaning Date	
		16 August 2020	
Crystalline Representative		Customer Representative	
			

GRP Water Tank 3 Cleaning

Before Photo




After Photo



Before Photo



After Photo



Mentioned tank has been Cleaned & disinfected

CRYSTALLINE CLEANING & ENVIRONMENTAL SERVICES

CLEANING & DISINFECTION CERTIFICATE

POTABLE WATER TANKS

CLIENT NAME : AL RAHA VILLGAE PROPERTIES LLC.

CLIENT ADDRESS : P.O. BOX: 6634, ABU DHABI, UAE.

CONTACT PERSON : MR. BASHAR ABU SALIM

SITE DETAILS : AL RAHA VILLAGE, ABU DHABI.

DETAILS : GRP WATER TANK – 03 (B/W HOSPITAL & MOSQUE)

DATE OF CLEANING : 16 FEBRUARY 2020

FREQUENCY OF CLEANING : EVERY SIX MONTHS

DATE OF NEXT CLEANING : 16 AUGUST 2020

The procedures employed in this cleaning and disinfection comply with HS (G) 70 health and safety guidelines for prevention of legionella as well as BS6700 and CARELA BIO PLUS method statement.

The entire water storage tank should be disinfected minimum every Six (6) month depending upon the condition.



CRYSTALLINE CLEANING AND ENVIRONMENTAL SERVICES