

WATER TANK CLEANING
&
DISINFECTION

COMPLETION REPORT

FOR

AN *d* AZ™

Client : ANDAZ CAPITAL GATE
Contact Person: Ms. Michelle Paulas
Housing Manager.
Site Details : Andaz Capital Gate,
Hyatt Capital Gate Hotel, ADNEC,
Abu Dhabi, UAE.
Date : 09 January 2019



CRYSTALLINE
ENVIRONMENTAL SERVICES

CRYSTALLINE ENVIRONMENTAL
SERVICES

P.O. BOX 131463, Abu Dhabi, U.A.E.

TEL: 02 6508930 FAX: 02 6508942

info@crystalline-uae.com

www.crystalline-uae.com





CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK – AFTER SERVICE REPORT

08956

CUSTOMER: <u>HYATT ACCOMODATION</u>			CONTACT PERSON: <u>MR-PURU</u>		
SITE DETAILS: <u>VILLA-NO-16</u>			CONTACT NO: <u>0562184516</u>		
TANK DETAILS: <u>SINTEX TANK</u>			LOCATION DETAILS: <u>GROUND FLOOR</u>		
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL		<input checked="" type="checkbox"/> RESIDENTIAL		<input type="checkbox"/> OTHERS	
TYPE OF TANK					
<input type="checkbox"/> CONCRETE	<input type="checkbox"/> GRP PANEL	<input type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED		<input checked="" type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS		
SIZE OF TANK			QUANTITY OF WATER		
M3	USG	L*B*H	<input checked="" type="checkbox"/> FULL	<input type="checkbox"/> HALF	<input type="checkbox"/> EMPTY
CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK AFTER CLEANING		
<input type="checkbox"/> CLEAN	<input checked="" type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input checked="" type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
ACCESS		MANHOLE		<input type="checkbox"/> COVERED	<input type="checkbox"/> DAMAGED
<input type="checkbox"/> NA					<input type="checkbox"/> NA
LADDER IN		LADDER OUT		LEAKS	
<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO
DRAIN LINE		VALVES		FLOAT VALVE	
<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO
TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> YES	<input type="checkbox"/> NO
LAST CLEANING DATE		CURRENT CLEANING DATE		NEXT CLEANING DATE	
		<u>17/12/2018</u>		<u>17/06/2019</u>	
CHEMICALS & EQUIPMENTS USED					
1. <u>CARELO BIO AND PLUS</u> Quantity <u>200 ML</u>					
2. _____ Quantity _____					
<input checked="" type="checkbox"/> Submersible Pump <input checked="" type="checkbox"/> High/Low Pressure Jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED lights <input checked="" type="checkbox"/> Foot Bath <input checked="" type="checkbox"/> Ladder					
<input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Meter <input checked="" type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials					
COMMENTS & RECOMMENDATIONS:					
<u>MENTIONED WATER TANK IS CLEANED AND DISINFECTED</u>					
Crystalline Representative: <u>SANKAR</u>			Signature: <u>[Signature]</u>		



CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK – AFTER SERVICE REPORT

08954

CUSTOMER: HYATT ACCOMODATION			CONTACT PERSON: MR-PURU		
SITE DETAILS: VILLA-NO-17			CONTACT NO: 0562184516		
TANK DETAILS: SINTEX TANK			LOCATION DETAILS: GROUND FLOOR		
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL		<input checked="" type="checkbox"/> RESIDENTIAL		<input type="checkbox"/> OTHERS	
TYPE OF TANK					
<input type="checkbox"/> CONCRETE	<input type="checkbox"/> GRP PANEL	<input type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED		<input checked="" type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS		
SIZE OF TANK			QUANTITY OF WATER		
M3	USG	L*B*H	<input checked="" type="checkbox"/> FULL	<input type="checkbox"/> HALF	<input type="checkbox"/> EMPTY
CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK AFTER CLEANING		
<input type="checkbox"/> CLEAN	<input checked="" type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input checked="" type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
ACCESS		MANHOLE		<input type="checkbox"/> COVERED	<input type="checkbox"/> DAMAGED
				<input type="checkbox"/> NA	
LADDER IN		LADDER OUT		LEAKS	
DRAIN LINE		VALVES		FLOAT VALVE	
<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO
<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO
TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> YES	<input type="checkbox"/> NO
				<input checked="" type="checkbox"/> NA	
LAST CLEANING DATE		CURRENT CLEANING DATE		NEXT CLEANING DATE	
		17/12/2018		17/06/2019	
CHEMICALS & EQUIPMENTS USED					
1. CARELO BIO AND PLUS Quantity 200 ML					
2. _____ Quantity _____					
<input checked="" type="checkbox"/> Submersible Pump <input checked="" type="checkbox"/> High/Low Pressure Jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED lights <input checked="" type="checkbox"/> Foot Bath <input checked="" type="checkbox"/> Ladder					
<input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Meter <input checked="" type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials					
COMMENTS & RECOMMENDATIONS:					
MENTIONED WATER TANK IS CLEANED AND DISINFECTED					
Crystalline Representative: SANKAR			Signature: <i>Sankar</i>		

Date of Cleaning: 17-12-2018

PHOTOGRAPHS

SINTEX WATER TANK (HYATT CAPITAL ACCOMMODATION – 16 & 17)

BEFORE



GROUND LEVEL SINTEX TANK 16



GROUND LEVEL SINTEX TANK 17



AFTER





CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK – AFTER SERVICE REPORT

08952

CUSTOMER: <u>HXATT ACCOMODATION</u>			CONTACT PERSON: <u>MR. PURU</u>		
SITE DETAILS: <u>VILLA-NO-18</u>			CONTACT NO: <u>0562184516</u>		
TANK DETAILS: <u>SINTEX TANK</u>			LOCATION DETAILS: <u>GROUND FLOOR</u>		
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL		<input checked="" type="checkbox"/> RESIDENTIAL		<input type="checkbox"/> OTHERS	
TYPE OF TANK					
<input type="checkbox"/> CONCRETE	<input type="checkbox"/> GRP PANEL	<input type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED		<input checked="" type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS		
SIZE OF TANK			QUANTITY OF WATER		
M3	USG	L*B*H	<input checked="" type="checkbox"/> FULL	<input type="checkbox"/> HALF	<input type="checkbox"/> EMPTY
CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK AFTER CLEANING		
<input type="checkbox"/> CLEAN	<input checked="" type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input checked="" type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
ACCESS		MANHOLE		<input type="checkbox"/> COVERED	<input type="checkbox"/> DAMAGED
<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> NA	<input type="checkbox"/> NA
LADDER IN		LADDER OUT		LEAKS	
<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO
TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> YES	<input type="checkbox"/> NO
LAST CLEANING DATE		CURRENT CLEANING DATE		NEXT CLEANING DATE	
		<u>17/12/2018</u>		<u>17/06/2019</u>	
CHEMICALS & EQUIPMENTS USED					
1. <u>CARELO BIO AND PLUS</u> Quantity <u>200 ml</u>					
2. _____ Quantity _____					
<input checked="" type="checkbox"/> Submersible Pump <input checked="" type="checkbox"/> High/Low Pressure Jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED lights <input checked="" type="checkbox"/> Foot Bath <input checked="" type="checkbox"/> Ladder					
<input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Meter <input checked="" type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials					
COMMENTS & RECOMMENDATIONS:					
<u>MENTIONED WATER TANK IS CLEANED AND DISINFECTED</u>					
Crystalline Representative: <u>SANKAR</u>			Signature: <u>[Signature]</u>		



CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT

19483

CUSTOMER: HYATT ACCOMODATION			CONTACT PERSON: MR-PURU		
SITE DETAILS: STAFF - ANDAZ VILLA NO. - 19			CONTACT NO: 0562184516		
TANK DETAILS: SINTEX TANK			LOCATION DETAILS: GROUND FLOOR		
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL		<input checked="" type="checkbox"/> RESIDENTIAL		<input type="checkbox"/> OTHERS	
TYPE OF TANK					
<input type="checkbox"/> CONCRETE	<input type="checkbox"/> GRP PANEL	<input type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED		<input checked="" type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS		
SIZE OF TANK			QUANTITY OF WATER		
M3	USG	L*B*H	<input checked="" type="checkbox"/> FULL	<input type="checkbox"/> HALF	<input type="checkbox"/> EMPTY
CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK AFTER CLEANING		
<input type="checkbox"/> CLEAN	<input checked="" type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input checked="" type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
ACCESS		MANHOLE		<input type="checkbox"/> COVERED	<input type="checkbox"/> DAMAGED
<input type="checkbox"/> LADDER IN	<input type="checkbox"/> LADDER OUT	LEAKS		DRAIN LINE	
<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO
TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> NA	
LAST CLEANING DATE		CURRENT CLEANING DATE		NEXT CLEANING DATE	
		17/12/2018		17/06/2019	
CHEMICALS & EQUIPMENTS USED					
1. CARELO BIO & PLUS Quantity 200 ml					
2. _____ Quantity _____					
<input checked="" type="checkbox"/> Submersibel Pump <input checked="" type="checkbox"/> High /Low Pressure jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED Lights <input checked="" type="checkbox"/> Foot Bath <input checked="" type="checkbox"/> Ladder <input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Mater <input checked="" type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials					
COMMENTS & RECOMMENDATIONS:					
MENTIONED WATER TANK IS CLEANED & DISINFECTED					
Crystalline Representative: SANKAR			Signature:		

Date of Cleaning: 17-12-2018

PHOTOGRAPHS


SINTEX WATER TANK (HYATT CAPITAL ACCOMMODATION – 18 & 19)

BEFORE



GROUND LEVEL SINTEX WATER TANK 18



GROUND LEVEL SINTEX WATER TANK 19



AFTER





CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK – AFTER SERVICE REPORT

08966

CUSTOMER: HYATT ACCOMODATION			CONTACT PERSON: MR- PURU		
SITE DETAILS: VILLA - NO - 7			CONTACT NO: 0562184516		
TANK DETAILS: SINTEX TANK			LOCATION DETAILS: GROUND FLOOR		
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL		<input checked="" type="checkbox"/> RESIDENTIAL		<input type="checkbox"/> OTHERS	
TYPE OF TANK					
<input type="checkbox"/> CONCRETE	<input type="checkbox"/> GRP PANEL	<input type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED		<input checked="" type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS		
SIZE OF TANK			QUANTITY OF WATER		
M3	USG	L*B*H	<input checked="" type="checkbox"/> FULL	<input type="checkbox"/> HALF	<input type="checkbox"/> EMPTY
CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK AFTER CLEANING		
<input type="checkbox"/> CLEAN	<input checked="" type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input checked="" type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
ACCESS		MANHOLE		<input type="checkbox"/> COVERED	<input type="checkbox"/> DAMAGED
<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input type="checkbox"/> NO
LADDER IN		LADDER OUT		LEAKS	
<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO
TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> YES	<input type="checkbox"/> NO
LAST CLEANING DATE		CURRENT CLEANING DATE		NEXT CLEANING DATE	
		18/12/2018		18/06/2019	
CHEMICALS & EQUIPMENTS USED					
1. CARELO Bio & PLUS Quantity 200 ml					
2. _____ Quantity _____					
<input checked="" type="checkbox"/> Submersible Pump <input checked="" type="checkbox"/> High/Low Pressure Jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED lights <input checked="" type="checkbox"/> Foot Bath <input checked="" type="checkbox"/> Ladder					
<input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Meter <input checked="" type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials					
COMMENTS & RECOMMENDATIONS:					
MENTIONED WATER TANK IS CLEANED & DISINFECTED					
Crystalline Representative: SANKAR			Signature:		



CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK – AFTER SERVICE REPORT

08965

CUSTOMER: <u>HYATT ACCOMODATION</u>			CONTACT PERSON: <u>MR- PURU</u>		
SITE DETAILS: <u>VILLA- NO -8</u>			CONTACT NO: <u>0562184516</u>		
TANK DETAILS: <u>SINTEX TANK</u>			LOCATION DETAILS: <u>GROUND FLOOR</u>		
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL		<input checked="" type="checkbox"/> RESIDENTIAL		<input type="checkbox"/> OTHERS	
TYPE OF TANK					
<input type="checkbox"/> CONCRETE	<input type="checkbox"/> GRP PANEL	<input type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED		<input checked="" type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS		
SIZE OF TANK			QUANTITY OF WATER		
M3	USG	L*B*H	<input checked="" type="checkbox"/> FULL	<input type="checkbox"/> HALF	<input type="checkbox"/> EMPTY
CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK AFTER CLEANING		
<input type="checkbox"/> CLEAN	<input checked="" type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input checked="" type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
ACCESS		MANHOLE		<input type="checkbox"/> COVERED	<input type="checkbox"/> DAMAGED
				<input type="checkbox"/> NA	
LADDER IN		LADDER OUT		LEAKS	
DRAIN LINE		VALVES		FLOAT VALVE	
<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO
TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> YES	<input type="checkbox"/> NO <input checked="" type="checkbox"/> NA
LAST CLEANING DATE		CURRENT CLEANING DATE		NEXT CLEANING DATE	
		<u>18/12/2018</u>		<u>18/06/2019</u>	
CHEMICALS & EQUIPMENTS USED					
1. <u>CARELO Bio 8 PLUS</u> Quantity <u>200 ml</u>					
2. _____ Quantity _____					
<input checked="" type="checkbox"/> Submersible Pump <input checked="" type="checkbox"/> High/Low Pressure Jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED lights <input checked="" type="checkbox"/> Foot Bath <input checked="" type="checkbox"/> Ladder <input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Meter <input checked="" type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials					
COMMENTS & RECOMMENDATIONS:					
<u>MENTIONED. TANK WATER TANK IS CLEANED AND DISINFECTED</u>					
Crystalline Representative: <u>SAANKAR</u>			Signature: <u>[Signature]</u>		



CRYSTALLINE
ENVIRONMENTAL SERVICES


Date of Cleaning: 18-12-2018

PHOTOGRAPHS


SINTEX WATER TANK (HYATT CAPITAL ACCOMMODATION – 07 & 08)

BEFORE



GROUND LEVEL SINTEX WATER TANK 07



GROUND LEVEL SINTEX WATER TANK 08



AFTER



CLEANER WATER GREENER TOMORROW



CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK – AFTER SERVICE REPORT

08964

CUSTOMER: <u>HYATT ACCOMODATION</u>			CONTACT PERSON: <u>MR-PURU</u>		
SITE DETAILS: <u>VILLA-NO-9</u>			CONTACT NO: <u>0562184516</u>		
TANK DETAILS: <u>SINTEX TANK</u>			LOCATION DETAILS: <u>GROUND FLOOR</u>		
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL		<input checked="" type="checkbox"/> RESIDENTIAL		<input type="checkbox"/> OTHERS	
TYPE OF TANK					
<input type="checkbox"/> CONCRETE	<input type="checkbox"/> GRP PANEL	<input type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED		<input checked="" type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS		
SIZE OF TANK			QUANTITY OF WATER		
M3	USG	L*B*H	<input checked="" type="checkbox"/> FULL	<input type="checkbox"/> HALF	<input type="checkbox"/> EMPTY
CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK AFTER CLEANING		
<input type="checkbox"/> CLEAN	<input checked="" type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input checked="" type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
ACCESS		MANHOLE		<input type="checkbox"/> COVERED	<input type="checkbox"/> DAMAGED
				<input type="checkbox"/> NA	
LADDER IN		LADDER OUT		LEAKS	
<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO
TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> YES	<input type="checkbox"/> NO
				<input checked="" type="checkbox"/> NA	
LAST CLEANING DATE		CURRENT CLEANING DATE		NEXT CLEANING DATE	
		<u>18/12/2018</u>		<u>18/06/2019</u>	
CHEMICALS & EQUIPMENTS USED					
1. <u>CARELO Bio 8 PLUS</u> Quantity <u>200 ml</u>					
2. _____ Quantity _____					
<input checked="" type="checkbox"/> Submersible Pump <input checked="" type="checkbox"/> High/Low Pressure Jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED lights <input checked="" type="checkbox"/> Foot Bath <input checked="" type="checkbox"/> Ladder					
<input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Meter <input checked="" type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials					
COMMENTS & RECOMMENDATIONS:					
<u>MENTIONED WATER TANK IS CLEANED AND DISINFECTED</u>					
Crystalline Representative: <u>SANKAR</u>			Signature: <u>[Signature]</u>		



CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK – AFTER SERVICE REPORT

08963

CUSTOMER: HYATT ACCOMODATION			CONTACT PERSON: MR- PURU		
SITE DETAILS: VILLA - NO - 10			CONTACT NO: 0562184516		
TANK DETAILS: SINTEX TANK			LOCATION DETAILS: GROUND FLOOR		
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL		<input checked="" type="checkbox"/> RESIDENTIAL		<input type="checkbox"/> OTHERS	
TYPE OF TANK					
<input type="checkbox"/> CONCRETE	<input type="checkbox"/> GRP PANEL	<input type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED		<input checked="" type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS		
SIZE OF TANK			QUANTITY OF WATER		
M3	USG	L*B*H	<input checked="" type="checkbox"/> FULL	<input type="checkbox"/> HALF	<input type="checkbox"/> EMPTY
CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK AFTER CLEANING		
<input type="checkbox"/> CLEAN	<input checked="" type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input checked="" type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
ACCESS		MANHOLE		<input type="checkbox"/> COVERED	<input type="checkbox"/> DAMAGED
				<input type="checkbox"/> NA	
LADDER IN		LADDER OUT		LEAKS	
<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO
DRAIN LINE		VALVES		FLOAT VALVE	
<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO
TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED	
<input type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> YES	<input type="checkbox"/> NO
				<input type="checkbox"/> NA	
LAST CLEANING DATE		CURRENT CLEANING DATE		NEXT CLEANING DATE	
		18/12/2018		18/06/2019	
CHEMICALS & EQUIPMENTS USED					
1. CARELO Bio & PLUS Quantity 200 ml					
2. _____ Quantity _____					
<input checked="" type="checkbox"/> Submersible Pump <input checked="" type="checkbox"/> High/Low Pressure Jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED lights <input checked="" type="checkbox"/> Foot Bath <input checked="" type="checkbox"/> Ladder					
<input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Meter <input checked="" type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials					
COMMENTS & RECOMMENDATIONS:					
MENTIONED WATER TANK IS CLEANED AND DISINFECTED					
Crystalline Representative: SANKAR			Signature: <i>Sankar</i>		



CRYSTALLINE
ENVIRONMENTAL SERVICES

Date of Cleaning: 18-12-2018

PHOTOGRAPHS


SINTEX WATER TANK (HYATT CAPITAL ACCOMMODATION – 09 & 10)

BEFORE



GROUND LEVEL SINTEX WATER TANK 09



GROUND LEVEL SINTEX WATER TANK 10



AFTER



CLEANER WATER GREENER TOMORROW



CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK – AFTER SERVICE REPORT

08962

CUSTOMER: <u>HYATT ACCOMODATION</u>			CONTACT PERSON: <u>MR. PURU</u>		
SITE DETAILS: <u>VILLA-NO-11</u>			CONTACT NO: <u>0562184516</u>		
TANK DETAILS: <u>SINTEX TANK</u>			LOCATION DETAILS: <u>GROUND FLOOR</u>		
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL		<input checked="" type="checkbox"/> RESIDENTIAL		<input type="checkbox"/> OTHERS	
TYPE OF TANK					
<input type="checkbox"/> CONCRETE	<input type="checkbox"/> GRP PANEL	<input type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED		<input checked="" type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS		
SIZE OF TANK			QUANTITY OF WATER		
M3	USG	L*B*H	<input checked="" type="checkbox"/> FULL	<input type="checkbox"/> HALF	<input type="checkbox"/> EMPTY
CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK AFTER CLEANING		
<input type="checkbox"/> CLEAN	<input checked="" type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input checked="" type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
ACCESS		MANHOLE	<input type="checkbox"/> COVERED	<input type="checkbox"/> DAMAGED	<input type="checkbox"/> NA
LADDER IN	LADDER OUT	LEAKS	DRAIN LINE	VALVES	FLOAT VALVE
<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO
TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED	
<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES <input type="checkbox"/> NO	<input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> NA	
LAST CLEANING DATE		CURRENT CLEANING DATE		NEXT CLEANING DATE	
		<u>18/12/2018</u>		<u>18/06/2019</u>	
CHEMICALS & EQUIPMENTS USED					
1. <u>CARELO BIO&PLUS</u> Quantity <u>200 ml</u>					
2. _____ Quantity _____					
<input checked="" type="checkbox"/> Submersible Pump <input checked="" type="checkbox"/> High/Low Pressure Jet <input checked="" type="checkbox"/> Extension Cords <input type="checkbox"/> LED lights <input checked="" type="checkbox"/> Foot Bath <input checked="" type="checkbox"/> Ladder					
<input checked="" type="checkbox"/> Ventilating Fan <input type="checkbox"/> Suction/Discharge Hoses <input type="checkbox"/> Oxygen Meter <input type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials					
COMMENTS & RECOMMENDATIONS:					
<u>MENTIONED WATER TANK IS CLEANED AND DISINFECTED</u>					
Crystalline Representative: <u>SANKAR</u>			Signature: <u>Puru</u>		



CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK – AFTER SERVICE REPORT

08961

CUSTOMER: <u>HYATT ACCOMODATION</u>			CONTACT PERSON: <u>MR. PURU</u>		
SITE DETAILS: <u>VILLA - NO - 12</u>			CONTACT NO: <u>0562184516</u>		
TANK DETAILS: <u>SINTEX TANK</u>			LOCATION DETAILS: <u>GROUND FLOOR</u>		
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL		<input checked="" type="checkbox"/> RESIDENTIAL		<input type="checkbox"/> OTHERS	
TYPE OF TANK					
<input type="checkbox"/> CONCRETE	<input type="checkbox"/> GRP PANEL	<input type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED		<input checked="" type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS		
SIZE OF TANK			QUANTITY OF WATER		
M3	USG	L*B*H	<input checked="" type="checkbox"/> FULL	<input type="checkbox"/> HALF	<input type="checkbox"/> EMPTY
CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK AFTER CLEANING		
<input type="checkbox"/> CLEAN	<input checked="" type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input checked="" type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
ACCESS		MANHOLE		<input type="checkbox"/> COVERED	<input type="checkbox"/> DAMAGED
				<input type="checkbox"/> NA	
LADDER IN		LADDER OUT		LEAKS	
<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO
DRAIN LINE		VALVES		FLOAT VALVE	
<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO
TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> YES	<input type="checkbox"/> NO
				<input checked="" type="checkbox"/> NA	
LAST CLEANING DATE		CURRENT CLEANING DATE		NEXT CLEANING DATE	
		<u>18/12/2018</u>		<u>18/06/2019</u>	
CHEMICALS & EQUIPMENTS USED					
1. <u>CARELO BIO AND PLUS</u> Quantity <u>200 ML</u>					
2. _____ Quantity _____					
<input checked="" type="checkbox"/> Submersible Pump <input checked="" type="checkbox"/> High/Low Pressure Jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED lights <input checked="" type="checkbox"/> Foot Bath <input checked="" type="checkbox"/> Ladder					
<input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Meter <input checked="" type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials					
COMMENTS & RECOMMENDATIONS:					
<u>MENTIONED WATER TANK IS CLEANED AND DISINFECTED</u>					
Crystalline Representative: <u>SANKAR</u>			Signature: <u>[Signature]</u>		



CRYSTALLINE
ENVIRONMENTAL SERVICES

Date of Cleaning: 18-12-2018

PHOTOGRAPHS


SINTEX WATER TANK (HYATT CAPITAL ACCOMMODATION – 11 & 12)

BEFORE



ROOF TOP SINTEX WATER TANK 11



ROOF TOP SINTEX WATER TANK 12



AFTER



CLEANER WATER GREENER TOMORROW



CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK – AFTER SERVICE REPORT

08960

CUSTOMER: HYATT ACCOMODATION			CONTACT PERSON: MR- PURU		
SITE DETAILS: VILLA-NO-13			CONTACT NO: 0562184516		
TANK DETAILS: SINTEX TANK			LOCATION DETAILS: GROUND FLOOR		
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL		<input checked="" type="checkbox"/> RESIDENTIAL		<input type="checkbox"/> OTHERS	
TYPE OF TANK					
<input type="checkbox"/> CONCRETE	<input type="checkbox"/> GRP PANEL	<input type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED		<input checked="" type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS		
SIZE OF TANK			QUANTITY OF WATER		
M3	USG	L*B*H	<input checked="" type="checkbox"/> FULL	<input type="checkbox"/> HALF	<input type="checkbox"/> EMPTY
CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK AFTER CLEANING		
<input type="checkbox"/> CLEAN	<input checked="" type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input checked="" type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
ACCESS		MANHOLE		<input type="checkbox"/> COVERED	<input type="checkbox"/> DAMAGED
				<input type="checkbox"/> NA	
LADDER IN		LADDER OUT		LEAKS	
<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO
TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> YES	<input type="checkbox"/> NO
				<input checked="" type="checkbox"/> NA	
LAST CLEANING DATE		CURRENT CLEANING DATE		NEXT CLEANING DATE	
		18/12/2018		18/06/2019	
CHEMICALS & EQUIPMENTS USED					
1. CARELO BIO AND PLUS Quantity 200 ml					
2. _____ Quantity _____					
<input checked="" type="checkbox"/> Submersible Pump <input checked="" type="checkbox"/> High/Low Pressure Jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED lights <input checked="" type="checkbox"/> Foot Bath <input checked="" type="checkbox"/> Ladder					
<input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Meter <input checked="" type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials					
COMMENTS & RECOMMENDATIONS:					
MENTIONED WATER TANK IS CLEANED AND DISINFECTED					
Crystalline Representative: SANKAR			Signature: <i>[Signature]</i>		



CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK – AFTER SERVICE REPORT

08959

CUSTOMER: HYATT ACCOMODATION			CONTACT PERSON: MR- PURU		
SITE DETAILS: VILLA-NO-14			CONTACT NO: 0562184516		
TANK DETAILS: SINTEX TANK			LOCATION DETAILS: GROUND FLOOR		
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL		<input checked="" type="checkbox"/> RESIDENTIAL		<input type="checkbox"/> OTHERS	
TYPE OF TANK					
<input type="checkbox"/> CONCRETE	<input type="checkbox"/> GRP PANEL	<input type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED		<input checked="" type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS		
SIZE OF TANK			QUANTITY OF WATER		
M3	USG	L*B*H	<input checked="" type="checkbox"/> FULL	<input type="checkbox"/> HALF	<input type="checkbox"/> EMPTY
CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK AFTER CLEANING		
<input type="checkbox"/> CLEAN	<input checked="" type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input checked="" type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
ACCESS		MANHOLE		<input type="checkbox"/> COVERED	<input type="checkbox"/> DAMAGED
<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input type="checkbox"/> NO
LADDER IN		LADDER OUT		VALVES	
<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO
TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> YES	<input type="checkbox"/> NO
LAST CLEANING DATE		CURRENT CLEANING DATE		NEXT CLEANING DATE	
		18/12/2018		18/06/2019	
CHEMICALS & EQUIPMENTS USED					
1. CARELO BIO AND PLUS Quantity 200 ML					
2. _____ Quantity _____					
<input checked="" type="checkbox"/> Submersible Pump <input checked="" type="checkbox"/> High/Low Pressure Jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED lights <input checked="" type="checkbox"/> Foot Bath <input checked="" type="checkbox"/> Ladder					
<input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Meter <input checked="" type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials					
COMMENTS & RECOMMENDATIONS:					
MENTIONED WATER TANK IS CLEANED AND DISINFECTED					
Crystalline Representative: SANKAR			Signature: Puru		



CRYSTALLINE
ENVIRONMENTAL SERVICES


Date of Cleaning: 18-12-2018

PHOTOGRAPHS

SINTEX WATER TANK (HYATT CAPITAL ACCOMMODATION – 13 & 14)

BEFORE



GROUND LEVEL SINTEX WATER TANK 13



GROUND LEVEL SINTEX WATER TANK 14



AFTER



CLEANER WATER GREENER TOMORROW



CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK – AFTER SERVICE REPORT

08958

CUSTOMER: HYATT ACCOMODATION			CONTACT PERSON: MR-PURU		
SITE DETAILS: VILLA-NO-15			CONTACT NO: 0562184516		
TANK DETAILS: SINTEX TANK			LOCATION DETAILS: GROUND FLOOR		
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL		<input checked="" type="checkbox"/> RESIDENTIAL		<input type="checkbox"/> OTHERS	
TYPE OF TANK					
<input type="checkbox"/> CONCRETE	<input type="checkbox"/> GRP PANEL	<input type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED		<input checked="" type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS		
SIZE OF TANK			QUANTITY OF WATER		
M3	USG	L*B*H	<input checked="" type="checkbox"/> FULL	<input type="checkbox"/> HALF	<input type="checkbox"/> EMPTY
CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK AFTER CLEANING		
<input type="checkbox"/> CLEAN	<input checked="" type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input checked="" type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
ACCESS		MANHOLE		<input type="checkbox"/> COVERED	<input type="checkbox"/> DAMAGED
				<input type="checkbox"/> NA	
LADDER IN		LADDER OUT		LEAKS	
DRAIN LINE		VALVES		FLOAT VALVE	
<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO
<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO
TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> YES	<input type="checkbox"/> NO
				<input checked="" type="checkbox"/> NA	
LAST CLEANING DATE		CURRENT CLEANING DATE		NEXT CLEANING DATE	
		18/12/2018		18/06/2019	
CHEMICALS & EQUIPMENTS USED					
1. CARELO BIO AND PLUS Quantity 200 ML					
2. _____ Quantity _____					
<input checked="" type="checkbox"/> Submersible Pump <input checked="" type="checkbox"/> High/Low Pressure Jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED lights <input checked="" type="checkbox"/> Foot Bath <input checked="" type="checkbox"/> Ladder					
<input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Meter <input checked="" type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials					
COMMENTS & RECOMMENDATIONS:					
MENTIONED WATER TANK IS CLEANED AND DISINFECTED					
Crystalline Representative: SANKAR			Signature:		



CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK – AFTER SERVICE REPORT

08967

CUSTOMER: <u>HYATT ACCOMODATION</u>			CONTACT PERSON: <u>MR-PURU</u>		
SITE DETAILS: <u>VILLA-NO-22</u>			CONTACT NO: <u>0562184516</u>		
TANK DETAILS: <u>SINTEX TANK</u>			LOCATION DETAILS: <u>GROUND FLOOR</u>		
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL		<input checked="" type="checkbox"/> RESIDENTIAL		<input type="checkbox"/> OTHERS	
TYPE OF TANK					
<input type="checkbox"/> CONCRETE	<input type="checkbox"/> GRP PANEL	<input type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED		<input checked="" type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS		
SIZE OF TANK			QUANTITY OF WATER		
M3	USG	L*B*H	<input checked="" type="checkbox"/> FULL	<input type="checkbox"/> HALF	<input type="checkbox"/> EMPTY
CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK AFTER CLEANING		
<input type="checkbox"/> CLEAN	<input checked="" type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input checked="" type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
ACCESS		MANHOLE		<input type="checkbox"/> COVERED	
<input type="checkbox"/> LADDER IN		<input type="checkbox"/> LADDER OUT		<input type="checkbox"/> DAMAGED	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input type="checkbox"/> NA	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input type="checkbox"/> YES	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input type="checkbox"/> NO	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input checked="" type="checkbox"/> YES	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input type="checkbox"/> NO	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input checked="" type="checkbox"/> YES	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input type="checkbox"/> NO	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input checked="" type="checkbox"/> YES	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input type="checkbox"/> NO	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input checked="" type="checkbox"/> YES	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input type="checkbox"/> NO	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input checked="" type="checkbox"/> YES	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input type="checkbox"/> NO	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input checked="" type="checkbox"/> YES	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input type="checkbox"/> NO	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input checked="" type="checkbox"/> YES	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input type="checkbox"/> NO	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input checked="" type="checkbox"/> YES	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input type="checkbox"/> NO	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input checked="" type="checkbox"/> YES	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input type="checkbox"/> NO	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input checked="" type="checkbox"/> YES	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input type="checkbox"/> NO	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input checked="" type="checkbox"/> YES	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input type="checkbox"/> NO	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input checked="" type="checkbox"/> YES	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input type="checkbox"/> NO	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input checked="" type="checkbox"/> YES	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input type="checkbox"/> NO	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input checked="" type="checkbox"/> YES	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input type="checkbox"/> NO	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input checked="" type="checkbox"/> YES	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input type="checkbox"/> NO	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input checked="" type="checkbox"/> YES	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input type="checkbox"/> NO	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input checked="" type="checkbox"/> YES	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input type="checkbox"/> NO	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input checked="" type="checkbox"/> YES	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input type="checkbox"/> NO	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input checked="" type="checkbox"/> YES	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input type="checkbox"/> NO	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input checked="" type="checkbox"/> YES	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input type="checkbox"/> NO	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input checked="" type="checkbox"/> YES	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input type="checkbox"/> NO	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input checked="" type="checkbox"/> YES	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input type="checkbox"/> NO	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input checked="" type="checkbox"/> YES	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input type="checkbox"/> NO	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input checked="" type="checkbox"/> YES	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input type="checkbox"/> NO	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input checked="" type="checkbox"/> YES	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input type="checkbox"/> NO	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input checked="" type="checkbox"/> YES	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input type="checkbox"/> NO	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input checked="" type="checkbox"/> YES	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input type="checkbox"/> NO	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input checked="" type="checkbox"/> YES	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input type="checkbox"/> NO	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input checked="" type="checkbox"/> YES	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input type="checkbox"/> NO	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input checked="" type="checkbox"/> YES	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input type="checkbox"/> NO	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input checked="" type="checkbox"/> YES	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input type="checkbox"/> NO	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input checked="" type="checkbox"/> YES	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input type="checkbox"/> NO	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input checked="" type="checkbox"/> YES	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input type="checkbox"/> NO	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input checked="" type="checkbox"/> YES	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input type="checkbox"/> NO	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input checked="" type="checkbox"/> YES	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input type="checkbox"/> NO	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input checked="" type="checkbox"/> YES	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input type="checkbox"/> NO	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input checked="" type="checkbox"/> YES	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input type="checkbox"/> NO	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input checked="" type="checkbox"/> YES	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input type="checkbox"/> NO	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input checked="" type="checkbox"/> YES	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input type="checkbox"/> NO	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input checked="" type="checkbox"/> YES	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input type="checkbox"/> NO	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input checked="" type="checkbox"/> YES	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input type="checkbox"/> NO	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input checked="" type="checkbox"/> YES	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input type="checkbox"/> NO	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input checked="" type="checkbox"/> YES	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input type="checkbox"/> NO	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input checked="" type="checkbox"/> YES	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input type="checkbox"/> NO	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input checked="" type="checkbox"/> YES	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input type="checkbox"/> NO	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input checked="" type="checkbox"/> YES	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input type="checkbox"/> NO	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input checked="" type="checkbox"/> YES	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input type="checkbox"/> NO	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input checked="" type="checkbox"/> YES	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input type="checkbox"/> NO	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input checked="" type="checkbox"/> YES	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input type="checkbox"/> NO	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input checked="" type="checkbox"/> YES	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input type="checkbox"/> NO	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input checked="" type="checkbox"/> YES	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input type="checkbox"/> NO	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input checked="" type="checkbox"/> YES	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input type="checkbox"/> NO	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input checked="" type="checkbox"/> YES	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input type="checkbox"/> NO	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input checked="" type="checkbox"/> YES	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input type="checkbox"/> NO	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input checked="" type="checkbox"/> YES	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input type="checkbox"/> NO	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input checked="" type="checkbox"/> YES	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input type="checkbox"/> NO	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input checked="" type="checkbox"/> YES	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input type="checkbox"/> NO	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input checked="" type="checkbox"/> YES	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input type="checkbox"/> NO	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input checked="" type="checkbox"/> YES	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input type="checkbox"/> NO	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input checked="" type="checkbox"/> YES	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input type="checkbox"/> NO	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input checked="" type="checkbox"/> YES	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input type="checkbox"/> NO	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input checked="" type="checkbox"/> YES	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input type="checkbox"/> NO	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input checked="" type="checkbox"/> YES	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input type="checkbox"/> NO	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input checked="" type="checkbox"/> YES	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input type="checkbox"/> NO	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input checked="" type="checkbox"/> YES	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input type="checkbox"/> NO	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input checked="" type="checkbox"/> YES	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input type="checkbox"/> NO	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input checked="" type="checkbox"/> YES	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input type="checkbox"/> NO	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input checked="" type="checkbox"/> YES	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input type="checkbox"/> NO	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input checked="" type="checkbox"/> YES	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input type="checkbox"/> NO	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input checked="" type="checkbox"/> YES	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input type="checkbox"/> NO	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input checked="" type="checkbox"/> YES	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input type="checkbox"/> NO	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input checked="" type="checkbox"/> YES	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input type="checkbox"/> NO	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input checked="" type="checkbox"/> YES	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input type="checkbox"/> NO	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input checked="" type="checkbox"/> YES	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input type="checkbox"/> NO	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input checked="" type="checkbox"/> YES	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input type="checkbox"/> NO	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input checked="" type="checkbox"/> YES	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input type="checkbox"/> NO	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input checked="" type="checkbox"/> YES	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input type="checkbox"/> NO	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input checked="" type="checkbox"/> YES	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input type="checkbox"/> NO	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input checked="" type="checkbox"/> YES	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input type="checkbox"/> NO	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input checked="" type="checkbox"/> YES	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input type="checkbox"/> NO	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input checked="" type="checkbox"/> YES	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input type="checkbox"/> NO	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input checked="" type="checkbox"/> YES	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input type="checkbox"/> NO	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input checked="" type="checkbox"/> YES	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input type="checkbox"/> NO	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input checked="" type="checkbox"/> YES	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input type="checkbox"/> NO	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input checked="" type="checkbox"/> YES	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input type="checkbox"/> NO	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input checked="" type="checkbox"/> YES	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input type="checkbox"/> NO	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input checked="" type="checkbox"/> YES	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input type="checkbox"/> NO	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input checked="" type="checkbox"/> YES	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input type="checkbox"/> NO	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input checked="" type="checkbox"/> YES	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input type="checkbox"/> NO	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input checked="" type="checkbox"/> YES	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input type="checkbox"/> NO	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input checked="" type="checkbox"/> YES	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input type="checkbox"/> NO	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input checked="" type="checkbox"/> YES	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input type="checkbox"/> NO	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input checked="" type="checkbox"/> YES	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input type="checkbox"/> NO	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input checked="" type="checkbox"/> YES	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input type="checkbox"/> NO	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input checked="" type="checkbox"/> YES	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input type="checkbox"/> NO	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input checked="" type="checkbox"/> YES	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input type="checkbox"/> NO	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input checked="" type="checkbox"/> YES	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input type="checkbox"/> NO	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input checked="" type="checkbox"/> YES	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input type="checkbox"/> NO	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input checked="" type="checkbox"/> YES	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input type="checkbox"/> NO	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input checked="" type="checkbox"/> YES	
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input type="checkbox"/> NO	
<input type="checkbox"/> YES					


Date of Cleaning: 18-12-2018

PHOTOGRAPHS

SINTEX WATER TANK (HYATT CAPITAL ACCOMMODATION – 15 & 22)

BEFORE



GROUND LEVEL SINTEX WATER TANK 15



GROUND LEVEL SINTEX WATER TANK 22



AFTER



CLEANER WATER GREENER TOMORROW



CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT

17451

CUSTOMER: <u>HYATT ACCOMMODATION</u>			CONTACT PERSON: <u>MR. PURU</u>		
SITE DETAILS: <u>VILLA NO. 20</u>			CONTACT NO: <u>0562184516</u>		
TANK DETAILS: <u>SINTEX TANK</u>			LOCATION DETAILS: <u>GROUND FLOOR</u>		
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL		<input type="checkbox"/> RESIDENTIAL		<input type="checkbox"/> OTHERS	
TYPE OF TANK					
<input type="checkbox"/> CONCRETE	<input type="checkbox"/> GRP PANEL	<input type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED		<input checked="" type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS		
SIZE OF TANK			QUANTITY OF WATER		
M3	USG	L*B*H	<input type="checkbox"/> FULL	<input checked="" type="checkbox"/> HALF	<input type="checkbox"/> EMPTY
CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK AFTER CLEANING		
<input type="checkbox"/> CLEAN	<input checked="" type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input checked="" type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
ACCESS		MANHOLE		<input type="checkbox"/> COVERED	
<input type="checkbox"/> DAMAGED		<input type="checkbox"/> NA			
LADDER IN		LADDER OUT		LEAKS	
DRAIN LINE		VALVES		FLOAT VALVE	
<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES <input type="checkbox"/> NO
TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> YES	<input type="checkbox"/> NO <input checked="" type="checkbox"/> NA
LAST CLEANING DATE		CURRENT CLEANING DATE		NEXT CLEANING DATE	
		<u>18/12/2018</u>		<u>18/06/2019</u>	
CHEMICALS & EQUIPMENTS USED					
1. <u>CARELO BIO - & PLUS</u> Quantity <u>200 ML</u>					
2. _____ Quantity _____					
<input checked="" type="checkbox"/> Submersibel Pump <input checked="" type="checkbox"/> High /Low Pressure jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED Lights <input checked="" type="checkbox"/> Foot Bath <input type="checkbox"/> Ladder					
<input checked="" type="checkbox"/> Ventilating Fan <input type="checkbox"/> Suction/Discharge Hoses <input type="checkbox"/> Oxygen Mater <input type="checkbox"/> Vacuum Cleaner <input type="checkbox"/> Cleaning Materials					
COMMENTS & RECOMMENDATIONS:					
<u>MENTIONED WATER TANK IS CLEANED & DISINFECTED</u>					
Crystalline Representative: <u>SANKAR</u>			Signature: <u>Puru</u>		



CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK – AFTER SERVICE REPORT

08968

CUSTOMER: HYATT ACCOMODATION			CONTACT PERSON: MR- PURU		
SITE DETAILS: VILLA- NO- 21			CONTACT NO: 0562184516		
TANK DETAILS: SINTEX TANK			LOCATION DETAILS: GROUND FLOOR		
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL		<input checked="" type="checkbox"/> RESIDENTIAL		<input type="checkbox"/> OTHERS	
TYPE OF TANK					
<input type="checkbox"/> CONCRETE	<input type="checkbox"/> GRP PANEL	<input type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED		<input checked="" type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS		
SIZE OF TANK			QUANTITY OF WATER		
M3	USG	L*B*H	<input checked="" type="checkbox"/> FULL	<input type="checkbox"/> HALF	<input type="checkbox"/> EMPTY
CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK AFTER CLEANING		
<input type="checkbox"/> CLEAN	<input checked="" type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input checked="" type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
ACCESS		MANHOLE		<input type="checkbox"/> COVERED	<input type="checkbox"/> DAMAGED
				<input type="checkbox"/> NA	
LADDER IN		LADDER OUT		LEAKS	
<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO
DRAIN LINE		VALVES		FLOAT VALVE	
<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO
TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> YES	<input type="checkbox"/> NO
				<input checked="" type="checkbox"/> NA	
LAST CLEANING DATE		CURRENT CLEANING DATE		NEXT CLEANING DATE	
		18/12/2018		18/06/2019	
CHEMICALS & EQUIPMENTS USED					
1. CARELO Bio 8 PLUS Quantity 200 ml					
2. _____ Quantity _____					
<input checked="" type="checkbox"/> Submersible Pump <input checked="" type="checkbox"/> High/Low Pressure Jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED lights <input checked="" type="checkbox"/> Foot Bath <input checked="" type="checkbox"/> Ladder					
<input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Meter <input checked="" type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials					
COMMENTS & RECOMMENDATIONS:					
MENTIONED WATER TANK IS CLEANED & DISINFECTED					
Crystalline Representative: SANKAR			Signature: <i>[Signature]</i>		



CRYSTALLINE
ENVIRONMENTAL SERVICES


Date of Cleaning: 18-12-2018

PHOTOGRAPHS


SINTEX WATER TANK (HYATT CAPITAL ACCOMMODATION – 20 & 21)

BEFORE



GROUND LEVEL SINTEX WATER TANK 20



GROUND LEVEL SINTEX WATER TANK 21



AFTER



CLEANER WATER GREENER TOMORROW



CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK – AFTER SERVICE REPORT

08969

CUSTOMER: <u>HYATT ACCOMODATION</u>			CONTACT PERSON: <u>MR- PURU</u>		
SITE DETAILS: <u>VILLA - GYM -</u>			CONTACT NO: <u>0562184516</u>		
TANK DETAILS: <u>SINTEX TANK</u>			LOCATION DETAILS: <u>GROUND FLOOR</u>		
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL		<input checked="" type="checkbox"/> RESIDENTIAL		<input type="checkbox"/> OTHERS	
TYPE OF TANK					
<input type="checkbox"/> CONCRETE	<input type="checkbox"/> GRP PANEL	<input type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED		<input checked="" type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS		
SIZE OF TANK			QUANTITY OF WATER		
M3	USG	L*B*H	<input checked="" type="checkbox"/> FULL	<input type="checkbox"/> HALF	<input type="checkbox"/> EMPTY
CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK AFTER CLEANING		
<input type="checkbox"/> CLEAN	<input checked="" type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input checked="" type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
ACCESS		MANHOLE		<input type="checkbox"/> COVERED	<input type="checkbox"/> DAMAGED
				<input type="checkbox"/> NA	
LADDER IN		LADDER OUT		LEAKS	
LADDER IN		LADDER OUT		DRAIN LINE	
<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO
VALVES		FLOAT VALVE			
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> YES	<input type="checkbox"/> NO
TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> YES	<input type="checkbox"/> NO
				<input checked="" type="checkbox"/> NA	
LAST CLEANING DATE		CURRENT CLEANING DATE		NEXT CLEANING DATE	
		<u>18/12/2018</u>		<u>18/06/2019</u>	
CHEMICALS & EQUIPMENTS USED					
1. <u>CARELO BIO & PLUS</u> Quantity <u>200 ML</u>					
2. _____ Quantity _____					
<input checked="" type="checkbox"/> Submersible Pump <input checked="" type="checkbox"/> High/Low Pressure Jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED lights <input type="checkbox"/> Foot Bath <input checked="" type="checkbox"/> Ladder					
<input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Meter <input type="checkbox"/> Vacuum Cleaner <input type="checkbox"/> Cleaning Materials					
COMMENTS & RECOMMENDATIONS:					
<u>MENTIONED WATER TANK IS CLEANED & DISINFECTED</u>					
Crystalline Representative: <u>SANKAR</u>			Signature: <u>[Signature]</u>		



CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK – AFTER SERVICE REPORT

08970

CUSTOMER: HYATT ACCOMODATION			CONTACT PERSON: MR- PURU		
SITE DETAILS: VILLA- GYM			CONTACT NO: 0562184516		
TANK DETAILS: FRP WATER TANK			LOCATION DETAILS: ROOF TOP		
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL		<input checked="" type="checkbox"/> RESIDENTIAL		<input type="checkbox"/> OTHERS	
TYPE OF TANK					
<input type="checkbox"/> CONCRETE	<input type="checkbox"/> GRP PANEL	<input checked="" type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED		<input checked="" type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS		
SIZE OF TANK			QUANTITY OF WATER		
M3	USG	L*B*H	<input checked="" type="checkbox"/> FULL	<input type="checkbox"/> HALF	<input type="checkbox"/> EMPTY
CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK AFTER CLEANING		
<input type="checkbox"/> CLEAN	<input checked="" type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input checked="" type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
ACCESS		MANHOLE		<input type="checkbox"/> COVERED	<input type="checkbox"/> DAMAGED
				<input type="checkbox"/> NA	
LADDER IN		LADDER OUT		LEAKS	
<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO		
				DRAIN LINE	
				<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO
				VALVES	
				<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO
				FLOAT VALVE	
				<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO
TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> YES	<input type="checkbox"/> NO
				<input checked="" type="checkbox"/> NA	
LAST CLEANING DATE		CURRENT CLEANING DATE		NEXT CLEANING DATE	
		18/12/2018		18/06/2019	
CHEMICALS & EQUIPMENTS USED					
1. CARELO Bio & PLUS Quantity 200 ml					
2. _____ Quantity _____					
<input checked="" type="checkbox"/> Submersible Pump <input checked="" type="checkbox"/> High/Low Pressure Jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED lights <input checked="" type="checkbox"/> Foot Bath <input checked="" type="checkbox"/> Ladder					
<input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Meter <input checked="" type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials					
COMMENTS & RECOMMENDATIONS:					
MENTIONED WATER TANK IS CLEANED & DISINFECTED					
Crystalline Representative: SANKAR			Signature:		




CRYSTALLINE
ENVIRONMENTAL SERVICES

Date of Cleaning: 18-12-2018

PHOTOGRAPHS
WATER TANK (HYATT CAPITAL ACCOMMODATION – GYM)

BEFORE



GROUND LEVEL SINTEX WATER TANK



ROOF TOP LEVEL FRP WATER TANK



AFTER



CLEANER WATER GREENER TOMORROW



CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK – AFTER SERVICE REPORT

08979

CUSTOMER: HYATT ACCOMODATION			CONTACT PERSON: MR- PURU		
SITE DETAILS: VILLA- NO- 7			CONTACT NO: 0564184518		
TANK DETAILS: FRP Water TANK			LOCATION DETAILS: ROOF TOP		
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL <input checked="" type="checkbox"/> RESIDENTIAL <input type="checkbox"/> OTHERS					
TYPE OF TANK					
<input type="checkbox"/> CONCRETE	<input type="checkbox"/> GRP PANEL	<input checked="" type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED		<input type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS		
SIZE OF TANK			QUANTITY OF WATER		
M3	USG	L*B*H	<input checked="" type="checkbox"/> FULL	<input type="checkbox"/> HALF	<input type="checkbox"/> EMPTY
CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK AFTER CLEANING		
<input type="checkbox"/> CLEAN	<input checked="" type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input checked="" type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
ACCESS		MANHOLE	<input type="checkbox"/> COVERED	<input type="checkbox"/> DAMAGED	<input type="checkbox"/> NA
LADDER IN	LADDER OUT	LEAKS	DRAIN LINE	VALVES	FLOAT VALVE
<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO
TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED	
<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES <input type="checkbox"/> NO	<input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> NA	
LAST CLEANING DATE		CURRENT CLEANING DATE		NEXT CLEANING DATE	
		19/12/2018		19/06/2019	
CHEMICALS & EQUIPMENTS USED					
1. CARELO Bio & PLUS Quantity 200 ml					
2. _____ Quantity _____					
<input checked="" type="checkbox"/> Submersible Pump <input checked="" type="checkbox"/> High/Low Pressure Jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED lights <input checked="" type="checkbox"/> Foot Bath <input checked="" type="checkbox"/> Ladder <input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Meter <input checked="" type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials					
COMMENTS & RECOMMENDATIONS:					
MENTIONED WATER TANK IS CLEANED & DISINFECTED					
Crystalline Representative: SANKAR			Signature:		



CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK – AFTER SERVICE REPORT

08978

CUSTOMER: HYATT ACCOMODATION			CONTACT PERSON: MR. PURU		
SITE DETAILS: VILLA- NO- 8			CONTACT NO: 0564184516		
TANK DETAILS: FRP WATER TANK			LOCATION DETAILS: ROOF TOP		
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL <input checked="" type="checkbox"/> RESIDENTIAL <input type="checkbox"/> OTHERS					
TYPE OF TANK					
<input type="checkbox"/> CONCRETE	<input type="checkbox"/> GRP PANEL	<input checked="" type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED		<input type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS		
SIZE OF TANK			QUANTITY OF WATER		
M3	USG	L*B*H	<input checked="" type="checkbox"/> FULL	<input type="checkbox"/> HALF	<input type="checkbox"/> EMPTY
CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK AFTER CLEANING		
<input type="checkbox"/> CLEAN	<input checked="" type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input checked="" type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
ACCESS		MANHOLE	<input type="checkbox"/> COVERED	<input type="checkbox"/> DAMAGED	<input type="checkbox"/> NA
LADDER IN		LADDER OUT		LEAKS	DRAIN LINE
<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO
TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> YES	<input type="checkbox"/> NO <input checked="" type="checkbox"/> NA
LAST CLEANING DATE		CURRENT CLEANING DATE		NEXT CLEANING DATE	
		19/12/2018		19/06/2019	
CHEMICALS & EQUIPMENTS USED					
1. CARELO BIO & PLUS Quantity 200 ML					
2. _____ Quantity _____					
<input checked="" type="checkbox"/> Submersible Pump	<input checked="" type="checkbox"/> High/Low Pressure Jet	<input checked="" type="checkbox"/> Extension Cords	<input checked="" type="checkbox"/> LED lights	<input checked="" type="checkbox"/> Foot Bath	<input checked="" type="checkbox"/> Ladder
<input checked="" type="checkbox"/> Ventilating Fan	<input checked="" type="checkbox"/> Suction/Discharge Hoses	<input checked="" type="checkbox"/> Oxygen Meter	<input checked="" type="checkbox"/> Vacuum Cleaner	<input type="checkbox"/> Cleaning Materials	
COMMENTS & RECOMMENDATIONS:					
MENTIONED WATER TANK IS CLEANED & DISINFECTED					
Crystalline Representative: SANKAR			Signature:		



CRYSTALLINE
ENVIRONMENTAL SERVICES


Date of Cleaning: 19-12-2018

PHOTOGRAPHS


FRP WATER TANK (HYATT CAPITAL ACCOMMODATION – 07 & 08)

BEFORE



ROOF TOP FRP WATER TANK 07



ROOF TOP FRP WATER TANK 08



AFTER



CLEANER WATER GREENER TOMORROW



CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK – AFTER SERVICE REPORT

08977

CUSTOMER: HYATT ACCOMMODATION			CONTACT PERSON: MR. PURU		
SITE DETAILS: VILLA-NO-9			CONTACT NO: 0562184516		
TANK DETAILS: FRP WATER TANK			LOCATION DETAILS: ROOF TOP		
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL		<input checked="" type="checkbox"/> RESIDENTIAL		<input type="checkbox"/> OTHERS	
TYPE OF TANK					
<input type="checkbox"/> CONCRETE	<input type="checkbox"/> GRP PANEL	<input checked="" type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED		<input checked="" type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS		
SIZE OF TANK			QUANTITY OF WATER		
M3	USG	L*B*H	<input checked="" type="checkbox"/> FULL	<input type="checkbox"/> HALF	<input type="checkbox"/> EMPTY
CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK AFTER CLEANING		
<input type="checkbox"/> CLEAN	<input checked="" type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input checked="" type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
ACCESS		MANHOLE		<input type="checkbox"/> COVERED	<input type="checkbox"/> DAMAGED
				<input type="checkbox"/> NA	
LADDER IN		LADDER OUT		LEAKS	
DRAIN LINE		VALVES		FLOAT VALVE	
<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO
<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO
TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> YES	<input type="checkbox"/> NO <input checked="" type="checkbox"/> NA
LAST CLEANING DATE		CURRENT CLEANING DATE		NEXT CLEANING DATE	
		19/12/2018		19/06/2019	
CHEMICALS & EQUIPMENTS USED					
1. CARELO Bio & PLUS Quantity 200ml					
2. _____ Quantity _____					
<input checked="" type="checkbox"/> Submersible Pump <input checked="" type="checkbox"/> High/Low Pressure Jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED lights <input checked="" type="checkbox"/> Foot Bath <input checked="" type="checkbox"/> Ladder					
<input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Meter <input checked="" type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials					
COMMENTS & RECOMMENDATIONS:					
MENTIONED WATER TANK IS CLEANED & DISINFECTED					
Crystalline Representative: SANKAR			Signature: <i>[Signature]</i>		



CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK – AFTER SERVICE REPORT

08976

CUSTOMER: <u>HYATT ACCOMODATION</u>			CONTACT PERSON: <u>MR- PURU</u>		
SITE DETAILS: <u>VILLA-NO-10</u>			CONTACT NO: <u>0562184516</u>		
TANK DETAILS: <u>FRP WATER TANK</u>			LOCATION DETAILS: <u>ROOF TOP</u>		
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL		<input checked="" type="checkbox"/> RESIDENTIAL		<input type="checkbox"/> OTHERS	
TYPE OF TANK					
<input type="checkbox"/> CONCRETE	<input type="checkbox"/> GRP PANEL	<input checked="" type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED		<input type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS		
SIZE OF TANK			QUANTITY OF WATER		
M3	USG	L*B*H	<input checked="" type="checkbox"/> FULL	<input type="checkbox"/> HALF	<input type="checkbox"/> EMPTY
CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK AFTER CLEANING		
<input type="checkbox"/> CLEAN	<input checked="" type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input checked="" type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
ACCESS		MANHOLE		<input type="checkbox"/> COVERED	<input type="checkbox"/> DAMAGED
				<input type="checkbox"/> NA	
LADDER IN		LADDER OUT		LEAKS	
<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO
DRAIN LINE		VALVES		FLOAT VALVE	
<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO
TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> YES	<input type="checkbox"/> NO
				<input checked="" type="checkbox"/> NA	
LAST CLEANING DATE		CURRENT CLEANING DATE		NEXT CLEANING DATE	
		<u>19/12/2018</u>		<u>19/06/2019</u>	
CHEMICALS & EQUIPMENTS USED					
1. <u>CARELO Bio & PLUS</u> Quantity <u>200 ml</u>					
2. _____ Quantity _____					
<input checked="" type="checkbox"/> Submersible Pump <input checked="" type="checkbox"/> High/Low Pressure Jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED lights <input checked="" type="checkbox"/> Foot Bath <input checked="" type="checkbox"/> Ladder					
<input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Meter <input checked="" type="checkbox"/> Vacuum Cleaner <input type="checkbox"/> Cleaning Materials					
COMMENTS & RECOMMENDATIONS:					
<u>MENTIONED WATER TANK IS CLEANED & DISINFECTED</u>					
Crystalline Representative: <u>SANKAR</u>			Signature: <u>[Signature]</u>		



CRYSTALLINE
ENVIRONMENTAL SERVICES

Date of Cleaning: 19-12-2018

PHOTOGRAPHS

FRP WATER TANK (HYATT CAPITAL ACCOMMODATION – 09 & 10)

BEFORE



ROOF TOP FRP WATER TANK 09



ROOF TOP FRP WATER TANK 10



AFTER



CLEANER WATER GREENER TOMORROW



CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK – AFTER SERVICE REPORT

08975

CUSTOMER: <u>HYATT ACCOMMODATION</u>			CONTACT PERSON: <u>MR - PURU</u>		
SITE DETAILS: <u>VILLA- NO - 11</u>			CONTACT NO: <u>0562184516</u>		
TANK DETAILS: <u>FRP WATER TANK</u>			LOCATION DETAILS: <u>ROOF TOP</u>		
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL		<input checked="" type="checkbox"/> RESIDENTIAL		<input type="checkbox"/> OTHERS	
TYPE OF TANK					
<input type="checkbox"/> CONCRETE	<input type="checkbox"/> GRP PANEL	<input checked="" type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED		<input type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS		
SIZE OF TANK			QUANTITY OF WATER		
M3	USG	L*B*H	<input checked="" type="checkbox"/> FULL	<input type="checkbox"/> HALF	<input type="checkbox"/> EMPTY
CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK AFTER CLEANING		
<input type="checkbox"/> CLEAN	<input checked="" type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input checked="" type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
ACCESS		MANHOLE		<input type="checkbox"/> COVERED	<input type="checkbox"/> DAMAGED
				<input type="checkbox"/> NA	
LADDER IN		LADDER OUT		LEAKS	
<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO
TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> YES	<input type="checkbox"/> NO
				<input checked="" type="checkbox"/> NA	
LAST CLEANING DATE		CURRENT CLEANING DATE		NEXT CLEANING DATE	
		<u>19/12/2018</u>		<u>19/06/2019</u>	
CHEMICALS & EQUIPMENTS USED					
1. <u>CARELO Bio & PLUS</u> Quantity <u>200 ml</u>					
2. _____ Quantity _____					
<input checked="" type="checkbox"/> Submersible Pump <input checked="" type="checkbox"/> High/Low Pressure Jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED lights <input checked="" type="checkbox"/> Foot Bath <input checked="" type="checkbox"/> Ladder <input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Meter <input checked="" type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials					
COMMENTS & RECOMMENDATIONS:					
<u>MENTIONED WATER TANK IS CLEANED & DISINFECTED</u>					
Crystalline Representative: <u>SANKAR</u>			Signature: <u>[Signature]</u>		



CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK – AFTER SERVICE REPORT

08974

CUSTOMER: HYATT ACCOMODATION			CONTACT PERSON: MR-PURU		
SITE DETAILS: VILLA-NO-12			CONTACT NO: 0562184516		
TANK DETAILS: FRP WATER TANK			LOCATION DETAILS: ROOF TOP		
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL <input checked="" type="checkbox"/> RESIDENTIAL <input type="checkbox"/> OTHERS					
TYPE OF TANK					
<input type="checkbox"/> CONCRETE	<input type="checkbox"/> GRP PANEL	<input checked="" type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED		<input type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS		
SIZE OF TANK			QUANTITY OF WATER		
M3	USG	L*B*H	<input checked="" type="checkbox"/> FULL	<input type="checkbox"/> HALF	<input type="checkbox"/> EMPTY
CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK AFTER CLEANING		
<input type="checkbox"/> CLEAN	<input checked="" type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input checked="" type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
ACCESS		MANHOLE	<input type="checkbox"/> COVERED	<input type="checkbox"/> DAMAGED	<input type="checkbox"/> NA
LADDER IN		LADDER OUT		LEAKS	DRAIN LINE
<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO
TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> YES	<input type="checkbox"/> NO <input checked="" type="checkbox"/> NA
LAST CLEANING DATE		CURRENT CLEANING DATE		NEXT CLEANING DATE	
		19/12/2018		19/06/2019	
CHEMICALS & EQUIPMENTS USED					
1. CARELO BIO & PLUS Quantity 200 ML					
2. _____ Quantity _____					
<input checked="" type="checkbox"/> Submersible Pump <input checked="" type="checkbox"/> High/Low Pressure Jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED lights <input checked="" type="checkbox"/> Foot Bath <input type="checkbox"/> Ladder					
<input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Suction/Discharge Hoses <input type="checkbox"/> Oxygen Meter <input checked="" type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials					
COMMENTS & RECOMMENDATIONS:					
MENTIONED WATER TANK IS CLEANED & DISINFECTED					
Crystalline Representative: SANKAR			Signature:		



CRYSTALLINE
ENVIRONMENTAL SERVICES


Date of Cleaning: 19-12-2018

PHOTOGRAPHS


FRP WATER TANK (HYATT CAPITAL ACCOMMODATION – 11 & 12)

BEFORE



ROOF TOP FRP WATER TANK 11



ROOF TOP FRP WATER TANK 12



AFTER



CLEANER WATER GREENER TOMORROW



CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK – AFTER SERVICE REPORT

08973

CUSTOMER: <u>HYATT ACCOMODATION</u>			CONTACT PERSON: <u>MR- PURU</u>		
SITE DETAILS: <u>VILLA- NO- 13</u>			CONTACT NO: <u>0562184516</u>		
TANK DETAILS: <u>FRP WATER TANK</u>			LOCATION DETAILS: <u>ROOF TOP</u>		
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL		<input checked="" type="checkbox"/> RESIDENTIAL		<input type="checkbox"/> OTHERS	
TYPE OF TANK					
<input type="checkbox"/> CONCRETE	<input type="checkbox"/> GRP PANEL	<input checked="" type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED		<input type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS		
SIZE OF TANK			QUANTITY OF WATER		
M3	USG	L*B*H	<input checked="" type="checkbox"/> FULL	<input type="checkbox"/> HALF	<input type="checkbox"/> EMPTY
CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK AFTER CLEANING		
<input type="checkbox"/> CLEAN	<input checked="" type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input checked="" type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
ACCESS		MANHOLE		<input type="checkbox"/> COVERED	<input type="checkbox"/> DAMAGED
				<input type="checkbox"/> NA	
LADDER IN		LADDER OUT		LEAKS	
DRAIN LINE		VALVES		FLOAT VALVE	
<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO
<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO
TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> YES	<input type="checkbox"/> NO
				<input checked="" type="checkbox"/> NA	
LAST CLEANING DATE		CURRENT CLEANING DATE		NEXT CLEANING DATE	
		<u>19/12/ 2018</u>		<u>19/06/ 2019</u>	
CHEMICALS & EQUIPMENTS USED					
1. <u>CARELO BIO & PLUS</u> Quantity <u>200 ml</u>					
2. _____ Quantity _____					
<input checked="" type="checkbox"/> Submersible Pump <input checked="" type="checkbox"/> High/Low Pressure Jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED lights <input checked="" type="checkbox"/> Foot Bath <input checked="" type="checkbox"/> Ladder					
<input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Meter <input checked="" type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials					
COMMENTS & RECOMMENDATIONS:					
<u>MENTIONED WATER TANK IS CLEANED & DISINFECTED</u>					
Crystalline Representative: <u>SANKAR</u>			Signature: <u>[Signature]</u>		



CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK – AFTER SERVICE REPORT

08972

CUSTOMER: <u>HYATT ACCOMODATION</u>			CONTACT PERSON: <u>MR-PURU</u>		
SITE DETAILS: <u>VILLA-NO-14</u>			CONTACT NO: <u>0562184516</u>		
TANK DETAILS: <u>FRP WATER TANK</u>			LOCATION DETAILS: <u>ROOF TOP</u>		
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL		<input checked="" type="checkbox"/> RESIDENTIAL		<input type="checkbox"/> OTHERS	
TYPE OF TANK					
<input type="checkbox"/> CONCRETE	<input type="checkbox"/> GRP PANEL	<input checked="" type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED		<input type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS		
SIZE OF TANK			QUANTITY OF WATER		
M3	USG	L*B*H	<input checked="" type="checkbox"/> FULL	<input type="checkbox"/> HALF	<input type="checkbox"/> EMPTY
CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK AFTER CLEANING		
<input type="checkbox"/> CLEAN	<input checked="" type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input checked="" type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
ACCESS		MANHOLE	<input type="checkbox"/> COVERED	<input type="checkbox"/> DAMAGED	<input type="checkbox"/> NA
LADDER IN	LADDER OUT	LEAKS	DRAIN LINE	VALVES	FLOAT VALVE
<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO
TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED	
<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES <input type="checkbox"/> NO	<input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> NA	
LAST CLEANING DATE		CURRENT CLEANING DATE		NEXT CLEANING DATE	
		<u>19/12/2018</u>		<u>19/06/2019</u>	
CHEMICALS & EQUIPMENTS USED					
1. <u>CARELO BIO & PLUS</u> Quantity <u>200 ml</u>					
2. _____ Quantity _____					
<input checked="" type="checkbox"/> Submersible Pump <input checked="" type="checkbox"/> High/Low Pressure Jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED lights <input checked="" type="checkbox"/> Foot Bath <input checked="" type="checkbox"/> Ladder <input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Meter <input checked="" type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials					
COMMENTS & RECOMMENDATIONS:					
<u>MENTIONED WATER TANK IS CLEANED & DISINFECTED</u>					
Crystalline Representative: <u>SANKAR</u>			Signature: <u>[Signature]</u>		




9Date of Cleaning: 19-12-2018

PHOTOGRAPHS

FRP WATER TANK (HYATT CAPITAL ACCOMMODATION –13 & 14)

BEFORE

ROOF TOP FRP WATER TANK- 13



ROOF TOP FRP WATER TANK- 14



AFTER





CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK – AFTER SERVICE REPORT

08971

CUSTOMER: HYATT ACCOMODATION			CONTACT PERSON: MR-PURU		
SITE DETAILS: VILLA-NO-15			CONTACT NO: 0562184516		
TANK DETAILS: FRP WATER TANK			LOCATION DETAILS: ROOF TOP		
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL		<input checked="" type="checkbox"/> RESIDENTIAL		<input type="checkbox"/> OTHERS	
TYPE OF TANK					
<input type="checkbox"/> CONCRETE	<input type="checkbox"/> GRP PANEL	<input checked="" type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED		<input type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS		
SIZE OF TANK			QUANTITY OF WATER		
M3	USG	L*B*H	<input checked="" type="checkbox"/> FULL	<input type="checkbox"/> HALF	<input type="checkbox"/> EMPTY
CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK AFTER CLEANING		
<input type="checkbox"/> CLEAN	<input checked="" type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input checked="" type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
ACCESS		MANHOLE		<input type="checkbox"/> COVERED	<input type="checkbox"/> DAMAGED
				<input type="checkbox"/> NA	
LADDER IN		LADDER OUT		LEAKS	
<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO
DRAIN LINE		VALVES		FLOAT VALVE	
<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO
TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> YES	<input type="checkbox"/> NO <input checked="" type="checkbox"/> NA
LAST CLEANING DATE		CURRENT CLEANING DATE		NEXT CLEANING DATE	
		19/02/2018		19/06/2019	
CHEMICALS & EQUIPMENTS USED					
1. CARELO Bio & PLUS Quantity 200 ML					
2. _____ Quantity _____					
<input checked="" type="checkbox"/> Submersible Pump <input checked="" type="checkbox"/> High/Low Pressure Jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED lights <input checked="" type="checkbox"/> Foot Bath <input checked="" type="checkbox"/> Ladder <input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Meter <input checked="" type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials					
COMMENTS & RECOMMENDATIONS:					
MENTIONED WATER TANK IS CLEANED & DISINFECTED					
Crystalline Representative: SANKAR			Signature:		



CRYSTALLINE
ENVIRONMENTAL SERVICES

Date of Cleaning: 19-12-2018

PHOTOGRAPHS

SINTEX WATER TANK (HYATT CAPITAL ACCOMMODATION- 15)

BEFORE



AFTER



CLEANER WATER GREENER TOMORROW



CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK – AFTER SERVICE REPORT

08957

CUSTOMER: <u>HYATT ACCOMODATION</u>			CONTACT PERSON: <u>MR-PURU</u>		
SITE DETAILS: <u>VILLA-NO-16</u>			CONTACT NO: <u>0562184516</u>		
TANK DETAILS: <u>FRP WATER TANK</u>			LOCATION DETAILS: <u>ROOF TOP</u>		
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL		<input checked="" type="checkbox"/> RESIDENTIAL		<input type="checkbox"/> OTHERS	
TYPE OF TANK					
<input type="checkbox"/> CONCRETE	<input type="checkbox"/> GRP PANEL	<input checked="" type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED		<input checked="" type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS		
SIZE OF TANK			QUANTITY OF WATER		
M3	USG	L*B*H	<input checked="" type="checkbox"/> FULL	<input type="checkbox"/> HALF	<input type="checkbox"/> EMPTY
CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK AFTER CLEANING		
<input type="checkbox"/> CLEAN	<input checked="" type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input checked="" type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
ACCESS		MANHOLE		<input type="checkbox"/> COVERED	<input type="checkbox"/> DAMAGED
				<input type="checkbox"/> NA	
LADDER IN		LADDER OUT		LEAKS	
<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO
DRAIN LINE		VALVES		FLOAT VALVE	
<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO
TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> YES	<input type="checkbox"/> NO
				<input checked="" type="checkbox"/> NA	
LAST CLEANING DATE		CURRENT CLEANING DATE		NEXT CLEANING DATE	
		<u>17/12/2018</u>		<u>17/06/2019</u>	
CHEMICALS & EQUIPMENTS USED					
1. <u>CARELO BIO AND PLUS</u> Quantity <u>200 ML</u>					
2. _____ Quantity _____					
<input checked="" type="checkbox"/> Submersible Pump <input checked="" type="checkbox"/> High/Low Pressure Jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED lights <input checked="" type="checkbox"/> Foot Bath <input checked="" type="checkbox"/> Ladder					
<input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Meter <input checked="" type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials					
COMMENTS & RECOMMENDATIONS:					
<u>MENTIONED WATER TANK IS CLEANED AND DISINFECTED</u>					
Crystalline Representative: <u>SANKAR</u>			Signature: <u>[Signature]</u>		



CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK – AFTER SERVICE REPORT

08955

CUSTOMER: <u>HYATT ACCOMODATION</u>			CONTACT PERSON: <u>MR- PURU</u>		
SITE DETAILS: <u>VILLA- NO- 17</u>			CONTACT NO: <u>0562184516</u>		
TANK DETAILS: <u>FRP WATER TANK</u>			LOCATION DETAILS: <u>ROOF TOP</u>		
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL			<input checked="" type="checkbox"/> RESIDENTIAL		<input type="checkbox"/> OTHERS
TYPE OF TANK					
<input type="checkbox"/> CONCRETE	<input type="checkbox"/> GRP PANEL	<input checked="" type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED		<input type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS		
SIZE OF TANK			QUANTITY OF WATER		
M3	USG	L*B*H	<input checked="" type="checkbox"/> FULL	<input type="checkbox"/> HALF	<input type="checkbox"/> EMPTY
CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK AFTER CLEANING		
<input type="checkbox"/> CLEAN	<input checked="" type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input checked="" type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
ACCESS		MANHOLE	<input type="checkbox"/> COVERED	<input type="checkbox"/> DAMAGED	<input type="checkbox"/> NA
LADDER IN	LADDER OUT	LEAKS	DRAIN LINE	VALVES	FLOAT VALVE
<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO
TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED	
<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES <input type="checkbox"/> NO	<input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> NA	
LAST CLEANING DATE		CURRENT CLEANING DATE		NEXT CLEANING DATE	
		<u>17/12/2018</u>		<u>17/06/2019</u>	
CHEMICALS & EQUIPMENTS USED					
1. <u>CARELO BIO AND PLUS</u> Quantity <u>200 ML</u>					
2. _____ Quantity _____					
<input checked="" type="checkbox"/> Submersible Pump <input checked="" type="checkbox"/> High/Low Pressure Jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED lights <input checked="" type="checkbox"/> Foot Bath <input checked="" type="checkbox"/> Ladder					
<input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Meter <input checked="" type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials					
COMMENTS & RECOMMENDATIONS:					
<u>MENTIONED WATER TANK IS CLEANED AND DISINFECTED</u>					
Crystalline Representative: <u>SANKAR</u>			Signature: <u>[Signature]</u>		


Date of Cleaning: 17-12-2018

PHOTOGRAPHS


FRP WATER TANK (HYATT CAPITAL ACCOMMODATION – 16 & 17)

BEFORE

ROOF TOP FRP WATER TANK 16



ROOF TOP FRP WATER TANK 17



AFTER





CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK – AFTER SERVICE REPORT

08953

CUSTOMER: <u>HYATT ACCOMODATION</u>			CONTACT PERSON: <u>MR-PLURU</u>		
SITE DETAILS: <u>VILLA-NO-18</u>			CONTACT NO: <u>0562184516</u>		
TANK DETAILS: <u>FRP WATER TANK</u>			LOCATION DETAILS: <u>ROOF TOP</u>		
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL		<input checked="" type="checkbox"/> RESIDENTIAL		<input type="checkbox"/> OTHERS	
TYPE OF TANK					
<input type="checkbox"/> CONCRETE	<input type="checkbox"/> GRP PANEL	<input checked="" type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED		<input checked="" type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS		
SIZE OF TANK			QUANTITY OF WATER		
M3	USG	L*B*H	<input checked="" type="checkbox"/> FULL	<input type="checkbox"/> HALF	<input type="checkbox"/> EMPTY
CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK AFTER CLEANING		
<input type="checkbox"/> CLEAN	<input checked="" type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input checked="" type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
ACCESS		MANHOLE		<input type="checkbox"/> COVERED	<input type="checkbox"/> DAMAGED
				<input type="checkbox"/> NA	
LADDER IN		LADDER OUT		LEAKS	
DRAIN LINE		VALVES		FLOAT VALVE	
<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO
<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO
TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> YES	<input type="checkbox"/> NO
				<input checked="" type="checkbox"/> NA	
LAST CLEANING DATE		CURRENT CLEANING DATE		NEXT CLEANING DATE	
		<u>17/12/2018</u>		<u>17/06/2019</u>	
CHEMICALS & EQUIPMENTS USED					
1. <u>CARELO BIO & PLUS</u> Quantity <u>200 ml</u>					
2. _____ Quantity _____					
<input checked="" type="checkbox"/> Submersible Pump <input checked="" type="checkbox"/> High/Low Pressure Jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED lights <input checked="" type="checkbox"/> Foot Bath <input checked="" type="checkbox"/> Ladder					
<input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Meter <input checked="" type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials					
COMMENTS & RECOMMENDATIONS:					
<u>MENTIONED WATER TANK IS CLEANED AND DISINFECTED</u>					
Crystalline Representative: <u>SANKAR</u>			Signature: <u>[Signature]</u>		





CRYSTALLINE
ENVIRONMENTAL SERVICES

Date of Cleaning: 17-12-2018


PHOTOGRAPHS

ROOF TOP FRP WATER TANK (HYATT CAPITAL ACCOMMODATION – 18)

BEFORE



AFTER



CLEANER WATER GREENER TOMORROW



CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT

19477

CUSTOMER: <i>Hyatt Accomodation</i>			CONTACT PERSON: <i>ms:- purvi</i>		
SITE DETAILS: <i>Sabaka villa no:- 19</i>			CONTACT NO: <i>025536132</i>		
TANK DETAILS: <i>F.R.P. water tank</i>			LOCATION DETAILS: <i>Roof top</i>		
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL		<input type="checkbox"/> RESIDENTIAL		<input type="checkbox"/> OTHERS	
TYPE OF TANK					
<input type="checkbox"/> CONCRETE	<input type="checkbox"/> GRP PANEL	<input checked="" type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED		<input type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS		
SIZE OF TANK			QUANTITY OF WATER		
M3	USG	L*B*H	<input type="checkbox"/> FULL	<input type="checkbox"/> HALF	<input type="checkbox"/> EMPTY
CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK AFTER CLEANING		
<input type="checkbox"/> CLEAN	<input checked="" type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input checked="" type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
ACCESS		MANHOLE		<input type="checkbox"/> DAMAGED	
<input type="checkbox"/> COVERED		<input checked="" type="checkbox"/> COVERED		<input type="checkbox"/> NA	
LADDER IN		LADDER OUT		LEAKS	
<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	
DRAIN LINE		VALVES		FLOAT VALVE	
<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO		<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO		<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	
TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED	
<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO		<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO		<input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> NA	
LAST CLEANING DATE		CURRENT CLEANING DATE		NEXT CLEANING DATE	
		<i>20/12/2018</i>		<i>20/06/2019</i>	
CHEMICALS & EQUIPMENTS USED					
1. <i>Carite bio plus</i> Quantity <i>250 ml</i>					
2. _____ Quantity _____					
<input checked="" type="checkbox"/> Submersibel Pump <input checked="" type="checkbox"/> High /Low Pressure jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED Lights <input checked="" type="checkbox"/> Foot Bath <input checked="" type="checkbox"/> Ladder <input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Mater <input checked="" type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials					
COMMENTS & RECOMMENDATIONS:					
<i>Above mentioned water tank are successfully cleared and disinfected.</i>					
Crystalline Representative: <i>Jasir. Shafiqdeen</i>			Signature: <i>Jasir</i>		

Jasir 20-12-018



CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT

19474

CUSTOMER: <i>Nyatt Accomodation</i>			CONTACT PERSON: <i>Ms:- priya</i>		
SITE DETAILS: <i>Shahal villa no:- 20</i>			CONTACT NO: <i>025536132</i>		
TANK DETAILS: <i>F.R.P. water tank</i>			LOCATION DETAILS: <i>Roof top</i>		
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL <input type="checkbox"/> RESIDENTIAL <input type="checkbox"/> OTHERS					
TYPE OF TANK					
<input type="checkbox"/> CONCRETE	<input type="checkbox"/> GRP PANEL	<input checked="" type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED		<input type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS		
SIZE OF TANK			QUANTITY OF WATER		
M3	USG	L*B*H	<input type="checkbox"/> FULL	<input type="checkbox"/> HALF	<input type="checkbox"/> EMPTY
CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK AFTER CLEANING		
<input type="checkbox"/> CLEAN	<input checked="" type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input checked="" type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
ACCESS		MANHOLE		<input checked="" type="checkbox"/> COVERED	<input type="checkbox"/> DAMAGED <input type="checkbox"/> NA
LADDER IN	LADDER OUT	LEAKS	DRAIN LINE	VALVES	FLOAT VALVE
<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO
TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> NA	
LAST CLEANING DATE		CURRENT CLEANING DATE		NEXT CLEANING DATE	
		<i>20/10/2018</i>		<i>20/06/2019</i>	
CHEMICALS & EQUIPMENTS USED					
1. <i>Carito bio plus</i> Quantity <i>250 ml</i>					
2. _____ Quantity _____					
<input checked="" type="checkbox"/> Submersibel Pump <input checked="" type="checkbox"/> High /Low Pressure jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED Lights <input checked="" type="checkbox"/> Foot Bath <input checked="" type="checkbox"/> Ladder					
<input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Mater <input checked="" type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials					
COMMENTS & RECOMMENDATIONS:					
<i>Above mentioned water tank are successfully cleared and disinfected</i>					
Crystalline Representative: <i>Jasin Shorofudeen</i>			Signature: <i>Jasin</i>		

Jasin 20-12-2018


Date of Cleaning: 20-12-2018

PHOTOGRAPHS


FRP WATER TANK (HYATT CAPITAL ACCOMMODATION – 19 & 20)

BEFORE


ROOF TOP FRP WATER TANK 19



ROOF TOP FRP WATER TANK 20



AFTER





CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT

19479

CUSTOMER: <i>Hyatt Accomodation</i>			CONTACT PERSON: <i>msr- puvu</i>		
SITE DETAILS: <i>Thawee villa no:- 21</i>			CONTACT NO: <i>0255 36132</i>		
TANK DETAILS: <i>F.R.P. water tank</i>			LOCATION DETAILS: <i>Roof top</i>		
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL		<input type="checkbox"/> RESIDENTIAL		<input type="checkbox"/> OTHERS	
TYPE OF TANK					
<input type="checkbox"/> CONCRETE	<input type="checkbox"/> GRP PANEL	<input checked="" type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED		<input type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS		
SIZE OF TANK			QUANTITY OF WATER		
M3	USG	L*B*H	<input type="checkbox"/> FULL	<input type="checkbox"/> HALF	<input type="checkbox"/> EMPTY
CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK AFTER CLEANING		
<input type="checkbox"/> CLEAN	<input checked="" type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input checked="" type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
ACCESS		MANHOLE		<input checked="" type="checkbox"/> COVERED	
				<input type="checkbox"/> DAMAGED	
				<input type="checkbox"/> NA	
LADDER IN		LADDER OUT		LEAKS	
<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	
TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED	
<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO		<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO		<input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> NA	
LAST CLEANING DATE		CURRENT CLEANING DATE		NEXT CLEANING DATE	
		<i>20/12/2018</i>		<i>20/06/2019</i>	
CHEMICALS & EQUIPMENTS USED					
1. <i>Carido bio plus</i> Quantity <i>250 ml</i>					
2. _____ Quantity _____					
<input checked="" type="checkbox"/> Submersibel Pump <input checked="" type="checkbox"/> High /Low Pressure jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED Lights <input checked="" type="checkbox"/> Foot Bath <input checked="" type="checkbox"/> Ladder					
<input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Mater <input checked="" type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials					
COMMENTS & RECOMMENDATIONS:					
<i>Above mentioned water tank are successfully cleaned and disinfected.</i>					
Crystalline Representative: <i>Jasir Sharafudeen</i>			Signature: <i>Jasir</i>		

Jasir 20-12-2018



CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT

19478

CUSTOMER: <i>Hyatt Accomodation</i>			CONTACT PERSON: <i>Ms:- puru</i>		
SITE DETAILS: <i>Marrara</i> <i>villa no:- 22</i>			CONTACT NO: <i>025536132</i>		
TANK DETAILS: <i>F.R.P. water tank</i>			LOCATION DETAILS: <i>Roof top</i>		
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL		<input type="checkbox"/> RESIDENTIAL		<input type="checkbox"/> OTHERS	
TYPE OF TANK					
<input type="checkbox"/> CONCRETE	<input type="checkbox"/> GRP PANEL	<input checked="" type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED		<input type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS		
SIZE OF TANK			QUANTITY OF WATER		
M3	USG	L*B*H	<input type="checkbox"/> FULL	<input type="checkbox"/> HALF	<input type="checkbox"/> EMPTY
CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK AFTER CLEANING		
<input type="checkbox"/> CLEAN	<input checked="" type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input checked="" type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
ACCESS		MANHOLE		<input checked="" type="checkbox"/> COVERED	
<input type="checkbox"/> DAMAGED		<input type="checkbox"/> NA			
LADDER IN		LADDER OUT		LEAKS	
<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	
DRAIN LINE		VALVES		FLOAT VALVE	
<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO		<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO		<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	
TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED	
<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO		<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO		<input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> NA	
LAST CLEANING DATE		CURRENT CLEANING DATE		NEXT CLEANING DATE	
		<i>20/12/2018</i>		<i>20/06/2019</i>	
CHEMICALS & EQUIPMENTS USED					
1. <i>Carito bio plus</i> Quantity <i>250 ml</i>					
2. _____ Quantity _____					
<input checked="" type="checkbox"/> Submersibel Pump <input checked="" type="checkbox"/> High /Low Pressure jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED Lights <input checked="" type="checkbox"/> Foot Bath <input checked="" type="checkbox"/> Ladder					
<input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Mater <input checked="" type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials					
COMMENTS & RECOMMENDATIONS:					
<i>Above mentioned water tank are successfully cleared and disinfected.</i>					
Crystalline Representative: <i>Jasir Sharafudan</i>			Signature: <i>Jasir</i>		

Jasir
20-12-2018



CRYSTALLINE
ENVIRONMENTAL SERVICES

Date of Cleaning: 20-12-2018

PHOTOGRAPHS


FRP WATER TANK (HYATT CAPITAL ACCOMMODATION – 21 & 22)

BEFORE



ROOF TOP FRP WATER TANK 21



ROOF TOP FRP WATER TANK 22



AFTER



CLEANER WATER GREENER TOMORROW

CRYSTALLINE CLEANING & ENVIRONMENTAL SERVICES

CLEANING & DISINFECTION CERTIFICATE

POTABLE WATER TANKS

CLIENT NAME : ANDZ CAPITAL GATE, ABU DHABI
CLIENT ADDRESS : P.O. BOX: 95165, ABU DHABI, UAE.
CONTACT PERSON : MICHELLE PAULAS.
SITE DETAILS : ANDAZ CAPITAL GATE ABU DHABI,
HYATT CAPITAL GATE HOTEL, ADNEC,
ABU DHABI, UAE.
DETAILS : WATER TANK CLEANING
DATE OF CLEANING : DECEMBER 2018
FREQUENCY OF CLEANING : EVERY SIX MONTHS
DATE OF NEXT CLEANING : JUNE 2019

The procedures employed in this cleaning and disinfection comply with HS (G) 70 health and safety guidelines for prevention of legionella as well as BS6700 and CARELA BIO PLUS method statement.

The entire water storage tank should be cleaned and disinfected minimum every six (6) months depending upon the condition.



CRYSTALLINE CLEANING AND ENVIRONMENTAL SERVICES