

DRAINLINE DISINFECTION

SERVICE REPORT

For



Client : Abu Dhabi International School.

Contact Person: Mr. George Alexander.

Site Details : Abu Dhabi International School,
Abu Dhabi, UAE.

Date : 29 August 2018



CRYSTALLINE
ENVIRONMENTAL SERVICES

**Crystalline environmental
services**

P.O. Box 131463, Abu Dhabi, U.A.E.

Tel: 02 6508930 Fax: 02 6508942

info@crystalline-uae.com

www.crystalline-uae.com



CRYSTALLINE ENVIRONMENTAL SERVICES

1005

MANHOLE, GULLY TRAP, DRAINAGE - AFTER SERVICE REPORT

CUSTOMER: INTERNATIONAL SCHOOL	CONTACT PERSON: Sunil
SITE DETAILS: ABU DHABI	CONTACT NUMBER: 050 8288531
NAME OF MANHOLE:	LOCALISQTION: Abu Dhabi
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL <input checked="" type="checkbox"/> EDUCATIONAL <input type="checkbox"/> RESIDENCIAL <input type="checkbox"/> INDUSTRIAL	

PART OF DRAINAGE

<input checked="" type="checkbox"/> MANHOLE	<input checked="" type="checkbox"/> UNDERGROUND DRAINAGE PIPE	<input checked="" type="checkbox"/> GULLY TRAP	<input type="checkbox"/> GREASE TRAP
<input checked="" type="checkbox"/> DRAINAGE PIPE	<input type="checkbox"/> APPARENT DRAINAGE PIPE	<input type="checkbox"/> EMBEDDED DRAINAGE PIPE	

CONDITION OF MANHOLE, GULLY TRAP, DRAINAGE BEFORE CLEANING

<input type="checkbox"/> LITTLE DIRTY	<input checked="" type="checkbox"/> DIRTY	<input checked="" type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> RUST	<input checked="" type="checkbox"/> SEDIMENTS	<input checked="" type="checkbox"/> MUD
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> SLIME	<input type="checkbox"/> GREASE	<input checked="" type="checkbox"/> ROOT	<input checked="" type="checkbox"/> SAND	<input type="checkbox"/> MOULDS
<input type="checkbox"/> OBSTRUCT	<input checked="" type="checkbox"/> BLOCK	<input checked="" type="checkbox"/> FLUENT FLOW	<input checked="" type="checkbox"/> LOW FLOW	<input type="checkbox"/> ANOTHER: _____	
MANHOLE BLOCKED	GULLY TRAP BLOCKED	DRAINAGE BLOCKED	ALL BLOCKED		
<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO		

COMMENTS: We had noticed the blockage of the drainage by the tree roots and kisu.

MANHOLE AND GULLY TRAP COVER: COVERED DAMAGED BLOCKED ADAPTED

CONDITION OF MANHOLE, GULLY TRAP, DRAINAGE AFTER CLEANING

<input type="checkbox"/> LITTLE CLEAN	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> VERY CLEAN	<input checked="" type="checkbox"/> FLUENT FLOW	<input type="checkbox"/> LOW FLOW	<input checked="" type="checkbox"/> UNBLOCK
NUMBER OF MANHOLE CLEANED	14	24	/	/	38
NUMBER OF MANHOLE BLOCKED	/	08	/	07	15

ACCESS

<input type="checkbox"/> LADDER IN	<input checked="" type="checkbox"/> NO LADDER			
MANHOLE CLEANED	GULLY TRAP CLEANED	DRAINAGE CLEANED	ALL DISINFECTED	
<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO				

SERVICES OF DATES

LAST CLEANING DATE	LAST CLEANING DATE	LAST CLEANING DATE
	20/08/2018	20/09/2019

CHEMICALS AND EQUIPMENTS USED

<input checked="" type="checkbox"/> PRESSURE MACHINE	<input checked="" type="checkbox"/> JETTING MACHINE	<input type="checkbox"/> MULTIGAS DETECTEUR	<input checked="" type="checkbox"/> INLET WATER HOSE
<input checked="" type="checkbox"/> EXTENTION CORDS	<input checked="" type="checkbox"/> VACCUM CLEANER	<input type="checkbox"/> VENTILATION FAN	<input checked="" type="checkbox"/> CLEANING MAT
<input checked="" type="checkbox"/> LED LIGHTS	<input checked="" type="checkbox"/> PLASTICS ROLL	<input checked="" type="checkbox"/> PLASTICS BAGS	<input checked="" type="checkbox"/> SUITABLE PPE
<input type="checkbox"/> TRIPOD	<input checked="" type="checkbox"/> AIR REPAIR 7D-A	<input type="checkbox"/> DEGREASER CHEMICAL	<input checked="" type="checkbox"/> LADDER

COMMENTS AND RECOMMENDATION: Manhole, gully trap and drainage pipe have been finished.

Crystalline representative: Patrick	Signature:
Customer/Customer representative: Sunil	Signature:



CRYSTALLINE ENVIRONMENTAL SERVICES

1006

MANHOLE, GULLY TRAP, DRAINAGE - AFTER SERVICE REPORT

CUSTOMER: <u>INTERNATIONAL SCHOOL</u>		CONTACT PERSON: <u>SUNIL</u>			
SITE DETAILS: <u>ABU DHABI</u>		CONTACT NUMBER: <u>050 8288531</u>			
NAME OF MANHOLE:		LOCALISATION: <u>Abudhabi</u>			
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL <input checked="" type="checkbox"/> EDUCATIONAL <input type="checkbox"/> RESIDENCIAL <input type="checkbox"/> INDUSTRIAL					
PART OF DRAINAGE					
<input checked="" type="checkbox"/> MANHOLE <input checked="" type="checkbox"/> UNDERGROUND DRAINAGE PIPE <input checked="" type="checkbox"/> GULLY TRAP <input checked="" type="checkbox"/> GREASE TRAP					
<input checked="" type="checkbox"/> DRAINAGE PIPE <input checked="" type="checkbox"/> APPARENT DRAINAGE PIPE <input type="checkbox"/> EMBEDDED DRAINAGE PIPE					
CONDITION OF MANHOLE, GULLY TRAP, DRAINAGE BEFORE CLEANING					
<input type="checkbox"/> LITTLE DIRTY <input checked="" type="checkbox"/> DIRTY <input type="checkbox"/> VERY DIRTY <input checked="" type="checkbox"/> RUST <input checked="" type="checkbox"/> SEDIMENTS <input type="checkbox"/> MUD					
<input type="checkbox"/> BIOFILMS <input type="checkbox"/> SLIME <input type="checkbox"/> GREASE <input type="checkbox"/> ROOT <input checked="" type="checkbox"/> SAND <input type="checkbox"/> MOULDS					
<input type="checkbox"/> OBSTRUCT <input type="checkbox"/> BLOCK <input checked="" type="checkbox"/> FLUENT FLOW <input checked="" type="checkbox"/> LOW FLOW <input type="checkbox"/> ANOTHER: _____					
MANHOLE BLOCKED		GULLY TRAP BLOCKED			
<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO			
DRAINAGE BLOCKED		ALL BLOCKED			
<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO			
COMMENTS: <u>We found some tissu inside the manhole.</u>					
MANHOLE AND GULLY TRAP COVER: <input checked="" type="checkbox"/> COVERED <input type="checkbox"/> DAMAGED <input type="checkbox"/> BLOCKED <input type="checkbox"/> ADAPTED					
CONDITION OF MANHOLE, GULLY TRAP, DRAINAGE AFTER CLEANING					
<input type="checkbox"/> LITTLE CLEAN <input checked="" type="checkbox"/> CLEAN <input type="checkbox"/> VERY CLEAN <input checked="" type="checkbox"/> FLUENT FLOW <input type="checkbox"/> LOW FLOW <input type="checkbox"/> UNBLOCK					
	MANHOLE	GULLY TRAP	STORM WATER	DRAINAGE	TOTAL
NUMBER OF MANHOLE CLEANED	<u>15</u>	<u>15</u>	<u>1</u>	<u>09</u>	<u>32</u>
NUMBER OF MANHOLE BLOCKED	<u>1</u>	<u>1</u>	<u>1</u>	<u>02</u>	<u>02</u>
ACCESS					
<input type="checkbox"/> LADDER IN <input checked="" type="checkbox"/> NO LADDER					
MANHOLE CLEANED		GULLY TRAP CLEANED		DRAINAGE CLEANED	
<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	
SERVICES OF DATES					
LAST CLEANING DATE		LAST CLEANING DATE		LAST CLEANING DATE	
		<u>21/08/2018</u>		<u>21/02/2019</u>	
CHEMICALS AND EQUIPMENTS USED					
<input checked="" type="checkbox"/> PRESSURE MACHINE <input checked="" type="checkbox"/> JETTING MACHINE <input type="checkbox"/> MULTIGAS DETECTEUR <input checked="" type="checkbox"/> INLET WATER HOSE					
<input checked="" type="checkbox"/> EXTENTION CORDS <input checked="" type="checkbox"/> VACCUM CLEANER <input type="checkbox"/> VENTILATION FAN <input checked="" type="checkbox"/> CLEANING MAT					
<input checked="" type="checkbox"/> LED LIGHTS <input checked="" type="checkbox"/> PLASTICS ROLL <input checked="" type="checkbox"/> PLASTICS BAGS <input checked="" type="checkbox"/> SUITABLE PPE					
<input type="checkbox"/> TRIPOD <input checked="" type="checkbox"/> AIR REPAIR 7D-A <input checked="" type="checkbox"/> DEGREASER CHEMICAL <input checked="" type="checkbox"/> LADDER					
COMMENTS AND RECOMMENDATION:					
<u>Manhole, grease trap, gully trap, Drainage pipe have been finished</u>					
Crystalline representative: <u>Patrick</u>				Signature:	
Customer/Customer representative: <u>SUNIL</u>				Signature:	



CRYSTALLINE
ENVIRONMENTAL SERVICES

Date of Cleaning: 20&21.08.2018

PHOTOGRAPHS
MANHOLE, GULLY TRAPS, DRAIN LINES CLEANING

BEFORE



AFTER



CLEANER WATER GREENER TOMORROW



Date of Cleaning: 20&21.08.2018

PHOTOGRAPHS
MANHOLE, GULLY TRAPS, DRAIN LINES CLEANING

BEFORE



75
74
73
72
71
70

AFTER



Date of Cleaning: 20&21.08.2018

PHOTOGRAPHS
MANHOLE, GULLY TRAPS, DRAIN LINES CLEANING

BEFORE



AFTER





Date of Cleaning: 20&21.08.2018

PHOTOGRAPHS
MANHOLE, GULLY TRAPS, DRAIN LINES CLEANING

BEFORE



AFTER






CRYSTALLINE
ENVIRONMENTAL SERVICES


Date of Cleaning: 20&21.08.2018

PHOTOGRAPHS
MANHOLE, GULLY TRAPS, DRAIN LINES CLEANING

BEFORE



AFTER



CLEANER WATER GREENER TOMORROW

Date of Cleaning: 20&21.08.2018

PHOTOGRAPHS
MANHOLE, GULLY TRAPS, DRAIN LINES CLEANING

BEFORE



AFTER



CLEANER WATER GREENER TOMORROW



CRYSTALLINE
ENVIRONMENTAL SERVICES

Date of Cleaning: 20&21.08.2018

PHOTOGRAPHS
MANHOLE, GRULLY TRAPS, DRAIN LINES CLEANING

BEFORE



AFTER



CLEANER WATER GREENER TOMORROW

CRYSTALLINE CLEANING & ENVIRONMENTAL SERVICES

CLEANING & DISINFECTION CERTIFICATE

CLIENT NAME : ABU DHABI INTERNATIONAL (PVT) SCHOOL.

CLIENT ADDRESS : P.O. BOX: 25898, ABU DHABI, UAE.

CONTACT PERSON : MR. GEORGE ALEXANDER.

SITE DETAILS : ABU DHABI INTERNATIONAL SCHOOL
COMPOUND, ABU DHABI, UAE.

DETAILS : CLEANING & FLUSHING OF DRAINLINES

DATE OF CLEANING : 20 AUGUST 2018

FREQUENCY OF CLEANING : EVERY SIX (6) MONTHS

DATE OF NEXT CLEANING : 20 FEBRUARY 2019

The procedures employed in this cleaning and disinfection comply with Abu Dhabi Municipality guidelines

The entire Sewage & Drain lines should be cleaned and disinfected minimum every six (6) months depending upon the condition.



CRYSTALLINE CLEANING AND ENVIRONMENTAL SERVICES