

WATER TANK CLEANING
&
DISINFECTION

COMPLETION REPORT

FOR



Client : Advanced Facilities Management.
Contact Person: Mr. Kennedy Pereira
Operational Manager.
Site Details : ENEC - Ruwais, Abu Dhabi, UAE.
Date : 04 February 2019



CRYSTALLINE
ENVIRONMENTAL SERVICES

CRYSTALLINE ENVIRONMENTAL
SERVICES

P.O. BOX 131463, Abu Dhabi, U.A.E.

TEL: 02 6508930 FAX: 02 6508942

info@crystalline-uae.com

www.crystalline-uae.com





CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT

17901

CUSTOMER: <u>ADVANCE FACILITY MANAGE</u>			CONTACT PERSON: <u>MR - JOY</u>		
SITE DETAILS: <u>ENEC BARAKA</u> <u>RUWAB</u>			CONTACT NO: <u>056-5368606</u>		
TANK DETAILS: <u>PCC POOL W' TANK</u>			LOCATION DETAILS: <u>GROUND</u>		
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL		<input type="checkbox"/> RESIDENTIAL		<input checked="" type="checkbox"/> OTHERS	
TYPE OF TANK					
<input checked="" type="checkbox"/> CONCRETE	<input type="checkbox"/> GRP PANEL	<input type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED		<input type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS		
SIZE OF TANK			QUANTITY OF WATER		
M3	<u>3000</u>	USG	L*B*H	<input checked="" type="checkbox"/> FULL	<input type="checkbox"/> HALF
<input type="checkbox"/> EMPTY					
CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK AFTER CLEANING		
<input type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input checked="" type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
ACCESS		MANHOLE		<input checked="" type="checkbox"/> COVERED	<input type="checkbox"/> DAMAGED
<input type="checkbox"/> NA					<input type="checkbox"/> NA
LADDER IN	LADDER OUT	LEAKS	DRAIN LINE	VALVES	FLOAT VALVE
<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO
TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO <input type="checkbox"/> NA
LAST CLEANING DATE		CURRENT CLEANING DATE		NEXT CLEANING DATE	
		<u>01-02-2019</u>		<u>01-07-2019</u>	
CHEMICALS & EQUIPMENTS USED					
1. <u>CARECO BIO 8 PLUS</u> Quantity <u>150 ML</u>					
2. _____ Quantity _____					
<input checked="" type="checkbox"/> Submersibel Pump <input checked="" type="checkbox"/> High /Low Pressure jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED Lights <input checked="" type="checkbox"/> Foot Bath <input type="checkbox"/> Ladder <input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Mater <input type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials					
COMMENTS & RECOMMENDATIONS:					
Crystalline Representative: <u>E. ANSARI</u>			Signature: <u>[Signature]</u>		

Thirupathi Raja
[Signature]
11/2/19


Date of Cleaning: 01-02-2019

PHOTOGRAPHS
GROUND LEVEL RCC POOL WATER TANK- 01

BEFORE



AFTER



CLEANER WATER GREENER TOMORROW



CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT

17903

CUSTOMER: <u>ADVANCE FM</u>			CONTACT PERSON: <u>MR-JOY</u>		
SITE DETAILS: <u>ENEC BRAKA</u> <u>RUWAIS</u>			CONTACT NO: <u>056-5368666</u>		
TANK DETAILS: <u>RCC-IRRIGATION TANK</u>			LOCATION DETAILS: <u>GROUND</u>		
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL		<input type="checkbox"/> RESIDENTIAL		<input checked="" type="checkbox"/> OTHERS	
TYPE OF TANK					
<input checked="" type="checkbox"/> CONCRETE	<input type="checkbox"/> GRP PANEL	<input type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED		<input type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS		
SIZE OF TANK			QUANTITY OF WATER		
M3	<u>7000</u>	USG	L*B*H	<input checked="" type="checkbox"/> FULL	<input checked="" type="checkbox"/> HALF
			<input type="checkbox"/> EMPTY		
CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK AFTER CLEANING		
<input type="checkbox"/> CLEAN	<input checked="" type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input checked="" type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input checked="" type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
ACCESS		MANHOLE		<input checked="" type="checkbox"/> COVERED	
				<input type="checkbox"/> DAMAGED	
				<input type="checkbox"/> NA	
LADDER IN		LADDER OUT		LEAKS	
DRAIN LINE		VALVES		FLOAT VALVE	
<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO
TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO <input type="checkbox"/> NA
LAST CLEANING DATE		CURRENT CLEANING DATE		NEXT CLEANING DATE	
		<u>01-02-2019</u>		<u>01-07-2019</u>	
CHEMICALS & EQUIPMENTS USED					
1. <u>CARECO BIO PLUS</u> Quantity <u>250 ML</u>					
2. _____ Quantity _____					
<input checked="" type="checkbox"/> Submersible Pump <input type="checkbox"/> High/Low Pressure jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED Lights <input checked="" type="checkbox"/> Foot Bath <input type="checkbox"/> Ladder					
<input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Meter <input type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials					
COMMENTS & RECOMMENDATIONS:					
Crystalline Representative: <u>KANSARI</u>			Signature: <u>[Signature]</u>		

Thirupathi Ravi
[Signature]
11/2/19





CRYSTALLINE
ENVIRONMENTAL SERVICES


Date of Cleaning: 01-02-2019

PHOTOGRAPHS
GROUND LEVEL RCC IRRIGATION WATER TANK

BEFORE



AFTER



CLEANER WATER GREENER TOMORROW



CRYSTALLINE ENVIRONMENTAL SERVICES

AFTER SERVICE REPORT

1702

CUSTOMER: ADVANCE FM CONTACT PERSON: MR-JAY

SITE DETAILS: ENEC-BRAKA-RUWAS CONTACT NO: 056-5368606

DATE: 01-02-2019

SWIMMING POOL & WATER FOUNTAIN DETAILS & TESTING

SWIMMING POOL CLEANING, REMOVED MUD, SANDS DIRTY - USING JETTING MACHINE, CHEMICALS BRUSH, CLEANED.

CLEANING & VACUUMING

REMOVE LEAF & PARTICLES	<input checked="" type="checkbox"/> Y/N	BRUSH WALL & FLOOR	<input checked="" type="checkbox"/> Y/N	VACUUM ENTIRE POOL	<input type="checkbox"/> Y/N
-------------------------	-----------------------------------------	--------------------	-----------------------------------------	--------------------	------------------------------

FILTRATION CLEANING

FILTER BACKWASHING	<input type="checkbox"/> Y/N	STRAINER CLEANING	<input checked="" type="checkbox"/> Y/N	CHEMICAL ADDITION	<input checked="" type="checkbox"/> Y/N
--------------------	------------------------------	-------------------	-----------------------------------------	-------------------	-----------------------------------------

CHEMICALS & EQUIPMENTS USED

TELESCOPIC ROD VACUUM HOSE VACUUM HEAD ALGAE BRUSH CHLORINE POOL ACID CHLORINE TABLETS
 CRYSTAL CARE CRYSTAL CLEAR SODA ASH DEEP NET LEAF NET TEST KIT

COMMENTS & RECOMMENDATIONS:

CRYSTALLINE REPRESENTATIVE: ANBARI

SIGNATURE: [Signature]

Thirupathi Raja

[Signature]
11/2/19



CRYSTALLINE
ENVIRONMENTAL SERVICES

Date of Cleaning: 01-02-2019

PHOTOGRAPHS

SWIMMING POOL DEEP CLEANING- ENEC

BEFORE



AFTER



CLEANER WATER GREENER TOMORROW



CRYSTALLINE
ENVIRONMENTAL SERVICES

Date of Cleaning: 01-02-2019


PHOTOGRAPHS

SWIMMING POOL DEEP CLEANING

BEFORE



AFTER



CLEANER WATER GREENER TOMORROW

Date of Cleaning: 01-02-2019


PHOTOGRAPHS

SWIMMING POOL DEEP CLEANING

BEFORE



AFTER




CLEANER WATER GREENER TOMORROW

Date of Cleaning: 01-02-2019


PHOTOGRAPHS

SWIMMING POOL DEEP CLEANING

BEFORE



AFTER



CLEANER WATER GREENER TOMORROW




CRYSTALLINE
ENVIRONMENTAL SERVICES

Date of Cleaning: 01-02-2019

PHOTOGRAPHS

SWIMMING POOL DEEP CLEANING

BEFORE



AFTER



CLEANER WATER GREENER TOMORROW

CRYSTALLINE CLEANING & ENVIRONMENTAL SERVICES

CLEANING & DISINFECTION CERTIFICATE

SWIMMING POOL WATER TANKS

CLIENT NAME : ADVANCED FACILITIES MANAGEMENT.
CLIENT ADDRESS : P.O. BOX: 44038, ABU DHABI, UAE.
CONTACT PERSON : MR. KENNEDY PEREIRA.
SITE DETAILS : ENEC – RUWAIS, ABU DHABI, UAE.
DETAILS : WATER TANK CLEANING
DATE OF CLEANING : FEBRUARY 2019
FREQUENCY OF CLEANING : EVERY FOUR MONTHS
DATE OF NEXT CLEANING : JUNE 2019

The procedures employed in this cleaning and disinfection comply with HS (G) 70 health and safety guidelines for prevention of legionella as well as BS6700 and CARELA BIO PLUS method statement.

The entire water storage tank should be cleaned and disinfected minimum every four (4) months depending upon the condition.

