

**ENVIRONMENTAL  
SERVICES FOR  
A GREENER  
TOMORROW...  
ONE STEP AT  
A TIME.**



Completion Report for

## **Water Tank Cleaning & Disinfection**

Date: **20 September 2020**  
Client Name: **Al Raha Viilage Properties LLC**  
Contact Person: **Mr. Bashar Abu Salim**  
Designation: **QHSE**  
Site Detail: **Al Raha Village - Abu Dhabi**



# Service Report



<b>Customer:</b> Al Raha Village Properties LLC		<b>Contact Person:</b> Mr. Bashar Abu Salim	
<b>Site:</b> Al Raha Village, Abu Dhabi		<b>Contact Number:</b> 050488 6406	
<b>Description:</b> GRP Water Tank 01		<b>Location:</b> GROUND LEVEL, BETWEEN HOSPITAL & MOSQUE	
<b>Type Of Building :</b>		<input checked="" type="checkbox"/> Commercial	<input type="checkbox"/> Residential <input type="checkbox"/> Others
<b>Type Of Tank</b>			
<input type="checkbox"/> Concrete	<input checked="" type="checkbox"/> GRP Panel	<input type="checkbox"/> FRP Tank	<input type="checkbox"/> Galvanized
<input type="checkbox"/> Steel Panel	<input type="checkbox"/> Plastic	<input type="checkbox"/> Concrete Coated	<input type="checkbox"/> Polyurethane
<input type="checkbox"/> Others			
<b>Condition before cleaning</b>		<b>Condition after cleaning</b>	
<input type="checkbox"/> Clean	<input type="checkbox"/> Dirty	<input checked="" type="checkbox"/> Very Dirty	<input checked="" type="checkbox"/> Clean
<input type="checkbox"/> Biofilms	<input type="checkbox"/> Moulds	<input type="checkbox"/> Slime	<input type="checkbox"/> Dirty
<input type="checkbox"/> Sediments	<input type="checkbox"/> Mud & Sand	<input type="checkbox"/> Rust	<input type="checkbox"/> Very Dirty
		<input type="checkbox"/> Biofilms	<input type="checkbox"/> Moulds
		<input type="checkbox"/> Sediments	<input type="checkbox"/> Mud & Sand
		<input type="checkbox"/> Rust	<input type="checkbox"/> Rust
<b>Size of Tank</b>			
<b>M3:</b>		<b>USG:</b> 126802.56	<b>L*B*H:</b>
<b>Quantity Of Water</b>		<b>Manhole</b>	
<input type="checkbox"/> Full	<input checked="" type="checkbox"/> Half	<input type="checkbox"/> Empty	<input checked="" type="checkbox"/> Covered
		<input type="checkbox"/> Damaged	<input type="checkbox"/> NA
<b>Ladder In</b>		<b>Ladder Out</b>	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
		<b>Leaks</b>	
		<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
<b>Drain Line</b>		<b>Valves</b>	
<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
		<b>Float Valve</b>	
		<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
<b>Tank Cleaned</b>		<b>Tank Disinfected</b>	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
		<b>Pipes Disinfected</b>	
		<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
<b>Chemicals Used</b>			
<b>Chemical:</b> Carela bio & plus		<b>Quantity:</b> 2000ml	
<b>Chemical:</b>		<b>Quantity:</b>	
<b>Equipments Used</b>			
<input checked="" type="checkbox"/> Submersibel Pump	<input checked="" type="checkbox"/> High/low Pressure Jet	<input checked="" type="checkbox"/> Extension Cords	<input checked="" type="checkbox"/> LED Lights
<input checked="" type="checkbox"/> Foot Bath	<input checked="" type="checkbox"/> Ladder	<input checked="" type="checkbox"/> Ventilating Fan	<input checked="" type="checkbox"/> Oxygen Meter
<input checked="" type="checkbox"/> Vacuum Cleaner	<input checked="" type="checkbox"/> Cleaning Materials	<input checked="" type="checkbox"/> Suction/Discharge Hoses	
<b>Last Cleaning Date</b>		<b>Current Cleaning Date</b>	
-		09 September 2020	
		<b>Next Cleaning Date</b>	
		09 March 2021	
<b>Crystalline Representative</b>		<b>Customer Representative</b>	
			

## GRP Water Tank 01


Before Photo



After Photo



Before Photo



After Photo



Water tank cleaned and disinfected

# CRYSTALLINE CLEANING & ENVIRONMENTAL SERVICES

## CLEANING & DISINFECTION CERTIFICATE POTABLE WATER TANKS

CLIENT NAME : AL RAHA VILLGAE PROPERTIES LLC.  
CLIENT ADDRESS : P.O. BOX: 6634, ABU DHABI, UAE.  
CONTACT PERSON : MR. BASHAR ABU SALIM  
SITE DETAILS : AL RAHA VILLAGE, ABU DHABI.  
DETAILS : GRP WATER TANK – 01 (B/W HOSPITAL & MOSQUE)  
DATE OF CLEANING : 09 SEPTEMBER 2020  
FREQUENCY OF CLEANING : EVERY SIX MONTHS  
DATE OF NEXT CLEANING : 09 MARCH 2021

*The procedures employed in this cleaning and disinfection comply with HS (G) 70 health and safety guidelines for prevention of legionella as well as BS6700 and CARELA BIO PLUS method statement.*

*The entire water storage tank should be disinfected minimum every Six (6) month depending upon the condition.*



CRYSTALLINE CLEANING AND ENVIRONMENTAL SERVICES

# Service Report



<b>Customer:</b> Al Raha Viilage Properties LLC		<b>Contact Person:</b> Mr. Bashar Abu Salim	
<b>Site:</b> Al Raha Village, Abu Dhabi		<b>Contact Number:</b> 050488 6406	
<b>Description:</b> GRP Water Tank 02		<b>Location:</b> GROUND LEVEL, BETWEEN HOSPITAL & MOSQUE	
<b>Type Of Building :</b> <input checked="" type="checkbox"/> Commercial <input type="checkbox"/> Residential <input type="checkbox"/> Others			
<b>Type Of Tank</b>			
<input type="checkbox"/> Concrete	<input checked="" type="checkbox"/> GRP Panel	<input type="checkbox"/> FRP Tank	<input type="checkbox"/> Galvanized
<input type="checkbox"/> Steel Panel	<input type="checkbox"/> Plastic	<input type="checkbox"/> Concrete Coated	<input type="checkbox"/> Polyurethane
<input type="checkbox"/> Others			
<b>Condition before cleaning</b>		<b>Condition after cleaning</b>	
<input type="checkbox"/> Clean	<input type="checkbox"/> Dirty	<input checked="" type="checkbox"/> Very Dirty	<input checked="" type="checkbox"/> Clean
<input type="checkbox"/> Biofilms	<input type="checkbox"/> Moulds	<input type="checkbox"/> Slime	<input type="checkbox"/> Dirty
<input type="checkbox"/> Sediments	<input type="checkbox"/> Mud & Sand	<input type="checkbox"/> Rust	<input type="checkbox"/> Very Dirty
<b>Size of Tank</b>			
<b>M3:</b>		<b>USG:</b> 126802.56	<b>L*B*H:</b>
<b>Quantity Of Water</b>		<b>Manhole</b>	
<input type="checkbox"/> Full	<input checked="" type="checkbox"/> Half	<input type="checkbox"/> Empty	<input checked="" type="checkbox"/> Covered
<input type="checkbox"/> Damaged		<input type="checkbox"/> NA	
<b>Ladder In</b>		<b>Ladder Out</b>	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
<b>Leaks</b>		<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	
<b>Drain Line</b>		<b>Valves</b>	
<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
<b>Float Valve</b>		<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	
<b>Tank Cleaned</b>		<b>Tank Disinfected</b>	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
<b>Pipes Disinfected</b>		<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	
<b>Chemicals Used</b>			
<b>Chemical:</b> Carela bio & plus		<b>Quantity:</b> 2000ml	
<b>Chemical:</b>		<b>Quantity:</b>	
<b>Equipments Used</b>			
<input checked="" type="checkbox"/> Submersibel Pump	<input checked="" type="checkbox"/> High/low Pressure Jet	<input checked="" type="checkbox"/> Extension Cords	<input checked="" type="checkbox"/> LED Lights
<input checked="" type="checkbox"/> Foot Bath	<input checked="" type="checkbox"/> Ladder	<input checked="" type="checkbox"/> Ventilating Fan	<input checked="" type="checkbox"/> Oxygen Meter
<input checked="" type="checkbox"/> Vacuum Cleaner	<input checked="" type="checkbox"/> Cleaning Materials	<input checked="" type="checkbox"/> Suction/Discharge Hoses	
<b>Last Cleaning Date</b>		<b>Current Cleaning Date</b>	
-		09 September 2020	
		<b>Next Cleaning Date</b>	
		09 March 2021	
<b>Crystalline Representative</b>		<b>Customer Representative</b>	
			

## GRP Water Tank 02

Before Photo



After Photo



Before Photo



After Photo



Water tank cleaned and disinfected

# CRYSTALLINE CLEANING & ENVIRONMENTAL SERVICES

## CLEANING & DISINFECTION CERTIFICATE POTABLE WATER TANKS

CLIENT NAME : AL RAHA VILLGAE PROPERTIES LLC.  
CLIENT ADDRESS : P.O. BOX: 6634, ABU DHABI, UAE.  
CONTACT PERSON : MR. BASHAR ABU SALIM  
SITE DETAILS : AL RAHA VILLAGE, ABU DHABI.  
DETAILS : GRP WATER TANK – 02 (B/W HOSPITAL & MOSQUE)  
DATE OF CLEANING : 09 SEPTEMBER 2020  
FREQUENCY OF CLEANING : EVERY SIX MONTHS  
DATE OF NEXT CLEANING : 09 MARCH 2021

*The procedures employed in this cleaning and disinfection comply with HS (G) 70 health and safety guidelines for prevention of legionella as well as BS6700 and CARELA BIO PLUS method statement.*

*The entire water storage tank should be disinfected minimum every Six (6) month depending upon the condition.*



CRYSTALLINE CLEANING AND ENVIRONMENTAL SERVICES

# Service Report



<b>Customer:</b> Al Raha Village Properties LLC		<b>Contact Person:</b> Mr. Bashar Abu Salim	
<b>Site:</b> Al Raha Village, Abu Dhabi		<b>Contact Number:</b> 050488 6406	
<b>Description:</b> GRP Water Tank 03		<b>Location:</b> GROUND LEVEL, BETWEEN HOSPITAL & MOSQUE	
<b>Type Of Building :</b>		<input checked="" type="checkbox"/> Commercial	<input type="checkbox"/> Residential <input type="checkbox"/> Others
<b>Type Of Tank</b>			
<input type="checkbox"/> Concrete	<input checked="" type="checkbox"/> GRP Panel	<input type="checkbox"/> FRP Tank	<input type="checkbox"/> Galvanized
<input type="checkbox"/> Steel Panel	<input type="checkbox"/> Plastic	<input type="checkbox"/> Concrete Coated	<input type="checkbox"/> Polyurethane
<input type="checkbox"/> Others			
<b>Condition before cleaning</b>		<b>Condition after cleaning</b>	
<input type="checkbox"/> Clean	<input type="checkbox"/> Dirty	<input checked="" type="checkbox"/> Very Dirty	<input checked="" type="checkbox"/> Clean
<input type="checkbox"/> Biofilms	<input type="checkbox"/> Moulds	<input type="checkbox"/> Slime	<input type="checkbox"/> Dirty
<input type="checkbox"/> Sediments	<input type="checkbox"/> Mud & Sand	<input type="checkbox"/> Rust	<input type="checkbox"/> Very Dirty
		<input type="checkbox"/> Biofilms	<input type="checkbox"/> Moulds
		<input type="checkbox"/> Sediments	<input type="checkbox"/> Mud & Sand
		<input type="checkbox"/> Rust	<input type="checkbox"/> Slime
<b>Size of Tank</b>			
<b>M3:</b>		<b>USG:</b> 126802.56	<b>L*B*H:</b>
<b>Quantity Of Water</b>		<b>Manhole</b>	
<input type="checkbox"/> Full	<input checked="" type="checkbox"/> Half	<input type="checkbox"/> Empty	<input checked="" type="checkbox"/> Covered
		<input type="checkbox"/> Damaged	<input type="checkbox"/> NA
<b>Ladder In</b>		<b>Ladder Out</b>	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
		<b>Leaks</b>	
		<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
<b>Drain Line</b>		<b>Valves</b>	
<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
		<b>Float Valve</b>	
		<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
<b>Tank Cleaned</b>		<b>Tank Disinfected</b>	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
		<b>Pipes Disinfected</b>	
		<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
<b>Chemicals Used</b>			
<b>Chemical:</b> Carela bio & plus		<b>Quantity:</b> 2000ml	
<b>Chemical:</b>		<b>Quantity:</b>	
<b>Equipments Used</b>			
<input checked="" type="checkbox"/> Submersibel Pump	<input checked="" type="checkbox"/> High/low Pressure Jet	<input checked="" type="checkbox"/> Extension Cords	<input checked="" type="checkbox"/> LED Lights
<input checked="" type="checkbox"/> Foot Bath	<input checked="" type="checkbox"/> Ladder	<input checked="" type="checkbox"/> Ventilating Fan	<input checked="" type="checkbox"/> Oxygen Meter
<input checked="" type="checkbox"/> Vacuum Cleaner	<input checked="" type="checkbox"/> Cleaning Materials	<input checked="" type="checkbox"/> Suction/Discharge Hoses	
<b>Last Cleaning Date</b>		<b>Current Cleaning Date</b>	
-		09 September 2020	
		<b>Next Cleaning Date</b>	
		09 March 2021	
<b>Crystalline Representative</b>		<b>Customer Representative</b>	
			

## GRP Water Tank 03

Before Photo



After Photo



Before Photo



After Photo



Water tank cleaned and disinfected

# CRYSTALLINE CLEANING & ENVIRONMENTAL SERVICES

## CLEANING & DISINFECTION CERTIFICATE POTABLE WATER TANKS

CLIENT NAME : AL RAHA VILLGAE PROPERTIES LLC.  
CLIENT ADDRESS : P.O. BOX: 6634, ABU DHABI, UAE.  
CONTACT PERSON : MR. BASHAR ABU SALIM  
SITE DETAILS : AL RAHA VILLAGE, ABU DHABI.  
DETAILS : GRP WATER TANK – 03 (B/W HOSPITAL & MOSQUE)  
DATE OF CLEANING : 09 SEPTEMBER 2020  
FREQUENCY OF CLEANING : EVERY SIX MONTHS  
DATE OF NEXT CLEANING : 09 MARCH 2021

*The procedures employed in this cleaning and disinfection comply with HS (G) 70 health and safety guidelines for prevention of legionella as well as BS6700 and CARELA BIO PLUS method statement.*

*The entire water storage tank should be disinfected minimum every Six (6) month depending upon the condition.*



CRYSTALLINE CLEANING AND ENVIRONMENTAL SERVICES

# Service Report



<b>Customer:</b> Al Raha Viilage Properties LLC		<b>Contact Person:</b> Mr. Bashar Abu Salim	
<b>Site:</b> Al Raha Village, Abu Dhabi		<b>Contact Number:</b> 050488 6406	
<b>Description:</b> RCC Water Tank 01		<b>Location:</b> Under Ground, Under Diner 7	
<b>Type Of Building :</b> <input checked="" type="checkbox"/> Commercial <input type="checkbox"/> Residential <input type="checkbox"/> Others			
<b>Type Of Tank</b> <input checked="" type="checkbox"/> Concrete <input type="checkbox"/> GRP Panel <input type="checkbox"/> FRP Tank <input type="checkbox"/> Galvanized <input type="checkbox"/> Steel Panel <input type="checkbox"/> Plastic <input type="checkbox"/> Concrete Coated <input type="checkbox"/> Polyurethane <input type="checkbox"/> Others			
<b>Condition before cleaning</b> <input type="checkbox"/> Clean <input type="checkbox"/> Dirty <input checked="" type="checkbox"/> Very Dirty <input type="checkbox"/> Biofilms <input type="checkbox"/> Moulds <input type="checkbox"/> Slime <input type="checkbox"/> Sediments <input type="checkbox"/> Mud & Sand <input type="checkbox"/> Rust		<b>Condition after cleaning</b> <input checked="" type="checkbox"/> Clean <input type="checkbox"/> Dirty <input type="checkbox"/> Very Dirty <input type="checkbox"/> Biofilms <input type="checkbox"/> Moulds <input type="checkbox"/> Slime <input type="checkbox"/> Sediments <input type="checkbox"/> Mud & Sand <input type="checkbox"/> Rust	
<b>Size of Tank</b> <b>M3:</b> <b>USG:</b> 678805.80 <b>L*B*H:</b>			
<b>Quantity Of Water</b> <input type="checkbox"/> Full <input checked="" type="checkbox"/> Half <input type="checkbox"/> Empty		<b>Manhole</b> <input checked="" type="checkbox"/> Covered <input type="checkbox"/> Damaged <input type="checkbox"/> NA	
<b>Ladder In</b> <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<b>Ladder Out</b> <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<b>Leaks</b> <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	
<b>Drain Line</b> <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	<b>Valves</b> <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<b>Float Valve</b> <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	
<b>Tank Cleaned</b> <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<b>Tank Disinfected</b> <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<b>Pipes Disinfected</b> <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	
<b>Chemicals Used</b> <b>Chemical:</b> Carela bio & plus <b>Quantity:</b> 2000ml <b>Chemical:</b> <b>Quantity:</b>			
<b>Equipments Used</b> <input checked="" type="checkbox"/> Submersibel Pump <input checked="" type="checkbox"/> High/low Pressure Jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED Lights <input checked="" type="checkbox"/> Foot Bath <input checked="" type="checkbox"/> Ladder <input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Oxygen Meter <input checked="" type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials <input checked="" type="checkbox"/> Suction/Discharge Hoses			
<b>Last Cleaning Date</b> -	<b>Current Cleaning Date</b> 08 September 2020	<b>Next Cleaning Date</b> 08 March 2021	
<b>Crystalline Representative</b> 		<b>Customer Representative</b> 	

## RCC Water Tank 01

Before Photo



After Photo



Before Photo



After Photo



Water tank cleaned and disinfected

# CRYSTALLINE CLEANING & ENVIRONMENTAL SERVICES

## CLEANING & DISINFECTION CERTIFICATE POTABLE WATER TANKS

CLIENT NAME : AL RAHA VILLGAE PROPERTIES LLC.  
CLIENT ADDRESS : P.O. BOX: 6634, ABU DHABI, UAE.  
CONTACT PERSON : MR. BASHAR ABU SALIM.  
SITE DETAILS : AL RAHA VILLAGE, ABU DHABI.  
DETAILS : U/G RCC WATER TANK - DINER '07'  
DATE OF CLEANING : 08 SEPTEMBER 2020  
FREQUENCY OF CLEANING : EVERY SIX MONTHS  
DATE OF NEXT CLEANING : 08 MARCH 2021

*The procedures employed in this cleaning and disinfection comply with HS (G) 70 health and safety guidelines for prevention of legionella as well as BS6700 and CARELA BIO PLUS method statement.*

*The entire water storage tank should be disinfected minimum every Six (6) month depending upon the condition.*



CRYSTALLINE CLEANING AND ENVIRONMENTAL SERVICES

# Service Report



<b>Customer:</b> Al Raha Village Properties LLC		<b>Contact Person:</b> Mr. Bashar Abu Salim	
<b>Site:</b> Al Raha Village, Abu Dhabi		<b>Contact Number:</b> 050488 6406	
<b>Description:</b> RCC Water Tank 02		<b>Location:</b> UNDER GROUND, UNDER MOSQUE-B	
<b>Type Of Building :</b> <input checked="" type="checkbox"/> Commercial <input type="checkbox"/> Residential <input type="checkbox"/> Others			
<b>Type Of Tank</b> <input checked="" type="checkbox"/> Concrete <input type="checkbox"/> GRP Panel <input type="checkbox"/> FRP Tank <input type="checkbox"/> Galvanized <input type="checkbox"/> Steel Panel <input type="checkbox"/> Plastic <input type="checkbox"/> Concrete Coated <input type="checkbox"/> Polyurethane <input type="checkbox"/> Others			
<b>Condition before cleaning</b> <input type="checkbox"/> Clean <input type="checkbox"/> Dirty <input checked="" type="checkbox"/> Very Dirty <input type="checkbox"/> Biofilms <input type="checkbox"/> Moulds <input type="checkbox"/> Slime <input type="checkbox"/> Sediments <input type="checkbox"/> Mud & Sand <input type="checkbox"/> Rust		<b>Condition after cleaning</b> <input checked="" type="checkbox"/> Clean <input type="checkbox"/> Dirty <input type="checkbox"/> Very Dirty <input type="checkbox"/> Biofilms <input type="checkbox"/> Moulds <input type="checkbox"/> Slime <input type="checkbox"/> Sediments <input type="checkbox"/> Mud & Sand <input type="checkbox"/> Rust	
<b>Size of Tank</b> <b>M3:</b> <b>USG:</b> 530034.70 <b>L*B*H:</b>			
<b>Quantity Of Water</b> <input type="checkbox"/> Full <input checked="" type="checkbox"/> Half <input type="checkbox"/> Empty		<b>Manhole</b> <input checked="" type="checkbox"/> Covered <input type="checkbox"/> Damaged <input type="checkbox"/> NA	
<b>Ladder In</b> <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<b>Ladder Out</b> <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<b>Leaks</b> <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	
<b>Drain Line</b> <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	<b>Valves</b> <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<b>Float Valve</b> <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	
<b>Tank Cleaned</b> <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<b>Tank Disinfected</b> <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<b>Pipes Disinfected</b> <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	
<b>Chemicals Used</b> <b>Chemical:</b> Carela bio & plus <b>Quantity:</b> 2000ml <b>Chemical:</b> <b>Quantity:</b>			
<b>Equipments Used</b> <input checked="" type="checkbox"/> Submersibel Pump <input checked="" type="checkbox"/> High/low Pressure Jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED Lights <input checked="" type="checkbox"/> Foot Bath <input checked="" type="checkbox"/> Ladder <input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Oxygen Meter <input checked="" type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials <input checked="" type="checkbox"/> Suction/Discharge Hoses			
<b>Last Cleaning Date</b> -	<b>Current Cleaning Date</b> 16 September 2020	<b>Next Cleaning Date</b> 16 March 2021	
<b>Crystalline Representative</b> 		<b>Customer Representative</b> 	

## RCC Water Tank 02

Before Photo



After Photo



Before Photo



After Photo



Water tank cleaned and disinfected

# CRYSTALLINE CLEANING & ENVIRONMENTAL SERVICES

## CLEANING & DISINFECTION CERTIFICATE POTABLE WATER TANKS

CLIENT NAME : AL RAHA VILLGAE PROPERTIES LLC.  
CLIENT ADDRESS : P.O. BOX: 6634, ABU DHABI, UAE.  
CONTACT PERSON : MR. BASHAR ABU SALIM.  
SITE DETAILS : AL RAHA VILLAGE, ABU DHABI.  
DETAILS : U/G RCC WATER TANK MOSQUE – 'B'  
DATE OF CLEANING : 16 SEPTEMBER 2020  
FREQUENCY OF CLEANING : EVERY SIX MONTHS  
DATE OF NEXT CLEANING : 16 MARCH 2021

*The procedures employed in this cleaning and disinfection comply with HS (G) 70 health and safety guidelines for prevention of legionella as well as BS6700 and CARELA BIO PLUS method statement.*

*The entire water storage tank should be disinfected minimum every Six (6) month depending upon the condition.*



CRYSTALLINE CLEANING AND ENVIRONMENTAL SERVICES

# Service Report



<b>Customer:</b> Al Raha Village Properties LLC		<b>Contact Person:</b> Mr. Bashar Abu Salim	
<b>Site:</b> Al Raha Village, Abu Dhabi		<b>Contact Number:</b> 050488 6406	
<b>Description:</b> RCC Water Tank 03		<b>Location:</b> Above ground, Diner 5	
<b>Type Of Building :</b> <input checked="" type="checkbox"/> Commercial <input type="checkbox"/> Residential <input type="checkbox"/> Others			
<b>Type Of Tank</b> <input checked="" type="checkbox"/> Concrete <input type="checkbox"/> GRP Panel <input type="checkbox"/> FRP Tank <input type="checkbox"/> Galvanized <input type="checkbox"/> Steel Panel <input type="checkbox"/> Plastic <input type="checkbox"/> Concrete Coated <input type="checkbox"/> Polyurethane <input type="checkbox"/> Others			
<b>Condition before cleaning</b> <input type="checkbox"/> Clean <input type="checkbox"/> Dirty <input checked="" type="checkbox"/> Very Dirty <input type="checkbox"/> Biofilms <input type="checkbox"/> Moulds <input type="checkbox"/> Slime <input type="checkbox"/> Sediments <input type="checkbox"/> Mud & Sand <input type="checkbox"/> Rust		<b>Condition after cleaning</b> <input checked="" type="checkbox"/> Clean <input type="checkbox"/> Dirty <input type="checkbox"/> Very Dirty <input type="checkbox"/> Biofilms <input type="checkbox"/> Moulds <input type="checkbox"/> Slime <input type="checkbox"/> Sediments <input type="checkbox"/> Mud & Sand <input type="checkbox"/> Rust	
<b>Size of Tank</b> <b>M3:</b> <b>USG:</b> 230070.56 <b>L*B*H:</b>			
<b>Quantity Of Water</b> <input type="checkbox"/> Full <input checked="" type="checkbox"/> Half <input type="checkbox"/> Empty		<b>Manhole</b> <input checked="" type="checkbox"/> Covered <input type="checkbox"/> Damaged <input type="checkbox"/> NA	
<b>Ladder In</b> <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<b>Ladder Out</b> <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<b>Leaks</b> <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	
<b>Drain Line</b> <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	<b>Valves</b> <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<b>Float Valve</b> <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	
<b>Tank Cleaned</b> <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<b>Tank Disinfected</b> <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<b>Pipes Disinfected</b> <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	
<b>Chemicals Used</b> <b>Chemical:</b> Carela bio & plus <b>Quantity:</b> 2000ml <b>Chemical:</b> <b>Quantity:</b>			
<b>Equipments Used</b> <input checked="" type="checkbox"/> Submersibel Pump <input checked="" type="checkbox"/> High/low Pressure Jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED Lights <input checked="" type="checkbox"/> Foot Bath <input checked="" type="checkbox"/> Ladder <input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Oxygen Meter <input checked="" type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials <input checked="" type="checkbox"/> Suction/Discharge Hoses			
<b>Last Cleaning Date</b> -	<b>Current Cleaning Date</b> 14 September 2020	<b>Next Cleaning Date</b> 14 March 2021	
<b>Crystalline Representative</b> 		<b>Customer Representative</b> 	

## RCC Water Tank 03

Before Photo



After Photo



Before Photo



After Photo



Water tank cleaned and disinfected

# CRYSTALLINE CLEANING & ENVIRONMENTAL SERVICES

## CLEANING & DISINFECTION CERTIFICATE POTABLE WATER TANKS

CLIENT NAME : AL RAHA VILLGAE PROPERTIES LLC.  
CLIENT ADDRESS : P.O. BOX: 6634, ABU DHABI, UAE.  
CONTACT PERSON : MR. BASHAR ABU SALIM.  
SITE DETAILS : AL RAHA VILLAGE, ABU DHABI.  
DETAILS : GROUND RCC WATER TANK - DINER '05'  
DATE OF CLEANING : 14 SEPTEMBER 2020  
FREQUENCY OF CLEANING : EVERY SIX MONTHS  
DATE OF NEXT CLEANING : 14 MARCH 2021

*The procedures employed in this cleaning and disinfection comply with HS (G) 70 health and safety guidelines for prevention of legionella as well as BS6700 and CARELA BIO PLUS method statement.*

*The entire water storage tank should be disinfected minimum every Six (6) month depending upon the condition.*



CRYSTALLINE CLEANING AND ENVIRONMENTAL SERVICES

# Service Report



<b>Customer:</b> Al Raha Village Properties LLC		<b>Contact Person:</b> Mr. Bashar Abu Salim	
<b>Site:</b> Al Raha Village, Abu Dhabi		<b>Contact Number:</b> 050488 6406	
<b>Description:</b> RCC Water Tank 04		<b>Location:</b> Above Ground, Diner 6	
<b>Type Of Building :</b>		<input checked="" type="checkbox"/> Commercial	<input type="checkbox"/> Residential <input type="checkbox"/> Others
<b>Type Of Tank</b>			
<input checked="" type="checkbox"/> Concrete	<input type="checkbox"/> GRP Panel	<input type="checkbox"/> FRP Tank	<input type="checkbox"/> Galvanized
<input type="checkbox"/> Steel Panel	<input type="checkbox"/> Plastic	<input type="checkbox"/> Concrete Coated	<input type="checkbox"/> Polyurethane
<input type="checkbox"/> Others			
<b>Condition before cleaning</b>		<b>Condition after cleaning</b>	
<input type="checkbox"/> Clean	<input type="checkbox"/> Dirty	<input checked="" type="checkbox"/> Very Dirty	<input type="checkbox"/> Dirty <input type="checkbox"/> Very Dirty
<input type="checkbox"/> Biofilms	<input type="checkbox"/> Moulds	<input type="checkbox"/> Slime	<input type="checkbox"/> Biofilms <input type="checkbox"/> Moulds <input type="checkbox"/> Slime
<input type="checkbox"/> Sediments	<input type="checkbox"/> Mud & Sand	<input type="checkbox"/> Rust	<input type="checkbox"/> Sediments <input type="checkbox"/> Mud & Sand <input type="checkbox"/> Rust
<b>Size of Tank</b>			
<b>M3:</b>		<b>USG:</b> 230070.56	<b>L*B*H:</b>
<b>Quantity Of Water</b>		<b>Manhole</b>	
<input type="checkbox"/> Full	<input checked="" type="checkbox"/> Half	<input type="checkbox"/> Empty	<input checked="" type="checkbox"/> Covered <input type="checkbox"/> Damaged <input type="checkbox"/> NA
<b>Ladder In</b>		<b>Ladder Out</b>	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
<b>Drain Line</b>		<b>Valves</b>	
<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
<b>Tank Cleaned</b>		<b>Tank Disinfected</b>	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
<b>Chemicals Used</b>		<b>Pipes Disinfected</b>	
<b>Chemical:</b> Carela bio & plus		<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	
<b>Chemical:</b>		<b>Quantity:</b> 2000ml	
<b>Chemical:</b>		<b>Quantity:</b>	
<b>Equipments Used</b>			
<input checked="" type="checkbox"/> Submersibel Pump	<input checked="" type="checkbox"/> High/low Pressure Jet	<input checked="" type="checkbox"/> Extension Cords	<input checked="" type="checkbox"/> LED Lights
<input checked="" type="checkbox"/> Foot Bath	<input checked="" type="checkbox"/> Ladder	<input checked="" type="checkbox"/> Ventilating Fan	<input checked="" type="checkbox"/> Oxygen Meter
<input checked="" type="checkbox"/> Vacuum Cleaner	<input checked="" type="checkbox"/> Cleaning Materials	<input checked="" type="checkbox"/> Suction/Discharge Hoses	
<b>Last Cleaning Date</b>		<b>Current Cleaning Date</b>	
-		08 September 2020	
		<b>Next Cleaning Date</b>	
		08 March 2021	
<b>Crystalline Representative</b>		<b>Customer Representative</b>	
			

## RCC Water Tank 04

Before Photo



After Photo



Before Photo



After Photo



Water tank cleaned and disinfected

# CRYSTALLINE CLEANING & ENVIRONMENTAL SERVICES

## CLEANING & DISINFECTION CERTIFICATE POTABLE WATER TANKS

CLIENT NAME : AL RAHA VILLGAE PROPERTIES LLC.  
CLIENT ADDRESS : P.O. BOX: 6634, ABU DHABI, UAE.  
CONTACT PERSON : MR. BASHAR ABU SALIM.  
SITE DETAILS : AL RAHA VILLAGE, ABU DHABI.  
DETAILS : GROUND RCC WATER TANK - DINER '06'  
DATE OF CLEANING : 08 SEPTEMBER 2020  
FREQUENCY OF CLEANING : EVERY SIX MONTHS  
DATE OF NEXT CLEANING : 08 MARCH 2021

*The procedures employed in this cleaning and disinfection comply with HS (G) 70 health and safety guidelines for prevention of legionella as well as BS6700 and CARELA BIO PLUS method statement.*

*The entire water storage tank should be disinfected minimum every Six (6) month depending upon the condition.*



CRYSTALLINE CLEANING AND ENVIRONMENTAL SERVICES

# Service Report



<b>Customer:</b> Al Raha Village Properties LLC		<b>Contact Person:</b> Mr. Bashar Abu Salim	
<b>Site:</b> Al Raha Village, Abu Dhabi		<b>Contact Number:</b> 050488 6406	
<b>Description:</b> RCC Water Tank 05		<b>Location:</b> Under ground, under Mosque A	
<b>Type Of Building :</b>		<input checked="" type="checkbox"/> Commercial	<input type="checkbox"/> Residential <input type="checkbox"/> Others
<b>Type Of Tank</b>			
<input checked="" type="checkbox"/> Concrete	<input type="checkbox"/> GRP Panel	<input type="checkbox"/> FRP Tank	<input type="checkbox"/> Galvanized
<input type="checkbox"/> Steel Panel	<input type="checkbox"/> Plastic	<input type="checkbox"/> Concrete Coated	<input type="checkbox"/> Polyurethane
<input type="checkbox"/> Others			
<b>Condition before cleaning</b>		<b>Condition after cleaning</b>	
<input type="checkbox"/> Clean	<input type="checkbox"/> Dirty	<input checked="" type="checkbox"/> Clean	<input type="checkbox"/> Dirty
<input type="checkbox"/> Biofilms	<input type="checkbox"/> Moulds	<input type="checkbox"/> Biofilms	<input type="checkbox"/> Moulds
<input type="checkbox"/> Sediments	<input type="checkbox"/> Mud & Sand	<input type="checkbox"/> Sediments	<input type="checkbox"/> Mud & Sand
<input checked="" type="checkbox"/> Very Dirty	<input type="checkbox"/> Slime	<input type="checkbox"/> Very Dirty	<input type="checkbox"/> Slime
<input type="checkbox"/> Rust		<input type="checkbox"/> Rust	
<b>Size of Tank</b>			
<b>M3:</b>		<b>USG:</b> 874557.26	<b>L*B*H:</b>
<b>Quantity Of Water</b>		<b>Manhole</b>	
<input type="checkbox"/> Full	<input checked="" type="checkbox"/> Half	<input type="checkbox"/> Empty	<input checked="" type="checkbox"/> Covered
<input type="checkbox"/> Damaged	<input type="checkbox"/> NA		
<b>Ladder In</b>		<b>Ladder Out</b>	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
<b>Drain Line</b>		<b>Valves</b>	
<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
<b>Tank Cleaned</b>		<b>Tank Disinfected</b>	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
		<b>Pipes Disinfected</b>	
		<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
<b>Chemicals Used</b>			
<b>Chemical:</b> Carela bio & plus		<b>Quantity:</b> 2000ml	
<b>Chemical:</b>		<b>Quantity:</b>	
<b>Equipments Used</b>			
<input checked="" type="checkbox"/> Submersibel Pump	<input checked="" type="checkbox"/> High/low Pressure Jet	<input checked="" type="checkbox"/> Extension Cords	<input checked="" type="checkbox"/> LED Lights
<input checked="" type="checkbox"/> Foot Bath	<input checked="" type="checkbox"/> Ladder	<input checked="" type="checkbox"/> Ventilating Fan	<input checked="" type="checkbox"/> Oxygen Meter
<input checked="" type="checkbox"/> Vacuum Cleaner	<input checked="" type="checkbox"/> Cleaning Materials	<input checked="" type="checkbox"/> Suction/Discharge Hoses	
<b>Last Cleaning Date</b>		<b>Current Cleaning Date</b>	
-		19 September 2020	
		<b>Next Cleaning Date</b>	
		19 March 2021	
<b>Crystalline Representative</b>		<b>Customer Representative</b>	
			

## RCC Water Tank 05

Before Photo



After Photo



Before Photo



After Photo



Water tank cleaned and disinfected

# CRYSTALLINE CLEANING & ENVIRONMENTAL SERVICES

## CLEANING & DISINFECTION CERTIFICATE POTABLE WATER TANKS

CLIENT NAME : AL RAHA VILLGAE PROPERTIES LLC.  
CLIENT ADDRESS : P.O. BOX: 6634, ABU DHABI, UAE.  
CONTACT PERSON : MR. BASHAR ABU SALIM.  
SITE DETAILS : AL RAHA VILLAGE, ABU DHABI.  
DETAILS : U/G RCC WATER TANK MOSQUE – 'A'  
DATE OF CLEANING : 19 SEPTEMBER 2020  
FREQUENCY OF CLEANING : EVERY SIX MONTHS  
DATE OF NEXT CLEANING : 19 MARCH 2021

*The procedures employed in this cleaning and disinfection comply with HS (G) 70 health and safety guidelines for prevention of legionella as well as BS6700 and CARELA BIO PLUS method statement.*

*The entire water storage tank should be disinfected minimum every Six (6) month depending upon the condition.*



CRYSTALLINE CLEANING AND ENVIRONMENTAL SERVICES