

WATER TANK CLEANING & DISINFECTION

COMPLETION REPORT

FOR



Client : **Bahrain & Emirates Electrical & Mechanical Contracting LLC.**
Contact Person: MS. Joyce Cancino
Admin Assistant
Site Details : Villa #4 Hidd Al Saadiyat,
Abu Dhabi, UAE.
Date : 27 March 2019



CRYSTALLINE
ENVIRONMENTAL SERVICES

CRYSTALLINE ENVIRONMENTAL
SERVICES

P.O. BOX 131463, Abu Dhabi, U.A.E.

TEL: 02 6508930 FAX: 02 6508942

info@crystalline-uae.com

www.crystalline-uae.com





CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT

19716

CUSTOMER: <u>Sadi Saadiyath</u>			CONTACT PERSON: <u>Ms. Joyce Cancino</u>		
SITE DETAILS: <u>7th street villa-4</u>			CONTACT NO: <u>0509818842</u>		
TANK DETAILS: <u>G.R.P domestic tank.</u>			LOCATION DETAILS:		
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL <input checked="" type="checkbox"/> RESIDENTIAL <input type="checkbox"/> OTHERS					
<u>TYPE OF TANK</u>					
<input type="checkbox"/> CONCRETE	<input checked="" type="checkbox"/> GRP PANEL	<input type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED		<input type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS		
<u>SIZE OF TANK</u>			<u>QUANTITY OF WATER</u>		
M3	USG	L*B*H	<input type="checkbox"/> FULL	<input type="checkbox"/> HALF	<input type="checkbox"/> EMPTY
<u>CONDITION OF WATER TANK BEFORE CLEANING</u>			<u>CONDITION OF WATER TANK AFTER CLEANING</u>		
<input type="checkbox"/> CLEAN	<input checked="" type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
<u>ACCESS</u>		<u>MANHOLE</u>	<input checked="" type="checkbox"/> COVERED	<input type="checkbox"/> DAMAGED	<input type="checkbox"/> NA
<u>LADDER IN</u>	<u>LADDER OUT</u>	<u>LEAKS</u>	<u>DRAIN LINE</u>	<u>VALVES</u>	<u>FLOAT VALVE</u>
<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO
<u>TANK CLEANED</u>		<u>TANK DISINFECTED</u>		<u>PIPES DISINFECTED</u>	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> YES	<input type="checkbox"/> NO <input checked="" type="checkbox"/> NA
<u>LAST CLEANING DATE</u>		<u>CURRENT CLEANING DATE</u>		<u>NEXT CLEANING DATE</u>	
		<u>19/3/2019</u>		<u>19/9/2019</u>	
<u>CHEMICALS & EQUIPMENTS USED</u>					
1. <u>Carelo bio</u> Quantity <u>250 ml</u>					
2. <u>Carelo plus</u> Quantity <u>250 ml</u>					
<input checked="" type="checkbox"/> Submersibel Pump <input checked="" type="checkbox"/> High /Low Pressure jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED Lights <input checked="" type="checkbox"/> Foot Bath <input checked="" type="checkbox"/> Ladder					
<input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Mater <input type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials					
<u>COMMENTS & RECOMMENDATIONS:</u>					
<u>Thank Tank cleaned and disinfected.</u>					
Crystalline Representative: <u>Kennedy Wah</u>			Signature: <u>[Signature]</u>		



CRYSTALLINE
ENVIRONMENTAL SERVICES

Date of Cleaning: 19-03-2019

PHOTOGRAPHS
ROOF TOP GRP WATER TANK

BEFORE



AFTER



CLEANER WATER GREENER TOMORROW

CRYSTALLINE CLEANING & ENVIRONMENTAL SERVICES

CLEANING & DISINFECTION CERTIFICATE

POTABLE WATER TANKS

CLIENT NAME : BAHRAIN & EMIRATES ELECTRICAL & MECHANICAL CONTRACTING LLC.

CLIENT ADDRESS : P.O. BOX: 131293, ABU DHABI, U A E.

CONTACT PERSON : MS. JOYCE CANCINO.

SITE DETAILS : VILLA #4 HIDD AL SAADIYAT, ABU DHABI.

DETAILS : WATER TANK CLEANING

DATE OF CLEANING : 19 MARCH 2019

FREQUENCY OF CLEANING : EVERY SIX MONTHS

DATE OF NEXT CLEANING : 19 SEPTEMBER 2019

The procedures employed in this cleaning and disinfection comply with HS (G) 70 health and safety guidelines for prevention of legionella as well as BS6700 and CARELA BIO PLUS method statement.

The entire water storage tank should be cleaned and disinfected minimum every six (6) months depending upon the condition.



CRYSTALLINE CLEANING AND ENVIRONMENTAL SERVICES