

**ENVIRONMENTAL
SERVICES FOR
A GREENER
TOMORROW...
ONE STEP AT
A TIME.**



CRYSTALLINE
ENVIRONMENTAL SERVICES



Completion Report for

Water Tank Cleaning & Disinfection

Date: **10 December 2020**
Client Name: **Tafawuq Facility Management**
Contact Person: **Mr. Sohail**
Designation: **FM Supervisor**
Site Detail: **C10, C11**




Service Report



Customer: Tafawuq facility management		Contact Person: Mr.sohail	
Site: Package C2 C3 - C10 C11, C10A -, City Of lights		Contact Number: -	
Description: Domestic Water Tank Cleaning #2		Location: C10 Basement #01	
Type Of Building : <input type="checkbox"/> Commercial <input checked="" type="checkbox"/> Residential <input type="checkbox"/> Others			
Type Of Tank			
<input checked="" type="checkbox"/> Concrete	<input type="checkbox"/> GRP Panel	<input type="checkbox"/> FRP Tank	<input type="checkbox"/> Galvanized
<input type="checkbox"/> Steel Panel	<input type="checkbox"/> Plastic	<input type="checkbox"/> Concrete Coated	<input type="checkbox"/> Polyurethane
<input type="checkbox"/> Others			
Condition before cleaning		Condition after cleaning	
<input type="checkbox"/> Clean	<input type="checkbox"/> Dirty	<input checked="" type="checkbox"/> Very Dirty	<input type="checkbox"/> Dirty
<input type="checkbox"/> Biofilms	<input checked="" type="checkbox"/> Moulds	<input checked="" type="checkbox"/> Slime	<input type="checkbox"/> Moulds
<input type="checkbox"/> Sediments	<input type="checkbox"/> Mud & Sand	<input type="checkbox"/> Rust	<input type="checkbox"/> Slime
<input type="checkbox"/> Rust		<input type="checkbox"/> Mud & Sand	
<input type="checkbox"/> Rust		<input type="checkbox"/> Rust	
Size of Tank			
M3:		USG:	
		L*B*H:	
Quantity Of Water		Manhole	
<input checked="" type="checkbox"/> Full	<input type="checkbox"/> Half	<input type="checkbox"/> Empty	<input type="checkbox"/> Covered
		<input type="checkbox"/> Damaged	<input checked="" type="checkbox"/> NA
Ladder In		Ladder Out	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
		Leaks	
		<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Drain Line		Valves	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
		Float Valve	
		<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Tank Cleaned		Tank Disinfected	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
		Pipes Disinfected	
		<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Chemicals Used			
Chemical: Crystal Shc		Quantity: 1ml	
Chemical: Crystal Shc		Quantity: 1ml	
Equipments Used			
<input checked="" type="checkbox"/> Submersibel Pump	<input checked="" type="checkbox"/> High/low Pressure Jet	<input checked="" type="checkbox"/> Extension Cords	<input checked="" type="checkbox"/> LED Lights
<input checked="" type="checkbox"/> Foot Bath	<input checked="" type="checkbox"/> Ladder	<input checked="" type="checkbox"/> Ventilating Fan	<input checked="" type="checkbox"/> Oxygen Meter
<input type="checkbox"/> Vacuum Cleaner	<input checked="" type="checkbox"/> Cleaning Materials	<input checked="" type="checkbox"/> Suction/Discharge Hoses	
Last Cleaning Date		Current Cleaning Date	
-		10 December 2020	
		Next Cleaning Date	
		10 June 2021	
Crystalline Representative		Customer Representative	
			

Domestic Water Tank Cleaning #2


Before Photo



After Photo



Before Photo



After Photo



We mention that the water tank has been cleaned and disinfected properly.

Service Report




Customer: Tafawuq facility management		Contact Person: Mr.sohail	
Site: Package C2 C3 - C10 C11, C10A -, City Of lights		Contact Number: -	
Description: Domestic water Tank Cleaning #3		Location: C10 Basement #01	
Type Of Building : <input type="checkbox"/> Commercial <input checked="" type="checkbox"/> Residential <input type="checkbox"/> Others			
Type Of Tank			
<input checked="" type="checkbox"/> Concrete	<input type="checkbox"/> GRP Panel	<input type="checkbox"/> FRP Tank	<input type="checkbox"/> Galvanized
<input type="checkbox"/> Steel Panel	<input type="checkbox"/> Plastic	<input type="checkbox"/> Concrete Coated	<input type="checkbox"/> Polyurethane
<input type="checkbox"/> Others			
Condition before cleaning		Condition after cleaning	
<input type="checkbox"/> Clean	<input type="checkbox"/> Dirty	<input checked="" type="checkbox"/> Very Dirty	<input type="checkbox"/> Very Dirty
<input type="checkbox"/> Biofilms	<input checked="" type="checkbox"/> Moulds	<input checked="" type="checkbox"/> Slime	<input type="checkbox"/> Slime
<input type="checkbox"/> Sediments	<input type="checkbox"/> Mud & Sand	<input type="checkbox"/> Rust	<input type="checkbox"/> Rust
Size of Tank			
M3:		USG:	L*B*H:
Quantity Of Water		Manhole	
<input checked="" type="checkbox"/> Full	<input type="checkbox"/> Half	<input type="checkbox"/> Empty	<input type="checkbox"/> Covered
		<input type="checkbox"/> Damaged	<input checked="" type="checkbox"/> NA
Ladder In	Ladder Out		Leaks
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> Yes
		<input type="checkbox"/> No	<input checked="" type="checkbox"/> No
Drain Line	Valves		Float Valve
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
		<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes
Tank Cleaned	Tank Disinfected		Pipes Disinfected
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
		<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes
Chemicals Used			
Chemical: Crystal Shc		Quantity: 1ml	
Chemical: Crystal Shc		Quantity: 1ml	
Equipments Used			
<input checked="" type="checkbox"/> Submersibel Pump	<input checked="" type="checkbox"/> High/low Pressure Jet	<input checked="" type="checkbox"/> Extension Cords	<input checked="" type="checkbox"/> LED Lights
<input checked="" type="checkbox"/> Foot Bath	<input checked="" type="checkbox"/> Ladder	<input checked="" type="checkbox"/> Ventilating Fan	<input checked="" type="checkbox"/> Oxygen Meter
<input type="checkbox"/> Vacuum Cleaner	<input checked="" type="checkbox"/> Cleaning Materials	<input checked="" type="checkbox"/> Suction/Discharge Hoses	
Last Cleaning Date	Current Cleaning Date	Next Cleaning Date	
-	10 December 2020	10 June 2021	
Crystalline Representative		Customer Representative	
			

Domestic water Tank Cleaning #3


Before Photo



After Photo



Before Photo



After Photo



We mention that the water tank has been cleaned and disinfected properly.

Service Report



Customer: Tafawuq facility management		Contact Person: Mr.sohail	
Site: Package C2 C3 - C10 C11, C10A -, City Of lights		Contact Number: -	
Description: Domestic Water Tank Cleaning #1		Location: C10 Roof Top	
Type Of Building : <input type="checkbox"/> Commercial <input checked="" type="checkbox"/> Residential <input type="checkbox"/> Others			
Type Of Tank			
<input type="checkbox"/> Concrete	<input checked="" type="checkbox"/> GRP Panel	<input type="checkbox"/> FRP Tank	<input type="checkbox"/> Galvanized
<input type="checkbox"/> Steel Panel	<input type="checkbox"/> Plastic	<input type="checkbox"/> Concrete Coated	<input type="checkbox"/> Polyurethane
<input type="checkbox"/> Others			
Condition before cleaning		Condition after cleaning	
<input type="checkbox"/> Clean	<input type="checkbox"/> Dirty	<input checked="" type="checkbox"/> Very Dirty	<input type="checkbox"/> Dirty
<input type="checkbox"/> Biofilms	<input checked="" type="checkbox"/> Moulds	<input checked="" type="checkbox"/> Slime	<input type="checkbox"/> Moulds
<input type="checkbox"/> Sediments	<input type="checkbox"/> Mud & Sand	<input type="checkbox"/> Rust	<input type="checkbox"/> Slime
<input type="checkbox"/> Very Dirty		<input type="checkbox"/> Very Dirty	
<input type="checkbox"/> Rust		<input type="checkbox"/> Rust	
Size of Tank			
M3:		USG:	
		L*B*H:	
Quantity Of Water		Manhole	
<input checked="" type="checkbox"/> Full	<input type="checkbox"/> Half	<input type="checkbox"/> Empty	<input type="checkbox"/> Covered
		<input type="checkbox"/> Damaged	<input checked="" type="checkbox"/> NA
Ladder In		Ladder Out	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
		Leaks	
		<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Drain Line		Valves	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
		Float Valve	
		<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Tank Cleaned		Tank Disinfected	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
		Pipes Disinfected	
		<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Chemicals Used			
Chemical: Crystal Shc		Quantity: 1ml	
Chemical: Crystal Shc		Quantity: 1ml	
Equipments Used			
<input checked="" type="checkbox"/> Submersibel Pump	<input checked="" type="checkbox"/> High/low Pressure Jet	<input checked="" type="checkbox"/> Extension Cords	<input checked="" type="checkbox"/> LED Lights
<input checked="" type="checkbox"/> Foot Bath	<input checked="" type="checkbox"/> Ladder	<input checked="" type="checkbox"/> Ventilating Fan	<input checked="" type="checkbox"/> Oxygen Meter
<input type="checkbox"/> Vacuum Cleaner	<input checked="" type="checkbox"/> Cleaning Materials	<input checked="" type="checkbox"/> Suction/Discharge Hoses	
Last Cleaning Date		Current Cleaning Date	
-		10 December 2020	
		Next Cleaning Date	
		10 June 2021	
Crystalline Representative		Customer Representative	
			

Domestic Water Tank Cleaning #1

Before Photo




After Photo



Before Photo



After Photo



We mention that the water tank has been cleaned and disinfected properly.

Service Report



Customer: Tafawuq facility management		Contact Person: Mr.sohail	
Site: Package C2 C3 - C10 C11, C10A -, City Of lights		Contact Number: -	
Description: Domestic water Tank Cleaning #2		Location: C10 Roof Top	
Type Of Building : <input type="checkbox"/> Commercial <input checked="" type="checkbox"/> Residential <input type="checkbox"/> Others			
Type Of Tank			
<input type="checkbox"/> Concrete	<input checked="" type="checkbox"/> GRP Panel	<input type="checkbox"/> FRP Tank	<input type="checkbox"/> Galvanized
<input type="checkbox"/> Steel Panel	<input type="checkbox"/> Plastic	<input type="checkbox"/> Concrete Coated	<input type="checkbox"/> Polyurethane
<input type="checkbox"/> Others			
Condition before cleaning		Condition after cleaning	
<input type="checkbox"/> Clean	<input type="checkbox"/> Dirty	<input checked="" type="checkbox"/> Very Dirty	<input type="checkbox"/> Dirty
<input type="checkbox"/> Biofilms	<input checked="" type="checkbox"/> Moulds	<input checked="" type="checkbox"/> Slime	<input type="checkbox"/> Moulds
<input type="checkbox"/> Sediments	<input type="checkbox"/> Mud & Sand	<input type="checkbox"/> Rust	<input type="checkbox"/> Slime
<input type="checkbox"/> Very Dirty		<input type="checkbox"/> Very Dirty	
<input type="checkbox"/> Rust		<input type="checkbox"/> Rust	
Size of Tank			
M3:		USG:	
		L*B*H:	
Quantity Of Water		Manhole	
<input checked="" type="checkbox"/> Full	<input type="checkbox"/> Half	<input type="checkbox"/> Empty	<input type="checkbox"/> Covered
		<input type="checkbox"/> Damaged	<input checked="" type="checkbox"/> NA
Ladder In		Ladder Out	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
		Leaks	
		<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Drain Line		Valves	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
		Float Valve	
		<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Tank Cleaned		Tank Disinfected	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
		Pipes Disinfected	
		<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Chemicals Used			
Chemical: Crystal Shc		Quantity: 1ml	
Chemical: Crystal Shc		Quantity: 1ml	
Equipments Used			
<input checked="" type="checkbox"/> Submersibel Pump	<input checked="" type="checkbox"/> High/low Pressure Jet	<input checked="" type="checkbox"/> Extension Cords	<input checked="" type="checkbox"/> LED Lights
<input checked="" type="checkbox"/> Foot Bath	<input checked="" type="checkbox"/> Ladder	<input checked="" type="checkbox"/> Ventilating Fan	<input checked="" type="checkbox"/> Oxygen Meter
<input type="checkbox"/> Vacuum Cleaner	<input checked="" type="checkbox"/> Cleaning Materials	<input checked="" type="checkbox"/> Suction/Discharge Hoses	
Last Cleaning Date		Current Cleaning Date	
-		12 December 2020	
		Next Cleaning Date	
		12 June 2021	
Crystalline Representative		Customer Representative	
			

Domestic water Tank Cleaning #2


Before Photo



After Photo



Before Photo



After Photo



We mention that the water tank has been cleaned and disinfected properly.


Service Report




Customer: Tafawuq facility management		Contact Person: Mr.sohail	
Site: Package C2 C3 - C10 C11, C10A -, City Of lights		Contact Number: -	
Description: Domestic Water Tank Cleaning #1		Location: C10 Basement #01	
Type Of Building : <input type="checkbox"/> Commercial <input checked="" type="checkbox"/> Residential <input type="checkbox"/> Others			
Type Of Tank			
<input checked="" type="checkbox"/> Concrete	<input type="checkbox"/> GRP Panel	<input type="checkbox"/> FRP Tank	<input type="checkbox"/> Galvanized
<input type="checkbox"/> Steel Panel	<input type="checkbox"/> Plastic	<input type="checkbox"/> Concrete Coated	<input type="checkbox"/> Polyurethane
<input type="checkbox"/> Others			
Condition before cleaning		Condition after cleaning	
<input type="checkbox"/> Clean	<input type="checkbox"/> Dirty	<input checked="" type="checkbox"/> Clean	<input type="checkbox"/> Dirty
<input type="checkbox"/> Biofilms	<input checked="" type="checkbox"/> Moulds	<input checked="" type="checkbox"/> Very Dirty	<input type="checkbox"/> Very Dirty
<input type="checkbox"/> Sediments	<input type="checkbox"/> Mud & Sand	<input checked="" type="checkbox"/> Slime	<input type="checkbox"/> Slime
	<input type="checkbox"/> Rust	<input type="checkbox"/> Sediments	<input type="checkbox"/> Mud & Sand
			<input type="checkbox"/> Rust
Size of Tank			
M3:		USG:	
		L*B*H:	
Quantity Of Water		Manhole	
<input checked="" type="checkbox"/> Full	<input type="checkbox"/> Half	<input type="checkbox"/> Covered	<input type="checkbox"/> Damaged
	<input type="checkbox"/> Empty		<input checked="" type="checkbox"/> NA
Ladder In		Ladder Out	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Drain Line		Valves	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Tank Cleaned		Tank Disinfected	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
		Pipes Disinfected	
		<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Chemicals Used			
Chemical: Crystal Shc		Quantity: 1ml	
Chemical: Crystal Shc		Quantity: 1ml	
Equipments Used			
<input checked="" type="checkbox"/> Submersibel Pump	<input checked="" type="checkbox"/> High/low Pressure Jet	<input checked="" type="checkbox"/> Extension Cords	<input checked="" type="checkbox"/> LED Lights
<input checked="" type="checkbox"/> Foot Bath	<input checked="" type="checkbox"/> Ladder	<input checked="" type="checkbox"/> Ventilating Fan	<input checked="" type="checkbox"/> Oxygen Meter
<input type="checkbox"/> Vacuum Cleaner	<input checked="" type="checkbox"/> Cleaning Materials	<input checked="" type="checkbox"/> Suction/Discharge Hoses	
Last Cleaning Date	Current Cleaning Date	Next Cleaning Date	
-	13 December 2020	13 June 2021	
Crystalline Representative		Customer Representative	
			

Domestic Water Tank Cleaning #1


Before Photo




After Photo



Before Photo



After Photo



We mention that the water tank has been cleaned and disinfected properly.

Service Report



Customer: Tafawuq facility management		Contact Person: Mr.sohail	
Site: Package C2 C3 - C10 C11, C10A -, City Of lights		Contact Number: -	
Description: Domestic Water Tank Cleaning #2		Location: C11 Basement #01	
Type Of Building : <input type="checkbox"/> Commercial <input checked="" type="checkbox"/> Residential <input type="checkbox"/> Others			
Type Of Tank			
<input checked="" type="checkbox"/> Concrete <input type="checkbox"/> GRP Panel <input type="checkbox"/> FRP Tank <input type="checkbox"/> Galvanized <input type="checkbox"/> Steel Panel <input type="checkbox"/> Plastic <input type="checkbox"/> Concrete Coated <input type="checkbox"/> Polyurethane <input type="checkbox"/> Others			
Condition before cleaning		Condition after cleaning	
<input type="checkbox"/> Clean <input type="checkbox"/> Dirty <input checked="" type="checkbox"/> Very Dirty <input type="checkbox"/> Biofilms <input checked="" type="checkbox"/> Moulds <input checked="" type="checkbox"/> Slime <input type="checkbox"/> Sediments <input type="checkbox"/> Mud & Sand <input type="checkbox"/> Rust		<input checked="" type="checkbox"/> Clean <input type="checkbox"/> Dirty <input type="checkbox"/> Very Dirty <input type="checkbox"/> Biofilms <input type="checkbox"/> Moulds <input type="checkbox"/> Slime <input type="checkbox"/> Sediments <input type="checkbox"/> Mud & Sand <input type="checkbox"/> Rust	
Size of Tank			
M3:		USG:	L*B*H:
Quantity Of Water		Manhole	
<input checked="" type="checkbox"/> Full <input type="checkbox"/> Half <input type="checkbox"/> Empty		<input type="checkbox"/> Covered <input type="checkbox"/> Damaged <input checked="" type="checkbox"/> NA	
Ladder In	Ladder Out	Leaks	
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	
Drain Line	Valves	Float Valve	
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	
Tank Cleaned	Tank Disinfected	Pipes Disinfected	
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	
Chemicals Used			
Chemical: Crystal Shc		Quantity: 1ml	
Chemical: Crystal Shc		Quantity: 1ml	
Equipments Used			
<input checked="" type="checkbox"/> Submersibel Pump	<input checked="" type="checkbox"/> High/low Pressure Jet	<input checked="" type="checkbox"/> Extension Cords	<input checked="" type="checkbox"/> LED Lights
<input checked="" type="checkbox"/> Foot Bath	<input checked="" type="checkbox"/> Ladder	<input checked="" type="checkbox"/> Ventilating Fan	<input checked="" type="checkbox"/> Oxygen Meter
<input type="checkbox"/> Vacuum Cleaner	<input checked="" type="checkbox"/> Cleaning Materials	<input checked="" type="checkbox"/> Suction/Discharge Hoses	
Last Cleaning Date	Current Cleaning Date	Next Cleaning Date	
-	10 December 2020	10 June 2021	
Crystalline Representative		Customer Representative	
			

Domestic Water Tank Cleaning #2


Before Photo




After Photo



Before Photo



After Photo



We mention that the water tank has been cleaned and disinfected properly.

Service Report



Customer: Tafawuq facility management		Contact Person: Mr.sohail	
Site: Package C2 C3 - C10 C11, C10A -, City Of lights		Contact Number: -	
Description: Domestic water Tank Cleaning #1		Location: C11 Basement #01	
Type Of Building : <input type="checkbox"/> Commercial <input checked="" type="checkbox"/> Residential <input type="checkbox"/> Others			
Type Of Tank			
<input checked="" type="checkbox"/> Concrete	<input type="checkbox"/> GRP Panel	<input type="checkbox"/> FRP Tank	<input type="checkbox"/> Galvanized
<input type="checkbox"/> Steel Panel	<input type="checkbox"/> Plastic	<input type="checkbox"/> Concrete Coated	<input type="checkbox"/> Polyurethane
<input type="checkbox"/> Others			
Condition before cleaning		Condition after cleaning	
<input type="checkbox"/> Clean	<input type="checkbox"/> Dirty	<input checked="" type="checkbox"/> Very Dirty	<input type="checkbox"/> Dirty
<input type="checkbox"/> Biofilms	<input checked="" type="checkbox"/> Moulds	<input checked="" type="checkbox"/> Slime	<input type="checkbox"/> Moulds
<input type="checkbox"/> Sediments	<input type="checkbox"/> Mud & Sand	<input type="checkbox"/> Rust	<input type="checkbox"/> Slime
<input type="checkbox"/> Rust		<input type="checkbox"/> Mud & Sand	
<input type="checkbox"/> Sediments		<input type="checkbox"/> Rust	
Size of Tank			
M3:		USG:	
		L*B*H:	
Quantity Of Water		Manhole	
<input checked="" type="checkbox"/> Full	<input type="checkbox"/> Half	<input type="checkbox"/> Empty	<input type="checkbox"/> Covered
		<input type="checkbox"/> Damaged	
		<input checked="" type="checkbox"/> NA	
Ladder In		Ladder Out	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
		<input type="checkbox"/> No	
		<input checked="" type="checkbox"/> No	
Drain Line		Valves	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
		<input type="checkbox"/> No	
		<input checked="" type="checkbox"/> No	
Tank Cleaned		Tank Disinfected	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
		<input type="checkbox"/> No	
		<input checked="" type="checkbox"/> No	
Chemicals Used			
Chemical: Crystal Shc		Quantity: 1ml	
Chemical:		Quantity: 1ml	
Equipments Used			
<input checked="" type="checkbox"/> Submersibel Pump	<input checked="" type="checkbox"/> High/low Pressure Jet	<input checked="" type="checkbox"/> Extension Cords	<input checked="" type="checkbox"/> LED Lights
<input checked="" type="checkbox"/> Foot Bath	<input checked="" type="checkbox"/> Ladder	<input checked="" type="checkbox"/> Ventilating Fan	<input checked="" type="checkbox"/> Oxygen Meter
<input type="checkbox"/> Vacuum Cleaner	<input checked="" type="checkbox"/> Cleaning Materials	<input checked="" type="checkbox"/> Suction/Discharge Hoses	
Last Cleaning Date		Current Cleaning Date	
-		10 December 2020	
		Next Cleaning Date	
		10 June 2021	
Crystalline Representative		Customer Representative	
			

Domestic water Tank Cleaning #1


Before Photo




After Photo



Before Photo




After Photo



We mention that the water tank has been cleaned and disinfected properly.

Service Report




Customer: Tafawuq facility management		Contact Person: Mr.sohail	
Site: Package C2 C3 - C10 C11, C10A -, City Of lights		Contact Number: -	
Description: Domestic water Tank Cleaning #1		Location: C11Roof Top	
Type Of Building : <input type="checkbox"/> Commercial <input checked="" type="checkbox"/> Residential <input type="checkbox"/> Others			
Type Of Tank			
<input type="checkbox"/> Concrete	<input checked="" type="checkbox"/> GRP Panel	<input type="checkbox"/> FRP Tank	<input type="checkbox"/> Galvanized
<input type="checkbox"/> Steel Panel	<input type="checkbox"/> Plastic	<input type="checkbox"/> Concrete Coated	<input type="checkbox"/> Polyurethane
<input type="checkbox"/> Others			
Condition before cleaning		Condition after cleaning	
<input type="checkbox"/> Clean	<input type="checkbox"/> Dirty	<input checked="" type="checkbox"/> Very Dirty	
<input type="checkbox"/> Biofilms	<input checked="" type="checkbox"/> Moulds	<input checked="" type="checkbox"/> Slime	
<input type="checkbox"/> Sediments	<input type="checkbox"/> Mud & Sand	<input type="checkbox"/> Rust	
<input type="checkbox"/> Clean		<input type="checkbox"/> Dirty	
<input type="checkbox"/> Biofilms		<input type="checkbox"/> Moulds	
<input type="checkbox"/> Sediments		<input type="checkbox"/> Mud & Sand	
<input type="checkbox"/> Very Dirty		<input type="checkbox"/> Slime	
<input type="checkbox"/> Rust		<input type="checkbox"/> Rust	
Size of Tank			
M3:		USG:	
		L*B*H:	
Quantity Of Water		Manhole	
<input checked="" type="checkbox"/> Full	<input type="checkbox"/> Half	<input type="checkbox"/> Empty	
<input type="checkbox"/> Covered		<input type="checkbox"/> Damaged	
<input checked="" type="checkbox"/> NA			
Ladder In		Ladder Out	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Leaks		<input checked="" type="checkbox"/> No	
<input type="checkbox"/> Yes			
Drain Line		Valves	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Float Valve		<input checked="" type="checkbox"/> Yes	
<input type="checkbox"/> No			
Tank Cleaned		Tank Disinfected	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Pipes Disinfected		<input checked="" type="checkbox"/> Yes	
<input type="checkbox"/> No			
Chemicals Used			
Chemical: Crystal Shc		Quantity: 1ml	
Chemical: Crystal Shc		Quantity: 1ml	
Equipments Used			
<input checked="" type="checkbox"/> Submersibel Pump	<input checked="" type="checkbox"/> High/low Pressure Jet	<input checked="" type="checkbox"/> Extension Cords	<input checked="" type="checkbox"/> LED Lights
<input checked="" type="checkbox"/> Foot Bath	<input checked="" type="checkbox"/> Ladder	<input checked="" type="checkbox"/> Ventilating Fan	<input checked="" type="checkbox"/> Oxygen Meter
<input type="checkbox"/> Vacuum Cleaner	<input checked="" type="checkbox"/> Cleaning Materials	<input checked="" type="checkbox"/> Suction/Discharge Hoses	
Last Cleaning Date	Current Cleaning Date	Next Cleaning Date	
-	12 December 2020	12 June 2021	
Crystalline Representative		Customer Representative	
			

Domestic water Tank Cleaning #1

Before Photo




After Photo



Before Photo



After Photo



We mention that the water tank has been cleaned and disinfected properly.

Service Report




Customer: Tafawuq facility management		Contact Person: Mr.sohail	
Site: Package C2 C3 - C10 C11, C10A -, City Of lights		Contact Number: -	
Description: Domestic water Tank Cleaning #3		Location: C11 Basement #01	
Type Of Building : <input type="checkbox"/> Commercial <input checked="" type="checkbox"/> Residential <input type="checkbox"/> Others			
Type Of Tank			
<input checked="" type="checkbox"/> Concrete	<input type="checkbox"/> GRP Panel	<input type="checkbox"/> FRP Tank	<input type="checkbox"/> Galvanized
<input type="checkbox"/> Steel Panel	<input type="checkbox"/> Plastic	<input type="checkbox"/> Concrete Coated	<input type="checkbox"/> Polyurethane
<input type="checkbox"/> Others			
Condition before cleaning		Condition after cleaning	
<input type="checkbox"/> Clean	<input type="checkbox"/> Dirty	<input checked="" type="checkbox"/> Very Dirty	<input type="checkbox"/> Very Dirty
<input type="checkbox"/> Biofilms	<input checked="" type="checkbox"/> Moulds	<input checked="" type="checkbox"/> Slime	<input type="checkbox"/> Slime
<input type="checkbox"/> Sediments	<input type="checkbox"/> Mud & Sand	<input type="checkbox"/> Rust	<input type="checkbox"/> Rust
Size of Tank			
M3:	USG:	L*B*H:	
Quantity Of Water		Manhole	
<input checked="" type="checkbox"/> Full	<input type="checkbox"/> Half	<input type="checkbox"/> Empty	<input type="checkbox"/> Covered
		<input type="checkbox"/> Damaged	<input checked="" type="checkbox"/> NA
Ladder In	Ladder Out		Leaks
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> Yes
		<input type="checkbox"/> No	<input checked="" type="checkbox"/> No
Drain Line	Valves		Float Valve
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input checked="" type="checkbox"/> Yes
		<input type="checkbox"/> No	<input type="checkbox"/> No
Tank Cleaned	Tank Disinfected		Pipes Disinfected
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input checked="" type="checkbox"/> Yes
		<input type="checkbox"/> No	<input type="checkbox"/> No
Chemicals Used			
Chemical: Crystal Shc		Quantity: 1ml	
Chemical: Crystal Shc		Quantity: 1ml	
Equipments Used			
<input checked="" type="checkbox"/> Submersibel Pump	<input checked="" type="checkbox"/> High/low Pressure Jet	<input checked="" type="checkbox"/> Extension Cords	<input checked="" type="checkbox"/> LED Lights
<input checked="" type="checkbox"/> Foot Bath	<input checked="" type="checkbox"/> Ladder	<input checked="" type="checkbox"/> Ventilating Fan	<input checked="" type="checkbox"/> Oxygen Meter
<input type="checkbox"/> Vacuum Cleaner	<input checked="" type="checkbox"/> Cleaning Materials	<input checked="" type="checkbox"/> Suction/Discharge Hoses	
Last Cleaning Date	Current Cleaning Date	Next Cleaning Date	
-	14 December 2020	14 June 2021	
Crystalline Representative		Customer Representative	
			

Domestic water Tank Cleaning #3

Before Photo




After Photo



Before Photo




After Photo



We mention that the water tank has been cleaned and disinfected properly.

Service Report




Customer: Tafawuq facility management		Contact Person: Mr.sohail	
Site: Package C2 C3 - C10 C11, C10A -, City Of lights		Contact Number: -	
Description: Domestic water Tank Cleaning #2		Location: C11 Roof top	
Type Of Building : <input type="checkbox"/> Commercial <input checked="" type="checkbox"/> Residential <input type="checkbox"/> Others			
Type Of Tank			
<input type="checkbox"/> Concrete	<input checked="" type="checkbox"/> GRP Panel	<input type="checkbox"/> FRP Tank	<input type="checkbox"/> Galvanized
<input type="checkbox"/> Steel Panel	<input type="checkbox"/> Plastic	<input type="checkbox"/> Concrete Coated	<input type="checkbox"/> Polyurethane
<input type="checkbox"/> Others			
Condition before cleaning		Condition after cleaning	
<input type="checkbox"/> Clean	<input type="checkbox"/> Dirty	<input checked="" type="checkbox"/> Very Dirty	
<input type="checkbox"/> Biofilms	<input checked="" type="checkbox"/> Moulds	<input checked="" type="checkbox"/> Slime	
<input type="checkbox"/> Sediments	<input type="checkbox"/> Mud & Sand	<input type="checkbox"/> Rust	
<input type="checkbox"/> Clean		<input type="checkbox"/> Dirty	
<input type="checkbox"/> Biofilms		<input type="checkbox"/> Moulds	
<input type="checkbox"/> Sediments		<input type="checkbox"/> Mud & Sand	
<input type="checkbox"/> Very Dirty		<input type="checkbox"/> Slime	
<input type="checkbox"/> Rust		<input type="checkbox"/> Rust	
Size of Tank			
M3:		USG:	
L*B*H:			
Quantity Of Water		Manhole	
<input checked="" type="checkbox"/> Full	<input type="checkbox"/> Half	<input type="checkbox"/> Empty	
<input type="checkbox"/> Covered		<input type="checkbox"/> Damaged	
<input checked="" type="checkbox"/> NA			
Ladder In		Ladder Out	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Leaks			
<input type="checkbox"/> Yes		<input checked="" type="checkbox"/> No	
Drain Line		Valves	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Float Valve			
<input checked="" type="checkbox"/> Yes		<input type="checkbox"/> No	
Tank Cleaned		Tank Disinfected	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Pipes Disinfected			
<input checked="" type="checkbox"/> Yes		<input type="checkbox"/> No	
Chemicals Used			
Chemical: Crystal Shc		Quantity: 1ml	
Chemical: Crystal Shc		Quantity: 1ml	
Equipments Used			
<input checked="" type="checkbox"/> Submersibel Pump	<input checked="" type="checkbox"/> High/low Pressure Jet	<input checked="" type="checkbox"/> Extension Cords	<input checked="" type="checkbox"/> LED Lights
<input checked="" type="checkbox"/> Foot Bath	<input checked="" type="checkbox"/> Ladder	<input checked="" type="checkbox"/> Ventilating Fan	<input checked="" type="checkbox"/> Oxygen Meter
<input type="checkbox"/> Vacuum Cleaner	<input checked="" type="checkbox"/> Cleaning Materials	<input checked="" type="checkbox"/> Suction/Discharge Hoses	
Last Cleaning Date		Current Cleaning Date	
-		14 December 2020	
Next Cleaning Date			
14 June 2021			
Crystalline Representative		Customer Representative	
			

Domestic water Tank Cleaning #2

Before Photo



After Photo



Before Photo



After Photo



We mention that the water tank has been cleaned and disinfected properly.

CRYSTALLINE CLEANING & ENVIRONMENTAL SERVICES

WATER TANK CLEANING & DISINFECTION

CLIENT NAME : TAFAWUQ FACILITY MANAGEMENT
CONTACT PERSON : MR. SOHAIL
DESIGNATION : FM SUPERVISOR
SITE DETAILS : C10, C11
DETAILS : WATER TANK CLEANING & DISINFECTION
DATE OF CLEANING : 10 DECEMBER 2020
FREQUENCY OF CLEANING : HALF YEARLY
DATE OF NEXT CLEANING : 10 JUNE 2021

The above water tanks were cleaned and disinfected in accordance with the Code of Practice for the inspection and cleaning of customer water storage tanks.



Tasman Pinto

CRYSTALLINE CLEANING AND ENVIRONMENTAL SERVICES