

**ENVIRONMENTAL
SERVICES FOR
A GREENER
TOMORROW...
ONE STEP AT
A TIME.**



CRYSTALLINE
ENVIRONMENTAL SERVICES



Completion Report for

Water Tank Cleaning & Disinfection

Date: **14 December 2020**
Client Name: **Tafawuq Facility Management**
Contact Person: **Mr. Sohail**
Designation: **FM Supervisor**
Site Detail: **C10A**



Service Report




| | | | |
|---|---|---|--|
| Customer: Tafawuq facility management | | Contact Person: Mr.sohail | |
| Site: Package C2 C3 - C10 C11, C10A -, City Of lights | | Contact Number: - | |
| Description: Domestic water Tank Cleaning #1 | | Location: Omega Basement #01 | |
| Type Of Building : <input type="checkbox"/> Commercial <input checked="" type="checkbox"/> Residential <input type="checkbox"/> Others | | | |
| Type Of Tank | | | |
| <input checked="" type="checkbox"/> Concrete | <input type="checkbox"/> GRP Panel | <input type="checkbox"/> FRP Tank | <input type="checkbox"/> Galvanized |
| <input type="checkbox"/> Steel Panel | <input type="checkbox"/> Plastic | <input type="checkbox"/> Concrete Coated | <input type="checkbox"/> Polyurethane |
| <input type="checkbox"/> Others | | | |
| Condition before cleaning | | Condition after cleaning | |
| <input type="checkbox"/> Clean | <input type="checkbox"/> Dirty | <input checked="" type="checkbox"/> Clean | <input type="checkbox"/> Dirty |
| <input type="checkbox"/> Biofilms | <input checked="" type="checkbox"/> Moulds | <input checked="" type="checkbox"/> Very Dirty | <input type="checkbox"/> Very Dirty |
| <input type="checkbox"/> Sediments | <input type="checkbox"/> Mud & Sand | <input checked="" type="checkbox"/> Slime | <input type="checkbox"/> Slime |
| | <input type="checkbox"/> Rust | <input type="checkbox"/> Sediments | <input type="checkbox"/> Mud & Sand |
| | | | <input type="checkbox"/> Rust |
| Size of Tank | | | |
| M3: | USG: | L*B*H: | |
| Quantity Of Water | | Manhole | |
| <input checked="" type="checkbox"/> Full | <input type="checkbox"/> Half | <input type="checkbox"/> Covered | <input type="checkbox"/> Damaged |
| | <input type="checkbox"/> Empty | | <input checked="" type="checkbox"/> NA |
| Ladder In | Ladder Out | Leaks | |
| <input checked="" type="checkbox"/> Yes | <input type="checkbox"/> No | <input type="checkbox"/> Yes | <input checked="" type="checkbox"/> No |
| Drain Line | Valves | Float Valve | |
| <input checked="" type="checkbox"/> Yes | <input type="checkbox"/> No | <input checked="" type="checkbox"/> Yes | <input type="checkbox"/> No |
| Tank Cleaned | Tank Disinfected | Pipes Disinfected | |
| <input checked="" type="checkbox"/> Yes | <input type="checkbox"/> No | <input checked="" type="checkbox"/> Yes | <input type="checkbox"/> No |
| Chemicals Used | | | |
| Chemical: Crystal Shc | | Quantity: 1ml | |
| Chemical: Crystal Shc | | Quantity: 1ml | |
| Equipments Used | | | |
| <input checked="" type="checkbox"/> Submersibel Pump | <input checked="" type="checkbox"/> High/low Pressure Jet | <input checked="" type="checkbox"/> Extension Cords | <input checked="" type="checkbox"/> LED Lights |
| <input checked="" type="checkbox"/> Foot Bath | <input checked="" type="checkbox"/> Ladder | <input checked="" type="checkbox"/> Ventilating Fan | <input checked="" type="checkbox"/> Oxygen Meter |
| <input type="checkbox"/> Vacuum Cleaner | <input checked="" type="checkbox"/> Cleaning Materials | <input checked="" type="checkbox"/> Suction/Discharge Hoses | |
| Last Cleaning Date | Current Cleaning Date | Next Cleaning Date | |
| - | 14 December 2020 | 14 June 2021 | |
| Crystalline Representative | | Customer Representative | |
|  | |  | |

Domestic water Tank Cleaning #1


Before Photo




After Photo



Before Photo




After Photo



We mention that the water tank has been cleaned and disinfected properly.

Service Report




| | | | |
|---|---|---|--|
| Customer: Tafawuq facility management | | Contact Person: Mr.sohail | |
| Site: Package C2 C3 - C10 C11, C10A -, City Of lights | | Contact Number: - | |
| Description: Domestic water Tank Cleaning #1 | | Location: Omega 44th floor | |
| Type Of Building : <input type="checkbox"/> Commercial <input checked="" type="checkbox"/> Residential <input type="checkbox"/> Others | | | |
| Type Of Tank | | | |
| <input checked="" type="checkbox"/> Concrete | <input type="checkbox"/> GRP Panel | <input type="checkbox"/> FRP Tank | <input type="checkbox"/> Galvanized |
| <input type="checkbox"/> Steel Panel | <input type="checkbox"/> Plastic | <input type="checkbox"/> Concrete Coated | <input type="checkbox"/> Polyurethane |
| <input type="checkbox"/> Others | | | |
| Condition before cleaning | | Condition after cleaning | |
| <input type="checkbox"/> Clean | <input type="checkbox"/> Dirty | <input checked="" type="checkbox"/> Clean | <input type="checkbox"/> Dirty |
| <input type="checkbox"/> Biofilms | <input checked="" type="checkbox"/> Moulds | <input checked="" type="checkbox"/> Slime | <input type="checkbox"/> Very Dirty |
| <input type="checkbox"/> Sediments | <input type="checkbox"/> Mud & Sand | <input type="checkbox"/> Biofilms | <input type="checkbox"/> Moulds |
| | | <input type="checkbox"/> Slime | <input type="checkbox"/> Rust |
| | | <input type="checkbox"/> Sediments | <input type="checkbox"/> Mud & Sand |
| | | <input type="checkbox"/> Rust | |
| Size of Tank | | | |
| M3: | USG: | L*B*H: | |
| Quantity Of Water | | Manhole | |
| <input checked="" type="checkbox"/> Full | <input type="checkbox"/> Half | <input type="checkbox"/> Covered | <input type="checkbox"/> Damaged |
| <input type="checkbox"/> Empty | | <input checked="" type="checkbox"/> NA | |
| Ladder In | Ladder Out | Leaks | |
| <input checked="" type="checkbox"/> Yes | <input type="checkbox"/> No | <input type="checkbox"/> Yes | <input checked="" type="checkbox"/> No |
| Drain Line | Valves | Float Valve | |
| <input checked="" type="checkbox"/> Yes | <input type="checkbox"/> No | <input checked="" type="checkbox"/> Yes | <input type="checkbox"/> No |
| Tank Cleaned | Tank Disinfected | Pipes Disinfected | |
| <input checked="" type="checkbox"/> Yes | <input type="checkbox"/> No | <input checked="" type="checkbox"/> Yes | <input type="checkbox"/> No |
| Chemicals Used | | | |
| Chemical: Crystal Shc | | Quantity: 500ml | |
| Chemical: Crystal Shc | | Quantity: 500ml | |
| Equipments Used | | | |
| <input checked="" type="checkbox"/> Submersibel Pump | <input checked="" type="checkbox"/> High/low Pressure Jet | <input checked="" type="checkbox"/> Extension Cords | <input checked="" type="checkbox"/> LED Lights |
| <input checked="" type="checkbox"/> Foot Bath | <input checked="" type="checkbox"/> Ladder | <input checked="" type="checkbox"/> Ventilating Fan | <input checked="" type="checkbox"/> Oxygen Meter |
| <input type="checkbox"/> Vacuum Cleaner | <input checked="" type="checkbox"/> Cleaning Materials | <input checked="" type="checkbox"/> Suction/Discharge Hoses | |
| Last Cleaning Date | Current Cleaning Date | Next Cleaning Date | |
| - | 13 December 2020 | 13 June 2021 | |
| Crystalline Representative | | Customer Representative | |
|  | |  | |

Domestic water Tank Cleaning #1


Before Photo



After Photo



Before Photo



After Photo



We mention that the water tank has been cleaned and disinfected properly.

Service Report




| | | | |
|---|---|---|--|
| Customer: Tafawuq facility management | | Contact Person: Mr.sohail | |
| Site: Package C2 C3 - C10 C11, C10A -, City Of lights | | Contact Number: - | |
| Description: Domestic water Tank Cleaning #2 | | Location: Omega 44th floor | |
| Type Of Building : <input type="checkbox"/> Commercial <input checked="" type="checkbox"/> Residential <input type="checkbox"/> Others | | | |
| Type Of Tank | | | |
| <input checked="" type="checkbox"/> Concrete | <input type="checkbox"/> GRP Panel | <input type="checkbox"/> FRP Tank | <input type="checkbox"/> Galvanized |
| <input type="checkbox"/> Steel Panel | <input type="checkbox"/> Plastic | <input type="checkbox"/> Concrete Coated | <input type="checkbox"/> Polyurethane |
| <input type="checkbox"/> Others | | | |
| Condition before cleaning | | Condition after cleaning | |
| <input type="checkbox"/> Clean | <input type="checkbox"/> Dirty | <input checked="" type="checkbox"/> Clean | <input type="checkbox"/> Dirty |
| <input type="checkbox"/> Biofilms | <input checked="" type="checkbox"/> Moulds | <input checked="" type="checkbox"/> Very Dirty | <input type="checkbox"/> Very Dirty |
| <input type="checkbox"/> Sediments | <input type="checkbox"/> Mud & Sand | <input checked="" type="checkbox"/> Slime | <input type="checkbox"/> Slime |
| | <input type="checkbox"/> Rust | <input type="checkbox"/> Sediments | <input type="checkbox"/> Mud & Sand |
| | | | <input type="checkbox"/> Rust |
| Size of Tank | | | |
| M3: | USG: | L*B*H: | |
| Quantity Of Water | | Manhole | |
| <input checked="" type="checkbox"/> Full | <input type="checkbox"/> Half | <input type="checkbox"/> Covered | <input type="checkbox"/> Damaged |
| <input type="checkbox"/> Empty | | <input checked="" type="checkbox"/> NA | |
| Ladder In | Ladder Out | Leaks | |
| <input checked="" type="checkbox"/> Yes | <input type="checkbox"/> No | <input type="checkbox"/> Yes | <input checked="" type="checkbox"/> No |
| Drain Line | Valves | Float Valve | |
| <input checked="" type="checkbox"/> Yes | <input type="checkbox"/> No | <input checked="" type="checkbox"/> Yes | <input type="checkbox"/> No |
| Tank Cleaned | Tank Disinfected | Pipes Disinfected | |
| <input checked="" type="checkbox"/> Yes | <input type="checkbox"/> No | <input checked="" type="checkbox"/> Yes | <input type="checkbox"/> No |
| Chemicals Used | | | |
| Chemical: Crystal Shc | | Quantity: 500ml | |
| Chemical: Crystal Shc | | Quantity: 500ml | |
| Equipments Used | | | |
| <input checked="" type="checkbox"/> Submersibel Pump | <input checked="" type="checkbox"/> High/low Pressure Jet | <input checked="" type="checkbox"/> Extension Cords | <input checked="" type="checkbox"/> LED Lights |
| <input checked="" type="checkbox"/> Foot Bath | <input checked="" type="checkbox"/> Ladder | <input checked="" type="checkbox"/> Ventilating Fan | <input checked="" type="checkbox"/> Oxygen Meter |
| <input type="checkbox"/> Vacuum Cleaner | <input checked="" type="checkbox"/> Cleaning Materials | <input checked="" type="checkbox"/> Suction/Discharge Hoses | |
| Last Cleaning Date | Current Cleaning Date | Next Cleaning Date | |
| - | 13 December 2020 | 13 June 2021 | |
| Crystalline Representative | | Customer Representative | |
|  | |  | |

Domestic water Tank Cleaning #2

Before Photo




After Photo



Before Photo




After Photo



We mention that the water tank has been cleaned and disinfected properly.

Service Report



| | | | |
|---|---|---|--|
| Customer: Tafawuq facility management | | Contact Person: Mr.sohail | |
| Site: Package C2 C3 - C10 C11, C10A -, City Of lights | | Contact Number: - | |
| Description: Domestic water Tank Cleaning #2 | | Location: Omega 16th floor | |
| Type Of Building : <input type="checkbox"/> Commercial <input checked="" type="checkbox"/> Residential <input type="checkbox"/> Others | | | |
| Type Of Tank | | | |
| <input checked="" type="checkbox"/> Concrete | <input type="checkbox"/> GRP Panel | <input type="checkbox"/> FRP Tank | <input type="checkbox"/> Galvanized |
| <input type="checkbox"/> Steel Panel | <input type="checkbox"/> Plastic | <input type="checkbox"/> Concrete Coated | <input type="checkbox"/> Polyurethane |
| <input type="checkbox"/> Others | | | |
| Condition before cleaning | | Condition after cleaning | |
| <input type="checkbox"/> Clean | <input type="checkbox"/> Dirty | <input checked="" type="checkbox"/> Clean | <input type="checkbox"/> Dirty |
| <input type="checkbox"/> Biofilms | <input checked="" type="checkbox"/> Moulds | <input type="checkbox"/> Biofilms | <input type="checkbox"/> Moulds |
| <input type="checkbox"/> Sediments | <input type="checkbox"/> Mud & Sand | <input type="checkbox"/> Sediments | <input type="checkbox"/> Mud & Sand |
| <input checked="" type="checkbox"/> Very Dirty | <input checked="" type="checkbox"/> Slime | <input type="checkbox"/> Very Dirty | <input type="checkbox"/> Slime |
| <input type="checkbox"/> Rust | | <input type="checkbox"/> Rust | |
| Size of Tank | | | |
| M3: | USG: | L*B*H: | |
| Quantity Of Water | | Manhole | |
| <input checked="" type="checkbox"/> Full | <input type="checkbox"/> Half | <input type="checkbox"/> Covered | <input type="checkbox"/> Damaged |
| <input type="checkbox"/> Empty | | <input checked="" type="checkbox"/> NA | |
| Ladder In | Ladder Out | Leaks | |
| <input checked="" type="checkbox"/> Yes | <input type="checkbox"/> No | <input type="checkbox"/> Yes | <input checked="" type="checkbox"/> No |
| Drain Line | Valves | Float Valve | |
| <input checked="" type="checkbox"/> Yes | <input type="checkbox"/> No | <input checked="" type="checkbox"/> Yes | <input type="checkbox"/> No |
| Tank Cleaned | Tank Disinfected | Pipes Disinfected | |
| <input checked="" type="checkbox"/> Yes | <input type="checkbox"/> No | <input checked="" type="checkbox"/> Yes | <input type="checkbox"/> No |
| Chemicals Used | | | |
| Chemical: Crystal Shc | | Quantity: 500ml | |
| Chemical: Crystal Shc | | Quantity: 500ml | |
| Equipments Used | | | |
| <input checked="" type="checkbox"/> Submersibel Pump | <input checked="" type="checkbox"/> High/low Pressure Jet | <input checked="" type="checkbox"/> Extension Cords | <input checked="" type="checkbox"/> LED Lights |
| <input checked="" type="checkbox"/> Foot Bath | <input checked="" type="checkbox"/> Ladder | <input checked="" type="checkbox"/> Ventilating Fan | <input checked="" type="checkbox"/> Oxygen Meter |
| <input type="checkbox"/> Vacuum Cleaner | <input checked="" type="checkbox"/> Cleaning Materials | <input checked="" type="checkbox"/> Suction/Discharge Hoses | |
| Last Cleaning Date | Current Cleaning Date | Next Cleaning Date | |
| - | 14 December 2020 | 14 June 2021 | |
| Crystalline Representative | | Customer Representative | |
|  | |  | |

Domestic water Tank Cleaning #2


Before Photo



After Photo



Before Photo




After Photo



We mention that the water tank has been cleaned and disinfected properly.

Service Report




| | | | |
|---|---|---|--|
| Customer: Tafawuq facility management | | Contact Person: Mr.sohail | |
| Site: Package C2 C3 - C10 C11, C10A -, City Of lights | | Contact Number: - | |
| Description: Domestic water Tank Cleaning #1 | | Location: Omega 16th floor | |
| Type Of Building : <input type="checkbox"/> Commercial <input checked="" type="checkbox"/> Residential <input type="checkbox"/> Others | | | |
| Type Of Tank | | | |
| <input checked="" type="checkbox"/> Concrete | <input type="checkbox"/> GRP Panel | <input type="checkbox"/> FRP Tank | <input type="checkbox"/> Galvanized |
| <input type="checkbox"/> Steel Panel | <input type="checkbox"/> Plastic | <input type="checkbox"/> Concrete Coated | <input type="checkbox"/> Polyurethane |
| <input type="checkbox"/> Others | | | |
| Condition before cleaning | | Condition after cleaning | |
| <input type="checkbox"/> Clean | <input type="checkbox"/> Dirty | <input checked="" type="checkbox"/> Very Dirty | <input type="checkbox"/> Very Dirty |
| <input type="checkbox"/> Biofilms | <input checked="" type="checkbox"/> Moulds | <input checked="" type="checkbox"/> Slime | <input type="checkbox"/> Slime |
| <input type="checkbox"/> Sediments | <input type="checkbox"/> Mud & Sand | <input type="checkbox"/> Rust | <input type="checkbox"/> Rust |
| Size of Tank | | | |
| M3: | | USG: | L*B*H: |
| Quantity Of Water | | Manhole | |
| <input checked="" type="checkbox"/> Full | <input type="checkbox"/> Half | <input type="checkbox"/> Empty | <input type="checkbox"/> Covered |
| | | <input type="checkbox"/> Damaged | <input checked="" type="checkbox"/> NA |
| Ladder In | | Ladder Out | |
| <input checked="" type="checkbox"/> Yes | <input type="checkbox"/> No | <input checked="" type="checkbox"/> Yes | <input type="checkbox"/> No |
| | | Leaks | |
| | | <input type="checkbox"/> Yes | <input checked="" type="checkbox"/> No |
| Drain Line | | Valves | |
| <input checked="" type="checkbox"/> Yes | <input type="checkbox"/> No | <input checked="" type="checkbox"/> Yes | <input type="checkbox"/> No |
| | | Float Valve | |
| | | <input checked="" type="checkbox"/> Yes | <input type="checkbox"/> No |
| Tank Cleaned | | Tank Disinfected | |
| <input checked="" type="checkbox"/> Yes | <input type="checkbox"/> No | <input checked="" type="checkbox"/> Yes | <input type="checkbox"/> No |
| | | Pipes Disinfected | |
| | | <input checked="" type="checkbox"/> Yes | <input type="checkbox"/> No |
| Chemicals Used | | | |
| Chemical: Crystal Shc | | Quantity: 500ml | |
| Chemical: Crystal Shc | | Quantity: 500ml | |
| Equipments Used | | | |
| <input checked="" type="checkbox"/> Submersibel Pump | <input checked="" type="checkbox"/> High/low Pressure Jet | <input checked="" type="checkbox"/> Extension Cords | <input checked="" type="checkbox"/> LED Lights |
| <input checked="" type="checkbox"/> Foot Bath | <input checked="" type="checkbox"/> Ladder | <input checked="" type="checkbox"/> Ventilating Fan | <input checked="" type="checkbox"/> Oxygen Meter |
| <input type="checkbox"/> Vacuum Cleaner | <input checked="" type="checkbox"/> Cleaning Materials | <input checked="" type="checkbox"/> Suction/Discharge Hoses | |
| Last Cleaning Date | | Current Cleaning Date | |
| - | | 16 December 2020 | |
| | | Next Cleaning Date | |
| | | 16 June 2021 | |
| Crystalline Representative | | Customer Representative | |
|  | |  | |

Domestic water Tank Cleaning #1

Before Photo




After Photo



Before Photo



After Photo



We mention that the water tank has been cleaned and disinfected properly.


Service Report



| | | | |
|---|---|---|--|
| Customer: Tafawuq facility management | | Contact Person: Mr.sohail | |
| Site: Package C2 C3 - C10 C11, C10A -, City Of lights | | Contact Number: - | |
| Description: Domestic Water Tank Cleaning #2 | | Location: Omega Basement #01 | |
| Type Of Building : <input type="checkbox"/> Commercial <input checked="" type="checkbox"/> Residential <input type="checkbox"/> Others | | | |
| Type Of Tank | | | |
| <input checked="" type="checkbox"/> Concrete | <input type="checkbox"/> GRP Panel | <input type="checkbox"/> FRP Tank | <input type="checkbox"/> Galvanized |
| <input type="checkbox"/> Steel Panel | <input type="checkbox"/> Plastic | <input type="checkbox"/> Concrete Coated | <input type="checkbox"/> Polyurethane |
| <input type="checkbox"/> Others | | | |
| Condition before cleaning | | Condition after cleaning | |
| <input type="checkbox"/> Clean | <input type="checkbox"/> Dirty | <input checked="" type="checkbox"/> Very Dirty | <input type="checkbox"/> Very Dirty |
| <input type="checkbox"/> Biofilms | <input checked="" type="checkbox"/> Moulds | <input checked="" type="checkbox"/> Slime | <input type="checkbox"/> Slime |
| <input type="checkbox"/> Sediments | <input type="checkbox"/> Mud & Sand | <input type="checkbox"/> Rust | <input type="checkbox"/> Rust |
| Size of Tank | | | |
| M3: | | USG: | |
| | | L*B*H: | |
| Quantity Of Water | | Manhole | |
| <input checked="" type="checkbox"/> Full | <input type="checkbox"/> Half | <input type="checkbox"/> Empty | <input type="checkbox"/> Covered |
| | | <input type="checkbox"/> Damaged | <input checked="" type="checkbox"/> NA |
| Ladder In | | Ladder Out | |
| <input checked="" type="checkbox"/> Yes | <input type="checkbox"/> No | <input checked="" type="checkbox"/> Yes | <input type="checkbox"/> No |
| | | Leaks | |
| | | <input type="checkbox"/> Yes | <input checked="" type="checkbox"/> No |
| Drain Line | | Valves | |
| <input checked="" type="checkbox"/> Yes | <input type="checkbox"/> No | <input checked="" type="checkbox"/> Yes | <input type="checkbox"/> No |
| | | Float Valve | |
| | | <input checked="" type="checkbox"/> Yes | <input type="checkbox"/> No |
| Tank Cleaned | | Tank Disinfected | |
| <input checked="" type="checkbox"/> Yes | <input type="checkbox"/> No | <input checked="" type="checkbox"/> Yes | <input type="checkbox"/> No |
| | | Pipes Disinfected | |
| | | <input checked="" type="checkbox"/> Yes | <input type="checkbox"/> No |
| Chemicals Used | | | |
| Chemical: Crystal Shc | | Quantity: 1ml | |
| Chemical: Crystal Shc | | Quantity: 1ml | |
| Equipments Used | | | |
| <input checked="" type="checkbox"/> Submersibel Pump | <input checked="" type="checkbox"/> High/low Pressure Jet | <input checked="" type="checkbox"/> Extension Cords | <input checked="" type="checkbox"/> LED Lights |
| <input checked="" type="checkbox"/> Foot Bath | <input checked="" type="checkbox"/> Ladder | <input checked="" type="checkbox"/> Ventilating Fan | <input checked="" type="checkbox"/> Oxygen Meter |
| <input type="checkbox"/> Vacuum Cleaner | <input checked="" type="checkbox"/> Cleaning Materials | <input checked="" type="checkbox"/> Suction/Discharge Hoses | |
| Last Cleaning Date | | Current Cleaning Date | |
| - | | 16 December 2020 | |
| | | Next Cleaning Date | |
| | | 16 June 2021 | |
| Crystalline Representative | | Customer Representative | |
|  | |  | |

Domestic Water Tank Cleaning #2


Before Photo



After Photo



Before Photo



After Photo



We mention that the water tank has been cleaned and disinfected properly.

CRYSTALLINE CLEANING & ENVIRONMENTAL SERVICES

WATER TANK CLEANING & DISINFECTION

CLIENT NAME : TAFAWUQ FACILITY MANAGEMENT
CONTACT PERSON : MR. SOHAIL
DESIGNATION : FM SUPERVISOR
SITE DETAILS : C10A
DETAILS : WATER TANK CLEANING & DISINFECTION
DATE OF CLEANING : 14 DECEMBER 2020
FREQUENCY OF CLEANING : HALF YEARLY
DATE OF NEXT CLEANING : 14 JUNE 2021

The above water tanks were cleaned and disinfected in accordance with the Code of Practice for the inspection and cleaning of customer water storage tanks.



Tasman Pinto

CRYSTALLINE CLEANING AND ENVIRONMENTAL SERVICES