

# WATER TANK CLEANING & DISINFECTION

## COMPLETION REPORT

FOR



Client : COFELY BESIX FACILITY  
MANAGEMENT  
Contact Person: Mr. Abdul Salam  
Facility Manager  
Site Details : HCT - Abu Dhabi Women's  
College, Abu Dhabi  
Date : 30 August 2018



**CRYSTALLINE**  
ENVIRONMENTAL SERVICES

CRYSTALLINE ENVIRONMENTAL  
SERVICES

P.O. BOX 131463, Abu Dhabi, U.A.E.  
TEL: 02 6508930 FAX: 02 6508942

[info@crystalline-uae.com](mailto:info@crystalline-uae.com)

[www.crystalline-uae.com](http://www.crystalline-uae.com)





# CRYSTALLINE ENVIRONMENTAL SERVICES

## WATER TANK - AFTER SERVICE REPORT

15662

CUSTOMER: <u>COFELY BESIDE</u>			CONTACT PERSON: <u>Mr. bhatib</u>		
SITE DETAILS: <u>WOMEN'S COLLEGE ABU D.</u>			CONTACT NO: <u>056 997 2152</u>		
TANK DETAILS: <u>GRP DOMESTIC TANK N. 01</u>			LOCATION DETAILS: <u>BLOCK-A ROOF TOP</u>		
TYPE OF BUILDING: <input checked="" type="checkbox"/> COMMERCIAL			<input type="checkbox"/> RESIDENTIAL		<input type="checkbox"/> OTHERS
TYPE OF TANK					
<input type="checkbox"/> CONCRETE	<input checked="" type="checkbox"/> GRP PANEL	<input type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED		<input type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS		
SIZE OF TANK			QUANTITY OF WATER		
M3	USG	L*B*H	<input checked="" type="checkbox"/> FULL	<input type="checkbox"/> HALF	<input type="checkbox"/> EMPTY
CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK AFTER CLEANING		
<input type="checkbox"/> CLEAN	<input checked="" type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
ACCESS		MANHOLE	<input type="checkbox"/> COVERED	<input type="checkbox"/> DAMAGED	<input type="checkbox"/> NA
LADDER IN	LADDER OUT	LEAKS	DRAIN LINE	VALVES	FLOAT VALVE
<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO
TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED	
<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input type="checkbox"/> YES <input type="checkbox"/> NO	<input type="checkbox"/> YES <input type="checkbox"/> NO	<input type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> NA
LAST CLEANING DATE		CURRENT CLEANING DATE		NEXT CLEANING DATE	
		<u>28-07-2018</u>		<u>28-01-2019</u>	
CHEMICALS & EQUIPMENTS USED					
1. <u>CARELA BIO \$ PLUS</u> Quantity <u>400CC</u>					
2. _____ Quantity _____					
<input checked="" type="checkbox"/> Submersibel Pump	<input checked="" type="checkbox"/> High/Low Pressure Jet	<input checked="" type="checkbox"/> Extension Cords	<input checked="" type="checkbox"/> LED lights	<input checked="" type="checkbox"/> Foot Bath	<input checked="" type="checkbox"/> Ladder
<input checked="" type="checkbox"/> Ventilating Fan	<input checked="" type="checkbox"/> Suction/Discharge Hoses	<input checked="" type="checkbox"/> Oxygen Meter	<input checked="" type="checkbox"/> Vacuum Cleaner	<input checked="" type="checkbox"/> Cleaning Materials	
COMMENTS & RECOMMENDATIONS:					
<u>TANK CLEANED &amp; DISINFECTED</u>					
Crystalline Representative: <u>VETALIST</u>			Signature: <u>[Signature]</u>		


Date of Cleaning: 28-07-2018

**PHOTOGRAPHS**  
**ROOF TOP GRP WATER TANK – 01 (BLOCK - A)**

**BEFORE**



**AFTER**





# CRYSTALLINE ENVIRONMENTAL SERVICES

## WATER TANK - AFTER SERVICE REPORT

15657

CUSTOMER: <u>COFFEY BESIX</u>			CONTACT PERSON: <u>Mrs. Shakib.</u>		
SITE DETAILS: <u>WOMEN'S COLLEGE ABU DHABI</u>			CONTACT NO: <u>056 997 2152</u>		
TANK DETAILS: <u>FIBER DOMESTIC TANK - N.02</u>			LOCATION DETAILS: <u>BLOCK-A ROOF TOP</u>		
TYPE OF BUILDING: <input checked="" type="checkbox"/> COMMERCIAL		<input type="checkbox"/> RESIDENTIAL		<input type="checkbox"/> OTHERS	
<b>TYPE OF TANK</b>					
<input type="checkbox"/> CONCRETE	<input type="checkbox"/> GRP PANEL	<input checked="" type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED		<input type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS		
<b>SIZE OF TANK</b>			<b>QUANTITY OF WATER</b>		
M3	USG	L*B*H	<input checked="" type="checkbox"/> FULL	<input type="checkbox"/> HALF	<input type="checkbox"/> EMPTY
<b>CONDITION OF WATER TANK BEFORE CLEANING</b>			<b>CONDITION OF WATER TANK AFTER CLEANING</b>		
<input type="checkbox"/> CLEAN	<input checked="" type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
<b>ACCESS</b>		<b>MANHOLE</b>		<input type="checkbox"/> COVERED	<input type="checkbox"/> DAMAGED
<input type="checkbox"/> NA		<input type="checkbox"/> NA		<input type="checkbox"/> NA	<input type="checkbox"/> NA
<b>LADDER IN</b>		<b>LADDER OUT</b>		<b>LEAKS</b>	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO
<b>DRAIN LINE</b>		<b>VALVES</b>		<b>FLOAT VALVE</b>	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO
<b>TANK CLEANED</b>		<b>TANK DISINFECTED</b>		<b>PIPES DISINFECTED</b>	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> YES	<input type="checkbox"/> NO <input checked="" type="checkbox"/> NA
<b>LAST CLEANING DATE</b>		<b>CURRENT CLEANING DATE</b>		<b>NEXT CLEANING DATE</b>	
		<u>28-07-2018</u>		<u>28-01-2019</u>	
<b>CHEMICALS &amp; EQUIPMENTS USED</b>					
1. <u>CAECLA BIO &amp; PLUS</u> Quantity <u>300cc</u>					
2. _____ Quantity _____					
<input checked="" type="checkbox"/> Submersibel Pump <input checked="" type="checkbox"/> High/Low Pressure Jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED lights <input checked="" type="checkbox"/> Foot Bath <input checked="" type="checkbox"/> Ladder					
<input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Meter <input checked="" type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials					
<b>COMMENTS &amp; RECOMMENDATIONS:</b>					
<u>TANK CLEANED &amp; DISINFECTED</u>					
Crystalline Representative: <u>NETALIST</u>			Signature: <u>[Signature]</u>		



**CRYSTALLINE**  
ENVIRONMENTAL SERVICES

Date of Cleaning: 28-07-2018

**PHOTOGRAPHS**  
**ROOF TOP FRP WATER TANK – 02 (BLOCK - A)**

**BEFORE**



**AFTER**



**CLEANER WATER GREENER TOMORROW**



# CRYSTALLINE ENVIRONMENTAL SERVICES

## WATER TANK - AFTER SERVICE REPORT

15658

CUSTOMER: <u>COFELY BESIX</u>			CONTACT PERSON: <u>Mr. Shetib.</u>		
SITE DETAILS: <u>WOMEN'S COLLEGE HIBU DHABI</u>			CONTACT NO: <u>056 997 2152</u>		
TANK DETAILS: <u>FIBER DOMESTIC TANK N.03</u>			LOCATION DETAILS: <u>BLOCK-A ROOF TOP</u>		
TYPE OF BUILDING: <input checked="" type="checkbox"/> COMMERCIAL		<input type="checkbox"/> RESIDENTIAL		<input type="checkbox"/> OTHERS	
<b>TYPE OF TANK</b>					
<input type="checkbox"/> CONCRETE	<input type="checkbox"/> GRP PANEL	<input checked="" type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED		<input type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS		
<b>SIZE OF TANK</b>			<b>QUANTITY OF WATER</b>		
M3	USG	L*B*H	<input checked="" type="checkbox"/> FULL	<input type="checkbox"/> HALF	<input type="checkbox"/> EMPTY
<b>CONDITION OF WATER TANK BEFORE CLEANING</b>			<b>CONDITION OF WATER TANK AFTER CLEANING</b>		
<input type="checkbox"/> CLEAN	<input checked="" type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
<b>ACCESS</b>		<b>MANHOLE</b>		<input type="checkbox"/> COVERED	<input type="checkbox"/> DAMAGED
<input type="checkbox"/> NA	<input type="checkbox"/> NA	<input type="checkbox"/> NA		<input type="checkbox"/> NA	<input type="checkbox"/> NA
<b>LADDER IN</b>		<b>LADDER OUT</b>		<b>LEAKS</b>	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO
<b>TANK CLEANED</b>		<b>TANK DISINFECTED</b>		<b>PIPES DISINFECTED</b>	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> YES	<input type="checkbox"/> NO
<b>LAST CLEANING DATE</b>		<b>CURRENT CLEANING DATE</b>		<b>NEXT CLEANING DATE</b>	
		<u>28-07-2018</u>		<u>28-01-2019</u>	
<b>CHEMICALS &amp; EQUIPMENTS USED</b>					
1. <u>CARELA BIO \$ PLUS</u> Quantity <u>400cc</u>					
2. _____ Quantity _____					
<input checked="" type="checkbox"/> Submersibel Pump <input checked="" type="checkbox"/> High/Low Pressure Jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED lights <input checked="" type="checkbox"/> Foot Bath <input checked="" type="checkbox"/> Ladder					
<input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Meter <input checked="" type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials					
<b>COMMENTS &amp; RECOMMENDATIONS:</b>					
<u>TANK CLEANED \$ DISINFECTED</u>					
Crystalline Representative: <u>VETAHST</u>			Signature: <u>[Signature]</u>		




**CRYSTALLINE**  
ENVIRONMENTAL SERVICES

Date of Cleaning: 28-07-2018

## PHOTOGRAPHS

### ROOF TOP FRP WATER TANK – 03 (BLOCK - A)

**BEFORE**



**AFTER**



**CLEANER WATER GREENER TOMORROW**



# CRYSTALLINE ENVIRONMENTAL SERVICES

## WATER TANK - AFTER SERVICE REPORT

15659

CUSTOMER: <u>COFFELY BESIX</u>			CONTACT PERSON: <u>Mr. Shrikib.</u>		
SITE DETAILS: <u>WOMEN'S COLLEGE ABCU DHABI</u>			CONTACT NO: <u>056 997 2152</u>		
TANK DETAILS: <u>FIBER DOMESTIC TANK N. 04</u>			LOCATION DETAILS: <u>SECURITY G. ROOF TOP</u>		
TYPE OF BUILDING: <input checked="" type="checkbox"/> COMMERCIAL		<input type="checkbox"/> RESIDENTIAL		<input type="checkbox"/> OTHERS	
<b>TYPE OF TANK</b>					
<input type="checkbox"/> CONCRETE	<input type="checkbox"/> GRP PANEL	<input checked="" type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED		<input type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS		
<b>SIZE OF TANK</b>			<b>QUANTITY OF WATER</b>		
M3	USG	L*B*H	<input type="checkbox"/> FULL	<input checked="" type="checkbox"/> HALF	<input type="checkbox"/> EMPTY
<b>CONDITION OF WATER TANK BEFORE CLEANING</b>			<b>CONDITION OF WATER TANK AFTER CLEANING</b>		
<input type="checkbox"/> CLEAN	<input checked="" type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
<b>ACCESS</b>		<b>MANHOLE</b>		<input type="checkbox"/> COVERED	<input type="checkbox"/> DAMAGED
				<input type="checkbox"/> NA	
<b>LADDER IN</b>		<b>LADDER OUT</b>		<b>LEAKS</b>	
<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO
<b>DRAIN LINE</b>		<b>VALVES</b>		<b>FLOAT VALVE</b>	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO
<b>TANK CLEANED</b>		<b>TANK DISINFECTED</b>		<b>PIPES DISINFECTED</b>	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> YES	<input type="checkbox"/> NO
				<input checked="" type="checkbox"/> NA	
<b>LAST CLEANING DATE</b>		<b>CURRENT CLEANING DATE</b>		<b>NEXT CLEANING DATE</b>	
		<u>28-07-2018</u>		<u>28-01-2019</u>	
<b>CHEMICALS &amp; EQUIPMENTS USED</b>					
1. <u>CARELA BIO \$ PLUS</u> Quantity <u>200cc</u>					
2. _____ Quantity _____					
<input checked="" type="checkbox"/> Submersibel Pump <input checked="" type="checkbox"/> High/Low Pressure Jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED lights <input checked="" type="checkbox"/> Foot Bath <input checked="" type="checkbox"/> Ladder					
<input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Meter <input checked="" type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials					
<b>COMMENTS &amp; RECOMMENDATIONS:</b>					
<u>TANK CLEANED &amp; DISINFECTED</u>					
Crystalline Representative: <u>VETALIST</u>			Signature: <u>[Signature]</u>		



Date of Cleaning: 28-07-2018

**PHOTOGRAPHS**  
**ROOF TOP FRP WATER TANK – 04**

**BEFORE**



**AFTER**





# CRYSTALLINE ENVIRONMENTAL SERVICES

## WATER TANK - AFTER SERVICE REPORT

15660

CUSTOMER: <u>COFFELY BESIDE</u>			CONTACT PERSON: <u>Mr. Shaksb</u>		
SITE DETAILS: <u>WOMEN'S COLLEGE ABU DHABI</u>			CONTACT NO: <u>056 917 2152</u>		
TANK DETAILS: <u>FIBER DOMESTIC TANK NOS</u>			LOCATION DETAILS: <u>SECURITY G. ROOF TOP</u>		
TYPE OF BUILDING: <input checked="" type="checkbox"/> COMMERCIAL			<input type="checkbox"/> RESIDENTIAL		<input type="checkbox"/> OTHERS
<b>TYPE OF TANK</b>					
<input type="checkbox"/> CONCRETE	<input type="checkbox"/> GRP PANEL	<input checked="" type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED		<input type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS		
<b>SIZE OF TANK</b>			<b>QUANTITY OF WATER</b>		
M3	USG	L*B*H	<input checked="" type="checkbox"/> FULL	<input type="checkbox"/> HALF	<input type="checkbox"/> EMPTY
<b>CONDITION OF WATER TANK BEFORE CLEANING</b>			<b>CONDITION OF WATER TANK AFTER CLEANING</b>		
<input type="checkbox"/> CLEAN	<input checked="" type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
<b>ACCESS</b>		<b>MANHOLE</b>	<input type="checkbox"/> COVERED	<input type="checkbox"/> DAMAGED	<input type="checkbox"/> NA
<b>LADDER IN</b>	<b>LADDER OUT</b>	<b>LEAKS</b>	<b>DRAIN LINE</b>	<b>VALVES</b>	<b>FLOAT VALVE</b>
<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO
<b>TANK CLEANED</b>		<b>TANK DISINFECTED</b>		<b>PIPES DISINFECTED</b>	
<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> NA	
<b>LAST CLEANING DATE</b>		<b>CURRENT CLEANING DATE</b>		<b>NEXT CLEANING DATE</b>	
		<u>28-07-2018</u>		<u>28-01-2019</u>	
<b>CHEMICALS &amp; EQUIPMENTS USED</b>					
1. <u>CARELA BIO &amp; PLUS</u> Quantity <u>200cc</u>					
2. _____ Quantity _____					
<input checked="" type="checkbox"/> Submersibel Pump <input checked="" type="checkbox"/> High/Low Pressure Jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED lights <input checked="" type="checkbox"/> Foot Bath <input checked="" type="checkbox"/> Ladder <input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Meter <input checked="" type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials					
<b>COMMENTS &amp; RECOMMENDATIONS:</b>					
<u>TANK CLEANED &amp; DISINFECTED</u>					
Crystalline Representative: <u>VETALIST</u>			Signature: <u>[Signature]</u>		




**CRYSTALLINE**  
ENVIRONMENTAL SERVICES

Date of Cleaning: 28-07-2018

**PHOTOGRAPHS**  
**ROOF TOP FRP WATER TANK - 05**

**BEFORE**



**AFTER**



**CLEANER WATER GREENER TOMORROW**



# CRYSTALLINE ENVIRONMENTAL SERVICES

## WATER TANK - AFTER SERVICE REPORT

15661

CUSTOMER: <u>COFELY RESID</u>			CONTACT PERSON: <u>Mr. Shakib</u>		
SITE DETAILS: <u>WOMEN'S COLLEGE ABU DHABI</u>			CONTACT NO: <u>056 997 2152</u>		
TANK DETAILS: <u>POLYCON DOMESTIC TANK 08</u>			LOCATION DETAILS: <u>BLOCK-B ROOF TOP</u>		
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL <input type="checkbox"/> RESIDENTIAL <input type="checkbox"/> OTHERS					
<u>TYPE OF TANK</u>					
<input type="checkbox"/> CONCRETE	<input type="checkbox"/> GRP PANEL	<input type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED		<input checked="" type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS		
<u>SIZE OF TANK</u>			<u>QUANTITY OF WATER</u>		
M3	USG	L*B*H	<input checked="" type="checkbox"/> FULL	<input type="checkbox"/> HALF	<input type="checkbox"/> EMPTY
<u>CONDITION OF WATER TANK BEFORE CLEANING</u>			<u>CONDITION OF WATER TANK AFTER CLEANING</u>		
<input type="checkbox"/> CLEAN	<input checked="" type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
<u>ACCESS</u>		<u>MANHOLE</u>	<input type="checkbox"/> COVERED	<input type="checkbox"/> DAMAGED	<input type="checkbox"/> NA
<u>LADDER IN</u>	<u>LADDER OUT</u>	<u>LEAKS</u>	<u>DRAIN LINE</u>	<u>VALVES</u>	<u>FLOAT VALVE</u>
<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO
<u>TANK CLEANED</u>		<u>TANK DISINFECTED</u>		<u>PIPES DISINFECTED</u>	
<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> NA	
<u>LAST CLEANING DATE</u>		<u>CURRENT CLEANING DATE</u>		<u>NEXT CLEANING DATE</u>	
		<u>98-07-2018</u>		<u>98-01-2019</u>	
<u>CHEMICALS &amp; EQUIPMENTS USED</u>					
1. <u>CHAGELA BIO \$ PLUS</u> Quantity <u>200cc</u>					
2. _____ Quantity _____					
<input checked="" type="checkbox"/> Submersibel Pump <input checked="" type="checkbox"/> High/Low Pressure Jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED lights <input checked="" type="checkbox"/> Foot Bath <input checked="" type="checkbox"/> Ladder					
<input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Meter <input checked="" type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials					
<u>COMMENTS &amp; RECOMMENDATIONS:</u>					
<u>TANK CLEANED \$ DISINFECTED</u>					
Crystalline Representative: <u>VETALIST</u>			Signature: <u>[Signature]</u>		





**CRYSTALLINE**  
ENVIRONMENTAL SERVICES


Date of Cleaning: 28-07-2018

**PHOTOGRAPHS**  
**ROOF TOP SYNTEX WATER TANK – 06 (BLOCK-B)**

**BEFORE**



**AFTER**



**CLEANER WATER GREENER TOMORROW**



# CRYSTALLINE ENVIRONMENTAL SERVICES

## WATER TANK - AFTER SERVICE REPORT

15901

CUSTOMER: <i>Cafely basinc</i>			CONTACT PERSON: <i>Ms:- Shakib</i>		
SITE DETAILS: <i>Woner's collage Abu Dhabi</i>			CONTACT NO: <i>056 9972152</i>		
TANK DETAILS: <i>Gr. R.P. water tank</i>			LOCATION DETAILS: <i>ground Block. c</i>		
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL		<input type="checkbox"/> RESIDENTIAL		<input type="checkbox"/> OTHERS	
<b>TYPE OF TANK</b>					
<input type="checkbox"/> CONCRETE	<input checked="" type="checkbox"/> GRP PANEL	<input type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED		<input type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS		
<b>SIZE OF TANK</b>			<b>QUANTITY OF WATER</b>		
M3	USG	L*B*H	<input type="checkbox"/> FULL	<input type="checkbox"/> HALF	<input type="checkbox"/> EMPTY
<b>CONDITION OF WATER TANK BEFORE CLEANING</b>			<b>CONDITION OF WATER TANK AFTER CLEANING</b>		
<input type="checkbox"/> CLEAN	<input checked="" type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input checked="" type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
<b>ACCESS</b>		<b>MANHOLE</b>		<input checked="" type="checkbox"/> COVERED	<input type="checkbox"/> DAMAGED
<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input type="checkbox"/> NO
<b>LADDER IN</b>		<b>LADDER OUT</b>		<b>LEAKS</b>	
<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO
<b>TANK CLEANED</b>		<b>TANK DISINFECTED</b>		<b>PIPES DISINFECTED</b>	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> YES	<input type="checkbox"/> NO
<b>LAST CLEANING DATE</b>		<b>CURRENT CLEANING DATE</b>		<b>NEXT CLEANING DATE</b>	
		<i>29/07/2018</i>		<i>29/01/2019</i>	
<b>CHEMICALS &amp; EQUIPMENTS USED</b>					
1. <i>Carito bio plus</i> Quantity <i>500 ml</i>					
2. _____ Quantity _____					
<input checked="" type="checkbox"/> Submersibel Pump <input checked="" type="checkbox"/> High/Low Pressure Jet <input checked="" type="checkbox"/> Extension Cords <input type="checkbox"/> LED lights <input checked="" type="checkbox"/> Foot Bath <input checked="" type="checkbox"/> Ladder <input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Meter <input checked="" type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials					
<b>COMMENTS &amp; RECOMMENDATIONS:</b>					
<i>Above mentioned water tank are successfully cleared and disinfected.</i>					
Crystalline Representative: <i>Sasir. Shanafudeer</i>			Signature: <i>Tajir</i>		




**CRYSTALLINE**  
ENVIRONMENTAL SERVICES

Date of Cleaning: 29-07-2018

**PHOTOGRAPHS**  
**GROUND LEVEL GRP WATER TANK (BLOCK - C)**

**BEFORE**



**AFTER**



**CLEANER WATER GREENER TOMORROW**



# CRYSTALLINE ENVIRONMENTAL SERVICES

## WATER TANK - AFTER SERVICE REPORT

15902

CUSTOMER: <i>Cofely basic</i>			CONTACT PERSON: <i>MR:- Shakib</i>		
SITE DETAILS: <i>Womera's collage Abu Dhabi</i>			CONTACT NO: <i>0569972152</i>		
TANK DETAILS: <i>on R.P. water tank</i>			LOCATION DETAILS: <i>ground Block:- F</i>		
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL		<input type="checkbox"/> RESIDENTIAL		<input type="checkbox"/> OTHERS	
<b>TYPE OF TANK</b>					
<input type="checkbox"/> CONCRETE	<input checked="" type="checkbox"/> GRP PANEL	<input type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED		<input type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS		
<b>SIZE OF TANK</b>			<b>QUANTITY OF WATER</b>		
M3	USG	L*B*H	<input type="checkbox"/> FULL	<input type="checkbox"/> HALF	<input type="checkbox"/> EMPTY
<b>CONDITION OF WATER TANK BEFORE CLEANING</b>			<b>CONDITION OF WATER TANK AFTER CLEANING</b>		
<input type="checkbox"/> CLEAN	<input checked="" type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input checked="" type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
<b>ACCESS</b>		<b>MANHOLE</b>		<input checked="" type="checkbox"/> COVERED	<input type="checkbox"/> DAMAGED
<input type="checkbox"/> NA			<input type="checkbox"/> NA		
<b>LADDER IN</b>		<b>LADDER OUT</b>		<b>LEAKS</b>	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO
<b>TANK CLEANED</b>		<b>TANK DISINFECTED</b>		<b>PIPES DISINFECTED</b>	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> YES	<input type="checkbox"/> NO <input checked="" type="checkbox"/> NA
<b>LAST CLEANING DATE</b>		<b>CURRENT CLEANING DATE</b>		<b>NEXT CLEANING DATE</b>	
		<i>29/07/2018</i>		<i>29/01/2019</i>	
<b>CHEMICALS &amp; EQUIPMENTS USED</b>					
1. <i>Carito bio plus</i> Quantity <i>500 ml</i>					
2. _____ Quantity _____					
<input checked="" type="checkbox"/> Submersibel Pump <input checked="" type="checkbox"/> High/Low Pressure Jet <input checked="" type="checkbox"/> Extension Cords <input type="checkbox"/> LED lights <input checked="" type="checkbox"/> Foot Bath <input checked="" type="checkbox"/> Ladder <input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Meter <input checked="" type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials					
<b>COMMENTS &amp; RECOMMENDATIONS:</b>					
<i>Above mentioned water tank are successfully cleaned and disinfected.</i>					
Crystalline Representative: <i>Basim Sharafudien</i>			Signature: <i>Tajir</i>		

Date of Cleaning: 29-07-2018

**PHOTOGRAPHS**  
**GROUND LEVEL FRP WATER TANK (BLOCK - F)**

**BEFORE**



**AFTER**





# CRYSTALLINE ENVIRONMENTAL SERVICES

## WATER TANK - AFTER SERVICE REPORT

15904

CUSTOMER: <i>Cofely besix</i>			CONTACT PERSON: <i>Ms:- Shatib.</i>		
SITE DETAILS: <i>Woman's collage Abu Dhabi</i>			CONTACT NO: <i>0569972152</i>		
TANK DETAILS: <i>F.R.P. water tank</i>			LOCATION DETAILS: <i>general block:- D</i>		
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL		<input type="checkbox"/> RESIDENTIAL		<input type="checkbox"/> OTHERS	
<b>TYPE OF TANK</b>					
<input type="checkbox"/> CONCRETE	<input type="checkbox"/> GRP PANEL	<input checked="" type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED		<input type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS		
<b>SIZE OF TANK</b>			<b>QUANTITY OF WATER</b>		
M3	USG	L*B*H	<input type="checkbox"/> FULL	<input type="checkbox"/> HALF	<input type="checkbox"/> EMPTY
<b>CONDITION OF WATER TANK BEFORE CLEANING</b>			<b>CONDITION OF WATER TANK AFTER CLEANING</b>		
<input type="checkbox"/> CLEAN	<input checked="" type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input checked="" type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
<b>ACCESS</b>		<b>MANHOLE</b>		<input checked="" type="checkbox"/> COVERED	
<input type="checkbox"/> DAMAGED		<input type="checkbox"/> NA			
<b>LADDER IN</b>		<b>LADDER OUT</b>		<b>LEAKS</b>	
<b>DRAIN LINE</b>		<b>VALVES</b>		<b>FLOAT VALVE</b>	
<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO
<b>TANK CLEANED</b>		<b>TANK DISINFECTED</b>		<b>PIPES DISINFECTED</b>	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> YES	<input type="checkbox"/> NO <input checked="" type="checkbox"/> NA
<b>LAST CLEANING DATE</b>		<b>CURRENT CLEANING DATE</b>		<b>NEXT CLEANING DATE</b>	
		<i>29/07/2018</i>		<i>29/01/2019</i>	
<b>CHEMICALS &amp; EQUIPMENTS USED</b>					
1. <i>Corito bio plus</i> Quantity <i>250 ml</i>					
2. _____ Quantity _____					
<input checked="" type="checkbox"/> Submersibel Pump <input checked="" type="checkbox"/> High/Low Pressure Jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED lights <input checked="" type="checkbox"/> Foot Bath <input checked="" type="checkbox"/> Ladder					
<input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Meter <input checked="" type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials					
<b>COMMENTS &amp; RECOMMENDATIONS:</b>					
<i>Above mentioned water tank are successfully cleaned and disinfected.</i>					
Crystalline Representative: <i>Jasir Sharafudan</i>			Signature: <i>Jasir</i>		

Date of Cleaning: 29-07-2018

**PHOTOGRAPHS**  
**GROUND LEVEL FRP WATER TANK (BLOCK - D)**

**BEFORE**



**AFTER**





# CRYSTALLINE ENVIRONMENTAL SERVICES

## WATER TANK - AFTER SERVICE REPORT

15665

CUSTOMER: <u>COFELY RESID</u>			CONTACT PERSON: <u>Mr. Shatib.</u>		
SITE DETAILS: <u>WOMEN'S COLLEGE ABU D.</u>			CONTACT NO: <u>056 997 2152</u>		
TANK DETAILS: <u>GRP DOMESTIC TANK N. 07</u>			LOCATION DETAILS: <u>SECURITY-4-5 G. FLOOR</u>		
TYPE OF BUILDING: <input checked="" type="checkbox"/> COMMERCIAL		<input type="checkbox"/> RESIDENTIAL		<input type="checkbox"/> OTHERS	
TYPE OF TANK					
<input type="checkbox"/> CONCRETE	<input checked="" type="checkbox"/> GRP PANEL	<input type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED		<input type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS		
SIZE OF TANK			QUANTITY OF WATER		
M3	USG	L*B*H	<input type="checkbox"/> FULL	<input checked="" type="checkbox"/> HALF	<input type="checkbox"/> EMPTY
CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK AFTER CLEANING		
<input type="checkbox"/> CLEAN	<input checked="" type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
<u>ACCESS</u>		<u>MANHOLE</u>	<input type="checkbox"/> COVERED	<input type="checkbox"/> DAMAGED	<input type="checkbox"/> NA
<u>LADDER IN</u>	<u>LADDER OUT</u>	<u>LEAKS</u>	<u>DRAIN LINE</u>	<u>VALVES</u>	<u>FLOAT VALVE</u>
<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO
<u>TANK CLEANED</u>		<u>TANK DISINFECTED</u>		<u>PIPES DISINFECTED</u>	
<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input type="checkbox"/> YES <input type="checkbox"/> NO	<input type="checkbox"/> YES <input type="checkbox"/> NO	<input type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> NA
<u>LAST CLEANING DATE</u>		<u>CURRENT CLEANING DATE</u>		<u>NEXT CLEANING DATE</u>	
		<u>30-07-2018</u>		<u>30-01-2019</u>	
CHEMICALS & EQUIPMENTS USED					
1. <u>CAPELA B10 &amp; PLUS</u> Quantity <u>500cc</u>					
2. _____ Quantity _____					
<input checked="" type="checkbox"/> Submersibel Pump <input checked="" type="checkbox"/> High/Low Pressure Jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED lights <input checked="" type="checkbox"/> Foot Bath <input checked="" type="checkbox"/> Ladder <input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Meter <input checked="" type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials					
COMMENTS & RECOMMENDATIONS:					
<u>TANK CLEANED &amp; DISINFECTED</u>					
Crystalline Representative: <u>YETALIST</u>			Signature: <u>[Signature]</u>		



**CRYSTALLINE**  
ENVIRONMENTAL SERVICES

Date of Cleaning: 30-07-2018

**PHOTOGRAPHS**  
**GROUND LEVEL GRP WATER TANK - 07**

**BEFORE**



**AFTER**



**CLEANER WATER GREENER TOMORROW**



# CRYSTALLINE ENVIRONMENTAL SERVICES

## WATER TANK - AFTER SERVICE REPORT

15656

CUSTOMER: <u>COFELY BESIX</u>			CONTACT PERSON: <u>Mr. Shakib</u>		
SITE DETAILS: <u>WOMEN'S COLLEGE ABU DHABI</u>			CONTACT NO: <u>056 997 2152</u>		
TANK DETAILS: <u>FIBER DOMESTIC TANK N. 08</u>			LOCATION DETAILS: <u>BLOCK-E ROOF TOP</u>		
TYPE OF BUILDING: <input checked="" type="checkbox"/> COMMERCIAL		<input type="checkbox"/> RESIDENTIAL		<input type="checkbox"/> OTHERS	
<b>TYPE OF TANK</b>					
<input type="checkbox"/> CONCRETE	<input type="checkbox"/> GRP PANEL	<input checked="" type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED		<input type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS		
<b>SIZE OF TANK</b>			<b>QUANTITY OF WATER</b>		
M3	USG	L*B*H	<input checked="" type="checkbox"/> FULL	<input type="checkbox"/> HALF	<input type="checkbox"/> EMPTY
<b>CONDITION OF WATER TANK BEFORE CLEANING</b>			<b>CONDITION OF WATER TANK AFTER CLEANING</b>		
<input type="checkbox"/> CLEAN	<input checked="" type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
<b>ACCESS</b>		<b>MANHOLE</b>		<input type="checkbox"/> COVERED	
<input type="checkbox"/> DAMAGED		<input type="checkbox"/> NA			
<b>LADDER IN</b>		<b>LADDER OUT</b>		<b>LEAKS</b>	
<b>DRAIN LINE</b>		<b>VALVES</b>		<b>FLOAT VALVE</b>	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO
<b>TANK CLEANED</b>		<b>TANK DISINFECTED</b>		<b>PIPES DISINFECTED</b>	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> YES	<input type="checkbox"/> NO <input checked="" type="checkbox"/> NA
<b>LAST CLEANING DATE</b>		<b>CURRENT CLEANING DATE</b>		<b>NEXT CLEANING DATE</b>	
		<u>31-07-2018</u>		<u>31-01-2019</u>	
<b>CHEMICALS &amp; EQUIPMENTS USED</b>					
1. <u>CARELA BIO \$ PLUS</u> Quantity <u>300cc</u>					
2. _____ Quantity _____					
<input checked="" type="checkbox"/> Submersibel Pump <input checked="" type="checkbox"/> High/Low Pressure Jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED lights <input checked="" type="checkbox"/> Foot Bath <input checked="" type="checkbox"/> Ladder					
<input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Meter <input checked="" type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials					
<b>COMMENTS &amp; RECOMMENDATIONS:</b>					
<u>TANK CLEANED &amp; DISINFECTED</u>					
Crystalline Representative: <u>VETALIST</u>			Signature: <u>[Signature]</u>		



Date of Cleaning: 31-07-2018

**PHOTOGRAPHS**  
**ROOF TOP FRP WATER TANK-08 (BLOCK - E)**

**BEFORE**



**AFTER**





# CRYSTALLINE ENVIRONMENTAL SERVICES

## WATER TANK - AFTER SERVICE REPORT

15666

CUSTOMER: <u>COFFELY BESIX</u>			CONTACT PERSON: <u>Mr. Shekib</u>		
SITE DETAILS: <u>WOMEN'S COLLEGE ABU DHABI</u>			CONTACT NO: <u>056 997 2125</u>		
TANK DETAILS: <u>GRP DOMESTIC TANK N. 09</u>			LOCATION DETAILS: <u>Block-D ROOF TOP</u>		
TYPE OF BUILDING: <input checked="" type="checkbox"/> COMMERCIAL			<input type="checkbox"/> RESIDENTIAL		<input type="checkbox"/> OTHERS
TYPE OF TANK					
<input type="checkbox"/> CONCRETE	<input checked="" type="checkbox"/> GRP PANEL	<input type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED		<input type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS		
SIZE OF TANK			QUANTITY OF WATER		
M3	USG	L*B*H	<input checked="" type="checkbox"/> FULL	<input type="checkbox"/> HALF	<input type="checkbox"/> EMPTY
CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK AFTER CLEANING		
<input type="checkbox"/> CLEAN	<input checked="" type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
ACCESS		MANHOLE	<input type="checkbox"/> COVERED	<input type="checkbox"/> DAMAGED	<input type="checkbox"/> NA
LADDER IN	LADDER OUT	LEAKS	DRAIN LINE	VALVES	FLOAT VALVE
<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO
TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED	
<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES <input type="checkbox"/> NO	<input type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> NA
LAST CLEANING DATE		CURRENT CLEANING DATE		NEXT CLEANING DATE	
		<u>31-07-2018</u>		<u>31-01-2019</u>	
CHEMICALS & EQUIPMENTS USED					
1. <u>CARELA BIO \$ PLUS</u> Quantity <u>200CC</u>					
2. _____ Quantity _____					
<input type="checkbox"/> Submersibel Pump <input type="checkbox"/> High/Low Pressure Jet <input type="checkbox"/> Extension Cords <input type="checkbox"/> LED lights <input type="checkbox"/> Foot Bath <input type="checkbox"/> Ladder					
<input type="checkbox"/> Ventilating Fan <input type="checkbox"/> Suction/Discharge Hoses <input type="checkbox"/> Oxygen Meter <input type="checkbox"/> Vacuum Cleaner <input type="checkbox"/> Cleaning Materials					
COMMENTS & RECOMMENDATIONS:					
<u>TANK CLEANED &amp; DISINFECTED</u>					
Crystalline Representative: <u>NETALIST</u>			Signature:		



**CRYSTALLINE**  
ENVIRONMENTAL SERVICES


Date of Cleaning: 31-07-2018

**PHOTOGRAPHS**  
**ROOF TOP GRP WATER TANK-09 (BLOCK - D)**

**BEFORE**



**AFTER**



**CLEANER WATER GREENER TOMORROW**



# CRYSTALLINE ENVIRONMENTAL SERVICES

## WATER TANK - AFTER SERVICE REPORT

15548

CUSTOMER: <u>HCT WOMANS (AUH)</u>			CONTACT PERSON: <u>M. SHAKIB</u>		
SITE DETAILS: <u>CENTRAL SERVICES</u>			CONTACT NO: <u>056 997 2152</u>		
TANK DETAILS: <u>WATER TANK</u>			LOCATION DETAILS: <u>UNDER GROUND</u>		
TYPE OF BUILDING: <input checked="" type="checkbox"/> COMMERCIAL		<input type="checkbox"/> RESIDENTIAL		<input type="checkbox"/> OTHERS	
<b>TYPE OF TANK</b>					
<input checked="" type="checkbox"/> CONCRETE	<input type="checkbox"/> GRP PANEL	<input type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED		<input type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS		
<b>SIZE OF TANK</b>			<b>QUANTITY OF WATER</b>		
M3	USG	L*B*H	<input checked="" type="checkbox"/> FULL	<input type="checkbox"/> HALF	<input type="checkbox"/> EMPTY
<b>CONDITION OF WATER TANK BEFORE CLEANING</b>			<b>CONDITION OF WATER TANK AFTER CLEANING</b>		
<input type="checkbox"/> CLEAN	<input checked="" type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input checked="" type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
<b>ACCESS</b>		<b>MANHOLE</b>		<input checked="" type="checkbox"/> COVERED	<input type="checkbox"/> DAMAGED
<input type="checkbox"/> NA			<input type="checkbox"/> NA		
<b>LADDER IN</b>		<b>LADDER OUT</b>		<b>LEAKS</b>	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO
<b>DRAIN LINE</b>		<b>VALVES</b>		<b>FLOAT VALVE</b>	
<input checked="" type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO
<b>TANK CLEANED</b>		<b>TANK DISINFECTED</b>		<b>PIPES DISINFECTED</b>	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO
<b>LAST CLEANING DATE</b>		<b>CURRENT CLEANING DATE</b>		<b>NEXT CLEANING DATE</b>	
		<u>03/08/2018</u>		<u>03/02/2019</u>	
<b>CHEMICALS &amp; EQUIPMENTS USED</b>					
1. <u>Zareba bio</u> Quantity <u>500 ml / 2</u>					
2. <u>Cueba bio plus</u> Quantity <u>500 ml / 2</u>					
<input checked="" type="checkbox"/> Submersibel Pump <input checked="" type="checkbox"/> High/Low Pressure Jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED lights <input checked="" type="checkbox"/> Foot Bath <input checked="" type="checkbox"/> Ladder <input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Meter <input checked="" type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials					
<b>COMMENTS &amp; RECOMMENDATIONS:</b>					
<u>We mention that the water tank has been cleaned and disinfected</u>					
Crystalline Representative: <u>Patrick</u>			Signature:		

Date of Cleaning: 03-08-2018

**PHOTOGRAPHS**  
**UNDER GROUND RCC WATER TANK**

**BEFORE**



**AFTER**





# CRYSTALLINE ENVIRONMENTAL SERVICES

## WATER TANK - AFTER SERVICE REPORT



15549

CUSTOMER: HCT WOMANS (AIJH)			CONTACT PERSON: M. SHAKIB		
SITE DETAILS: E-BLOCK			CONTACT NO: 056 997 2152		
TANK DETAILS: WATER TANK			LOCATION DETAILS: GROUND		
TYPE OF BUILDING: <input checked="" type="checkbox"/> COMMERCIAL		<input type="checkbox"/> RESIDENTIAL		<input type="checkbox"/> OTHERS	
<b>TYPE OF TANK</b>					
<input checked="" type="checkbox"/> CONCRETE	<input type="checkbox"/> GRP PANEL	<input type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED		<input type="checkbox"/> POLYURETHANE		<input type="checkbox"/> OTHERS	
<b>SIZE OF TANK</b>			<b>QUANTITY OF WATER</b>		
M3	USG	L*B*H	<input type="checkbox"/> FULL	<input checked="" type="checkbox"/> HALF	<input type="checkbox"/> EMPTY
<b>CONDITION OF WATER TANK BEFORE CLEANING</b>			<b>CONDITION OF WATER TANK AFTER CLEANING</b>		
<input type="checkbox"/> CLEAN	<input checked="" type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input checked="" type="checkbox"/> SEDIMENTS	<input checked="" type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
<b>ACCESS</b>		<b>MANHOLE</b>		<input checked="" type="checkbox"/> COVERED	<input type="checkbox"/> DAMAGED
				<input type="checkbox"/> NA	
<b>LADDER IN</b>		<b>LADDER OUT</b>		<b>LEAKS</b>	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO
<b>DRAIN LINE</b>		<b>VALVES</b>		<b>FLOAT VALVE</b>	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO
<b>TANK CLEANED</b>		<b>TANK DISINFECTED</b>		<b>PIPES DISINFECTED</b>	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO
<b>LAST CLEANING DATE</b>		<b>CURRENT CLEANING DATE</b>		<b>NEXT CLEANING DATE</b>	
		03/08/2018		03/01/2019	
<b>CHEMICALS &amp; EQUIPMENTS USED</b>					
1. Carela bio Quantity 1f					
2. Carela bio plus Quantity 1f					
<input checked="" type="checkbox"/> Submersibel Pump <input checked="" type="checkbox"/> High/Low Pressure Jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED lights <input checked="" type="checkbox"/> Foot Bath <input checked="" type="checkbox"/> Ladder					
<input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Meter <input checked="" type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials					
<b>COMMENTS &amp; RECOMMENDATIONS:</b>					
We mention that the water tank has been cleaned and disinfected					
Crystalline Representative: Patrick			Signature:		

Date of Cleaning: 03-08-2018

**PHOTOGRAPHS**  
**GROUND LEVEL RCC WATER TANK (BLOCK - E)**

**BEFORE**



**AFTER**



# CRYSTALLINE CLEANING & ENVIRONMENTAL SERVICES

## CLEANING & DISINFECTION CERTIFICATE

### POTABLE WATER TANKS

CLIENT NAME : COFELY BESIX FACILITY MANAGEMENT.  
CLIENT ADDRESS : P.O. BOX: 43139, ABU DHABI, UAE.  
CONTACT PERSON : MR. ABDUL SALAM  
SITE DETAILS : HCT – ABU DHABI WOMEN'S COLLEGE,  
ABU DHABI, UAE.  
DETAILS : WATER TANK CLEANING  
DATE OF CLEANING : AUGUST 2018  
FREQUENCY OF CLEANING : EVERY SIX MONTHS  
DATE OF NEXT CLEANING : FEBRUARY 2019

*The procedures employed in this cleaning and disinfection comply with HS (G) 70 health and safety guidelines for prevention of legionella as well as BS6700 and CARELA BIO PLUS method statement.*

*The entire water storage tank should be cleaned and disinfected minimum every six (6) months depending upon the condition.*



CRYSTALLINE CLEANING AND ENVIRONMENTAL SERVICES