

**ENVIRONMENTAL
SERVICES FOR
A GREENER
TOMORROW...
ONE STEP AT
A TIME.**



CRYSTALLINE
ENVIRONMENTAL SERVICES




Completion Report for

Water Tank Cleaning & Disinfection

Date: **21 August 2019**
Client Name: **Deerfield mall**
Contact Person: **Benjamin Panis**
Designation: **FM Supervisor**
Site Detail: **Deerfield Mall**



Address: PO BOX 131463, Abu Dhabi, UAE | Phone: +971 2 650 8930, +971 55 716 7017
E-mail: info@crystalline-uae.com | Website: www.crystalline-uae.com

Customer: Deerfield mall		Contact Person: Benjamin Panis	
Site: Deerfield Mall		Contact Number: 056 199 1971	
Description: Deerfeild		Location: Basement filtered domestic water tank no 1	
Type Of Building :		<input checked="" type="checkbox"/> Commercial	<input type="checkbox"/> Residential <input type="checkbox"/> Others
Type Of Tank			
<input checked="" type="checkbox"/> Concrete	<input type="checkbox"/> GRP Panel	<input type="checkbox"/> FRP Tank	<input type="checkbox"/> Galvanized
<input type="checkbox"/> Steel Panel	<input type="checkbox"/> Plastic	<input type="checkbox"/> Concrete Coated	<input type="checkbox"/> Polyurethane
<input type="checkbox"/> Others			
Condition Of Water before cleaning		Condition Of Water after cleaning	
<input type="checkbox"/> Clean	<input type="checkbox"/> Dirty	<input checked="" type="checkbox"/> Very Dirty	<input type="checkbox"/> Dirty
<input type="checkbox"/> Biofilms	<input type="checkbox"/> Moulds	<input type="checkbox"/> Slime	<input type="checkbox"/> Moulds
<input type="checkbox"/> Sediments	<input type="checkbox"/> Mud & Sand	<input type="checkbox"/> Rust	<input type="checkbox"/> Rust
Size of Tank			
M3:		USG:	L*B*H:
Quantity Of Water		Manhole	
<input type="checkbox"/> Full	<input checked="" type="checkbox"/> Half	<input type="checkbox"/> Empty	<input type="checkbox"/> Covered <input type="checkbox"/> Damaged <input checked="" type="checkbox"/> NA
Ladder In		Ladder Out	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Drain Line		Valves	
<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Tank Cleaned		Tank Disinfected	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Chemicals Used		Pipes Disinfected	
Chemical: Carelo bio		<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	
Chemical: Carelo bio plus		<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	
Quantity: 500ml			
Quantity: 500ml			
Equipments Used			
<input checked="" type="checkbox"/> Submersibel Pump	<input checked="" type="checkbox"/> High/low Pressure Jet	<input checked="" type="checkbox"/> Extension Cords	<input checked="" type="checkbox"/> LED Lights
<input checked="" type="checkbox"/> Foot Bath	<input checked="" type="checkbox"/> Ladder	<input checked="" type="checkbox"/> Ventilating Fan	<input checked="" type="checkbox"/> Oxygen Meter
<input checked="" type="checkbox"/> Vacuum Cleaner	<input checked="" type="checkbox"/> Cleaning Materials	<input checked="" type="checkbox"/> Suction/Discharge Hoses	
Last Cleaning Date		Current Cleaning Date	
-		21 August 2019	
		Next Cleaning Date	
		21 February 2020	
Crystalline Representative		Customer Representative	
			

Deerfeild

Before Photo



After Photo




Before Photo



After Photo



Water tank is cleaned & disinfected

Customer: Deerfield mall		Contact Person: Benjamin Panis	
Site: Deerfield Mall		Contact Number: 056 199 1971	
Description: Deerfeild		Location: Basement fire domestic water tank no2	
Type Of Building :			
<input checked="" type="checkbox"/> Commercial		<input type="checkbox"/> Residential <input type="checkbox"/> Others	
Type Of Tank			
<input checked="" type="checkbox"/> Concrete		<input type="checkbox"/> GRP Panel	
<input type="checkbox"/> Steel Panel		<input type="checkbox"/> Plastic	
<input type="checkbox"/> Others		<input type="checkbox"/> FRP Tank	
		<input type="checkbox"/> Concrete Coated	
		<input type="checkbox"/> Galvanized	
		<input type="checkbox"/> Polyurethane	
Condition Of Water before cleaning		Condition Of Water after cleaning	
<input type="checkbox"/> Clean		<input checked="" type="checkbox"/> Clean	
<input type="checkbox"/> Dirty		<input type="checkbox"/> Dirty	
<input checked="" type="checkbox"/> Very Dirty		<input type="checkbox"/> Very Dirty	
<input type="checkbox"/> Biofilms		<input type="checkbox"/> Biofilms	
<input type="checkbox"/> Moulds		<input type="checkbox"/> Moulds	
<input type="checkbox"/> Slime		<input type="checkbox"/> Slime	
<input type="checkbox"/> Sediments		<input type="checkbox"/> Sediments	
<input type="checkbox"/> Mud & Sand		<input type="checkbox"/> Mud & Sand	
<input type="checkbox"/> Rust		<input type="checkbox"/> Rust	
Size of Tank			
M3:		USG:	
		L*B*H:	
Quantity Of Water		Manhole	
<input type="checkbox"/> Full		<input type="checkbox"/> Covered	
<input checked="" type="checkbox"/> Half		<input type="checkbox"/> Damaged	
<input type="checkbox"/> Empty		<input checked="" type="checkbox"/> NA	
Ladder In		Ladder Out	
<input checked="" type="checkbox"/> Yes		<input checked="" type="checkbox"/> Yes	
<input type="checkbox"/> No		<input type="checkbox"/> No	
Drain Line		Valves	
<input type="checkbox"/> Yes		<input checked="" type="checkbox"/> Yes	
<input checked="" type="checkbox"/> No		<input type="checkbox"/> No	
Tank Cleaned		Tank Disinfected	
<input checked="" type="checkbox"/> Yes		<input checked="" type="checkbox"/> Yes	
<input type="checkbox"/> No		<input type="checkbox"/> No	
		Pipes Disinfected	
		<input type="checkbox"/> Yes	
		<input checked="" type="checkbox"/> No	
Chemicals Used			
Chemical: Carelo bio		Quantity: 500ml	
Chemical: Carelo bio plus		Quantity: 500ml	
Equipments Used			
<input checked="" type="checkbox"/> Submersibel Pump		<input checked="" type="checkbox"/> High/low Pressure Jet	
<input checked="" type="checkbox"/> Foot Bath		<input checked="" type="checkbox"/> Ladder	
<input checked="" type="checkbox"/> Vacuum Cleaner		<input checked="" type="checkbox"/> Cleaning Materials	
		<input checked="" type="checkbox"/> Extension Cords	
		<input checked="" type="checkbox"/> Ventilating Fan	
		<input checked="" type="checkbox"/> Suction/Discharge Hoses	
		<input checked="" type="checkbox"/> LED Lights	
		<input checked="" type="checkbox"/> Oxygen Meter	
Last Cleaning Date		Current Cleaning Date	
-		21 August 2019	
		Next Cleaning Date	
		21 February 2020	
Crystalline Representative		Customer Representative	
			

Deerfeild

Before Photo



After Photo



Before Photo



After Photo



Water tank is cleaned & disinfected



Customer: Deerfield mall		Contact Person: Benjamin Panis	
Site: Deerfield Mall		Contact Number: 056 199 1971	
Description: Deerfeild		Location: Basement cooling tower make up tank no2	
Type Of Building : <input checked="" type="checkbox"/> Commercial <input type="checkbox"/> Residential <input type="checkbox"/> Others			
Type Of Tank			
<input checked="" type="checkbox"/> Concrete <input type="checkbox"/> GRP Panel <input type="checkbox"/> FRP Tank <input type="checkbox"/> Galvanized <input type="checkbox"/> Steel Panel <input type="checkbox"/> Plastic <input type="checkbox"/> Concrete Coated <input type="checkbox"/> Polyurethane <input type="checkbox"/> Others			
Condition Of Water before cleaning		Condition Of Water after cleaning	
<input type="checkbox"/> Clean <input type="checkbox"/> Dirty <input checked="" type="checkbox"/> Very Dirty <input type="checkbox"/> Biofilms <input type="checkbox"/> Moulds <input type="checkbox"/> Slime <input type="checkbox"/> Sediments <input type="checkbox"/> Mud & Sand <input type="checkbox"/> Rust		<input checked="" type="checkbox"/> Clean <input type="checkbox"/> Dirty <input type="checkbox"/> Very Dirty <input type="checkbox"/> Biofilms <input type="checkbox"/> Moulds <input type="checkbox"/> Slime <input type="checkbox"/> Sediments <input type="checkbox"/> Mud & Sand <input type="checkbox"/> Rust	
Size of Tank			
M3:		USG:	L*B*H:
Quantity Of Water		Manhole	
<input type="checkbox"/> Full <input checked="" type="checkbox"/> Half <input type="checkbox"/> Empty		<input type="checkbox"/> Covered <input type="checkbox"/> Damaged <input checked="" type="checkbox"/> NA	
Ladder In	Ladder Out	Leaks	
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	
Drain Line	Valves	Float Valve	
<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	
Tank Cleaned	Tank Disinfected	Pipes Disinfected	
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	
Chemicals Used			
Chemical: Carelo bio		Quantity: 500ml	
Chemical: Carelo bio plus		Quantity: 500ml	
Equipments Used			
<input checked="" type="checkbox"/> Submersibel Pump <input checked="" type="checkbox"/> High/low Pressure Jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED Lights <input checked="" type="checkbox"/> Foot Bath <input checked="" type="checkbox"/> Ladder <input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Oxygen Meter <input checked="" type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials <input checked="" type="checkbox"/> Suction/Discharge Hoses			
Last Cleaning Date	Current Cleaning Date	Next Cleaning Date	
-	22 August 2019	22 February 2020	
Crystalline Representative		Customer Representative	
			

Deerfeild

Before Photo



After Photo



Before Photo





After Photo



Water tank is cleaned &disinfected



Customer: Deerfield mall		Contact Person: Benjamin Panis	
Site: Deerfield Mall		Contact Number: 056 199 1971	
Description: Deerfeild		Location: Basement	
Type Of Building : <input checked="" type="checkbox"/> Commercial <input type="checkbox"/> Residential <input type="checkbox"/> Others			
Type Of Tank			
<input checked="" type="checkbox"/> Concrete	<input type="checkbox"/> GRP Panel	<input type="checkbox"/> FRP Tank	<input type="checkbox"/> Galvanized
<input type="checkbox"/> Steel Panel	<input type="checkbox"/> Plastic	<input type="checkbox"/> Concrete Coated	<input type="checkbox"/> Polyurethane
<input type="checkbox"/> Others			
Condition Of Water before cleaning		Condition Of Water after cleaning	
<input type="checkbox"/> Clean	<input type="checkbox"/> Dirty	<input checked="" type="checkbox"/> Very Dirty	<input type="checkbox"/> Clean
<input type="checkbox"/> Biofilms	<input type="checkbox"/> Moulds	<input type="checkbox"/> Slime	<input type="checkbox"/> Dirty
<input type="checkbox"/> Sediments	<input type="checkbox"/> Mud & Sand	<input type="checkbox"/> Rust	<input type="checkbox"/> Very Dirty
Size of Tank			
M3:		USG:	L*B*H:
Quantity Of Water		Manhole	
<input type="checkbox"/> Full	<input checked="" type="checkbox"/> Half	<input type="checkbox"/> Empty	<input type="checkbox"/> Covered
		<input type="checkbox"/> Damaged	<input checked="" type="checkbox"/> NA
Ladder In		Ladder Out	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Drain Line		Valves	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Tank Cleaned		Tank Disinfected	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
		Pipes Disinfected	
		<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Chemicals Used			
Chemical: Carelo bio		Quantity: 500ml	
Chemical: Carelo bio plus		Quantity: 500ml	
Equipments Used			
<input checked="" type="checkbox"/> Submersibel Pump	<input checked="" type="checkbox"/> High/low Pressure Jet	<input checked="" type="checkbox"/> Extension Cords	<input checked="" type="checkbox"/> LED Lights
<input checked="" type="checkbox"/> Foot Bath	<input checked="" type="checkbox"/> Ladder	<input checked="" type="checkbox"/> Ventilating Fan	<input checked="" type="checkbox"/> Oxygen Meter
<input checked="" type="checkbox"/> Vacuum Cleaner	<input checked="" type="checkbox"/> Cleaning Materials	<input checked="" type="checkbox"/> Suction/Discharge Hoses	
Last Cleaning Date		Current Cleaning Date	
-		22 August 2019	
		Next Cleaning Date	
		22 February 2020	
Crystalline Representative		Customer Representative	
			

Deerfeild

Before Photo



After Photo



Before Photo



After Photo



Water tank is cleaned &disinfected



Deerfeild

Before Photo




After Photo



Water tank is cleaned & disinfected

Address: PO BOX 131463, Abu Dhabi, UAE | Phone: +971 2 650 8930, +971 55 716 7017
E-mail: info@crystalline-uae.com | Website: www.crystalline-uae.com

Customer: Deerfield mall		Contact Person: Benjamin Panis	
Site: Deerfield Mall		Contact Number: 056 199 1971	
Description: Deerfeild mall		Location: Basement filtered domestic water tank no1 2	
Type Of Building : <input checked="" type="checkbox"/> Commercial <input type="checkbox"/> Residential <input type="checkbox"/> Others			
Type Of Tank			
<input checked="" type="checkbox"/> Concrete <input type="checkbox"/> GRP Panel <input type="checkbox"/> FRP Tank <input type="checkbox"/> Galvanized <input type="checkbox"/> Steel Panel <input type="checkbox"/> Plastic <input type="checkbox"/> Concrete Coated <input type="checkbox"/> Polyurethane <input type="checkbox"/> Others			
Condition Of Water before cleaning		Condition Of Water after cleaning	
<input type="checkbox"/> Clean <input type="checkbox"/> Dirty <input checked="" type="checkbox"/> Very Dirty <input type="checkbox"/> Biofilms <input type="checkbox"/> Moulds <input type="checkbox"/> Slime <input type="checkbox"/> Sediments <input type="checkbox"/> Mud & Sand <input type="checkbox"/> Rust		<input checked="" type="checkbox"/> Clean <input type="checkbox"/> Dirty <input type="checkbox"/> Very Dirty <input type="checkbox"/> Biofilms <input type="checkbox"/> Moulds <input type="checkbox"/> Slime <input type="checkbox"/> Sediments <input type="checkbox"/> Mud & Sand <input type="checkbox"/> Rust	
Size of Tank			
M3:		USG:	L*B*H:
Quantity Of Water		Manhole	
<input type="checkbox"/> Full <input checked="" type="checkbox"/> Half <input type="checkbox"/> Empty		<input type="checkbox"/> Covered <input type="checkbox"/> Damaged <input checked="" type="checkbox"/> NA	
Ladder In	Ladder Out	Leaks	
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	
Drain Line	Valves	Float Valve	
<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	
Tank Cleaned	Tank Disinfected	Pipes Disinfected	
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	
Chemicals Used			
Chemical: Carelo bio		Quantity: 500ml	
Chemical: Carelo bio plus		Quantity: 500ml	
Equipments Used			
<input checked="" type="checkbox"/> Submersibel Pump <input checked="" type="checkbox"/> High/low Pressure Jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED Lights <input checked="" type="checkbox"/> Foot Bath <input checked="" type="checkbox"/> Ladder <input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Oxygen Meter <input checked="" type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials <input checked="" type="checkbox"/> Suction/Discharge Hoses			
Last Cleaning Date	Current Cleaning Date	Next Cleaning Date	
-	25 August 2019	25 February 2020	
Crystalline Representative		Customer Representative	
			

Deerfeild mall

Before Photo



After Photo



Before Photo



After Photo



Water tank is cleaned &disinfected

Deerfeild mall

Before Photo



After Photo



Water tank is cleaned & disinfected

Address: PO BOX 131463, Abu Dhabi, UAE | Phone: +971 2 650 8930, +971 55 716 7017
E-mail: info@crystalline-uae.com | Website: www.crystalline-uae.com

Customer: Deerfield mall		Contact Person: Benjamin Panis	
Site: Deerfield Mall		Contact Number: 056 199 1971	
Description: Deerfeild mall		Location: Basement domestic water tank no 1	
Type Of Building : <input checked="" type="checkbox"/> Commercial <input type="checkbox"/> Residential <input type="checkbox"/> Others			
Type Of Tank			
<input checked="" type="checkbox"/> Concrete <input type="checkbox"/> GRP Panel <input type="checkbox"/> FRP Tank <input type="checkbox"/> Galvanized <input type="checkbox"/> Steel Panel <input type="checkbox"/> Plastic <input type="checkbox"/> Concrete Coated <input type="checkbox"/> Polyurethane <input type="checkbox"/> Others			
Condition Of Water before cleaning		Condition Of Water after cleaning	
<input type="checkbox"/> Clean <input type="checkbox"/> Dirty <input checked="" type="checkbox"/> Very Dirty <input type="checkbox"/> Biofilms <input type="checkbox"/> Moulds <input type="checkbox"/> Slime <input type="checkbox"/> Sediments <input type="checkbox"/> Mud & Sand <input type="checkbox"/> Rust		<input checked="" type="checkbox"/> Clean <input type="checkbox"/> Dirty <input type="checkbox"/> Very Dirty <input type="checkbox"/> Biofilms <input type="checkbox"/> Moulds <input type="checkbox"/> Slime <input type="checkbox"/> Sediments <input type="checkbox"/> Mud & Sand <input type="checkbox"/> Rust	
Size of Tank			
M3:		USG:	L*B*H:
Quantity Of Water		Manhole	
<input type="checkbox"/> Full <input checked="" type="checkbox"/> Half <input type="checkbox"/> Empty		<input type="checkbox"/> Covered <input type="checkbox"/> Damaged <input checked="" type="checkbox"/> NA	
Ladder In	Ladder Out	Leaks	
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	
Drain Line	Valves	Float Valve	
<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	
Tank Cleaned	Tank Disinfected	Pipes Disinfected	
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	
Chemicals Used			
Chemical: Carelo bio		Quantity: 500ml	
Chemical: Carelo bio plus		Quantity: 500ml	
Equipments Used			
<input checked="" type="checkbox"/> Submersibel Pump	<input checked="" type="checkbox"/> High/low Pressure Jet	<input checked="" type="checkbox"/> Extension Cords	<input checked="" type="checkbox"/> LED Lights
<input checked="" type="checkbox"/> Foot Bath	<input checked="" type="checkbox"/> Ladder	<input checked="" type="checkbox"/> Ventilating Fan	<input checked="" type="checkbox"/> Oxygen Meter
<input checked="" type="checkbox"/> Vacuum Cleaner	<input checked="" type="checkbox"/> Cleaning Materials	<input checked="" type="checkbox"/> Suction/Discharge Hoses	
Last Cleaning Date	Current Cleaning Date	Next Cleaning Date	
-	25 August 2019	25 February 2020	
Crystalline Representative		Customer Representative	
			

Deerfeild mall

Before Photo



After Photo



Before Photo




After Photo



Water tank is cleaned &disinfected

Deerfeild mall

Before Photo



After Photo



Water tank is cleaned & disinfected

Address: PO BOX 131463, Abu Dhabi, UAE | Phone: +971 2 650 8930, +971 55 716 7017
E-mail: info@crystalline-uae.com | Website: www.crystalline-uae.com

Customer: Deerfield mall		Contact Person: Benjamin Panis	
Site: Deerfield Mall		Contact Number: 056 199 1971	
Description: Deerfeild mall		Location: Basement	
Type Of Building : <input checked="" type="checkbox"/> Commercial <input type="checkbox"/> Residential <input type="checkbox"/> Others			
Type Of Tank			
<input checked="" type="checkbox"/> Concrete <input type="checkbox"/> GRP Panel <input type="checkbox"/> FRP Tank <input type="checkbox"/> Galvanized <input type="checkbox"/> Steel Panel <input type="checkbox"/> Plastic <input type="checkbox"/> Concrete Coated <input type="checkbox"/> Polyurethane <input type="checkbox"/> Others			
Condition Of Water before cleaning		Condition Of Water after cleaning	
<input type="checkbox"/> Clean <input type="checkbox"/> Dirty <input checked="" type="checkbox"/> Very Dirty <input type="checkbox"/> Biofilms <input type="checkbox"/> Moulds <input type="checkbox"/> Slime <input type="checkbox"/> Sediments <input type="checkbox"/> Mud & Sand <input type="checkbox"/> Rust		<input checked="" type="checkbox"/> Clean <input type="checkbox"/> Dirty <input type="checkbox"/> Very Dirty <input type="checkbox"/> Biofilms <input type="checkbox"/> Moulds <input type="checkbox"/> Slime <input type="checkbox"/> Sediments <input type="checkbox"/> Mud & Sand <input type="checkbox"/> Rust	
Size of Tank			
M3:		USG:	L*B*H:
Quantity Of Water		Manhole	
<input type="checkbox"/> Full <input checked="" type="checkbox"/> Half <input type="checkbox"/> Empty		<input type="checkbox"/> Covered <input type="checkbox"/> Damaged <input checked="" type="checkbox"/> NA	
Ladder In	Ladder Out	Leaks	
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	
Drain Line	Valves	Float Valve	
<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	
Tank Cleaned	Tank Disinfected	Pipes Disinfected	
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	
Chemicals Used			
Chemical: Carelo bio		Quantity: 500ml	
Chemical: Carelo bio plus		Quantity: 500ml	
Equipments Used			
<input checked="" type="checkbox"/> Submersibel Pump	<input checked="" type="checkbox"/> High/low Pressure Jet	<input checked="" type="checkbox"/> Extension Cords	<input checked="" type="checkbox"/> LED Lights
<input checked="" type="checkbox"/> Foot Bath	<input checked="" type="checkbox"/> Ladder	<input checked="" type="checkbox"/> Ventilating Fan	<input checked="" type="checkbox"/> Oxygen Meter
<input checked="" type="checkbox"/> Vacuum Cleaner	<input checked="" type="checkbox"/> Cleaning Materials	<input checked="" type="checkbox"/> Suction/Discharge Hoses	
Last Cleaning Date	Current Cleaning Date	Next Cleaning Date	
-	26 August 2019	26 February 2020	
Crystalline Representative		Customer Representative	
			

Deerfeild mall

Before Photo



After Photo



Before Photo



After Photo



Water tank is cleaned &disinfected

Deerfeild mall

Before Photo



After Photo



Before Photo





After Photo



Water tank is cleaned &disinfected



Customer: Deerfield mall		Contact Person: Benjamin Panis	
Site: Deerfield Mall		Contact Number: 056 199 1971	
Description: Deerfeild mall		Location: Basement	
Type Of Building :		<input checked="" type="checkbox"/> Commercial	<input type="checkbox"/> Residential <input type="checkbox"/> Others
Type Of Tank			
<input checked="" type="checkbox"/> Concrete	<input type="checkbox"/> GRP Panel	<input type="checkbox"/> FRP Tank	<input type="checkbox"/> Galvanized
<input type="checkbox"/> Steel Panel	<input type="checkbox"/> Plastic	<input type="checkbox"/> Concrete Coated	<input type="checkbox"/> Polyurethane
<input type="checkbox"/> Others			
Condition Of Water before cleaning		Condition Of Water after cleaning	
<input type="checkbox"/> Clean	<input type="checkbox"/> Dirty	<input checked="" type="checkbox"/> Very Dirty	<input type="checkbox"/> Dirty
<input type="checkbox"/> Biofilms	<input type="checkbox"/> Moulds	<input type="checkbox"/> Slime	<input type="checkbox"/> Moulds
<input type="checkbox"/> Sediments	<input type="checkbox"/> Mud & Sand	<input type="checkbox"/> Rust	<input type="checkbox"/> Mud & Sand
Size of Tank			
M3:		USG:	L*B*H:
Quantity Of Water		Manhole	
<input type="checkbox"/> Full	<input checked="" type="checkbox"/> Half	<input type="checkbox"/> Empty	<input type="checkbox"/> Covered <input type="checkbox"/> Damaged <input checked="" type="checkbox"/> NA
Ladder In		Ladder Out	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Drain Line		Valves	
<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Tank Cleaned		Tank Disinfected	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Chemicals Used		Pipes Disinfected	
Chemical: Carelo bio		<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	
Chemical: Carelo bio plus		<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	
Quantity: 500ml		Quantity: 500ml	
Equipments Used			
<input checked="" type="checkbox"/> Submersibel Pump	<input checked="" type="checkbox"/> High/low Pressure Jet	<input checked="" type="checkbox"/> Extension Cords	<input checked="" type="checkbox"/> LED Lights
<input checked="" type="checkbox"/> Foot Bath	<input checked="" type="checkbox"/> Ladder	<input checked="" type="checkbox"/> Ventilating Fan	<input checked="" type="checkbox"/> Oxygen Meter
<input checked="" type="checkbox"/> Vacuum Cleaner	<input checked="" type="checkbox"/> Cleaning Materials	<input checked="" type="checkbox"/> Suction/Discharge Hoses	
Last Cleaning Date		Current Cleaning Date	
-		27 August 2019	
		Next Cleaning Date	
		27 February 2020	
Crystalline Representative		Customer Representative	
			

CRYSTALLINE CLEANING & ENVIRONMENTAL SERVICES

WATER TANK CLEANING & DISINFECTION

CLIENT NAME : DEERFIELD MALL
CONTACT PERSON : BENJAMIN PANIS
DESIGNATION : FM SUPERVISOR
SITE DETAILS : DEERFIELD MALL
DETAILS : WATER TANK CLEANING & DISINFECTION
DATE OF CLEANING : 21/08/2019
FREQUENCY OF CLEANING : HALF YEARLY
DATE OF NEXT CLEANING : 21 FEBRUARY 2020

The above water tanks were cleaned and disinfected in accordance with the Code of Practice for the inspection and cleaning of customer water storage tanks.



Ismanpinto

CRYSTALLINE CLEANING AND ENVIRONMENTAL SERVICES