

**ENVIRONMENTAL  
SERVICES FOR  
A GREENER  
TOMORROW...  
ONE STEP AT  
A TIME.**




Completion Report for  
**Water Tank Cleaning & Disinfection**

Date: **08 September 2019**  
Client Name: **Cofely Besix Facility Management- ESC**  
Contact Person: **Mr. Brilliant Skaria**  
Designation: **MEP Team Leader**  
Site Detail: **Emirates Sky Cargo, Abu Dhabi**



---

**Address: PO BOX 131463, Abu Dhabi, UAE | Phone: +971 2 650 8930, +971 55 716 7017**  
**E-mail: [info@crystalline-uae.com](mailto:info@crystalline-uae.com) | Website: [www.crystalline-uae.com](http://www.crystalline-uae.com)**

<b>Customer:</b> Cofely Besix Facility Management- ESC		<b>Contact Person:</b> Brilliant Skaria	
<b>Site:</b> Emirates Sky Cargo, Abu Dhabi		<b>Contact Number:</b> 050 550 0473	
<b>Description:</b> Emirates Sky Cargo		<b>Location:</b> Dubai	
<b>Type Of Building :</b> <input checked="" type="checkbox"/> Commercial <input type="checkbox"/> Residential <input type="checkbox"/> Others			
<b>Type Of Tank</b>			
<input type="checkbox"/> Concrete	<input checked="" type="checkbox"/> GRP Panel	<input type="checkbox"/> FRP Tank	<input type="checkbox"/> Galvanized
<input type="checkbox"/> Steel Panel	<input type="checkbox"/> Plastic	<input type="checkbox"/> Concrete Coated	<input type="checkbox"/> Polyurethane
<input type="checkbox"/> Others			
<b>Condition Of Water before cleaning</b>		<b>Condition Of Water after cleaning</b>	
<input type="checkbox"/> Clean	<input type="checkbox"/> Dirty	<input checked="" type="checkbox"/> Very Dirty	
<input type="checkbox"/> Biofilms	<input type="checkbox"/> Moulds	<input type="checkbox"/> Slime	
<input type="checkbox"/> Sediments	<input type="checkbox"/> Mud & Sand	<input type="checkbox"/> Rust	
<b>Size of Tank</b>			
<b>M3:</b>		<b>USG:</b>	<b>L*B*H:</b>
<b>Quantity Of Water</b>		<b>Manhole</b>	
<input type="checkbox"/> Full	<input checked="" type="checkbox"/> Half	<input type="checkbox"/> Empty	
<input type="checkbox"/> Covered		<input type="checkbox"/> Damaged	
<input checked="" type="checkbox"/> NA			
<b>Ladder In</b>		<b>Ladder Out</b>	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
<b>Drain Line</b>		<b>Valves</b>	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
<b>Tank Cleaned</b>		<b>Tank Disinfected</b>	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
<b>Leaks</b>		<b>Float Valve</b>	
<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
<b>Pipes Disinfected</b>			
<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No		
<b>Chemicals Used</b>			
<b>Chemical:</b> Carela Bio		<b>Quantity:</b> 250ml	
<b>Chemical:</b> Carela Bio Plus		<b>Quantity:</b> 250ml	
<b>Equipments Used</b>			
<input checked="" type="checkbox"/> Submersibel Pump	<input checked="" type="checkbox"/> High/low Pressure Jet	<input checked="" type="checkbox"/> Extension Cords	<input checked="" type="checkbox"/> LED Lights
<input checked="" type="checkbox"/> Foot Bath	<input checked="" type="checkbox"/> Ladder	<input checked="" type="checkbox"/> Ventilating Fan	<input checked="" type="checkbox"/> Oxygen Meter
<input checked="" type="checkbox"/> Vacuum Cleaner	<input checked="" type="checkbox"/> Cleaning Materials	<input checked="" type="checkbox"/> Suction/Discharge Hoses	
<b>Last Cleaning Date</b>		<b>Current Cleaning Date</b>	
-		08 September 2019	
		<b>Next Cleaning Date</b>	
		08 March 2020	
<b>Crystalline Representative</b>		<b>Customer Representative</b>	
			

# Emirates Sky Cargo

Before Photo




After Photo




Before Photo



After Photo



Water tank is cleaned & disinfected

<b>Customer:</b> Cofely Besix Facility Management- ESC		<b>Contact Person:</b> Brilliant Skaria	
<b>Site:</b> Emirates Sky Cargo, Abu Dhabi		<b>Contact Number:</b> 050 550 0473	
<b>Description:</b> Emirates Sky Cargo		<b>Location:</b> Dubai	
<b>Type Of Building :</b>		<input checked="" type="checkbox"/> Commercial	<input type="checkbox"/> Residential <input type="checkbox"/> Others
<b>Type Of Tank</b>			
<input type="checkbox"/> Concrete	<input checked="" type="checkbox"/> GRP Panel	<input type="checkbox"/> FRP Tank	<input type="checkbox"/> Galvanized
<input type="checkbox"/> Steel Panel	<input type="checkbox"/> Plastic	<input type="checkbox"/> Concrete Coated	<input type="checkbox"/> Polyurethane
<input type="checkbox"/> Others			
<b>Condition Of Water before cleaning</b>		<b>Condition Of Water after cleaning</b>	
<input type="checkbox"/> Clean	<input type="checkbox"/> Dirty	<input checked="" type="checkbox"/> Very Dirty	
<input type="checkbox"/> Biofilms	<input type="checkbox"/> Moulds	<input type="checkbox"/> Slime	
<input type="checkbox"/> Sediments	<input type="checkbox"/> Mud & Sand	<input type="checkbox"/> Rust	
<b>Size of Tank</b>			
<b>M3:</b>		<b>USG:</b>	<b>L*B*H:</b>
<b>Quantity Of Water</b>		<b>Manhole</b>	
<input type="checkbox"/> Full	<input checked="" type="checkbox"/> Half	<input type="checkbox"/> Empty	<input type="checkbox"/> Covered <input type="checkbox"/> Damaged <input checked="" type="checkbox"/> NA
<b>Ladder In</b>		<b>Ladder Out</b>	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
<b>Drain Line</b>		<b>Valves</b>	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
<b>Tank Cleaned</b>		<b>Tank Disinfected</b>	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
		<b>Pipes Disinfected</b>	
		<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
<b>Chemicals Used</b>			
<b>Chemical:</b> Carela Bio		<b>Quantity:</b> 250ml	
<b>Chemical:</b> Carela Bio Plus		<b>Quantity:</b> 250ml	
<b>Equipments Used</b>			
<input checked="" type="checkbox"/> Submersibel Pump	<input checked="" type="checkbox"/> High/low Pressure Jet	<input checked="" type="checkbox"/> Extension Cords	<input checked="" type="checkbox"/> LED Lights
<input checked="" type="checkbox"/> Foot Bath	<input checked="" type="checkbox"/> Ladder	<input checked="" type="checkbox"/> Ventilating Fan	<input checked="" type="checkbox"/> Oxygen Meter
<input checked="" type="checkbox"/> Vacuum Cleaner	<input checked="" type="checkbox"/> Cleaning Materials	<input checked="" type="checkbox"/> Suction/Discharge Hoses	
<b>Last Cleaning Date</b>		<b>Current Cleaning Date</b>	
-		08 September 2019	
		<b>Next Cleaning Date</b>	
		08 March 2020	
<b>Crystalline Representative</b>		<b>Customer Representative</b>	
			

# Emirates Sky Cargo

Before Photo



After Photo




Before Photo



After Photo



Water tank is cleaned & disinfected

<b>Customer:</b> Cofely Besix Facility Management- ESC		<b>Contact Person:</b> Brilliant Skaria	
<b>Site:</b> Emirates Sky Cargo, Abu Dhabi		<b>Contact Number:</b> 050 550 0473	
<b>Description:</b> Emirates Sky Cargo		<b>Location:</b> Dubai	
<b>Type Of Building :</b>		<input checked="" type="checkbox"/> Commercial	<input type="checkbox"/> Residential <input type="checkbox"/> Others
<b>Type Of Tank</b>			
<input type="checkbox"/> Concrete	<input checked="" type="checkbox"/> GRP Panel	<input type="checkbox"/> FRP Tank	<input type="checkbox"/> Galvanized
<input type="checkbox"/> Steel Panel	<input type="checkbox"/> Plastic	<input type="checkbox"/> Concrete Coated	<input type="checkbox"/> Polyurethane
<input type="checkbox"/> Others			
<b>Condition Of Water before cleaning</b>		<b>Condition Of Water after cleaning</b>	
<input type="checkbox"/> Clean	<input type="checkbox"/> Dirty	<input checked="" type="checkbox"/> Very Dirty	<input type="checkbox"/> Clean
<input type="checkbox"/> Biofilms	<input type="checkbox"/> Moulds	<input type="checkbox"/> Slime	<input type="checkbox"/> Dirty
<input type="checkbox"/> Sediments	<input type="checkbox"/> Mud & Sand	<input type="checkbox"/> Rust	<input type="checkbox"/> Very Dirty
		<input type="checkbox"/> Biofilms	<input type="checkbox"/> Moulds
		<input type="checkbox"/> Sediments	<input type="checkbox"/> Mud & Sand
		<input type="checkbox"/> Rust	<input type="checkbox"/> Rust
<b>Size of Tank</b>			
<b>M3:</b>		<b>USG:</b>	<b>L*B*H:</b>
<b>Quantity Of Water</b>		<b>Manhole</b>	
<input type="checkbox"/> Full	<input checked="" type="checkbox"/> Half	<input type="checkbox"/> Empty	<input type="checkbox"/> Covered
		<input type="checkbox"/> Damaged	<input checked="" type="checkbox"/> NA
<b>Ladder In</b>		<b>Ladder Out</b>	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
<b>Drain Line</b>		<b>Valves</b>	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
<b>Tank Cleaned</b>		<b>Tank Disinfected</b>	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
		<b>Pipes Disinfected</b>	
		<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
<b>Chemicals Used</b>			
<b>Chemical:</b> Carela Bio		<b>Quantity:</b> 250ml	
<b>Chemical:</b> Carela Bio Plus		<b>Quantity:</b> 250ml	
<b>Equipments Used</b>			
<input checked="" type="checkbox"/> Submersibel Pump	<input checked="" type="checkbox"/> High/low Pressure Jet	<input checked="" type="checkbox"/> Extension Cords	<input checked="" type="checkbox"/> LED Lights
<input checked="" type="checkbox"/> Foot Bath	<input checked="" type="checkbox"/> Ladder	<input checked="" type="checkbox"/> Ventilating Fan	<input checked="" type="checkbox"/> Oxygen Meter
<input checked="" type="checkbox"/> Vacuum Cleaner	<input checked="" type="checkbox"/> Cleaning Materials	<input checked="" type="checkbox"/> Suction/Discharge Hoses	
<b>Last Cleaning Date</b>		<b>Current Cleaning Date</b>	
-		09 September 2019	
		<b>Next Cleaning Date</b>	
		09 March 2020	
<b>Crystalline Representative</b>		<b>Customer Representative</b>	
			

# Emirates Sky Cargo

Before Photo



After Photo




Before Photo



After Photo



Water tank is cleaned & disinfected

<b>Customer:</b> Cofely Besix Facility Management- ESC		<b>Contact Person:</b> Brilliant Skaria	
<b>Site:</b> Emirates Sky Cargo, Abu Dhabi		<b>Contact Number:</b> 050 550 0473	
<b>Description:</b> Emirates Sky Cargo		<b>Location:</b> Dubai	
<b>Type Of Building :</b>		<input checked="" type="checkbox"/> Commercial	<input type="checkbox"/> Residential <input type="checkbox"/> Others
<b>Type Of Tank</b>			
<input type="checkbox"/> Concrete	<input checked="" type="checkbox"/> GRP Panel	<input type="checkbox"/> FRP Tank	<input type="checkbox"/> Galvanized
<input type="checkbox"/> Steel Panel	<input type="checkbox"/> Plastic	<input type="checkbox"/> Concrete Coated	<input type="checkbox"/> Polyurethane
<input type="checkbox"/> Others			
<b>Condition Of Water before cleaning</b>		<b>Condition Of Water after cleaning</b>	
<input type="checkbox"/> Clean	<input type="checkbox"/> Dirty	<input checked="" type="checkbox"/> Very Dirty	<input type="checkbox"/> Dirty
<input type="checkbox"/> Biofilms	<input type="checkbox"/> Moulds	<input type="checkbox"/> Slime	<input type="checkbox"/> Moulds
<input type="checkbox"/> Sediments	<input type="checkbox"/> Mud & Sand	<input type="checkbox"/> Rust	<input type="checkbox"/> Rust
<b>Size of Tank</b>			
<b>M3:</b>		<b>USG:</b>	<b>L*B*H:</b>
<b>Quantity Of Water</b>		<b>Manhole</b>	
<input type="checkbox"/> Full	<input checked="" type="checkbox"/> Half	<input type="checkbox"/> Empty	<input type="checkbox"/> Covered <input type="checkbox"/> Damaged <input checked="" type="checkbox"/> NA
<b>Ladder In</b>		<b>Ladder Out</b>	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
<b>Drain Line</b>		<b>Valves</b>	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
<b>Tank Cleaned</b>		<b>Tank Disinfected</b>	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
		<b>Pipes Disinfected</b>	
		<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
<b>Chemicals Used</b>			
<b>Chemical:</b> Carela Bio		<b>Quantity:</b> 250ml	
<b>Chemical:</b> Carela Bio Plus		<b>Quantity:</b> 250ml	
<b>Equipments Used</b>			
<input checked="" type="checkbox"/> Submersibel Pump	<input checked="" type="checkbox"/> High/low Pressure Jet	<input checked="" type="checkbox"/> Extension Cords	<input checked="" type="checkbox"/> LED Lights
<input checked="" type="checkbox"/> Foot Bath	<input checked="" type="checkbox"/> Ladder	<input checked="" type="checkbox"/> Ventilating Fan	<input checked="" type="checkbox"/> Oxygen Meter
<input checked="" type="checkbox"/> Vacuum Cleaner	<input checked="" type="checkbox"/> Cleaning Materials	<input checked="" type="checkbox"/> Suction/Discharge Hoses	
<b>Last Cleaning Date</b>		<b>Current Cleaning Date</b>	
-		09 September 2019	
		<b>Next Cleaning Date</b>	
		09 March 2020	
<b>Crystalline Representative</b>		<b>Customer Representative</b>	
			

# Emirates Sky Cargo

Before Photo



After Photo



Before Photo



After Photo



Water tank is cleaned &disinfected



# CRYSTALLINE CLEANING & ENVIRONMENTAL SERVICES

## WATER TANK CLEANING & DISINFECTION

**CLIENT NAME** : COFELY BESIX FACILITY MANAGEMENT- ESC

**CONTACT PERSON** : MR. BRILLIANT SKARIA

**DESIGNATION** : MEP TEAM LEADER

**SITE DETAILS** : EMIRATES SKY CARGO, ABU DHABI

**DETAILS** : WATER TANK CLEANING & DISINFECTION

**DATE OF CLEANING** : 08 SEPTEMBER 2019

**FREQUENCY OF CLEANING** : HALF YEARLY

**DATE OF NEXT CLEANING** : 08 MARCH 2020

*The above water tanks were cleaned and disinfected in accordance with the Code of Practice for the inspection and cleaning of customer water storage tanks.*



*Insmanpinto*

**CRYSTALLINE CLEANING AND ENVIRONMENTAL SERVICES**