

**ENVIRONMENTAL  
SERVICES FOR  
A GREENER  
TOMORROW...  
ONE STEP AT  
A TIME.**



Completion Report for  
**Water Tank Cleaning & Disinfection**

Date: **24 August 2019**  
Client Name: **Hirmas Real Estate LLC**  
Contact Person: **Bashar Abu Salim**  
Designation: **Head Of QHSES**  
Site Detail: **DIC Village**



---

**Address: PO BOX 131463, Abu Dhabi, UAE | Phone: +971 2 650 8930, +971 55 716 7017**  
**E-mail: [info@crystalline-uae.com](mailto:info@crystalline-uae.com) | Website: [www.crystalline-uae.com](http://www.crystalline-uae.com)**

<b>Customer:</b> Hirmas Real Estate LLC		<b>Contact Person:</b> Bashar Abu Salim	
<b>Site:</b> DIC Village		<b>Contact Number:</b> 052 536 7437	
<b>Description:</b> Domestic Tank Part A and B		<b>Location:</b> Building #04 Ground	
<b>Type Of Building :</b> <input checked="" type="checkbox"/> Commercial <input type="checkbox"/> Residential <input type="checkbox"/> Others			
<b>Type Of Tank</b>			
<input type="checkbox"/> Concrete	<input checked="" type="checkbox"/> GRP Panel	<input type="checkbox"/> FRP Tank	<input type="checkbox"/> Galvanized
<input type="checkbox"/> Steel Panel	<input type="checkbox"/> Plastic	<input type="checkbox"/> Concrete Coated	<input type="checkbox"/> Polyurethane
<input type="checkbox"/> Others			
<b>Condition Of Water before cleaning</b>		<b>Condition Of Water after cleaning</b>	
<input type="checkbox"/> Clean	<input checked="" type="checkbox"/> Dirty	<input type="checkbox"/> Very Dirty	<input type="checkbox"/> Very Dirty
<input type="checkbox"/> Biofilms	<input type="checkbox"/> Moulds	<input type="checkbox"/> Slime	<input type="checkbox"/> Slime
<input checked="" type="checkbox"/> Sediments	<input checked="" type="checkbox"/> Mud & Sand	<input type="checkbox"/> Rust	<input type="checkbox"/> Rust
<b>Size of Tank</b>			
<b>M3:</b> 140		<b>USG:</b>	<b>L*B*H:</b>
<b>Quantity Of Water</b>		<b>Manhole</b>	
<input type="checkbox"/> Full	<input checked="" type="checkbox"/> Half	<input type="checkbox"/> Empty	<input checked="" type="checkbox"/> Covered <input type="checkbox"/> Damaged <input type="checkbox"/> NA
<b>Ladder In</b>		<b>Ladder Out</b>	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
<b>Drain Line</b>		<b>Valves</b>	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
<b>Tank Cleaned</b>		<b>Tank Disinfected</b>	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
		<b>Pipes Disinfected</b>	
		<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
<b>Chemicals Used</b>			
<b>Chemical:</b> Carela Bio		<b>Quantity:</b> 500ml	
<b>Chemical:</b> Carela Bio Plus		<b>Quantity:</b> 500ml	
<b>Equipments Used</b>			
<input checked="" type="checkbox"/> Submersibel Pump	<input type="checkbox"/> High/low Pressure Jet	<input checked="" type="checkbox"/> Extension Cords	<input type="checkbox"/> LED Lights
<input checked="" type="checkbox"/> Foot Bath	<input checked="" type="checkbox"/> Ladder	<input checked="" type="checkbox"/> Ventilating Fan	<input checked="" type="checkbox"/> Oxygen Meter
<input checked="" type="checkbox"/> Vacuum Cleaner	<input checked="" type="checkbox"/> Cleaning Materials	<input checked="" type="checkbox"/> Suction/Discharge Hoses	
<b>Last Cleaning Date</b>		<b>Current Cleaning Date</b>	<b>Next Cleaning Date</b>
-		24 August 2019	24 February 2020
<b>Crystalline Representative</b>		<b>Customer Representative</b>	
			

## Domestic Tank Part A and B

Before Photo



After Photo



Before Photo



After Photo




Water Tank is Cleaned & Disinfected

<b>Customer:</b> Hirmas Real Estate LLC		<b>Contact Person:</b> Bashar Abu Salim	
<b>Site:</b> DIC Village		<b>Contact Number:</b> 052 536 7437	
<b>Description:</b> Domestic Tank Part A and B		<b>Location:</b> Building #06 Ground	
<b>Type Of Building :</b> <input checked="" type="checkbox"/> Commercial <input type="checkbox"/> Residential <input type="checkbox"/> Others			
<b>Type Of Tank</b>			
<input type="checkbox"/> Concrete	<input checked="" type="checkbox"/> GRP Panel	<input type="checkbox"/> FRP Tank	<input type="checkbox"/> Galvanized
<input type="checkbox"/> Steel Panel	<input type="checkbox"/> Plastic	<input type="checkbox"/> Concrete Coated	<input type="checkbox"/> Polyurethane
<input type="checkbox"/> Others			
<b>Condition Of Water before cleaning</b>		<b>Condition Of Water after cleaning</b>	
<input type="checkbox"/> Clean	<input checked="" type="checkbox"/> Dirty	<input type="checkbox"/> Very Dirty	<input type="checkbox"/> Clean
<input type="checkbox"/> Biofilms	<input type="checkbox"/> Moulds	<input type="checkbox"/> Slime	<input type="checkbox"/> Dirty
<input type="checkbox"/> Sediments	<input checked="" type="checkbox"/> Mud & Sand	<input type="checkbox"/> Rust	<input type="checkbox"/> Very Dirty
		<input type="checkbox"/> Biofilms	<input type="checkbox"/> Moulds
		<input type="checkbox"/> Sediments	<input type="checkbox"/> Mud & Sand
		<input type="checkbox"/> Rust	<input type="checkbox"/> Rust
<b>Size of Tank</b>			
<b>M3:</b> 140		<b>USG:</b>	<b>L*B*H:</b>
<b>Quantity Of Water</b>		<b>Manhole</b>	
<input type="checkbox"/> Full	<input checked="" type="checkbox"/> Half	<input type="checkbox"/> Empty	<input checked="" type="checkbox"/> Covered
		<input type="checkbox"/> Damaged	<input type="checkbox"/> NA
<b>Ladder In</b>		<b>Ladder Out</b>	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
<b>Drain Line</b>		<b>Valves</b>	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
<b>Tank Cleaned</b>		<b>Tank Disinfected</b>	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
		<b>Pipes Disinfected</b>	
		<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
<b>Chemicals Used</b>			
<b>Chemical:</b> Carela Bio		<b>Quantity:</b> 500ml	
<b>Chemical:</b> Carela Bio Plus		<b>Quantity:</b> 500ml	
<b>Equipments Used</b>			
<input checked="" type="checkbox"/> Submersibel Pump	<input type="checkbox"/> High/low Pressure Jet	<input checked="" type="checkbox"/> Extension Cords	<input type="checkbox"/> LED Lights
<input checked="" type="checkbox"/> Foot Bath	<input checked="" type="checkbox"/> Ladder	<input checked="" type="checkbox"/> Ventilating Fan	<input checked="" type="checkbox"/> Oxygen Meter
<input checked="" type="checkbox"/> Vacuum Cleaner	<input checked="" type="checkbox"/> Cleaning Materials	<input checked="" type="checkbox"/> Suction/Discharge Hoses	
<b>Last Cleaning Date</b>		<b>Current Cleaning Date</b>	
-		24 August 2019	
		<b>Next Cleaning Date</b>	
		24 February 2020	
<b>Crystalline Representative</b>		<b>Customer Representative</b>	
			

# Domestic Tank Part A and B

Before Photo



After Photo



Before Photo



After Photo



Water Tank is Cleaned & Disinfected

<b>Customer:</b> Hirmas Real Estate LLC		<b>Contact Person:</b> Bashar Abu Salim	
<b>Site:</b> DIC Village		<b>Contact Number:</b> 052 536 7437	
<b>Description:</b> Domestic Tank Part A and B		<b>Location:</b> Building #01 Ground	
<b>Type Of Building :</b> <input checked="" type="checkbox"/> Commercial <input type="checkbox"/> Residential <input type="checkbox"/> Others			
<b>Type Of Tank</b>			
<input type="checkbox"/> Concrete <input checked="" type="checkbox"/> GRP Panel <input type="checkbox"/> FRP Tank <input type="checkbox"/> Galvanized <input type="checkbox"/> Steel Panel <input type="checkbox"/> Plastic <input type="checkbox"/> Concrete Coated <input type="checkbox"/> Polyurethane <input type="checkbox"/> Others			
<b>Condition Of Water before cleaning</b>		<b>Condition Of Water after cleaning</b>	
<input type="checkbox"/> Clean <input checked="" type="checkbox"/> Dirty <input type="checkbox"/> Very Dirty <input type="checkbox"/> Biofilms <input type="checkbox"/> Moulds <input type="checkbox"/> Slime <input type="checkbox"/> Sediments <input type="checkbox"/> Mud & Sand <input type="checkbox"/> Rust		<input checked="" type="checkbox"/> Clean <input type="checkbox"/> Dirty <input type="checkbox"/> Very Dirty <input type="checkbox"/> Biofilms <input type="checkbox"/> Moulds <input type="checkbox"/> Slime <input type="checkbox"/> Sediments <input type="checkbox"/> Mud & Sand <input type="checkbox"/> Rust	
<b>Size of Tank</b>			
<b>M3:</b> 140		<b>USG:</b>	<b>L*B*H:</b>
<b>Quantity Of Water</b>		<b>Manhole</b>	
<input type="checkbox"/> Full <input checked="" type="checkbox"/> Half <input type="checkbox"/> Empty		<input checked="" type="checkbox"/> Covered <input type="checkbox"/> Damaged <input type="checkbox"/> NA	
<b>Ladder In</b>	<b>Ladder Out</b>	<b>Leaks</b>	
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	
<b>Drain Line</b>	<b>Valves</b>	<b>Float Valve</b>	
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	
<b>Tank Cleaned</b>	<b>Tank Disinfected</b>	<b>Pipes Disinfected</b>	
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	
<b>Chemicals Used</b>			
<b>Chemical:</b> Carela Bio		<b>Quantity:</b> 500ml	
<b>Chemical:</b> Carela Bio Plus		<b>Quantity:</b> 500ml	
<b>Equipments Used</b>			
<input checked="" type="checkbox"/> Submersibel Pump <input type="checkbox"/> High/low Pressure Jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED Lights <input checked="" type="checkbox"/> Foot Bath <input checked="" type="checkbox"/> Ladder <input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Oxygen Meter <input checked="" type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials <input checked="" type="checkbox"/> Suction/Discharge Hoses			
<b>Last Cleaning Date</b>	<b>Current Cleaning Date</b>	<b>Next Cleaning Date</b>	
-	24 August 2019	24 February 2020	
<b>Crystalline Representative</b>		<b>Customer Representative</b>	
			

# Domestic Tank Part A and B

Before Photo



After Photo



Before Photo



After Photo



Water Tank is Cleaned & Disinfected

<b>Customer:</b> Hirmas Real Estate LLC		<b>Contact Person:</b> Bashar Abu Salim	
<b>Site:</b> DIC Village		<b>Contact Number:</b> 052 536 7437	
<b>Description:</b> Domestic Tank Part A and B		<b>Location:</b> Building #07 Ground	
<b>Type Of Building :</b>		<input checked="" type="checkbox"/> Commercial	<input type="checkbox"/> Residential <input type="checkbox"/> Others
<b>Type Of Tank</b>			
<input type="checkbox"/> Concrete	<input checked="" type="checkbox"/> GRP Panel	<input type="checkbox"/> FRP Tank	<input type="checkbox"/> Galvanized
<input type="checkbox"/> Steel Panel	<input type="checkbox"/> Plastic	<input type="checkbox"/> Concrete Coated	<input type="checkbox"/> Polyurethane
<input type="checkbox"/> Others			
<b>Condition Of Water before cleaning</b>		<b>Condition Of Water after cleaning</b>	
<input type="checkbox"/> Clean	<input checked="" type="checkbox"/> Dirty	<input type="checkbox"/> Very Dirty	<input type="checkbox"/> Clean
<input type="checkbox"/> Biofilms	<input type="checkbox"/> Moulds	<input type="checkbox"/> Slime	<input type="checkbox"/> Dirty
<input type="checkbox"/> Sediments	<input checked="" type="checkbox"/> Mud & Sand	<input type="checkbox"/> Rust	<input type="checkbox"/> Very Dirty
		<input type="checkbox"/> Biofilms	<input type="checkbox"/> Moulds
		<input type="checkbox"/> Sediments	<input type="checkbox"/> Mud & Sand
		<input type="checkbox"/> Rust	<input type="checkbox"/> Rust
<b>Size of Tank</b>			
<b>M3:</b> 140		<b>USG:</b>	<b>L*B*H:</b>
<b>Quantity Of Water</b>		<b>Manhole</b>	
<input type="checkbox"/> Full	<input checked="" type="checkbox"/> Half	<input type="checkbox"/> Empty	<input checked="" type="checkbox"/> Covered <input type="checkbox"/> Damaged <input type="checkbox"/> NA
<b>Ladder In</b>		<b>Ladder Out</b>	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
<b>Drain Line</b>		<b>Valves</b>	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
<b>Tank Cleaned</b>		<b>Tank Disinfected</b>	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
		<b>Pipes Disinfected</b>	
		<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
<b>Chemicals Used</b>			
<b>Chemical:</b> Carela Bio		<b>Quantity:</b> 500ml	
<b>Chemical:</b> Carela Bio Plus		<b>Quantity:</b> 500ml	
<b>Equipments Used</b>			
<input checked="" type="checkbox"/> Submersibel Pump	<input type="checkbox"/> High/low Pressure Jet	<input checked="" type="checkbox"/> Extension Cords	<input type="checkbox"/> LED Lights
<input checked="" type="checkbox"/> Foot Bath	<input checked="" type="checkbox"/> Ladder	<input checked="" type="checkbox"/> Ventilating Fan	<input checked="" type="checkbox"/> Oxygen Meter
<input checked="" type="checkbox"/> Vacuum Cleaner	<input checked="" type="checkbox"/> Cleaning Materials	<input checked="" type="checkbox"/> Suction/Discharge Hoses	
<b>Last Cleaning Date</b>		<b>Current Cleaning Date</b>	
-		25 August 2019	
		<b>Next Cleaning Date</b>	
		25 February 2020	
<b>Crystalline Representative</b>		<b>Customer Representative</b>	
			

# Domestic Tank Part A and B

Before Photo



After Photo



Before Photo



After Photo



Water Tank is Cleaned & Disinfected

<b>Customer:</b> Hirmas Real Estate LLC		<b>Contact Person:</b> Bashar Abu Salim	
<b>Site:</b> DIC Village		<b>Contact Number:</b> 052 536 7437	
<b>Description:</b> Domestic Tank Part A and B		<b>Location:</b> Building #05 Ground	
<b>Type Of Building :</b> <input checked="" type="checkbox"/> Commercial <input type="checkbox"/> Residential <input type="checkbox"/> Others			
<b>Type Of Tank</b>			
<input type="checkbox"/> Concrete	<input checked="" type="checkbox"/> GRP Panel	<input type="checkbox"/> FRP Tank	<input type="checkbox"/> Galvanized
<input type="checkbox"/> Steel Panel	<input type="checkbox"/> Plastic	<input type="checkbox"/> Concrete Coated	<input type="checkbox"/> Polyurethane
<input type="checkbox"/> Others			
<b>Condition Of Water before cleaning</b>		<b>Condition Of Water after cleaning</b>	
<input type="checkbox"/> Clean	<input checked="" type="checkbox"/> Dirty	<input type="checkbox"/> Very Dirty	<input type="checkbox"/> Clean
<input type="checkbox"/> Biofilms	<input type="checkbox"/> Moulds	<input type="checkbox"/> Slime	<input type="checkbox"/> Dirty
<input type="checkbox"/> Sediments	<input checked="" type="checkbox"/> Mud & Sand	<input type="checkbox"/> Rust	<input type="checkbox"/> Very Dirty
		<input type="checkbox"/> Biofilms	<input type="checkbox"/> Moulds
		<input type="checkbox"/> Sediments	<input type="checkbox"/> Mud & Sand
		<input type="checkbox"/> Rust	<input type="checkbox"/> Rust
<b>Size of Tank</b>			
<b>M3:</b> 140		<b>USG:</b>	<b>L*B*H:</b>
<b>Quantity Of Water</b>		<b>Manhole</b>	
<input type="checkbox"/> Full	<input checked="" type="checkbox"/> Half	<input type="checkbox"/> Empty	<input checked="" type="checkbox"/> Covered
		<input type="checkbox"/> Damaged	<input type="checkbox"/> NA
<b>Ladder In</b>	<b>Ladder Out</b>	<b>Leaks</b>	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
<input type="checkbox"/> No	<input type="checkbox"/> No	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
<b>Drain Line</b>	<b>Valves</b>	<b>Float Valve</b>	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
<input type="checkbox"/> No	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
<b>Tank Cleaned</b>	<b>Tank Disinfected</b>	<b>Pipes Disinfected</b>	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
<input type="checkbox"/> No	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
<b>Chemicals Used</b>			
<b>Chemical:</b> Carela Bio		<b>Quantity:</b> 500ml	
<b>Chemical:</b> Carela Bio Plus		<b>Quantity:</b> 500ml	
<b>Equipments Used</b>			
<input checked="" type="checkbox"/> Submersibel Pump	<input type="checkbox"/> High/low Pressure Jet	<input checked="" type="checkbox"/> Extension Cords	<input type="checkbox"/> LED Lights
<input checked="" type="checkbox"/> Foot Bath	<input checked="" type="checkbox"/> Ladder	<input checked="" type="checkbox"/> Ventilating Fan	<input checked="" type="checkbox"/> Oxygen Meter
<input checked="" type="checkbox"/> Vacuum Cleaner	<input checked="" type="checkbox"/> Cleaning Materials	<input checked="" type="checkbox"/> Suction/Discharge Hoses	
<b>Last Cleaning Date</b>	<b>Current Cleaning Date</b>	<b>Next Cleaning Date</b>	
-	25 August 2019	25 February 2020	
<b>Crystalline Representative</b>		<b>Customer Representative</b>	
			

# Domestic Tank Part A and B

Before Photo



After Photo



Before Photo



After Photo




Water Tank is Cleaned & Disinfected


<b>Customer:</b> Hirmas Real Estate LLC		<b>Contact Person:</b> Bashar Abu Salim	
<b>Site:</b> DIC Village		<b>Contact Number:</b> 052 536 7437	
<b>Description:</b> Domestic Tank Part A and B		<b>Location:</b> Building #08 Ground	
<b>Type Of Building :</b> <input checked="" type="checkbox"/> Commercial <input type="checkbox"/> Residential <input type="checkbox"/> Others			
<b>Type Of Tank</b>			
<input type="checkbox"/> Concrete <input checked="" type="checkbox"/> GRP Panel <input type="checkbox"/> FRP Tank <input type="checkbox"/> Galvanized <input type="checkbox"/> Steel Panel <input type="checkbox"/> Plastic <input type="checkbox"/> Concrete Coated <input type="checkbox"/> Polyurethane <input type="checkbox"/> Others			
<b>Condition Of Water before cleaning</b>		<b>Condition Of Water after cleaning</b>	
<input type="checkbox"/> Clean <input checked="" type="checkbox"/> Dirty <input type="checkbox"/> Very Dirty <input type="checkbox"/> Biofilms <input type="checkbox"/> Moulds <input type="checkbox"/> Slime <input type="checkbox"/> Sediments <input checked="" type="checkbox"/> Mud & Sand <input type="checkbox"/> Rust		<input checked="" type="checkbox"/> Clean <input type="checkbox"/> Dirty <input type="checkbox"/> Very Dirty <input type="checkbox"/> Biofilms <input type="checkbox"/> Moulds <input type="checkbox"/> Slime <input type="checkbox"/> Sediments <input type="checkbox"/> Mud & Sand <input type="checkbox"/> Rust	
<b>Size of Tank</b>			
<b>M3:</b> 140		<b>USG:</b>	<b>L*B*H:</b>
<b>Quantity Of Water</b>		<b>Manhole</b>	
<input type="checkbox"/> Full <input checked="" type="checkbox"/> Half <input type="checkbox"/> Empty		<input checked="" type="checkbox"/> Covered <input type="checkbox"/> Damaged <input type="checkbox"/> NA	
<b>Ladder In</b>	<b>Ladder Out</b>	<b>Leaks</b>	
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	
<b>Drain Line</b>	<b>Valves</b>	<b>Float Valve</b>	
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	
<b>Tank Cleaned</b>	<b>Tank Disinfected</b>	<b>Pipes Disinfected</b>	
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	
<b>Chemicals Used</b>			
<b>Chemical:</b> Carela Bio		<b>Quantity:</b> 500ml	
<b>Chemical:</b> Carela Bio Plus		<b>Quantity:</b> 500ml	
<b>Equipments Used</b>			
<input checked="" type="checkbox"/> Submersibel Pump <input type="checkbox"/> High/low Pressure Jet <input checked="" type="checkbox"/> Extension Cords <input type="checkbox"/> LED Lights <input checked="" type="checkbox"/> Foot Bath <input checked="" type="checkbox"/> Ladder <input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Oxygen Meter <input checked="" type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials <input checked="" type="checkbox"/> Suction/Discharge Hoses			
<b>Last Cleaning Date</b>	<b>Current Cleaning Date</b>	<b>Next Cleaning Date</b>	
-	25 August 2019	25 February 2020	
<b>Crystalline Representative</b>		<b>Customer Representative</b>	
			

# Domestic Tank Part A and B

Before Photo



After Photo



Before Photo



After Photo



Water Tank is Cleaned & Disinfected

<b>Customer:</b> Hirmas Real Estate LLC		<b>Contact Person:</b> Bashar Abu Salim	
<b>Site:</b> DIC Village		<b>Contact Number:</b> 052 536 7437	
<b>Description:</b> Domestic Tank Part A and B		<b>Location:</b> Building #14 Ground	
<b>Type Of Building :</b> <input checked="" type="checkbox"/> Commercial <input type="checkbox"/> Residential <input type="checkbox"/> Others			
<b>Type Of Tank</b>			
<input type="checkbox"/> Concrete <input checked="" type="checkbox"/> GRP Panel <input type="checkbox"/> FRP Tank <input type="checkbox"/> Galvanized <input type="checkbox"/> Steel Panel <input type="checkbox"/> Plastic <input type="checkbox"/> Concrete Coated <input type="checkbox"/> Polyurethane <input type="checkbox"/> Others			
<b>Condition Of Water before cleaning</b>		<b>Condition Of Water after cleaning</b>	
<input type="checkbox"/> Clean <input checked="" type="checkbox"/> Dirty <input type="checkbox"/> Very Dirty <input type="checkbox"/> Biofilms <input type="checkbox"/> Moulds <input type="checkbox"/> Slime <input type="checkbox"/> Sediments <input checked="" type="checkbox"/> Mud & Sand <input type="checkbox"/> Rust		<input checked="" type="checkbox"/> Clean <input type="checkbox"/> Dirty <input type="checkbox"/> Very Dirty <input type="checkbox"/> Biofilms <input type="checkbox"/> Moulds <input type="checkbox"/> Slime <input type="checkbox"/> Sediments <input type="checkbox"/> Mud & Sand <input type="checkbox"/> Rust	
<b>Size of Tank</b>			
<b>M3:</b> 140		<b>USG:</b>	<b>L*B*H:</b>
<b>Quantity Of Water</b>		<b>Manhole</b>	
<input type="checkbox"/> Full <input checked="" type="checkbox"/> Half <input type="checkbox"/> Empty		<input checked="" type="checkbox"/> Covered <input type="checkbox"/> Damaged <input type="checkbox"/> NA	
<b>Ladder In</b>	<b>Ladder Out</b>	<b>Leaks</b>	
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	
<b>Drain Line</b>	<b>Valves</b>	<b>Float Valve</b>	
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	
<b>Tank Cleaned</b>	<b>Tank Disinfected</b>	<b>Pipes Disinfected</b>	
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	
<b>Chemicals Used</b>			
<b>Chemical:</b> Carela Bio		<b>Quantity:</b> 500ml	
<b>Chemical:</b> Carela Bio Plus		<b>Quantity:</b> 500ml	
<b>Equipments Used</b>			
<input checked="" type="checkbox"/> Submersibel Pump <input type="checkbox"/> High/low Pressure Jet <input checked="" type="checkbox"/> Extension Cords <input type="checkbox"/> LED Lights <input checked="" type="checkbox"/> Foot Bath <input checked="" type="checkbox"/> Ladder <input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Oxygen Meter <input checked="" type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials <input checked="" type="checkbox"/> Suction/Discharge Hoses			
<b>Last Cleaning Date</b>	<b>Current Cleaning Date</b>	<b>Next Cleaning Date</b>	
-	26 August 2019	26 February 2020	
<b>Crystalline Representative</b>		<b>Customer Representative</b>	
			

# Domestic Tank Part A and B

Before Photo



After Photo



Before Photo



After Photo



Water Tank is Cleaned & Disinfected




<b>Customer:</b> Hirmas Real Estate LLC		<b>Contact Person:</b> Bashar Abu Salim	
<b>Site:</b> DIC Village		<b>Contact Number:</b> 052 536 7437	
<b>Description:</b> Domestic Tank Part A and B		<b>Location:</b> Building #10 Ground	
<b>Type Of Building :</b>		<input checked="" type="checkbox"/> Commercial	<input type="checkbox"/> Residential <input type="checkbox"/> Others
<b>Type Of Tank</b>			
<input type="checkbox"/> Concrete	<input checked="" type="checkbox"/> GRP Panel	<input type="checkbox"/> FRP Tank	<input type="checkbox"/> Galvanized
<input type="checkbox"/> Steel Panel	<input type="checkbox"/> Plastic	<input type="checkbox"/> Concrete Coated	<input type="checkbox"/> Polyurethane
<input type="checkbox"/> Others			
<b>Condition Of Water before cleaning</b>		<b>Condition Of Water after cleaning</b>	
<input type="checkbox"/> Clean	<input checked="" type="checkbox"/> Dirty	<input type="checkbox"/> Very Dirty	<input type="checkbox"/> Very Dirty
<input type="checkbox"/> Biofilms	<input type="checkbox"/> Moulds	<input type="checkbox"/> Slime	<input type="checkbox"/> Slime
<input type="checkbox"/> Sediments	<input checked="" type="checkbox"/> Mud & Sand	<input type="checkbox"/> Rust	<input type="checkbox"/> Rust
<b>Size of Tank</b>			
<b>M3:</b> 140		<b>USG:</b>	<b>L*B*H:</b>
<b>Quantity Of Water</b>		<b>Manhole</b>	
<input type="checkbox"/> Full	<input checked="" type="checkbox"/> Half	<input type="checkbox"/> Empty	<input checked="" type="checkbox"/> Covered <input type="checkbox"/> Damaged <input type="checkbox"/> NA
<b>Ladder In</b>		<b>Ladder Out</b>	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
<b>Drain Line</b>		<b>Valves</b>	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
<b>Tank Cleaned</b>		<b>Tank Disinfected</b>	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
		<b>Pipes Disinfected</b>	
		<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
<b>Chemicals Used</b>			
<b>Chemical:</b> Carela Bio		<b>Quantity:</b> 500ml	
<b>Chemical:</b> Carela Bio Plus		<b>Quantity:</b> 500ml	
<b>Equipments Used</b>			
<input checked="" type="checkbox"/> Submersibel Pump	<input type="checkbox"/> High/low Pressure Jet	<input checked="" type="checkbox"/> Extension Cords	<input checked="" type="checkbox"/> LED Lights
<input checked="" type="checkbox"/> Foot Bath	<input checked="" type="checkbox"/> Ladder	<input checked="" type="checkbox"/> Ventilating Fan	<input checked="" type="checkbox"/> Oxygen Meter
<input checked="" type="checkbox"/> Vacuum Cleaner	<input checked="" type="checkbox"/> Cleaning Materials	<input checked="" type="checkbox"/> Suction/Discharge Hoses	
<b>Last Cleaning Date</b>		<b>Current Cleaning Date</b>	
-		26 August 2019	
		<b>Next Cleaning Date</b>	
		26 February 2020	
<b>Crystalline Representative</b>		<b>Customer Representative</b>	
			

# Domestic Tank Part A and B

Before Photo



After Photo



Before Photo



After Photo



Water Tank is Cleaned & Disinfected

<b>Customer:</b> Hirmas Real Estate LLC		<b>Contact Person:</b> Bashar Abu Salim	
<b>Site:</b> DIC Village		<b>Contact Number:</b> 052 536 7437	
<b>Description:</b> Domestic Tank Part A and B		<b>Location:</b> Building #09 Ground	
<b>Type Of Building :</b> <input checked="" type="checkbox"/> Commercial <input type="checkbox"/> Residential <input type="checkbox"/> Others			
<b>Type Of Tank</b>			
<input type="checkbox"/> Concrete <input checked="" type="checkbox"/> GRP Panel <input type="checkbox"/> FRP Tank <input type="checkbox"/> Galvanized <input type="checkbox"/> Steel Panel <input type="checkbox"/> Plastic <input type="checkbox"/> Concrete Coated <input type="checkbox"/> Polyurethane <input type="checkbox"/> Others			
<b>Condition Of Water before cleaning</b>		<b>Condition Of Water after cleaning</b>	
<input type="checkbox"/> Clean <input checked="" type="checkbox"/> Dirty <input type="checkbox"/> Very Dirty <input type="checkbox"/> Biofilms <input type="checkbox"/> Moulds <input type="checkbox"/> Slime <input type="checkbox"/> Sediments <input checked="" type="checkbox"/> Mud & Sand <input type="checkbox"/> Rust		<input checked="" type="checkbox"/> Clean <input type="checkbox"/> Dirty <input type="checkbox"/> Very Dirty <input type="checkbox"/> Biofilms <input type="checkbox"/> Moulds <input type="checkbox"/> Slime <input type="checkbox"/> Sediments <input type="checkbox"/> Mud & Sand <input type="checkbox"/> Rust	
<b>Size of Tank</b>			
<b>M3:</b> 140		<b>USG:</b>	<b>L*B*H:</b>
<b>Quantity Of Water</b>		<b>Manhole</b>	
<input type="checkbox"/> Full <input checked="" type="checkbox"/> Half <input type="checkbox"/> Empty		<input checked="" type="checkbox"/> Covered <input type="checkbox"/> Damaged <input type="checkbox"/> NA	
<b>Ladder In</b>	<b>Ladder Out</b>	<b>Leaks</b>	
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	
<b>Drain Line</b>	<b>Valves</b>	<b>Float Valve</b>	
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	
<b>Tank Cleaned</b>	<b>Tank Disinfected</b>	<b>Pipes Disinfected</b>	
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	
<b>Chemicals Used</b>			
<b>Chemical:</b> Carela Bio		<b>Quantity:</b> 500ml	
<b>Chemical:</b> Carela Bio Plus		<b>Quantity:</b> 500ml	
<b>Equipments Used</b>			
<input checked="" type="checkbox"/> Submersibel Pump <input type="checkbox"/> High/low Pressure Jet <input checked="" type="checkbox"/> Extension Cords <input type="checkbox"/> LED Lights <input checked="" type="checkbox"/> Foot Bath <input checked="" type="checkbox"/> Ladder <input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Oxygen Meter <input checked="" type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials <input checked="" type="checkbox"/> Suction/Discharge Hoses			
<b>Last Cleaning Date</b>	<b>Current Cleaning Date</b>	<b>Next Cleaning Date</b>	
-	26 August 2019	26 February 2020	
<b>Crystalline Representative</b>		<b>Customer Representative</b>	
			

## Domestic Tank Part A and B

Before Photo



After Photo




Before Photo



After Photo



Water Tank is Cleaned & Disinfected

<b>Customer:</b> Hirmas Real Estate LLC		<b>Contact Person:</b> Bashar Abu Salim	
<b>Site:</b> DIC Village		<b>Contact Number:</b> 052 536 7437	
<b>Description:</b> Domestic Tank Part A and B		<b>Location:</b> Building #15 Ground	
<b>Type Of Building :</b> <input checked="" type="checkbox"/> Commercial <input type="checkbox"/> Residential <input type="checkbox"/> Others			
<b>Type Of Tank</b>			
<input type="checkbox"/> Concrete <input checked="" type="checkbox"/> GRP Panel <input type="checkbox"/> FRP Tank <input type="checkbox"/> Galvanized <input type="checkbox"/> Steel Panel <input type="checkbox"/> Plastic <input type="checkbox"/> Concrete Coated <input type="checkbox"/> Polyurethane <input type="checkbox"/> Others			
<b>Condition Of Water before cleaning</b>		<b>Condition Of Water after cleaning</b>	
<input type="checkbox"/> Clean <input checked="" type="checkbox"/> Dirty <input type="checkbox"/> Very Dirty <input type="checkbox"/> Biofilms <input type="checkbox"/> Moulds <input type="checkbox"/> Slime <input type="checkbox"/> Sediments <input checked="" type="checkbox"/> Mud & Sand <input type="checkbox"/> Rust		<input checked="" type="checkbox"/> Clean <input type="checkbox"/> Dirty <input type="checkbox"/> Very Dirty <input type="checkbox"/> Biofilms <input type="checkbox"/> Moulds <input type="checkbox"/> Slime <input type="checkbox"/> Sediments <input type="checkbox"/> Mud & Sand <input type="checkbox"/> Rust	
<b>Size of Tank</b>			
<b>M3:</b> 140		<b>USG:</b>	<b>L*B*H:</b>
<b>Quantity Of Water</b>		<b>Manhole</b>	
<input type="checkbox"/> Full <input checked="" type="checkbox"/> Half <input type="checkbox"/> Empty		<input checked="" type="checkbox"/> Covered <input type="checkbox"/> Damaged <input type="checkbox"/> NA	
<b>Ladder In</b>	<b>Ladder Out</b>	<b>Leaks</b>	
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	
<b>Drain Line</b>	<b>Valves</b>	<b>Float Valve</b>	
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	
<b>Tank Cleaned</b>	<b>Tank Disinfected</b>	<b>Pipes Disinfected</b>	
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	
<b>Chemicals Used</b>			
<b>Chemical:</b> Carela Bio		<b>Quantity:</b> 500ml	
<b>Chemical:</b> Carela Bio Plus		<b>Quantity:</b> 500ml	
<b>Equipments Used</b>			
<input checked="" type="checkbox"/> Submersibel Pump <input type="checkbox"/> High/low Pressure Jet <input checked="" type="checkbox"/> Extension Cords <input type="checkbox"/> LED Lights <input checked="" type="checkbox"/> Foot Bath <input checked="" type="checkbox"/> Ladder <input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Oxygen Meter <input checked="" type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials <input checked="" type="checkbox"/> Suction/Discharge Hoses			
<b>Last Cleaning Date</b>	<b>Current Cleaning Date</b>	<b>Next Cleaning Date</b>	
-	27 August 2019	27 February 2020	
<b>Crystalline Representative</b>		<b>Customer Representative</b>	
			

# Domestic Tank Part A and B


Before Photo



After Photo




Before Photo



After Photo



Water Tank is Cleaned & Disinfected

<b>Customer:</b> Hirmas Real Estate LLC		<b>Contact Person:</b> Bashar Abu Salim	
<b>Site:</b> DIC Village		<b>Contact Number:</b> 052 536 7437	
<b>Description:</b> Domestic Tank Part A and B		<b>Location:</b> Building #11 Ground	
<b>Type Of Building :</b> <input checked="" type="checkbox"/> Commercial <input type="checkbox"/> Residential <input type="checkbox"/> Others			
<b>Type Of Tank</b>			
<input type="checkbox"/> Concrete	<input checked="" type="checkbox"/> GRP Panel	<input type="checkbox"/> FRP Tank	<input type="checkbox"/> Galvanized
<input type="checkbox"/> Steel Panel	<input type="checkbox"/> Plastic	<input type="checkbox"/> Concrete Coated	<input type="checkbox"/> Polyurethane
<input type="checkbox"/> Others			
<b>Condition Of Water before cleaning</b>		<b>Condition Of Water after cleaning</b>	
<input type="checkbox"/> Clean	<input checked="" type="checkbox"/> Dirty	<input type="checkbox"/> Very Dirty	<input type="checkbox"/> Clean
<input type="checkbox"/> Biofilms	<input type="checkbox"/> Moulds	<input type="checkbox"/> Slime	<input type="checkbox"/> Dirty
<input type="checkbox"/> Sediments	<input checked="" type="checkbox"/> Mud & Sand	<input type="checkbox"/> Rust	<input type="checkbox"/> Very Dirty
		<input type="checkbox"/> Biofilms	<input type="checkbox"/> Moulds
		<input type="checkbox"/> Sediments	<input type="checkbox"/> Mud & Sand
		<input type="checkbox"/> Rust	<input type="checkbox"/> Rust
<b>Size of Tank</b>			
<b>M3:</b> 140		<b>USG:</b>	<b>L*B*H:</b>
<b>Quantity Of Water</b>		<b>Manhole</b>	
<input type="checkbox"/> Full	<input checked="" type="checkbox"/> Half	<input type="checkbox"/> Empty	<input type="checkbox"/> Covered
		<input type="checkbox"/> Damaged	<input type="checkbox"/> NA
<b>Ladder In</b>		<b>Ladder Out</b>	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
<b>Drain Line</b>		<b>Valves</b>	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
<b>Tank Cleaned</b>		<b>Tank Disinfected</b>	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
		<b>Pipes Disinfected</b>	
		<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
<b>Chemicals Used</b>			
<b>Chemical:</b> Carela Bio		<b>Quantity:</b> 500ml	
<b>Chemical:</b> Carela Bio Plus		<b>Quantity:</b> 500ml	
<b>Equipments Used</b>			
<input checked="" type="checkbox"/> Submersibel Pump	<input type="checkbox"/> High/low Pressure Jet	<input checked="" type="checkbox"/> Extension Cords	<input checked="" type="checkbox"/> LED Lights
<input checked="" type="checkbox"/> Foot Bath	<input checked="" type="checkbox"/> Ladder	<input checked="" type="checkbox"/> Ventilating Fan	<input checked="" type="checkbox"/> Oxygen Meter
<input checked="" type="checkbox"/> Vacuum Cleaner	<input checked="" type="checkbox"/> Cleaning Materials	<input checked="" type="checkbox"/> Suction/Discharge Hoses	
<b>Last Cleaning Date</b>		<b>Current Cleaning Date</b>	
-		27 August 2019	
		<b>Next Cleaning Date</b>	
		27 February 2020	
<b>Crystalline Representative</b>		<b>Customer Representative</b>	
			

# Domestic Tank Part A and B

Before Photo



After Photo



Before Photo



After Photo



Water Tank is Cleaned & Disinfected

<b>Customer:</b> Hirmas Real Estate LLC		<b>Contact Person:</b> Bashar Abu Salim	
<b>Site:</b> DIC Village		<b>Contact Number:</b> 052 536 7437	
<b>Description:</b> Domestic Tank Part A and B		<b>Location:</b> Building # 12 Ground	
<b>Type Of Building :</b> <input checked="" type="checkbox"/> Commercial <input type="checkbox"/> Residential <input type="checkbox"/> Others			
<b>Type Of Tank</b>			
<input type="checkbox"/> Concrete <input checked="" type="checkbox"/> GRP Panel <input type="checkbox"/> FRP Tank <input type="checkbox"/> Galvanized <input type="checkbox"/> Steel Panel <input type="checkbox"/> Plastic <input type="checkbox"/> Concrete Coated <input type="checkbox"/> Polyurethane <input type="checkbox"/> Others			
<b>Condition Of Water before cleaning</b>		<b>Condition Of Water after cleaning</b>	
<input type="checkbox"/> Clean <input checked="" type="checkbox"/> Dirty <input type="checkbox"/> Very Dirty <input type="checkbox"/> Biofilms <input type="checkbox"/> Moulds <input type="checkbox"/> Slime <input type="checkbox"/> Sediments <input checked="" type="checkbox"/> Mud & Sand <input type="checkbox"/> Rust		<input checked="" type="checkbox"/> Clean <input type="checkbox"/> Dirty <input type="checkbox"/> Very Dirty <input type="checkbox"/> Biofilms <input type="checkbox"/> Moulds <input type="checkbox"/> Slime <input type="checkbox"/> Sediments <input type="checkbox"/> Mud & Sand <input type="checkbox"/> Rust	
<b>Size of Tank</b>			
<b>M3:</b> 140		<b>USG:</b>	<b>L*B*H:</b>
<b>Quantity Of Water</b>		<b>Manhole</b>	
<input type="checkbox"/> Full <input checked="" type="checkbox"/> Half <input type="checkbox"/> Empty		<input checked="" type="checkbox"/> Covered <input type="checkbox"/> Damaged <input type="checkbox"/> NA	
<b>Ladder In</b>	<b>Ladder Out</b>	<b>Leaks</b>	
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	
<b>Drain Line</b>	<b>Valves</b>	<b>Float Valve</b>	
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	
<b>Tank Cleaned</b>	<b>Tank Disinfected</b>	<b>Pipes Disinfected</b>	
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	
<b>Chemicals Used</b>			
<b>Chemical:</b> Carela Bio		<b>Quantity:</b> 500ml	
<b>Chemical:</b> Carela Bio Plus		<b>Quantity:</b> 500ml	
<b>Equipments Used</b>			
<input checked="" type="checkbox"/> Submersibel Pump <input type="checkbox"/> High/low Pressure Jet <input checked="" type="checkbox"/> Extension Cords <input type="checkbox"/> LED Lights <input checked="" type="checkbox"/> Foot Bath <input checked="" type="checkbox"/> Ladder <input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Oxygen Meter <input checked="" type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials <input checked="" type="checkbox"/> Suction/Discharge Hoses			
<b>Last Cleaning Date</b>	<b>Current Cleaning Date</b>	<b>Next Cleaning Date</b>	
-	27 August 2019	27 February 2020	
<b>Crystalline Representative</b>		<b>Customer Representative</b>	
			

# Domestic Tank Part A and B

Before Photo



After Photo



Before Photo



After Photo




Water Tank is Cleaned & Disinfected



<b>Customer:</b> Hirmas Real Estate LLC		<b>Contact Person:</b> Bashar Abu Salim	
<b>Site:</b> DIC Village		<b>Contact Number:</b> 052 536 7437	
<b>Description:</b> Domestic Tank Part A and B		<b>Location:</b> Building #02 Ground	
<b>Type Of Building :</b> <input checked="" type="checkbox"/> Commercial <input type="checkbox"/> Residential <input type="checkbox"/> Others			
<b>Type Of Tank</b>			
<input type="checkbox"/> Concrete <input checked="" type="checkbox"/> GRP Panel <input type="checkbox"/> FRP Tank <input type="checkbox"/> Galvanized <input type="checkbox"/> Steel Panel <input type="checkbox"/> Plastic <input type="checkbox"/> Concrete Coated <input type="checkbox"/> Polyurethane <input type="checkbox"/> Others			
<b>Condition Of Water before cleaning</b>		<b>Condition Of Water after cleaning</b>	
<input type="checkbox"/> Clean <input checked="" type="checkbox"/> Dirty <input type="checkbox"/> Very Dirty <input type="checkbox"/> Biofilms <input type="checkbox"/> Moulds <input type="checkbox"/> Slime <input type="checkbox"/> Sediments <input type="checkbox"/> Mud & Sand <input type="checkbox"/> Rust		<input checked="" type="checkbox"/> Clean <input type="checkbox"/> Dirty <input type="checkbox"/> Very Dirty <input type="checkbox"/> Biofilms <input type="checkbox"/> Moulds <input type="checkbox"/> Slime <input type="checkbox"/> Sediments <input type="checkbox"/> Mud & Sand <input type="checkbox"/> Rust	
<b>Size of Tank</b>			
<b>M3:</b> 140		<b>USG:</b>	<b>L*B*H:</b>
<b>Quantity Of Water</b>		<b>Manhole</b>	
<input type="checkbox"/> Full <input checked="" type="checkbox"/> Half <input type="checkbox"/> Empty		<input type="checkbox"/> Covered <input checked="" type="checkbox"/> Damaged <input type="checkbox"/> NA	
<b>Ladder In</b>	<b>Ladder Out</b>	<b>Leaks</b>	
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	
<b>Drain Line</b>	<b>Valves</b>	<b>Float Valve</b>	
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	
<b>Tank Cleaned</b>	<b>Tank Disinfected</b>	<b>Pipes Disinfected</b>	
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	
<b>Chemicals Used</b>			
<b>Chemical:</b> Carela Bio		<b>Quantity:</b> 500ml	
<b>Chemical:</b> Carela Bio Plus		<b>Quantity:</b> 500ml	
<b>Equipments Used</b>			
<input checked="" type="checkbox"/> Submersibel Pump <input type="checkbox"/> High/low Pressure Jet <input checked="" type="checkbox"/> Extension Cords <input type="checkbox"/> LED Lights <input checked="" type="checkbox"/> Foot Bath <input checked="" type="checkbox"/> Ladder <input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Oxygen Meter <input checked="" type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials <input checked="" type="checkbox"/> Suction/Discharge Hoses			
<b>Last Cleaning Date</b>	<b>Current Cleaning Date</b>	<b>Next Cleaning Date</b>	
-	27 August 2019	27 February 2020	
<b>Crystalline Representative</b>		<b>Customer Representative</b>	
			

# Domestic Tank Part A and B

Before Photo



After Photo




Before Photo



After Photo



Water Tank is Cleaned & Disinfected

<b>Customer:</b> Hirmas Real Estate LLC		<b>Contact Person:</b> Bashar Abu Salim	
<b>Site:</b> DIC Village		<b>Contact Number:</b> 052 536 7437	
<b>Description:</b> Domestic tank Part A and B		<b>Location:</b> Building #25 Ground	
<b>Type Of Building :</b> <input checked="" type="checkbox"/> Commercial <input type="checkbox"/> Residential <input type="checkbox"/> Others			
<b>Type Of Tank</b>			
<input type="checkbox"/> Concrete <input checked="" type="checkbox"/> GRP Panel <input type="checkbox"/> FRP Tank <input type="checkbox"/> Galvanized <input type="checkbox"/> Steel Panel <input type="checkbox"/> Plastic <input type="checkbox"/> Concrete Coated <input type="checkbox"/> Polyurethane <input type="checkbox"/> Others			
<b>Condition Of Water before cleaning</b>		<b>Condition Of Water after cleaning</b>	
<input type="checkbox"/> Clean <input checked="" type="checkbox"/> Dirty <input type="checkbox"/> Very Dirty <input type="checkbox"/> Biofilms <input type="checkbox"/> Moulds <input type="checkbox"/> Slime <input type="checkbox"/> Sediments <input checked="" type="checkbox"/> Mud & Sand <input type="checkbox"/> Rust		<input checked="" type="checkbox"/> Clean <input type="checkbox"/> Dirty <input type="checkbox"/> Very Dirty <input type="checkbox"/> Biofilms <input type="checkbox"/> Moulds <input type="checkbox"/> Slime <input type="checkbox"/> Sediments <input type="checkbox"/> Mud & Sand <input type="checkbox"/> Rust	
<b>Size of Tank</b>			
<b>M3:</b> 140		<b>USG:</b>	<b>L*B*H:</b>
<b>Quantity Of Water</b>		<b>Manhole</b>	
<input type="checkbox"/> Full <input checked="" type="checkbox"/> Half <input type="checkbox"/> Empty		<input checked="" type="checkbox"/> Covered <input type="checkbox"/> Damaged <input type="checkbox"/> NA	
<b>Ladder In</b>	<b>Ladder Out</b>	<b>Leaks</b>	
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	
<b>Drain Line</b>	<b>Valves</b>	<b>Float Valve</b>	
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	
<b>Tank Cleaned</b>	<b>Tank Disinfected</b>	<b>Pipes Disinfected</b>	
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	
<b>Chemicals Used</b>			
<b>Chemical:</b> Carela Bio		<b>Quantity:</b> 500ml	
<b>Chemical:</b> Carela Bio Plus		<b>Quantity:</b> 500ml	
<b>Equipments Used</b>			
<input checked="" type="checkbox"/> Submersibel Pump <input type="checkbox"/> High/low Pressure Jet <input checked="" type="checkbox"/> Extension Cords <input type="checkbox"/> LED Lights <input checked="" type="checkbox"/> Foot Bath <input checked="" type="checkbox"/> Ladder <input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Oxygen Meter <input checked="" type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials <input checked="" type="checkbox"/> Suction/Discharge Hoses			
<b>Last Cleaning Date</b>	<b>Current Cleaning Date</b>	<b>Next Cleaning Date</b>	
-	29 August 2019	29 February 2020	
<b>Crystalline Representative</b>		<b>Customer Representative</b>	
			

# Domestic tank Part A and B

Before Photo



After Photo




Before Photo



After Photo



Water Tank is Cleaned & Disinfected

<b>Customer:</b> Hirmas Real Estate LLC		<b>Contact Person:</b> Bashar Abu Salim	
<b>Site:</b> DIC Village		<b>Contact Number:</b> 052 536 7437	
<b>Description:</b> Domestic Tank Part A B		<b>Location:</b> Building #16 Ground	
<b>Type Of Building :</b> <input checked="" type="checkbox"/> Commercial <input type="checkbox"/> Residential <input type="checkbox"/> Others			
<b>Type Of Tank</b>			
<input type="checkbox"/> Concrete <input checked="" type="checkbox"/> GRP Panel <input type="checkbox"/> FRP Tank <input type="checkbox"/> Galvanized <input type="checkbox"/> Steel Panel <input type="checkbox"/> Plastic <input type="checkbox"/> Concrete Coated <input type="checkbox"/> Polyurethane <input type="checkbox"/> Others			
<b>Condition Of Water before cleaning</b>		<b>Condition Of Water after cleaning</b>	
<input type="checkbox"/> Clean <input checked="" type="checkbox"/> Dirty <input type="checkbox"/> Very Dirty <input type="checkbox"/> Biofilms <input type="checkbox"/> Moulds <input type="checkbox"/> Slime <input type="checkbox"/> Sediments <input checked="" type="checkbox"/> Mud & Sand <input type="checkbox"/> Rust		<input checked="" type="checkbox"/> Clean <input type="checkbox"/> Dirty <input type="checkbox"/> Very Dirty <input type="checkbox"/> Biofilms <input type="checkbox"/> Moulds <input type="checkbox"/> Slime <input type="checkbox"/> Sediments <input type="checkbox"/> Mud & Sand <input type="checkbox"/> Rust	
<b>Size of Tank</b>			
<b>M3:</b> 140		<b>USG:</b>	<b>L*B*H:</b>
<b>Quantity Of Water</b>		<b>Manhole</b>	
<input type="checkbox"/> Full <input checked="" type="checkbox"/> Half <input type="checkbox"/> Empty		<input checked="" type="checkbox"/> Covered <input type="checkbox"/> Damaged <input type="checkbox"/> NA	
<b>Ladder In</b>	<b>Ladder Out</b>	<b>Leaks</b>	
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	
<b>Drain Line</b>	<b>Valves</b>	<b>Float Valve</b>	
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	
<b>Tank Cleaned</b>	<b>Tank Disinfected</b>	<b>Pipes Disinfected</b>	
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	
<b>Chemicals Used</b>			
<b>Chemical:</b> Carela Bio		<b>Quantity:</b> 500ml	
<b>Chemical:</b> Carela Bio Plus		<b>Quantity:</b> 500ml	
<b>Equipments Used</b>			
<input checked="" type="checkbox"/> Submersibel Pump <input type="checkbox"/> High/low Pressure Jet <input checked="" type="checkbox"/> Extension Cords <input type="checkbox"/> LED Lights <input checked="" type="checkbox"/> Foot Bath <input checked="" type="checkbox"/> Ladder <input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Oxygen Meter <input checked="" type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials <input checked="" type="checkbox"/> Suction/Discharge Hoses			
<b>Last Cleaning Date</b>	<b>Current Cleaning Date</b>	<b>Next Cleaning Date</b>	
-	29 August 2019	29 February 2020	
<b>Crystalline Representative</b>		<b>Customer Representative</b>	
			

# Domestic Tank Part A B

Before Photo



After Photo




Before Photo



After Photo



Water Tank is Cleaned & Disinfected

<b>Customer:</b> Hirmas Real Estate LLC		<b>Contact Person:</b> Bashar Abu Salim	
<b>Site:</b> DIC Village		<b>Contact Number:</b> 052 536 7437	
<b>Description:</b> Domestic Tank Part A and B		<b>Location:</b> Building #18 Ground	
<b>Type Of Building :</b> <input checked="" type="checkbox"/> Commercial <input type="checkbox"/> Residential <input type="checkbox"/> Others			
<b>Type Of Tank</b>			
<input type="checkbox"/> Concrete <input checked="" type="checkbox"/> GRP Panel <input type="checkbox"/> FRP Tank <input type="checkbox"/> Galvanized <input type="checkbox"/> Steel Panel <input type="checkbox"/> Plastic <input type="checkbox"/> Concrete Coated <input type="checkbox"/> Polyurethane <input type="checkbox"/> Others			
<b>Condition Of Water before cleaning</b>		<b>Condition Of Water after cleaning</b>	
<input type="checkbox"/> Clean <input checked="" type="checkbox"/> Dirty <input type="checkbox"/> Very Dirty <input type="checkbox"/> Biofilms <input type="checkbox"/> Moulds <input type="checkbox"/> Slime <input type="checkbox"/> Sediments <input checked="" type="checkbox"/> Mud & Sand <input type="checkbox"/> Rust		<input checked="" type="checkbox"/> Clean <input type="checkbox"/> Dirty <input type="checkbox"/> Very Dirty <input type="checkbox"/> Biofilms <input type="checkbox"/> Moulds <input type="checkbox"/> Slime <input type="checkbox"/> Sediments <input type="checkbox"/> Mud & Sand <input type="checkbox"/> Rust	
<b>Size of Tank</b>			
<b>M3:</b> 140		<b>USG:</b>	<b>L*B*H:</b>
<b>Quantity Of Water</b>		<b>Manhole</b>	
<input type="checkbox"/> Full <input checked="" type="checkbox"/> Half <input type="checkbox"/> Empty		<input checked="" type="checkbox"/> Covered <input type="checkbox"/> Damaged <input type="checkbox"/> NA	
<b>Ladder In</b>	<b>Ladder Out</b>	<b>Leaks</b>	
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	
<b>Drain Line</b>	<b>Valves</b>	<b>Float Valve</b>	
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	
<b>Tank Cleaned</b>	<b>Tank Disinfected</b>	<b>Pipes Disinfected</b>	
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	
<b>Chemicals Used</b>			
<b>Chemical:</b> Carela Bio		<b>Quantity:</b> 500ml	
<b>Chemical:</b> Carela Bio Plus		<b>Quantity:</b> 500ml	
<b>Equipments Used</b>			
<input checked="" type="checkbox"/> Submersibel Pump <input type="checkbox"/> High/low Pressure Jet <input checked="" type="checkbox"/> Extension Cords <input type="checkbox"/> LED Lights <input checked="" type="checkbox"/> Foot Bath <input checked="" type="checkbox"/> Ladder <input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Oxygen Meter <input checked="" type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials <input checked="" type="checkbox"/> Suction/Discharge Hoses			
<b>Last Cleaning Date</b>	<b>Current Cleaning Date</b>	<b>Next Cleaning Date</b>	
-	29 August 2019	29 February 2020	
<b>Crystalline Representative</b>		<b>Customer Representative</b>	
			

# Domestic Tank Part A and B

Before Photo



After Photo



Before Photo



After Photo



Water Tank is Cleaned & Disinfected

<b>Customer:</b> Hirmas Real Estate LLC		<b>Contact Person:</b> Bashar Abu Salim	
<b>Site:</b> DIC Village		<b>Contact Number:</b> 052 536 7437	
<b>Description:</b> Domestic Tank Part A and B		<b>Location:</b> Diner#05 Ground	
<b>Type Of Building :</b> <input checked="" type="checkbox"/> Commercial <input type="checkbox"/> Residential <input type="checkbox"/> Others			
<b>Type Of Tank</b>			
<input type="checkbox"/> Concrete	<input checked="" type="checkbox"/> GRP Panel	<input type="checkbox"/> FRP Tank	<input type="checkbox"/> Galvanized
<input type="checkbox"/> Steel Panel	<input type="checkbox"/> Plastic	<input type="checkbox"/> Concrete Coated	<input type="checkbox"/> Polyurethane
<input type="checkbox"/> Others			
<b>Condition Of Water before cleaning</b>		<b>Condition Of Water after cleaning</b>	
<input type="checkbox"/> Clean	<input checked="" type="checkbox"/> Dirty	<input type="checkbox"/> Very Dirty	<input type="checkbox"/> Clean
<input type="checkbox"/> Biofilms	<input type="checkbox"/> Moulds	<input type="checkbox"/> Slime	<input type="checkbox"/> Dirty
<input type="checkbox"/> Sediments	<input checked="" type="checkbox"/> Mud & Sand	<input type="checkbox"/> Rust	<input type="checkbox"/> Very Dirty
		<input type="checkbox"/> Biofilms	<input type="checkbox"/> Moulds
		<input type="checkbox"/> Sediments	<input type="checkbox"/> Mud & Sand
		<input type="checkbox"/> Rust	<input type="checkbox"/> Rust
<b>Size of Tank</b>			
<b>M3:</b> 60		<b>USG:</b>	<b>L*B*H:</b>
<b>Quantity Of Water</b>		<b>Manhole</b>	
<input type="checkbox"/> Full	<input checked="" type="checkbox"/> Half	<input type="checkbox"/> Empty	<input checked="" type="checkbox"/> Covered
		<input type="checkbox"/> Damaged	<input type="checkbox"/> NA
<b>Ladder In</b>		<b>Ladder Out</b>	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
<b>Drain Line</b>		<b>Valves</b>	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
<b>Tank Cleaned</b>		<b>Tank Disinfected</b>	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
		<b>Pipes Disinfected</b>	
		<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
<b>Chemicals Used</b>			
<b>Chemical:</b> Carela Bio		<b>Quantity:</b> 500ml	
<b>Chemical:</b> Carela Bio Plus		<b>Quantity:</b> 500ml	
<b>Equipments Used</b>			
<input checked="" type="checkbox"/> Submersibel Pump	<input type="checkbox"/> High/low Pressure Jet	<input checked="" type="checkbox"/> Extension Cords	<input type="checkbox"/> LED Lights
<input checked="" type="checkbox"/> Foot Bath	<input checked="" type="checkbox"/> Ladder	<input checked="" type="checkbox"/> Ventilating Fan	<input checked="" type="checkbox"/> Oxygen Meter
<input checked="" type="checkbox"/> Vacuum Cleaner	<input checked="" type="checkbox"/> Cleaning Materials	<input checked="" type="checkbox"/> Suction/Discharge Hoses	
<b>Last Cleaning Date</b>		<b>Current Cleaning Date</b>	
-		29 August 2019	
		<b>Next Cleaning Date</b>	
		29 February 2020	
<b>Crystalline Representative</b>		<b>Customer Representative</b>	
			

# Domestic Tank Part A and B

Before Photo



After Photo



Before Photo




After Photo



Water Tank is Cleaned & Disinfected



<b>Customer:</b> Hirmas Real Estate LLC		<b>Contact Person:</b> Bashar Abu Salim	
<b>Site:</b> DIC Village		<b>Contact Number:</b> 052 536 7437	
<b>Description:</b> Domestic Tank Part A and B		<b>Location:</b> Building #26 Ground	
<b>Type Of Building :</b> <input checked="" type="checkbox"/> Commercial <input type="checkbox"/> Residential <input type="checkbox"/> Others			
<b>Type Of Tank</b>			
<input type="checkbox"/> Concrete <input checked="" type="checkbox"/> GRP Panel <input type="checkbox"/> FRP Tank <input type="checkbox"/> Galvanized <input type="checkbox"/> Steel Panel <input type="checkbox"/> Plastic <input type="checkbox"/> Concrete Coated <input type="checkbox"/> Polyurethane <input type="checkbox"/> Others			
<b>Condition Of Water before cleaning</b>		<b>Condition Of Water after cleaning</b>	
<input type="checkbox"/> Clean <input checked="" type="checkbox"/> Dirty <input type="checkbox"/> Very Dirty <input type="checkbox"/> Biofilms <input type="checkbox"/> Moulds <input type="checkbox"/> Slime <input type="checkbox"/> Sediments <input checked="" type="checkbox"/> Mud & Sand <input type="checkbox"/> Rust		<input checked="" type="checkbox"/> Clean <input type="checkbox"/> Dirty <input type="checkbox"/> Very Dirty <input type="checkbox"/> Biofilms <input type="checkbox"/> Moulds <input type="checkbox"/> Slime <input type="checkbox"/> Sediments <input type="checkbox"/> Mud & Sand <input type="checkbox"/> Rust	
<b>Size of Tank</b>			
<b>M3:</b> 140		<b>USG:</b>	<b>L*B*H:</b>
<b>Quantity Of Water</b>		<b>Manhole</b>	
<input type="checkbox"/> Full <input checked="" type="checkbox"/> Half <input type="checkbox"/> Empty		<input checked="" type="checkbox"/> Covered <input type="checkbox"/> Damaged <input type="checkbox"/> NA	
<b>Ladder In</b>	<b>Ladder Out</b>	<b>Leaks</b>	
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	
<b>Drain Line</b>	<b>Valves</b>	<b>Float Valve</b>	
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	
<b>Tank Cleaned</b>	<b>Tank Disinfected</b>	<b>Pipes Disinfected</b>	
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	
<b>Chemicals Used</b>			
<b>Chemical:</b> Carela Bio		<b>Quantity:</b> 500ml	
<b>Chemical:</b> Carela Bio Plus		<b>Quantity:</b> 500ml	
<b>Equipments Used</b>			
<input checked="" type="checkbox"/> Submersibel Pump <input type="checkbox"/> High/low Pressure Jet <input checked="" type="checkbox"/> Extension Cords <input type="checkbox"/> LED Lights <input checked="" type="checkbox"/> Foot Bath <input checked="" type="checkbox"/> Ladder <input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Oxygen Meter <input checked="" type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials <input checked="" type="checkbox"/> Suction/Discharge Hoses			
<b>Last Cleaning Date</b>	<b>Current Cleaning Date</b>	<b>Next Cleaning Date</b>	
-	02 September 2019	02 March 2020	
<b>Crystalline Representative</b>		<b>Customer Representative</b>	
			

# Domestic Tank Part A and B

Before Photo



After Photo



Before Photo



After Photo




Water Tank is Cleaned & Disinfected



<b>Customer:</b> Hirmas Real Estate LLC		<b>Contact Person:</b> Bashar Abu Salim	
<b>Site:</b> DIC Village		<b>Contact Number:</b> 052 536 7437	
<b>Description:</b> Domestic Tank Part A and B		<b>Location:</b> Diner#02 Ground	
<b>Type Of Building :</b> <input checked="" type="checkbox"/> Commercial <input type="checkbox"/> Residential <input type="checkbox"/> Others			
<b>Type Of Tank</b>			
<input type="checkbox"/> Concrete <input checked="" type="checkbox"/> GRP Panel <input type="checkbox"/> FRP Tank <input type="checkbox"/> Galvanized <input type="checkbox"/> Steel Panel <input type="checkbox"/> Plastic <input type="checkbox"/> Concrete Coated <input type="checkbox"/> Polyurethane <input type="checkbox"/> Others			
<b>Condition Of Water before cleaning</b>		<b>Condition Of Water after cleaning</b>	
<input type="checkbox"/> Clean <input checked="" type="checkbox"/> Dirty <input type="checkbox"/> Very Dirty <input type="checkbox"/> Biofilms <input type="checkbox"/> Moulds <input type="checkbox"/> Slime <input type="checkbox"/> Sediments <input checked="" type="checkbox"/> Mud & Sand <input type="checkbox"/> Rust		<input checked="" type="checkbox"/> Clean <input type="checkbox"/> Dirty <input type="checkbox"/> Very Dirty <input type="checkbox"/> Biofilms <input type="checkbox"/> Moulds <input type="checkbox"/> Slime <input type="checkbox"/> Sediments <input type="checkbox"/> Mud & Sand <input type="checkbox"/> Rust	
<b>Size of Tank</b>			
<b>M3:</b> 60		<b>USG:</b>	<b>L*B*H:</b>
<b>Quantity Of Water</b>		<b>Manhole</b>	
<input type="checkbox"/> Full <input checked="" type="checkbox"/> Half <input type="checkbox"/> Empty		<input checked="" type="checkbox"/> Covered <input type="checkbox"/> Damaged <input type="checkbox"/> NA	
<b>Ladder In</b>	<b>Ladder Out</b>	<b>Leaks</b>	
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	
<b>Drain Line</b>	<b>Valves</b>	<b>Float Valve</b>	
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	
<b>Tank Cleaned</b>	<b>Tank Disinfected</b>	<b>Pipes Disinfected</b>	
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	
<b>Chemicals Used</b>			
<b>Chemical:</b> Carela Bio		<b>Quantity:</b> 250ml	
<b>Chemical:</b> Carela Bio Plus		<b>Quantity:</b> 250ml	
<b>Equipments Used</b>			
<input checked="" type="checkbox"/> Submersibel Pump <input type="checkbox"/> High/low Pressure Jet <input checked="" type="checkbox"/> Extension Cords <input type="checkbox"/> LED Lights <input checked="" type="checkbox"/> Foot Bath <input checked="" type="checkbox"/> Ladder <input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Oxygen Meter <input checked="" type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials <input checked="" type="checkbox"/> Suction/Discharge Hoses			
<b>Last Cleaning Date</b>	<b>Current Cleaning Date</b>	<b>Next Cleaning Date</b>	
-	02 September 2019	02 March 2020	
<b>Crystalline Representative</b>		<b>Customer Representative</b>	
			

# Domestic Tank Part A and B

Before Photo



After Photo




Before Photo



After Photo



Water Tank is Cleaned & Disinfected

<b>Customer:</b> Hirmas Real Estate LLC		<b>Contact Person:</b> Bashar Abu Salim	
<b>Site:</b> DIC Village		<b>Contact Number:</b> 052 536 7437	
<b>Description:</b> Domestic Tank Part A and B		<b>Location:</b> Building #24	
<b>Type Of Building :</b> <input checked="" type="checkbox"/> Commercial <input type="checkbox"/> Residential <input type="checkbox"/> Others			
<b>Type Of Tank</b>			
<input type="checkbox"/> Concrete <input checked="" type="checkbox"/> GRP Panel <input type="checkbox"/> FRP Tank <input type="checkbox"/> Galvanized <input type="checkbox"/> Steel Panel <input type="checkbox"/> Plastic <input type="checkbox"/> Concrete Coated <input type="checkbox"/> Polyurethane <input type="checkbox"/> Others			
<b>Condition Of Water before cleaning</b>		<b>Condition Of Water after cleaning</b>	
<input type="checkbox"/> Clean <input checked="" type="checkbox"/> Dirty <input type="checkbox"/> Very Dirty <input type="checkbox"/> Biofilms <input type="checkbox"/> Moulds <input type="checkbox"/> Slime <input type="checkbox"/> Sediments <input checked="" type="checkbox"/> Mud & Sand <input type="checkbox"/> Rust		<input checked="" type="checkbox"/> Clean <input type="checkbox"/> Dirty <input type="checkbox"/> Very Dirty <input type="checkbox"/> Biofilms <input type="checkbox"/> Moulds <input type="checkbox"/> Slime <input type="checkbox"/> Sediments <input type="checkbox"/> Mud & Sand <input type="checkbox"/> Rust	
<b>Size of Tank</b>			
<b>M3:</b> 140		<b>USG:</b>	<b>L*B*H:</b>
<b>Quantity Of Water</b>		<b>Manhole</b>	
<input type="checkbox"/> Full <input checked="" type="checkbox"/> Half <input type="checkbox"/> Empty		<input checked="" type="checkbox"/> Covered <input type="checkbox"/> Damaged <input type="checkbox"/> NA	
<b>Ladder In</b>	<b>Ladder Out</b>	<b>Leaks</b>	
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	
<b>Drain Line</b>	<b>Valves</b>	<b>Float Valve</b>	
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	
<b>Tank Cleaned</b>	<b>Tank Disinfected</b>	<b>Pipes Disinfected</b>	
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	
<b>Chemicals Used</b>			
<b>Chemical:</b> Carela Bio		<b>Quantity:</b> 500ml	
<b>Chemical:</b> Carela Bio Plus		<b>Quantity:</b> 500ml	
<b>Equipments Used</b>			
<input checked="" type="checkbox"/> Submersibel Pump <input type="checkbox"/> High/low Pressure Jet <input checked="" type="checkbox"/> Extension Cords <input type="checkbox"/> LED Lights <input checked="" type="checkbox"/> Foot Bath <input checked="" type="checkbox"/> Ladder <input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Oxygen Meter <input checked="" type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials <input checked="" type="checkbox"/> Suction/Discharge Hoses			
<b>Last Cleaning Date</b>	<b>Current Cleaning Date</b>	<b>Next Cleaning Date</b>	
-	02 September 2019	02 March 2020	
<b>Crystalline Representative</b>		<b>Customer Representative</b>	
			

## Domestic Tank Part A and B

Before Photo



After Photo




Before Photo



After Photo




Water Tank is Cleaned & Disinfected

<b>Customer:</b> Hirmas Real Estate LLC		<b>Contact Person:</b> Bashar Abu Salim	
<b>Site:</b> DIC Village		<b>Contact Number:</b> 052 536 7437	
<b>Description:</b> Domestic Tank Part A and B		<b>Location:</b> Diner#07 Ground	
<b>Type Of Building :</b>		<input checked="" type="checkbox"/> Commercial	<input type="checkbox"/> Residential <input type="checkbox"/> Others
<b>Type Of Tank</b>			
<input type="checkbox"/> Concrete	<input checked="" type="checkbox"/> GRP Panel	<input type="checkbox"/> FRP Tank	<input type="checkbox"/> Galvanized
<input type="checkbox"/> Steel Panel	<input type="checkbox"/> Plastic	<input type="checkbox"/> Concrete Coated	<input type="checkbox"/> Polyurethane
<input type="checkbox"/> Others			
<b>Condition Of Water before cleaning</b>		<b>Condition Of Water after cleaning</b>	
<input type="checkbox"/> Clean	<input checked="" type="checkbox"/> Dirty	<input type="checkbox"/> Very Dirty	<input type="checkbox"/> Very Dirty
<input type="checkbox"/> Biofilms	<input type="checkbox"/> Moulds	<input type="checkbox"/> Slime	<input type="checkbox"/> Slime
<input type="checkbox"/> Sediments	<input checked="" type="checkbox"/> Mud & Sand	<input type="checkbox"/> Rust	<input type="checkbox"/> Rust
<b>Size of Tank</b>			
<b>M3:</b> 60		<b>USG:</b>	<b>L*B*H:</b>
<b>Quantity Of Water</b>		<b>Manhole</b>	
<input type="checkbox"/> Full	<input checked="" type="checkbox"/> Half	<input type="checkbox"/> Empty	<input checked="" type="checkbox"/> Covered <input type="checkbox"/> Damaged <input type="checkbox"/> NA
<b>Ladder In</b>		<b>Ladder Out</b>	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
<b>Drain Line</b>		<b>Valves</b>	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
<b>Tank Cleaned</b>		<b>Tank Disinfected</b>	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
		<b>Pipes Disinfected</b>	
		<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
<b>Chemicals Used</b>			
<b>Chemical:</b> Carela Bio Plus		<b>Quantity:</b> 250ml	
<b>Chemical:</b> Carela Bio		<b>Quantity:</b> 250ml	
<b>Equipments Used</b>			
<input checked="" type="checkbox"/> Submersibel Pump	<input type="checkbox"/> High/low Pressure Jet	<input checked="" type="checkbox"/> Extension Cords	<input type="checkbox"/> LED Lights
<input checked="" type="checkbox"/> Foot Bath	<input checked="" type="checkbox"/> Ladder	<input checked="" type="checkbox"/> Ventilating Fan	<input checked="" type="checkbox"/> Oxygen Meter
<input checked="" type="checkbox"/> Vacuum Cleaner	<input checked="" type="checkbox"/> Cleaning Materials	<input checked="" type="checkbox"/> Suction/Discharge Hoses	
<b>Last Cleaning Date</b>		<b>Current Cleaning Date</b>	
-		02 September 2019	
		<b>Next Cleaning Date</b>	
		02 March 2020	
<b>Crystalline Representative</b>		<b>Customer Representative</b>	
			

# Domestic Tank Part A and B

Before Photo



After Photo



Before Photo



After Photo



Water Tank is Cleaned & Disinfected

# CRYSTALLINE CLEANING & ENVIRONMENTAL SERVICES

## WATER TANK CLEANING & DISINFECTION

**CLIENT NAME** : HIRMAS REAL ESTATE LLC  
**CONTACT PERSON** : BASHAR ABU SALIM  
**DESIGNATION** : HEAD OF QHSES  
**SITE DETAILS** : DIC VILLAGE  
**DETAILS** : WATER TANK CLEANING & DISINFECTION  
**DATE OF CLEANING** : AUGUST 2019  
**FREQUENCY OF CLEANING** : HALF YEARLY  
**DATE OF NEXT CLEANING** : 24 FEBRUARY 2020

*The above water tanks were cleaned and disinfected in accordance with the Code of Practice for the inspection and cleaning of customer water storage tanks.*



*Jasmanpinto*

## CRYSTALLINE CLEANING AND ENVIRONMENTAL SERVICES