

WATER TANK CLEANING & DISINFECTION COMPLETION REPORT

FOR



Client : SAMIR NAJIB EST. FOR
CENTRAL AIR-CONDITIONING
Contact Person: Mr. Mohammed Mashal
General Manager
Site Details : Khalifa Complex Building - A1, A2,
A4, A5, A6 & C70 Abu Dhabi.
Date : 12 September 2018



CRYSTALLINE
ENVIRONMENTAL SERVICES

CRYSTALLINE ENVIRONMENTAL
SERVICES

P.O. BOX 131463, Abu Dhabi, U.A.E.

TEL: 02 6508930 FAX: 02 6508942

info@crystalline-uae.com

www.crystalline-uae.com





CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT

19893

CUSTOMER: <u>SANA AIR No 01</u>			CONTACT PERSON: <u>MR INDRA</u>		
SITE DETAILS: <u>KHALIFA COMPLEX ABU DHABI</u>			CONTACT NO: <u>055 9838071</u>		
TANK DETAILS: <u>R-EE-KAW TANK No 01</u>			LOCATION DETAILS: <u>Under Ground</u>		
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL <input type="checkbox"/> RESIDENTIAL <input type="checkbox"/> OTHERS					
TYPE OF TANK					
<input type="checkbox"/> CONCRETE	<input type="checkbox"/> GRP PANEL	<input type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED		<input type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS		
SIZE OF TANK			QUANTITY OF WATER		
M3	USG	L*B*H	<input type="checkbox"/> FULL	<input type="checkbox"/> HALF	<input type="checkbox"/> EMPTY
CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK AFTER CLEANING		
<input type="checkbox"/> CLEAN	<input checked="" type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input checked="" type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
ACCESS		MANHOLE		<input checked="" type="checkbox"/> COVERED	<input type="checkbox"/> DAMAGED <input type="checkbox"/> NA
LADDER IN	LADDER OUT	LEAKS	DRAIN LINE	VALVES	FLOAT VALVE
<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO
TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> NA	
LAST CLEANING DATE		CURRENT CLEANING DATE		NEXT CLEANING DATE	
		<u>01/09/2018</u>		<u>01/03/2019</u>	
CHEMICALS & EQUIPMENTS USED					
1. <u>Caruh Bio Plug</u> Quantity <u>1.45PKS</u>					
2. _____ Quantity _____					
<input checked="" type="checkbox"/> Submersibel Pump <input checked="" type="checkbox"/> High /Low Pressure jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED Lights <input checked="" type="checkbox"/> Foot Bath <input checked="" type="checkbox"/> Ladder <input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Mater <input checked="" type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials					
COMMENTS & RECOMMENDATIONS: <u>Above mentioned water tanks are cleaned & disinfected</u>					
Crystalline Representative: <u>Mushki</u>			Signature: <u>[Signature]</u>		

Date of Cleaning: 01-09-2018

PHOTOGRAPHS
UNDER GROUND RCC RAW WATER TANK (A 01) - 01

BEFORE



AFTER





CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT

19894

CUSTOMER: <u>SANA AIR</u>			CONTACT PERSON: <u>MR INDRAN</u>		
SITE DETAILS: <u>KHALIFA COMPLEX A-01</u> <u>ABU DHABI</u>			CONTACT NO: <u>0559838071</u>		
TANK DETAILS: <u>FIBER FILTER TANK NO 01</u>			LOCATION DETAILS: <u>ROOF TOP</u>		
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL <input type="checkbox"/> RESIDENTIAL <input type="checkbox"/> OTHERS					
TYPE OF TANK					
<input type="checkbox"/> CONCRETE	<input type="checkbox"/> GRP PANEL	<input type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED		<input type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS		
SIZE OF TANK			QUANTITY OF WATER		
M3	USG	L*B*H	<input type="checkbox"/> FULL	<input type="checkbox"/> HALF	<input type="checkbox"/> EMPTY
CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK AFTER CLEANING		
<input type="checkbox"/> CLEAN	<input checked="" type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input checked="" type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
ACCESS		MANHOLE	<input checked="" type="checkbox"/> COVERED	<input type="checkbox"/> DAMAGED	<input type="checkbox"/> NA
LADDER IN	LADDER OUT	LEAKS	DRAIN LINE	VALVES	FLOAT VALVE
<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO
TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> YES	<input type="checkbox"/> NO <input checked="" type="checkbox"/> NA
LAST CLEANING DATE		CURRENT CLEANING DATE		NEXT CLEANING DATE	
		<u>01/09/2018</u>		<u>01/03/2019</u>	
CHEMICALS & EQUIPMENTS USED					
1. <u>Carebo Bio Plus</u> Quantity <u>400 ML</u>					
2. _____ Quantity _____					
<input checked="" type="checkbox"/> Submersibel Pump <input checked="" type="checkbox"/> High /Low Pressure jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED Lights <input checked="" type="checkbox"/> Foot Bath <input checked="" type="checkbox"/> Ladder <input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Mater <input checked="" type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials					
COMMENTS & RECOMMENDATIONS: <u>Above mentioned water tank are cleaned & Disinfected.</u>					
Crystalline Representative: <u>Mudhep</u>			Signature: <u>[Signature]</u>		



CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT

19895

CUSTOMER: <u>SANA AIR</u>			CONTACT PERSON: <u>MR INDRAN</u>		
SITE DETAILS: <u>KHALIFA COMPLEX A-01</u> <u>ABU DHABI</u>			CONTACT NO: <u>0559838071</u>		
TANK DETAILS: <u>FIBER FILTER TANK 02</u>			LOCATION DETAILS: <u>ROOF TOP</u>		
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL <input type="checkbox"/> RESIDENTIAL <input type="checkbox"/> OTHERS					
TYPE OF TANK					
<input type="checkbox"/> CONCRETE	<input type="checkbox"/> GRP PANEL	<input type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED	<input type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS			
SIZE OF TANK			QUANTITY OF WATER		
M3	USG	L*B*H	<input type="checkbox"/> FULL	<input type="checkbox"/> HALF	<input type="checkbox"/> EMPTY
CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK AFTER CLEANING		
<input type="checkbox"/> CLEAN	<input checked="" type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input checked="" type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
ACCESS		MANHOLE	<input checked="" type="checkbox"/> COVERED	<input type="checkbox"/> DAMAGED	<input type="checkbox"/> NA
LADDER IN	LADDER OUT	LEAKS	DRAIN LINE	VALVES	FLOAT VALVE
<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO
TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> YES	<input type="checkbox"/> NO <input checked="" type="checkbox"/> NA
LAST CLEANING DATE		CURRENT CLEANING DATE		NEXT CLEANING DATE	
		<u>01/09/2018</u>		<u>01/03/2019</u>	
CHEMICALS & EQUIPMENTS USED					
1. <u>Care Bio Plus</u> Quantity <u>400 ml</u>					
2. _____ Quantity _____					
<input checked="" type="checkbox"/> Submersibel Pump <input checked="" type="checkbox"/> High /Low Pressure jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED Lights <input checked="" type="checkbox"/> Foot Bath <input checked="" type="checkbox"/> Ladder <input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Mater <input checked="" type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials					
COMMENTS & RECOMMENDATIONS: <u>Above mentioned water tank are cleaned & disinfected</u>					
Crystalline Representative: <u>Musthik</u>			Signature: <u>[Signature]</u>		

Date of Cleaning: 01-09-2018

PHOTOGRAPHS
ROOF TOP FRP FILTER TANK (A 01) – 01&02

BEFORE


FRP FILTER TANK-01



FRP FILTER TANK-02



AFTER





CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT

19896

CUSTOMER: <u>SANA AIR.</u>			CONTACT PERSON: <u>MR INDRAN</u>		
SITE DETAILS: <u>KHALIFA COMPLEX ABU DHABI A-01.</u>			CONTACT NO: <u>0559838071.</u>		
TANK DETAILS: <u>FIBER. -3</u>			LOCATION DETAILS: <u>ROOF TOP.</u>		
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL		<input type="checkbox"/> RESIDENTIAL		<input type="checkbox"/> OTHERS	
TYPE OF TANK					
<input type="checkbox"/> CONCRETE	<input type="checkbox"/> GRP PANEL	<input type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED	<input type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS			
SIZE OF TANK			QUANTITY OF WATER		
M3	USG	L*B*H	<input type="checkbox"/> FULL	<input type="checkbox"/> HALF	<input type="checkbox"/> EMPTY
CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK AFTER CLEANING		
<input type="checkbox"/> CLEAN	<input checked="" type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input checked="" type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
ACCESS		MANHOLE		<input checked="" type="checkbox"/> COVERED	<input type="checkbox"/> DAMAGED
<input type="checkbox"/> NA					<input type="checkbox"/> NA
LADDER IN		LADDER OUT		LEAKS	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO
TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> YES	<input type="checkbox"/> NO <input checked="" type="checkbox"/> NA
LAST CLEANING DATE		CURRENT CLEANING DATE		NEXT CLEANING DATE	
		<u>02/09/2018</u>		<u>02/03/2019.</u>	
CHEMICALS & EQUIPMENTS USED					
1. <u>Carbo Bio Plus</u> Quantity <u>400ML</u>					
2. _____ Quantity _____					
<input checked="" type="checkbox"/> Submersibel Pump <input checked="" type="checkbox"/> High /Low Pressure jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED Lights <input checked="" type="checkbox"/> Foot Bath <input checked="" type="checkbox"/> Ladder					
<input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Mater <input checked="" type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials					
COMMENTS & RECOMMENDATIONS: <u>Above mentioned water tank are cleaned & disinfected</u>					
Crystalline Representative: <u>Mustafa</u>			Signature: <u>[Signature]</u>		



CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT

19897

CUSTOMER: <u>SANA AIR.</u>			CONTACT PERSON: <u>MR INDIRAN</u>		
SITE DETAILS: <u>KHALIFA COMPLEX ABU DHABI</u>			CONTACT NO: <u>055 98 38 011</u>		
TANK DETAILS: <u>FIBER -4</u>			LOCATION DETAILS: <u>Roof Top. A-1</u>		
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL		<input type="checkbox"/> RESIDENTIAL		<input type="checkbox"/> OTHERS	
TYPE OF TANK					
<input type="checkbox"/> CONCRETE	<input type="checkbox"/> GRP PANEL	<input type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED		<input type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS		
SIZE OF TANK			QUANTITY OF WATER		
M3	USG	L*B*H	<input type="checkbox"/> FULL	<input type="checkbox"/> HALF	<input type="checkbox"/> EMPTY
CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK AFTER CLEANING		
<input type="checkbox"/> CLEAN	<input checked="" type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input checked="" type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
ACCESS		MANHOLE		<input checked="" type="checkbox"/> COVERED	<input type="checkbox"/> DAMAGED
<input type="checkbox"/> NA	<input type="checkbox"/> NA	<input type="checkbox"/> NA	<input type="checkbox"/> NA	<input type="checkbox"/> NA	<input type="checkbox"/> NA
LADDER IN		LADDER OUT		LEAKS	
<input type="checkbox"/> YES <input type="checkbox"/> NO	<input type="checkbox"/> YES <input type="checkbox"/> NO	<input type="checkbox"/> YES <input type="checkbox"/> NO	<input type="checkbox"/> YES <input type="checkbox"/> NO	DRAIN LINE	
TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED	
<input type="checkbox"/> YES <input type="checkbox"/> NO	<input type="checkbox"/> YES <input type="checkbox"/> NO	<input type="checkbox"/> YES <input type="checkbox"/> NO	<input type="checkbox"/> YES <input type="checkbox"/> NO	<input type="checkbox"/> YES <input type="checkbox"/> NO	<input type="checkbox"/> YES <input type="checkbox"/> NO <input type="checkbox"/> NA
LAST CLEANING DATE		CURRENT CLEANING DATE		NEXT CLEANING DATE	
		<u>02/09/2018</u>		<u>02/03/2019</u>	
CHEMICALS & EQUIPMENTS USED					
1. <u>Cambo Bio Plus</u> Quantity <u>400ML</u>					
2. _____ Quantity _____					
<input checked="" type="checkbox"/> Submersibel Pump <input checked="" type="checkbox"/> High /Low Pressure jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED Lights <input checked="" type="checkbox"/> Foot Bath <input checked="" type="checkbox"/> Ladder					
<input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Mater <input checked="" type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials					
COMMENTS & RECOMMENDATIONS: <u>Above mentioned water Tank are cleaned & disinfected</u>					
Crystalline Representative: <u>Mustafa</u>			Signature: <u>[Signature]</u>		

Date of Cleaning: 02-09-2018

PHOTOGRAPHS
ROOF TOP FRP FILTER TANK (A 01) – 03&04

BEFORE

FRP FILTER TANK-03



FRP FILTER TANK-04



AFTER





CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT

19898

CUSTOMER: <u>SANA AIR</u>			CONTACT PERSON: <u>MR INDIRAM.</u>		
SITE DETAILS: <u>KHALIFA COMPLEX</u> <u>ABU DHABI - A-02</u>			CONTACT NO: <u>0559838071</u>		
TANK DETAILS: <u>REE RAW TANK NO. 1</u>			LOCATION DETAILS: <u>Under Ground</u>		
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL <input type="checkbox"/> RESIDENTIAL <input type="checkbox"/> OTHERS					
TYPE OF TANK					
<input type="checkbox"/> CONCRETE	<input type="checkbox"/> GRP PANEL	<input type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED		<input type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS		
SIZE OF TANK			QUANTITY OF WATER		
M3	USG	L*B*H	<input type="checkbox"/> FULL	<input type="checkbox"/> HALF	<input type="checkbox"/> EMPTY
CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK AFTER CLEANING		
<input type="checkbox"/> CLEAN	<input checked="" type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input checked="" type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
ACCESS		MANHOLE	<input checked="" type="checkbox"/> COVERED	<input type="checkbox"/> DAMAGED	<input type="checkbox"/> NA
LADDER IN	LADDER OUT	LEAKS	DRAIN LINE	VALVES	FLOAT VALVE
<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO
TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED	
<input type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> YES	<input type="checkbox"/> NO <input type="checkbox"/> NA
LAST CLEANING DATE		CURRENT CLEANING DATE		NEXT CLEANING DATE	
		<u>03/09/2018</u>		<u>03/03/2019</u>	
CHEMICALS & EQUIPMENTS USED					
1. <u>Carbo Bio</u> Quantity <u>1-00LTR</u>					
2. _____ Quantity _____					
<input checked="" type="checkbox"/> Submersibel Pump <input checked="" type="checkbox"/> High /Low Pressure jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED Lights <input type="checkbox"/> Foot Bath <input checked="" type="checkbox"/> Ladder <input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Mater <input checked="" type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials					
COMMENTS & RECOMMENDATIONS: <u>Above mentioned water tank as cleaned & disinfected</u>					
Crystalline Representative: <u>Mustafa</u>			Signature: <u>[Signature]</u>		



CRYSTALLINE
ENVIRONMENTAL SERVICES

Date of Cleaning: 03-09-2018


PHOTOGRAPHS

UNDE GROUND RCC RAW TANK (A 02) - 01

BEFORE



AFTER



CLEANER WATER GREENER TOMORROW



CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT

19899

CUSTOMER: <u>SANA AIR</u>			CONTACT PERSON: <u>MR INDIRAN</u>		
SITE DETAILS: <u>KHARIFA Complex A-02</u> <u>ABU DHABI</u>			CONTACT NO: <u>0559838071</u>		
TANK DETAILS: <u>FIBER FILTER TANK-01</u>			LOCATION DETAILS: <u>ROOF TOP</u>		
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL <input type="checkbox"/> RESIDENTIAL <input type="checkbox"/> OTHERS					
TYPE OF TANK					
<input type="checkbox"/> CONCRETE	<input type="checkbox"/> GRP PANEL	<input type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED		<input type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS		
SIZE OF TANK			QUANTITY OF WATER		
M3	USG	L*B*H	<input type="checkbox"/> FULL	<input type="checkbox"/> HALF	<input type="checkbox"/> EMPTY
CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK AFTER CLEANING		
<input type="checkbox"/> CLEAN	<input checked="" type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input checked="" type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
ACCESS		MANHOLE	<input checked="" type="checkbox"/> COVERED	<input type="checkbox"/> DAMAGED	<input type="checkbox"/> NA
LADDER IN	LADDER OUT	LEAKS	DRAIN LINE	VALVES	FLOAT VALVE
<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO
TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> YES	<input type="checkbox"/> NO <input checked="" type="checkbox"/> NA
LAST CLEANING DATE		CURRENT CLEANING DATE		NEXT CLEANING DATE	
		<u>03/09/2018</u>		<u>03/03/2019</u>	
CHEMICALS & EQUIPMENTS USED					
1. <u>Carubo Bio Plus</u> Quantity <u>400ml</u>					
2. _____ Quantity _____					
<input checked="" type="checkbox"/> Submersibel Pump <input checked="" type="checkbox"/> High /Low Pressure jet <input checked="" type="checkbox"/> Extension Cords <input type="checkbox"/> LED Lights <input checked="" type="checkbox"/> Foot Bath <input checked="" type="checkbox"/> Ladder					
<input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Mater <input checked="" type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials					
COMMENTS & RECOMMENDATIONS: <u>Above mentioned water tank are cleaned & disinfected</u>					
Crystalline Representative: <u>Mushtaq</u>			Signature: <u>[Signature]</u>		



CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT

19900

CUSTOMER: <u>SANA AIR</u>			CONTACT PERSON: <u>MR INDIRAN</u>		
SITE DETAILS: <u>KHALIFA COMPLEX A02</u> <u>ABU DHABI</u>			CONTACT NO: <u>0559838071</u>		
TANK DETAILS: <u>FIBER FILTER TANK A02</u>			LOCATION DETAILS: <u>ROOF TOP</u>		
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL <input type="checkbox"/> RESIDENTIAL <input type="checkbox"/> OTHERS					
TYPE OF TANK					
<input type="checkbox"/> CONCRETE	<input type="checkbox"/> GRP PANEL	<input type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED		<input type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS		
SIZE OF TANK			QUANTITY OF WATER		
M3	USG	L*B*H	<input type="checkbox"/> FULL	<input type="checkbox"/> HALF	<input type="checkbox"/> EMPTY
CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK AFTER CLEANING		
<input type="checkbox"/> CLEAN	<input checked="" type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input checked="" type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
ACCESS		MANHOLE	<input checked="" type="checkbox"/> COVERED	<input type="checkbox"/> DAMAGED	<input type="checkbox"/> NA
LADDER IN	LADDER OUT	LEAKS	DRAIN LINE	VALVES	FLOAT VALVE
<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO
TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> YES	<input type="checkbox"/> NO <input checked="" type="checkbox"/> NA
LAST CLEANING DATE		CURRENT CLEANING DATE		NEXT CLEANING DATE	
		<u>03/09/2018</u>		<u>03/03/2019</u>	
CHEMICALS & EQUIPMENTS USED					
1. <u>Cericho Bio Plus</u> Quantity <u>400 ML</u>					
2. _____ Quantity _____					
<input checked="" type="checkbox"/> Submersibel Pump	<input checked="" type="checkbox"/> High /Low Pressure jet	<input checked="" type="checkbox"/> Extension Cords	<input checked="" type="checkbox"/> LED Lights	<input checked="" type="checkbox"/> Foot Bath	<input checked="" type="checkbox"/> Ladder
<input checked="" type="checkbox"/> Ventilating Fan	<input checked="" type="checkbox"/> Suction/Discharge Hoses	<input checked="" type="checkbox"/> Oxygen Mater	<input checked="" type="checkbox"/> Vacuum Cleaner	<input checked="" type="checkbox"/> Cleaning Materials	
COMMENTS & RECOMMENDATIONS: <u>Above mentioned water tank are cleaned & Disinfected</u>					
Crystalline Representative: <u>Mustafa</u>			Signature: <u>mf</u>		

Date of Cleaning: 03-09-2018

PHOTOGRAPHS
ROOF TOP FRP FILTER TANK (A 02) – 01&02

BEFORE

FRP FILTER TANK-01



FRP FILTER TANK-02



AFTER





CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT

20151

CUSTOMER: SANA AIR			CONTACT PERSON: MR INDIRAN		
SITE DETAILS: KHALIFA COMPLEX ABU DHABI A-02			CONTACT NO: 0559838071		
TANK DETAILS: FIBER RAKE WATER 03			LOCATION DETAILS: ROOF TOP A-2		
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL		<input type="checkbox"/> RESIDENTIAL		<input type="checkbox"/> OTHERS	
TYPE OF TANK					
<input type="checkbox"/> CONCRETE	<input type="checkbox"/> GRP PANEL	<input type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED		<input type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS		
SIZE OF TANK			QUANTITY OF WATER		
M3	USG	L*B*H	<input type="checkbox"/> FULL	<input type="checkbox"/> HALF	<input type="checkbox"/> EMPTY
CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK AFTER CLEANING		
<input type="checkbox"/> CLEAN	<input checked="" type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input checked="" type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
ACCESS		MANHOLE		<input checked="" type="checkbox"/> COVERED	
<input type="checkbox"/> DAMAGED		<input type="checkbox"/> NA			
LADDER IN		LADDER OUT		LEAKS	
<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	
TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED	
<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO		<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO		<input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> NA	
LAST CLEANING DATE		CURRENT CLEANING DATE		NEXT CLEANING DATE	
		04/09/2018		04/09/2019	
CHEMICALS & EQUIPMENTS USED					
1. _____ Quantity _____					
2. _____ Quantity _____					
<input checked="" type="checkbox"/> Submersibel Pump <input checked="" type="checkbox"/> High /Low Pressure jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED Lights <input checked="" type="checkbox"/> Foot Bath <input checked="" type="checkbox"/> Ladder					
<input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Mater <input checked="" type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials					
COMMENTS & RECOMMENDATIONS: Above mentioned water tank are cleaned & Disinfected					
Crystalline Representative: Muhammad			Signature: [Signature]		



CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT

20152

CUSTOMER: <u>SANIA AIR.</u>			CONTACT PERSON: <u>MR MUDIRAN</u>		
SITE DETAILS: <u>KHALIFA COMPLY, ABU DHABI A-02</u>			CONTACT NO: <u>055 9 8 38 071</u>		
TANK DETAILS: <u>FIBER RAW. TANUN004</u>			LOCATION DETAILS: <u>ROOF TOP</u>		
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL <input type="checkbox"/> RESIDENTIAL <input type="checkbox"/> OTHERS					
TYPE OF TANK					
<input type="checkbox"/> CONCRETE	<input type="checkbox"/> GRP PANEL	<input type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED		<input type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS		
SIZE OF TANK			QUANTITY OF WATER		
M3	USG	L*B*H	<input type="checkbox"/> FULL	<input type="checkbox"/> HALF	<input type="checkbox"/> EMPTY
CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK AFTER CLEANING		
<input type="checkbox"/> CLEAN	<input checked="" type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input checked="" type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input checked="" type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
ACCESS		MANHOLE	<input checked="" type="checkbox"/> COVERED	<input type="checkbox"/> DAMAGED	<input type="checkbox"/> NA
LADDER IN	LADDER OUT	LEAKS	DRAIN LINE	VALVES	FLOAT VALVE
<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO
TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> YES	<input type="checkbox"/> NO <input checked="" type="checkbox"/> NA
LAST CLEANING DATE		CURRENT CLEANING DATE		NEXT CLEANING DATE	
		<u>04/09/2018</u>		<u>04/03/2019</u>	
CHEMICALS & EQUIPMENTS USED					
1. <u>Caulk Bio Phu</u> Quantity <u>400 ml</u>					
2. _____ Quantity _____					
<input checked="" type="checkbox"/> Submersibel Pump	<input checked="" type="checkbox"/> High /Low Pressure jet	<input type="checkbox"/> Extension Cords	<input type="checkbox"/> LED Lights	<input type="checkbox"/> Foot Bath	<input checked="" type="checkbox"/> Ladder
<input checked="" type="checkbox"/> Ventilating Fan	<input checked="" type="checkbox"/> Suction/Discharge Hoses	<input type="checkbox"/> Oxygen Mater	<input type="checkbox"/> Vacuum Cleaner	<input checked="" type="checkbox"/> Cleaning Materials	
COMMENTS & RECOMMENDATIONS: <u>Above mentioned water tanks are cleaned & Disinfected.</u>					
Crystalline Representative: <u>Mudir</u>			Signature: <u>[Signature]</u>		

Date of Cleaning: 04-09-2018

PHOTOGRAPHS
ROOF TOP FRP RAW TANK (A 02) – 03&04

BEFORE


FRP RAW TANK-03



FRP RAW TANK-04



AFTER





CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT

20153

CUSTOMER: SANA AIR.			CONTACT PERSON: MR INDIRANI		
SITE DETAILS: KHALIFA COMPLEX ABU DHABI A-03			CONTACT NO: 055 9838071		
TANK DETAILS: REC. RAW. WATER T. 01			LOCATION DETAILS: Under A Road		
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL <input type="checkbox"/> RESIDENTIAL <input type="checkbox"/> OTHERS					
TYPE OF TANK					
<input type="checkbox"/> CONCRETE	<input type="checkbox"/> GRP PANEL	<input type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED		<input type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS		
SIZE OF TANK			QUANTITY OF WATER		
M3	USG	L*B*H	<input type="checkbox"/> FULL	<input type="checkbox"/> HALF	<input type="checkbox"/> EMPTY
CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK AFTER CLEANING		
<input type="checkbox"/> CLEAN	<input checked="" type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input checked="" type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
ACCESS		MANHOLE	<input checked="" type="checkbox"/> COVERED	<input type="checkbox"/> DAMAGED	<input type="checkbox"/> NA
LADDER IN	LADDER OUT	LEAKS	DRAIN LINE	VALVES	FLOAT VALVE
<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO
TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> YES	<input type="checkbox"/> NO <input checked="" type="checkbox"/> NA
LAST CLEANING DATE		CURRENT CLEANING DATE		NEXT CLEANING DATE	
		05/09/2018.		05/03/2019.	
CHEMICALS & EQUIPMENTS USED					
1. Carub Bio Phu Quantity 1-002R.					
2. Quantity					
<input checked="" type="checkbox"/> Submersibel Pump	<input checked="" type="checkbox"/> High /Low Pressure jet	<input checked="" type="checkbox"/> Extension Cords	<input checked="" type="checkbox"/> LED Lights	<input checked="" type="checkbox"/> Foot Bath	<input checked="" type="checkbox"/> Ladder
<input checked="" type="checkbox"/> Ventilating Fan	<input checked="" type="checkbox"/> Suction/Discharge Hoses	<input checked="" type="checkbox"/> Oxygen Mater	<input checked="" type="checkbox"/> Vacuum Cleaner	<input checked="" type="checkbox"/> Cleaning Materials	
COMMENTS & RECOMMENDATIONS: Above mentioned water tank are cleaned & disinfected.					
Crystalline Representative: <i>Mustafa</i>			Signature: <i>Amir</i>		



CRYSTALLINE
ENVIRONMENTAL SERVICES

Date of Cleaning: 05-09-2018

PHOTOGRAPHS

UNDER GROUND RCC RAW WATER TANK (A 03) - 01

BEFORE



AFTER



CLEANER WATER GREENER TOMORROW



CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT

20154

CUSTOMER: <u>SANA AIR</u>			CONTACT PERSON: <u>MR INDIRAN</u>		
SITE DETAILS: <u>KHALIFA COMPLEX</u> <u>ABU DHABI A-03</u>			CONTACT NO: <u>0559838071</u>		
TANK DETAILS: <u>FIBER FILTER TANK No 01</u>			LOCATION DETAILS: <u>ROOF TOP</u>		
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL <input type="checkbox"/> RESIDENTIAL <input type="checkbox"/> OTHERS					
TYPE OF TANK					
<input type="checkbox"/> CONCRETE	<input type="checkbox"/> GRP PANEL	<input type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED		<input type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS		
SIZE OF TANK			QUANTITY OF WATER		
M3	USG	L*B*H	<input type="checkbox"/> FULL	<input type="checkbox"/> HALF	<input type="checkbox"/> EMPTY
CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK AFTER CLEANING		
<input type="checkbox"/> CLEAN	<input checked="" type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input checked="" type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
ACCESS		MANHOLE	<input checked="" type="checkbox"/> COVERED	<input type="checkbox"/> DAMAGED	<input type="checkbox"/> NA
LADDER IN	LADDER OUT	LEAKS	DRAIN LINE	VALVES	FLOAT VALVE
<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO
TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> YES	<input type="checkbox"/> NO <input checked="" type="checkbox"/> NA
LAST CLEANING DATE		CURRENT CLEANING DATE		NEXT CLEANING DATE	
		<u>05/09/2018</u>		<u>05/03/2019</u>	
CHEMICALS & EQUIPMENTS USED					
1. <u>Carbo Bio Plus</u> Quantity <u>400ml</u>					
2. _____ Quantity _____					
<input checked="" type="checkbox"/> Submersible Pump	<input checked="" type="checkbox"/> High/Low Pressure jet	<input checked="" type="checkbox"/> Extension Cords	<input checked="" type="checkbox"/> LED Lights	<input checked="" type="checkbox"/> Foot Bath	<input type="checkbox"/> Ladder
<input checked="" type="checkbox"/> Ventilating Fan	<input checked="" type="checkbox"/> Suction/Discharge Hoses	<input checked="" type="checkbox"/> Oxygen Meter	<input checked="" type="checkbox"/> Vacuum Cleaner	<input checked="" type="checkbox"/> Cleaning Materials	
COMMENTS & RECOMMENDATIONS: <u>Above mentioned water tank is cleaned & disinfected</u>					
Crystalline Representative: <u>Muski</u>			Signature: <u>[Signature]</u>		



CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT

20155

CUSTOMER: <u>SANA AIR</u>			CONTACT PERSON: <u>MR INDIRAN</u>		
SITE DETAILS: <u>KHALIFA COMPLEX, A-03</u> <u>ABUDHABI</u>			CONTACT NO: <u>055 9838071</u>		
TANK DETAILS: <u>FIBER FILTER TANK No 02</u>			LOCATION DETAILS: <u>ROOF TOP</u>		
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL <input type="checkbox"/> RESIDENTIAL <input type="checkbox"/> OTHERS					
TYPE OF TANK					
<input type="checkbox"/> CONCRETE	<input type="checkbox"/> GRP PANEL	<input type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED	<input type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS			
SIZE OF TANK			QUANTITY OF WATER		
M3	USG	L*B*H	<input type="checkbox"/> FULL	<input type="checkbox"/> HALF	<input type="checkbox"/> EMPTY
CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK AFTER CLEANING		
<input type="checkbox"/> CLEAN	<input checked="" type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input checked="" type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
ACCESS		MANHOLE	<input checked="" type="checkbox"/> COVERED	<input type="checkbox"/> DAMAGED	<input type="checkbox"/> NA
LADDER IN	LADDER OUT	LEAKS	DRAIN LINE	VALVES	FLOAT VALVE
<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO
TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> YES	<input type="checkbox"/> NO <input checked="" type="checkbox"/> NA
LAST CLEANING DATE		CURRENT CLEANING DATE		NEXT CLEANING DATE	
		<u>05/09/2018</u>		<u>05/03/2019</u>	
CHEMICALS & EQUIPMENTS USED					
1. <u>Carbo Bio Plus</u> Quantity <u>400ml</u>					
2. _____ Quantity _____					
<input checked="" type="checkbox"/> Submersibel Pump <input checked="" type="checkbox"/> High /Low Pressure jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED Lights <input checked="" type="checkbox"/> Foot Bath <input checked="" type="checkbox"/> Ladder					
<input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Mater <input checked="" type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials					
COMMENTS & RECOMMENDATIONS: <u>Above mentioned water Tank are cleaned & Disinfected</u>					
Crystalline Representative: <u>Muhammad</u>			Signature: <u>[Signature]</u>		

Date of Cleaning: 05-09-2018

PHOTOGRAPHS
ROOF TOP FRP FILTER TANK (A 03)-01&02

BEFORE

FRP FILTER TANK-01



FRP FILTER TANK-02



AFTER





CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT

20156

CUSTOMER: <u>SANA AIR</u>			CONTACT PERSON: <u>MR INDIRAN</u>		
SITE DETAILS: <u>KHALIFA COMPLEX</u> <u>ABU DHABI A03.</u>			CONTACT NO: <u>0559838071,</u>		
TANK DETAILS: <u>FIBER RAW TANK NO03</u>			LOCATION DETAILS: <u>ROOF TOP.</u>		
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL <input type="checkbox"/> RESIDENTIAL <input type="checkbox"/> OTHERS					
TYPE OF TANK					
<input type="checkbox"/> CONCRETE	<input type="checkbox"/> GRP PANEL	<input type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED	<input type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS			
SIZE OF TANK			QUANTITY OF WATER		
M3	USG	L*B*H	<input type="checkbox"/> FULL	<input type="checkbox"/> HALF	<input type="checkbox"/> EMPTY
CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK AFTER CLEANING		
<input type="checkbox"/> CLEAN	<input checked="" type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input checked="" type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
ACCESS		MANHOLE	<input checked="" type="checkbox"/> COVERED	<input type="checkbox"/> DAMAGED	<input type="checkbox"/> NA
LADDER IN	LADDER OUT	LEAKS	DRAIN LINE	VALVES	FLOAT VALVE
<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO
TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> YES	<input type="checkbox"/> NO <input checked="" type="checkbox"/> NA
LAST CLEANING DATE		CURRENT CLEANING DATE		NEXT CLEANING DATE	
		<u>06/09/2018.</u>		<u>09/03/2019</u>	
CHEMICALS & EQUIPMENTS USED					
1. <u>Carbo Bio Plus</u> . Quantity <u>400ml</u>					
2. _____ Quantity _____					
<input checked="" type="checkbox"/> Submersibel Pump <input checked="" type="checkbox"/> High /Low Pressure jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED Lights <input checked="" type="checkbox"/> Foot Bath <input checked="" type="checkbox"/> Ladder					
<input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Mater <input checked="" type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials					
COMMENTS & RECOMMENDATIONS: <u>Above mentioned water tank as cleaned & Disinfected</u>					
Crystalline Representative: <u>Mushtaq</u>			Signature: <u>[Signature]</u>		



CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT

20157


CUSTOMER: <u>SANA AIR.</u>			CONTACT PERSON: <u>MR INDIRAN</u>		
SITE DETAILS: <u>KHALIFA COMPLEX ABU DHABI A-03.</u>			CONTACT NO: <u>055 9838071.</u>		
TANK DETAILS: <u>FIBER RAW TOWER</u>			LOCATION DETAILS: <u>ROOF TOP.</u>		
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL <input type="checkbox"/> RESIDENTIAL <input type="checkbox"/> OTHERS					
TYPE OF TANK					
<input type="checkbox"/> CONCRETE	<input type="checkbox"/> GRP PANEL	<input type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED		<input type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS		
SIZE OF TANK			QUANTITY OF WATER		
M3	USG	L*B*H	<input type="checkbox"/> FULL	<input type="checkbox"/> HALF	<input type="checkbox"/> EMPTY
CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK AFTER CLEANING		
<input checked="" type="checkbox"/> CLEAN	<input checked="" type="checkbox"/> DIRTY	<input checked="" type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input checked="" type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
ACCESS		MANHOLE		<input checked="" type="checkbox"/> COVERED	<input type="checkbox"/> DAMAGED <input type="checkbox"/> NA
LADDER IN		LADDER OUT		FLOAT VALVE	
<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO
TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> NA	
LAST CLEANING DATE		CURRENT CLEANING DATE		NEXT CLEANING DATE	
		<u>06/09/2018</u>		<u>06/03/2019.</u>	
CHEMICALS & EQUIPMENTS USED					
1. <u>Carbo Bio Plus</u> Quantity <u>400ml</u>					
2. _____ Quantity _____					
<input checked="" type="checkbox"/> Submersible Pump <input checked="" type="checkbox"/> High/Low Pressure jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED Lights <input checked="" type="checkbox"/> Foot Bath <input checked="" type="checkbox"/> Ladder <input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Meter <input checked="" type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials					
COMMENTS & RECOMMENDATIONS: <u>Above mentioned water tank are cleaned & disinfected</u>					
Crystalline Representative: <u>Mustafa</u>			Signature: <u>[Signature]</u>		

Date of Cleaning: 06-09-2018

PHOTOGRAPHS
ROOF TOP FRP RAW WATER TANK (A 03)-03&04

BEFORE


FRP RAW WATER TANK-03



FRP RAW WATER TANK-04



AFTER





CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT


12885

CUSTOMER: <i>Sanad</i>			CONTACT PERSON: <i>Ms. Indhu</i>		
SITE DETAILS: <i>Khalifa Complex A-4 Abu Dhabi</i>			CONTACT NO: <i>0559838071</i>		
TANK DETAILS: <i>RCC water Tank</i>			LOCATION DETAILS: <i>Under Ground</i>		
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL		<input type="checkbox"/> RESIDENTIAL		<input type="checkbox"/> OTHERS	
TYPE OF TANK					
<input checked="" type="checkbox"/> CONCRETE	<input type="checkbox"/> GRP PANEL	<input type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED		<input type="checkbox"/> POLYURETHANE		<input type="checkbox"/> OTHERS	
SIZE OF TANK			QUANTITY OF WATER		
M3	USG	L*B*H	<input type="checkbox"/> FULL	<input type="checkbox"/> HALF	<input type="checkbox"/> EMPTY
CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK AFTER CLEANING		
<input type="checkbox"/> CLEAN	<input checked="" type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input checked="" type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
ACCESS		MANHOLE		<input checked="" type="checkbox"/> COVERED	
<input type="checkbox"/> DAMAGED		<input type="checkbox"/> NA			
LADDER IN		LADDER OUT		LEAKS	
DRAIN LINE		VALVES		FLOAT VALVE	
<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO
TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> YES	<input type="checkbox"/> NO
<input checked="" type="checkbox"/> NA					
LAST CLEANING DATE		CURRENT CLEANING DATE		NEXT CLEANING DATE	
		<i>26/06/2018</i>		<i>26/02/2018</i>	
CHEMICALS & EQUIPMENTS USED					
1. <i>Carilo bio Plus</i> Quantity <i>1 Ltr.</i>					
2. _____ Quantity _____					
<input checked="" type="checkbox"/> Submersibel Pump <input type="checkbox"/> High/Low Pressure Jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED lights <input type="checkbox"/> Foot Bath <input type="checkbox"/> Ladder					
<input checked="" type="checkbox"/> Ventilating Fan <input type="checkbox"/> Suction/Discharge Hoses <input type="checkbox"/> Oxygen Meter <input type="checkbox"/> Vacuum Cleaner <input type="checkbox"/> Cleaning Materials					
COMMENTS & RECOMMENDATIONS:					
<i>Above mentioned water tank is successfully cleaned and disinfected</i>					
Crystalline Representative: <i>Tasim Sherajuddin</i>			Signature: <i>Tasim</i>		


Date of Cleaning: 26-06-2018

PHOTOGRAPHS
UNDER GROUND RCC WATER TANK (A 04) – 01

BEFORE



AFTER





CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT

15367

CUSTOMER: <i>Sarai</i>			CONTACT PERSON: <i>ms:- indhara</i>		
SITE DETAILS: <i>Khalifa Complex - 174 Abu Dhabi</i>			CONTACT NO: <i>0559838071</i>		
TANK DETAILS: <i>F.R.P. Domestic tank no: 01</i>			LOCATION DETAILS: <i>roof top</i>		
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL		<input type="checkbox"/> RESIDENTIAL		<input type="checkbox"/> OTHERS	
TYPE OF TANK					
<input type="checkbox"/> CONCRETE	<input type="checkbox"/> GRP PANEL	<input checked="" type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED		<input type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS		
SIZE OF TANK			QUANTITY OF WATER		
M3	USG	L*B*H	<input type="checkbox"/> FULL	<input type="checkbox"/> HALF	<input type="checkbox"/> EMPTY
CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK AFTER CLEANING		
<input type="checkbox"/> CLEAN	<input checked="" type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input checked="" type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
ACCESS		MANHOLE		<input checked="" type="checkbox"/> COVERED	<input type="checkbox"/> DAMAGED
<input type="checkbox"/> NA	<input type="checkbox"/> NA			<input type="checkbox"/> NA	<input type="checkbox"/> NA
LADDER IN		LADDER OUT		LEAKS	
<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO
TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> YES	<input type="checkbox"/> NO
LAST CLEANING DATE		CURRENT CLEANING DATE		NEXT CLEANING DATE	
		<i>27/06/2018</i>		<i>27/12/2018</i>	
CHEMICALS & EQUIPMENTS USED					
1. <i>Carite bio plus</i> Quantity <i>250 ml</i>					
2. _____ Quantity _____					
<input checked="" type="checkbox"/> Submersibel Pump <input checked="" type="checkbox"/> High/Low Pressure Jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED lights <input type="checkbox"/> Foot Bath <input checked="" type="checkbox"/> Ladder <input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Meter <input checked="" type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials					
COMMENTS & RECOMMENDATIONS:					
<i>Above mentioned water tank are successfully cleaned and disinfected.</i>					
Crystalline Representative: <i>Sasir Shergudon</i>			Signature: <i>[Signature]</i>		



CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT

15368

CUSTOMER: <i>Sarair</i>			CONTACT PERSON: <i>Mrs. - Vidya</i>		
SITE DETAILS: <i>Khalifa Complex - A-4 Abul Dhabi</i>			CONTACT NO: <i>055 9838071</i>		
TANK DETAILS: <i>F.R.P. Domestic Tank no:-02</i>			LOCATION DETAILS: <i>roof top</i>		
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL		<input type="checkbox"/> RESIDENTIAL		<input type="checkbox"/> OTHERS	
TYPE OF TANK					
<input type="checkbox"/> CONCRETE	<input type="checkbox"/> GRP PANEL	<input checked="" type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED		<input type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS		
SIZE OF TANK			QUANTITY OF WATER		
M3	USG	L*B*H	<input type="checkbox"/> FULL	<input type="checkbox"/> HALF	<input type="checkbox"/> EMPTY
CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK AFTER CLEANING		
<input type="checkbox"/> CLEAN	<input checked="" type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input checked="" type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
ACCESS		MANHOLE		<input checked="" type="checkbox"/> COVERED	<input type="checkbox"/> DAMAGED
<input type="checkbox"/> NA	<input type="checkbox"/> NA			<input type="checkbox"/> NA	<input type="checkbox"/> NA
LADDER IN		LADDER OUT		LEAKS	
<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO
TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> YES	<input type="checkbox"/> NO
LAST CLEANING DATE		CURRENT CLEANING DATE		NEXT CLEANING DATE	
		<i>27/06/2018</i>		<i>27/12/2018</i>	
CHEMICALS & EQUIPMENTS USED					
1. <i>Casibo bio plus</i> Quantity <i>250 ml</i>					
2. _____ Quantity _____					
<input checked="" type="checkbox"/> Submersibel Pump <input checked="" type="checkbox"/> High/Low Pressure Jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED lights <input checked="" type="checkbox"/> Foot Bath <input checked="" type="checkbox"/> Ladder <input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Meter <input checked="" type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials					
COMMENTS & RECOMMENDATIONS:					
<i>Above mentioned water tank are successfully cleaned and disinfected.</i>					
Crystalline Representative: <i>Jasin Shengudasa</i>			Signature: <i>Jasin</i>		

Date of Cleaning: 27-06-2018


PHOTOGRAPHS
ROOF TOP FRP WATER TANK (A 04) – 01&02

BEFORE

FRP WATER TANK-01



FRP WATER TANK-02



AFTER





CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT

15369

CUSTOMER: <i>Sarair</i>			CONTACT PERSON: <i>Ms:- Vidhwan</i>		
SITE DETAILS: <i>Khalifa Complex A-5 Abu Dhabi</i>			CONTACT NO: <i>0559838071</i>		
TANK DETAILS: <i>R.C.C. water tank no:-01</i>			LOCATION DETAILS: <i>under ground</i>		
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL		<input type="checkbox"/> RESIDENTIAL		<input type="checkbox"/> OTHERS	
TYPE OF TANK					
<input checked="" type="checkbox"/> CONCRETE	<input type="checkbox"/> GRP PANEL	<input type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED		<input type="checkbox"/> POLYURETHANE		<input type="checkbox"/> OTHERS	
SIZE OF TANK			QUANTITY OF WATER		
M3	USG	L*B*H	<input type="checkbox"/> FULL	<input type="checkbox"/> HALF	<input type="checkbox"/> EMPTY
CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK AFTER CLEANING		
<input type="checkbox"/> CLEAN	<input checked="" type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input checked="" type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
ACCESS		MANHOLE		<input checked="" type="checkbox"/> COVERED	<input type="checkbox"/> DAMAGED
<input type="checkbox"/> NA	<input type="checkbox"/> NA			<input type="checkbox"/> NA	<input type="checkbox"/> NA
LADDER IN		LADDER OUT		LEAKS	
<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO
DRAIN LINE		VALVES		FLOAT VALVE	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO
TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> YES	<input type="checkbox"/> NO
LAST CLEANING DATE		CURRENT CLEANING DATE		NEXT CLEANING DATE	
		<i>28/06/2018</i>		<i>28/12/2018</i>	
CHEMICALS & EQUIPMENTS USED					
1. <i>Carito bio plus</i> Quantity <i>500 ml</i>					
2. _____ Quantity _____					
<input checked="" type="checkbox"/> Submersibel Pump <input checked="" type="checkbox"/> High/Low Pressure Jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED lights <input checked="" type="checkbox"/> Foot Bath <input checked="" type="checkbox"/> Ladder <input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Meter <input checked="" type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials					
COMMENTS & RECOMMENDATIONS:					
<i>Above mentioned water tank are successfully cleaned and disinfected</i>					
Crystalline Representative: <i>Jasir Sharafudeen</i>			Signature: <i>Jasir</i>		




CRYSTALLINE
ENVIRONMENTAL SERVICES


Date of Cleaning: 28-06-2018

PHOTOGRAPHS
UNDER GROUND RCC WATER TANK (A 05) - 01

BEFORE



AFTER



CLEANER WATER GREENER TOMORROW



CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT

15370

CUSTOMER: <i>Sanaiz</i>			CONTACT PERSON: <i>Ms. Vidhara</i>		
SITE DETAILS: <i>Khalifa Complex A-5 Abu Dhabi</i>			CONTACT NO: <i>0559838071</i>		
TANK DETAILS: <i>F.R.P. filter tank no.-01</i>			LOCATION DETAILS: <i>roof top</i>		
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL		<input type="checkbox"/> RESIDENTIAL		<input type="checkbox"/> OTHERS	
TYPE OF TANK					
<input type="checkbox"/> CONCRETE	<input type="checkbox"/> GRP PANEL	<input checked="" type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED		<input type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS		
SIZE OF TANK			QUANTITY OF WATER		
M3	USG	L*B*H	<input type="checkbox"/> FULL	<input type="checkbox"/> HALF	<input type="checkbox"/> EMPTY
CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK AFTER CLEANING		
<input type="checkbox"/> CLEAN	<input checked="" type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input checked="" type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
ACCESS		MANHOLE		<input checked="" type="checkbox"/> COVERED	
<input type="checkbox"/> DAMAGED		<input type="checkbox"/> NA			
LADDER IN		LADDER OUT		LEAKS	
<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO
DRAIN LINE		VALVES		FLOAT VALVE	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO
TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> YES	<input type="checkbox"/> NO <input checked="" type="checkbox"/> NA
LAST CLEANING DATE		CURRENT CLEANING DATE		NEXT CLEANING DATE	
		<i>28/06/2018</i>		<i>28/12/2018</i>	
CHEMICALS & EQUIPMENTS USED					
1. <i>Carito bio plus</i> Quantity <i>250 ml</i>					
2. _____ Quantity _____					
<input checked="" type="checkbox"/> Submersibel Pump <input checked="" type="checkbox"/> High/Low Pressure Jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED lights <input checked="" type="checkbox"/> Foot Bath <input checked="" type="checkbox"/> Ladder <input checked="" type="checkbox"/> Ventilating Fan <input type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Meter <input checked="" type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials					
COMMENTS & RECOMMENDATIONS:					
<i>Above mentioned water tank are successfully cleared and disinfected.</i>					
Crystalline Representative: <i>Jasim Shamsudeen</i>			Signature: <i>Jasim</i>		



CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT

15371

CUSTOMER: <i>Sarai's</i>			CONTACT PERSON: <i>Ms:- Vidhara</i>		
SITE DETAILS: <i>Khalifa Complex A-5 Abu Dhabi</i>			CONTACT NO: <i>0559838071</i>		
TANK DETAILS: <i>F.R.P. filter tank no:-02</i>			LOCATION DETAILS: <i>roof top</i>		
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL		<input type="checkbox"/> RESIDENTIAL		<input type="checkbox"/> OTHERS	
TYPE OF TANK					
<input type="checkbox"/> CONCRETE	<input type="checkbox"/> GRP PANEL	<input checked="" type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED		<input type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS		
SIZE OF TANK			QUANTITY OF WATER		
M3	USG	L*B*H	<input type="checkbox"/> FULL	<input type="checkbox"/> HALF	<input type="checkbox"/> EMPTY
CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK AFTER CLEANING		
<input type="checkbox"/> CLEAN	<input checked="" type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input checked="" type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
ACCESS		MANHOLE		<input checked="" type="checkbox"/> COVERED	<input type="checkbox"/> DAMAGED
				<input type="checkbox"/> NA	
LADDER IN		LADDER OUT		LEAKS	
<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO
DRAIN LINE		VALVES		FLOAT VALVE	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO
TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> YES	<input type="checkbox"/> NO <input checked="" type="checkbox"/> NA
LAST CLEANING DATE		CURRENT CLEANING DATE		NEXT CLEANING DATE	
		<i>28/06/2018</i>		<i>28/12/2018</i>	
CHEMICALS & EQUIPMENTS USED					
1. <i>Caribo bio plus</i> Quantity <i>250 ml</i>					
2. _____ Quantity _____					
<input checked="" type="checkbox"/> Submersibel Pump <input checked="" type="checkbox"/> High/Low Pressure Jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED lights <input type="checkbox"/> Foot Bath <input checked="" type="checkbox"/> Ladder <input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Suction/Discharge Hoses <input type="checkbox"/> Oxygen Meter <input checked="" type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials					
COMMENTS & RECOMMENDATIONS:					
<i>Above mentioned water tank are successfully cleaned and disinfected</i>					
Crystalline Representative: <i>Susir Sharafudeen</i>			Signature: <i>Susir</i>		

Date of Cleaning: 28-06-2018

PHOTOGRAPHS
ROOF TOP FRP FILTER TANK (A 05) – 01&02

BEFORE

FRP FILTER TANK-01



FRP FILTER TANK-02



AFTER





CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT

15372

CUSTOMER: <i>Sarais</i>			CONTACT PERSON: <i>Ms. Vidhwan</i>		
SITE DETAILS: <i>Khalifa Complex A-5 Abu Dhabi</i>			CONTACT NO: <i>0559838071</i>		
TANK DETAILS: <i>F.R.P. Domestic tank no. 03</i>			LOCATION DETAILS: <i>roof top</i>		
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL		<input type="checkbox"/> RESIDENTIAL		<input type="checkbox"/> OTHERS	
TYPE OF TANK					
<input type="checkbox"/> CONCRETE	<input type="checkbox"/> GRP PANEL	<input checked="" type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED		<input type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS		
SIZE OF TANK			QUANTITY OF WATER		
M3	USG	L*B*H	<input type="checkbox"/> FULL	<input type="checkbox"/> HALF	<input type="checkbox"/> EMPTY
CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK AFTER CLEANING		
<input type="checkbox"/> CLEAN	<input checked="" type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input checked="" type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
ACCESS		MANHOLE		<input checked="" type="checkbox"/> COVERED	<input type="checkbox"/> DAMAGED <input type="checkbox"/> NA
LADDER IN		LADDER OUT		LEAKS	
<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	DRAIN LINE	
TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED	
<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES <input type="checkbox"/> NO	<input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> NA	
LAST CLEANING DATE		CURRENT CLEANING DATE		NEXT CLEANING DATE	
		<i>30/06/2018</i>		<i>30/12/2018</i>	
CHEMICALS & EQUIPMENTS USED					
1. <i>Carite bio plus</i> Quantity <i>250 ml</i>					
2. _____ Quantity _____					
<input checked="" type="checkbox"/> Submersibel Pump <input checked="" type="checkbox"/> High/Low Pressure Jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED lights <input checked="" type="checkbox"/> Foot Bath <input checked="" type="checkbox"/> Ladder <input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Meter <input checked="" type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials					
COMMENTS & RECOMMENDATIONS:					
<i>Above mentioned water tank are successfully cleared and disinfected.</i>					
Crystalline Representative: <i>Sasir Shorofuder</i>			Signature: <i>[Signature]</i>		



CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT

15373


CUSTOMER: <i>Sarais</i>			CONTACT PERSON: <i>ms:- vidhwa</i>		
SITE DETAILS: <i>Khodifa Complex A-5 Abu Dhabi</i>			CONTACT NO: <i>0559838071</i>		
TANK DETAILS: <i>F.R.P Domestic Tank no-02</i>			LOCATION DETAILS: <i>Roof top</i>		
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL		<input type="checkbox"/> RESIDENTIAL		<input type="checkbox"/> OTHERS	
TYPE OF TANK					
<input type="checkbox"/> CONCRETE	<input type="checkbox"/> GRP PANEL	<input checked="" type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED		<input type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS		
SIZE OF TANK			QUANTITY OF WATER		
M3	USG	L*B*H	<input type="checkbox"/> FULL	<input type="checkbox"/> HALF	<input type="checkbox"/> EMPTY
CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK AFTER CLEANING		
<input type="checkbox"/> CLEAN	<input checked="" type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input checked="" type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
ACCESS		MANHOLE		<input checked="" type="checkbox"/> COVERED	<input type="checkbox"/> DAMAGED
				<input type="checkbox"/> NA	
LADDER IN		LADDER OUT		LEAKS	
<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO
DRAIN LINE		VALVES		FLOAT VALVE	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO
TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> YES	<input type="checkbox"/> NO
				<input checked="" type="checkbox"/> NA	
LAST CLEANING DATE		CURRENT CLEANING DATE		NEXT CLEANING DATE	
		<i>30/06/2018</i>		<i>30/12/2018</i>	
CHEMICALS & EQUIPMENTS USED					
1. <i>Carite bio plus</i> Quantity <i>250 ml</i>					
2. _____ Quantity _____					
<input checked="" type="checkbox"/> Submersibel Pump <input checked="" type="checkbox"/> High/Low Pressure Jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED lights <input checked="" type="checkbox"/> Foot Bath <input checked="" type="checkbox"/> Ladder					
<input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Meter <input checked="" type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials					
COMMENTS & RECOMMENDATIONS:					
<i>Above mentioned water tank are successfully cleaned and disinfected.</i>					
Crystalline Representative: <i>Sajid Sharafudeen</i>			Signature: <i>Sajid</i>		

Date of Cleaning: 30-06-2018


PHOTOGRAPHS
ROOF TOP FRP FILTER TANK (A 05) – 03&04

BEFORE

FRP FILTER TANK-03



FRP FILTER TANK-04



AFTER





CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT

15374

CUSTOMER: <i>Sarair</i>			CONTACT PERSON: <i>Ms:- Vidhana</i>		
SITE DETAILS: <i>Khalifa Complex A-6 Abu Dhabi</i>			CONTACT NO: <i>0559838071</i>		
TANK DETAILS: <i>R.C.C. water tank no:- 01</i>			LOCATION DETAILS: <i>under ground</i>		
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL		<input type="checkbox"/> RESIDENTIAL		<input type="checkbox"/> OTHERS	
TYPE OF TANK					
<input checked="" type="checkbox"/> CONCRETE	<input type="checkbox"/> GRP PANEL	<input type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED		<input type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS		
SIZE OF TANK			QUANTITY OF WATER		
M3	USG	L*B*H	<input type="checkbox"/> FULL	<input type="checkbox"/> HALF	<input type="checkbox"/> EMPTY
CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK AFTER CLEANING		
<input type="checkbox"/> CLEAN	<input checked="" type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input checked="" type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
ACCESS		MANHOLE		<input checked="" type="checkbox"/> COVERED	<input type="checkbox"/> DAMAGED
<input type="checkbox"/> YES		<input type="checkbox"/> YES		<input type="checkbox"/> NA	<input type="checkbox"/> NA
<input checked="" type="checkbox"/> NO		<input checked="" type="checkbox"/> NO		<input type="checkbox"/> YES	<input type="checkbox"/> NO
<input type="checkbox"/> YES		<input checked="" type="checkbox"/> NO		<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO
<input checked="" type="checkbox"/> NO		<input type="checkbox"/> YES		<input type="checkbox"/> YES	<input type="checkbox"/> NO
<input type="checkbox"/> YES		<input type="checkbox"/> YES		<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO
<input type="checkbox"/> NO		<input type="checkbox"/> NO		<input type="checkbox"/> YES	<input type="checkbox"/> NO
<input checked="" type="checkbox"/> YES		<input checked="" type="checkbox"/> YES		<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NA
<input type="checkbox"/> NO		<input type="checkbox"/> NO		<input type="checkbox"/> NO	<input type="checkbox"/> NA
<input checked="" type="checkbox"/> YES		<input type="checkbox"/> YES		<input type="checkbox"/> YES	<input type="checkbox"/> NO
<input type="checkbox"/> NO		<input type="checkbox"/> NO		<input type="checkbox"/> NO	<input type="checkbox"/> NA
<input checked="" type="checkbox"/> YES		<input type="checkbox"/> YES		<input type="checkbox"/> YES	<input type="checkbox"/> NO
<input type="checkbox"/> NO		<input type="checkbox"/> NO		<input type="checkbox"/> NO	<input type="checkbox"/> NA
<input checked="" type="checkbox"/> YES		<input type="checkbox"/> YES		<input type="checkbox"/> YES	<input type="checkbox"/> NO
<input type="checkbox"/> NO		<input type="checkbox"/> NO		<input type="checkbox"/> NO	<input type="checkbox"/> NA
<input checked="" type="checkbox"/> YES		<input type="checkbox"/> YES		<input type="checkbox"/> YES	<input type="checkbox"/> NO
<input type="checkbox"/> NO		<input type="checkbox"/> NO		<input type="checkbox"/> NO	<input type="checkbox"/> NA
<input checked="" type="checkbox"/> YES		<input type="checkbox"/> YES		<input type="checkbox"/> YES	<input type="checkbox"/> NO
<input type="checkbox"/> NO		<input type="checkbox"/> NO		<input type="checkbox"/> NO	<input type="checkbox"/> NA
<input checked="" type="checkbox"/> YES		<input type="checkbox"/> YES		<input type="checkbox"/> YES	<input type="checkbox"/> NO
<input type="checkbox"/> NO		<input type="checkbox"/> NO		<input type="checkbox"/> NO	<input type="checkbox"/> NA
<input checked="" type="checkbox"/> YES		<input type="checkbox"/> YES		<input type="checkbox"/> YES	<input type="checkbox"/> NO
<input type="checkbox"/> NO		<input type="checkbox"/> NO		<input type="checkbox"/> NO	<input type="checkbox"/> NA
<input checked="" type="checkbox"/> YES		<input type="checkbox"/> YES		<input type="checkbox"/> YES	<input type="checkbox"/> NO
<input type="checkbox"/> NO		<input type="checkbox"/> NO		<input type="checkbox"/> NO	<input type="checkbox"/> NA
<input checked="" type="checkbox"/> YES		<input type="checkbox"/> YES		<input type="checkbox"/> YES	<input type="checkbox"/> NO
<input type="checkbox"/> NO		<input type="checkbox"/> NO		<input type="checkbox"/> NO	<input type="checkbox"/> NA
<input checked="" type="checkbox"/> YES		<input type="checkbox"/> YES		<input type="checkbox"/> YES	<input type="checkbox"/> NO
<input type="checkbox"/> NO		<input type="checkbox"/> NO		<input type="checkbox"/> NO	<input type="checkbox"/> NA
<input checked="" type="checkbox"/> YES		<input type="checkbox"/> YES		<input type="checkbox"/> YES	<input type="checkbox"/> NO
<input type="checkbox"/> NO		<input type="checkbox"/> NO		<input type="checkbox"/> NO	<input type="checkbox"/> NA
<input checked="" type="checkbox"/> YES		<input type="checkbox"/> YES		<input type="checkbox"/> YES	<input type="checkbox"/> NO
<input type="checkbox"/> NO		<input type="checkbox"/> NO		<input type="checkbox"/> NO	<input type="checkbox"/> NA
<input checked="" type="checkbox"/> YES		<input type="checkbox"/> YES		<input type="checkbox"/> YES	<input type="checkbox"/> NO
<input type="checkbox"/> NO		<input type="checkbox"/> NO		<input type="checkbox"/> NO	<input type="checkbox"/> NA
<input checked="" type="checkbox"/> YES		<input type="checkbox"/> YES		<input type="checkbox"/> YES	<input type="checkbox"/> NO
<input type="checkbox"/> NO		<input type="checkbox"/> NO		<input type="checkbox"/> NO	<input type="checkbox"/> NA
<input checked="" type="checkbox"/> YES		<input type="checkbox"/> YES		<input type="checkbox"/> YES	<input type="checkbox"/> NO
<input type="checkbox"/> NO		<input type="checkbox"/> NO		<input type="checkbox"/> NO	<input type="checkbox"/> NA
<input checked="" type="checkbox"/> YES		<input type="checkbox"/> YES		<input type="checkbox"/> YES	<input type="checkbox"/> NO
<input type="checkbox"/> NO		<input type="checkbox"/> NO		<input type="checkbox"/> NO	<input type="checkbox"/> NA
<input checked="" type="checkbox"/> YES		<input type="checkbox"/> YES		<input type="checkbox"/> YES	<input type="checkbox"/> NO
<input type="checkbox"/> NO		<input type="checkbox"/> NO		<input type="checkbox"/> NO	<input type="checkbox"/> NA
<input checked="" type="checkbox"/> YES		<input type="checkbox"/> YES		<input type="checkbox"/> YES	<input type="checkbox"/> NO
<input type="checkbox"/> NO		<input type="checkbox"/> NO		<input type="checkbox"/> NO	<input type="checkbox"/> NA
<input checked="" type="checkbox"/> YES		<input type="checkbox"/> YES		<input type="checkbox"/> YES	<input type="checkbox"/> NO
<input type="checkbox"/> NO		<input type="checkbox"/> NO		<input type="checkbox"/> NO	<input type="checkbox"/> NA
<input checked="" type="checkbox"/> YES		<input type="checkbox"/> YES		<input type="checkbox"/> YES	<input type="checkbox"/> NO
<input type="checkbox"/> NO		<input type="checkbox"/> NO		<input type="checkbox"/> NO	<input type="checkbox"/> NA
<input checked="" type="checkbox"/> YES		<input type="checkbox"/> YES		<input type="checkbox"/> YES	<input type="checkbox"/> NO
<input type="checkbox"/> NO		<input type="checkbox"/> NO		<input type="checkbox"/> NO	<input type="checkbox"/> NA
<input checked="" type="checkbox"/> YES		<input type="checkbox"/> YES		<input type="checkbox"/> YES	<input type="checkbox"/> NO
<input type="checkbox"/> NO		<input type="checkbox"/> NO		<input type="checkbox"/> NO	<input type="checkbox"/> NA
<input checked="" type="checkbox"/> YES		<input type="checkbox"/> YES		<input type="checkbox"/> YES	<input type="checkbox"/> NO
<input type="checkbox"/> NO		<input type="checkbox"/> NO		<input type="checkbox"/> NO	<input type="checkbox"/> NA
<input checked="" type="checkbox"/> YES		<input type="checkbox"/> YES		<input type="checkbox"/> YES	<input type="checkbox"/> NO
<input type="checkbox"/> NO		<input type="checkbox"/> NO		<input type="checkbox"/> NO	<input type="checkbox"/> NA
<input checked="" type="checkbox"/> YES		<input type="checkbox"/> YES		<input type="checkbox"/> YES	<input type="checkbox"/> NO
<input type="checkbox"/> NO		<input type="checkbox"/> NO		<input type="checkbox"/> NO	<input type="checkbox"/> NA
<input checked="" type="checkbox"/> YES		<input type="checkbox"/> YES		<input type="checkbox"/> YES	<input type="checkbox"/> NO
<input type="checkbox"/> NO		<input type="checkbox"/> NO		<input type="checkbox"/> NO	<input type="checkbox"/> NA
<input checked="" type="checkbox"/> YES		<input type="checkbox"/> YES		<input type="checkbox"/> YES	<input type="checkbox"/> NO
<input type="checkbox"/> NO		<input type="checkbox"/> NO		<input type="checkbox"/> NO	<input type="checkbox"/> NA
<input checked="" type="checkbox"/> YES		<input type="checkbox"/> YES		<input type="checkbox"/> YES	<input type="checkbox"/> NO
<input type="checkbox"/> NO		<input type="checkbox"/> NO		<input type="checkbox"/> NO	<input type="checkbox"/> NA
<input checked="" type="checkbox"/> YES		<input type="checkbox"/> YES		<input type="checkbox"/> YES	<input type="checkbox"/> NO
<input type="checkbox"/> NO		<input type="checkbox"/> NO		<input type="checkbox"/> NO	<input type="checkbox"/> NA
<input checked="" type="checkbox"/> YES		<input type="checkbox"/> YES		<input type="checkbox"/> YES	<input type="checkbox"/> NO
<input type="checkbox"/> NO		<input type="checkbox"/> NO		<input type="checkbox"/> NO	<input type="checkbox"/> NA
<input checked="" type="checkbox"/> YES		<input type="checkbox"/> YES		<input type="checkbox"/> YES	<input type="checkbox"/> NO
<input type="checkbox"/> NO		<input type="checkbox"/> NO		<input type="checkbox"/> NO	<input type="checkbox"/> NA
<input checked="" type="checkbox"/> YES		<input type="checkbox"/> YES		<input type="checkbox"/> YES	<input type="checkbox"/> NO
<input type="checkbox"/> NO		<input type="checkbox"/> NO		<input type="checkbox"/> NO	<input type="checkbox"/> NA
<input checked="" type="checkbox"/> YES		<input type="checkbox"/> YES		<input type="checkbox"/> YES	<input type="checkbox"/> NO
<input type="checkbox"/> NO		<input type="checkbox"/> NO		<input type="checkbox"/> NO	<input type="checkbox"/> NA
<input checked="" type="checkbox"/> YES		<input type="checkbox"/> YES		<input type="checkbox"/> YES	<input type="checkbox"/> NO
<input type="checkbox"/> NO		<input type="checkbox"/> NO		<input type="checkbox"/> NO	<input type="checkbox"/> NA
<input checked="" type="checkbox"/> YES		<input type="checkbox"/> YES		<input type="checkbox"/> YES	<input type="checkbox"/> NO
<input type="checkbox"/> NO		<input type="checkbox"/> NO		<input type="checkbox"/> NO	<input type="checkbox"/> NA
<input checked="" type="checkbox"/> YES		<input type="checkbox"/> YES		<input type="checkbox"/> YES	<input type="checkbox"/> NO
<input type="checkbox"/> NO		<input type="checkbox"/> NO		<input type="checkbox"/> NO	<input type="checkbox"/> NA
<input checked="" type="checkbox"/> YES		<input type="checkbox"/> YES		<input type="checkbox"/> YES	<input type="checkbox"/> NO
<input type="checkbox"/> NO		<input type="checkbox"/> NO		<input type="checkbox"/> NO	<input type="checkbox"/> NA
<input checked="" type="checkbox"/> YES		<input type="checkbox"/> YES		<input type="checkbox"/> YES	<input type="checkbox"/> NO
<input type="checkbox"/> NO		<input type="checkbox"/> NO		<input type="checkbox"/> NO	<input type="checkbox"/> NA
<input checked="" type="checkbox"/> YES		<input type="checkbox"/> YES		<input type="checkbox"/> YES	<input type="checkbox"/> NO
<input type="checkbox"/> NO		<input type="checkbox"/> NO		<input type="checkbox"/> NO	<input type="checkbox"/> NA
<input checked="" type="checkbox"/> YES		<input type="checkbox"/> YES		<input type="checkbox"/> YES	<input type="checkbox"/> NO
<input type="checkbox"/> NO		<input type="checkbox"/> NO		<input type="checkbox"/> NO	<input type="checkbox"/> NA
<input checked="" type="checkbox"/> YES		<input type="checkbox"/> YES		<input type="checkbox"/> YES	<input type="checkbox"/> NO
<input type="checkbox"/> NO		<input type="checkbox"/> NO		<input type="checkbox"/> NO	<input type="checkbox"/> NA
<input checked="" type="checkbox"/> YES		<input type="checkbox"/> YES		<input type="checkbox"/> YES	<input type="checkbox"/> NO
<input type="checkbox"/> NO		<input type="checkbox"/> NO		<input type="checkbox"/> NO	<input type="checkbox"/> NA
<input checked="" type="checkbox"/> YES		<input type="checkbox"/> YES		<input type="checkbox"/> YES	<input type="checkbox"/> NO
<input type="checkbox"/> NO		<input type="checkbox"/> NO		<input type="checkbox"/> NO	<input type="checkbox"/> NA
<input checked="" type="checkbox"/> YES		<input type="checkbox"/> YES		<input type="checkbox"/> YES	<input type="checkbox"/> NO
<input type="checkbox"/> NO		<input type="checkbox"/> NO		<input type="checkbox"/> NO	<input type="checkbox"/> NA
<input checked="" type="checkbox"/> YES		<input type="checkbox"/> YES		<input type="checkbox"/> YES	<input type="checkbox"/> NO
<input type="checkbox"/> NO		<input type="checkbox"/> NO		<input type="checkbox"/> NO	<input type="checkbox"/> NA
<input checked="" type="checkbox"/> YES		<input type="checkbox"/> YES		<input type="checkbox"/> YES	<input type="checkbox"/> NO
<input type="checkbox"/> NO		<input type="checkbox"/> NO		<input type="checkbox"/> NO	<input type="checkbox"/> NA
<input checked="" type="checkbox"/> YES		<input type="checkbox"/> YES		<input type="checkbox"/> YES	<input type="checkbox"/> NO
<input type="checkbox"/> NO		<input type="checkbox"/> NO		<input type="checkbox"/> NO	<input type="checkbox"/> NA
<input checked="" type="checkbox"/> YES		<input type="checkbox"/> YES		<input type="checkbox"/> YES	<input type="checkbox"/> NO
<input type="checkbox"/> NO		<input type="checkbox"/> NO		<input type="checkbox"/> NO	<input type="checkbox"/> NA
<input checked="" type="checkbox"/> YES		<input type="checkbox"/> YES		<input type="checkbox"/> YES	<input type="checkbox"/> NO
<input type="checkbox"/> NO		<input type="checkbox"/> NO		<input type="checkbox"/> NO	<input type="checkbox"/> NA
<input checked="" type="checkbox"/> YES		<input type="checkbox"/> YES		<input type="checkbox"/> YES	<input type="checkbox"/> NO
<input type="checkbox"/> NO		<input type="checkbox"/> NO		<input type="checkbox"/> NO	<input type="checkbox"/> NA
<input checked="" type="checkbox"/> YES		<input type="checkbox"/> YES		<input type="checkbox"/> YES	<input type="checkbox"/> NO
<input type="checkbox"/> NO		<input type="checkbox"/> NO		<input type="checkbox"/> NO	<input type="checkbox"/> NA
<input checked="" type="checkbox"/> YES		<input type="checkbox"/> YES		<input type="checkbox"/> YES	<input type="checkbox"/> NO
<input type="checkbox"/> NO		<input type="checkbox"/> NO		<input type="checkbox"/> NO	<input type="checkbox"/> NA
<input checked="" type="checkbox"/> YES		<input type="checkbox"/> YES		<input type="checkbox"/> YES	<input type="checkbox"/> NO
<input type="checkbox"/> NO		<input type="checkbox"/> NO		<input type="checkbox"/> NO	<input type="checkbox"/> NA
<input checked="" type="checkbox"/> YES		<input type="checkbox"/> YES		<input type="checkbox"/> YES	<input type="checkbox"/> NO
<input type="checkbox"/> NO		<input type="checkbox"/> NO		<input type="checkbox"/> NO	<input type="checkbox"/> NA
<input checked="" type="checkbox"/> YES		<input type="checkbox"/> YES		<input type="checkbox"/> YES	<input type="checkbox"/> NO
<input type="checkbox"/> NO		<input type="checkbox"/> NO		<input type="checkbox"/> NO	<input type="checkbox"/> NA
<input checked="" type="checkbox"/> YES		<input type="checkbox"/> YES		<input type="checkbox"/> YES	<input type="checkbox"/> NO
<input type="checkbox"/> NO		<input type="checkbox"/> NO		<input type="checkbox"/> NO	<input type="checkbox"/> NA
<input checked="" type="checkbox"/> YES		<input type="checkbox"/> YES		<input type="checkbox"/> YES	<input type="checkbox"/> NO
<input type="checkbox"/> NO		<input type="checkbox"/> NO		<input type="checkbox"/> NO	<input type="checkbox"/> NA
<input checked="" type="checkbox"/> YES		<input type="checkbox"/> YES		<input type="checkbox"/> YES	<input type="checkbox"/> NO
<input type="checkbox"/> NO		<input type="checkbox"/> NO		<input type="checkbox"/> NO	<input type="checkbox"/> NA
<input checked="" type="checkbox"/> YES		<input type="checkbox"/> YES		<input type="checkbox"/> YES	<input type="checkbox"/> NO
<input type="checkbox"/> NO		<input type="checkbox"/> NO		<input type="checkbox"/> NO	<input type="checkbox"/> NA
<input checked="" type="checkbox"/> YES		<input type="checkbox"/> YES		<input type="checkbox"/> YES	<input type="checkbox"/> NO
<input type="checkbox"/> NO		<input type="checkbox"/> NO		<input type="checkbox"/> NO	<input type="checkbox"/> NA
<input checked="" type="checkbox"/> YES		<input type="checkbox"/> YES		<input type="checkbox"/> YES	<input type="checkbox"/> NO
<input type="checkbox"/> NO		<input type="checkbox"/> NO		<input type="checkbox"/> NO	<input type="checkbox"/> NA
<input checked="" type="checkbox"/> YES		<input type="checkbox"/> YES		<input type="checkbox"/> YES	<input type="checkbox"/> NO
<input type="checkbox"/> NO		<input type="checkbox"/> NO		<input type="checkbox"/> NO	<input type="checkbox"/> NA
<input checked="" type="checkbox"/> YES		<input type="checkbox"/> YES		<input type="checkbox"/> YES	<input type="checkbox"/> NO
<input type="checkbox"/> NO		<input type="checkbox"/> NO		<input type="checkbox"/> NO	<input type="checkbox"/> NA
<input checked="" type="checkbox"/> YES		<input type="checkbox"/> YES		<input type="checkbox"/> YES	<input type="checkbox"/> NO
<input type="checkbox"/> NO		<input type="checkbox"/> NO		<input type="checkbox"/> NO	<input type="checkbox"/> NA
<input checked="" type="checkbox"/> YES		<input type="checkbox"/> YES		<input type="checkbox"/> YES	<input type="checkbox"/> NO
<input type="checkbox"/> NO		<input type="checkbox"/> NO		<input type="checkbox"/> NO	<input type="checkbox"/> NA
<input checked="" type="checkbox"/> YES		<input type="checkbox"/> YES		<input type="checkbox"/> YES	<input type="checkbox"/> NO
<input type="checkbox"/> NO		<input type="checkbox"/> NO		<input type="checkbox"/> NO	<input type="checkbox"/> NA
<input checked="" type="checkbox"/> YES		<input type="checkbox"/> YES		<input type="checkbox"/> YES	<input type="checkbox"/> NO
<input type="checkbox"/> NO		<input type="checkbox"/> NO		<input type="checkbox"/> NO	<input type="checkbox"/> NA
<input checked="" type="checkbox"/> YES		<input type="checkbox"/> YES		<input type="checkbox"/> YES	<input type="checkbox"/> NO
<input type="checkbox"/> NO		<input type="checkbox"/> NO		<input type="checkbox"/> NO	<input type="checkbox"/> NA
<input checked="" type="checkbox"/> YES		<input type="checkbox"/> YES		<input type="checkbox"/> YES	<input type="checkbox"/> NO
<input type="checkbox"/> NO		<input type="checkbox"/> NO		<input type="checkbox"/> NO	<input type="checkbox"/> NA
<input checked="" type="checkbox"/> YES		<input type="checkbox"/> YES		<input type="checkbox"/> YES	<input type="checkbox"/> NO
<input type="checkbox"/> NO		<input type="checkbox"/> NO		<input type="checkbox"/> NO	<input type="checkbox"/> NA
<input checked="" type="checkbox"/> YES		<input type="checkbox"/> YES		<input type="checkbox"/> YES	<input type="checkbox"/> NO
<input type="checkbox"/> NO		<input type="checkbox"/> NO		<input type="checkbox"/> NO	<input type="checkbox"/> NA
<input checked="" type="checkbox"/> YES		<input type="checkbox"/> YES		<input type="checkbox"/> YES	<input type="checkbox"/> NO
<input type="checkbox"/> NO		<input type="checkbox"/> NO		<input type="checkbox"/> NO	<input type="checkbox"/> NA
<input checked="" type="checkbox"/> YES		<input type="checkbox"/> YES		<input type="checkbox"/> YES	<input type="checkbox"/> NO
<input type="checkbox"/> NO		<input type="checkbox"/> NO		<input type="checkbox"/> NO	<input type="checkbox"/> NA
<input checked="" type="checkbox"/> YES		<input type="checkbox"/> YES		<input type="checkbox"/> YES	<input type="checkbox"/> NO
<input type="checkbox"/> NO		<input type="checkbox"/> NO		<input type="checkbox"/> NO	<input type="checkbox"/> NA
<input checked="" type="checkbox"/> YES		<input type="checkbox"/> YES		<input type="checkbox"/> YES	<input type="checkbox"/> NO
<input type="checkbox"/> NO		<input type="checkbox"/> NO		<input type="checkbox"/> NO	<input type="checkbox"/> NA
<input checked="" type="checkbox"/> YES		<input type="checkbox"/> YES		<input type="checkbox"/> YES	<input type="checkbox"/> NO
<input type="checkbox"/> NO		<input type="checkbox"/> NO		<input type="checkbox"/> NO	<input type="checkbox"/> NA
<input checked="" type="checkbox"/> YES		<input type="checkbox"/> YES		<input type="checkbox"/> YES	<input type="checkbox"/> NO
<input type="checkbox"/> NO		<input type="checkbox"/> NO		<input type="checkbox"/> NO	<input type="checkbox"/> NA
<input checked="" type="checkbox"/> YES		<input type="checkbox"/> YES		<input type="checkbox"/> YES	<input type="checkbox"/> NO
<input type="checkbox"/> NO		<input type="checkbox"/> NO		<input type="checkbox"/> NO	<input type="checkbox"/> NA
<input checked="" type="checkbox"/> YES		<input type="checkbox"/> YES		<input type="checkbox"/> YES	<input type="checkbox"/> NO
<input type="checkbox"/> NO		<input type="checkbox"/> NO		<input type="checkbox"/> NO	<input type="checkbox"/> NA
<input checked="" type="checkbox"/> YES		<input type="checkbox"/> YES		<input type="checkbox"/> YES	<input type="checkbox"/> NO
<input type="checkbox"/> NO		<input type="checkbox"/> NO		<input type="checkbox"/> NO	<input type="checkbox"/> NA
<input checked="" type="checkbox"/> YES		<input type="checkbox"/> YES		<input type="checkbox"/> YES	<input type="checkbox"/> NO
<input type="checkbox"/> NO		<input type="checkbox"/> NO		<input type="checkbox"/> NO	<input type="checkbox"/> NA
<input checked="" type="checkbox"/> YES		<input type="checkbox"/> YES		<input type="checkbox"/> YES	<input type="checkbox"/> NO
<input type="checkbox"/> NO		<input type="checkbox"/> NO		<input type="checkbox"/> NO	<input type="checkbox"/> NA
<input checked="" type="checkbox"/> YES		<input type="checkbox"/> YES		<input type="checkbox"/> YES	<input type="checkbox"/> NO
<input type="checkbox"/> NO		<input type="checkbox"/> NO		<input type="checkbox"/> NO	<input type="checkbox"/> NA
<input checked="" type="checkbox"/> YES		<input type="checkbox"/> YES		<input type="checkbox"/> YES	<input type="checkbox"/> NO
<input type="checkbox"/> NO		<input type="checkbox"/> NO		<input type="checkbox"/> NO	<input type="checkbox"/> NA
<input checked="" type="checkbox"/> YES		<input type="checkbox"/> YES		<input type="checkbox"/> YES	<input type="checkbox"/> NO
<input type="checkbox"/> NO		<input type="checkbox"/> NO		<input type="checkbox"/> NO	<input type="checkbox"/> NA
<input checked="" type="checkbox"/> YES		<input type="checkbox"/> YES		<input type="checkbox"/> YES	<input type="checkbox"/> NO
<input type="checkbox"/> NO		<input type="checkbox"/> NO		<input type="checkbox"/> NO	<input type="checkbox"/> NA
<input checked="" type="checkbox"/> YES		<input type="checkbox"/> YES		<input type="checkbox"/> YES	<input type="checkbox"/> NO



CRYSTALLINE
ENVIRONMENTAL SERVICES


Date of Cleaning: 01-07-2018

PHOTOGRAPHS
UNDER GROUND RCC WATER TANK (A 06) - 01

BEFORE



AFTER



CLEANER WATER GREENER TOMORROW



CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT

15375

CUSTOMER: <i>Sarair</i>			CONTACT PERSON: <i>MR:- vidhans</i>		
SITE DETAILS: <i>Khalifa complex A-6 Abu Dhabi</i>			CONTACT NO: <i>0559838071</i>		
TANK DETAILS: <i>F.R.P. filler tank no:-01</i>			LOCATION DETAILS: <i>roof top</i>		
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL		<input type="checkbox"/> RESIDENTIAL		<input type="checkbox"/> OTHERS	
TYPE OF TANK					
<input type="checkbox"/> CONCRETE	<input type="checkbox"/> GRP PANEL	<input checked="" type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED		<input type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS		
SIZE OF TANK			QUANTITY OF WATER		
M3	USG	L*B*H	<input type="checkbox"/> FULL	<input type="checkbox"/> HALF	<input type="checkbox"/> EMPTY
CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK AFTER CLEANING		
<input type="checkbox"/> CLEAN	<input checked="" type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input checked="" type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
ACCESS		MANHOLE		<input checked="" type="checkbox"/> COVERED	<input type="checkbox"/> DAMAGED
				<input type="checkbox"/> NA	
LADDER IN		LADDER OUT		LEAKS	
<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO
				DRAIN LINE	
				<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO
				VALVES	
				<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO
				FLOAT VALVE	
				<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO
TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> YES	<input type="checkbox"/> NO
				<input checked="" type="checkbox"/> NA	
LAST CLEANING DATE		CURRENT CLEANING DATE		NEXT CLEANING DATE	
		<i>01/07/2018</i>		<i>01/01/2019</i>	
CHEMICALS & EQUIPMENTS USED					
1. <i>Carite bio plus</i> Quantity <i>250 ml</i>					
2. _____ Quantity _____					
<input checked="" type="checkbox"/> Submersibel Pump <input checked="" type="checkbox"/> High/Low Pressure Jet <input type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED lights <input type="checkbox"/> Foot Bath <input type="checkbox"/> Ladder <input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Meter <input type="checkbox"/> Vacuum Cleaner <input type="checkbox"/> Cleaning Materials					
COMMENTS & RECOMMENDATIONS:					
<i>Above mentioned water tank are successfully cleaned and disinfected.</i>					
Crystalline Representative: <i>Sasir Sharafudeen</i>			Signature: <i>Sasir</i>		



CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT

15382

CUSTOMER: <i>Sarais</i>			CONTACT PERSON: <i>Ms:- Vidhwan</i>		
SITE DETAILS: <i>Khalifa Complex - A6 Abu Dhabi</i>			CONTACT NO: <i>0559838071</i>		
TANK DETAILS: <i>F.R.P. filter tank no:-020</i>			LOCATION DETAILS: <i>roof top</i>		
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL		<input type="checkbox"/> RESIDENTIAL		<input type="checkbox"/> OTHERS	
TYPE OF TANK					
<input type="checkbox"/> CONCRETE	<input type="checkbox"/> GRP PANEL	<input checked="" type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED		<input type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS		
SIZE OF TANK			QUANTITY OF WATER		
M3	USG	L*B*H	<input type="checkbox"/> FULL	<input type="checkbox"/> HALF	<input type="checkbox"/> EMPTY
CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK AFTER CLEANING		
<input type="checkbox"/> CLEAN	<input checked="" type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input checked="" type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
ACCESS		MANHOLE		<input checked="" type="checkbox"/> COVERED	<input type="checkbox"/> DAMAGED
				<input type="checkbox"/> NA	
LADDER IN		LADDER OUT		LEAKS	
<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO
DRAIN LINE		VALVES		FLOAT VALVE	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> YES	<input type="checkbox"/> NO
TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> YES	<input type="checkbox"/> NO
				<input checked="" type="checkbox"/> NA	
LAST CLEANING DATE		CURRENT CLEANING DATE		NEXT CLEANING DATE	
		<i>01/07/2018</i>		<i>01/01/2019</i>	
CHEMICALS & EQUIPMENTS USED					
1. <i>Carito bio plus</i> Quantity <i>250 ml</i>					
2. _____ Quantity _____					
<input checked="" type="checkbox"/> Submersibel Pump <input checked="" type="checkbox"/> High/Low Pressure Jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED lights <input checked="" type="checkbox"/> Foot Bath <input checked="" type="checkbox"/> Ladder <input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Meter <input checked="" type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials					
COMMENTS & RECOMMENDATIONS:					
<i>Above mentioned water tanks are successfully cleaned and disinfected.</i>					
Crystalline Representative: <i>Sarim Sharafudin</i>			Signature: <i>Sarim</i>		

Date of Cleaning: 01-07-2018

PHOTOGRAPHS
ROOF TOP FRP FILTER TANK (A 06) – 01&02

BEFORE

FRP FILTER TANK-01



FRP FILTER TANK-02



AFTER





CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT

15383

CUSTOMER: <i>Sarais</i>			CONTACT PERSON: <i>Ms. - Vidhwan</i>		
SITE DETAILS: <i>Khalifa Complex - A-6 Abu Dhabi</i>			CONTACT NO: <i>055 9838071</i>		
TANK DETAILS: <i>F.R.P. Domestic Tank - no. - 01</i>			LOCATION DETAILS: <i>roof top</i>		
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL		<input type="checkbox"/> RESIDENTIAL		<input type="checkbox"/> OTHERS	
TYPE OF TANK					
<input type="checkbox"/> CONCRETE	<input type="checkbox"/> GRP PANEL	<input checked="" type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED		<input type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS		
SIZE OF TANK			QUANTITY OF WATER		
M3	USG	L*B*H	<input type="checkbox"/> FULL	<input type="checkbox"/> HALF	<input type="checkbox"/> EMPTY
CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK AFTER CLEANING		
<input type="checkbox"/> CLEAN	<input checked="" type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input checked="" type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
ACCESS		MANHOLE		<input checked="" type="checkbox"/> COVERED	
<input type="checkbox"/> DAMAGED		<input type="checkbox"/> NA			
LADDER IN		LADDER OUT		LEAKS	
<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO
DRAIN LINE		VALVES		FLOAT VALVE	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO
TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> YES	<input type="checkbox"/> NO <input checked="" type="checkbox"/> NA
LAST CLEANING DATE		CURRENT CLEANING DATE		NEXT CLEANING DATE	
		<i>02/07/2018</i>		<i>02/01/2019</i>	
CHEMICALS & EQUIPMENTS USED					
1. <i>Carito bio plus</i> Quantity <i>250 ml</i>					
2. _____ Quantity _____					
<input checked="" type="checkbox"/> Submersibel Pump <input checked="" type="checkbox"/> High/Low Pressure Jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED lights <input checked="" type="checkbox"/> Foot Bath <input checked="" type="checkbox"/> Ladder <input checked="" type="checkbox"/> Ventilating Fan <input type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Meter <input checked="" type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials					
COMMENTS & RECOMMENDATIONS:					
<i>Above mentioned water tank case successfully cleaned and disinfected.</i>					
Crystalline Representative: <i>Sasir Sharghudekar</i>			Signature: <i>Sasir</i>		



CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT

15384

CUSTOMER: <i>Sarair</i>			CONTACT PERSON: <i>Ms. - Indira</i>		
SITE DETAILS: <i>Khalifa Complex A.6 Abu Dhabi</i>			CONTACT NO: <i>0559838071</i>		
TANK DETAILS: <i>F.R.P. Domestic tank no:-02</i>			LOCATION DETAILS: <i>roof top</i>		
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL		<input type="checkbox"/> RESIDENTIAL		<input type="checkbox"/> OTHERS	
TYPE OF TANK					
<input type="checkbox"/> CONCRETE	<input type="checkbox"/> GRP PANEL	<input checked="" type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED		<input type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS		
SIZE OF TANK			QUANTITY OF WATER		
M3	USG	L*B*H	<input type="checkbox"/> FULL	<input type="checkbox"/> HALF	<input type="checkbox"/> EMPTY
CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK AFTER CLEANING		
<input type="checkbox"/> CLEAN	<input checked="" type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input checked="" type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
ACCESS		MANHOLE		<input checked="" type="checkbox"/> COVERED	<input type="checkbox"/> DAMAGED
				<input type="checkbox"/> NA	
LADDER IN		LADDER OUT		LEAKS	
<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO
DRAIN LINE		VALVES		FLOAT VALVE	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO
TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> YES	<input type="checkbox"/> NO
				<input checked="" type="checkbox"/> NA	
LAST CLEANING DATE		CURRENT CLEANING DATE		NEXT CLEANING DATE	
		<i>02/07/2018</i>		<i>02/01/2019</i>	
CHEMICALS & EQUIPMENTS USED					
1. <i>Carito bio plus</i> Quantity <i>250 ml</i>					
2. _____ Quantity _____					
<input checked="" type="checkbox"/> Submersibel Pump <input checked="" type="checkbox"/> High/Low Pressure Jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED lights <input checked="" type="checkbox"/> Foot Bath <input checked="" type="checkbox"/> Ladder <input checked="" type="checkbox"/> Ventilating Fan <input type="checkbox"/> Suction/Discharge Hoses <input type="checkbox"/> Oxygen Meter <input checked="" type="checkbox"/> Vacuum Cleaner <input type="checkbox"/> Cleaning Materials					
COMMENTS & RECOMMENDATIONS:					
<i>Above mentioned water tank are successfully cleaned and disinfected.</i>					
Crystalline Representative: <i>Sasir - Sharghader</i>			Signature: <i>Sasir</i>		

Date of Cleaning: 02-07-2018

PHOTOGRAPHS
ROOF TOP FRP WATER TANK (A 06) – 03&04

BEFORE

FRP WATER TANK-03



FRP WATER TANK-04



AFTER





CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT


20253

CUSTOMER: <i>ICTC - 70 Sarai</i>			CONTACT PERSON:		
SITE DETAILS: <i>spark Building</i>			CONTACT NO: <i>0509089532</i>		
TANK DETAILS: <i>R.C.C. water tank</i>			LOCATION DETAILS: <i>under ground</i>		
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL		<input type="checkbox"/> RESIDENTIAL		<input type="checkbox"/> OTHERS	
TYPE OF TANK					
<input type="checkbox"/> CONCRETE	<input type="checkbox"/> GRP PANEL	<input type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED		<input type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS		
SIZE OF TANK			QUANTITY OF WATER		
M3	USG	L*B*H	<input type="checkbox"/> FULL	<input type="checkbox"/> HALF	<input type="checkbox"/> EMPTY
CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK AFTER CLEANING		
<input type="checkbox"/> CLEAN	<input checked="" type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input checked="" type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
ACCESS		MANHOLE		<input checked="" type="checkbox"/> COVERED	<input type="checkbox"/> DAMAGED
<input type="checkbox"/> NA					<input type="checkbox"/> NA
LADDER IN	LADDER OUT	LEAKS	DRAIN LINE	VALVES	FLOAT VALVE
<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO
TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> YES	<input type="checkbox"/> NO <input checked="" type="checkbox"/> NA
LAST CLEANING DATE		CURRENT CLEANING DATE		NEXT CLEANING DATE	
		<i>09/09/2018</i>		<i>09/03/2019</i>	
CHEMICALS & EQUIPMENTS USED					
1. <i>Carite bio plus</i> Quantity <i>500 ml</i>					
2. _____ Quantity _____					
<input checked="" type="checkbox"/> Submersibel Pump <input checked="" type="checkbox"/> High /Low Pressure jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED Lights <input checked="" type="checkbox"/> Foot Bath <input checked="" type="checkbox"/> Ladder					
<input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Mater <input checked="" type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials					
COMMENTS & RECOMMENDATIONS:					
<i>Above nondrilled water tank are successfully cleaned and disinfected.</i>					
Crystalline Representative: <i>Basir Shamshudin</i>			Signature: <i>Basir</i>		

Date of Cleaning: 09-09-2018

PHOTOGRAPHS
UNDER GROUND RCC WATER TANK - ICTC 70 (Spark Building)

BEFORE



AFTER



CRYSTALLINE CLEANING & ENVIRONMENTAL SERVICES

CLEANING & DISINFECTION CERTIFICATE

POTABLE WATER TANKS

CLIENT NAME : SAMIR NAJIB EST. FOR CENTRAL AIR-CONDITIONING.

CLIENT ADDRESS : P.O BOX: 2216, ABU DHABI, UAE.

CONTACT PERSON : MR. MOHAMMED MASHAL.

SITE DETAILS : KHALIFA COMPLEX BUILDING (A1,A2,A3,A4,A5,A6 & C70) ABU DHABI.

DETAILS : WATER TANK CLEANING

DATE OF CLEANING : SEPTEMBER 2018

FREQUENCY OF CLEANING : EVERY SIX MONTHS

DATE OF NEXT CLEANING : MARCH 2019

The procedures employed in this cleaning and disinfection comply with HS (G) 70 health and safety guidelines for prevention of legionella as well as BS6700 and CARELA BIO PLUS method statement.

The entire water storage tank should be cleaned and disinfected minimum every six (6) months depending upon the condition.



CRYSTALLINE CLEANING AND ENVIRONMENTAL SERVICES