

WATER TANK CLEANING
&
DISINFECTION

COMPLETION REPORT

FOR



Client : AL REEM HOSPICO COMPANY
Contact Person: Mr. Ferdinand
Engineering Department.
Site Details : Al Wagan Hospital, Al Ain, UAE
Date : 30 September 2018



CRYSTALLINE
ENVIRONMENTAL SERVICES

CRYSTALLINE ENVIRONMENTAL
SERVICES

P.O. BOX 131463, Abu Dhabi, U.A.E.

TEL: 02 6508930 FAX: 02 6508942

info@crystalline-uae.com

www.crystalline-uae.com





CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT

20542

| | | | | | |
|---|--|---|---|---|---|
| CUSTOMER: <i>Al Wagon Hospital</i> | | | CONTACT PERSON: <i>Mr. Shimi</i> | | |
| SITE DETAILS: <i>Al Wagon, Al Ain</i> | | | CONTACT NO: | | |
| TANK DETAILS: <i>Er. R. P Water tank - 3</i> | | | LOCATION DETAILS: <i>Ground floor</i> | | |
| TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL | | <input type="checkbox"/> RESIDENTIAL | | <input type="checkbox"/> OTHERS | |
| TYPE OF TANK | | | | | |
| <input type="checkbox"/> CONCRETE | <input checked="" type="checkbox"/> GRP PANEL | <input type="checkbox"/> FRP TANK | <input type="checkbox"/> GALVANIZED | <input type="checkbox"/> STEEL PANEL | <input type="checkbox"/> PLASTIC |
| <input type="checkbox"/> CONCRETE COATED | | <input type="checkbox"/> POLYURETHANE | <input type="checkbox"/> OTHERS | | |
| SIZE OF TANK | | | QUANTITY OF WATER | | |
| M3 | USG | L*B*H | <input type="checkbox"/> FULL | <input checked="" type="checkbox"/> HALF | <input type="checkbox"/> EMPTY |
| CONDITION OF WATER TANK BEFORE CLEANING | | | CONDITION OF WATER TANK AFTER CLEANING | | |
| <input type="checkbox"/> CLEAN | <input type="checkbox"/> DIRTY | <input checked="" type="checkbox"/> VERY DIRTY | <input checked="" type="checkbox"/> CLEAN | <input type="checkbox"/> DIRTY | <input type="checkbox"/> VERY DIRTY |
| <input type="checkbox"/> BIOFILMS | <input type="checkbox"/> MOULDS | <input type="checkbox"/> SLIME | <input type="checkbox"/> BIOFILMS | <input type="checkbox"/> MOULDS | <input type="checkbox"/> SLIME |
| <input type="checkbox"/> SEDIMENTS | <input checked="" type="checkbox"/> MUD & SAND | <input type="checkbox"/> RUST | <input type="checkbox"/> SEDIMENTS | <input type="checkbox"/> MUD & SAND | <input type="checkbox"/> RUST |
| ACCESS | | MANHOLE | | <input checked="" type="checkbox"/> COVERED | <input type="checkbox"/> DAMAGED |
| <input type="checkbox"/> NA | | | | | <input type="checkbox"/> NA |
| LADDER IN | LADDER OUT | LEAKS | DRAIN LINE | VALVES | FLOAT VALVE |
| <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO | <input type="checkbox"/> YES <input type="checkbox"/> NO | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO |
| TANK CLEANED | | TANK DISINFECTED | | PIPES DISINFECTED | |
| <input checked="" type="checkbox"/> YES | <input type="checkbox"/> NO | <input checked="" type="checkbox"/> YES | <input type="checkbox"/> NO | <input type="checkbox"/> YES | <input type="checkbox"/> NO <input checked="" type="checkbox"/> NA |
| LAST CLEANING DATE | | CURRENT CLEANING DATE | | NEXT CLEANING DATE | |
| | | <i>21/09/2013</i> | | <i>21-03-2017</i> | |
| CHEMICALS & EQUIPMENTS USED | | | | | |
| 1. <i>Cerulo bio and plus</i> Quantity <i>200 ml</i> | | | | | |
| 2. _____ Quantity _____ | | | | | |
| <input checked="" type="checkbox"/> Submersibel Pump <input checked="" type="checkbox"/> High /Low Pressure jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED Lights <input type="checkbox"/> Foot Bath <input type="checkbox"/> Ladder | | | | | |
| <input checked="" type="checkbox"/> Ventilating Fan <input type="checkbox"/> Suction/Discharge Hoses <input type="checkbox"/> Oxygen Mater <input type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials | | | | | |
| COMMENTS & RECOMMENDATIONS: | | | | | |
| <i>Mentioned water tank is cleaned and disinfected</i> | | | | | |
| Crystalline Representative: <i>Mary</i> | | | Signature: <i>Mary</i> | | |


Date of Cleaning: 21-09-2018

PHOTOGRAPHS
GROUND LEVEL GRP WATER TANK- 03

BEFORE



AFTER





CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT

20539

| | | | | | |
|---|---|---|--|---|---|
| CUSTOMER: <i>Al Wagon Hospital</i> | | | CONTACT PERSON: <i>Mr. Jhivan</i> | | |
| SITE DETAILS: <i>Al Wagon, Alain</i> | | | CONTACT NO: | | |
| TANK DETAILS: <i>R.C.C Water tank 1</i> | | | LOCATION DETAILS: <i>Enclosed from New Pump</i> | | |
| TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL <input type="checkbox"/> RESIDENTIAL <input type="checkbox"/> OTHERS | | | | | |
| TYPE OF TANK | | | | | |
| <input checked="" type="checkbox"/> CONCRETE | <input type="checkbox"/> GRP PANEL | <input type="checkbox"/> FRP TANK | <input type="checkbox"/> GALVANIZED | <input type="checkbox"/> STEEL PANEL | <input type="checkbox"/> PLASTIC |
| <input type="checkbox"/> CONCRETE COATED | <input type="checkbox"/> POLYURETHANE | | <input type="checkbox"/> OTHERS | | |
| SIZE OF TANK | | | QUANTITY OF WATER | | |
| M3 | USG | L*B*H | <input checked="" type="checkbox"/> FULL | <input type="checkbox"/> HALF | <input checked="" type="checkbox"/> EMPTY |
| CONDITION OF WATER TANK BEFORE CLEANING | | | CONDITION OF WATER TANK AFTER CLEANING | | |
| <input type="checkbox"/> CLEAN | <input type="checkbox"/> DIRTY | <input checked="" type="checkbox"/> VERY DIRTY | <input checked="" type="checkbox"/> CLEAN | <input type="checkbox"/> DIRTY | <input type="checkbox"/> VERY DIRTY |
| <input type="checkbox"/> BIOFILMS | <input type="checkbox"/> MOULDS | <input type="checkbox"/> SLIME | <input type="checkbox"/> BIOFILMS | <input type="checkbox"/> MOULDS | <input type="checkbox"/> SLIME |
| <input type="checkbox"/> SEDIMENTS | <input checked="" type="checkbox"/> MUD & SAND | <input type="checkbox"/> RUST | <input type="checkbox"/> SEDIMENTS | <input type="checkbox"/> MUD & SAND | <input type="checkbox"/> RUST |
| ACCESS | | MANHOLE | <input checked="" type="checkbox"/> COVERED | <input type="checkbox"/> DAMAGED | <input type="checkbox"/> NA |
| LADDER IN | LADDER OUT | LEAKS | DRAIN LINE | VALVES | FLOAT VALVE |
| <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO | <input type="checkbox"/> YES <input type="checkbox"/> NO | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO |
| TANK CLEANED | | TANK DISINFECTED | | PIPES DISINFECTED | |
| <input checked="" type="checkbox"/> YES | <input type="checkbox"/> NO | <input checked="" type="checkbox"/> YES | <input type="checkbox"/> NO | <input type="checkbox"/> YES | <input type="checkbox"/> NO <input checked="" type="checkbox"/> NA |
| LAST CLEANING DATE | | CURRENT CLEANING DATE | | NEXT CLEANING DATE | |
| | | <i>21/09/2018</i> | | <i>21/03/2019</i> | |
| CHEMICALS & EQUIPMENTS USED | | | | | |
| 1. <i>Carolo bio and plus</i> Quantity <i>250ml</i> | | | | | |
| 2. _____ Quantity _____ | | | | | |
| <input checked="" type="checkbox"/> Submersibel Pump <input checked="" type="checkbox"/> High /Low Pressure jet <input type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED Lights <input checked="" type="checkbox"/> Foot Bath <input type="checkbox"/> Ladder <input checked="" type="checkbox"/> Ventilating Fan <input type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Mater <input type="checkbox"/> Vaeuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials | | | | | |
| COMMENTS & RECOMMENDATIONS: | | | | | |
| <i>Mentioned water tank is cleaned and disinfected</i> | | | | | |
| Crystalline Representative: <i>Manoj</i> | | | Signature: <i>Manoj</i> | | |




CRYSTALLINE
ENVIRONMENTAL SERVICES

Date of Cleaning: 21-09-2018

PHOTOGRAPHS
GROUND LEVEL RCC WATER TANK- 01

BEFORE



AFTER



CLEANER WATER GREENER TOMORROW



CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT


20543

| | | | | | |
|--|---|---|---|---|---|
| CUSTOMER: <i>Al Wagan hospital</i> | | | CONTACT PERSON: <i>Mr. Shiru</i> | | |
| SITE DETAILS: <i>Al Wagan, Al Ain</i> | | | CONTACT NO: | | |
| TANK DETAILS: <i>Cr. R.P Water tank - 2</i> | | | LOCATION DETAILS: <i>Ground floor (Dump Room)</i> | | |
| TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL <input type="checkbox"/> RESIDENTIAL <input type="checkbox"/> OTHERS | | | | | |
| TYPE OF TANK | | | | | |
| <input checked="" type="checkbox"/> CONCRETE | <input type="checkbox"/> GRP PANEL | <input type="checkbox"/> FRP TANK | <input type="checkbox"/> GALVANIZED | <input type="checkbox"/> STEEL PANEL | <input type="checkbox"/> PLASTIC |
| <input type="checkbox"/> CONCRETE COATED | | <input type="checkbox"/> POLYURETHANE | <input type="checkbox"/> OTHERS | | |
| SIZE OF TANK | | | QUANTITY OF WATER | | |
| M3 | USG | L*B*H | <input checked="" type="checkbox"/> FULL | <input type="checkbox"/> HALF | <input type="checkbox"/> EMPTY |
| CONDITION OF WATER TANK BEFORE CLEANING | | | CONDITION OF WATER TANK AFTER CLEANING | | |
| <input type="checkbox"/> CLEAN | <input type="checkbox"/> DIRTY | <input checked="" type="checkbox"/> VERY DIRTY | <input checked="" type="checkbox"/> CLEAN | <input type="checkbox"/> DIRTY | <input type="checkbox"/> VERY DIRTY |
| <input type="checkbox"/> BIOFILMS | <input type="checkbox"/> MOULDS | <input type="checkbox"/> SLIME | <input type="checkbox"/> BIOFILMS | <input type="checkbox"/> MOULDS | <input type="checkbox"/> SLIME |
| <input type="checkbox"/> SEDIMENTS | <input checked="" type="checkbox"/> MUD & SAND | <input type="checkbox"/> RUST | <input type="checkbox"/> SEDIMENTS | <input type="checkbox"/> MUD & SAND | <input type="checkbox"/> RUST |
| ACCESS | | MANHOLE | <input checked="" type="checkbox"/> COVERED | <input type="checkbox"/> DAMAGED | <input type="checkbox"/> NA |
| LADDER IN | LADDER OUT | LEAKS | DRAIN LINE | VALVES | FLOAT VALVE |
| <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO |
| TANK CLEANED | | TANK DISINFECTED | | PIPES DISINFECTED | |
| <input checked="" type="checkbox"/> YES | <input type="checkbox"/> NO | <input checked="" type="checkbox"/> YES | <input type="checkbox"/> NO | <input type="checkbox"/> YES | <input type="checkbox"/> NO <input checked="" type="checkbox"/> NA |
| LAST CLEANING DATE | | CURRENT CLEANING DATE | | NEXT CLEANING DATE | |
| | | <i>21/09/2018</i> | | <i>21/03/2019</i> | |
| CHEMICALS & EQUIPMENTS USED | | | | | |
| 1. <i>Carex bio amel plus</i> Quantity <i>250ml</i> | | | | | |
| 2. _____ Quantity _____ | | | | | |
| <input checked="" type="checkbox"/> Submersibel Pump <input type="checkbox"/> High /Low Pressure jet <input type="checkbox"/> Extension Cords <input type="checkbox"/> LED Lights <input checked="" type="checkbox"/> Foot Bath <input type="checkbox"/> Ladder <input checked="" type="checkbox"/> Ventilating Fan <input type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Mater <input type="checkbox"/> Vacuum Cleaner <input type="checkbox"/> Cleaning Materials | | | | | |
| COMMENTS & RECOMMENDATIONS: | | | | | |
| <i>Mentioned water tank is cleaned and disinfected</i> | | | | | |
| Crystalline Representative: <i>Mauj</i> | | | Signature: <i>Mauj</i> | | |

Date of Cleaning: 21-09-2018

PHOTOGRAPHS
GROUND LEVEL GRP WATER TANK- 02

BEFORE



AFTER



CLEANER WATER GREENER TOMORROW



CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT

13288



| CUSTOMER: <i>Al Wagan hospital</i> | | | CONTACT PERSON: <i>Mr. Krishna</i> | | |
|---|---|---|---|---|---|
| SITE DETAILS: <i>Al Wagan, Al ain</i> | | | CONTACT NO: <i>0509014607</i> | | |
| TANK DETAILS: <i>n.c.c fire and domestic-2</i> | | | LOCATION DETAILS: <i>Ground floor New Pump room</i> | | |
| TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL | | <input type="checkbox"/> RESIDENTIAL | | <input type="checkbox"/> OTHERS | |
| TYPE OF TANK | | | | | |
| <input checked="" type="checkbox"/> CONCRETE | <input type="checkbox"/> GRP PANEL | <input type="checkbox"/> FRP TANK | <input type="checkbox"/> GALVANIZED | <input type="checkbox"/> STEEL PANEL | <input type="checkbox"/> PLASTIC |
| <input type="checkbox"/> CONCRETE COATED | | <input type="checkbox"/> POLYURETHANE | <input type="checkbox"/> OTHERS | | |
| SIZE OF TANK | | | QUANTITY OF WATER | | |
| M3 | USG | L*B*H | <input type="checkbox"/> FULL | <input checked="" type="checkbox"/> HALF | <input type="checkbox"/> EMPTY |
| CONDITION OF WATER TANK BEFORE CLEANING | | | CONDITION OF WATER TANK AFTER CLEANING | | |
| <input type="checkbox"/> CLEAN | <input type="checkbox"/> DIRTY | <input checked="" type="checkbox"/> VERY DIRTY | <input checked="" type="checkbox"/> CLEAN | <input type="checkbox"/> DIRTY | <input type="checkbox"/> VERY DIRTY |
| <input type="checkbox"/> BIOFILMS | <input type="checkbox"/> MOULDS | <input type="checkbox"/> SLIME | <input type="checkbox"/> BIOFILMS | <input type="checkbox"/> MOULDS | <input type="checkbox"/> SLIME |
| <input type="checkbox"/> SEDIMENTS | <input checked="" type="checkbox"/> MUD & SAND | <input type="checkbox"/> RUST | <input type="checkbox"/> SEDIMENTS | <input type="checkbox"/> MUD & SAND | <input type="checkbox"/> RUST |
| ACCESS | | MANHOLE | | <input checked="" type="checkbox"/> COVERED | <input type="checkbox"/> DAMAGED |
| <input type="checkbox"/> NA |
| LADDER IN | LADDER OUT | LEAKS | DRAIN LINE | VALVES | FLOAT VALVE |
| <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO |
| TANK CLEANED | | TANK DISINFECTED | | PIPES DISINFECTED | |
| <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO | <input type="checkbox"/> YES <input type="checkbox"/> NO | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO | <input type="checkbox"/> YES <input type="checkbox"/> NO | <input type="checkbox"/> YES <input type="checkbox"/> NO | <input checked="" type="checkbox"/> NA |
| LAST CLEANING DATE | | CURRENT CLEANING DATE | | NEXT CLEANING DATE | |
| | | <i>22/09/2018</i> | | <i>22/09/2019</i> | |
| CHEMICALS & EQUIPMENTS USED | | | | | |
| 1. <i>Coro bio and plus</i> Quantity <i>250 ml</i> | | | | | |
| 2. _____ Quantity _____ | | | | | |
| <input checked="" type="checkbox"/> Submersible Pump | <input type="checkbox"/> High/Low Pressure Jet | <input checked="" type="checkbox"/> Extension Cords | <input checked="" type="checkbox"/> LED lights | <input type="checkbox"/> Foot Bath | <input checked="" type="checkbox"/> Ladder |
| <input checked="" type="checkbox"/> Ventilating Fan | <input type="checkbox"/> Suction/Discharge Hoses | <input type="checkbox"/> Oxygen Meter | <input type="checkbox"/> Vacuum Cleaner | <input type="checkbox"/> Cleaning Materials | |
| COMMENTS & RECOMMENDATIONS: | | | | | |
| <i>mentioned Water tank is cleaned and disinfected</i> | | | | | |
| Crystalline Representative: <i>Manoj</i> | | | Signature: <i>Manoj</i> | | |





Date of Cleaning: 22-09-2018

PHOTOGRAPHS
GROUND LEVEL RCC WATER TANK- 02

BEFORE



AFTER





CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT

13289

| | | | | | |
|---|--|--|---|---|-------------------------------------|
| CUSTOMER: <i>Al Wagan Hospital</i> | | | CONTACT PERSON: <i>Ms Krishna</i> | | |
| SITE DETAILS: <i>Al Wagan, Alain</i> | | | CONTACT NO: <i>050 9014607</i> | | |
| TANK DETAILS: <i>C.P.P Water tank - 2</i> | | | LOCATION DETAILS: <i>Ground floor. New Pump</i> | | |
| TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL | | <input type="checkbox"/> RESIDENTIAL | | <input type="checkbox"/> OTHERS | |
| TYPE OF TANK | | | | | |
| <input type="checkbox"/> CONCRETE | <input checked="" type="checkbox"/> GRP PANEL | <input type="checkbox"/> FRP TANK | <input type="checkbox"/> GALVANIZED | <input type="checkbox"/> STEEL PANEL | <input type="checkbox"/> PLASTIC |
| <input type="checkbox"/> CONCRETE COATED | | <input type="checkbox"/> POLYURETHANE | | <input type="checkbox"/> OTHERS | |
| SIZE OF TANK | | | QUANTITY OF WATER | | |
| M3 | USG | L*B*H | <input checked="" type="checkbox"/> FULL | <input type="checkbox"/> HALF | <input type="checkbox"/> EMPTY |
| CONDITION OF WATER TANK BEFORE CLEANING | | | CONDITION OF WATER TANK AFTER CLEANING | | |
| <input type="checkbox"/> CLEAN | <input type="checkbox"/> DIRTY | <input checked="" type="checkbox"/> VERY DIRTY | <input checked="" type="checkbox"/> CLEAN | <input type="checkbox"/> DIRTY | <input type="checkbox"/> VERY DIRTY |
| <input type="checkbox"/> BIOFILMS | <input type="checkbox"/> MOULDS | <input type="checkbox"/> SLIME | <input type="checkbox"/> BIOFILMS | <input type="checkbox"/> MOULDS | <input type="checkbox"/> SLIME |
| <input type="checkbox"/> SEDIMENTS | <input checked="" type="checkbox"/> MUD & SAND | <input type="checkbox"/> RUST | <input type="checkbox"/> SEDIMENTS | <input type="checkbox"/> MUD & SAND | <input type="checkbox"/> RUST |
| ACCESS | | MANHOLE | | <input checked="" type="checkbox"/> COVERED | |
| <input type="checkbox"/> DAMAGED | | <input type="checkbox"/> NA | | | |
| LADDER IN | | LADDER OUT | | LEAKS | |
| DRAIN LINE | | VALVES | | FLOAT VALVE | |
| <input checked="" type="checkbox"/> YES | <input type="checkbox"/> NO | <input checked="" type="checkbox"/> YES | <input type="checkbox"/> NO | <input type="checkbox"/> YES | <input type="checkbox"/> NO |
| <input type="checkbox"/> YES | <input type="checkbox"/> NO | <input type="checkbox"/> YES | <input checked="" type="checkbox"/> NO | <input checked="" type="checkbox"/> YES | <input type="checkbox"/> NO |
| <input checked="" type="checkbox"/> YES | <input type="checkbox"/> NO | <input type="checkbox"/> YES | <input type="checkbox"/> NO | <input type="checkbox"/> YES | <input type="checkbox"/> NO |
| TANK CLEANED | | TANK DISINFECTED | | PIPES DISINFECTED | |
| <input checked="" type="checkbox"/> YES | <input type="checkbox"/> NO | <input checked="" type="checkbox"/> YES | <input type="checkbox"/> NO | <input type="checkbox"/> YES | <input type="checkbox"/> NO |
| | | | | <input checked="" type="checkbox"/> NA | |
| LAST CLEANING DATE | | CURRENT CLEANING DATE | | NEXT CLEANING DATE | |
| | | <i>22/09/2018</i> | | <i>22/09/2019</i> | |
| CHEMICALS & EQUIPMENTS USED | | | | | |
| 1. <i>Carbide bis and plus</i> Quantity <i>250ml</i> | | | | | |
| 2. _____ Quantity _____ | | | | | |
| <input type="checkbox"/> Submersibel Pump <input type="checkbox"/> High/Low Pressure Jet <input checked="" type="checkbox"/> Extension Cords <input type="checkbox"/> LED lights <input type="checkbox"/> Foot Bath <input type="checkbox"/> Ladder <input checked="" type="checkbox"/> Ventilating Fan <input type="checkbox"/> Suction/Discharge Hoses <input type="checkbox"/> Oxygen Meter <input type="checkbox"/> Vacuum Cleaner <input type="checkbox"/> Cleaning Materials | | | | | |
| COMMENTS & RECOMMENDATIONS: | | | | | |
| <i>mentioned water tank is cleaned and disinfected</i> | | | | | |
| Crystalline Representative: <i>Mona</i> | | | Signature: <i>Mona</i> | | |

Date of Cleaning: 22-09-2018

PHOTOGRAPHS
GROUND LEVEL GRP WATER TANK- 01

BEFORE



AFTER



CRYSTALLINE CLEANING & ENVIRONMENTAL SERVICES

CLEANING & DISINFECTION CERTIFICATE

POTABLE WATER TANKS

CLIENT NAME : AL REEM HOSPICO COMPANY LLC,
CLIENT ADDRESS : P.O. BOX: 81379, AL AIN, ABU DHABI.
CONTACT PERSON : MR. FERDINAND.
SITE DETAILS : AL WAGAN HOSPITAL, AL AIN, UAE.
DETAILS : WATER TANK CLEANING
DATE OF CLEANING : SEPTEMBER 2018
FREQUENCY OF CLEANING : EVERY YEAR
DATE OF NEXT CLEANING : SEPTEMBER 2019

The procedures employed in this cleaning and disinfection comply with HS (G) 70 health and safety guidelines for prevention of legionella as well as BS6700 and CARELA BIO PLUS method statement.

The entire water storage tank should be cleaned and disinfected minimum every six (6) months depending upon the condition.



CRYSTALLINE CLEANING AND ENVIRONMENTAL SERVICES