

# WATER TANK CLEANING & DISINFECTION COMPLETION REPORT



Client : GLOBAL EMIRATES SERVICES  
LLC

Contact Person: Mr. Syed Sameem

Site Details : GLOBAL VILLAGE-SHAH, ABU  
DHABI, UNITED ARAB  
EMIRATES

Date : 01 OCTOBER 2018



**CRYSTALLINE**  
ENVIRONMENTAL SERVICES

CRYSTALLINE ENVIRONMENTAL  
SERVICES

P.O. BOX 131463, Abu Dhabi, U.A.E.

TEL: 02 6508930 FAX: 02 6508942

[info@crystalline-uae.com](mailto:info@crystalline-uae.com)

[www.crystalline-uae.com](http://www.crystalline-uae.com)





# CRYSTALLINE ENVIRONMENTAL SERVICES

## WATER TANK - AFTER SERVICE REPORT

20751

CUSTOMER: <u>Global Emirate Services</u>			CONTACT PERSON: <u>Faisal</u>			
SITE DETAILS: <u>Global Village - Shah</u>			CONTACT NO: <u>050 - 604 3223</u>			
TANK DETAILS: <u>GRB TANK</u>			LOCATION DETAILS: <u>GROUND FLOOR</u>			
TYPE OF BUILDING: <input checked="" type="checkbox"/> COMMERCIAL		<input type="checkbox"/> RESIDENTIAL		<input type="checkbox"/> OTHERS		
<b>TYPE OF TANK</b>						
<input type="checkbox"/> CONCRETE	<input checked="" type="checkbox"/> GRP PANEL	<input type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input checked="" type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC	
<input type="checkbox"/> CONCRETE COATED		<input type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS			
<b>SIZE OF TANK</b>			<b>QUANTITY OF WATER</b>			
M3	<u>65000</u>	USG	L*B*H	<input type="checkbox"/> FULL	<input type="checkbox"/> HALF	<input type="checkbox"/> EMPTY
<b>CONDITION OF WATER TANK BEFORE CLEANING</b>			<b>CONDITION OF WATER TANK AFTER CLEANING</b>			
<input type="checkbox"/> CLEAN	<input checked="" type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY	
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	
<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	
<b>ACCESS</b>		<b>MANHOLE</b>		<input type="checkbox"/> COVERED	<input type="checkbox"/> DAMAGED	<input type="checkbox"/> NA
<b>LADDER IN</b>	<b>LADDER OUT</b>	<b>LEAKS</b>	<b>DRAIN LINE</b>	<b>VALVES</b>	<b>FLOAT VALVE</b>	
<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	
<b>TANK CLEANED</b>		<b>TANK DISINFECTED</b>		<b>PIPES DISINFECTED</b>		
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> YES	<input type="checkbox"/> NO <input checked="" type="checkbox"/> NA	
<b>LAST CLEANING DATE</b>		<b>CURRENT CLEANING DATE</b>		<b>NEXT CLEANING DATE</b>		
		<u>29 Sept. 2018</u>		<u>March 2019</u>		
<b>CHEMICALS &amp; EQUIPMENTS USED</b>						
1. <u>Carella Bro Plus</u> Quantity _____						
2. _____ Quantity _____						
<input checked="" type="checkbox"/> Submersibel   Pump <input type="checkbox"/> High /Low Pressure jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED Lights <input checked="" type="checkbox"/> Foot Bath <input type="checkbox"/> Ladder <input checked="" type="checkbox"/> Ventilating Fan <input type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Mater <input checked="" type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials						
<b>COMMENTS &amp; RECOMMENDATIONS:</b>						
<u>Water Tank has been cleaned &amp; disinfected</u>						
Crystalline Representative: <u>Faisal Bishal</u>			Signature: <u>[Signature]</u>			



**CRYSTALLINE**  
ENVIRONMENTAL SERVICES

Date of Cleaning: 29.09.2018


**PHOTOGRAPHS**  
**WATER TANK CLEANING- GRB TANK**

**WATER TANK CLEANING**

**BEFORE**



**AFTER**



**CLEANER WATER GREENER TOMORROW**

Date of Cleaning: 29.09.2018

**PHOTOGRAPHS**  
**WATER TANK CLEANING- GRB TANK**

**WATER TANK CLEANING**

**BEFORE**



**AFTER**



**CLEANER WATER GREENER TOMORROW**



# CRYSTALLINE ENVIRONMENTAL SERVICES

## WATER TANK - AFTER SERVICE REPORT

20752

CUSTOMER: <i>Global Emirates Service</i>			CONTACT PERSON: <i>Faisal</i>			
SITE DETAILS: <i>Global Village - Shoh</i>			CONTACT NO: <i>050 600 3223</i>			
TANK DETAILS: <i>CRB</i>			LOCATION DETAILS: <i>Ground floor</i>			
TYPE OF BUILDING: <input checked="" type="checkbox"/> COMMERCIAL		<input type="checkbox"/> RESIDENTIAL		<input type="checkbox"/> OTHERS		
<b>TYPE OF TANK</b>						
<input type="checkbox"/> CONCRETE	<input checked="" type="checkbox"/> GRP PANEL	<input type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input checked="" type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC	
<input type="checkbox"/> CONCRETE COATED		<input type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS			
<b>SIZE OF TANK</b>			<b>QUANTITY OF WATER</b>			
M3	<i>6000</i>	USG	L*B*H	<input type="checkbox"/> FULL	<input type="checkbox"/> HALF	<input type="checkbox"/> EMPTY
<b>CONDITION OF WATER TANK BEFORE CLEANING</b>			<b>CONDITION OF WATER TANK AFTER CLEANING</b>			
<input type="checkbox"/> CLEAN	<input checked="" type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY	
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	
<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	
<b>ACCESS</b>		<b>MANHOLE</b>		<input type="checkbox"/> COVERED	<input type="checkbox"/> DAMAGED	<input type="checkbox"/> NA
<b>LADDER IN</b>	<b>LADDER OUT</b>	<b>LEAKS</b>	<b>DRAIN LINE</b>	<b>VALVES</b>	<b>FLOAT VALVE</b>	
<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input type="checkbox"/> YES <input type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	
<b>TANK CLEANED</b>		<b>TANK DISINFECTED</b>		<b>PIPES DISINFECTED</b>		
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> YES	<input type="checkbox"/> NO <input checked="" type="checkbox"/> NA	
<b>LAST CLEANING DATE</b>		<b>CURRENT CLEANING DATE</b>		<b>NEXT CLEANING DATE</b>		
		<i>30 Sept 2018</i>		<i>March 2019</i>		
<b>CHEMICALS &amp; EQUIPMENTS USED</b>						
1. <i>Carbor Pro Phe</i> Quantity _____						
2. _____ Quantity _____						
<input checked="" type="checkbox"/> Submersibel   Pump <input checked="" type="checkbox"/> High /Low Pressure jet <input type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED Lights <input checked="" type="checkbox"/> Foot Bath <input type="checkbox"/> Ladder <input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Suction/Discharge Hoses <input type="checkbox"/> Oxygen Mater <input checked="" type="checkbox"/> Vacuum Cleaner <input type="checkbox"/> Cleaning Materials						
<b>COMMENTS &amp; RECOMMENDATIONS:</b>						
<i>Water tank has been cleaned &amp; Disinfected</i>						
Crystalline Representative: <i>Preshal</i>			Signature: <i>Am</i>			



**CRYSTALLINE**  
ENVIRONMENTAL SERVICES

Date of Cleaning: 30.09.2018

**PHOTOGRAPHS**  
**WATER TANK CLEANING- GRB TANK**

**WATER TANK CLEANING**

**BEFORE**



**AFTER**



**CLEANER WATER GREENER TOMORROW**



**CRYSTALLINE**  
ENVIRONMENTAL SERVICES

Date of Cleaning: 30.09.2018


**PHOTOGRAPHS**  
**WATER TANK CLEANING- GRB TANK**

**WATER TANK CLEANING**

**BEFORE**



**AFTER**



**CLEANER WATER GREENER TOMORROW**

# CRYSTALLINE CLEANING & ENVIRONMENTAL SERVICES

## CLEANING & DISINFECTION CERTIFICATE

### POTABLE WATER TANKS

CLIENT NAME : GLOBAL EMIRATES SERVICES LLC.  
CLIENT ADDRESS : P.O. BOX: 3916, ABU DHABI, UAE.  
CONTACT PERSON : MR. SYED SAMEEM  
SITE DETAILS : PLGLOBAL VILLAGE, SHAH, ABU DHABI,  
UNITED ARAB EMIRATES.  
DETAILS : WATER TANK CLEANING  
DATE OF CLEANING : SEPTEMBER 29 & 30, 2018  
FREQUENCY OF CLEANING : EVERY SIX MONTHS  
DATE OF NEXT CLEANING : MARCH 2019

*The procedures employed in this cleaning and disinfection comply with HS (G) 70 health and safety guidelines for prevention of legionella as well as BS6700 and CARELA BIO PLUS method statement.*

*The entire water storage tank should be cleaned and disinfected minimum every six (6) months depending upon the condition.*

CRYSTALLINE CLEANING AND ENVIRONMENTAL SERVICES

