

**KITCHEN EXHAUST SYSTEM
CLEANING
&
DIGREASING**

COMPLETION REPORT

For



Client: PETEK RESTAURANT &
SWEETS LLC.

Contact Person: MR. MUZZAMIL

Site Details: NEAR WTC, ABU DHABI, UAE.

Date: 01 OCTOBER 2018



CRYSTALLINE
ENVIRONMENTAL SERVICES

**Crystalline environmental
services**

P.O. Box 131463, Abu Dhabi, U.A.E.

Tel: 02 6508930 Fax: 02 6508942

info@crystalline-uae.com

www.crystalline-uae.com



KITCHEN EXHAUST SYSTEM – AFTER SERVICE REPORT

CUSTOMER: <i>patek Restaurant</i>	CONTACT PERSON: <i>muzamil</i>
SITE DETAILS: <i>Rolex-Tower</i>	CONTACT NO: <i>050-4578640</i>
NAME OF KITCHEN/DETAILS: <i>3-Ex fan</i>	LOCATION OF KITCHEN: <i>Roof-Top</i>

TYPE OF BUILDING: COMMERCIAL RESIDENTIAL EDUCATIONAL INDUSTRIAL

Roof-Top Total-3-fan

COOKING VOLUME	<input type="checkbox"/> HIGH	<input checked="" type="checkbox"/> MEDIUM	<input type="checkbox"/> LOW
TYPE OF FILTERS	<input checked="" type="checkbox"/> MESH	<input type="checkbox"/> BAFFLE	<input type="checkbox"/> N/A
FILTERS IN PLACE	<input type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> N/A
EXHAUST FAN	<input checked="" type="checkbox"/> UPBLAST	<input type="checkbox"/> INLINE	<input type="checkbox"/> UTILITY
CONDITION OF DUCT	<input type="checkbox"/> DAMAGED	<input checked="" type="checkbox"/> NOT DAMAGED	<input type="checkbox"/> N/A
FILTER CLEANING FREQUENCY	<input type="checkbox"/> DAILY	<input type="checkbox"/> WEEKLY	<input checked="" type="checkbox"/> MONTHLY
	<input type="checkbox"/> BIMONTHLY	<input type="checkbox"/> QUARTERLY	HALF YEARLY
DOORS/PLATES PRESENT	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	HOW MANY DOORS <u>1</u>
			HOW MANY PANELS <u>1</u>
DOORS/PANELS INSTALLED	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	HOW MANY DOORS <u>✓</u>
			HOW MANY PANELS <u>✓</u>
CONDITION OF ROOF/WALL	<input type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input checked="" type="checkbox"/> VERY DIRTY

CONDITION OF KITCHEN DUCT BEFORE CLEANING			CONDITION OF KITCHEN DUCT AFTER CLEANING		
<input type="checkbox"/> CLEAN	<input checked="" type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
LAST CLEANING DATE	CURRENT CLEANING DATE	NEXT CLEANING DATE			
	<i>26-09-2018</i>	<i>26-03-2019</i>			

CHEMICALS & EQUIPMENTS USED

degreaser chemical - used

- High/Low Pressure Jet Extension Cords LED Lights Ladder Ventilating Fan Degreaser Chemical Plastic Roll
- Vacuum Cleaner Cleaning Materials.

TEAM <i>Kitchen Team</i>	Crystalline <u>✓</u>	TEAM LEADER <i>Bishal</i>	<u>✓</u>
--------------------------	----------------------	---------------------------	----------

COMMENTS & RECOMMENDATIONS: *Kitchen duct & hood cleaning and disinfected*

The above kitchen exhaust duct was successfully degreased and cleaned as per local municipality guidelines.

Crystalline Representative: <i>Bishal Rai</i>	Signature: <i>[Signature]</i>
---	-------------------------------



KITCHEN EXHAUST SYSTEM – AFTER SERVICE REPORT

CUSTOMER: <u>pctek - Restaurant</u>	CONTACT PERSON: <u>muzamil</u>
SITE DETAILS: <u>Rolex - Tower</u>	CONTACT NO: <u>050-4578640</u>
NAME OF KITCHEN/DETAILS: <u>normal kitchen</u>	LOCATION OF KITCHEN: <u>Bestment-1</u>
TYPE OF BUILDING: <input checked="" type="checkbox"/> COMMERCIAL <input type="checkbox"/> RESIDENTIAL <input type="checkbox"/> EDUCATIONAL <input type="checkbox"/> INDUSTRIAL	

Bestment - Total - 2 hood

COOKING VOLUME	<input type="checkbox"/> HIGH	<input checked="" type="checkbox"/> MEDIUM	<input type="checkbox"/> LOW
TYPE OF FILTERS	<input checked="" type="checkbox"/> MESH	<input type="checkbox"/> BAFFLE	<input type="checkbox"/> N/A
FILTERS IN PLACE	<input type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> N/A
EXHAUST FAN	<input checked="" type="checkbox"/> UPBLAST	<input type="checkbox"/> INLINE	<input type="checkbox"/> UTILITY
CONDITION OF DUCT	<input type="checkbox"/> DAMAGED	<input checked="" type="checkbox"/> NOT DAMAGED	<input type="checkbox"/> N/A
FILTER CLEANING FREQUENCY	<input type="checkbox"/> DAILY	<input type="checkbox"/> WEEKLY	<input checked="" type="checkbox"/> MONTHLY
	<input type="checkbox"/> BIMONTHLY	<input type="checkbox"/> QUARTERLY	HALF YEARLY
DOORS/PLATES PRESENT	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	HOW MANY DOORS <u>2</u>
			HOW MANY PANELS <u>2</u>
DOORS/PANELS INSTALLED	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	HOW MANY DOORS <u>✓</u>
			HOW MANY PANELS <u>✓</u>
CONDITION OF ROOF/WALL	<input type="checkbox"/> CLEAN	<input checked="" type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY

CONDITION OF KITCHEN DUCT BEFORE CLEANING			CONDITION OF KITCHEN DUCT AFTER CLEANING		
<input type="checkbox"/> CLEAN	<input checked="" type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY

LAST CLEANING DATE	CURRENT CLEANING DATE	NEXT CLEANING DATE
	<u>25-09-2018</u>	<u>25-03-2019</u>

CHEMICALS & EQUIPMENTS USED
degreaser chemical - USED

- High/Low Pressure Jet Extension Cords LED Lights Ladder Ventilating Fan Degreaser Chemical Plastic Roll
- Vacuum Cleaner Cleaning Materials.

TEAM <u>Kitchen Team</u> Crystalline <u>✓</u>	TEAM LEADER <u>Bishal</u> <u>✓</u>
---	------------------------------------

COMMENTS & RECOMMENDATIONS: Kitchen duct & hood cleaning and disinfected
The above kitchen exhaust duct was successfully degreased and cleaned as per local municipality guidelines.

Crystalline Representative: <u>Bishal Rai</u>	Signature: <u>[Signature]</u>
---	-------------------------------



KITCHEN EXHAUST SYSTEM – AFTER SERVICE REPORT

CUSTOMER: <u>petek Restaurant</u>		CONTACT PERSON: <u>muzamil</u>	
SITE DETAILS: <u>Rolox - Tower</u>		CONTACT NO: <u>050478640</u>	
NAME OF KITCHEN/DETAILS: <u>main kitchen - Tand</u>		LOCATION OF KITCHEN: <u>level - 7</u>	
TYPE OF BUILDING: <input checked="" type="checkbox"/> COMMERCIAL <input type="checkbox"/> RESIDENTIAL <input type="checkbox"/> EDUCATIONAL <input type="checkbox"/> INDUSTRIAL			
<u>level - 7 Total - 2 hood</u>			
COOKING VOLUME	<input type="checkbox"/> HIGH	<input checked="" type="checkbox"/> MEDIUM	<input type="checkbox"/> LOW
TYPE OF FILTERS	<input type="checkbox"/> MESH	<input checked="" type="checkbox"/> BAFFLE	<input type="checkbox"/> N/A
FILTERS IN PLACE	<input type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> N/A
EXHAUST FAN	<input checked="" type="checkbox"/> UPBLAST	<input type="checkbox"/> INLINE	<input type="checkbox"/> UTILITY
CONDITION OF DUCT	<input type="checkbox"/> DAMAGED	<input checked="" type="checkbox"/> NOT DAMAGED	<input type="checkbox"/> N/A
FILTER CLEANING FREQUENCY	<input type="checkbox"/> DAILY	<input type="checkbox"/> WEEKLY	<input checked="" type="checkbox"/> MONTHLY
	<input type="checkbox"/> BIMONTHLY	<input type="checkbox"/> QUARTERLY	HALF YEARLY <input checked="" type="checkbox"/>
DOORS/PLATES PRESENT	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	HOW MANY DOORS <u>2</u>
			HOW MANY PANELS <u>3</u>
DOORS/PANELS INSTALLED	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	HOW MANY DOORS <input checked="" type="checkbox"/>
			HOW MANY PANELS <input checked="" type="checkbox"/>
CONDITION OF ROOF/WALL	<input type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input checked="" type="checkbox"/> VERY DIRTY
<u>CONDITION OF KITCHEN DUCT BEFORE CLEANING</u>		<u>CONDITION OF KITCHEN DUCT AFTER CLEANING</u>	
<input type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input checked="" type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN
			<input type="checkbox"/> DIRTY
			<input type="checkbox"/> VERY DIRTY
<u>LAST CLEANING DATE</u>		<u>CURRENT CLEANING DATE</u>	
		<u>25-09-2019</u>	
		<u>25-03-2019</u>	
<u>CHEMICALS & EQUIPMENTS USED</u>			
<u>degreaser chemical - USED</u>			
<input checked="" type="checkbox"/> High/Low Pressure Jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED Lights <input checked="" type="checkbox"/> Ladder <input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Degreaser Chemical <input type="checkbox"/> Plastic Roll <input type="checkbox"/> Vacuum Cleaner <input type="checkbox"/> Cleaning Materials.			
TEAM <u>Kitchen - Team</u>	Crystalline <input checked="" type="checkbox"/>	TEAM LEADER <u>Bishal Rai</u>	<input checked="" type="checkbox"/>
<u>COMMENTS & RECOMMENDATIONS:</u> <u>Kitchen duct & hood cleaning and disinfected</u>			
The above kitchen exhaust duct was successfully degreased and cleaned as per local municipality guidelines.			
Crystalline Representative: <u>Bishal - Rai</u>		Signature: <u>Bishal Rai</u>	



KITCHEN EXHAUST SYSTEM – AFTER SERVICE REPORT

CUSTOMER: <i>petek - Restaurant</i>	CONTACT PERSON: <i>muzamil</i>
SITE DETAILS: <i>Rolex - Tower</i>	CONTACT NO: <i>050-4578640</i>
NAME OF KITCHEN/DETAILS: <i>normal kitchen</i>	LOCATION OF KITCHEN: <i>ground floor</i>
TYPE OF BUILDING: <input checked="" type="checkbox"/> COMMERCIAL <input type="checkbox"/> RESIDENTIAL <input type="checkbox"/> EDUCATIONAL <input type="checkbox"/> INDUSTRIAL	

COOKING VOLUME	<input type="checkbox"/> HIGH	<input checked="" type="checkbox"/> MEDIUM	<input type="checkbox"/> LOW
TYPE OF FILTERS	<input checked="" type="checkbox"/> MESH	<input type="checkbox"/> BAFFLE	<input type="checkbox"/> N/A
FILTERS IN PLACE	<input type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> N/A
EXHAUST FAN	<input checked="" type="checkbox"/> UPBLAST	<input type="checkbox"/> INLINE	<input type="checkbox"/> UTILITY
CONDITION OF DUCT	<input type="checkbox"/> DAMAGED	<input checked="" type="checkbox"/> NOT DAMAGED	<input type="checkbox"/> N/A
FILTER CLEANING FREQUENCY	<input type="checkbox"/> DAILY	<input type="checkbox"/> WEEKLY	<input checked="" type="checkbox"/> MONTHLY
	<input type="checkbox"/> BIMONTHLY	<input type="checkbox"/> QUARTERLY	HALF YEARLY
DOORS/PLATES PRESENT	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	HOW MANY DOORS <i>2</i>
			HOW MANY PANELS <i>2</i>
DOORS/PANELS INSTALLED	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	HOW MANY DOORS <input checked="" type="checkbox"/>
			HOW MANY PANELS <input checked="" type="checkbox"/>
CONDITION OF ROOF/WALL	<input type="checkbox"/> CLEAN	<input checked="" type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY

<u>CONDITION OF KITCHEN DUCT BEFORE CLEANING</u>			<u>CONDITION OF KITCHEN DUCT AFTER CLEANING</u>		
<input type="checkbox"/> CLEAN	<input checked="" type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY

<u>LAST CLEANING DATE</u>	<u>CURRENT CLEANING DATE</u>	<u>NEXT CLEANING DATE</u>
	<i>25-09-2018</i>	<i>25-03-2019</i>

CHEMICALS & EQUIPMENTS USED

degreaser chemical

High/Low Pressure Jet Extension Cords LED Lights Ladder Ventilating Fan Degreaser Chemical Plastic Roll

Vacuum Cleaner Cleaning Materials.

TEAM <i>Kitchen Team</i>	Crystalline <input checked="" type="checkbox"/>	TEAM LEADER <i>Bishal</i>	<input checked="" type="checkbox"/>
---------------------------------	---	----------------------------------	-------------------------------------

COMMENTS & RECOMMENDATIONS: *Kitchen duct & hood cleaning and disinfected*

The above kitchen exhaust duct was successfully degreased and cleaned as per local municipality guidelines.

Crystalline Representative: <i>Bishal-Rai</i>	Signature: <i>[Signature]</i>
--	--------------------------------------



CRYSTALLINE
ENVIRONMENTAL SERVICES

Date of Cleaning: 25.09.2018


PHOTOGRAPHS
KITCHEN HOOD –PETEK RESTAURANT

KITCHEN HOOD CLEANING

BEFORE



AFTER



CLEANER WATER GREENER TOMORROW

Date of Cleaning: 25.09.2018


PHOTOGRAPHS
KITCHEN HOOD –PETEK RESTAURANT

KITCHEN HOOD CLEANING

BEFORE



AFTER





Date of Cleaning: 25.09.2018


PHOTOGRAPHS
KITCHEN HOOD –PETEK RESTAURANT

KITCHEN HOOD CLEANING

BEFORE



AFTER





CRYSTALLINE
ENVIRONMENTAL SERVICES

Date of Cleaning: 25.09.2018

PHOTOGRAPHS
KITCHEN HOOD –PETEK RESTAURANT

KITCHEN HOOD CLEANING

BEFORE



AFTER



CLEANER WATER GREENER TOMORROW

Date of Cleaning: 25.09.2018

PHOTOGRAPHS
KITCHEN HOOD –PETEK RESTAURANT

KITCHEN HOOD CLEANING

BEFORE



AFTER





CRYSTALLINE
ENVIRONMENTAL SERVICES

Date of Cleaning: 25.09.2018


PHOTOGRAPHS
KITCHEN HOOD –PETEK RESTAURANT

KITCHEN HOOD CLEANING

BEFORE



AFTER



CLEANER WATER GREENER TOMORROW

Date of Cleaning: 26.09.2018


PHOTOGRAPHS
KITCHEN HOOD –PETEK RESTAURANT

KITCHEN HOOD CLEANING

BEFORE



AFTER





CRYSTALLINE
ENVIRONMENTAL SERVICES

Date of Cleaning: 26.09.2018

PHOTOGRAPHS
KITCHEN HOOD –PETEK RESTAURANT

KITCHEN HOOD CLEANING

BEFORE



AFTER



CLEANER WATER GREENER TOMORROW

Date of Cleaning: 26.09.2018

PHOTOGRAPHS
KITCHEN HOOD –PETEK RESTAURANT

KITCHEN HOOD CLEANING

BEFORE



AFTER





CRYSTALLINE
ENVIRONMENTAL SERVICES

Date of Cleaning: 26.09.2018

PHOTOGRAPHS
KITCHEN HOOD –PETEK RESTAURANT

KITCHEN HOOD CLEANING

BEFORE



AFTER



CLEANER WATER GREENER TOMORROW



METHODOLOGY:

- ✓ Preliminary site visit. To choose the effective procedure.
- ✓ Live Camera Inspection for the internal duct.
- ✓ Safety clothing/equipment required: overalls, safety boots, eye protection, gloves and correct respirators.
- ✓ Conduct safety briefing with client's representative to ensure all possible hazards are identified and reported immediately if assistance is required for the control of hazards.
- ✓ Ensure spill control Kit and fire extinguisher is available.
- ✓ Digital photo taken for the proof of cleaning process.
- ✓ Access holes in ducts shall be cut if required.
- ✓ Fans shall be isolated and warning labels should be placed on isolation switches.
- ✓ Areas of duct to be cleaned to bare metal.
- ✓ Toxic or flammable products shall not be used.
- ✓ Waste rags and lint will be disposed of in the clients waste disposal facilities.
- ✓ Record any areas unable to be cleaned giving exact reasons.

If you have any queries concerning our services, please contact: +971 2 6508930

Thank you for your business!

Crystalline Cleaning & Environmental Services

CRYSTALLINE CLEANING & ENVIRONMENTAL SERVICES

CLEANING & DISINFECTION CERTIFICATE

CLIENT NAME

: PETEK RESTAURANT & SWEETS LLC

CLIENT ADDRESS

: P.O. BOX , ABU DHABI, UAE.

CONTACT PERSON

: MR. MUZZAMIL

SITE DETAILS

: NEAR WTC, ABU DHABI, UAE.

DETAILS

: KITCHEN EXHAUST SYSTEM CLEANING

DATE OF CLEANING

: SEPTEMBER 2018

FREQUENCY OF CLEANING

: EVERY SIX (6) MONTHS

DATE OF NEXT CLEANING

: MARCH 2019

The procedures employed in this cleaning and degreasing comply with Abu Dhabi Municipality guidelines

The entire Kitchen Duct should be cleaned and degreased minimum every SIX (6) months depending upon the condition.

CRYSTALLINE CLEANING AND ENVIRONMENTAL SERVICES