

**KITCHEN EXHAUST SYSTEM
CLEANING
&
DISINFECTION**

COMPLETION REPORT

For



Client: Emirates Palace Abu Dhabi.
Contact Person: Mr. Abdul Majeed
Finance Chief Accountant
Site Details: Emirates Palace Abu Dhabi, UAE.
Date: 21 October 2018



CRYSTALLINE
ENVIRONMENTAL SERVICES

**Crystalline Environmental
Services**

P.O. Box 131463, Abu Dhabi, U.A.E.

Tel: 02 6508930 Fax: 02 6508942

info@crystalline-uae.com

www.crystalline-uae.com



KITCHEN EXHAUST SYSTEM – AFTER SERVICE REPORT

CUSTOMER: <u>Emirates palace</u>		CONTACT PERSON: <u>Kasim</u>	
SITE DETAILS: <u>Emirates palace</u>		CONTACT NO: <u>050-8119065</u>	
NAME OF KITCHEN/DETAILS: <u>Mawal kitchen</u>		LOCATION OF KITCHEN: <u>level-1</u>	
TYPE OF BUILDING: <input checked="" type="checkbox"/> COMMERCIAL <input type="checkbox"/> RESIDENTIAL <input type="checkbox"/> EDUCATIONAL <input type="checkbox"/> INDUSTRIAL			
<u>kitchen duct cleaned & disinfected</u>			
COOKING VOLUME	<input checked="" type="checkbox"/> HIGH	<input type="checkbox"/> MEDIUM	<input type="checkbox"/> LOW
TYPE OF FILTERS	<input checked="" type="checkbox"/> MESH	<input type="checkbox"/> BAFFLE	<input type="checkbox"/> N/A
FILTERS IN PLACE	<input type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> N/A
EXHAUST FAN	<input checked="" type="checkbox"/> UPBLAST	<input type="checkbox"/> INLINE	<input type="checkbox"/> UTILITY
CONDITION OF DUCT	<input type="checkbox"/> DAMAGED	<input checked="" type="checkbox"/> NOT DAMAGED	<input type="checkbox"/> N/A
FILTER CLEANING FREQUENCY	<input type="checkbox"/> DAILY	<input type="checkbox"/> WEEKLY	<input type="checkbox"/> MONTHLY
	<input type="checkbox"/> BIMONTHLY	<input type="checkbox"/> QUARTERLY	HALF YEARLY <input checked="" type="checkbox"/>
DOORS/PLATES PRESENT	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	HOW MANY DOORS <u>02</u> HOW MANY PANELS <u>03</u>
DOORS/PANELS INSTALLED	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	HOW MANY DOORS <input checked="" type="checkbox"/> HOW MANY PANELS <input checked="" type="checkbox"/>
CONDITION OF ROOF/WALL	<input type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input checked="" type="checkbox"/> VERY DIRTY
CONDITION OF KITCHEN DUCT BEFORE CLEANING		CONDITION OF KITCHEN DUCT AFTER CLEANING	
<input type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input checked="" type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN
			<input type="checkbox"/> DIRTY
			<input type="checkbox"/> VERY DIRTY
LAST CLEANING DATE		CURRENT CLEANING DATE	
		<u>14-10-2018</u>	
		<u>14-04-2019</u>	
<u>CHEMICALS & EQUIPMENTS USED</u>			
<input checked="" type="checkbox"/> High/Low Pressure Jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED Lights <input checked="" type="checkbox"/> Ladder <input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Degreaser Chemical <input type="checkbox"/> Plastic Roll <input checked="" type="checkbox"/> Vacuum Cleaner <input type="checkbox"/> Cleaning Materials.			
TEAM <u>works</u>	<input checked="" type="checkbox"/>	TEAM LEADER <u>Bishal shankar</u>	
COMMENTS & RECOMMENDATIONS: <u>kitchen hood & duct Exhaust fan oil filter</u>			
The above kitchen exhaust duct was successfully degreased and cleaned as per local municipality guidelines.			
Crystalline Representative: <u>Bishal Rai</u>		Signature: <u>[Signature]</u>	

hood-3 Exhaust fan-2 duct 2 oil filter-3 cleaned



CRYSTALLINE
ENVIRONMENTAL SERVICES


Date of Cleaning: 14-10-2018

PHOTOGRAPHS
KITCHEN HOOD CLEANING- EMIRATES PALACE

BEFORE



AFTER



CLEANER WATER GREENER TOMORROW



CRYSTALLINE
ENVIRONMENTAL SERVICES



Date of Cleaning: 14-10-2018

PHOTOGRAPHS
KITCHEN HOOD CLEANING- EMIRATES PALACE

BEFORE



AFTER



CLEANER WATER GREENER TOMORROW



CRYSTALLINE
ENVIRONMENTAL SERVICES


Date of Cleaning: 14-10-2018

PHOTOGRAPHS
KITCHEN HOOD CLEANING- EMIRATES PALACE

BEFORE



AFTER



CLEANER WATER GREENER TOMORROW


Date of Cleaning: 14-10-2018

PHOTOGRAPHS
KITCHEN HOOD CLEANING- EMIRATES PALACE

BEFORE



AFTER





CRYSTALLINE
ENVIRONMENTAL SERVICES

Date of Cleaning: 14-10-2018

PHOTOGRAPHS

KITCHEN HOOD, EXHAUST FAN & DUCT CLEANING- EMIRATES PALACE

BEFORE



AFTER



CLEANER WATER GREENER TOMORROW



CRYSTALLINE
ENVIRONMENTAL SERVICES

Date of Cleaning: 14-10-2018

PHOTOGRAPHS

KITCHEN HOOD, EXHAUST FAN & DUCT CLEANING- EMIRATES PALACE

BEFORE



AFTER



CLEANER WATER GREENER TOMORROW



CRYSTALLINE
ENVIRONMENTAL SERVICES

Date of Cleaning: 14-10-2018

PHOTOGRAPHS

KITCHEN HOOD, EXHAUST FAN & DUCT CLEANING- EMIRATES PALACE

BEFORE



AFTER



CLEANER WATER GREENER TOMORROW



CRYSTALLINE
ENVIRONMENTAL SERVICES

Date of Cleaning: 14-10-2018


PHOTOGRAPHS

KITCHEN HOOD, EXHAUST FAN & DUCT CLEANING- EMIRATES PALACE

BEFORE



AFTER



CLEANER WATER GREENER TOMORROW




CRYSTALLINE
ENVIRONMENTAL SERVICES

Date of Cleaning: 14-10-2018


PHOTOGRAPHS

KITCHEN HOOD, EXHAUST FAN & DUCT CLEANING- EMIRATES PALACE

BEFORE



AFTER



CLEANER WATER GREENER TOMORROW



METHODOLOGY:

- ✓ Preliminary site visit. To choose the effective procedure.
- ✓ Live Camera Inspection for the internal duct.
- ✓ Safety clothing/equipment required: overalls, safety boots, eye protection, gloves and correct respirators.
- ✓ Conduct safety briefing with client's representative to ensure all possible hazards are identified and reported immediately if assistance is required for the control of hazards.
- ✓ Ensure spill control Kit and fire extinguisher is available.
- ✓ Digital photo taken for the proof of cleaning process.
- ✓ Access holes in ducts shall be cut if required.
- ✓ Fans shall be isolated and warning labels should be placed on isolation switches.
- ✓ Areas of duct to be cleaned to bare metal.
- ✓ Toxic or flammable products shall not be used.
- ✓ Waste rags and lint will be disposed of in the client's waste disposal facilities.
- ✓ Record any areas unable to be cleaned giving exact reasons.

If you have any queries concerning our services, please contact: +971 2 6508930

Thank you for your business!

Crystalline Cleaning & Environmental Services

CRYSTALLINE CLEANING & ENVIRONMENTAL SERVICES

CLEANING & DISINFECTION CERTIFICATE

CLIENT NAME : EMIRATES PALACE ABU DHABI.
CLIENT ADDRESS : P.O BOX: 39999, ABU DHABI, UAE.
CONTACT PERSON : MR. ABDUL MAJEED.
SITE DETAILS : EMIRATES PALACE ABU DHABI, UAE.
DETAILS : KITCHEN HOOD CLEANING
DATE OF CLEANING : 14 OCTOBER 2018
FREQUENCY OF CLEANING : EVERY SIX (6) MONTHS
DATE OF NEXT CLEANING : 14 APRIL 2019

The procedures employed in this cleaning and disinfection comply with Abu Dhabi Municipality guidelines

The entire Kitchen Duct should be cleaned and disinfected minimum every six (6) months depending upon the condition.



CRYSTALLINE CLEANING AND ENVIRONMENTAL SERVICES