

**CLEANING & FLUSHING OF  
FLOOR DRAIN LINE  
COMPLETION REPORT**

**For**



Client : EMRILL FACILITY MGT.  
Contact Person: Mr. Venkatesh Subramaniam  
Facilities Manager  
Site Details : IPIC Tower, Abu Dhabi, UAE.  
Date : 08 November 2018



**CRYSTALLINE**  
ENVIRONMENTAL SERVICES

**Crystalline environmental  
services**

P.O. Box 131463, Abu Dhabi, U.A.E.

Tel: 02 6508930 Fax: 02 6508942

[info@crystalline-uae.com](mailto:info@crystalline-uae.com)

[www.crystalline-uae.com](http://www.crystalline-uae.com)



# CRYSTALLINE ENVIRONMENTAL SERVICES

1167

## MANHOLE, GULLY TRAP, DRAINAGE - AFTER SERVICE REPORT

CUSTOMER: <b>EMRILL</b>	CONTACT PERSON: <b>Mr. Venkatesh</b>
SITE DETAILS: <b>IPIC TOWER</b>	CONTACT NUMBER: <b>0507080469</b>
NAME OF MANHOLE: <b>Drain Line Jetting</b>	LOCALISATION: <b>Basement 1 Garbage room</b>
TYPE OF BUILDING: <input checked="" type="checkbox"/> COMMERCIAL <input type="checkbox"/> EDUCATIONAL <input type="checkbox"/> RESIDENCIAL <input type="checkbox"/> INDUSTRIAL	

### PART OF DRAINAGE

MANHOLE     UNDERGROUND DRAINAGE PIPE     GULLY TRAP     GREASE TRAP  
 DRAINAGE PIPE     APPARENT DRAINAGE PIPE     EMBEDDED DRAINAGE PIPE

### CONDITION OF MANHOLE, GULLY TRAP, DRAINAGE BEFORE CLEANING

LITTLE DIRTY     DIRTY     VERY DIRTY     RUST     SEDIMENTS     MUD  
 BIOFILMS     SLIME     GREASE     ROOT     SAND     MOULDS  
 OBSTRUCT     BLOCK     FLUENT FLOW     LOW FLOW     ANOTHER: \_\_\_\_\_

<b>MANHOLE BLOCKED</b>	<b>GULLY TRAP BLOCKED</b>	<b>DRAINAGE BLOCKED</b>	<b>ALL BLOCKED</b>
<input type="checkbox"/> YES <input type="checkbox"/> NO	<input type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

### COMMENTS:

MANHOLE AND GULLY TRAP COVER:  COVERED     DAMAGED     BLOCKED     ADAPTED

### CONDITION OF MANHOLE, GULLY TRAP, DRAINAGE AFTER CLEANING

LITTLE CLEAN     CLEAN     VERY CLEAN     FLUENT FLOW     LOW FLOW     UNBLOCK

	MANHOLE	GULLY TRAP	STORM WATER	DRAINAGE	TOTAL
NUMBER OF MANHOLE CLEANED				1	1
NUMBER OF MANHOLE BLOCKED				1	1

### ACCESS

LADDER IN     NO LADDER

<b>MANHOLE CLEANED</b>	<b>GULLY TRAP CLEANED</b>	<b>DRAINAGE CLEANED</b>	<b>ALL DISINFECTED</b>
<input type="checkbox"/> YES <input type="checkbox"/> NO	<input type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input type="checkbox"/> YES <input type="checkbox"/> NO

### SERVICES OF DATES

LAST CLEANING DATE	<i>service</i> LAST CLEANING DATE	<i>next</i> LAST CLEANING DATE
	31/10/2018	31/04/2018

### CHEMICALS AND EQUIPMENTS USED

PRESSURE MACHINE     JETTING MACHINE     MULTIGAS DETECTEUR     INLET WATER HOSE  
 EXTENTION CORDS     VACCUM CLEANER     VENTILATION FAN     CLEANING MAT  
 LED LIGHTS     PLASTICS ROLL     PLASTICS BAGS     SUITABLE PPE  
 TRIPOD     AIR REPAIR 7D-A     DEGREASER CHEMICAL     LADDER

### COMMENTS AND RECOMMENDATION:

*Above mention drain pipe well cleaned and disinfected.*

Crystalline representative: <b>Kennedy Wah</b>	Signature: <i>Kennedy Wah</i>
Customer/Customer representative: <b>Mr. Venkatesh</b>	Signature: <b>0507080469</b>





**CRYSTALLINE**  
ENVIRONMENTAL SERVICES

Date of Cleaning: 31-10-2018

**PHOTOGRAPHS**  
**DRAINLINE JETTING - EMRILL**

**BEFORE**



**AFTER**



**CLEANER WATER GREENER TOMORROW**



# CRYSTALLINE ENVIRONMENTAL SERVICES

1168

## MANHOLE, GULLY TRAP, DRAINAGE - AFTER SERVICE REPORT

CUSTOMER: <b>EMRILL</b>	CONTACT PERSON: <b>Mr. Venkatesh</b>
SITE DETAILS: <b>IPIC TOWAH</b>	CONTACT NUMBER: <b>0507080469</b>
NAME OF MANHOLE: <b>Drain Line Jetting</b>	LOCALISQTION: <b>Ground Floor</b>
TYPE OF BUILDING: <input checked="" type="checkbox"/> COMMERCIAL <input type="checkbox"/> EDUCATIONAL <input type="checkbox"/> RESIDENCIAL <input type="checkbox"/> INDUSTRIAL	

### PART OF DRAINAGE

MANHOLE  UNDERGROUND DRAINAGE PIPE  GULLY TRAP  GREASE TRAP

DRAINAGE PIPE  APPARENT DRAINAGE PIPE  EMBEDDED DRAINAGE PIPE

### CONDITION OF MANHOLE, GULLY TRAP, DRAINAGE BEFORE CLEANING

LITTLE DIRTY  DIRTY  VERY DIRTY  RUST  SEDIMENTS  MUD

BIOFILMS  SLIME  GREASE  ROOT  SAND  MOULDS

OBSTRUCT  BLOCK  FLUENT FLOW  LOW FLOW  ANOTHER: \_\_\_\_\_

MANHOLE BLOCKED	GULLY TRAP BLOCKED	DRAINAGE BLOCKED	ALL BLOCKED
<input type="checkbox"/> YES <input type="checkbox"/> NO	<input type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input type="checkbox"/> YES <input type="checkbox"/> NO

### COMMENTS:

MANHOLE AND GULLY TRAP COVER:  COVERED  DAMAGED  BLOCKED  ADAPTED

### CONDITION OF MANHOLE, GULLY TRAP, DRAINAGE AFTER CLEANING

LITTLE CLEAN  CLEAN  VERY CLEAN  FLUENT FLOW  LOW FLOW  UNBLOCK

	MANHOLE	GULLY TRAP	STORM WATER	DRAINAGE	TOTAL
NUMBER OF MANHOLE CLEANED				<b>1</b>	<b>1</b>
NUMBER OF MANHOLE BLOCKED				<b>1</b>	<b>1</b>

### ACCESS

LADDER IN  NO LADDER

MANHOLE CLEANED	GULLY TRAP CLEANED	DRAINAGE CLEANED	ALL DISINFECTED
<input type="checkbox"/> YES <input type="checkbox"/> NO	<input type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO

### SERVICES OF DATES

LAST CLEANING DATE	<i>service</i> LAST CLEANING DATE	<i>next</i> LAST CLEANING DATE
	<b>31/10/2018</b>	<b>31/04/2018</b>

### CHEMICALS AND EQUIPMENTS USED

PRESSURE MACHINE  JETTING MACHINE  MULTIGAS DETECTEUR  INLET WATER HOSE

EXTENTION CORDS  VACCUM CLEANER  VENTILATION FAN  CLEANING MAT

LED LIGHTS  PLASTICS ROLL  PLASTICS BAGS  SUITABLE PPE

TRIPOD  AIR REPAIR 7D-A  DEGREASER CHEMICAL  LADDER

### COMMENTS AND RECOMMENDATION:

*Above drain pipe well cleaned and disinfected.*

Crystalline representative: <b>Kennedy Nah</b>	Signature: <i>[Signature]</i>
Customer/Customer representative: <b>Mr. Venkatesh</b>	Signature: <b>0507080469</b>



**CRYSTALLINE**  
ENVIRONMENTAL SERVICES

Date of Cleaning: 31-10-2018

**PHOTOGRAPHS**  
**DRAINLINE JETTING - EMRILL**

**BEFORE**



**AFTER**



**CLEANER WATER GREENER TOMORROW**

# CRYSTALLINE CLEANING & ENVIRONMENTAL SERVICES

## CLEANING & DISINFECTION CERTIFICATE

CLIENT NAME : EMRILL FACILITY MANAGEMENT.  
CLIENT ADDRESS : P.O. BOX: 108388, ABU DHABI, UAE.  
CONTACT PERSON : MR. VENKATESH SUBRAMANIAM.  
SITE DETAILS : IPIC TOWER, ABU DHABI, UAE.  
DETAILS : CLEANING & FLUSHING PIPELINE  
DATE OF CLEANING : 31 OCTOBER 2018  
FREQUENCY OF CLEANING : EVERY SIX (6) MONTHS  
DATE OF NEXT CLEANING : 30 APRIL 2019

*The procedures employed in this cleaning and disinfection comply with Abu Dhabi Municipality guidelines.*

*The entire Drain line should be cleaned and disinfected minimum every six (6) months depending upon the condition.*



CRYSTALLINE CLEANING AND ENVIRONMENTAL SERVICES