

# WATER TANK CLEANING & DISINFECTION

## COMPLETION REPORT

FOR



شركة الراها للعقارات  
AL RAHA VILLAGE PROPERTIES L.L.C

Client : AL RAHA VILLAGE  
PROPERTIES LLC.  
Contact Person: Mr. Bejoy Thomas Zachariah  
Manager Hygiene & Quality Dept.  
Site Details : Al Raha Village, Abu Dhabi.  
Date : 11 November 2018



**CRYSTALLINE**  
ENVIRONMENTAL SERVICES

CRYSTALLINE ENVIRONMENTAL  
SERVICES

P.O. BOX 131463, Abu Dhabi, U.A.E.  
TEL: 02 6508930 FAX: 02 6508942

[info@crystalline-uae.com](mailto:info@crystalline-uae.com)

[www.crystalline-uae.com](http://www.crystalline-uae.com)





# CRYSTALLINE ENVIRONMENTAL SERVICES

## WATER TANK - AFTER SERVICE REPORT

20879

CUSTOMER: <i>Al Raha Village</i>			CONTACT PERSON: <i>Mr. Alim</i>		
SITE DETAILS: <i>Baniyas</i>			CONTACT NO: <i>056 38 93 208</i>		
TANK DETAILS: <i>Br 12-P Water Tank</i>			LOCATION DETAILS: <i>Near Admin</i>		
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL <input type="checkbox"/> RESIDENTIAL <input type="checkbox"/> OTHERS					
<b>TYPE OF TANK</b>					
<input type="checkbox"/> CONCRETE	<input checked="" type="checkbox"/> GRP PANEL	<input type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED		<input type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS		
<b>SIZE OF TANK</b>			<b>QUANTITY OF WATER</b>		
M3	USG	L*B*H	<input type="checkbox"/> FULL	<input checked="" type="checkbox"/> HALF	<input type="checkbox"/> EMPTY
<b>CONDITION OF WATER TANK BEFORE CLEANING</b>			<b>CONDITION OF WATER TANK AFTER CLEANING</b>		
<input type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input checked="" type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
<b>ACCESS</b>		<b>MANHOLE</b>	<input checked="" type="checkbox"/> COVERED	<input type="checkbox"/> DAMAGED	<input type="checkbox"/> NA
<b>LADDER IN</b>	<b>LADDER OUT</b>	<b>LEAKS</b>	<b>DRAIN LINE</b>	<b>VALVES</b>	<b>FLOAT VALVE</b>
<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO
<b>TANK CLEANED</b>		<b>TANK DISINFECTED</b>		<b>PIPES DISINFECTED</b>	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> YES	<input type="checkbox"/> NO <input type="checkbox"/> NA
<b>LAST CLEANING DATE</b>		<b>CURRENT CLEANING DATE</b>		<b>NEXT CLEANING DATE</b>	
		<i>16/10/2018</i>		<i>16/10/2019</i>	
<b>CHEMICALS &amp; EQUIPMENTS USED</b>					
1. <i>Carbox bio and plus</i> Quantity <i>250 ml</i>					
2. _____ Quantity _____					
<input checked="" type="checkbox"/> Submersibel   Pump <input type="checkbox"/> High /Low Pressure jet <input type="checkbox"/> Extension Cords <input type="checkbox"/> LED Lights <input type="checkbox"/> Foot Bath <input type="checkbox"/> Ladder <input type="checkbox"/> Ventilating Fan <input type="checkbox"/> Suction/Discharge Hoses <input type="checkbox"/> Oxygen Mater <input type="checkbox"/> Vacuum Cleaner <input type="checkbox"/> Cleaning Materials					
<b>COMMENTS &amp; RECOMMENDATIONS:</b>					
<i>mentioned water tank is cleaned and disinfected</i>					
Crystalline Representative: <i>Mary</i>			Signature: <i>[Signature]</i>		


*[Signature]*  
*16/10/2018*

*[Signature]*  
*16/10/2018*

Date of Cleaning: 16-10-2018

**PHOTOGRAPHS**  
**GRP WATER TANK – 01 (ADMIN)**

**BEFORE**



**AFTER**





# CRYSTALLINE ENVIRONMENTAL SERVICES

## WATER TANK - AFTER SERVICE REPORT

20879

CUSTOMER: <i>Al Raha Village</i>			CONTACT PERSON: <i>Mr. Alim</i>		
SITE DETAILS: <i>Baniyas</i>			CONTACT NO: <i>056 3893208</i>		
TANK DETAILS: <i>Cr. R. P Water tank - 2</i>			LOCATION DETAILS: <i>Near Admin</i>		
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL		<input type="checkbox"/> RESIDENTIAL		<input type="checkbox"/> OTHERS	
<b>TYPE OF TANK</b>					
<input type="checkbox"/> CONCRETE	<input checked="" type="checkbox"/> GRP PANEL	<input type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED		<input type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS		
<b>SIZE OF TANK</b>			<b>QUANTITY OF WATER</b>		
M3	USG	L*B*H	<input type="checkbox"/> FULL	<input checked="" type="checkbox"/> HALF	<input type="checkbox"/> EMPTY
<b>CONDITION OF WATER TANK BEFORE CLEANING</b>			<b>CONDITION OF WATER TANK AFTER CLEANING</b>		
<input type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input checked="" type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input checked="" type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
<b>ACCESS</b>		<b>MANHOLE</b>		<input checked="" type="checkbox"/> COVERED	
<input type="checkbox"/> DAMAGED	<input type="checkbox"/> NA				
<b>LADDER IN</b>	<b>LADDER OUT</b>	<b>LEAKS</b>	<b>DRAIN LINE</b>	<b>VALVES</b>	<b>FLOAT VALVE</b>
<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO
<b>TANK CLEANED</b>		<b>TANK DISINFECTED</b>		<b>PIPES DISINFECTED</b>	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> YES	<input type="checkbox"/> NO <input type="checkbox"/> NA
<b>LAST CLEANING DATE</b>		<b>CURRENT CLEANING DATE</b>		<b>NEXT CLEANING DATE</b>	
		<i>16/10/2018</i>		<i>16/10/2019</i>	
<b>CHEMICALS &amp; EQUIPMENTS USED</b>					
1. <i>Carbo bio and plus</i> Quantity <i>250ml</i>					
2. _____ Quantity _____					
<input type="checkbox"/> Submersibel   Pump <input checked="" type="checkbox"/> High /Low Pressure jet <input type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED Lights <input type="checkbox"/> Foot Bath <input type="checkbox"/> Ladder <input checked="" type="checkbox"/> Ventilating Fan <input type="checkbox"/> Suction/Discharge Hoses <input type="checkbox"/> Oxygen Mater <input type="checkbox"/> Vacuum Cleaner <input type="checkbox"/> Cleaning Materials					
<b>COMMENTS &amp; RECOMMENDATIONS:</b>					
<i>mentioned water tank is cleaned and disinfected</i>					
Crystalline Representative: <i>marj</i>			Signature: <i>mgrews</i>		

*16/10/2018*

*3/11/2019*


Date of Cleaning: 16-10-2018

**PHOTOGRAPHS**  
**GRP WATER TANK- 02 (ADMIN)**

**BEFORE**



**AFTER**



**CLEANER WATER GREENER TOMORROW**



# CRYSTALLINE ENVIRONMENTAL SERVICES

## WATER TANK - AFTER SERVICE REPORT

20892

CUSTOMER: <i>Al Naha village</i>			CONTACT PERSON: <i>Mr. Alim</i>		
SITE DETAILS: <i>Baniyas</i>			CONTACT NO: <i>0563893208</i>		
TANK DETAILS: <i>C.N.P Water tank</i>			LOCATION DETAILS: <i>Elevated Near Admin</i>		
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL		<input type="checkbox"/> RESIDENTIAL		<input type="checkbox"/> OTHERS	
<b>TYPE OF TANK</b>					
<input type="checkbox"/> CONCRETE	<input checked="" type="checkbox"/> GRP PANEL	<input type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED		<input type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS		
<b>SIZE OF TANK</b>			<b>QUANTITY OF WATER</b>		
M3	USG	L*B*H	<input type="checkbox"/> FULL	<input type="checkbox"/> HALF	<input checked="" type="checkbox"/> EMPTY
<b>CONDITION OF WATER TANK BEFORE CLEANING</b>			<b>CONDITION OF WATER TANK AFTER CLEANING</b>		
<input type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input checked="" type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input checked="" type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
<b>ACCESS</b>		<b>MANHOLE</b>		<input checked="" type="checkbox"/> COVERED	
<input type="checkbox"/> DAMAGED		<input type="checkbox"/> NA			
<b>LADDER IN</b>		<b>LADDER OUT</b>		<b>LEAKS</b>	
<b>DRAIN LINE</b>		<b>VALVES</b>		<b>FLOAT VALVE</b>	
<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input type="checkbox"/> YES <input type="checkbox"/> NO
<b>TANK CLEANED</b>		<b>TANK DISINFECTED</b>		<b>PIPES DISINFECTED</b>	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> YES	<input type="checkbox"/> NO <input checked="" type="checkbox"/> NA
<b>LAST CLEANING DATE</b>		<b>CURRENT CLEANING DATE</b>		<b>NEXT CLEANING DATE</b>	
		<i>23/10/2018</i>		<i>23/10/2019</i>	
<b>CHEMICALS &amp; EQUIPMENTS USED</b>					
1. <i>carbo bio and plus</i> Quantity <i>500ml</i>					
2. _____ Quantity _____					
<input checked="" type="checkbox"/> Submersibel   Pump <input checked="" type="checkbox"/> High /Low Pressure jet <input type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED Lights <input type="checkbox"/> Foot Bath <input checked="" type="checkbox"/> Ladder <input checked="" type="checkbox"/> Ventilating Fan <input type="checkbox"/> Suction/Discharge Hoses <input type="checkbox"/> Oxygen Mater <input checked="" type="checkbox"/> Vacuum Cleaner <input type="checkbox"/> Cleaning Materials					
<b>COMMENTS &amp; RECOMMENDATIONS:</b>					
<i>mentioned water tank is cleaned and disinfected</i>					
Crystalline Representative: <i>Mans</i>			Signature: <i>Mughesal</i>		

*23/10/2018*

*3 days  
23/10/2018*



**CRYSTALLINE**  
ENVIRONMENTAL SERVICES

Date of Cleaning: 23-10-2018

**PHOTOGRAPHS**  
**GRP WATER TANK- 01 (ADMIN)**

**BEFORE**



**AFTER**



**CLEANER WATER GREENER TOMORROW**



# CRYSTALLINE ENVIRONMENTAL SERVICES

## WATER TANK - AFTER SERVICE REPORT

20890

CUSTOMER: <i>Al Naha Village</i>			CONTACT PERSON: <i>Mr. Aalim</i>		
SITE DETAILS: <i>Baniyas</i>			CONTACT NO: <i>052389328</i>		
TANK DETAILS: <i>Cr. HP Water Tank-2</i>			LOCATION DETAILS: <i>Elevated Near Admin 2</i>		
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL		<input type="checkbox"/> RESIDENTIAL		<input type="checkbox"/> OTHERS	
<b>TYPE OF TANK</b>					
<input type="checkbox"/> CONCRETE	<input checked="" type="checkbox"/> GRP PANEL	<input type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED		<input type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS		
<b>SIZE OF TANK</b>			<b>QUANTITY OF WATER</b>		
M3	USG	L*B*H	<input type="checkbox"/> FULL	<input checked="" type="checkbox"/> HALF	<input type="checkbox"/> EMPTY
<b>CONDITION OF WATER TANK BEFORE CLEANING</b>			<b>CONDITION OF WATER TANK AFTER CLEANING</b>		
<input type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input checked="" type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input checked="" type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
<b>ACCESS</b>		<b>MANHOLE</b>		<input checked="" type="checkbox"/> COVERED	
<input type="checkbox"/> DAMAGED		<input type="checkbox"/> NA			
<b>LADDER IN</b>		<b>LADDER OUT</b>		<b>LEAKS</b>	
<b>DRAIN LINE</b>		<b>VALVES</b>		<b>FLOAT VALVE</b>	
<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input type="checkbox"/> YES <input type="checkbox"/> NO
<b>TANK CLEANED</b>		<b>TANK DISINFECTED</b>		<b>PIPES DISINFECTED</b>	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> YES	<input type="checkbox"/> NO <input checked="" type="checkbox"/> NA
<b>LAST CLEANING DATE</b>		<b>CURRENT CLEANING DATE</b>		<b>NEXT CLEANING DATE</b>	
		<i>23/10/2018</i>		<i>23/10/2019</i>	
<b>CHEMICALS &amp; EQUIPMENTS USED</b>					
1. <i>Carbo bio and plus</i> Quantity <i>50ml</i>					
2. _____ Quantity _____					
<input checked="" type="checkbox"/> Submersibel   Pump <input type="checkbox"/> High /Low Pressure jet <input type="checkbox"/> Extension Cords <input type="checkbox"/> LED Lights <input type="checkbox"/> Foot Bath <input type="checkbox"/> Ladder					
<input type="checkbox"/> Ventilating Fan <input type="checkbox"/> Suction/Discharge Hoses <input type="checkbox"/> Oxygen Mater <input type="checkbox"/> Vacuum Cleaner <input type="checkbox"/> Cleaning Materials					
<b>COMMENTS &amp; RECOMMENDATIONS:</b>					
<i>Mentioned water tank is cleaned and disinfected</i>					
Crystalline Representative: <i>Mansour</i>			Signature: <i>Mansour</i>		

CLEANER WATER GREENER TOMORROW

*[Signature]*  
*23/10/2018*

*[Signature]*  
*23/10/2018*

Web: www.crystalline-uae.com  
E-mail: info@crystalline-uae.com  
Tel : +971 55 7167017



**CRYSTALLINE**  
ENVIRONMENTAL SERVICES

Date of Cleaning: 23-10-2018

**PHOTOGRAPHS**  
**GRP WATER TANK – 02 (ADMIN)**

**BEFORE**



**AFTER**



**CLEANER WATER GREENER TOMORROW**



# CRYSTALLINE ENVIRONMENTAL SERVICES

## WATER TANK - AFTER SERVICE REPORT

20880

CUSTOMER: <i>Al Raha Village</i>			CONTACT PERSON: <i>Mr. Alina</i>		
SITE DETAILS: <i>Baniyas</i>			CONTACT NO: <i>0563893208</i>		
TANK DETAILS: <i>Cr. P.P Water tank</i>			LOCATION DETAILS: <i>Near Civil store</i>		
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL		<input type="checkbox"/> RESIDENTIAL		<input type="checkbox"/> OTHERS	
TYPE OF TANK					
<input type="checkbox"/> CONCRETE	<input checked="" type="checkbox"/> GRP PANEL	<input type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED		<input type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS		
SIZE OF TANK			QUANTITY OF WATER		
M3	USG	L*B*H	<input type="checkbox"/> FULL	<input type="checkbox"/> HALF	<input checked="" type="checkbox"/> EMPTY
CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK AFTER CLEANING		
<input type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input checked="" type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input checked="" type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
ACCESS		MANHOLE		<input checked="" type="checkbox"/> COVERED	<input type="checkbox"/> DAMAGED
<input checked="" type="checkbox"/> LADDER IN	<input type="checkbox"/> LADDER OUT	<input type="checkbox"/> LEAKS		<input type="checkbox"/> DRAIN LINE	<input type="checkbox"/> VALVES
<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO		<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO
TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO		<input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> NA	
LAST CLEANING DATE		CURRENT CLEANING DATE		NEXT CLEANING DATE	
		<i>17/10/2018</i>		<i>17/10/2019</i>	
CHEMICALS & EQUIPMENTS USED					
1. <i>Carb bio and plus</i> Quantity <i>250 ml</i>					
2. _____ Quantity _____					
<input checked="" type="checkbox"/> Submersibel   Pump <input checked="" type="checkbox"/> High /Low Pressure jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED Lights <input checked="" type="checkbox"/> Foot Bath <input type="checkbox"/> Ladder <input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Mater <input checked="" type="checkbox"/> Vacuum Cleaner <input type="checkbox"/> Cleaning Materials					
COMMENTS & RECOMMENDATIONS:					
<i>mentioned water tank is cleaned and disinfected</i>					
Crystalline Representative: <i>Mansj</i>			Signature: <i>Mghera</i>		

*17/10/2018*

*3 hys*  
*17/10/2018*


Date of Cleaning: 17-10-2018

**PHOTOGRAPHS**  
**GRP WATER TANK- 01 (CIVIL STORE)**

**BEFORE**



**AFTER**





# CRYSTALLINE ENVIRONMENTAL SERVICES

## WATER TANK - AFTER SERVICE REPORT

20881

CUSTOMER: <i>Al Naha village</i>			CONTACT PERSON: <i>Mr. Min</i>		
SITE DETAILS: <i>Baniyas</i>			CONTACT NO: <i>0563893208</i>		
TANK DETAILS: <i>C.P.P Water tank-2</i>			LOCATION DETAILS: <i>amil store</i>		
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL		<input type="checkbox"/> RESIDENTIAL		<input type="checkbox"/> OTHERS	
<b>TYPE OF TANK</b>					
<input type="checkbox"/> CONCRETE	<input checked="" type="checkbox"/> GRP PANEL	<input type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED		<input type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS		
<b>SIZE OF TANK</b>			<b>QUANTITY OF WATER</b>		
M3	USG	L*B*H	<input type="checkbox"/> FULL	<input type="checkbox"/> HALF	<input checked="" type="checkbox"/> EMPTY
<b>CONDITION OF WATER TANK BEFORE CLEANING</b>			<b>CONDITION OF WATER TANK AFTER CLEANING</b>		
<input type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input checked="" type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input checked="" type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
<b>ACCESS</b>		<b>MANHOLE</b>		<input type="checkbox"/> COVERED	
<input type="checkbox"/> DAMAGED		<input type="checkbox"/> NA			
<b>LADDER IN</b>		<b>LADDER OUT</b>		<b>LEAKS</b>	
<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO		<input type="checkbox"/> YES <input type="checkbox"/> NO		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	
<b>TANK CLEANED</b>		<b>TANK DISINFECTED</b>		<b>PIPES DISINFECTED</b>	
<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO		<input type="checkbox"/> YES <input type="checkbox"/> NO		<input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> NA	
<b>LAST CLEANING DATE</b>		<b>CURRENT CLEANING DATE</b>		<b>NEXT CLEANING DATE</b>	
		<i>17/10/2018</i>		<i>17/10/2019</i>	
<b>CHEMICALS &amp; EQUIPMENTS USED</b>					
1. <i>Carbo bio and plus</i> Quantity <i>2000</i>					
2. _____ Quantity _____					
<input type="checkbox"/> Submersibel   Pump <input type="checkbox"/> High /Low Pressure jet <input checked="" type="checkbox"/> Extension Cords <input type="checkbox"/> LED Lights <input type="checkbox"/> Foot Bath <input type="checkbox"/> Ladder <input checked="" type="checkbox"/> Ventilating Fan <input type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Mater <input type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials					
<b>COMMENTS &amp; RECOMMENDATIONS:</b>					
<i>mentioned water tank is cleaned and disinfected</i>					
Crystalline Representative: <i>Mary</i>			Signature: <i>Mary</i>		

CLEANER WATER GREENER TOMORROW

*Mary*  
*17/10/2018*

*Mary*  
*17/10/2018*

Web: www.crystalline-uae.com  
E-mail: info@crystalline-uae.com  
Tel : +971 55 7167017



Date of Cleaning: 17-10-2018

**PHOTOGRAPHS**  
**GRP WATER TANK- 02 (CIVIL STORE)**

**BEFORE**



**AFTER**





# CRYSTALLINE ENVIRONMENTAL SERVICES

## WATER TANK - AFTER SERVICE REPORT

20885

CUSTOMER: <i>Al Reha Village</i>			CONTACT PERSON: <i>Mr. Alim</i>		
SITE DETAILS: <i>Baniyas</i>			CONTACT NO: <i>052 389 328</i>		
TANK DETAILS: <i>On-HP Water tank</i>			LOCATION DETAILS: <i>Plumbing Store</i>		
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL		<input type="checkbox"/> RESIDENTIAL		<input type="checkbox"/> OTHERS	
<b>TYPE OF TANK</b>					
<input type="checkbox"/> CONCRETE	<input checked="" type="checkbox"/> GRP PANEL	<input type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED		<input type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS		
<b>SIZE OF TANK</b>			<b>QUANTITY OF WATER</b>		
M3	USG	L*B*H	<input type="checkbox"/> FULL	<input type="checkbox"/> HALF	<input checked="" type="checkbox"/> EMPTY
<b>CONDITION OF WATER TANK BEFORE CLEANING</b>			<b>CONDITION OF WATER TANK AFTER CLEANING</b>		
<input type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input checked="" type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input checked="" type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
<b>ACCESS</b>		<b>MANHOLE</b>		<input checked="" type="checkbox"/> COVERED	
<input type="checkbox"/> DAMAGED		<input type="checkbox"/> NA			
<b>LADDER IN</b>		<b>LADDER OUT</b>		<b>LEAKS</b>	
<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO		<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	
<b>DRAIN LINE</b>		<b>VALVES</b>		<b>FLOAT VALVE</b>	
<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO		<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO		<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	
<b>TANK CLEANED</b>		<b>TANK DISINFECTED</b>		<b>PIPES DISINFECTED</b>	
<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO		<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO		<input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> NA	
<b>LAST CLEANING DATE</b>		<b>CURRENT CLEANING DATE</b>		<b>NEXT CLEANING DATE</b>	
		<i>20/10/2018</i>		<i>20/10/2019</i>	
<b>CHEMICALS &amp; EQUIPMENTS USED</b>					
1. <i>Carbo bio and plus</i> Quantity <i>500 ml</i>					
2. _____ Quantity _____					
<input checked="" type="checkbox"/> Submersibel   Pump <input checked="" type="checkbox"/> High /Low Pressure jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED Lights <input type="checkbox"/> Foot Bath <input type="checkbox"/> Ladder					
<input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Mater <input type="checkbox"/> Vacuum Cleaner <input type="checkbox"/> Cleaning Materials					
<b>COMMENTS &amp; RECOMMENDATIONS:</b>					
<i>mentioned water tank is cleaned and disinfected</i>					
Crystalline Representative: <i>Mary</i>			Signature: <i>Mary</i>		

*Mary*  
*20/10/2018*

*Mary*  
*20/10/2018*

Date of Cleaning: 20-10-2018

**PHOTOGRAPHS**  
**GRP WATER TANK – 01 (PLUMBING STORE)**

**BEFORE**



**AFTER**





# CRYSTALLINE ENVIRONMENTAL SERVICES

## WATER TANK - AFTER SERVICE REPORT

20887

CUSTOMER: <i>Al Raha Village</i>			CONTACT PERSON: <i>Mr. Alim</i>		
SITE DETAILS: <i>Baniyas</i>			CONTACT NO: <i>056389328</i>		
TANK DETAILS: <i>C.R.P Water Tank - 2</i>			LOCATION DETAILS: <i>Plumbing Store - Elevated</i>		
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL		<input type="checkbox"/> RESIDENTIAL		<input type="checkbox"/> OTHERS	
<b>TYPE OF TANK</b>					
<input type="checkbox"/> CONCRETE	<input checked="" type="checkbox"/> GRP PANEL	<input type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED		<input type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS		
<b>SIZE OF TANK</b>			<b>QUANTITY OF WATER</b>		
M3	USG	L*B*H	<input type="checkbox"/> FULL	<input checked="" type="checkbox"/> HALF	<input type="checkbox"/> EMPTY
<b>CONDITION OF WATER TANK BEFORE CLEANING</b>			<b>CONDITION OF WATER TANK AFTER CLEANING</b>		
<input type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input checked="" type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input checked="" type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
<b>ACCESS</b>		<b>MANHOLE</b>		<input checked="" type="checkbox"/> COVERED	
<input checked="" type="checkbox"/> LADDER IN	<input checked="" type="checkbox"/> LADDER OUT	<b>LEAKS</b>		<b>DRAIN LINE</b>	
<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO		<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	
<b>TANK CLEANED</b>		<b>TANK DISINFECTED</b>		<b>PIPES DISINFECTED</b>	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> YES	<input type="checkbox"/> NO <input checked="" type="checkbox"/> NA
<b>LAST CLEANING DATE</b>		<b>CURRENT CLEANING DATE</b>		<b>NEXT CLEANING DATE</b>	
		<i>20/10/2018</i>		<i>20/10/2019</i>	
<b>CHEMICALS &amp; EQUIPMENTS USED</b>					
1. <i>Carolo bio and plus</i> Quantity <i>500ml</i>					
2. _____ Quantity _____					
<input checked="" type="checkbox"/> Submersibel   Pump <input checked="" type="checkbox"/> High /Low Pressure jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED Lights <input checked="" type="checkbox"/> Foot Bath <input checked="" type="checkbox"/> Ladder					
<input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Mater <input checked="" type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials					
<b>COMMENTS &amp; RECOMMENDATIONS:</b>					
<i>mentioned water tank is cleaned and disinfected</i>					
Crystalline Representative: <i>Mansur</i>			Signature: <i>Mansur</i>		

*Mansur*  
*20/10/2018*

*Mansur*  
*20/10/2018*



**CRYSTALLINE**  
ENVIRONMENTAL SERVICES


Date of Cleaning: 20-10-2018

**PHOTOGRAPHS**  
**GRP WATER TANK – 02 (PLUMBING STORES)**

**BEFORE**



**AFTER**



**CLEANER WATER GREENER TOMORROW**



# CRYSTALLINE ENVIRONMENTAL SERVICES

## WATER TANK - AFTER SERVICE REPORT

20888

CUSTOMER: <i>Al Raha village</i>			CONTACT PERSON: <i>Mr. Adim</i>		
SITE DETAILS: <i>Banijay</i>			CONTACT NO: <i>052 389 3208</i>		
TANK DETAILS: <i>CRP water tank</i>			LOCATION DETAILS: <i>Elevated W9 cluster</i>		
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL		<input type="checkbox"/> RESIDENTIAL		<input type="checkbox"/> OTHERS	
<b>TYPE OF TANK</b>					
<input type="checkbox"/> CONCRETE	<input checked="" type="checkbox"/> GRP PANEL	<input type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED		<input type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS		
<b>SIZE OF TANK</b>			<b>QUANTITY OF WATER</b>		
M3	USG	L*B*H	<input type="checkbox"/> FULL	<input checked="" type="checkbox"/> HALF	<input type="checkbox"/> EMPTY
<b>CONDITION OF WATER TANK BEFORE CLEANING</b>			<b>CONDITION OF WATER TANK AFTER CLEANING</b>		
<input type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input checked="" type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input checked="" type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
<b>ACCESS</b>		<b>MANHOLE</b>		<input checked="" type="checkbox"/> COVERED	
<input type="checkbox"/> DAMAGED		<input type="checkbox"/> NA			
<b>LADDER IN</b>		<b>LADDER OUT</b>		<b>LEAKS</b>	
<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO		<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	
<b>TANK CLEANED</b>		<b>TANK DISINFECTED</b>		<b>PIPES DISINFECTED</b>	
<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO		<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO		<input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> NA	
<b>LAST CLEANING DATE</b>		<b>CURRENT CLEANING DATE</b>		<b>NEXT CLEANING DATE</b>	
		<i>21/10/2018</i>		<i>21/10/2019</i>	
<b>CHEMICALS &amp; EQUIPMENTS USED</b>					
1. <i>Coroels low and plus</i> Quantity <i>500ml</i>					
2. _____ Quantity _____					
<input checked="" type="checkbox"/> Submersibel   Pump <input checked="" type="checkbox"/> High /Low Pressure jet <input type="checkbox"/> Extension Cords <input type="checkbox"/> LED Lights <input type="checkbox"/> Foot Bath <input type="checkbox"/> Ladder <input checked="" type="checkbox"/> Ventilating Fan <input type="checkbox"/> Suction/Discharge Hoses <input type="checkbox"/> Oxygen Mater <input type="checkbox"/> Vacuum Cleaner <input type="checkbox"/> Cleaning Materials					
<b>COMMENTS &amp; RECOMMENDATIONS:</b>					
<i>mentioned water tank is cleaned and disinfected</i>					
Crystalline Representative: <i>manoj</i>			Signature: <i>M. P. Phua</i>		

*Manoj*  
21/10/2018

*M. P. Phua*  
21/10/2018


Date of Cleaning: 21-10-2018

**PHOTOGRAPHS**  
**GRP WATER TANK- 01 (CLUSTER W2)**

**BEFORE**



**AFTER**





# CRYSTALLINE ENVIRONMENTAL SERVICES

## WATER TANK - AFTER SERVICE REPORT

20889

CUSTOMER: <i>Al Naha Village</i>			CONTACT PERSON: <i>Ms. Alina</i>		
SITE DETAILS: <i>Baniyas</i>			CONTACT NO: <i>052 389328</i>		
TANK DETAILS: <i>C.R.P Water tank</i>			LOCATION DETAILS: <i>Elevated w 3 depth</i>		
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL		<input type="checkbox"/> RESIDENTIAL		<input type="checkbox"/> OTHERS	
<b>TYPE OF TANK</b>					
<input type="checkbox"/> CONCRETE	<input checked="" type="checkbox"/> GRP PANEL	<input type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED		<input type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS		
<b>SIZE OF TANK</b>			<b>QUANTITY OF WATER</b>		
M3	USG	L*B*H	<input type="checkbox"/> FULL	<input type="checkbox"/> HALF	<input checked="" type="checkbox"/> EMPTY
<b>CONDITION OF WATER TANK BEFORE CLEANING</b>			<b>CONDITION OF WATER TANK AFTER CLEANING</b>		
<input type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input checked="" type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input checked="" type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
<b>ACCESS</b>		<b>MANHOLE</b>		<input checked="" type="checkbox"/> COVERED	<input type="checkbox"/> DAMAGED
<input checked="" type="checkbox"/> LADDER IN	<input checked="" type="checkbox"/> LADDER OUT	<b>LEAKS</b>		<b>DRAIN LINE</b>	
<input type="checkbox"/> YES <input type="checkbox"/> NO	<input type="checkbox"/> YES <input type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO		<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	
<b>TANK CLEANED</b>		<b>TANK DISINFECTED</b>		<b>PIPES DISINFECTED</b>	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> YES	<input type="checkbox"/> NO <input checked="" type="checkbox"/> NA
<b>LAST CLEANING DATE</b>		<b>CURRENT CLEANING DATE</b>		<b>NEXT CLEANING DATE</b>	
		<i>22/10/2018</i>		<i>22/10/2019</i>	
<b>CHEMICALS &amp; EQUIPMENTS USED</b>					
1. <i>Coro bio and plus</i> Quantity <i>500 ml</i>					
2. _____ Quantity _____					
<input checked="" type="checkbox"/> Submersibel   Pump <input checked="" type="checkbox"/> High /Low Pressure jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED Lights <input checked="" type="checkbox"/> Foot Bath <input type="checkbox"/> Ladder <input checked="" type="checkbox"/> Ventilating Fan <input type="checkbox"/> Suction/Discharge Hoses <input type="checkbox"/> Oxygen Mater <input type="checkbox"/> Vacuum Cleaner <input type="checkbox"/> Cleaning Materials					
<b>COMMENTS &amp; RECOMMENDATIONS:</b>					
<i>mentioned water tank is cleaned and disinfected</i>					
Crystalline Representative: <i>Mary</i>			Signature: <i>[Signature]</i>		

CLEANER WATER GREENER TOMORROW

*[Signature]*  
*22/10/2018*


*[Signature]*  
*22/10/2018*

Web: www.crystalline-uae.com  
E-mail: info@crystalline-uae.com  
Tel : +971 55 7167017

Date of Cleaning: 22-10-2018

**PHOTOGRAPHS**  
**GRP WATER TANK- 01 (CLUSTER W3)**

**BEFORE**



**AFTER**



0



# CRYSTALLINE ENVIRONMENTAL SERVICES

## WATER TANK - AFTER SERVICE REPORT

20882

CUSTOMER: <i>Al Naha Village</i>			CONTACT PERSON: <i>Mr. Alim</i>		
SITE DETAILS: <i>Baniyas</i>			CONTACT NO: <i>056389328</i>		
TANK DETAILS: <i>Under Water Tank-1</i>			LOCATION DETAILS: <i>Kitchen-01 ground level</i>		
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL		<input type="checkbox"/> RESIDENTIAL		<input type="checkbox"/> OTHERS	
<b>TYPE OF TANK</b>					
<input type="checkbox"/> CONCRETE	<input type="checkbox"/> GRP PANEL	<input type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED		<input checked="" type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS		
<b>SIZE OF TANK</b>			<b>QUANTITY OF WATER</b>		
M3	USG	L*B*H	<input type="checkbox"/> FULL	<input checked="" type="checkbox"/> HALF	<input type="checkbox"/> EMPTY
<b>CONDITION OF WATER TANK BEFORE CLEANING</b>			<b>CONDITION OF WATER TANK AFTER CLEANING</b>		
<input type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input checked="" type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input checked="" type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
<b>ACCESS</b>		<b>MANHOLE</b>		<input checked="" type="checkbox"/> COVERED	
<input type="checkbox"/> LADDER IN	<input type="checkbox"/> LADDER OUT	<input type="checkbox"/> LEAKS		<input type="checkbox"/> DRAIN LINE	<input type="checkbox"/> VALVES
<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO
<b>TANK CLEANED</b>		<b>TANK DISINFECTED</b>		<b>PIPES DISINFECTED</b>	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> YES	<input type="checkbox"/> NO <input checked="" type="checkbox"/> NA
<b>LAST CLEANING DATE</b>		<b>CURRENT CLEANING DATE</b>		<b>NEXT CLEANING DATE</b>	
		<i>18/10/2018</i>		<i>18/10/2019</i>	
<b>CHEMICALS &amp; EQUIPMENTS USED</b>					
1. <i>Carbo bio cond plus</i> Quantity <i>250ml</i>					
2. _____ Quantity _____					
<input checked="" type="checkbox"/> Submersibel   Pump <input checked="" type="checkbox"/> High /Low Pressure jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED Lights <input type="checkbox"/> Foot Bath <input type="checkbox"/> Ladder <input type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Suction/Discharge Hoses <input type="checkbox"/> Oxygen Mater <input type="checkbox"/> Vacuum Cleaner <input type="checkbox"/> Cleaning Materials					
<b>COMMENTS &amp; RECOMMENDATIONS:</b>					
<i>mentioned water tank is closed and disinfected</i>					
Crystalline Representative: <i>Mari Gola</i>			Signature: <i>Mari Gola</i>		

CLEANER WATER GREENER TOMORROW

*15/10/2018*



*18/10/2018*

Web: www.crystalline-uae.com  
E-mail: info@crystalline-uae.com  
Tel : +971 55 7167017

Date of Cleaning: 18-10-2018

**PHOTOGRAPHS**  
**GROUND LEVEL SINTEX WATER TANK – 01 (KITCHEN 1)**

**BEFORE**



**AFTER**





# CRYSTALLINE ENVIRONMENTAL SERVICES

## WATER TANK - AFTER SERVICE REPORT

20883

CUSTOMER: <i>Al Raha Village</i>			CONTACT PERSON: <i>Mr. Alim</i>		
SITE DETAILS: <i>Baniyas</i>			CONTACT NO: <i>056 38 93208</i>		
TANK DETAILS: <i>Sinter Water tank - 2</i>			LOCATION DETAILS: <i>Kitchen - 1 Ground level</i>		
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL		<input type="checkbox"/> RESIDENTIAL		<input type="checkbox"/> OTHERS	
<b>TYPE OF TANK</b>					
<input type="checkbox"/> CONCRETE	<input type="checkbox"/> GRP PANEL	<input type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED		<input checked="" type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS		
<b>SIZE OF TANK</b>			<b>QUANTITY OF WATER</b>		
M3	USG	L*B*H	<input type="checkbox"/> FULL	<input checked="" type="checkbox"/> HALF	<input type="checkbox"/> EMPTY
<b>CONDITION OF WATER TANK BEFORE CLEANING</b>			<b>CONDITION OF WATER TANK AFTER CLEANING</b>		
<input type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input checked="" type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input checked="" type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
<b>ACCESS</b>		<b>MANHOLE</b>		<input checked="" type="checkbox"/> COVERED	<input type="checkbox"/> DAMAGED
<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input type="checkbox"/> NO
<b>LADDER IN</b>		<b>LADDER OUT</b>		<b>LEAKS</b>	
<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO
<b>TANK CLEANED</b>		<b>TANK DISINFECTED</b>		<b>PIPES DISINFECTED</b>	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> YES	<input type="checkbox"/> NO
<b>LAST CLEANING DATE</b>		<b>CURRENT CLEANING DATE</b>		<b>NEXT CLEANING DATE</b>	
		<i>18/10/2018</i>		<i>18/10/2019</i>	
<b>CHEMICALS &amp; EQUIPMENTS USED</b>					
1. <i>Carbo bio and plus</i> Quantity <i>250 ml</i>					
2. _____ Quantity _____					
<input checked="" type="checkbox"/> Submersibel   Pump <input type="checkbox"/> High /Low Pressure jet <input type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED Lights <input type="checkbox"/> Foot Bath <input type="checkbox"/> Ladder					
<input checked="" type="checkbox"/> Ventilating Fan <input type="checkbox"/> Suction/Discharge Hoses <input type="checkbox"/> Oxygen Mater <input type="checkbox"/> Vacuum Cleaner <input type="checkbox"/> Cleaning Materials					
<b>COMMENTS &amp; RECOMMENDATIONS:</b>					
<i>mentioned water tank is cleaned and disinfected</i>					
Crystalline Representative: <i>Mansaj</i>			Signature: <i>Mansaj</i>		

CLEANER WATER GREENER TOMORROW

*Mansaj*


*Mansaj*  
*18/10/2018*

Web: www.crystalline-uae.com  
E-mail: info@crystalline-uae.com  
Tel : +971 55 7167017



Date of Cleaning: 18-10-2018

**PHOTOGRAPHS**  
**GROUND LEVEL SINTEX WATER TANK – 02 (KITCHEN 1)**

**BEFORE**



**AFTER**





# CRYSTALLINE ENVIRONMENTAL SERVICES

## WATER TANK - AFTER SERVICE REPORT

20884

CUSTOMER: <i>All Raha Village</i>			CONTACT PERSON: <i>Mr. Alim</i>		
SITE DETAILS: <i>Baniyas</i>			CONTACT NO: <i>056 389 328</i>		
TANK DETAILS: <i>Linear Water Tank - 1</i>			LOCATION DETAILS: <i>Kitchen - 2 on L</i>		
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL		<input type="checkbox"/> RESIDENTIAL		<input type="checkbox"/> OTHERS	
<b>TYPE OF TANK</b>					
<input type="checkbox"/> CONCRETE	<input type="checkbox"/> GRP PANEL	<input type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED		<input checked="" type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS		
<b>SIZE OF TANK</b>			<b>QUANTITY OF WATER</b>		
M3	USG	L*B*H	<input type="checkbox"/> FULL	<input checked="" type="checkbox"/> HALF	<input type="checkbox"/> EMPTY
<b>CONDITION OF WATER TANK BEFORE CLEANING</b>			<b>CONDITION OF WATER TANK AFTER CLEANING</b>		
<input type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input checked="" type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input checked="" type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
<b>ACCESS</b>		<b>MANHOLE</b>		<input checked="" type="checkbox"/> COVERED	
<input type="checkbox"/> DAMAGED		<input type="checkbox"/> NA			
<b>LADDER IN</b>		<b>LADDER OUT</b>		<b>LEAKS</b>	
<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	
<b>TANK CLEANED</b>		<b>TANK DISINFECTED</b>		<b>PIPES DISINFECTED</b>	
<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO		<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO		<input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> NA	
<b>LAST CLEANING DATE</b>		<b>CURRENT CLEANING DATE</b>		<b>NEXT CLEANING DATE</b>	
		<i>18/10/2018</i>		<i>18/10/2019</i>	
<b>CHEMICALS &amp; EQUIPMENTS USED</b>					
1. <i>Caruto bio and plus</i> Quantity <i>200ml</i>					
2. _____ Quantity _____					
<input checked="" type="checkbox"/> Submersibel   Pump <input type="checkbox"/> High /Low Pressure jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED Lights <input type="checkbox"/> Foot Bath <input type="checkbox"/> Ladder <input checked="" type="checkbox"/> Ventilating Fan <input type="checkbox"/> Suction/Discharge Hoses <input type="checkbox"/> Oxygen Mater <input type="checkbox"/> Vacuum Cleaner <input type="checkbox"/> Cleaning Materials					
<b>COMMENTS &amp; RECOMMENDATIONS:</b>					
<i>mentioned water tank is cleaned and disinfected</i>					
Crystalline Representative: <i>nowj</i>			Signature: <i>[Signature]</i>		



*[Signature]*  
18/10/2018

*[Signature]*  
18/10/2018


Date of Cleaning: 18-10-2018

**PHOTOGRAPHS**  
**GROUND LEVEL SINTEX WATER TANK – 01 (KITCHEN 2)**

**BEFORE**



**AFTER**





# CRYSTALLINE ENVIRONMENTAL SERVICES

## WATER TANK - AFTER SERVICE REPORT

20885

CUSTOMER: <i>Al Raha Village</i>			CONTACT PERSON: <i>Mr. Allim</i>		
SITE DETAILS: <i>Baniyas</i>			CONTACT NO: <i>0523893203</i>		
TANK DETAILS: <i>Sinter Water tank-2</i>			LOCATION DETAILS: <i>Kitchen-2 G.L</i>		
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL		<input type="checkbox"/> RESIDENTIAL		<input type="checkbox"/> OTHERS	
<b>TYPE OF TANK</b>					
<input type="checkbox"/> CONCRETE	<input type="checkbox"/> GRP PANEL	<input type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED		<input checked="" type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS		
<b>SIZE OF TANK</b>			<b>QUANTITY OF WATER</b>		
M3	USG	L*B*H	<input type="checkbox"/> FULL	<input type="checkbox"/> HALF	<input checked="" type="checkbox"/> EMPTY
<b>CONDITION OF WATER TANK BEFORE CLEANING</b>			<b>CONDITION OF WATER TANK AFTER CLEANING</b>		
<input type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input checked="" type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input checked="" type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
<b>ACCESS</b>		<b>MANHOLE</b>		<input checked="" type="checkbox"/> COVERED	
<input type="checkbox"/> DAMAGED		<input type="checkbox"/> NA			
<b>LADDER IN</b>		<b>LADDER OUT</b>		<b>LEAKS</b>	
<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	
<b>TANK CLEANED</b>		<b>TANK DISINFECTED</b>		<b>PIPES DISINFECTED</b>	
<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO		<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO		<input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> NA	
<b>LAST CLEANING DATE</b>		<b>CURRENT CLEANING DATE</b>		<b>NEXT CLEANING DATE</b>	
		<i>18/10/2018</i>		<i>18/10/2019</i>	
<b>CHEMICALS &amp; EQUIPMENTS USED</b>					
1. <i>carelo bio and plus</i> Quantity <i>250 ml</i>					
2. _____ Quantity _____					
<input checked="" type="checkbox"/> Submersibel   Pump <input checked="" type="checkbox"/> High /Low Pressure jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED Lights <input checked="" type="checkbox"/> Foot Bath <input checked="" type="checkbox"/> Ladder					
<input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Mater <input checked="" type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials					
<b>COMMENTS &amp; RECOMMENDATIONS:</b>					
<i>mentioned Water tank is cleaned and disinfected</i>					
Crystalline Representative: <i>Manoj</i>			Signature: <i>Manoj</i>		

CLEANER WATER GREENER TOMORROW

*Manoj*  
*18/10/2018*

*Manoj*  
*18/10/2018*

Web: www.crystalline-uae.com  
E-mail: info@crystalline-uae.com  
Tel : +971 55 7167017



Date of Cleaning: 18-10-2018

**PHOTOGRAPHS**  
**GROUND LEVEL SINTEX WATER TANK – 02 (KITCHEN 2)**

**BEFORE**



**AFTER**





# CRYSTALLINE ENVIRONMENTAL SERVICES

## WATER TANK - AFTER SERVICE REPORT

20893

CUSTOMER: <i>Al Naha Village</i>			CONTACT PERSON: <i>Mr. Alim</i>		
SITE DETAILS: <i>Baniyas</i>			CONTACT NO: <i>056 339 328</i>		
TANK DETAILS: <i>Inter water tank</i>			LOCATION DETAILS: <i>Laundry outside</i>		
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL		<input type="checkbox"/> RESIDENTIAL		<input type="checkbox"/> OTHERS	
<b>TYPE OF TANK</b>					
<input type="checkbox"/> CONCRETE	<input type="checkbox"/> GRP PANEL	<input type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED		<input checked="" type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS		
<b>SIZE OF TANK</b>			<b>QUANTITY OF WATER</b>		
M3	USG	L*B*H	<input type="checkbox"/> FULL	<input checked="" type="checkbox"/> HALF	<input type="checkbox"/> EMPTY
<b>CONDITION OF WATER TANK BEFORE CLEANING</b>			<b>CONDITION OF WATER TANK AFTER CLEANING</b>		
<input type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input checked="" type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input checked="" type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
<b>ACCESS</b>		<b>MANHOLE</b>		<input checked="" type="checkbox"/> COVERED	
<input type="checkbox"/> DAMAGED			<input type="checkbox"/> DAMAGED		<input type="checkbox"/> NA
<b>LADDER IN</b>		<b>LADDER OUT</b>		<b>LEAKS</b>	
<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO
<b>TANK CLEANED</b>		<b>TANK DISINFECTED</b>		<b>PIPES DISINFECTED</b>	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> YES	<input type="checkbox"/> NO <input checked="" type="checkbox"/> NA
<b>LAST CLEANING DATE</b>		<b>CURRENT CLEANING DATE</b>		<b>NEXT CLEANING DATE</b>	
		<i>24/10/2018</i>		<i>24/10/2019</i>	
<b>CHEMICALS &amp; EQUIPMENTS USED</b>					
1. <i>Carbo bio and plus</i> Quantity <i>250ml</i>					
2. _____ Quantity _____					
<input type="checkbox"/> Submersibel   Pump <input checked="" type="checkbox"/> High /Low Pressure jet <input type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED Lights <input type="checkbox"/> Foot Bath <input type="checkbox"/> Ladder <input checked="" type="checkbox"/> Ventilating Fan <input type="checkbox"/> Suction/Discharge Hoses <input type="checkbox"/> Oxygen Mater <input checked="" type="checkbox"/> Vacuum Cleaner <input type="checkbox"/> Cleaning Materials					
<b>COMMENTS &amp; RECOMMENDATIONS:</b>					
<i>Mentioned water tank is cleaned and disinfected</i>					
Crystalline Representative: <i>Mansour</i>			Signature: <i>Mansour</i>		



*24/10/2018*

*24/10/2018*


Date of Cleaning: 24-10-2018

**PHOTOGRAPHS**  
**GROUND LEVEL SINTEX WATER TANK – 01 (LAUNDRY)**

**BEFORE**



**AFTER**





# CRYSTALLINE ENVIRONMENTAL SERVICES

## WATER TANK - AFTER SERVICE REPORT

20895

CUSTOMER: <i>Al Naha Village</i>			CONTACT PERSON: <i>Mr. Alim</i>		
SITE DETAILS: <i>Banijas</i>			CONTACT NO: <i>0563893208</i>		
TANK DETAILS: <i>Winter Water tank-2</i>			LOCATION DETAILS: <i>Laundry outside</i>		
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL		<input type="checkbox"/> RESIDENTIAL		<input checked="" type="checkbox"/> OTHERS	
<b>TYPE OF TANK</b>					
<input type="checkbox"/> CONCRETE	<input type="checkbox"/> GRP PANEL	<input type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED		<input checked="" type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS		
<b>SIZE OF TANK</b>			<b>QUANTITY OF WATER</b>		
M3	USG	L*B*H	<input type="checkbox"/> FULL	<input type="checkbox"/> HALF	<input checked="" type="checkbox"/> EMPTY
<b>CONDITION OF WATER TANK BEFORE CLEANING</b>			<b>CONDITION OF WATER TANK AFTER CLEANING</b>		
<input type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input checked="" type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input checked="" type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
<b>ACCESS</b>		<b>MANHOLE</b>		<input checked="" type="checkbox"/> COVERED	
<input type="checkbox"/> DAMAGED		<input type="checkbox"/> DAMAGED		<input type="checkbox"/> NA	
<b>LADDER IN</b>		<b>LADDER OUT</b>		<b>LEAKS</b>	
<b>DRAIN LINE</b>		<b>VALVES</b>		<b>FLOAT VALVE</b>	
<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO
<b>TANK CLEANED</b>		<b>TANK DISINFECTED</b>		<b>PIPES DISINFECTED</b>	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> YES	<input type="checkbox"/> NO <input checked="" type="checkbox"/> NA
<b>LAST CLEANING DATE</b>		<b>CURRENT CLEANING DATE</b>		<b>NEXT CLEANING DATE</b>	
		<i>24/10/2018</i>		<i>24/10/2019</i>	
<b>CHEMICALS &amp; EQUIPMENTS USED</b>					
1. <i>Carbo bio and plus</i> Quantity <i>250 ml</i>					
2. _____ Quantity _____					
<input checked="" type="checkbox"/> Submersibel   Pump <input checked="" type="checkbox"/> High /Low Pressure jet <input type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED Lights <input type="checkbox"/> Foot Bath <input type="checkbox"/> Ladder					
<input checked="" type="checkbox"/> Ventilating Fan <input type="checkbox"/> Suction/Discharge Hoses <input type="checkbox"/> Oxygen Mater <input type="checkbox"/> Vacuum Cleaner <input type="checkbox"/> Cleaning Materials					
<b>COMMENTS &amp; RECOMMENDATIONS:</b>					
<i>mentioned water tank is cleaned and disinfected</i>					
Crystalline Representative: <i>Mansoor</i>			Signature: <i>Mansoor</i>		

CLEANER WATER GREENER TOMORROW

*29/10/2018*

*3 dy*  
*29/10/2018*

Web: www.crystalline-uae.com  
E-mail: info@crystalline-uae.com  
Tel : +971 55 7167017




**CRYSTALLINE**  
ENVIRONMENTAL SERVICES

Date of Cleaning: 24-10-2018



## PHOTOGRAPHS

### GROUND LEVEL SINTEX WATER TANK – 02 (LAUNDRY)

BEFORE



AFTER



**CLEANER WATER GREENER TOMORROW**



# CRYSTALLINE ENVIRONMENTAL SERVICES

## WATER TANK - AFTER SERVICE REPORT

20897

CUSTOMER: <i>Al Naha Village</i>			CONTACT PERSON: <i>Mr. Alim</i>		
SITE DETAILS: <i>Baniyas</i>			CONTACT NO: <i>056389323</i>		
TANK DETAILS: <i>Lintex Water tank-3</i>			LOCATION DETAILS: <i>Jambyr outside</i>		
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL		<input type="checkbox"/> RESIDENTIAL		<input type="checkbox"/> OTHERS	
<b>TYPE OF TANK</b>					
<input type="checkbox"/> CONCRETE	<input type="checkbox"/> GRP PANEL	<input type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED		<input checked="" type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS		
<b>SIZE OF TANK</b>			<b>QUANTITY OF WATER</b>		
M3	USG	L*B*H	<input type="checkbox"/> FULL	<input type="checkbox"/> HALF	<input checked="" type="checkbox"/> EMPTY
<b>CONDITION OF WATER TANK BEFORE CLEANING</b>			<b>CONDITION OF WATER TANK AFTER CLEANING</b>		
<input type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input checked="" type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input checked="" type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
<b>ACCESS</b>		<b>MANHOLE</b>		<input checked="" type="checkbox"/> COVERED	
<input type="checkbox"/> DAMAGED		<input type="checkbox"/> NA			
<b>LADDER IN</b>		<b>LADDER OUT</b>		<b>LEAKS</b>	
<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	
<b>TANK CLEANED</b>		<b>TANK DISINFECTED</b>		<b>PIPES DISINFECTED</b>	
<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO		<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO		<input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> NA	
<b>LAST CLEANING DATE</b>		<b>CURRENT CLEANING DATE</b>		<b>NEXT CLEANING DATE</b>	
		<i>24/10/2018</i>		<i>24/10/2019</i>	
<b>CHEMICALS &amp; EQUIPMENTS USED</b>					
1. <i>Carbo bio and plus</i> Quantity <i>250ml</i>					
2. _____ Quantity _____					
<input checked="" type="checkbox"/> Submersibel   Pump <input checked="" type="checkbox"/> High /Low Pressure jet <input type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED Lights <input checked="" type="checkbox"/> Foot Bath <input type="checkbox"/> Ladder <input type="checkbox"/> Ventilating Fan <input type="checkbox"/> Suction/Discharge Hoses <input type="checkbox"/> Oxygen Mater <input type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials					
<b>COMMENTS &amp; RECOMMENDATIONS:</b>					
<i>mentioned water tank is cleaned and disinfected</i>					
Crystalline Representative: <i>Mans</i>			Signature: <i>engheer</i>		

*24/10/2018*

*27/10/2018*





**CRYSTALLINE**  
ENVIRONMENTAL SERVICES


Date of Cleaning: 24-10-2018

**PHOTOGRAPHS**  
**GROUND LEVEL SINTEX WATER TANK – 03 (LAUNDRY)**

**BEFORE**



**AFTER**



**CLEANER WATER GREENER TOMORROW**



# CRYSTALLINE ENVIRONMENTAL SERVICES

## WATER TANK - AFTER SERVICE REPORT

20899

CUSTOMER: <i>Al Naha Village</i>			CONTACT PERSON: <i>Mr Alim</i>		
SITE DETAILS: <i>Baniyas</i>			CONTACT NO: <i>0563893208</i>		
TANK DETAILS: <i>Sinter water tank</i>			LOCATION DETAILS: <i>Laundry outjoll</i>		
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL <input type="checkbox"/> RESIDENTIAL <input type="checkbox"/> OTHERS					
<b>TYPE OF TANK</b>					
<input type="checkbox"/> CONCRETE	<input type="checkbox"/> GRP PANEL	<input type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED		<input checked="" type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS		
<b>SIZE OF TANK</b>			<b>QUANTITY OF WATER</b>		
M3	USG	L*B*H	<input type="checkbox"/> FULL	<input checked="" type="checkbox"/> HALF	<input type="checkbox"/> EMPTY
<b>CONDITION OF WATER TANK BEFORE CLEANING</b>			<b>CONDITION OF WATER TANK AFTER CLEANING</b>		
<input type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input checked="" type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input checked="" type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
<b>ACCESS</b>		<b>MANHOLE</b>	<input checked="" type="checkbox"/> COVERED	<input type="checkbox"/> DAMAGED	<input type="checkbox"/> NA
<b>LADDER IN</b>	<b>LADDER OUT</b>	<b>LEAKS</b>	<b>DRAIN LINE</b>	<b>VALVES</b>	<b>FLOAT VALVE</b>
<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO
<b>TANK CLEANED</b>		<b>TANK DISINFECTED</b>		<b>PIPES DISINFECTED</b>	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> YES	<input type="checkbox"/> NO <input checked="" type="checkbox"/> NA
<b>LAST CLEANING DATE</b>		<b>CURRENT CLEANING DATE</b>		<b>NEXT CLEANING DATE</b>	
		<i>24/10/2018</i>		<i>24/10/2019</i>	
<b>CHEMICALS &amp; EQUIPMENTS USED</b>					
1. <i>carbo bio and plus</i> Quantity <i>250ml</i>					
2. _____ Quantity _____					
<input checked="" type="checkbox"/> Submersibel   Pump <input checked="" type="checkbox"/> High /Low Pressure jet <input type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED Lights <input checked="" type="checkbox"/> Foot Bath <input type="checkbox"/> Ladder					
<input checked="" type="checkbox"/> Ventilating Fan <input type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Mater <input checked="" type="checkbox"/> Vacuum Cleaner <input type="checkbox"/> Cleaning Materials					
<b>COMMENTS &amp; RECOMMENDATIONS:</b>					
<i>Mentioned water tank is cleaned and disinfected</i>					
Crystalline Representative: <i>Mary</i>			Signature: <i>Mary</i>		



*24/10/2018*

*24/10/2018*



Date of Cleaning: 24-10-2018

**PHOTOGRAPHS**  
**GROUND LEVEL SINTEX WATER TANK – 04 (LAUNDRY)**

**BEFORE**



**AFTER**



# CRYSTALLINE CLEANING & ENVIRONMENTAL SERVICES

## CLEANING & DISINFECTION CERTIFICATE

### POTABLE WATER TANKS

**CLIENT NAME** : AL RAHA VILLAGAE PROPERTIES LLC.

**CLIENT ADDRESS** : P.O. BOX: 6634, ABU DHABI, UAE.

**CONTACT PERSON** : MR. BEJOY THOMAS ZACHARIAH.

**SITE DETAILS** : AL RAHA VILLAGE, ABU DHABI.

**DETAILS** : WATER TANK DISINFECTION

**DATE OF CLEANING** : 16-24 OCTOBER 2018

**FREQUENCY OF CLEANING** : EVERY ONE YEAR

**DATE OF NEXT CLEANING** : 16 OCTOBER 2019

*The procedures employed in this cleaning and disinfection comply with HS (G) 70 health and safety guidelines for prevention of legionella as well as BS6700 and CARELA BIO PLUS method statement.*

*The entire water storage tank should be disinfected minimum every one (1) year depending upon the condition.*



CRYSTALLINE CLEANING AND ENVIRONMENTAL SERVICES