

# WATER TANK CLEANING & DISINFECTION

## COMPLETION REPORT

FOR



Client : Advanced Facilities Management.  
Contact Person: Mr. Kennedy Pereira  
Operational Manager.  
Site Details : ENEC - Ruwais, Abu Dhabi, UAE.  
Date : 19 November 2018



**CRYSTALLINE**  
ENVIRONMENTAL SERVICES

CRYSTALLINE ENVIRONMENTAL  
SERVICES

P.O. BOX 131463, Abu Dhabi, U.A.E.  
TEL: 02 6508930 FAX: 02 6508942

[info@crystalline-uae.com](mailto:info@crystalline-uae.com)

[www.crystalline-uae.com](http://www.crystalline-uae.com)





# CRYSTALLINE ENVIRONMENTAL SERVICES

## WATER TANK - AFTER SERVICE REPORT

13468

|   |   |   |   |  |   |
|---|---|---|---|--|---|
| CUSTOMER: <i>Advanced, Ruwais</i>   |   |   | CONTACT PERSON: <i>Ms Joy Thomas</i>                                |  |   |
| SITE DETAILS: <i>Emirates Nuclear</i>   |   |   | CONTACT NO: <i>056 536 8606</i>                                     |  |   |
| TANK DETAILS: <i>GRP tanks of</i>   |   |   | LOCATION DETAILS: <i>Emirates Zone</i>                              |  |   |
| TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL <input type="checkbox"/> RESIDENTIAL <input type="checkbox"/> OTHERS  |   |   |   |  |   |
| <b>TYPE OF TANK</b>   |   |   |   |  |   |
| <input type="checkbox"/> CONCRETE   | <input checked="" type="checkbox"/> GRP PANEL                       | <input type="checkbox"/> FRP TANK                                   | <input type="checkbox"/> GALVANIZED                                 | <input type="checkbox"/> STEEL PANEL   | <input type="checkbox"/> PLASTIC                                    |
| <input type="checkbox"/> CONCRETE COATED  |   | <input type="checkbox"/> POLYURETHANE                               | <input type="checkbox"/> OTHERS                                     |  |   |
| <b>SIZE OF TANK</b>   |   |   | <b>QUANTITY OF WATER</b>  |  |   |
| M3  | USG   | L*B*H   | <input type="checkbox"/> FULL                                       | <input checked="" type="checkbox"/> HALF   | <input type="checkbox"/> EMPTY                                      |
| <b>CONDITION OF WATER TANK BEFORE CLEANING</b>  |   |   | <b>CONDITION OF WATER TANK AFTER CLEANING</b>                       |  |   |
| <input type="checkbox"/> CLEAN  | <input checked="" type="checkbox"/> DIRTY                           | <input type="checkbox"/> VERY DIRTY                                 | <input checked="" type="checkbox"/> CLEAN                           | <input type="checkbox"/> DIRTY   | <input type="checkbox"/> VERY DIRTY                                 |
| <input type="checkbox"/> BIOFILMS   | <input type="checkbox"/> MOULDS                                     | <input type="checkbox"/> SLIME                                      | <input type="checkbox"/> BIOFILMS                                   | <input type="checkbox"/> MOULDS  | <input type="checkbox"/> SLIME                                      |
| <input type="checkbox"/> SEDIMENTS  | <input checked="" type="checkbox"/> MUD & SAND                      | <input type="checkbox"/> RUST                                       | <input type="checkbox"/> SEDIMENTS                                  | <input type="checkbox"/> MUD & SAND  | <input type="checkbox"/> RUST                                       |
| <b>ACCESS</b>   |   | <b>MANHOLE</b>  | <input type="checkbox"/> COVERED                                    | <input type="checkbox"/> DAMAGED   | <input type="checkbox"/> NA   |
| <b>LADDER IN</b>  | <b>LADDER OUT</b>   | <b>LEAKS</b>  | <b>DRAIN LINE</b>   | <b>VALVES</b>  | <b>FLOAT VALVE</b>  |
| <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO   | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO                  | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO |
| <b>TANK CLEANED</b>   |   | <b>TANK DISINFECTED</b>   |   | <b>PIPES DISINFECTED</b>   |   |
| <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO   | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO | <input type="checkbox"/> YES <input type="checkbox"/> NO            | <input type="checkbox"/> YES <input type="checkbox"/> NO            | <input type="checkbox"/> YES <input type="checkbox"/> NO <input type="checkbox"/> NA |   |
| <b>LAST CLEANING DATE</b>   |   | <b>CURRENT CLEANING DATE</b>  |   | <b>NEXT CLEANING DATE</b>  |   |
|   |   | <i>05/11/2018</i>   |   | <i>05/05/2019</i>  |   |
| <b>CHEMICALS &amp; EQUIPMENTS USED</b>  |   |   |   |  |   |
| 1. <i>Sodium hypochloride</i> Quantity <i>500 ml</i>  |   |   |   |  |   |
| 2. _____ Quantity _____   |   |   |   |  |   |
| <input checked="" type="checkbox"/> Submersibel Pump <input type="checkbox"/> High/Low Pressure Jet <input type="checkbox"/> Extension Cords <input type="checkbox"/> LED lights <input checked="" type="checkbox"/> Foot Bath <input type="checkbox"/> Ladder<br><input checked="" type="checkbox"/> Ventilating Fan <input type="checkbox"/> Suction/Discharge Hoses <input type="checkbox"/> Oxygen Meter <input checked="" type="checkbox"/> Vacuum Cleaner <input type="checkbox"/> Cleaning Materials |   |   |   |  |   |
| <b>COMMENTS &amp; RECOMMENDATIONS:</b>  |   |   |   |  |   |
| <i>Mentioned tanks is cleaned &amp; disinfected</i>   |   |   |   |  |   |
| Crystalline Representative: <i>Yattousk</i>   |   |   | Signature: <i>[Signature]</i>                                       |  |   |

Date of Cleaning: 05-11-2018

**PHOTOGRAPHS**  
**GROUND LEVEL GRP WATER TANK – 01**

**BEFORE**



**AFTER**





# CRYSTALLINE ENVIRONMENTAL SERVICES

## WATER TANK - AFTER SERVICE REPORT

13471

|   |  |   |   |  |  |
|---|--|---|---|--|--|
| CUSTOMER: <i>Advanced, Rasais</i>   |  |   | CONTACT PERSON: <i>M. Jay Thomas</i>          |  |  |
| SITE DETAILS: <i>Emirates Nuclear</i>   |  |   | CONTACT NO: <i>0565368606</i>                 |  |  |
| TANK DETAILS: <i>GRP tanks 02</i>   |  |   | LOCATION DETAILS: <i>Emirates zone</i>        |  |  |
| TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL   |  | <input type="checkbox"/> RESIDENTIAL    |   | <input type="checkbox"/> OTHERS          |  |
| <b>TYPE OF TANK</b>   |  |   |   |  |  |
| <input type="checkbox"/> CONCRETE   | <input checked="" type="checkbox"/> GRP PANEL  | <input type="checkbox"/> FRP TANK       | <input type="checkbox"/> GALVANIZED           | <input type="checkbox"/> STEEL PANEL     | <input type="checkbox"/> PLASTIC       |
| <input type="checkbox"/> CONCRETE COATED  |  | <input type="checkbox"/> POLYURETHANE   | <input type="checkbox"/> OTHERS               |  |  |
| <b>SIZE OF TANK</b>   |  |   | <b>QUANTITY OF WATER</b>                      |  |  |
| M3  | USG  | L*B*H                                   | <input type="checkbox"/> FULL                 | <input checked="" type="checkbox"/> HALF | <input type="checkbox"/> EMPTY         |
| <b>CONDITION OF WATER TANK BEFORE CLEANING</b>  |  |   | <b>CONDITION OF WATER TANK AFTER CLEANING</b> |  |  |
| <input type="checkbox"/> CLEAN  | <input checked="" type="checkbox"/> DIRTY      | <input type="checkbox"/> VERY DIRTY     | <input checked="" type="checkbox"/> CLEAN     | <input type="checkbox"/> DIRTY           | <input type="checkbox"/> VERY DIRTY    |
| <input type="checkbox"/> BIOFILMS   | <input type="checkbox"/> MOULDS                | <input type="checkbox"/> SLIME          | <input type="checkbox"/> BIOFILMS             | <input type="checkbox"/> MOULDS          | <input type="checkbox"/> SLIME         |
| <input type="checkbox"/> SEDIMENTS  | <input checked="" type="checkbox"/> MUD & SAND | <input type="checkbox"/> RUST           | <input type="checkbox"/> SEDIMENTS            | <input type="checkbox"/> MUD & SAND      | <input type="checkbox"/> RUST          |
| <b>ACCESS</b>   |  | <b>MANHOLE</b>                          |   | <input type="checkbox"/> COVERED         | <input type="checkbox"/> DAMAGED       |
|   |  |   |   | <input type="checkbox"/> NA              |  |
| <b>LADDER IN</b>  |  | <b>LADDER OUT</b>                       |   | <b>LEAKS</b>                             |  |
|   |  |   |   |  |  |
| <input checked="" type="checkbox"/> YES   | <input type="checkbox"/> NO                    | <input checked="" type="checkbox"/> YES | <input type="checkbox"/> NO                   | <input type="checkbox"/> YES             | <input checked="" type="checkbox"/> NO |
| <b>DRAIN LINE</b>   |  | <b>VALVES</b>                           |   | <b>FLOAT VALVE</b>                       |  |
|   |  |   |   |  |  |
| <input checked="" type="checkbox"/> YES   | <input type="checkbox"/> NO                    | <input checked="" type="checkbox"/> YES | <input type="checkbox"/> NO                   | <input checked="" type="checkbox"/> YES  | <input type="checkbox"/> NO            |
| <b>TANK CLEANED</b>   |  | <b>TANK DISINFECTED</b>                 |   | <b>PIPES DISINFECTED</b>                 |  |
|   |  |   |   |  |  |
| <input checked="" type="checkbox"/> YES   | <input type="checkbox"/> NO                    | <input checked="" type="checkbox"/> YES | <input type="checkbox"/> NO                   | <input type="checkbox"/> YES             | <input type="checkbox"/> NO            |
| <b>LAST CLEANING DATE</b>   |  | <b>CURRENT CLEANING DATE</b>            |   | <b>NEXT CLEANING DATE</b>                |  |
|   |  | <i>05/11/2018</i>                       |   | <i>05/05/2019</i>                        |  |
| <b>CHEMICALS &amp; EQUIPMENTS USED</b>  |  |   |   |  |  |
| 1. <i>Sodium hypochloride</i> Quantity <i>500 ml</i>  |  |   |   |  |  |
| 2. _____ Quantity _____   |  |   |   |  |  |
| <input checked="" type="checkbox"/> Submersibel Pump <input checked="" type="checkbox"/> High/Low Pressure Jet <input type="checkbox"/> Extension Cords <input type="checkbox"/> LED lights <input type="checkbox"/> Foot Bath <input type="checkbox"/> Ladder<br><input type="checkbox"/> Ventilating Fan <input type="checkbox"/> Suction/Discharge Hoses <input type="checkbox"/> Oxygen Meter <input checked="" type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials |  |   |   |  |  |
| <b>COMMENTS &amp; RECOMMENDATIONS:</b>  |  |   |   |  |  |
| <i>Mentioned tanks is cleaned &amp; disinfected</i>   |  |   |   |  |  |
| Crystalline Representative: <i>Yalder</i>   |  |   | Signature: <i>[Signature]</i>                 |  |  |

Date of Cleaning: 05-11-2018

**PHOTOGRAPHS**  
**GROUND LEVEL GRP WATER TANK – 02**

**BEFORE**



**AFTER**





# CRYSTALLINE ENVIRONMENTAL SERVICES

## WATER TANK - AFTER SERVICE REPORT

13472

|   |  |   |   |  |  |
|---|--|---|---|--|--|
| CUSTOMER: <i>Advanced, Ruweis</i>   |  |   | CONTACT PERSON: <i>Ms. Joy Thomas</i>         |  |  |
| SITE DETAILS: <i>Emirates Nucleon</i>   |  |   | CONTACT NO: <i>0565368606</i>                 |  |  |
| TANK DETAILS: <i>GRP tanks a3-</i>  |  |   | LOCATION DETAILS: <i>Emirates Zone</i>        |  |  |
| TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL   |  | <input type="checkbox"/> RESIDENTIAL    |   | <input type="checkbox"/> OTHERS          |  |
| <b>TYPE OF TANK</b>   |  |   |   |  |  |
| <input type="checkbox"/> CONCRETE   | <input checked="" type="checkbox"/> GRP PANEL  | <input type="checkbox"/> FRP TANK       | <input type="checkbox"/> GALVANIZED           | <input type="checkbox"/> STEEL PANEL     | <input type="checkbox"/> PLASTIC       |
| <input type="checkbox"/> CONCRETE COATED  |  | <input type="checkbox"/> POLYURETHANE   | <input type="checkbox"/> OTHERS               |  |  |
| <b>SIZE OF TANK</b>   |  |   | <b>QUANTITY OF WATER</b>                      |  |  |
| M3  | USG  | L*B*H                                   | <input type="checkbox"/> FULL                 | <input checked="" type="checkbox"/> HALF | <input type="checkbox"/> EMPTY         |
| <b>CONDITION OF WATER TANK BEFORE CLEANING</b>  |  |   | <b>CONDITION OF WATER TANK AFTER CLEANING</b> |  |  |
| <input type="checkbox"/> CLEAN  | <input checked="" type="checkbox"/> DIRTY      | <input type="checkbox"/> VERY DIRTY     | <input checked="" type="checkbox"/> CLEAN     | <input type="checkbox"/> DIRTY           | <input type="checkbox"/> VERY DIRTY    |
| <input type="checkbox"/> BIOFILMS   | <input type="checkbox"/> MOULDS                | <input type="checkbox"/> SLIME          | <input type="checkbox"/> BIOFILMS             | <input type="checkbox"/> MOULDS          | <input type="checkbox"/> SLIME         |
| <input type="checkbox"/> SEDIMENTS  | <input checked="" type="checkbox"/> MUD & SAND | <input type="checkbox"/> RUST           | <input type="checkbox"/> SEDIMENTS            | <input type="checkbox"/> MUD & SAND      | <input type="checkbox"/> RUST          |
| <b>ACCESS</b>   |  | <b>MANHOLE</b>                          |   | <input type="checkbox"/> COVERED         | <input type="checkbox"/> DAMAGED       |
| <input type="checkbox"/> NA   |  |   |   |  | <input type="checkbox"/> NA            |
| <b>LADDER IN</b>  |  | <b>LADDER OUT</b>                       |   | <b>LEAKS</b>                             |  |
| <input checked="" type="checkbox"/> YES   | <input type="checkbox"/> NO                    | <input checked="" type="checkbox"/> YES | <input type="checkbox"/> NO                   | <input type="checkbox"/> YES             | <input checked="" type="checkbox"/> NO |
| <b>DRAIN LINE</b>   |  | <b>VALVES</b>                           |   | <b>FLOAT VALVE</b>                       |  |
| <input checked="" type="checkbox"/> YES   | <input type="checkbox"/> NO                    | <input checked="" type="checkbox"/> YES | <input type="checkbox"/> NO                   | <input checked="" type="checkbox"/> YES  | <input type="checkbox"/> NO            |
| <b>TANK CLEANED</b>   |  | <b>TANK DISINFECTED</b>                 |   | <b>PIPES DISINFECTED</b>                 |  |
| <input checked="" type="checkbox"/> YES   | <input type="checkbox"/> NO                    | <input checked="" type="checkbox"/> YES | <input type="checkbox"/> NO                   | <input type="checkbox"/> YES             | <input type="checkbox"/> NO            |
| <b>LAST CLEANING DATE</b>   |  | <b>CURRENT CLEANING DATE</b>            |   | <b>NEXT CLEANING DATE</b>                |  |
|   |  | <i>05/11/2018</i>                       |   | <i>05/05/2019</i>                        |  |
| <b>CHEMICALS &amp; EQUIPMENTS USED</b>  |  |   |   |  |  |
| 1. <i>Sodium hypochlorite</i> Quantity <i>500 ml</i>  |  |   |   |  |  |
| 2. _____ Quantity _____   |  |   |   |  |  |
| <input checked="" type="checkbox"/> Submersible Pump <input type="checkbox"/> High/Low Pressure Jet <input type="checkbox"/> Extension Cords <input type="checkbox"/> LED lights <input type="checkbox"/> Foot Bath <input type="checkbox"/> Ladder |  |   |   |  |  |
| <input type="checkbox"/> Ventilating Fan <input type="checkbox"/> Suction/Discharge Hoses <input type="checkbox"/> Oxygen Meter <input type="checkbox"/> Vacuum Cleaner <input type="checkbox"/> Cleaning Materials                                 |  |   |   |  |  |
| <b>COMMENTS &amp; RECOMMENDATIONS:</b>  |  |   |   |  |  |
| <i>Mentioned tanks is cleaned &amp; disinfected</i>   |  |   |   |  |  |
| Crystalline Representative: <i>Yathar</i>   |  |   | Signature: <i>[Signature]</i>                 |  |  |

Date of Cleaning: 05-11-2018

**PHOTOGRAPHS**  
**GROUND LEVEL GRP WATER TANK – 03**

**BEFORE**



**AFTER**





# CRYSTALLINE ENVIRONMENTAL SERVICES

## WATER TANK - AFTER SERVICE REPORT


13473

|  |  |   |   |  |  |
|--|--|---|---|--|--|
| CUSTOMER: <i>Advanced, Ruwais</i>  |  |   | CONTACT PERSON: <i>Ms. Joy Cross</i>          |  |  |
| SITE DETAILS: <i>Emirates nuclear</i>  |  |   | CONTACT NO: <i>0565368606</i>                 |  |  |
| TANK DETAILS: <i>GRP tanks 04</i>  |  |   | LOCATION DETAILS: <i>Emirate zone</i>         |  |  |
| TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL  |  | <input type="checkbox"/> RESIDENTIAL    |   | <input type="checkbox"/> OTHERS          |  |
| <b>TYPE OF TANK</b>  |  |   |   |  |  |
| <input type="checkbox"/> CONCRETE  | <input checked="" type="checkbox"/> GRP PANEL  | <input type="checkbox"/> FRP TANK       | <input type="checkbox"/> GALVANIZED           | <input type="checkbox"/> STEEL PANEL     | <input type="checkbox"/> PLASTIC       |
| <input type="checkbox"/> CONCRETE COATED   |  | <input type="checkbox"/> POLYURETHANE   | <input type="checkbox"/> OTHERS               |  |  |
| <b>SIZE OF TANK</b>  |  |   | <b>QUANTITY OF WATER</b>                      |  |  |
| M3   | USG  | L*B*H                                   | <input type="checkbox"/> FULL                 | <input checked="" type="checkbox"/> HALF | <input type="checkbox"/> EMPTY         |
| <b>CONDITION OF WATER TANK BEFORE CLEANING</b>   |  |   | <b>CONDITION OF WATER TANK AFTER CLEANING</b> |  |  |
| <input type="checkbox"/> CLEAN   | <input checked="" type="checkbox"/> DIRTY      | <input type="checkbox"/> VERY DIRTY     | <input checked="" type="checkbox"/> CLEAN     | <input type="checkbox"/> DIRTY           | <input type="checkbox"/> VERY DIRTY    |
| <input type="checkbox"/> BIOFILMS  | <input type="checkbox"/> MOULDS                | <input type="checkbox"/> SLIME          | <input type="checkbox"/> BIOFILMS             | <input type="checkbox"/> MOULDS          | <input type="checkbox"/> SLIME         |
| <input type="checkbox"/> SEDIMENTS   | <input checked="" type="checkbox"/> MUD & SAND | <input type="checkbox"/> RUST           | <input type="checkbox"/> SEDIMENTS            | <input type="checkbox"/> MUD & SAND      | <input type="checkbox"/> RUST          |
| <b>ACCESS</b>  |  | <b>MANHOLE</b>                          |   | <input type="checkbox"/> COVERED         | <input type="checkbox"/> DAMAGED       |
| <input type="checkbox"/> NA  | <input type="checkbox"/> NA                    |   |   | <input type="checkbox"/> NA              | <input type="checkbox"/> NA            |
| <b>LADDER IN</b>   |  | <b>LADDER OUT</b>                       |   | <b>LEAKS</b>                             |  |
| <input checked="" type="checkbox"/> YES  | <input type="checkbox"/> NO                    | <input checked="" type="checkbox"/> YES | <input type="checkbox"/> NO                   | <input type="checkbox"/> YES             | <input checked="" type="checkbox"/> NO |
| <b>TANK CLEANED</b>  |  | <b>TANK DISINFECTED</b>                 |   | <b>PIPES DISINFECTED</b>                 |  |
| <input checked="" type="checkbox"/> YES  | <input type="checkbox"/> NO                    | <input checked="" type="checkbox"/> YES | <input type="checkbox"/> NO                   | <input type="checkbox"/> YES             | <input type="checkbox"/> NO            |
| <b>LAST CLEANING DATE</b>  |  | <b>CURRENT CLEANING DATE</b>            |   | <b>NEXT CLEANING DATE</b>                |  |
|  |  | <i>06/11/2018</i>                       |   | <i>06/05/2019</i>                        |  |
| <b>CHEMICALS &amp; EQUIPMENTS USED</b>   |  |   |   |  |  |
| 1. <i>Sodium hypochloride</i> Quantity <i>500 ml</i>   |  |   |   |  |  |
| 2. _____ Quantity _____  |  |   |   |  |  |
| <input type="checkbox"/> Submersibel Pump <input type="checkbox"/> High/Low Pressure Jet <input type="checkbox"/> Extension Cords <input type="checkbox"/> LED lights <input checked="" type="checkbox"/> Foot Bath <input type="checkbox"/> Ladder<br><input checked="" type="checkbox"/> Ventilating Fan <input type="checkbox"/> Suction/Discharge Hoses <input type="checkbox"/> Oxygen Meter <input checked="" type="checkbox"/> Vacuum Cleaner <input type="checkbox"/> Cleaning Materials |  |   |   |  |  |
| <b>COMMENTS &amp; RECOMMENDATIONS:</b>   |  |   |   |  |  |
| <i>Mentioned tanks is cleaned &amp; disinfected</i>  |  |   |   |  |  |
| Crystalline Representative: <i>Yathash</i>   |  |   | Signature: <i>Joy Cross</i>                   |  |  |


Date of Cleaning: 06-11-2018

**PHOTOGRAPHS**  
**GROUND LEVEL GRP WATER TANK – 04**

**BEFORE**



**AFTER**





# CRYSTALLINE ENVIRONMENTAL SERVICES

## WATER TANK - AFTER SERVICE REPORT

13474

| CUSTOMER: <i>Advanced &gt; Ruweis</i>                  |  |  | CONTACT PERSON: <i>Ms. Jay Thomas</i>          |   |  |
|--|--|--|--|---|--|
| SITE DETAILS: <i>Emirates mubon</i>                    |  |  | CONTACT NO: <i>056 536 8606</i>                |   |  |
| TANK DETAILS: <i>RCC tanks of</i>                      |  |  | LOCATION DETAILS: <i>Guest pump room</i>       |   |  |
| TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL  |  | <input type="checkbox"/> RESIDENTIAL             |  | <input type="checkbox"/> OTHERS             |  |
| TYPE OF TANK   |  |  |  |   |  |
| <input checked="" type="checkbox"/> CONCRETE           | <input type="checkbox"/> GRP PANEL               | <input type="checkbox"/> FRP TANK                | <input type="checkbox"/> GALVANIZED            | <input type="checkbox"/> STEEL PANEL        | <input type="checkbox"/> PLASTIC       |
| <input type="checkbox"/> CONCRETE COATED               |  | <input type="checkbox"/> POLYURETHANE            | <input type="checkbox"/> OTHERS                |   |  |
| SIZE OF TANK   |  |  | QUANTITY OF WATER                              |   |  |
| M3   | USG  | L*B*H  | <input checked="" type="checkbox"/> FULL       | <input type="checkbox"/> HALF               | <input type="checkbox"/> EMPTY         |
| CONDITION OF WATER TANK BEFORE CLEANING                |  |  | CONDITION OF WATER TANK AFTER CLEANING         |   |  |
| <input type="checkbox"/> CLEAN                         | <input checked="" type="checkbox"/> DIRTY        | <input type="checkbox"/> VERY DIRTY              | <input checked="" type="checkbox"/> CLEAN      | <input type="checkbox"/> DIRTY              | <input type="checkbox"/> VERY DIRTY    |
| <input type="checkbox"/> BIOFILMS                      | <input type="checkbox"/> MOULDS                  | <input type="checkbox"/> SLIME                   | <input type="checkbox"/> BIOFILMS              | <input type="checkbox"/> MOULDS             | <input type="checkbox"/> SLIME         |
| <input type="checkbox"/> SEDIMENTS                     | <input checked="" type="checkbox"/> MUD & SAND   | <input type="checkbox"/> RUST                    | <input type="checkbox"/> SEDIMENTS             | <input type="checkbox"/> MUD & SAND         | <input type="checkbox"/> RUST          |
| ACCESS   |  | MANHOLE  |  | <input type="checkbox"/> COVERED            | <input type="checkbox"/> DAMAGED       |
| <input type="checkbox"/> NA                            | <input type="checkbox"/> NA                      | <input type="checkbox"/> NA                      | <input type="checkbox"/> NA                    | <input type="checkbox"/> NA                 | <input type="checkbox"/> NA            |
| LADDER IN  |  | LADDER OUT                                       |  | LEAKS                                       |  |
| <input checked="" type="checkbox"/> YES                | <input type="checkbox"/> NO                      | <input checked="" type="checkbox"/> YES          | <input type="checkbox"/> NO                    | <input type="checkbox"/> YES                | <input checked="" type="checkbox"/> NO |
| DRAIN LINE   |  | VALVES   |  | FLOAT VALVE                                 |  |
| <input type="checkbox"/> YES                           | <input checked="" type="checkbox"/> NO           | <input checked="" type="checkbox"/> YES          | <input type="checkbox"/> NO                    | <input checked="" type="checkbox"/> YES     | <input type="checkbox"/> NO            |
| TANK CLEANED   |  | TANK DISINFECTED                                 |  | PIPES DISINFECTED                           |  |
| <input checked="" type="checkbox"/> YES                | <input type="checkbox"/> NO                      | <input checked="" type="checkbox"/> YES          | <input type="checkbox"/> NO                    | <input type="checkbox"/> YES                | <input type="checkbox"/> NO            |
| <input type="checkbox"/> NA                            | <input type="checkbox"/> NA                      | <input type="checkbox"/> NA                      | <input type="checkbox"/> NA                    | <input type="checkbox"/> NA                 | <input type="checkbox"/> NA            |
| LAST CLEANING DATE                                     |  | CURRENT CLEANING DATE                            |  | NEXT CLEANING DATE                          |  |
|  |  | <i>06/11/2018</i>                                |  | <i>06/05/2019</i>                           |  |
| CHEMICALS & EQUIPMENTS USED                            |  |  |  |   |  |
| 1. <i>Sodium hypochloride</i> Quantity <i>of liter</i> |  |  |  |   |  |
| 2. _____ Quantity _____                                |  |  |  |   |  |
| <input checked="" type="checkbox"/> Submersibel Pump   | <input type="checkbox"/> High/Low Pressure Jet   | <input type="checkbox"/> Extension Cords         | <input checked="" type="checkbox"/> LED lights | <input type="checkbox"/> Foot Bath          | <input type="checkbox"/> Ladder        |
| <input checked="" type="checkbox"/> Ventilating Fan    | <input type="checkbox"/> Suction/Discharge Hoses | <input checked="" type="checkbox"/> Oxygen Meter | <input type="checkbox"/> Vacuum Cleaner        | <input type="checkbox"/> Cleaning Materials |  |
| COMMENTS & RECOMMENDATIONS:                            |  |  |  |   |  |
| <i>Mentioned tanks is cleaned &amp; disinfected</i>    |  |  |  |   |  |
| Crystalline Representative: <i>Yaltesh</i>             |  |  | Signature: <i>[Signature]</i>                  |   |  |

Date of Cleaning: 06-11-2018

**PHOTOGRAPHS**  
**GROUND LEVEL RCC WATER TANK – 01**

**BEFORE**



**AFTER**





# CRYSTALLINE ENVIRONMENTAL SERVICES

## WATER TANK - AFTER SERVICE REPORT


13475

|   |  |   |   |  |  |
|---|--|---|---|--|--|
| CUSTOMER: <i>Advanced, Rawais</i>   |  |   | CONTACT PERSON: <i>Mr. Jay Thomas</i>         |  |  |
| SITE DETAILS: <i>Emirates nuclear</i>   |  |   | CONTACT NO: <i>0565368606</i>                 |  |  |
| TANK DETAILS: <i>RCC tanks 2</i>  |  |   | LOCATION DETAILS: <i>Guest pump room</i>      |  |  |
| TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL   |  | <input type="checkbox"/> RESIDENTIAL    |   | <input type="checkbox"/> OTHERS          |  |
| <b>TYPE OF TANK</b>   |  |   |   |  |  |
| <input checked="" type="checkbox"/> CONCRETE  | <input type="checkbox"/> GRP PANEL             | <input type="checkbox"/> FRP TANK       | <input type="checkbox"/> GALVANIZED           | <input type="checkbox"/> STEEL PANEL     | <input type="checkbox"/> PLASTIC       |
| <input type="checkbox"/> CONCRETE COATED  |  | <input type="checkbox"/> POLYURETHANE   | <input type="checkbox"/> OTHERS               |  |  |
| <b>SIZE OF TANK</b>   |  |   | <b>QUANTITY OF WATER</b>                      |  |  |
| M3  | USG  | L*B*H                                   | <input type="checkbox"/> FULL                 | <input checked="" type="checkbox"/> HALF | <input type="checkbox"/> EMPTY         |
| <b>CONDITION OF WATER TANK BEFORE CLEANING</b>  |  |   | <b>CONDITION OF WATER TANK AFTER CLEANING</b> |  |  |
| <input type="checkbox"/> CLEAN  | <input checked="" type="checkbox"/> DIRTY      | <input type="checkbox"/> VERY DIRTY     | <input checked="" type="checkbox"/> CLEAN     | <input type="checkbox"/> DIRTY           | <input type="checkbox"/> VERY DIRTY    |
| <input type="checkbox"/> BIOFILMS   | <input type="checkbox"/> MOULDS                | <input type="checkbox"/> SLIME          | <input type="checkbox"/> BIOFILMS             | <input type="checkbox"/> MOULDS          | <input type="checkbox"/> SLIME         |
| <input type="checkbox"/> SEDIMENTS  | <input checked="" type="checkbox"/> MUD & SAND | <input type="checkbox"/> RUST           | <input type="checkbox"/> SEDIMENTS            | <input type="checkbox"/> MUD & SAND      | <input type="checkbox"/> RUST          |
| <b>ACCESS</b>   |  | <b>MANHOLE</b>                          |   | <input type="checkbox"/> COVERED         | <input type="checkbox"/> DAMAGED       |
| <input type="checkbox"/> NA   |  |   | <input type="checkbox"/> NA                   |  |  |
| <b>LADDER IN</b>  |  | <b>LADDER OUT</b>                       |   | <b>LEAKS</b>                             |  |
| <input checked="" type="checkbox"/> YES   | <input type="checkbox"/> NO                    | <input checked="" type="checkbox"/> YES | <input type="checkbox"/> NO                   | <input type="checkbox"/> YES             | <input checked="" type="checkbox"/> NO |
| <b>TANK CLEANED</b>   |  | <b>TANK DISINFECTED</b>                 |   | <b>PIPES DISINFECTED</b>                 |  |
| <input checked="" type="checkbox"/> YES   | <input type="checkbox"/> NO                    | <input checked="" type="checkbox"/> YES | <input type="checkbox"/> NO                   | <input type="checkbox"/> YES             | <input type="checkbox"/> NO            |
| <b>LAST CLEANING DATE</b>   |  | <b>CURRENT CLEANING DATE</b>            |   | <b>NEXT CLEANING DATE</b>                |  |
|   |  | <i>07/11/2018</i>                       |   | <i>07/05/2019</i>                        |  |
| <b>CHEMICALS &amp; EQUIPMENTS USED</b>  |  |   |   |  |  |
| 1. <i>Sodium Hypochloride</i> Quantity <i>01 liter</i>  |  |   |   |  |  |
| 2. _____ Quantity _____   |  |   |   |  |  |
| <input checked="" type="checkbox"/> Submersibel Pump <input type="checkbox"/> High/Low Pressure Jet <input type="checkbox"/> Extension Cords <input type="checkbox"/> LED lights <input type="checkbox"/> Foot Bath <input type="checkbox"/> Ladder<br><input type="checkbox"/> Ventilating Fan <input type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Meter <input type="checkbox"/> Vacuum Cleaner <input type="checkbox"/> Cleaning Materials |  |   |   |  |  |
| <b>COMMENTS &amp; RECOMMENDATIONS:</b>  |  |   |   |  |  |
| <i>Mentioned tanks is cleaned &amp; disinfected</i>   |  |   |   |  |  |
| Crystalline Representative: <i>Yalton</i>   |  |   | Signature: <i>[Signature]</i>                 |  |  |


Date of Cleaning: 07-11-2018

**PHOTOGRAPHS**  
**GROUND LEVEL RCC WATER TANK – 02**

**BEFORE**



**AFTER**





# CRYSTALLINE ENVIRONMENTAL SERVICES

## WATER TANK - AFTER SERVICE REPORT

13476

|  |  |   |   |                                      |   |
|--|--|---|---|--------------------------------------|---|
| CUSTOMER: <i>Advanced, Ruwais</i>  |  |   | CONTACT PERSON: <i>Mr Joy Thomas</i>          |                                      |   |
| SITE DETAILS: <i>Emirates, Nuclear</i>   |  |   | CONTACT NO: <i>055 5368606</i>                |                                      |   |
| TANK DETAILS: <i>RCC tanks 3</i>   |  |   | LOCATION DETAILS: <i>Guest pump room</i>      |                                      |   |
| TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL  |  | <input type="checkbox"/> RESIDENTIAL    |   | <input type="checkbox"/> OTHERS      |   |
| <b>TYPE OF TANK</b>  |  |   |   |                                      |   |
| <input checked="" type="checkbox"/> CONCRETE   | <input type="checkbox"/> GRP PANEL             | <input type="checkbox"/> FRP TANK       | <input type="checkbox"/> GALVANIZED           | <input type="checkbox"/> STEEL PANEL | <input type="checkbox"/> PLASTIC                        |
| <input type="checkbox"/> CONCRETE COATED   |  | <input type="checkbox"/> POLYURETHANE   |   | <input type="checkbox"/> OTHERS      |   |
| <b>SIZE OF TANK</b>  |  |   | <b>QUANTITY OF WATER</b>                      |                                      |   |
| M3   | USG  | L*B*H                                   | <input checked="" type="checkbox"/> FULL      | <input type="checkbox"/> HALF        | <input type="checkbox"/> EMPTY                          |
| <b>CONDITION OF WATER TANK BEFORE CLEANING</b>   |  |   | <b>CONDITION OF WATER TANK AFTER CLEANING</b> |                                      |   |
| <input type="checkbox"/> CLEAN   | <input checked="" type="checkbox"/> DIRTY      | <input type="checkbox"/> VERY DIRTY     | <input checked="" type="checkbox"/> CLEAN     | <input type="checkbox"/> DIRTY       | <input type="checkbox"/> VERY DIRTY                     |
| <input type="checkbox"/> BIOFILMS  | <input type="checkbox"/> MOULDS                | <input type="checkbox"/> SLIME          | <input type="checkbox"/> BIOFILMS             | <input type="checkbox"/> MOULDS      | <input type="checkbox"/> SLIME                          |
| <input type="checkbox"/> SEDIMENTS   | <input checked="" type="checkbox"/> MUD & SAND | <input type="checkbox"/> RUST           | <input type="checkbox"/> SEDIMENTS            | <input type="checkbox"/> MUD & SAND  | <input type="checkbox"/> RUST                           |
| <b>ACCESS</b>  |  | <b>MANHOLE</b>                          |   | <input type="checkbox"/> COVERED     |   |
| <input type="checkbox"/> DAMAGED   |  | <input type="checkbox"/> NA             |   |                                      |   |
| <b>LADDER IN</b>   |  | <b>LADDER OUT</b>                       |   | <b>LEAKS</b>                         |   |
| <b>DRAIN LINE</b>  |  | <b>VALVES</b>                           |   | <b>FLOAT VALVE</b>                   |   |
| <input checked="" type="checkbox"/> YES  | <input type="checkbox"/> NO                    | <input checked="" type="checkbox"/> YES | <input type="checkbox"/> NO                   | <input type="checkbox"/> YES         | <input checked="" type="checkbox"/> NO                  |
| <input type="checkbox"/> YES   | <input checked="" type="checkbox"/> NO         | <input type="checkbox"/> YES            | <input checked="" type="checkbox"/> NO        | <input type="checkbox"/> YES         | <input checked="" type="checkbox"/> NO                  |
| <b>TANK CLEANED</b>  |  | <b>TANK DISINFECTED</b>                 |   | <b>PIPES DISINFECTED</b>             |   |
| <input checked="" type="checkbox"/> YES  | <input type="checkbox"/> NO                    | <input checked="" type="checkbox"/> YES | <input type="checkbox"/> NO                   | <input type="checkbox"/> YES         | <input type="checkbox"/> NO <input type="checkbox"/> NA |
| <b>LAST CLEANING DATE</b>  |  | <b>CURRENT CLEANING DATE</b>            |   | <b>NEXT CLEANING DATE</b>            |   |
|  |  | <i>07/11/2018</i>                       |   | <i>07/05/2019</i>                    |   |
| <b>CHEMICALS &amp; EQUIPMENTS USED</b>   |  |   |   |                                      |   |
| 1. <i>Sodium hypochloride</i> Quantity <i>750 ml</i>   |  |   |   |                                      |   |
| 2. _____ Quantity _____  |  |   |   |                                      |   |
| <input checked="" type="checkbox"/> Submersibel Pump <input type="checkbox"/> High/Low Pressure Jet <input type="checkbox"/> Extension Cords <input type="checkbox"/> LED lights <input type="checkbox"/> Foot Bath <input type="checkbox"/> Ladder  |  |   |   |                                      |   |
| <input type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Meter <input checked="" type="checkbox"/> Vacuum Cleaner <input type="checkbox"/> Cleaning Materials |  |   |   |                                      |   |
| <b>COMMENTS &amp; RECOMMENDATIONS:</b>   |  |   |   |                                      |   |
| <i>Mentioned tanks is cleaned &amp; disinfected</i>  |  |   |   |                                      |   |
| Crystalline Representative: <i>Yathens</i>   |  |   | Signature: <i>[Signature]</i>                 |                                      |   |



**CRYSTALLINE**  
ENVIRONMENTAL SERVICES

Date of Cleaning: 07-11-2018

**PHOTOGRAPHS**  
**GROUND LEVEL RCC WATER TANK – 03**

**BEFORE**



**AFTER**



**CLEANER WATER GREENER TOMORROW**



# CRYSTALLINE ENVIRONMENTAL SERVICES

## WATER TANK - AFTER SERVICE REPORT

13477

| CUSTOMER: <i>Advanced Ruwais</i>  |  |  | CONTACT PERSON: <i>Mr. Jay Thomas</i>     |  |  |
|---|--|--|---|--|--|
| SITE DETAILS: <i>Emirates nucleon</i>   |  |  | CONTACT NO: <i>0555368606</i>             |  |  |
| TANK DETAILS: <i>RCC tanks 04</i>   |  |  | LOCATION DETAILS: <i>Quest pump room</i>  |  |  |
| TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL   |  | <input type="checkbox"/> RESIDENTIAL                 |   | <input type="checkbox"/> OTHERS            |  |
| TYPE OF TANK  |  |  |   |  |  |
| <input checked="" type="checkbox"/> CONCRETE  | <input type="checkbox"/> GRP PANEL             | <input type="checkbox"/> FRP TANK                    | <input type="checkbox"/> GALVANIZED       | <input type="checkbox"/> STEEL PANEL       | <input type="checkbox"/> PLASTIC                                   |
| <input type="checkbox"/> CONCRETE COATED  |  | <input type="checkbox"/> POLYURETHANE                |   | <input type="checkbox"/> OTHERS            |  |
| SIZE OF TANK  |  |  | QUANTITY OF WATER                         |  |  |
| M3  | USG  | L*B*H  | <input checked="" type="checkbox"/> FULL  | <input type="checkbox"/> HALF              | <input type="checkbox"/> EMPTY                                     |
| CONDITION OF WATER TANK BEFORE CLEANING   |  |  | CONDITION OF WATER TANK AFTER CLEANING    |  |  |
| <input type="checkbox"/> CLEAN  | <input checked="" type="checkbox"/> DIRTY      | <input type="checkbox"/> VERY DIRTY                  | <input checked="" type="checkbox"/> CLEAN | <input type="checkbox"/> DIRTY             | <input type="checkbox"/> VERY DIRTY                                |
| <input type="checkbox"/> BIOFILMS   | <input type="checkbox"/> MOULDS                | <input type="checkbox"/> SLIME                       | <input type="checkbox"/> BIOFILMS         | <input type="checkbox"/> MOULDS            | <input type="checkbox"/> SLIME                                     |
| <input type="checkbox"/> SEDIMENTS  | <input checked="" type="checkbox"/> MUD & SAND | <input type="checkbox"/> RUST                        | <input type="checkbox"/> SEDIMENTS        | <input type="checkbox"/> MUD & SAND        | <input type="checkbox"/> RUST                                      |
| ACCESS  |  | MANHOLE  |   | <input type="checkbox"/> COVERED           | <input type="checkbox"/> DAMAGED                                   |
| <input checked="" type="checkbox"/> LADDER IN   | <input type="checkbox"/> LADDER OUT            | <input type="checkbox"/> LEAKS                       |   | <input type="checkbox"/> DRAIN LINE        | <input type="checkbox"/> VALVES                                    |
| <input checked="" type="checkbox"/> YES   | <input type="checkbox"/> NO                    | <input checked="" type="checkbox"/> YES              | <input type="checkbox"/> NO               | <input type="checkbox"/> YES               | <input type="checkbox"/> NO  |
| <input checked="" type="checkbox"/> TANK CLEANED  |  | <input checked="" type="checkbox"/> TANK DISINFECTED |   | <input type="checkbox"/> PIPES DISINFECTED |  |
| <input checked="" type="checkbox"/> YES   | <input type="checkbox"/> NO                    | <input checked="" type="checkbox"/> YES              | <input type="checkbox"/> NO               | <input type="checkbox"/> YES               | <input type="checkbox"/> NO <input checked="" type="checkbox"/> NA |
| LAST CLEANING DATE  |  | CURRENT CLEANING DATE                                |   | NEXT CLEANING DATE                         |  |
|   |  | <i>07/11/2018</i>                                    |   | <i>07/05/2019</i>                          |  |
| CHEMICALS & EQUIPMENTS USED   |  |  |   |  |  |
| 1. <i>Sodium hypochloride</i> Quantity <i>750 ml</i>  |  |  |   |  |  |
| 2. _____ Quantity _____   |  |  |   |  |  |
| <input type="checkbox"/> Submersibel Pump <input checked="" type="checkbox"/> High/Low Pressure Jet <input type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED lights <input type="checkbox"/> Foot Bath <input checked="" type="checkbox"/> Ladder<br><input checked="" type="checkbox"/> Ventilating Fan <input type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Meter <input type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials |  |  |   |  |  |
| COMMENTS & RECOMMENDATIONS:   |  |  |   |  |  |
| <i>Mentored tanks is cleaned &amp; disinfected</i>  |  |  |   |  |  |
| Crystalline Representative: <i>Yathen</i>   |  |  | Signature: <i>[Signature]</i>             |  |  |



Date of Cleaning: 07-11-2018

**PHOTOGRAPHS**  
**GROUND LEVEL RCC WATER TANK – 04**

**BEFORE**



**AFTER**





# CRYSTALLINE ENVIRONMENTAL SERVICES

## WATER TANK - AFTER SERVICE REPORT

13478

|   |  |   |   |  |  |
|---|--|---|---|--|--|
| CUSTOMER: <i>Advanced, Renewis</i>  |  |   | CONTACT PERSON: <i>M. Joy Thomas</i>          |  |  |
| SITE DETAILS: <i>Emirates, nuclear</i>  |  |   | CONTACT NO: <i>0555065606</i>                 |  |  |
| TANK DETAILS: <i>GRP tanks of [A+B]</i>   |  |   | LOCATION DETAILS: <i>Quant pump room</i>      |  |  |
| TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL   |  | <input type="checkbox"/> RESIDENTIAL    |   | <input type="checkbox"/> OTHERS          |  |
| <b>TYPE OF TANK</b>   |  |   |   |  |  |
| <input type="checkbox"/> CONCRETE   | <input checked="" type="checkbox"/> GRP PANEL  | <input type="checkbox"/> FRP TANK       | <input type="checkbox"/> GALVANIZED           | <input type="checkbox"/> STEEL PANEL     | <input type="checkbox"/> PLASTIC       |
| <input type="checkbox"/> CONCRETE COATED  |  | <input type="checkbox"/> POLYURETHANE   | <input type="checkbox"/> OTHERS               |  |  |
| <b>SIZE OF TANK</b>   |  |   | <b>QUANTITY OF WATER</b>                      |  |  |
| M3  | USG  | L*B*H                                   | <input type="checkbox"/> FULL                 | <input checked="" type="checkbox"/> HALF | <input type="checkbox"/> EMPTY         |
| <b>CONDITION OF WATER TANK BEFORE CLEANING</b>  |  |   | <b>CONDITION OF WATER TANK AFTER CLEANING</b> |  |  |
| <input type="checkbox"/> CLEAN  | <input checked="" type="checkbox"/> DIRTY      | <input type="checkbox"/> VERY DIRTY     | <input checked="" type="checkbox"/> CLEAN     | <input type="checkbox"/> DIRTY           | <input type="checkbox"/> VERY DIRTY    |
| <input type="checkbox"/> BIOFILMS   | <input type="checkbox"/> MOULDS                | <input type="checkbox"/> SLIME          | <input type="checkbox"/> BIOFILMS             | <input type="checkbox"/> MOULDS          | <input type="checkbox"/> SLIME         |
| <input type="checkbox"/> SEDIMENTS  | <input checked="" type="checkbox"/> MUD & SAND | <input type="checkbox"/> RUST           | <input type="checkbox"/> SEDIMENTS            | <input type="checkbox"/> MUD & SAND      | <input type="checkbox"/> RUST          |
| <b>ACCESS</b>   |  | <b>MANHOLE</b>                          |   | <input type="checkbox"/> COVERED         | <input type="checkbox"/> DAMAGED       |
| <input type="checkbox"/> NA   |  |   |   |  | <input type="checkbox"/> NA            |
| <b>LADDER IN</b>  |  | <b>LADDER OUT</b>                       |   | <b>LEAKS</b>                             |  |
| <input checked="" type="checkbox"/> YES   | <input type="checkbox"/> NO                    | <input checked="" type="checkbox"/> YES | <input type="checkbox"/> NO                   | <input type="checkbox"/> YES             | <input checked="" type="checkbox"/> NO |
| <b>DRAIN LINE</b>   |  | <b>VALVES</b>                           |   | <b>FLOAT VALVE</b>                       |  |
| <input checked="" type="checkbox"/> YES   | <input type="checkbox"/> NO                    | <input checked="" type="checkbox"/> YES | <input type="checkbox"/> NO                   | <input checked="" type="checkbox"/> YES  | <input type="checkbox"/> NO            |
| <b>TANK CLEANED</b>   |  | <b>TANK DISINFECTED</b>                 |   | <b>PIPES DISINFECTED</b>                 |  |
| <input checked="" type="checkbox"/> YES   | <input type="checkbox"/> NO                    | <input checked="" type="checkbox"/> YES | <input type="checkbox"/> NO                   | <input type="checkbox"/> YES             | <input type="checkbox"/> NO            |
| <b>LAST CLEANING DATE</b>   |  | <b>CURRENT CLEANING DATE</b>            |   | <b>NEXT CLEANING DATE</b>                |  |
|   |  | <i>08/11/2018</i>                       |   | <i>08/05/2019</i>                        |  |
| <b>CHEMICALS &amp; EQUIPMENTS USED</b>  |  |   |   |  |  |
| 1. <i>Sodium hypochloride</i> Quantity <i>500 ml</i>  |  |   |   |  |  |
| 2. _____ Quantity _____   |  |   |   |  |  |
| <input checked="" type="checkbox"/> Submersibel Pump <input type="checkbox"/> High/Low Pressure Jet <input type="checkbox"/> Extension Cords <input type="checkbox"/> LED lights <input type="checkbox"/> Foot Bath <input type="checkbox"/> Ladder |  |   |   |  |  |
| <input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Suction/Discharge Hoses <input type="checkbox"/> Oxygen Meter <input type="checkbox"/> Vacuum Cleaner <input type="checkbox"/> Cleaning Materials           |  |   |   |  |  |
| <b>COMMENTS &amp; RECOMMENDATIONS:</b>  |  |   |   |  |  |
| <i>Mentioned tanks is cleaned &amp; disinfected</i>   |  |   |   |  |  |
| Crystalline Representative: <i>Yathens</i>  |  |   | Signature: <i>[Signature]</i>                 |  |  |



**CRYSTALLINE**  
ENVIRONMENTAL SERVICES

Date of Cleaning: 08-11-2018

**PHOTOGRAPHS**  
**GROUND LEVEL GRP WATER TANK – A & B**

**BEFORE**



**AFTER**



**CLEANER WATER GREENER TOMORROW**



# CRYSTALLINE ENVIRONMENTAL SERVICES

## WATER TANK - AFTER SERVICE REPORT

13479

|   |   |  |  |   |  |
|---|---|--|--|---|--|
| CUSTOMER: <i>Advanced, Renewals</i>                   |   |  | CONTACT PERSON: <i>Ms Joy Thomas</i>               |   |  |
| SITE DETAILS: <i>Emirates, nuclear</i>                |   |  | CONTACT NO: <i>055 536 8606</i>                    |   |  |
| TANK DETAILS: <i>GRP tanks of</i>                     |   |  | LOCATION DETAILS: <i>172 Zone Area</i>             |   |  |
| TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL |   | <input type="checkbox"/> RESIDENTIAL     |  | <input type="checkbox"/> OTHERS             |  |
| <b>TYPE OF TANK</b>                                   |   |  |  |   |  |
| <input type="checkbox"/> CONCRETE                     | <input checked="" type="checkbox"/> GRP PANEL             | <input type="checkbox"/> FRP TANK        | <input type="checkbox"/> GALVANIZED                | <input type="checkbox"/> STEEL PANEL        | <input type="checkbox"/> PLASTIC       |
| <input type="checkbox"/> CONCRETE COATED              |   | <input type="checkbox"/> POLYURETHANE    | <input type="checkbox"/> OTHERS                    |   |  |
| <b>SIZE OF TANK</b>                                   |   |  | <b>QUANTITY OF WATER</b>                           |   |  |
| M3  | USG   | L*B*H                                    | <input checked="" type="checkbox"/> FULL           | <input type="checkbox"/> HALF               | <input type="checkbox"/> EMPTY         |
| <b>CONDITION OF WATER TANK BEFORE CLEANING</b>        |   |  | <b>CONDITION OF WATER TANK AFTER CLEANING</b>      |   |  |
| <input type="checkbox"/> CLEAN                        | <input checked="" type="checkbox"/> DIRTY                 | <input type="checkbox"/> VERY DIRTY      | <input checked="" type="checkbox"/> CLEAN          | <input type="checkbox"/> DIRTY              | <input type="checkbox"/> VERY DIRTY    |
| <input type="checkbox"/> BIOFILMS                     | <input type="checkbox"/> MOULDS                           | <input type="checkbox"/> SLIME           | <input type="checkbox"/> BIOFILMS                  | <input type="checkbox"/> MOULDS             | <input type="checkbox"/> SLIME         |
| <input type="checkbox"/> SEDIMENTS                    | <input checked="" type="checkbox"/> MUD & SAND            | <input type="checkbox"/> RUST            | <input type="checkbox"/> SEDIMENTS                 | <input type="checkbox"/> MUD & SAND         | <input type="checkbox"/> RUST          |
| <b>ACCESS</b>   |   | <b>MANHOLE</b>                           |  | <input type="checkbox"/> COVERED            | <input type="checkbox"/> DAMAGED       |
| <input type="checkbox"/> NA                           |   |  |  |   | <input type="checkbox"/> NA            |
| <b>LADDER IN</b>                                      |   | <b>LADDER OUT</b>                        |  | <b>LEAKS</b>                                |  |
| <input checked="" type="checkbox"/> YES               | <input type="checkbox"/> NO                               | <input checked="" type="checkbox"/> YES  | <input type="checkbox"/> NO                        | <input type="checkbox"/> YES                | <input checked="" type="checkbox"/> NO |
| <b>DRAIN LINE</b>                                     |   | <b>VALVES</b>                            |  | <b>FLOAT VALVE</b>                          |  |
| <input checked="" type="checkbox"/> YES               | <input type="checkbox"/> NO                               | <input checked="" type="checkbox"/> YES  | <input type="checkbox"/> NO                        | <input checked="" type="checkbox"/> YES     | <input type="checkbox"/> NO            |
| <b>TANK CLEANED</b>                                   |   | <b>TANK DISINFECTED</b>                  |  | <b>PIPES DISINFECTED</b>                    |  |
| <input checked="" type="checkbox"/> YES               | <input type="checkbox"/> NO                               | <input checked="" type="checkbox"/> YES  | <input type="checkbox"/> NO                        | <input type="checkbox"/> YES                | <input type="checkbox"/> NO            |
| <b>LAST CLEANING DATE</b>                             |   | <b>CURRENT CLEANING DATE</b>             |  | <b>NEXT CLEANING DATE</b>                   |  |
|   |   | <i>09/11/2018</i>                        |  | <i>09/05/2019</i>                           |  |
| <b>CHEMICALS &amp; EQUIPMENTS USED</b>                |   |  |  |   |  |
| 1. <i>Sodium hypochlorite</i> Quantity <i>500 ml</i>  |   |  |  |   |  |
| 2. _____ Quantity _____                               |   |  |  |   |  |
| <input checked="" type="checkbox"/> Submersible Pump  | <input checked="" type="checkbox"/> High/Low Pressure Jet | <input type="checkbox"/> Extension Cords | <input type="checkbox"/> LED lights                | <input type="checkbox"/> Foot Bath          | <input type="checkbox"/> Ladder        |
| <input checked="" type="checkbox"/> Ventilating Fan   | <input type="checkbox"/> Suction/Discharge Hoses          | <input type="checkbox"/> Oxygen Meter    | <input checked="" type="checkbox"/> Vacuum Cleaner | <input type="checkbox"/> Cleaning Materials |  |
| <b>COMMENTS &amp; RECOMMENDATIONS:</b>                |   |  |  |   |  |
| <i>Mentioned tanks is cleaned &amp; disinfected</i>   |   |  |  |   |  |
| Crystalline Representative: <i>Yalberk</i>            |   |  | Signature: <i>[Signature]</i>                      |   |  |

Date of Cleaning: 09-11-2018

**PHOTOGRAPHS**  
**GROUND LEVEL GRP WATER TANK – 172 Zone Area**

**BEFORE**



**AFTER**



# CRYSTALLINE CLEANING & ENVIRONMENTAL SERVICES

## CLEANING & DISINFECTION CERTIFICATE

### POTABLE WATER TANKS

**CLIENT NAME** : ADVANCED FACILITIES MANAGEMENT.

**CLIENT ADDRESS** : P.O. BOX: 44038, ABU DHABI, UAE.

**CONTACT PERSON** : MR. KENNEDY PEREIRA.

**SITE DETAILS** : ENEC – RUWAIS, ABU DHABI, UAE.

**DETAILS** : WATER TANK CLEANING

**DATE OF CLEANING** : NOVEMBER 2018

**FREQUENCY OF CLEANING** : EVERY FOUR MONTHS

**DATE OF NEXT CLEANING** : MAY 2019

*The procedures employed in this cleaning and disinfection comply with HS (G) 70 health and safety guidelines for prevention of legionella as well as BS6700 and CARELA BIO PLUS method statement.*

*The entire water storage tank should be cleaned and disinfected minimum every four (4) months depending upon the condition.*



CRYSTALLINE CLEANING AND ENVIRONMENTAL SERVICES