

SEWAGE SUMP PIT TANK CLEANING

COMPLETION REPORT

For



Client : Eastern International LLC.
Contact Person: Mr. Husam Hussain
Project Manager - MEP
Site Details : Specialist Rehabilitation Hospital,
Abu Dhabi, UAE.
Date : 22 November 2018



CRYSTALLINE
ENVIRONMENTAL SERVICES

Crystalline environmental Service

P.O. Box 131463, Abu Dhabi, U.A.E.

Tel: 02 6508930 Fax: 02 6508942

info@crystalline-uae.com

www.crystalline-uae.com



CRYSTALLINE ENVIRONMENTAL SERVICES

1253

MANHOLE, GULLY TRAP, DRAINAGE - AFTER SERVICE REPORT

CUSTOMER: <i>Wates Eastern int/40</i>	CONTACT PERSON: <i>Husam</i>
SITE DETAILS: <i>SAH</i>	CONTACT NUMBER: <i>0508304232</i>
NAME OF MANHOLE: <i>sewage</i>	LOCALISATION: <i>Basement</i>
TYPE OF BUILDING: <input checked="" type="checkbox"/> COMMERCIAL <input type="checkbox"/> EDUCATIONAL <input type="checkbox"/> RESIDENCIAL <input type="checkbox"/> INDUSTRIAL	

PART OF DRAINAGE

MANHOLE UNDERGROUND DRAINAGE PIPE GULLY TRAP GREASE TRAP

DRAINAGE PIPE APPARENT DRAINAGE PIPE EMBEDDED DRAINAGE PIPE

CONDITION OF MANHOLE, GULLY TRAP, DRAINAGE BEFORE CLEANING

LITTLE DIRTY DIRTY VERY DIRTY RUST SEDIMENTS MUD
 BIOFILMS SLIME GREASE ROOT SAND MOULDS
 OBSTRUCT BLOCK FLUENT FLOW LOW FLOW ANOTHER: *Rock*

MANHOLE BLOCKED	GULLY TRAP BLOCKED	DRAINAGE BLOCKED	ALL BLOCKED
<input type="checkbox"/> YES <input type="checkbox"/> NO			

COMMENTS:

MANHOLE AND GULLY TRAP COVER: COVERED DAMAGED BLOCKED ADAPTED

CONDITION OF MANHOLE, GULLY TRAP, DRAINAGE AFTER CLEANING

LITTLE CLEAN CLEAN VERY CLEAN FLUENT FLOW LOW FLOW UNBLOCK

	MANHOLE	GULLY TRAP	STORM WATER	DRAINAGE	TOTAL
NUMBER OF MANHOLE CLEANED	<i>2</i>	<i>2</i>	<i>2</i>	<i>2</i>	<i>6</i>
NUMBER OF MANHOLE BLOCKED	<i>0</i>	<i>0</i>	<i>0</i>	<i>0</i>	<i>0</i>

ACCESS

LADDER IN NO LADDER

MANHOLE CLEANED	GULLY TRAP CLEANED	DRAINAGE CLEANED	ALL DISINFECTED
<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO

SERVICES OF DATES

LAST CLEANING DATE	LAST CLEANING DATE	LAST CLEANING DATE
	<i>16/11/2018</i>	<i>16/11/2018</i>

CHEMICALS AND EQUIPMENTS USED

PRESSURE MACHINE JETTING MACHINE MULTIGAS DETECTEUR INLET WATER HOSE
 EXTENTION CORDS VACCUM CLEANER VENTILATION FAN CLEANING MAT
 LED LIGHTS PLASTICS ROLL PLASTICS BAGS SUITABLE PPE
 TRIPOD AIR REPAIR 7D-A DEGREASER CHEMICAL LADDER

COMMENTS AND RECOMMENDATION: *sewage and manhole well cleaned and disinfected*

Crystalline representative: *fannick*

Signature: *[Signature]*

Customer/Customer representative:

Signature:



CRYSTALLINE
ENVIRONMENTAL SERVICES

Date of Cleaning: 16-11-2018

PHOTOGRAPHS
SEWAGE CLEANING –EASTERN INTERNATIONAL

BEFORE CLEANING



AFTER CLEANING




CLEANER WATER GREENER TOMORROW

Date of Cleaning: 16-11-2018

PHOTOGRAPHS
SEWAGE CLEANING –EASTERN INTERNATIONAL

BEFORE CLEANING



AFTER CLEANING





MANHOLE, GULLY TRAP, DRAINAGE - AFTER SERVICE REPORT

CUSTOMER: <i>Wates and Eastern int (LLC)</i>	CONTACT PERSON: <i>Hugam</i>
SITE DETAILS: <i>SRH</i>	CONTACT NUMBER: <i>0808304232</i>
NAME OF MANHOLE: <i>Sewage</i>	LOCALISATION:
TYPE OF BUILDING: <input checked="" type="checkbox"/> COMMERCIAL <input type="checkbox"/> EDUCATIONAL <input type="checkbox"/> RESIDENCIAL <input type="checkbox"/> INDUSTRIAL	

PART OF DRAINAGE

MANHOLE UNDERGROUND DRAINAGE PIPE GULLY TRAP GREASE TRAP

DRAINAGE PIPE APPARENT DRAINAGE PIPE EMBEDDED DRAINAGE PIPE

CONDITION OF MANHOLE, GULLY TRAP, DRAINAGE BEFORE CLEANING

LITTLE DIRTY DIRTY VERY DIRTY RUST SEDIMENTS MUD

BIOFILMS SLIME GREASE ROOT SAND MOULDS

OBSTRUCT BLOCK FLUENT FLOW LOW FLOW ANOTHER: *rocks*

MANHOLE BLOCKED	GULLY TRAP BLOCKED	DRAINAGE BLOCKED	ALL BLOCKED
<input type="checkbox"/> YES <input type="checkbox"/> NO			

COMMENTS:

MANHOLE AND GULLY TRAP COVER: COVERED DAMAGED BLOCKED ADAPTED

CONDITION OF MANHOLE, GULLY TRAP, DRAINAGE AFTER CLEANING

LITTLE CLEAN CLEAN VERY CLEAN FLUENT FLOW LOW FLOW UNBLOCK

	MANHOLE	GULLY TRAP	STORM WATER	DRAINAGE	TOTAL
NUMBER OF MANHOLE CLEANED	<i>20</i>	<i>1</i>	<i>1</i>	<i>1</i>	<i>23</i>
NUMBER OF MANHOLE BLOCKED					

ACCESS

LADDER IN NO LADDER

MANHOLE CLEANED	GULLY TRAP CLEANED	DRAINAGE CLEANED	ALL DISINFECTED
<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input type="checkbox"/> YES <input type="checkbox"/> NO

SERVICES OF DATES

LAST CLEANING DATE	LAST CLEANING DATE	LAST CLEANING DATE
	<i>13/11/2018</i>	<i>18/11/2018</i>

CHEMICALS AND EQUIPMENTS USED

PRESSURE MACHINE JETTING MACHINE MULTIGAS DETECTEUR INLET WATER HOSE

EXTENTION CORDS VACCUM CLEANER VENTILATION FAN CLEANING MAT

LED LIGHTS PLASTICS ROLL PLASTICS BAGS SUITABLE PPE

TRIPOD AIR REPAIR 7D-A DEGREASER CHEMICAL LADDER


COMMENTS AND RECOMMENDATION: *sewage & manhole well cleaned and disinfected*

Crystalline representative: <i>Yannick</i>	Signature: <i>[Signature]</i>
Customer/Customer representative:	Signature:

Date of Cleaning: 18-11-2018

PHOTOGRAPHS
SEWAGE CLEANING—EASTERN INTERNATIONAL

BEFORE CLEANING



AFTER CLEANING




Date of Cleaning: 18-11-2018

PHOTOGRAPHS
SEWAGE CLEANING—EASTERN INTERNATIONAL

BEFORE CLEANING



AFTER CLEANING



CLEANER WATER GREENER TOMORROW

CRYSTALLINE CLEANING & ENVIRONMENTAL SERVICES

CLEANING & DISINFECTION CERTIFICATE

SEWAGE SUMP PIT TANKS

CLIENT NAME : EASTERN INTERNATIONAL LLC.
CLIENT ADDRESS : P.O. BOX: 46790, ABU DHABI, UAE.
CONTACT PERSON : MR. HUSAM HUSSAIN.
SITE DETAILS : SPECIALIST REHABILITATION HOSPITAL,
ABU DHABI, UAE.
DETAILS : SEWAGE SUMP PIT TANK CLEANING
DATE OF CLEANING : 16th & 18 NOVEMBER 2018
FREQUENCY OF CLEANING : EVERY SIX MONTHS
DATE OF NEXT CLEANING : 16 MAY 2019

The procedures employed in this cleaning and disinfection comply with HS (G) 70 health and safety guidelines for prevention of legionella as well as BS6700 and CARELA BIO PLUS method statement.

The entire Sewage Sump Pit tank should be cleaned and disinfected minimum every six (6) months depending upon the condition.



CRYSTALLINE CLEANING AND ENVIRONMENTAL SERVICES