

KITCHEN DUCT CLEANING & DISINFECTION

COMPLETION REPORT

For



Client : HAVANA GROUP.
Contact Person: Mr. Rajesh
Maintenance
Site Details : Havana Cafe, Shahama, Abu Dhabi.
Date : 21 November 2018

**Crystalline environmental
services**

P.O. Box 131463, Abu Dhabi, U.A.E.

Tel: 02 6508930 Fax: 02 6508942

info@crystalline-uae.com

www.crystalline-uae.com



CRYSTALLINE
ENVIRONMENTAL SERVICES



KITCHEN EXHAUST SYSTEM – AFTER SERVICE REPORT

CUSTOMER: <i>Havana Cafe Restaurant</i>	CONTACT PERSON: <i>Naceem</i>
SITE DETAILS: <i>Havana shahama</i>	CONTACT NO: <i>052-1458796</i>
NAME OF KITCHEN/DETAILS: <i>main kitchen hood</i>	LOCATION OF KITCHEN: <i>ground floor shahama</i>
TYPE OF BUILDING: <input checked="" type="checkbox"/> COMMERCIAL <input type="checkbox"/> RESIDENTIAL <input type="checkbox"/> EDUCATIONAL <input type="checkbox"/> INDUSTRIAL	

COOKING VOLUME	<input type="checkbox"/> HIGH	<input checked="" type="checkbox"/> MEDIUM	<input type="checkbox"/> LOW
TYPE OF FILTERS	<input checked="" type="checkbox"/> MESH	<input type="checkbox"/> BAFFLE	<input type="checkbox"/> N/A
FILTERS IN PLACE	<input type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> N/A
EXHAUST FAN	<input checked="" type="checkbox"/> UPBLAST	<input type="checkbox"/> INLINE	<input type="checkbox"/> UTILITY
CONDITION OF DUCT	<input type="checkbox"/> DAMAGED	<input checked="" type="checkbox"/> NOT DAMAGED	<input type="checkbox"/> N/A
FILTER CLEANING FREQUENCY	<input type="checkbox"/> DAILY	<input type="checkbox"/> WEEKLY	<input type="checkbox"/> MONTHLY
	<input type="checkbox"/> BIMONTHLY	<input type="checkbox"/> QUARTERLY	HALF YEARLY <input checked="" type="checkbox"/>
DOORS/PLATES PRESENT	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	HOW MANY DOORS <i>01</i>
			HOW MANY PANELS <i>02</i>
DOORS/PANELS INSTALLED	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	HOW MANY DOORS <input checked="" type="checkbox"/>
			HOW MANY PANELS <input checked="" type="checkbox"/>
CONDITION OF ROOF/WALL	<input type="checkbox"/> CLEAN	<input checked="" type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY

CONDITION OF KITCHEN DUCT BEFORE CLEANING			CONDITION OF KITCHEN DUCT AFTER CLEANING		
<input type="checkbox"/> CLEAN	<input checked="" type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY

LAST CLEANING DATE	CURRENT CLEANING DATE	NEXT CLEANING DATE
	<i>19-11-2018</i>	<i>19-05-2019</i>

CHEMICALS & EQUIPMENTS USED

- High/Low Pressure Jet
 Extension Cords
 LED Lights
 Ladder
 Ventilating Fan
 Degreaser Chemical
 Plastic Roll
 Vacuum Cleaner
 Cleaning Materials.

TEAM <i>Crystal line</i>	TEAM LEADER <i>Bishal shankar</i>
---------------------------------	--

COMMENTS & RECOMMENDATIONS: *kitchen duct disinfected*

The above kitchen exhaust duct was successfully degreased and cleaned as per local municipality guidelines.

Crystalline Representative: <i>Bishal Rai</i>	Signature: <i>[Signature]</i>
--	--------------------------------------

kitchen hood and Exhaust fan cleaned & disinfected



CRYSTALLINE
ENVIRONMENTAL SERVICES

Date of Cleaning: 19-11-2018

PHOTOGRAPHS
KITCHEN EXHAUST FAN & DUCT CLEANING

BEFORE



AFTER



CLEANER WATER GREENER TOMORROW


Date of Cleaning: 19-11-2018

PHOTOGRAPHS
KITCHEN EXHAUST FAN & DUCT CLEANING

BEFORE





AFTER



Date of Cleaning: 19-11-2018

PHOTOGRAPHS
KITCHEN EXHAUST FAN & DUCT CLEANING

BEFORE



AFTER





METHODOLOGY:

- ✓ Preliminary site visit. To choose the effective procedure.
- ✓ Live Camera Inspection for the internal duct.
- ✓ Safety clothing/equipment required: overalls, safety boots, eye protection, gloves and correct respirators.
- ✓ Conduct safety briefing with client's representative to ensure all possible hazards are identified and reported immediately if assistance is required for the control of hazards.
- ✓ Ensure spill control Kit and fire extinguisher is available.
- ✓ Digital photo taken for the proof of cleaning process.
- ✓ Access holes in ducts shall be cut if required.
- ✓ Fans shall be isolated and warning labels should be placed on isolation switches.
- ✓ Areas of duct to be cleaned to bare metal.
- ✓ Toxic or flammable products shall not be used.
- ✓ Waste rags and lint will be disposed of in the client's waste disposal facilities.
- ✓ Record any areas unable to be cleaned giving exact reasons.

If you have any queries concerning our services, please contact: +971 2 6508930

Thank you for your business!

Crystalline Cleaning & Environmental Services

CRYSTALLINE CLEANING & ENVIRONMENTAL SERVICES

CLEANING & DISINFECTION CERTIFICATE

CLIENT NAME : HAVANA GROUP ABU DHABI

CLIENT ADDRESS : P.O BOX 33066, ABU DHABI, UAE.

CONTACT PERSON : MR. RAJESH.

SITE DETAILS : HAVANA CAFE, SHAHAMA, ABU DHABI.

DETAILS : KITCHEN DUCT CLEANING

DATE OF CLEANING : 19 NOVEMBER 2018

FREQUENCY OF CLEANING : EVERY SIX (6) MONTHS

DATE OF NEXT CLEANING : 19 MAY 2019

The procedures employed in this cleaning and disinfection comply with Abu Dhabi Municipality guidelines

The entire Laundry Duct should be cleaned and disinfected minimum every six (6) months depending upon the condition.



CRYSTALLINE CLEANING AND ENVIRONMENTAL SERVICES