

# KITCHEN DUCT CLEANING & DISINFECTION

## COMPLETION REPORT

For



Client : Emirates Park Zoo.  
Contact Person: Mr. Malik  
Purchasing Department  
Site Details : Aldar Garden Restaurant, Old Shahama, Al  
Bahiya Street,  
Abu Dhabi, UAE.  
Date : 29 November 2018



**CRYSTALLINE**  
ENVIRONMENTAL SERVICES

**Crystalline environmental  
services**

P.O. Box 131463, Abu Dhabi, U.A.E.

Tel: 02 6508930 Fax: 02 6508942

[info@crystalline-uae.com](mailto:info@crystalline-uae.com)

[www.crystalline-uae.com](http://www.crystalline-uae.com)



**KITCHEN EXHAUST SYSTEM – AFTER SERVICE REPORT**

CUSTOMER: <i>All dar Restaurant</i>	CONTACT PERSON:
SITE DETAILS: <i>Emirates park zoo shahama</i>	CONTACT NO: <i>055-5220676</i>
NAME OF KITCHEN/DETAILS: <i>main kitchen hood</i>	LOCATION OF KITCHEN: <i>ground floor shahama</i>
TYPE OF BUILDING: <input checked="" type="checkbox"/> COMMERCIAL <input type="checkbox"/> RESIDENTIAL <input type="checkbox"/> EDUCATIONAL <input type="checkbox"/> INDUSTRIAL	

*Exhaust fan cleaned and disinfected*

COOKING VOLUME	<input type="checkbox"/> HIGH	<input checked="" type="checkbox"/> MEDIUM	<input type="checkbox"/> LOW
TYPE OF FILTERS	<input checked="" type="checkbox"/> MESH	<input type="checkbox"/> BAFFLE	<input type="checkbox"/> N/A
FILTERS IN PLACE	<input type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> N/A
EXHAUST FAN	<input checked="" type="checkbox"/> UPBLAST	<input type="checkbox"/> INLINE	<input type="checkbox"/> UTILITY
CONDITION OF DUCT	<input type="checkbox"/> DAMAGED	<input checked="" type="checkbox"/> NOT DAMAGED	<input type="checkbox"/> N/A
FILTER CLEANING FREQUENCY	<input type="checkbox"/> DAILY	<input type="checkbox"/> WEEKLY	<input type="checkbox"/> MONTHLY
	<input type="checkbox"/> BIMONTHLY	<input type="checkbox"/> QUARTERLY	HALF YEARLY <input checked="" type="checkbox"/>
DOORS/PLATES PRESENT	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	HOW MANY DOORS <i>03</i>
			HOW MANY PANELS <i>03</i>
DOORS/PANELS INSTALLED	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	HOW MANY DOORS <input checked="" type="checkbox"/>
			HOW MANY PANELS <input checked="" type="checkbox"/>
CONDITION OF ROOF/WALL	<input type="checkbox"/> CLEAN	<input checked="" type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY

CONDITION OF KITCHEN DUCT BEFORE CLEANING			CONDITION OF KITCHEN DUCT AFTER CLEANING		
<input type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input checked="" type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY

LAST CLEANING DATE	CURRENT CLEANING DATE	NEXT CLEANING DATE
	<i>27-11-2018</i>	<i>27-05-2019</i>

**CHEMICALS & EQUIPMENTS USED**

- High/Low Pressure Jet
- Extension Cords
- LED Lights
- Ladder
- Ventilating Fan
- Degreaser Chemical
- Plastic Roll
- Vacuum Cleaner
- Cleaning Materials.

TEAM	<i>Crystalline</i> <input checked="" type="checkbox"/>	TEAM LEADER	<i>Bishal</i>	<i>Magn Kumar</i>
------	--	-------------	---------------	-------------------

**COMMENTS & RECOMMENDATIONS:**  
*Kitchen hood and duct cleaned & disinfected*

Crystalline Representative: <i>Bishal Rai</i>	Signature: <i>[Signature]</i>
---	-------------------------------


Date of Cleaning: 27-11-2018

**PHOTOGRAPHS**  
**KITCHEN EXHAUST FAN & DUCT CLEANING- Al Dar Restaurant**

**BEFORE**



**AFTER**





**CRYSTALLINE**  
ENVIRONMENTAL SERVICES

Date of Cleaning: 27-11-2018

**PHOTOGRAPHS**  
**KITCHEN EXHAUST FAN & DUCT CLEANING**

**BEFORE**



**AFTER**



**CLEANER WATER GREENER TOMORROW**



**KITCHEN EXHAUST SYSTEM – AFTER SERVICE REPORT**

CUSTOMER: <i>Al dar Restaurant</i>	CONTACT PERSON:
SITE DETAILS: <i>Emirates park zoo shahama</i>	CONTACT NO: <i>055-5220676</i>
NAME OF KITCHEN/DETAILS: <i>Tandoori kitchen hood</i>	LOCATION OF KITCHEN: <i>ground floor shahama</i>
TYPE OF BUILDING: <input checked="" type="checkbox"/> COMMERCIAL <input type="checkbox"/> RESIDENTIAL <input type="checkbox"/> EDUCATIONAL <input type="checkbox"/> INDUSTRIAL	

*Exhaust fan cleaned and disinfected*

COOKING VOLUME	<input type="checkbox"/> HIGH	<input checked="" type="checkbox"/> MEDIUM	<input type="checkbox"/> LOW
TYPE OF FILTERS	<input checked="" type="checkbox"/> MESH	<input type="checkbox"/> BAFFLE	<input type="checkbox"/> N/A
FILTERS IN PLACE	<input type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> N/A
EXHAUST FAN	<input checked="" type="checkbox"/> UPBLAST	<input type="checkbox"/> INLINE	<input type="checkbox"/> UTILITY
CONDITION OF DUCT	<input type="checkbox"/> DAMAGED	<input checked="" type="checkbox"/> NOT DAMAGED	<input type="checkbox"/> N/A
FILTER CLEANING FREQUENCY	<input type="checkbox"/> DAILY	<input type="checkbox"/> WEEKLY	<input type="checkbox"/> MONTHLY
	<input type="checkbox"/> BIMONTHLY	<input type="checkbox"/> QUARTERLY	HALF YEARLY <input checked="" type="checkbox"/>
DOORS/PLATES PRESENT	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	HOW MANY DOORS <i>02</i>
			HOW MANY PANELS <i>02</i>
DOORS/PANELS INSTALLED	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	HOW MANY DOORS <input checked="" type="checkbox"/>
			HOW MANY PANELS <input checked="" type="checkbox"/>
CONDITION OF ROOF/WALL	<input type="checkbox"/> CLEAN	<input checked="" type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY

**CONDITION OF KITCHEN DUCT BEFORE CLEANING**

**CONDITION OF KITCHEN DUCT AFTER CLEANING**

<input type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input checked="" type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
--------------------------------	--------------------------------	--	---	--------------------------------	-------------------------------------

**LAST CLEANING DATE**

**CURRENT CLEANING DATE**

**NEXT CLEANING DATE**

*27-11-2018*

*27-05-2019*

**CHEMICALS & EQUIPMENTS USED**

- High/Low Pressure Jet     Extension Cords     LED Lights     Ladder     Ventilating Fan     Degreaser Chemical     Plastic Roll  
 Vacuum Cleaner     Cleaning Materials.

TEAM	<i>Crystalline</i> ✓	TEAM LEADER	<i>Bishal</i> <i>Man Kumar</i>
------	----------------------	-------------	--------------------------------

**COMMENTS & RECOMMENDATIONS:**


*Kitchen hood and duct cleaned & disinfected*

Crystalline Representative: <i>Bishal Rai</i>	Signature: <i>[Signature]</i>
---	-------------------------------


Date of Cleaning: 27-11-2018

**PHOTOGRAPHS**  
**KITCHEN EXHAUST FAN & DUCT CLEANING**

**BEFORE**



**AFTER**





**CRYSTALLINE**  
ENVIRONMENTAL SERVICES

Date of Cleaning: 27-11-2018

**PHOTOGRAPHS**  
**KITCHEN EXHAUST FAN & DUCT CLEANING**

**BEFORE**



**AFTER**



**CLEANER WATER GREENER TOMORROW**



**METHODOLOGY:**

- ✓ Preliminary site visit. To choose the effective procedure.
- ✓ Live Camera Inspection for the internal duct.
- ✓ Safety clothing/equipment required: overalls, safety boots, eye protection, gloves and correct respirators.
- ✓ Conduct safety briefing with client's representative to ensure all possible hazards are identified and reported immediately if assistance is required for the control of hazards.
- ✓ Ensure spill control Kit and fire extinguisher is available.
- ✓ Digital photo taken for the proof of cleaning process.
- ✓ Access holes in ducts shall be cut if required.
- ✓ Fans shall be isolated and warning labels should be placed on isolation switches.
- ✓ Areas of duct to be cleaned to bare metal.
- ✓ Toxic or flammable products shall not be used.
- ✓ Waste rags and lint will be disposed of in the client's waste disposal facilities.
- ✓ Record any areas unable to be cleaned giving exact reasons.

If you have any queries concerning our services, please contact: +971 2 6508930

Thank you for your business!

Crystalline Cleaning & Environmental Services

# CRYSTALLINE CLEANING & ENVIRONMENTAL SERVICES

## CLEANING & DISINFECTION CERTIFICATE

**CLIENT NAME** : EMIRATES PARK ZOO.

**CLIENT ADDRESS** : P.O. BOX: 111026, ABU DHABI, UAE.

**CONTACT PERSON** : MR. MALIK.

**SITE DETAILS** : ALDAR GARDEN RESTAURANT, OLD  
SHAHAMA, AL BAHIYA STREET,  
ABU DHABI, UAE.

**DETAILS** : KITCHEN EXHAUST SYSTEM CLEANING

**DATE OF CLEANING** : 27 NOVEMBER 2018

**FREQUENCY OF CLEANING** : EVERY SIX (6) MONTHS

**DATE OF NEXT CLEANING** : 27 MAY 2019

*The procedures employed in this cleaning and degreasing comply with Abu Dhabi Municipality guidelines.*

*The entire Kitchen Duct should be cleaned and Degreased minimum every six (6) months depending upon the condition.*



CRYSTALLINE CLEANING AND ENVIRONMENTAL SERVICES