

WATER TANK CLEANING & DISINFECTION

COMPLETION REPORT

FOR

DHAFIR
Development & Contracting LLC

Client : DHAFIR DEVELOPMENT &
CONTRACTING LLC.
Contact Person: Mr. PRATHAP
Facility Manager
Site Details : Amaya Tower, Reem Island,
Abu Dhabi, UAE.
Date : 26 December 2018



CRYSTALLINE
ENVIRONMENTAL SERVICES

CRYSTALLINE ENVIRONMENTAL
SERVICES

P.O. BOX 131463, Abu Dhabi, U.A.E.
TEL: 02 6508930 FAX: 02 6508942

info@crystalline-uae.com

www.crystalline-uae.com





CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT


15578

CUSTOMER: <u>AMAYA TOWER</u>			CONTACT PERSON: <u>ARIF</u>		
SITE DETAILS: <u>TOWER ONE TOWER TWO REEM ISLAND</u>			CONTACT NO: <u>0506934791</u>		
TANK DETAILS: <u>R.C.G W.TANK UNDERGROUND</u>			LOCATION DETAILS: <u>BASEMENT</u>		
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL		<input checked="" type="checkbox"/> RESIDENTIAL		<input type="checkbox"/> OTHERS	
<u>TYPE OF TANK</u>					
<input checked="" type="checkbox"/> CONCRETE	<input type="checkbox"/> GRP PANEL	<input type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED		<input type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS		
<u>SIZE OF TANK</u>			<u>QUANTITY OF WATER</u>		
M3	USG	L*B*H	<input type="checkbox"/> FULL	<input checked="" type="checkbox"/> HALF	<input type="checkbox"/> EMPTY
<u>CONDITION OF WATER TANK BEFORE CLEANING</u>			<u>CONDITION OF WATER TANK AFTER CLEANING</u>		
<input type="checkbox"/> CLEAN	<input checked="" type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input checked="" type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
<u>ACCESS</u>		<u>MANHOLE</u>		<input type="checkbox"/> COVERED	<input type="checkbox"/> DAMAGED
<input type="checkbox"/> NA					<input type="checkbox"/> NA
<u>LADDER IN</u>		<u>LADDER OUT</u>		<u>LEAKS</u>	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO
<u>TANK CLEANED</u>		<u>TANK DISINFECTED</u>		<u>PIPES DISINFECTED</u>	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> YES	<input type="checkbox"/> NO
<u>LAST CLEANING DATE</u>		<u>CURRENT CLEANING DATE</u>		<u>NEXT CLEANING DATE</u>	
		<u>12/12/2018</u>		<u>12/06/2019</u>	
<u>CHEMICALS & EQUIPMENTS USED</u>					
1. <u>SODIUM HYPO CHLORIDE</u> Quantity <u>500ML</u>					
2. _____ Quantity _____					
<input checked="" type="checkbox"/> Submersibel Pump <input checked="" type="checkbox"/> High/Low Pressure Jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED lights <input checked="" type="checkbox"/> Foot Bath <input type="checkbox"/> Ladder <input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Meter <input checked="" type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials					
<u>COMMENTS & RECOMMENDATIONS:</u>					
<u>MENTIONED WATER TANK VACUUMED AND DISINFECTED</u>					
Crystalline Representative: <u>HARIS</u>			Signature: <u>HARIS</u>		


Date of Cleaning: 12-12-2018

PHOTOGRAPHS
UNDER GROUND RCC RAW WATER TANK - 01

CLEANING



CLEANING



CLEANER WATER GREENER TOMORROW



CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT

15641


CUSTOMER: <u>AMAYA TOWER</u>			CONTACT PERSON: <u>Arif</u>		
SITE DETAILS: <u>TOWER-01 REEM ISLAND</u>			CONTACT NO: <u>0562184516</u>		
TANK DETAILS: <u>R.C.C.W. TANK. 01</u>			LOCATION DETAILS: <u>ROOF TOP</u>		
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL		<input checked="" type="checkbox"/> RESIDENTIAL		<input type="checkbox"/> OTHERS	
TYPE OF TANK					
<input checked="" type="checkbox"/> CONCRETE	<input type="checkbox"/> GRP PANEL	<input type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED		<input type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS		
SIZE OF TANK			QUANTITY OF WATER		
M3	USG	L*B*H	<input type="checkbox"/> FULL	<input checked="" type="checkbox"/> HALF	<input type="checkbox"/> EMPTY
CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK AFTER CLEANING		
<input type="checkbox"/> CLEAN	<input checked="" type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input checked="" type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
ACCESS		MANHOLE		<input type="checkbox"/> COVERED	<input type="checkbox"/> DAMAGED
<input type="checkbox"/> NA					<input type="checkbox"/> NA
LADDER IN		LADDER OUT		LEAKS	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO
TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> YES	<input type="checkbox"/> NO <input checked="" type="checkbox"/> NA
LAST CLEANING DATE		CURRENT CLEANING DATE		NEXT CLEANING DATE	
		<u>16/12/2018</u>		<u>16/06/2019</u>	
CHEMICALS & EQUIPMENTS USED					
1. <u>CARELO BIO 9 plus</u> Quantity <u>500ML</u>					
2. _____ Quantity _____					
<input checked="" type="checkbox"/> Submersibel Pump <input checked="" type="checkbox"/> High/Low Pressure Jet <input checked="" type="checkbox"/> Extension Cords <input type="checkbox"/> LED lights <input checked="" type="checkbox"/> Foot Bath <input checked="" type="checkbox"/> Ladder <input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Meter <input checked="" type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials					
COMMENTS & RECOMMENDATIONS:					
<u>MENTIONED W. TANK (CLEANED AND DISINFECTED)</u>					
Crystalline Representative: <u>HARIS</u>			Signature: <u>[Signature]</u>		

ARIF 16/12/18

Date of Cleaning: 16-12-2018

PHOTOGRAPHS
ROOF TOP RCC WATER TANK - 01

BEFORE



AFTER



CLEANER WATER GREENER TOMORROW



CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT

15640

CUSTOMER: <u>AMAYA TOWER</u>			CONTACT PERSON: <u>ARIF</u>		
SITE DETAILS: <u>TOWER. 02. REEM ISLAND</u>			CONTACT NO: <u>0562184516</u>		
TANK DETAILS: <u>R.C.C W. TANK. 01</u>			LOCATION DETAILS: <u>ROOF TOP</u>		
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL		<input checked="" type="checkbox"/> RESIDENTIAL		<input type="checkbox"/> OTHERS	
TYPE OF TANK					
<input checked="" type="checkbox"/> CONCRETE	<input type="checkbox"/> GRP PANEL	<input type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED		<input type="checkbox"/> POLYURETHANE		<input type="checkbox"/> OTHERS	
SIZE OF TANK			QUANTITY OF WATER		
M3	USG	L*B*H	<input type="checkbox"/> FULL	<input checked="" type="checkbox"/> HALF	<input type="checkbox"/> EMPTY
CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK AFTER CLEANING		
<input type="checkbox"/> CLEAN	<input checked="" type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input checked="" type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
ACCESS		MANHOLE		<input type="checkbox"/> COVERED	<input type="checkbox"/> DAMAGED
<input type="checkbox"/> NA	<input type="checkbox"/> NA	<input type="checkbox"/> NA	<input type="checkbox"/> NA	<input type="checkbox"/> NA	<input type="checkbox"/> NA
LADDER IN		LADDER OUT		LEAKS	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO
DRAIN LINE		VALVES		FLOAT VALVE	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO
TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> YES	<input type="checkbox"/> NO
LAST CLEANING DATE		CURRENT CLEANING DATE		NEXT CLEANING DATE	
		<u>16/12/2018</u>		<u>16/06/2019</u>	
CHEMICALS & EQUIPMENTS USED					
1. <u>CARECO BIO @ plus</u> Quantity <u>500ml</u>					
2. _____ Quantity _____					
<input checked="" type="checkbox"/> Submersibel Pump <input checked="" type="checkbox"/> High/Low Pressure Jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED lights <input checked="" type="checkbox"/> Foot Bath <input checked="" type="checkbox"/> Ladder					
<input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Meter <input checked="" type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials					
COMMENTS & RECOMMENDATIONS:					
<u>MENTIONED W. TANK CLEANED AND DISINFECTED</u>					
Crystalline Representative: <u>HARIS</u>			Signature: <u>ARIF</u>		


Date of Cleaning: 16-12-2018

PHOTOGRAPHS
ROOF TOP RCC WATER TANK - 02

BEFORE



AFTER





CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK – AFTER SERVICE REPORT

08980

CUSTOMER: AMAYA TOWER			CONTACT PERSON: MR-ARIF		
SITE DETAILS: TOWER-02 REEM ISLAND			CONTACT NO: 0562184516		
TANK DETAILS: R.C.C. W. TANK-2			LOCATION DETAILS: ROOF TOP		
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL		<input checked="" type="checkbox"/> RESIDENTIAL		<input type="checkbox"/> OTHERS	
TYPE OF TANK					
<input checked="" type="checkbox"/> CONCRETE	<input type="checkbox"/> GRP PANEL	<input type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED		<input type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS		
SIZE OF TANK			QUANTITY OF WATER		
M3	USG	L*B*H	<input type="checkbox"/> FULL	<input checked="" type="checkbox"/> HALF	<input type="checkbox"/> EMPTY
CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK AFTER CLEANING		
<input type="checkbox"/> CLEAN	<input checked="" type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input checked="" type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
ACCESS		MANHOLE		<input type="checkbox"/> COVERED	<input type="checkbox"/> DAMAGED
<input type="checkbox"/> NA	<input type="checkbox"/> NA	<input type="checkbox"/> NA	<input type="checkbox"/> NA	<input type="checkbox"/> NA	<input type="checkbox"/> NA
LADDER IN		LADDER OUT		LEAKS	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO
TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> YES	<input type="checkbox"/> NO
LAST CLEANING DATE		CURRENT CLEANING DATE		NEXT CLEANING DATE	
		20/12/2018		20/06/2019	
CHEMICALS & EQUIPMENTS USED					
1. CARELO Bio & PLUS Quantity 500 ML					
2. _____ Quantity _____					
<input checked="" type="checkbox"/> Submersible Pump <input checked="" type="checkbox"/> High/Low Pressure Jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED lights <input checked="" type="checkbox"/> Foot Bath <input checked="" type="checkbox"/> Ladder					
<input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Meter <input checked="" type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials					
COMMENTS & RECOMMENDATIONS:					
MENTIONED WATER TANK IS CLEANED & DISINFECTED					
Crystalline Representative: SANKAR			Signature: 		

ARIF 20, 12, 18.

Date of Cleaning: 20-12-2018

PHOTOGRAPHS
ROOF TOP RCC WATER TANK - 03

BEFORE



AFTER



CLEANER WATER GREENER TOMORROW



CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT

20745



CUSTOMER: <i>Amaja Tower</i>			CONTACT PERSON: <i>Asif</i>		
SITE DETAILS: <i>Amaja Tower 1 Abu Dhabi</i>			CONTACT NO: <i>0562184516</i>		
TANK DETAILS: <i>R.C.C water Tank-2</i>			LOCATION DETAILS: <i>Roof Top Abu Dhabi</i>		
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL		<input checked="" type="checkbox"/> RESIDENTIAL		<input type="checkbox"/> OTHERS	
TYPE OF TANK					
<input checked="" type="checkbox"/> CONCRETE	<input type="checkbox"/> GRP PANEL	<input type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED	<input type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS			
SIZE OF TANK			QUANTITY OF WATER		
M3	USG	L*B*H	<input type="checkbox"/> FULL	<input checked="" type="checkbox"/> HALF	<input type="checkbox"/> EMPTY
CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK AFTER CLEANING		
<input type="checkbox"/> CLEAN	<input checked="" type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
ACCESS		MANHOLE		<input type="checkbox"/> COVERED	<input type="checkbox"/> DAMAGED
<input type="checkbox"/> LADDER IN	<input type="checkbox"/> LADDER OUT	<input type="checkbox"/> LEAKS	<input type="checkbox"/> DRAIN LINE	<input type="checkbox"/> VALVES	<input type="checkbox"/> FLOAT VALVE
<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO
TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> YES	<input type="checkbox"/> NO <input checked="" type="checkbox"/> NA
LAST CLEANING DATE		CURRENT CLEANING DATE		NEXT CLEANING DATE	
		<i>20-12-2018</i>		<i>20-06-2019</i>	
CHEMICALS & EQUIPMENTS USED					
1. <i>Carela bio and plus</i> Quantity <i>500-ml</i>					
2. _____ Quantity _____					
<input checked="" type="checkbox"/> Submersibel Pump <input checked="" type="checkbox"/> High /Low Pressure jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED Lights <input checked="" type="checkbox"/> Foot Bath <input checked="" type="checkbox"/> Ladder					
<input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Mater <input checked="" type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials					
COMMENTS & RECOMMENDATIONS:					
<i>water Tank cleaned and disinfected</i>					
Crystalline Representative: <i>Bishal Rai</i>			Signature: <i>[Signature]</i>		

Asif *[Signature]* 20/12/18



Date of Cleaning: 20-12-2018

PHOTOGRAPHS
ROOF TOP RCC WATER TANK - 04

BEFORE



AFTER



CLEANER WATER GREENER TOMORROW

CRYSTALLINE CLEANING & ENVIRONMENTAL SERVICES

CLEANING & DISINFECTION CERTIFICATE

POTABLE WATER TANKS

CLIENT NAME : DHAFIR DEVELOPMENT & CONTRACTING.
CLIENT ADDRESS : P.O. BOX: 3706, ABU DHABI, UAE.
CONTACT PERSON : MR. PRATHAP.
SITE DETAILS : AMAYA TOWER, REEM ISLAND, ABU DHABI.
DETAILS : WATER TANK CLEANING
DATE OF CLEANING : DECEMBER 2018
FREQUENCY OF CLEANING : EVERY SIX MONTHS
DATE OF NEXT CLEANING : JUNE 2019

The procedures employed in this cleaning and disinfection comply with HS (G) 70 health and safety guidelines for prevention of legionella as well as BS6700 and CARELA BIO PLUS method statement.

The entire water storage tank should be cleaned and disinfected minimum every six (6) months depending upon the condition.



CRYSTALLINE CLEANING AND ENVIRONMENTAL SERVICES