

WATER TANK CLEANING & DISINFECTION

COMPLETION REPORT

FOR



Al Nasser Properties LLC

Client : Al Nasser Properties LLC.
Contact Person: Mr. Harish Kumar
Maintenance Supervisor
Site Details : Al Nasser Labour Camp - Taj 01,
Abu Dhabi, UAE.
Date : 29 December 2018



CRYSTALLINE
ENVIRONMENTAL SERVICES

CRYSTALLINE ENVIRONMENTAL
SERVICES

P.O. BOX 131463, Abu Dhabi, U.A.E.
TEL: 02 6508930 FAX: 02 6508942

info@crystalline-uae.com

www.crystalline-uae.com





CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK – AFTER SERVICE REPORT

08987

| | | | | | |
|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------|-------------------------------------------------|-----------------------------------------------|------------------------------------------|----------------------------------------|
| CUSTOMER: <u>AL-NASSER</u> | | | CONTACT PERSON: <u>MR-HARISH</u> | | |
| SITE DETAILS: <u>AL-NASSER CAMP BANUYAS</u> | | | CONTACT NO: <u>0566833929</u> | | |
| TANK DETAILS: <u>G.R.P. W. TANK-NO-1</u> | | | LOCATION DETAILS: <u>GROUND FLOOR</u> | | |
| TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL | | <input checked="" type="checkbox"/> RESIDENTIAL | | <input type="checkbox"/> OTHERS | |
| TYPE OF TANK | | | | | |
| <input type="checkbox"/> CONCRETE | <input checked="" type="checkbox"/> GRP PANEL | <input type="checkbox"/> FRP TANK | <input type="checkbox"/> GALVANIZED | <input type="checkbox"/> STEEL PANEL | <input type="checkbox"/> PLASTIC |
| <input type="checkbox"/> CONCRETE COATED | | <input type="checkbox"/> POLYURETHANE | <input type="checkbox"/> OTHERS | | |
| SIZE OF TANK | | | QUANTITY OF WATER | | |
| M3 | USG | L*B*H | <input type="checkbox"/> FULL | <input checked="" type="checkbox"/> HALF | <input type="checkbox"/> EMPTY |
| CONDITION OF WATER TANK BEFORE CLEANING | | | CONDITION OF WATER TANK AFTER CLEANING | | |
| <input type="checkbox"/> CLEAN | <input checked="" type="checkbox"/> DIRTY | <input type="checkbox"/> VERY DIRTY | <input checked="" type="checkbox"/> CLEAN | <input type="checkbox"/> DIRTY | <input type="checkbox"/> VERY DIRTY |
| <input type="checkbox"/> BIOFILMS | <input type="checkbox"/> MOULDS | <input type="checkbox"/> SLIME | <input type="checkbox"/> BIOFILMS | <input type="checkbox"/> MOULDS | <input type="checkbox"/> SLIME |
| <input type="checkbox"/> SEDIMENTS | <input checked="" type="checkbox"/> MUD & SAND | <input type="checkbox"/> RUST | <input type="checkbox"/> SEDIMENTS | <input type="checkbox"/> MUD & SAND | <input type="checkbox"/> RUST |
| ACCESS | | MANHOLE | | <input type="checkbox"/> COVERED | <input type="checkbox"/> DAMAGED |
| | | | | <input type="checkbox"/> NA | |
| LADDER IN | | LADDER OUT | | LEAKS | |
| <input checked="" type="checkbox"/> YES | <input type="checkbox"/> NO | <input checked="" type="checkbox"/> YES | <input type="checkbox"/> NO | <input type="checkbox"/> YES | <input checked="" type="checkbox"/> NO |
| | | | | DRAIN LINE | |
| | | | | <input checked="" type="checkbox"/> YES | <input type="checkbox"/> NO |
| | | | | VALVES | |
| | | | | <input checked="" type="checkbox"/> YES | <input type="checkbox"/> NO |
| | | | | FLOAT VALVE | |
| | | | | <input checked="" type="checkbox"/> YES | <input type="checkbox"/> NO |
| TANK CLEANED | | TANK DISINFECTED | | PIPES DISINFECTED | |
| <input checked="" type="checkbox"/> YES | <input type="checkbox"/> NO | <input checked="" type="checkbox"/> YES | <input type="checkbox"/> NO | <input type="checkbox"/> YES | <input type="checkbox"/> NO |
| | | | | <input checked="" type="checkbox"/> NA | |
| LAST CLEANING DATE | | CURRENT CLEANING DATE | | NEXT CLEANING DATE | |
| | | <u>23/12/2018</u> | | <u>23/06/2019</u> | |
| CHEMICALS & EQUIPMENTS USED | | | | | |
| 1. <u>CARELO BIO & PLUS</u> Quantity <u>500 ML</u> | | | | | |
| 2. _____ Quantity _____ | | | | | |
| <input checked="" type="checkbox"/> Submersible Pump <input checked="" type="checkbox"/> High/Low Pressure Jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED lights <input checked="" type="checkbox"/> Foot Bath <input checked="" type="checkbox"/> Ladder | | | | | |
| <input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Meter <input checked="" type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials | | | | | |
| COMMENTS & RECOMMENDATIONS: | | | | | |
| <u>MENTIONED WATER TANK IS CLEANED & DISINFECTED</u> | | | | | |
| Crystalline Representative: <u>SANKAR</u> | | | Signature: <u>[Signature]</u> | | |

Date of Cleaning: 23-12-2018

PHOTOGRAPHS
GROUND LEVEL GRP WATER TANK - 01

BEFORE



AFTER






CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK – AFTER SERVICE REPORT

08988

| | | | | | |
|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------|-------------------------------------------------|-----------------------------------------------|------------------------------------------|----------------------------------------|
| CUSTOMER: AL-NASSER | | | CONTACT PERSON: MR. HARISH | | |
| SITE DETAILS: AL-NASSER CAMP BANUYAS | | | CONTACT NO: 0566833929 | | |
| TANK DETAILS: G.R.P.W. TANK-NO-2 | | | LOCATION DETAILS: GROUND FLOOR | | |
| TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL | | <input checked="" type="checkbox"/> RESIDENTIAL | | <input type="checkbox"/> OTHERS | |
| TYPE OF TANK | | | | | |
| <input type="checkbox"/> CONCRETE | <input checked="" type="checkbox"/> GRP PANEL | <input type="checkbox"/> FRP TANK | <input type="checkbox"/> GALVANIZED | <input type="checkbox"/> STEEL PANEL | <input type="checkbox"/> PLASTIC |
| <input type="checkbox"/> CONCRETE COATED | | <input type="checkbox"/> POLYURETHANE | <input type="checkbox"/> OTHERS | | |
| SIZE OF TANK | | | QUANTITY OF WATER | | |
| M3 | USG | L*B*H | <input type="checkbox"/> FULL | <input checked="" type="checkbox"/> HALF | <input type="checkbox"/> EMPTY |
| CONDITION OF WATER TANK BEFORE CLEANING | | | CONDITION OF WATER TANK AFTER CLEANING | | |
| <input type="checkbox"/> CLEAN | <input checked="" type="checkbox"/> DIRTY | <input type="checkbox"/> VERY DIRTY | <input checked="" type="checkbox"/> CLEAN | <input type="checkbox"/> DIRTY | <input type="checkbox"/> VERY DIRTY |
| <input type="checkbox"/> BIOFILMS | <input type="checkbox"/> MOULDS | <input type="checkbox"/> SLIME | <input type="checkbox"/> BIOFILMS | <input type="checkbox"/> MOULDS | <input type="checkbox"/> SLIME |
| <input type="checkbox"/> SEDIMENTS | <input checked="" type="checkbox"/> MUD & SAND | <input type="checkbox"/> RUST | <input type="checkbox"/> SEDIMENTS | <input type="checkbox"/> MUD & SAND | <input type="checkbox"/> RUST |
| ACCESS | | MANHOLE | | <input type="checkbox"/> COVERED | <input type="checkbox"/> DAMAGED |
| <input type="checkbox"/> NA | | | | | <input type="checkbox"/> NA |
| LADDER IN | | LADDER OUT | | LEAKS | |
| <input checked="" type="checkbox"/> YES | <input type="checkbox"/> NO | <input checked="" type="checkbox"/> YES | <input type="checkbox"/> NO | <input type="checkbox"/> YES | <input checked="" type="checkbox"/> NO |
| TANK CLEANED | | TANK DISINFECTED | | PIPES DISINFECTED | |
| <input checked="" type="checkbox"/> YES | <input type="checkbox"/> NO | <input checked="" type="checkbox"/> YES | <input type="checkbox"/> NO | <input type="checkbox"/> YES | <input type="checkbox"/> NO |
| LAST CLEANING DATE | | CURRENT CLEANING DATE | | NEXT CLEANING DATE | |
| | | 24/12/2018 | | 24/06/2019 | |
| CHEMICALS & EQUIPMENTS USED | | | | | |
| 1. CARELO BIO 8 PLUS Quantity 500 ML | | | | | |
| 2. _____ Quantity _____ | | | | | |
| <input checked="" type="checkbox"/> Submersible Pump <input checked="" type="checkbox"/> High/Low Pressure Jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED lights <input checked="" type="checkbox"/> Foot Bath <input checked="" type="checkbox"/> Ladder | | | | | |
| <input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Meter <input checked="" type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials | | | | | |
| COMMENTS & RECOMMENDATIONS: | | | | | |
| MENTIONED WATER TANK IS CLEANED & DISINFECTED | | | | | |
| Crystalline Representative: SANKAR | | | Signature: | | |



Date of Cleaning: 24-12-2018

PHOTOGRAPHS
GROUND LEVEL GRP WATER TANK - 02

BEFORE



AFTER





CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK – AFTER SERVICE REPORT

08984

| | | | | | |
|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------|---------------------------------------------------------------------|---------------------------------------------------------------------|---------------------------------------------------------------------|---------------------------------------------------------------------|
| CUSTOMER: AL-NASSER | | | CONTACT PERSON: MR-HARISH | | |
| SITE DETAILS: AL-NASSER-CAMP BANIYAS BANIYAS | | | CONTACT NO: 0566833929 | | |
| TANK DETAILS: G.R.P W. TANK-NO. 3 | | | LOCATION DETAILS: GROUND FLOOR | | |
| TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL | | | <input checked="" type="checkbox"/> RESIDENTIAL | | <input type="checkbox"/> OTHERS |
| TYPE OF TANK | | | | | |
| <input type="checkbox"/> CONCRETE | <input checked="" type="checkbox"/> GRP PANEL | <input type="checkbox"/> FRP TANK | <input type="checkbox"/> GALVANIZED | <input type="checkbox"/> STEEL PANEL | <input type="checkbox"/> PLASTIC |
| <input type="checkbox"/> CONCRETE COATED | | <input type="checkbox"/> POLYURETHANE | <input type="checkbox"/> OTHERS | | |
| SIZE OF TANK | | | QUANTITY OF WATER | | |
| M3 | USG | L*B*H | <input type="checkbox"/> FULL | <input checked="" type="checkbox"/> HALF | <input type="checkbox"/> EMPTY |
| CONDITION OF WATER TANK BEFORE CLEANING | | | CONDITION OF WATER TANK AFTER CLEANING | | |
| <input type="checkbox"/> CLEAN | <input checked="" type="checkbox"/> DIRTY | <input type="checkbox"/> VERY DIRTY | <input checked="" type="checkbox"/> CLEAN | <input type="checkbox"/> DIRTY | <input type="checkbox"/> VERY DIRTY |
| <input type="checkbox"/> BIOFILMS | <input type="checkbox"/> MOULDS | <input type="checkbox"/> SLIME | <input type="checkbox"/> BIOFILMS | <input type="checkbox"/> MOULDS | <input type="checkbox"/> SLIME |
| <input type="checkbox"/> SEDIMENTS | <input checked="" type="checkbox"/> MUD & SAND | <input type="checkbox"/> RUST | <input type="checkbox"/> SEDIMENTS | <input type="checkbox"/> MUD & SAND | <input type="checkbox"/> RUST |
| ACCESS | | MANHOLE | <input type="checkbox"/> COVERED | <input type="checkbox"/> DAMAGED | <input type="checkbox"/> NA |
| LADDER IN | LADDER OUT | LEAKS | DRAIN LINE | VALVES | FLOAT VALVE |
| <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO |
| TANK CLEANED | | TANK DISINFECTED | | PIPES DISINFECTED | |
| <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO | <input type="checkbox"/> YES <input type="checkbox"/> NO | <input type="checkbox"/> YES <input type="checkbox"/> NO | <input type="checkbox"/> YES <input type="checkbox"/> NO | <input checked="" type="checkbox"/> NA |
| LAST CLEANING DATE | | CURRENT CLEANING DATE | | NEXT CLEANING DATE | |
| | | 22/12/2018 | | 22/06/2019 | |
| CHEMICALS & EQUIPMENTS USED | | | | | |
| 1. CARELO BIO & PLUS Quantity 500 ml | | | | | |
| 2. _____ Quantity _____ | | | | | |
| <input checked="" type="checkbox"/> Submersible Pump <input checked="" type="checkbox"/> High/Low Pressure Jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED lights <input checked="" type="checkbox"/> Foot Bath <input checked="" type="checkbox"/> Ladder <input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Meter <input checked="" type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials | | | | | |
| COMMENTS & RECOMMENDATIONS: | | | | | |
| MENTIONED WATER TANK IS CLEANED & DISINFECTED | | | | | |
| Crystalline Representative: SANKAR | | | Signature: | | |

Date of Cleaning: 22-12-2018

PHOTOGRAPHS
GROUND LEVEL GRP WATER TANK - 03

BEFORE



AFTER





CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK – AFTER SERVICE REPORT

08989

| | | | | | |
|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------|-------------------------------------------------|-----------------------------------------------|------------------------------------------|-------------------------------------|
| CUSTOMER: <u>AL-NASSER</u> | | | CONTACT PERSON: <u>MR-HARISH</u> | | |
| SITE DETAILS: <u>AL-NASSER CAMP BANİYAS</u> | | | CONTACT NO: <u>0566833929</u> | | |
| TANK DETAILS: <u>G.R.P. W. TANK-NO-1</u> | | | LOCATION DETAILS: <u>ROOF TOP</u> | | |
| TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL | | <input checked="" type="checkbox"/> RESIDENTIAL | | <input type="checkbox"/> OTHERS | |
| TYPE OF TANK | | | | | |
| <input type="checkbox"/> CONCRETE | <input checked="" type="checkbox"/> GRP PANEL | <input type="checkbox"/> FRP TANK | <input type="checkbox"/> GALVANIZED | <input type="checkbox"/> STEEL PANEL | <input type="checkbox"/> PLASTIC |
| <input type="checkbox"/> CONCRETE COATED | | <input type="checkbox"/> POLYURETHANE | <input type="checkbox"/> OTHERS | | |
| SIZE OF TANK | | | QUANTITY OF WATER | | |
| M3 | USG | L*B*H | <input type="checkbox"/> FULL | <input checked="" type="checkbox"/> HALF | <input type="checkbox"/> EMPTY |
| CONDITION OF WATER TANK BEFORE CLEANING | | | CONDITION OF WATER TANK AFTER CLEANING | | |
| <input type="checkbox"/> CLEAN | <input checked="" type="checkbox"/> DIRTY | <input type="checkbox"/> VERY DIRTY | <input checked="" type="checkbox"/> CLEAN | <input type="checkbox"/> DIRTY | <input type="checkbox"/> VERY DIRTY |
| <input type="checkbox"/> BIOFILMS | <input type="checkbox"/> MOULDS | <input type="checkbox"/> SLIME | <input type="checkbox"/> BIOFILMS | <input type="checkbox"/> MOULDS | <input type="checkbox"/> SLIME |
| <input type="checkbox"/> SEDIMENTS | <input checked="" type="checkbox"/> MUD & SAND | <input type="checkbox"/> RUST | <input type="checkbox"/> SEDIMENTS | <input type="checkbox"/> MUD & SAND | <input type="checkbox"/> RUST |
| ACCESS | | MANHOLE | | <input type="checkbox"/> COVERED | <input type="checkbox"/> DAMAGED |
| | | | | <input type="checkbox"/> NA | |
| LADDER IN | | LADDER OUT | | LEAKS | |
| | | | | | |
| DRAIN LINE | | VALVES | | FLOAT VALVE | |
| <input checked="" type="checkbox"/> YES | <input type="checkbox"/> NO | <input checked="" type="checkbox"/> YES | <input type="checkbox"/> NO | <input checked="" type="checkbox"/> YES | <input type="checkbox"/> NO |
| TANK CLEANED | | TANK DISINFECTED | | PIPES DISINFECTED | |
| <input checked="" type="checkbox"/> YES | <input type="checkbox"/> NO | <input checked="" type="checkbox"/> YES | <input type="checkbox"/> NO | <input type="checkbox"/> YES | <input type="checkbox"/> NO |
| | | | | <input checked="" type="checkbox"/> NA | |
| LAST CLEANING DATE | | CURRENT CLEANING DATE | | NEXT CLEANING DATE | |
| | | <u>25/12/2018</u> | | <u>25/06/2019</u> | |
| CHEMICALS & EQUIPMENTS USED | | | | | |
| 1. <u>CARELO BIO & PLUS</u> Quantity <u>500 ml</u> | | | | | |
| 2. _____ Quantity _____ | | | | | |
| <input checked="" type="checkbox"/> Submersible Pump <input checked="" type="checkbox"/> High/Low Pressure Jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED lights <input checked="" type="checkbox"/> Foot Bath <input checked="" type="checkbox"/> Ladder <input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Meter <input checked="" type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials | | | | | |
| COMMENTS & RECOMMENDATIONS: | | | | | |
| <u>MENTIONED WATER TANK IS CLEANED & DISINFECTED</u> | | | | | |
| Crystalline Representative: <u>SANKAR</u> | | | Signature: <u>[Signature]</u> | | |





CRYSTALLINE
ENVIRONMENTAL SERVICES

Date of Cleaning: 25-12-2018

PHOTOGRAPHS
ROOF TOP GRP WATER TANK - 01

BEFORE



AFTER



CLEANER WATER GREENER TOMORROW



CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK – AFTER SERVICE REPORT

08990

| | | | | | |
|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------|-------------------------------------------------|-----------------------------------------------|------------------------------------------|----------------------------------------|
| CUSTOMER: AL-NASSER | | | CONTACT PERSON: MR-HARISH | | |
| SITE DETAILS: AL NASSER CAMP BANIXAS | | | CONTACT NO: 0566833929 | | |
| TANK DETAILS: G.R.P.W. TANK-NO. 2 | | | LOCATION DETAILS: ROOF TOP | | |
| TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL | | <input checked="" type="checkbox"/> RESIDENTIAL | | <input type="checkbox"/> OTHERS | |
| TYPE OF TANK | | | | | |
| <input type="checkbox"/> CONCRETE | <input checked="" type="checkbox"/> GRP PANEL | <input type="checkbox"/> FRP TANK | <input type="checkbox"/> GALVANIZED | <input type="checkbox"/> STEEL PANEL | <input type="checkbox"/> PLASTIC |
| <input type="checkbox"/> CONCRETE COATED | | <input type="checkbox"/> POLYURETHANE | <input type="checkbox"/> OTHERS | | |
| SIZE OF TANK | | | QUANTITY OF WATER | | |
| M3 | USG | L*B*H | <input type="checkbox"/> FULL | <input checked="" type="checkbox"/> HALF | <input type="checkbox"/> EMPTY |
| CONDITION OF WATER TANK BEFORE CLEANING | | | CONDITION OF WATER TANK AFTER CLEANING | | |
| <input type="checkbox"/> CLEAN | <input checked="" type="checkbox"/> DIRTY | <input type="checkbox"/> VERY DIRTY | <input checked="" type="checkbox"/> CLEAN | <input type="checkbox"/> DIRTY | <input type="checkbox"/> VERY DIRTY |
| <input type="checkbox"/> BIOFILMS | <input type="checkbox"/> MOULDS | <input type="checkbox"/> SLIME | <input type="checkbox"/> BIOFILMS | <input type="checkbox"/> MOULDS | <input type="checkbox"/> SLIME |
| <input type="checkbox"/> SEDIMENTS | <input checked="" type="checkbox"/> MUD & SAND | <input type="checkbox"/> RUST | <input type="checkbox"/> SEDIMENTS | <input type="checkbox"/> MUD & SAND | <input type="checkbox"/> RUST |
| ACCESS | | MANHOLE | | <input type="checkbox"/> COVERED | <input type="checkbox"/> DAMAGED |
| <input type="checkbox"/> NA | <input type="checkbox"/> NA | <input type="checkbox"/> NA | <input type="checkbox"/> NA | <input type="checkbox"/> NA | <input type="checkbox"/> NA |
| LADDER IN | | LADDER OUT | | LEAKS | |
| <input checked="" type="checkbox"/> YES | <input type="checkbox"/> NO | <input checked="" type="checkbox"/> YES | <input type="checkbox"/> NO | <input type="checkbox"/> YES | <input checked="" type="checkbox"/> NO |
| TANK CLEANED | | TANK DISINFECTED | | PIPES DISINFECTED | |
| <input checked="" type="checkbox"/> YES | <input type="checkbox"/> NO | <input checked="" type="checkbox"/> YES | <input type="checkbox"/> NO | <input type="checkbox"/> YES | <input type="checkbox"/> NO |
| LAST CLEANING DATE | | CURRENT CLEANING DATE | | NEXT CLEANING DATE | |
| | | 26/12/2018 | | 26/06/2019 | |
| CHEMICALS & EQUIPMENTS USED | | | | | |
| 1. CARELO BIO & PLUS Quantity 500 ML | | | | | |
| 2. _____ Quantity _____ | | | | | |
| <input checked="" type="checkbox"/> Submersible Pump <input checked="" type="checkbox"/> High/Low Pressure Jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED lights <input checked="" type="checkbox"/> Foot Bath <input checked="" type="checkbox"/> Ladder | | | | | |
| <input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Meter <input checked="" type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials | | | | | |
| COMMENTS & RECOMMENDATIONS: | | | | | |
| MENTIONED WATER TANK IS CLEANED & DISINFECTED | | | | | |
| Crystalline Representative: SANKAR | | | Signature: | | |



Date of Cleaning: 26-12-2018

PHOTOGRAPHS
ROOF TOP GRP WATER TANK - 02

BEFORE



AFTER



CLEANER WATER GREENER TOMORROW

CRYSTALLINE CLEANING & ENVIRONMENTAL SERVICES

CLEANING & DISINFECTION CERTIFICATE

POTABLE WATER TANKS

CLIENT NAME : AL NASSER PROPERTIES LLC.
CLIENT ADDRESS : P.O.BOX: 46611, ABU DHABI, UAE.
CONTACT PERSON : MR. HARISH KUMAR
SITE DETAILS : AL NASSER LABOUR CAMP – TAJ 01,
ABU DHABI, UAE.
DETAILS : WATER TANK CLEANING
DATE OF CLEANING : DECEMBER 2018
FREQUENCY OF CLEANING : EVERY SIX MONTHS
DATE OF NEXT CLEANING : JUNE 2019

The procedures employed in this cleaning and disinfection comply with HS (G) 70 health and safety guidelines for prevention of legionella as well as BS6700 and CARELA BIO PLUS method statement.

The entire water storage tank should be cleaned and disinfected minimum every six (6) months depending upon the condition.



CRYSTALLINE CLEANING AND ENVIRONMENTAL SERVICES