

AIR CONDITION DUCT CLEANING

COMPLETION REPORT

For



Client : Emirates International Property
Services LLC.
Contact Person: Mr. Anthony Rodrigues.
Site Details : Apartment No. 1103,
Al Heel Tower, Khalidhiya,
Abu Dhabi, UAE.
Date : 22 January 2019

**Crystalline environmental
services**

P.O. Box 131463, Abu Dhabi, U.A.E.

Tel: 02 6508930 Fax: 02 6508942

info@crystalline-uae.com

www.crystalline-uae.com



CRYSTALLINE
ENVIRONMENTAL SERVICES



CRYSTALLINE ENVIROMENTAL SERVICES

AC DUCT - AFTER SERVICE REPORT

1005

CUSTOMER: BFM		CONTACT PERSON: MR. IBRAHIM			
SITE DETAILS: AL-HEEL TOWER		CONTACT NO. 056-5366740			
AC DETAILS: 11TH FLOOR FLAT-1103		LOCATION DETAILS: KHALIDIYA-ABUDHAB			
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL		<input checked="" type="checkbox"/> RESIDENTIAL		<input type="checkbox"/> OTHER	
AIR CONDITIONING MACHINE:		NO. OF ROOMS SUPPLIED BY A/C:			
Type of A/C:	<input type="checkbox"/> Package Unit	<input type="checkbox"/> AHU	<input checked="" type="checkbox"/> Fan Coil / Split Unit		
Tilted correctly:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No			
Drip tray accessible:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No			
Drip tray:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No			
Direct drain:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No			
Condition of Drip tray cleaned:	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<input checked="" type="checkbox"/> Slime	<input type="checkbox"/> Mould	<input type="checkbox"/> Rusty	<input type="checkbox"/> Damage
TYPE OF FILTERS: FILTER CLEANING FREQUENCY:					
Filters:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No			
Location of filters:	<input type="checkbox"/> Duct	<input checked="" type="checkbox"/> Machine			
DUCTWORK:					
Only physical entry into ducts:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	<input type="checkbox"/> Partly		
Access with tools only:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input type="checkbox"/> Partly		
NUMBER OF SUPPLY GRILLS:		NUMBER OF RETURN GRILLS:			
Type of grill:	<input checked="" type="checkbox"/> Square	<input type="checkbox"/> Rectangle	<input type="checkbox"/> Slot	<input type="checkbox"/> Round	
Fresh air inlet:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input type="checkbox"/> Open	<input type="checkbox"/> Closed	
Return air:	<input type="checkbox"/> Ducts	<input checked="" type="checkbox"/> Cavity			
Flow dumpers:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No			
Sensors:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No			
Damaged:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No			
Internal acoustic insulation:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No			
Type:	<input checked="" type="checkbox"/> Polystyrene	<input type="checkbox"/> Rockwood	<input type="checkbox"/> Foam		
External insulation:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No			
Type:	<input type="checkbox"/> Polystyrene	<input type="checkbox"/> Rockwood	<input type="checkbox"/> Foam		
Covering insulation:	<input type="checkbox"/> Canvas	<input type="checkbox"/> Aluminum	<input checked="" type="checkbox"/> Others		
Sanitization of ducts:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No			
Entire system cleaned:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	If no, give details		
Access doors/panels present:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	How many		
Access doors/panels fitted:	<input checked="" type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	How many		
Ducts damaged:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	Where		
Where installed:					
Ducts size and approximate length: 20 MT					
LAST CLEANED:		CURRENT CLEANING DATE:		NEXT CLEANING DATE:	
		20-01-2019		20-07-2019	
CHEMICALS & EQUIPMENTS USED					
Quantity:					
Comments & recommendations: A/C DUCT CLEANING & SANITIZING FINISHED NO: 5 FCU UNITS FILTER & BLOWER CLEANED.					
Crystalline Representative KANSARI			Signature:		
Client Representative:			Signature:		

CLEANER WATER GREENER TOMORROW
WORK CHECKED BY: MR. BIJU

Web: www.crystalline-uae.com
E-mail: info@crystalline-uae.com
Tel.: +971 55 7167017
  20/1/19




CRYSTALLINE
ENVIRONMENTAL SERVICES

Date of Cleaning: 20-01-2019

PHOTOGRAPHS
A C DUCT CLEANING – AL HEEL TOWER (1103)

BEFORE



AFTER



CLEANER WATER GREENER TOMORROW

Date of Cleaning: 20-01-2019

PHOTOGRAPHS
AC DUCT CLEANING – AL HEEL TOWER 1103

BEFORE



AFTER





CRYSTALLINE
ENVIRONMENTAL SERVICES

Date of Cleaning: 20-01-2019

PHOTOGRAPHS
AC DUCT CLEANING – AL HEEL TOWER 1103

BEFORE



AFTER




CLEANER WATER GREENER TOMORROW

Date of Cleaning: 20-01-2019

PHOTOGRAPHS
A C DUCT CLEANING – AL HEEL TOWER (1103)

BEFORE



AFTER





CRYSTALLINE
ENVIRONMENTAL SERVICES

Date of Cleaning: 20-01-2019

PHOTOGRAPHS
A C DUCT CLEANING – AL HEEL TOWER (1103)

BEFORE



AFTER




CLEANER WATER GREENER TOMORROW

Date of Cleaning: 20-01-2019

PHOTOGRAPHS
A C DUCT CLEANING – AL HEEL TOWER (1103)

BEFORE



AFTER



CRYSTALLINE CLEANING & ENVIRONMENTAL SERVICES

CLEANING & DISINFECTION CERTIFICATE

CLIENT NAME : EMIRATES INTERNATIONAL PROPERTY SERVICES LLC.

CLIENT ADDRESS : P.O. BOX 28928, ABU DHABI, UAE.

CONTACT PERSON : MR. ANTHONY RODRIGUES.

SITE DETAILS : FLAT 1103, AL HEEL TOWER, KHALIDHIYA, ABU DHABI, UAE

DETAILS : AIR CONDITION DUCT CLEANING

DATE OF CLEANING : 20 JANUARY 2019

FREQUENCY OF CLEANING : EVERY SIX (6) MONTHS

DATE OF NEXT CLEANING : 20 JULY 2019

The procedures employed in this cleaning and degreasing comply with Abu Dhabi Municipality guidelines

The entire AC Duct should be cleaned and Degreased minimum every six (6) months depending upon the condition.



CRYSTALLINE CLEANING AND ENVIRONMENTAL SERVICES