

KITCHEN DUCT CLEANING & DISINFECTION

COMPLETION REPORT

For



Al Nasser Properties LLC

Client : Al Nasser Properties L.L.C.
Contact Person: Mr. Harish Kumar
Maintenance Supervisor
Site Details : Al Nasser Camp- TAJ-1,
Abu Dhabi, UAE.
Date : 20 January 2019



CRYSTALLINE
ENVIRONMENTAL SERVICES

**Crystalline environmental
services**

P.O. Box 131463, Abu Dhabi, U.A.E.

Tel: 02 6508930 Fax: 02 6508942

info@crystalline-uae.com

www.crystalline-uae.com



CRYSTALLINE ENVIROMENTAL SERVICES

KITCHEN EXHAUST SYSTEM - AFTER SERVICE REPORT

1059

CUSTOMER: <u>AL NASER PROPERTIES</u>	CONTACT PERSON: <u>MR. HARI SH</u>
SITE DETAILS: <u>BANIYAS</u>	CONTACT NUMBER: <u>056-6833929</u>
NAME OF KITCHEN: <u>HOT KITCHEN</u>	LOCATION: <u>BANIYAS</u>
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL <input type="checkbox"/> HOTEL <input checked="" type="checkbox"/> RESIDENCIAL <input type="checkbox"/> RESTAURANT	
Type & Size of Hood: <u>DOBLE HOOD</u>	
Cooking Volume: <input checked="" type="checkbox"/> Very High <input type="checkbox"/> High <input type="checkbox"/> Medium <input type="checkbox"/> Low	
Type of Filters: <input type="checkbox"/> Mesh <input checked="" type="checkbox"/> Baffle (<u>CYCLON</u>) <input type="checkbox"/> N/A	
Filters in Place: <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> N/A	
Filter Cleaning Freq. <input type="checkbox"/> Daily <input type="checkbox"/> Weekly <input type="checkbox"/> Monthly <input type="checkbox"/> Not Known	
Comments: <u>HOT KITCHEN PAROTA COOKING AREA.</u>	

FIRE PROTECTION SYSTEM

Kitchen: <input type="checkbox"/> Powder <input checked="" type="checkbox"/> CO2 <input type="checkbox"/> Foam <input type="checkbox"/> Other
Cooker Hoods: <input type="checkbox"/> CO2 <input checked="" type="checkbox"/> Sprinkler <input type="checkbox"/> Dry Powder <input type="checkbox"/> Other
Fire Dampers: <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No Fusible Links: <input type="checkbox"/> Yes <input type="checkbox"/> No

DUCTWORK

Duct Made of: <input checked="" type="checkbox"/> Galvanized Steel <input type="checkbox"/> Stainless Steel <input type="checkbox"/> Other
Physical Entry: <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Partly
Access with Tools only: <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Partly
Vertical Access: <input type="checkbox"/> Rope access <input checked="" type="checkbox"/> Safety Harness <input type="checkbox"/> N/A
Entire System Cleaned <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No if No, give details

Comments

Doors/Plates Present: <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> No. of doors <input type="checkbox"/> No of Panels
Doors/Plates Installed: <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> No. of doors <input type="checkbox"/> No of Panels

Where Installed:

Duct Size & Approx. Length: <u>7 MT</u> Insulated: <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
Condition of Ducts: <input checked="" type="checkbox"/> Clean <input type="checkbox"/> Dirty <input type="checkbox"/> Very Dirty
Damaged: <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Where <input type="checkbox"/> N/A
Exhaust Fans: <input checked="" type="checkbox"/> Upblast <input type="checkbox"/> Inline <input type="checkbox"/> Utility <input type="checkbox"/> Others
Location: <u>EXHAUST FAN ROOF</u> Condition of Roof: <u>NORMAL</u>

LAST CLEANING DATE

CURRENT CLEANING DATE

NEXT CLEANING DATE

CHEMICALS AND EQUIPMENTS USED

<input checked="" type="checkbox"/> JETTING MACHINE <input checked="" type="checkbox"/> INLET WATER HOSE <input checked="" type="checkbox"/> EXTENTION CORDS <input type="checkbox"/> VACCUM CLEANER
<input type="checkbox"/> LED LIGHTS <input checked="" type="checkbox"/> PLASTICS ROLL/BAGS <input checked="" type="checkbox"/> SUITABLE PPE <input type="checkbox"/> DEGREASER CHEMICAL <input checked="" type="checkbox"/> LADDER

COMMENTS AND RECOMMENDATION:

This time the workers were not able to go fully inside since they didn't had enough access. So they assured us that next time, if we provide an access they will do it completely (JOSE).

Crystalline Representative: K. ANSARI

Signature:

Customer Representative: Raju / Jose

Signature:



CRYSTALLINE
ENVIRONMENTAL SERVICES


Date of Cleaning: 06-01-2019

PHOTOGRAPHS
KITCHEN HOOD CLEANING- AL NASSER KITCHEN (TAJ 1)

BEFORE



AFTER



CLEANER WATER GREENER TOMORROW



CRYSTALLINE
ENVIRONMENTAL SERVICES

Date of Cleaning: 06-01-2019

PHOTOGRAPHS
KITCHEN HOOD CLEANING- AL NASSER KITCHEN (TAJ 1)

BEFORE



AFTER



CLEANER WATER GREENER TOMORROW



CRYSTALLINE ENVIROMENTAL SERVICES

KITCHEN EXHAUST SYSTEM - AFTER SERVICE REPORT

1060

CUSTOMER: <u>AL NASER PROPERTIES</u>	CONTACT PERSON: <u>MR. HARISH</u>
SITE DETAILS: <u>BANIYAS</u>	CONTACT NUMBER: <u>056-6833929</u>
NAME OF KITCHEN: <u>HOT KITCHEN</u>	LOCATION: <u>BANIYAS</u>
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL <input type="checkbox"/> HOTEL <input checked="" type="checkbox"/> RESIDENCIAL <input type="checkbox"/> RESTAURANT	
Type & Size of Hood:	
Cooking Volume:	<input checked="" type="checkbox"/> Very High <input type="checkbox"/> High <input type="checkbox"/> Medium <input type="checkbox"/> Low
Type of Filters:	<input type="checkbox"/> Mesh <input checked="" type="checkbox"/> Baffle (CYCLON) <input type="checkbox"/> N/A
Filters in Place:	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> N/A
Filter Cleaning Freq.	<input type="checkbox"/> Daily <input type="checkbox"/> Weekly <input type="checkbox"/> Monthly <input type="checkbox"/> Not Known
Comments: <u>HOT KITCHEN PAROTA AREA</u>	

FIRE PROTECTION SYSTEM

Kitchen:	<input type="checkbox"/> Powder <input checked="" type="checkbox"/> CO2 <input type="checkbox"/> Foam <input type="checkbox"/> Other
Cooker Hoods:	<input type="checkbox"/> CO2 <input checked="" type="checkbox"/> Sprinkler <input type="checkbox"/> Dry Powder <input type="checkbox"/> Other
Fire Dampers:	<input type="checkbox"/> Yes <input type="checkbox"/> No Fusible Links: <input type="checkbox"/> Yes <input type="checkbox"/> No

DUCTWORK

Duct Made of:	<input checked="" type="checkbox"/> Galvanized Steel <input type="checkbox"/> Stainless Steel <input type="checkbox"/> Other
Physical Entry:	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Partly
Access with Tools only:	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Partly
Vertical Access:	<input type="checkbox"/> Rope access <input checked="" type="checkbox"/> Safety Harness <input type="checkbox"/> N/A
Entire System Cleaned	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No if No, give details
Comments	

Doors/Plates Present:	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> No. of doors <input type="checkbox"/> No of Panels
Doors/Plates Installed:	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> No. of doors <input type="checkbox"/> No of Panels
Where Installed:	

Duct Size & Approx. Length: <u>7MT</u>	Insulated: <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
Condition of Ducts:	<input checked="" type="checkbox"/> Clean <input type="checkbox"/> Dirty <input type="checkbox"/> Very Dirty
Damaged:	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Where <input type="checkbox"/> N/A
Exhaust Fans:	<input checked="" type="checkbox"/> Upblast <input type="checkbox"/> Inline <input type="checkbox"/> Utility <input type="checkbox"/> Others
Location: <u>ROOF FAN ACCESES</u>	Condition of Roof: <u>NORMAL</u>

LAST CLEANING DATE	CURRENT CLEANING DATE	NEXT CLEANING DATE
	<u>07-01-2019</u>	<u>06-06-2019</u>

CHEMICALS AND EQUIPMENTS USED

<input checked="" type="checkbox"/> JETTING MACHINE	<input checked="" type="checkbox"/> INLET WATER HOSE	<input checked="" type="checkbox"/> EXTENTION CORDS	<input type="checkbox"/> VACCUM CLEANER
<input type="checkbox"/> LED LIGHTS	<input checked="" type="checkbox"/> PLASTICS ROLL/BAGS	<input type="checkbox"/> SUITABLE PPE	<input checked="" type="checkbox"/> DEGREASER CHEMICAL
<input checked="" type="checkbox"/> LADDER			

COMMENTS AND RECOMMENDATION:

Crystalline Representative: <u>K ANSARI</u>	Signature:
Customer Representative: <u>Raju / Jose</u>	Signature:




CRYSTALLINE
ENVIRONMENTAL SERVICES

Date of Cleaning: 07-01-2019

PHOTOGRAPHS
KITCHEN HOOD CLEANING- AL NASSER KITCHEN (TAJ 1)

BEFORE



AFTER



CLEANER WATER GREENER TOMORROW



CRYSTALLINE
ENVIRONMENTAL SERVICES

Date of Cleaning: 07-01-2019

PHOTOGRAPHS
KITCHEN HOOD CLEANING- AL NASSER KITCHEN (TAJ 1)

BEFORE



AFTER



CLEANER WATER GREENER TOMORROW



CRYSTALLINE
ENVIRONMENTAL SERVICES

Date of Cleaning: 07-01-2019

PHOTOGRAPHS
KITCHEN HOOD CLEANING- AL NASSER KITCHEN (TAJ 1)

BEFORE



AFTER



CLEANER WATER GREENER TOMORROW

Date of Cleaning: 07-01-2019

PHOTOGRAPHS
KITCHEN HOOD CLEANING- AL NASSER KITCHEN (TAJ 1)

BEFORE



AFTER





CRYSTALLINE ENVIROMENTAL SERVICES

KITCHEN EXHAUST SYSTEM - AFTER SERVICE REPORT

1061

CUSTOMER: <u>AL NASER PROPERTIES</u>		CONTACT PERSON: <u>MR. HARISH</u>	
SITE DETAILS: <u>BANIYAS</u>		CONTACT NUMBER: <u>056-6833929</u>	
NAME OF KITCHEN: <u>HOT KITCHEN</u>		LOCATION: <u>BANIYAS</u>	
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL <input type="checkbox"/> HOTEL <input checked="" type="checkbox"/> RESIDENCIAL <input type="checkbox"/> RESTAURANT			
Type & Size of Hood: <u>HOT KITCHEN RICE COOKING AREA.</u>			
Cooking Volume:	<input checked="" type="checkbox"/> Very High	<input type="checkbox"/> High	<input type="checkbox"/> Medium <input type="checkbox"/> Low
Type of Filters:	<input type="checkbox"/> Mesh	<input checked="" type="checkbox"/> Baffle	<input type="checkbox"/> N/A
Filters in Place:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input type="checkbox"/> N/A
Filter Cleaning Freq.	<input type="checkbox"/> Daily	<input checked="" type="checkbox"/> Weekly	<input type="checkbox"/> Monthly <input type="checkbox"/> Not Known

Comments:

FIRE PROTECTION SYSTEM

Kitchen:	<input type="checkbox"/> Powder	<input checked="" type="checkbox"/> CO2	<input type="checkbox"/> Foam	<input type="checkbox"/> Other
Cooker Hoods:	<input type="checkbox"/> CO2	<input checked="" type="checkbox"/> Sprinkler	<input type="checkbox"/> Dry Powder	<input type="checkbox"/> Other
Fire Dampers:	<input type="checkbox"/> Yes	<input type="checkbox"/> No	Fusible Links:	<input type="checkbox"/> Yes <input type="checkbox"/> No

DUCTWORK

Duct Made of:	<input checked="" type="checkbox"/> Galvanized Steel	<input type="checkbox"/> Stainless Steel	<input type="checkbox"/> Other
Physical Entry:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input type="checkbox"/> Partly
Access with Tools only:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input type="checkbox"/> Partly
Vertical Access:	<input type="checkbox"/> Rope access	<input checked="" type="checkbox"/> Safety Harness	<input type="checkbox"/> N/A
Entire System Cleaned	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No if No, give details	

Comments

Doors/Plates Present:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	<input type="checkbox"/> No. of doors	<input type="checkbox"/> No of Panels
Doors/Plates Installed:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	<input type="checkbox"/> No. of doors	<input type="checkbox"/> No of Panels

Where Installed:

Duct Size & Approx. Length:	Insulated:	<input type="checkbox"/> Yes	<input type="checkbox"/> No
Condition of Ducts:	<input checked="" type="checkbox"/> Clean	<input type="checkbox"/> Dirty	<input type="checkbox"/> Very Dirty
Damaged:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	<input type="checkbox"/> Where <input type="checkbox"/> N/A
Exhaust Fans:	<input checked="" type="checkbox"/> Upblast	<input type="checkbox"/> Inline	<input type="checkbox"/> Utility <input type="checkbox"/> Others

Location: <u>EXHAUST ROOF</u>	Condition of Roof: <u>NORMAL</u>
-------------------------------	----------------------------------

LAST CLEANING DATE	CURRENT CLEANING DATE	NEXT CLEANING DATE
	<u>08-1-2019</u>	<u>08-06-2019</u>

CHEMICALS AND EQUIPMENTS USED

<input checked="" type="checkbox"/> JETTING MACHINE	<input type="checkbox"/> INLET WATER HOSE	<input checked="" type="checkbox"/> EXTENTION CORDS	<input type="checkbox"/> VACCUM CLEANER
<input type="checkbox"/> LED LIGHTS	<input checked="" type="checkbox"/> PLASTICS ROLL/BAGS	<input checked="" type="checkbox"/> SUITABLE PPE	<input checked="" type="checkbox"/> DEGREASER CHEMICAL
<input type="checkbox"/> LADDER			

COMMENTS AND RECOMMENDATION: I am inform the josh sir we need access 1, 1 duct cleaning next cleaning date.

Crystalline Representative: <u>lc. ANSARI</u>	Signature: <u>lc. A</u>
Customer Representative: <u>Raju / Gose</u>	Signature: <u>[Signature]</u>



CRYSTALLINE
ENVIRONMENTAL SERVICES


Date of Cleaning: 08-01-2019

PHOTOGRAPHS
KITCHEN HOOD CLEANING- AL NASSER KITCHEN (TAJ 1)

BEFORE



AFTER




CLEANER WATER GREENER TOMORROW

Date of Cleaning: 08-01-2019

PHOTOGRAPHS
KITCHEN DUCT CLEANING- AL NASSER KITCHEN (TAJ 1)

BEFORE



AFTER





CRYSTALLINE
ENVIRONMENTAL SERVICES

Date of Cleaning: 08-01-2019

PHOTOGRAPHS
KITCHEN HOOD CLEANING- AL NASSER KITCHEN (TAJ 1)

BEFORE



AFTER



CLEANER WATER GREENER TOMORROW

Date of Cleaning: 08-01-2019

PHOTOGRAPHS
KITCHEN DUCT CLEANING- AL NASSER KITCHEN (TAJ 1)

BEFORE



AFTER





CRYSTALLINE
ENVIRONMENTAL SERVICES

Date of Cleaning: 08-01-2019

PHOTOGRAPHS
KITCHEN HOOD CLEANING- AL NASSER KITCHEN (TAJ 1)

BEFORE



AFTER



CLEANER WATER GREENER TOMORROW



METHODOLOGY:

- ✓ Preliminary site visit. To choose the effective procedure.
- ✓ Live Camera Inspection for the internal duct.
- ✓ Safety clothing/equipment required: overalls, safety boots, eye protection, gloves and correct respirators.
- ✓ Conduct safety briefing with client's representative to ensure all possible hazards are identified and reported immediately if assistance is required for the control of hazards.
- ✓ Ensure spill control Kit and fire extinguisher is available.
- ✓ Digital photo taken for the proof of cleaning process.
- ✓ Access holes in ducts shall be cut if required.
- ✓ Fans shall be isolated and warning labels should be placed on isolation switches.
- ✓ Areas of duct to be cleaned to bare metal.
- ✓ Toxic or flammable products shall not be used.
- ✓ Waste rags and lint will be disposed of in the client's waste disposal facilities.
- ✓ Record any areas unable to be cleaned giving exact reasons.

If you have any queries concerning our services, please contact: +971 2 6508930

Thank you for your business!

Crystalline Cleaning & Environmental Services

CRYSTALLINE CLEANING & ENVIRONMENTAL SERVICES

CLEANING & DISINFECTION CERTIFICATE

CLIENT NAME : AL NASSER PROPERTIES L.L.C.
CLIENT ADDRESS : P.O.BOX: 46611, ABU DHABI, UAE.
CONTACT PERSON : MR. HARISH KUMAR
SITE DETAILS : AL NASSER CAMP TAJ-1, ABU DHABI.
DETAILS : KITCHEN DUCT CLEANING
DATE OF CLEANING : JANUARY 2019
FREQUENCY OF CLEANING : EVERY SIX (6) MONTHS
DATE OF NEXT CLEANING : JULY 2019

The procedures employed in this cleaning and disinfection comply with Abu Dhabi Municipality guidelines

The entire Kitchen Hood should be cleaned and disinfected minimum every six (6) months depending upon the condition.



CRYSTALLINE CLEANING AND ENVIRONMENTAL SERVICES