

AIR CONDITION DUCT CLEANING AND SANITIZING

COMPLETION REPORT

For



Client : Squad Line General Contracting &
Maintenance L.L.C.
Contact Person: Mr. Ansari K.
Asst. Manager
Site Details : Mr. Bin Hayai, Villa No. 19,
Bain Al Jesrain, Abu Dhabi, UAE
Date : 07 February 2019

**Crystalline environmental
services**

P.O. Box 131463, Abu Dhabi, U.A.E.

Tel: 02 6508930 Fax: 02 6508942

info@crystalline-uae.com

www.crystalline-uae.com



CRYSTALLINE
ENVIRONMENTAL SERVICES



CRYSTALLINE ENVIROMENTAL SERVICES

AC DUCT - AFTER SERVICE REPORT

1051

CUSTOMER: MOHAMMED SALEM BIN ZAYED		CONTACT PERSON: Mr. JOHEIR UDDIN	
SITE DETAILS: BAY AL JASREEN - VILLA - 19		CONTACT NO.	
AC DETAILS: Fan - Unit - Duct		LOCATION DETAILS: Ground Floor	
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL		<input checked="" type="checkbox"/> RESIDENTIAL <input type="checkbox"/> OTHER	
AIR CONDITIONING MACHINE:		NO. OF ROOMS SUPPLIED BY A/C:	
Type of A/C:	<input type="checkbox"/> Package Unit	<input type="checkbox"/> AHU	<input checked="" type="checkbox"/> Fan Coil / Split Unit
Tilted correctly:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	
Drip tray accessible:	<input checked="" type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	
Drip tray:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	
Direct drain:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	
Condition of Drip tray cleaned:	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<input type="checkbox"/> Slime	<input type="checkbox"/> Mould <input type="checkbox"/> Rusty <input type="checkbox"/> Damage
TYPE OF FILTERS: FILTER CLEANING FREQUENCY:			
Filters:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	
Location of filters:	<input type="checkbox"/> Duct	<input checked="" type="checkbox"/> Machine	
DUCTWORK:			
Only physical entry into ducts:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	<input type="checkbox"/> Partly
Access with tools only:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input type="checkbox"/> Partly
NUMBER OF SUPPLY GRILLS:		NUMBER OF RETURN GRILLS:	
Type of grill:	<input checked="" type="checkbox"/> Square	<input checked="" type="checkbox"/> Rectangle	<input type="checkbox"/> Slot <input type="checkbox"/> Round
Fresh air inlet:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Open <input type="checkbox"/> Closed
Return air:	<input type="checkbox"/> Ducts	<input checked="" type="checkbox"/> Cavity	
Flow dumpers:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	
Sensors:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	
Damaged:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	
Internal acoustic insulation:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	
Type:	<input checked="" type="checkbox"/> Polystyrene	<input type="checkbox"/> Rockwood	<input type="checkbox"/> Foam
External insulation:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	
Type:	<input checked="" type="checkbox"/> Polystyrene	<input type="checkbox"/> Rockwood	<input type="checkbox"/> Foam
Covering insulation:	<input checked="" type="checkbox"/> Canvas	<input type="checkbox"/> Aluminum	<input type="checkbox"/> Others
Sanitization of ducts:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	
Entire system cleaned:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	If no, give details
Access doors/panels present:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	How many 12
Access doors/panels fitted:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	How many 03
Ducts damaged:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	Where
Where installed:	/		
Ducts size and approximate length:			
LAST CLEANED:	CURRENT CLEANING DATE:	NEXT CLEANING DATE:	
	29-30/01/2019	29-01-2020	
CHEMICALS & EQUIPMENTS USED			
Quantity: sanitization of duct - Vacuum WFA - special cleaner - Air compressor			
Comments & recommendations: A/C Duct system has been cleaned.			
Crystalline Representative: Patricia	Signature:		
Client Representative: JOHEIR UDDIN	Signature:		



CRYSTALLINE
ENVIRONMENTAL SERVICES

Date of Cleaning: 29-01-2019

PHOTOGRAPHS

GROUND LEVEL A C DUCT CLEANING – Villa 19 Bain Al Jesrain

BEFORE



AFTER




CLEANER WATER GREENER TOMORROW

Date of Cleaning: 29-01-2019

PHOTOGRAPHS
GROUND LEVEL AC DUCT CLEANING

BEFORE



AFTER




Date of Cleaning: 29-01-2019

PHOTOGRAPHS
GROUND LEVEL AC DUCT CLEANING

BEFORE



AFTER



Date of Cleaning: 29-01-2019

PHOTOGRAPHS
GROUND LEVEL A C DUCT CLEANING

BEFORE




AFTER





Date of Cleaning: 29-01-2019

PHOTOGRAPHS
GROUND LEVEL A C DUCT CLEANING

BEFORE



AFTER





CRYSTALLINE
ENVIRONMENTAL SERVICES

Date of Cleaning: 29-01-2019

PHOTOGRAPHS
GROUND LEVEL A C DUCT CLEANING

BEFORE



AFTER



CLEANER WATER GREENER TOMORROW

Date of Cleaning: 29-01-2019

PHOTOGRAPHS
GROUND LEVEL A C DUCT CLEANING

BEFORE



AFTER



Date of Cleaning: 30-01-2019

PHOTOGRAPHS
GROUND LEVEL AC DUCT CLEANING

BEFORE



AFTER





CRYSTALLINE
ENVIRONMENTAL SERVICES


Date of Cleaning: 30-01-2019

PHOTOGRAPHS
GROUND LEVEL AC DUCT CLEANING

BEFORE



AFTER



CLEANER WATER GREENER TOMORROW



CRYSTALLINE
ENVIRONMENTAL SERVICES

Date of Cleaning: 30-01-2019

PHOTOGRAPHS
GROUND LEVEL A C DUCT CLEANING

BEFORE



AFTER



CLEANER WATER GREENER TOMORROW


Date of Cleaning: 30-01-2019

PHOTOGRAPHS
GROUND LEVEL A C DUCT CLEANING

BEFORE



AFTER





CRYSTALLINE ENVIROMENTAL SERVICES

AC DUCT - AFTER SERVICE REPORT

1052

CUSTOMER: MOHAMMED SAALEM BIN ZAYED		CONTACT PERSON: Mr JOHEIR UDDIN	
SITE DETAILS: BAY AL JASREEN - VILLA - 19		CONTACT NO. 055 122 34 09	
AC DETAILS: A/c Duct system		LOCATION DETAILS: 1 st FLOOR	
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL		<input checked="" type="checkbox"/> RESIDENTIAL <input type="checkbox"/> OTHER	
AIR CONDITIONING MACHINE:		NO. OF ROOMS SUPPLIED BY A/C:	
Type of A/C:	<input type="checkbox"/> Package Unit	<input type="checkbox"/> AHU	<input checked="" type="checkbox"/> Fan Coil / Split Unit
Tilted correctly:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	
Drip tray accessible:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	
Drip tray:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	
Direct drain:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	
Condition of Drip tray cleaned:	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<input type="checkbox"/> Slime	<input type="checkbox"/> Mould <input type="checkbox"/> Rusty <input type="checkbox"/> Damage
TYPE OF FILTERS: FILTER CLEANING FREQUENCY:			
Filters:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	
Location of filters:	<input type="checkbox"/> Duct	<input checked="" type="checkbox"/> Machine	
DUCTWORK:			
Only physical entry into ducts:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	<input type="checkbox"/> Partly
Access with tools only:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input type="checkbox"/> Partly
NUMBER OF SUPPLY GRILLS:		NUMBER OF RETURN GRILLS:	
Type of grill:	<input type="checkbox"/> Square	<input checked="" type="checkbox"/> Rectangle	<input type="checkbox"/> Slot <input type="checkbox"/> Round
Fresh air inlet:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input type="checkbox"/> Open <input type="checkbox"/> Closed
Return air:	<input type="checkbox"/> Ducts	<input checked="" type="checkbox"/> Cavity	
Flow dumpers:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	
Sensors:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	
Damaged:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	
Internal acoustic insulation:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	
Type:	<input checked="" type="checkbox"/> Polystyrene	<input type="checkbox"/> Rockwood	<input type="checkbox"/> Foam
External insulation:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	
Type:	<input checked="" type="checkbox"/> Polystyrene	<input type="checkbox"/> Rockwood	<input type="checkbox"/> Foam
Covering insulation:	<input checked="" type="checkbox"/> Canvas	<input type="checkbox"/> Aluminum	<input type="checkbox"/> Others
Sanitization of ducts:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	
Entire system cleaned:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	If no, give details
Access doors/panels present:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	How many 14
Access doors/panels fitted:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	How many 04
Ducts damaged:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	Where
Where installed:	✓		
Ducts size and approximate length:			
LAST CLEANED:	CURRENT CLEANING DATE:	NEXT CLEANING DATE:	
	31-01-03-02 / 2019	29-01-2020	
CHEMICALS & EQUIPMENTS USED			
Quantity: Special cleaner - Vacuum/LFA - Air Compressor - Sanitization ducts			
Comments & recommendations: A/c Duct system has been cleaned, We had noticed that one filter was damaged			
Crystalline Representative: Patrick		Signature:	
Client Representative: JOHEIR UDDIN		Signature:	

Date of Cleaning: 31-01-2019

PHOTOGRAPHS
1ST FLOOR A C DUCT CLEANING

BEFORE



AFTER





CRYSTALLINE
ENVIRONMENTAL SERVICES

Date of Cleaning: 31-01-2019

PHOTOGRAPHS
1ST FLOOR A C DUCT CLEANING

BEFORE



AFTER



CLEANER WATER GREENER TOMORROW

Date of Cleaning: 31-01-2019

PHOTOGRAPHS
1ST FLOOR A C DUCT CLEANING

BEFORE



AFTER





CRYSTALLINE
ENVIRONMENTAL SERVICES

Date of Cleaning: 31-01-2019

PHOTOGRAPHS
1ST FLOOR A C DUCT CLEANING

BEFORE



AFTER



CLEANER WATER GREENER TOMORROW



CRYSTALLINE
ENVIRONMENTAL SERVICES

Date of Cleaning: 31-01-2019

PHOTOGRAPHS
1ST FLOOR A C DUCT CLEANING

BEFORE



AFTER



CLEANER WATER GREENER TOMORROW



CRYSTALLINE ENVIROMENTAL SERVICES

AC DUCT - AFTER SERVICE REPORT

1053

CUSTOMER: MOHAMMED SHALEH BIN ZAYED		CONTACT PERSON: Mr JOHEIR UDDIN	
SITE DETAILS: BAY AL JASREEN - VILLA-19		CONTACT NO. 055 122 3409	
AC DETAILS: Ac Duct system		LOCATION DETAILS: 2nd Floor	
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL		<input checked="" type="checkbox"/> RESIDENTIAL <input type="checkbox"/> OTHER	
AIR CONDITIONING MACHINE:		NO. OF ROOMS SUPPLIED BY A/C:	
Type of A/C:	<input type="checkbox"/> Package Unit	<input type="checkbox"/> AHU	<input checked="" type="checkbox"/> Fan Coil / Split Unit
Tilted correctly:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	
Drip tray accessible:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	
Drip tray:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	
Direct drain:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	
Condition of Drip tray cleaned:	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	<input type="checkbox"/> Slime	<input type="checkbox"/> Mould <input type="checkbox"/> Rusty <input type="checkbox"/> Damage
TYPE OF FILTERS: FILTER CLEANING FREQUENCY:			
Filters:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	
Location of filters:	<input type="checkbox"/> Duct	<input checked="" type="checkbox"/> Machine	
DUCTWORK:			
Only physical entry into ducts:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	<input type="checkbox"/> Partly
Access with tools only:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input type="checkbox"/> Partly
NUMBER OF SUPPLY GRILLS:		NUMBER OF RETURN GRILLS:	
Type of grill:	<input checked="" type="checkbox"/> Square	<input checked="" type="checkbox"/> Rectangle	<input type="checkbox"/> Slot <input type="checkbox"/> Round
Fresh air inlet:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input type="checkbox"/> Open <input type="checkbox"/> Closed
Return air:	<input type="checkbox"/> Ducts	<input checked="" type="checkbox"/> Cavity	
Flow dumpers:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	
Sensors:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	
Damaged:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	
Internal acoustic insulation:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	
Type:	<input checked="" type="checkbox"/> Polystyrene	<input type="checkbox"/> Rockwood	<input type="checkbox"/> Foam
External insulation:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	
Type:	<input checked="" type="checkbox"/> Polystyrene	<input type="checkbox"/> Rockwood	<input type="checkbox"/> Foam
Covering insulation:	<input checked="" type="checkbox"/> Canvas	<input type="checkbox"/> Aluminum	<input type="checkbox"/> Others
Sanitization of ducts:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	
Entire system cleaned:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	If no, give details
Access doors/panels present:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	How many 05
Access doors/panels fitted:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	How many 01
Ducts damaged:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	Where
Where installed:	<input checked="" type="checkbox"/>		
Ducts size and approximate length:	<input checked="" type="checkbox"/>		
LAST CLEANED:	CURRENT CLEANING DATE:	NEXT CLEANING DATE:	
	03-02-2019	03-02-2020	
CHEMICALS & EQUIPMENTS USED			
Quantity:	Special cleaner - Air Compressor - Vacuum machine - Sanitization		
Comments & recommendations:	AC Duct system has been cleaned. we had noticed that, one filter was completely damaged		
Crystalline Representative Polieris	Signature:		
Client Representative JOHEIR UDDIN	Signature:		



CRYSTALLINE
ENVIRONMENTAL SERVICES



Date of Cleaning: 03-02-2019

PHOTOGRAPHS
1ST FLOOR A C DUCT CLEANING

BEFORE



AFTER



CLEANER WATER GREENER TOMORROW




CRYSTALLINE
ENVIRONMENTAL SERVICES


Date of Cleaning: 03-02-2019

PHOTOGRAPHS
2ND FLOOR A C DUCT CLEANING

BEFORE



AFTER




CLEANER WATER GREENER TOMORROW

Date of Cleaning: 03-02-2019

PHOTOGRAPHS
2ND FLOOR A C DUCT CLEANING

BEFORE



AFTER





CRYSTALLINE
ENVIRONMENTAL SERVICES

Date of Cleaning: 03-02-2019

PHOTOGRAPHS
2ND FLOOR A C DUCT CLEANING

BEFORE



AFTER



CLEANER WATER GREENER TOMORROW


Date of Cleaning: 03-02-2019

PHOTOGRAPHS
2ND FLOOR A C DUCT CLEANING

BEFORE



AFTER



CRYSTALLINE CLEANING & ENVIRONMENTAL SERVICES

CLEANING & DISINFECTION CERTIFICATE

CLIENT NAME : SQUAD LINE GENERAL CONTRACTING & MAINTENANCE L.L.C.

CLIENT ADDRESS : P.O. BOX 52945, ABU DHABI, UAE.

CONTACT PERSON : MR. ANSARI K.

SITE DETAILS : Mr. BIN HAYAL, VILLA #19, BAIN AL JESRAIN, ABU DHABI, UAE.

DETAILS : AIR CONDITION DUCT CLEANING & SANITIZING

DATE OF CLEANING : FEBRUARY 2019

FREQUENCY OF CLEANING : EVERY ONE (1) YEAR

DATE OF NEXT CLEANING : FEBRUARY 2020

The procedures employed in this cleaning and degreasing comply with Abu Dhabi Municipality guidelines

The entire AC Duct should be cleaned and Degreased minimum every one (1) Year depending upon the condition.



CRYSTALLINE CLEANING AND ENVIRONMENTAL SERVICES