

# MANHOLE CLEANING & COMPLETION REPORT

For



شركة يوش للضيافة  
YOSH HOSPITALITY LLC

Client : YOSH HOSPITALITY LLC  
Contact Person : Mr. Nikola Dimirijevic  
Facilities Manager  
Site Details : Al Grum Villa 55,  
Property No- 1245101,  
Abu Dhabi, UAE.  
Service Date : 07 February 2019  
Next Service Date : 07 August 2019

**Crystalline environmental Services**

P.O. Box 131463, Abu Dhabi, U.A.E.

Tel: 02 6508930 Fax: 02 6508942

[info@crystalline-uae.com](mailto:info@crystalline-uae.com)

[www.crystalline-uae.com](http://www.crystalline-uae.com)



**CRYSTALLINE**  
ENVIRONMENTAL SERVICES



# CRYSTALLINE ENVIRONMENTAL SERVICES

1112

## MANHOLE, GULLY TRAP, DRAINAGE - AFTER SERVICE REPORT

<b>CUSTOMER:</b> Al Groom Villa	<b>CONTACT PERSON:</b> Mr. Mohammed Tariq
<b>SITE DETAILS:</b> Al Groom Villa 55	<b>CONTACT NUMBER:</b> 055 3256807
<b>NAME OF MANHOLE:</b> Under ground manhole	<b>LOCALISATION:</b> Front and back building
<b>TYPE OF BUILDING:</b> <input type="checkbox"/> COMMERCIAL <input type="checkbox"/> EDUCATIONAL <input checked="" type="checkbox"/> RESIDENCIAL <input type="checkbox"/> INDUSTRIAL	

### PART OF DRAINAGE

MANHOLE     UNDERGROUND DRAINAGE PIPE     GULLY TRAP     GREASE TRAP

DRAINAGE PIPE     APPARENT DRAINAGE PIPE     EMBEDDED DRAINAGE PIPE

### CONDITION OF MANHOLE, GULLY TRAP, DRAINAGE BEFORE CLEANING

LITTLE DIRTY     DIRTY     VERY DIRTY     RUST     SEDIMENTS     MUD

BIOFILMS     SLIME     GREASE     ROOT     SAND     MOULDS

OBSTRUCT     BLOCK     FLUENT FLOW     LOW FLOW     ANOTHER: *Tissue Paper*

<b>MANHOLE BLOCKED</b>	<b>GULLY TRAP BLOCKED</b>	<b>DRAINAGE BLOCKED</b>	<b>ALL BLOCKED</b>
<input type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input type="checkbox"/> YES <input type="checkbox"/> NO	<input type="checkbox"/> YES <input type="checkbox"/> NO

### COMMENTS:

**MANHOLE AND GULLY TRAP COVER:**  COVERED     DAMAGED     BLOCKED     ADAPTED

### CONDITION OF MANHOLE, GULLY TRAP, DRAINAGE AFTER CLEANING

LITTLE CLEAN     CLEAN     VERY CLEAN     FLUENT FLOW     LOW FLOW     UNBLOCK

	MANHOLE	GULLY TRAP	STORM WATER	DRAINAGE	TOTAL
NUMBER OF MANHOLE CLEANED	10	7	/	8	25
NUMBER OF MANHOLE BLOCKED	/	1	/	/	7

### ACCESS

LADDER IN     NO LADDER

<b>MANHOLE CLEANED</b>	<b>GULLY TRAP CLEANED</b>	<b>DRAINAGE CLEANED</b>	<b>ALL DISINFECTED</b>
<input type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO

### SERVICES OF DATES

<b>LAST CLEANING DATE</b>	<b>LAST CLEANING DATE</b>	<b>Next LAST CLEANING DATE</b>
	7/02/2019	7/08/2019

### CHEMICALS AND EQUIPMENTS USED

PRESSURE MACHINE     JETTING MACHINE     MULTIGAS DETECTEUR     INLET WATER HOSE

EXTENTION CORDS     VACCUM CLEANER     VENTILATION FAN     CLEANING MAT

LED LIGHTS     PLASTICS ROLL     PLASTICS BAGS     SUITABLE PPE

TRIPOD     AIR REPAIR 7D-A     DEGREASER CHEMICAL     LADDER

**COMMENTS AND RECOMMENDATION:** All above mention cleaned and disinfected

<b>Crystalline representative:</b> <i>Tanirick</i>	<b>Signature:</b> <i>[Signature]</i>
<b>Customer/Customer representative:</b> <i>Jishay.mw</i>	<b>Signature:</b> <i>[Signature]</i>




**CRYSTALLINE**  
ENVIRONMENTAL SERVICES

Date of Cleaning: 07-02-2019

**PHOTOGRAPHS**  
**MANHOLE CLEANING – (AL GRUM VILLA 55)**

**BEFORE CLEANING**



**AFTER CLEANING**



**CLEANER WATER GREENER TOMORROW**

Date of Cleaning: 07-02-2019

**PHOTOGRAPHS**  
**MANHOLE CLEANING – (VILLA 55)**

**BEFORE CLEANING**



**AFTER CLEANING**



Date of Cleaning: 07-02-2019

**PHOTOGRAPHS**  
**MANHOLE CLEANING – (VILLA 55)**

**BEFORE CLEANING**



**AFTER CLEANING**



Date of Cleaning: 07-02-2019

**PHOTOGRAPHS**  
**MANHOLE CLEANING – (VILLA 55)**

**BEFORE CLEANING**



**AFTER CLEANING**




Date of Cleaning: 07-02-2019

**PHOTOGRAPHS**  
**MANHOLE CLEANING – (VILLA 55)**

**BEFORE CLEANING**



**AFTER CLEANING**



Date of Cleaning: 07-02-2019

**PHOTOGRAPHS**  
**MANHOLE CLEANING – (VILLA 55)**

**BEFORE CLEANING**



**AFTER CLEANING**



# CRYSTALLINE CLEANING & ENVIRONMENTAL SERVICES

## CLEANING & DISINFECTION CERTIFICATE

**CLIENT NAME** : YOSH HOSPITALITY LLC.  
**CLIENT ADDRESS** : P.O.BOX: 4347, ABU DHABI, UAE.  
**CONTACT PERSON** : MR. NIKOLA DIMITRIJEVIC  
**SITE DETAILS** : PROPERTY NO – 1245101, ABU DHABI, UAE.  
**DETAILS** : MANHOLE & GULLY TRAP CLEANING  
**DATE OF CLEANING** : 07 FEBRUARY 2019  
**FREQUENCY OF CLEANING** : EVERY SIX (6) MONTHS  
**DATE OF NEXT CLEANING** : 07 AUGUST 2019

*The procedures employed in this cleaning and disinfection comply with Abu Dhabi Municipality guidelines*

*The entire Manhole & Gully Trap should be cleaned and disinfected minimum every six (6) months depending upon the condition.*



CRYSTALLINE CLEANING AND ENVIRONMENTAL SERVICES