

**ENVIRONMENTAL
SERVICES FOR
A GREENER
TOMORROW...
ONE STEP AT
A TIME.**



Completion Report for

Water Tank Cleaning & Disinfection



Date: **10 September 2019**
Client Name: **Food World**
Contact Person: **Mr. Karunakar**
Designation: **Accountant**
Site Detail: **Foodworld Restaurant, Al Ain**



Address: PO BOX 131463, Abu Dhabi, UAE | Phone: +971 2 650 8930, +971 55 716 7017
E-mail: info@crystalline-uae.com | Website: www.crystalline-uae.com


Service Report



Customer: Food World		Contact Person: Mr. Karunakar	
Site: Foodworld Restaurant, Al Ain		Contact Number: 0555180198	
Description: RCC Water Tank 1		Location: Basement 1 pump Room	
Type Of Building : <input checked="" type="checkbox"/> Commercial <input type="checkbox"/> Residential <input type="checkbox"/> Others			
Type Of Tank			
<input checked="" type="checkbox"/> Concrete	<input type="checkbox"/> GRP Panel	<input type="checkbox"/> FRP Tank	<input type="checkbox"/> Galvanized
<input type="checkbox"/> Steel Panel	<input type="checkbox"/> Plastic	<input type="checkbox"/> Concrete Coated	<input type="checkbox"/> Polyurethane
<input type="checkbox"/> Others			
Condition Of Water before cleaning		Condition Of Water after cleaning	
<input type="checkbox"/> Clean	<input checked="" type="checkbox"/> Dirty	<input type="checkbox"/> Very Dirty	<input type="checkbox"/> Dirty
<input type="checkbox"/> Biofilms	<input type="checkbox"/> Moulds	<input type="checkbox"/> Slime	<input type="checkbox"/> Moulds
<input type="checkbox"/> Sediments	<input checked="" type="checkbox"/> Mud & Sand	<input type="checkbox"/> Rust	<input type="checkbox"/> Slime
<input type="checkbox"/> Rust		<input type="checkbox"/> Rust	
Size of Tank			
M3:		USG: 20000 Gln	L*B*H:
Quantity Of Water		Manhole	
<input type="checkbox"/> Full	<input checked="" type="checkbox"/> Half	<input type="checkbox"/> Empty	<input checked="" type="checkbox"/> Covered
<input type="checkbox"/> Damaged		<input type="checkbox"/> NA	
Ladder In		Ladder Out	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Leaks		<input checked="" type="checkbox"/> No	
<input type="checkbox"/> Yes		<input type="checkbox"/> No	
Drain Line		Valves	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Float Valve		<input checked="" type="checkbox"/> Yes	
<input type="checkbox"/> Yes		<input type="checkbox"/> No	
Tank Cleaned		Tank Disinfected	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Pipes Disinfected		<input type="checkbox"/> Yes	
<input checked="" type="checkbox"/> No		<input type="checkbox"/> No	
Chemicals Used			
Chemical: Carela bio and plus		Quantity: 200 MI	
Chemical:		Quantity:	
Equipments Used			
<input checked="" type="checkbox"/> Submersibel Pump	<input checked="" type="checkbox"/> High/low Pressure Jet	<input checked="" type="checkbox"/> Extension Cords	<input checked="" type="checkbox"/> LED Lights
<input checked="" type="checkbox"/> Foot Bath	<input checked="" type="checkbox"/> Ladder	<input checked="" type="checkbox"/> Ventilating Fan	<input checked="" type="checkbox"/> Oxygen Meter
<input checked="" type="checkbox"/> Vacuum Cleaner	<input checked="" type="checkbox"/> Cleaning Materials	<input checked="" type="checkbox"/> Suction/Discharge Hoses	
Last Cleaning Date		Current Cleaning Date	Next Cleaning Date
-		10 September 2019	10 March 2020
Crystalline Representative		Customer Representative	
			

RCC Water Tank 1


Before Photo




After Photo



Before Photo




After Photo



Water tank cleaned and disinfected

Service Report



Customer: Food World		Contact Person: Mr. Karunakar	
Site: Foodworld Restaurant, Al Ain		Contact Number: 0555180198	
Description: Sintex water tank 1		Location: Roof top	
Type Of Building : <input checked="" type="checkbox"/> Commercial <input type="checkbox"/> Residential <input type="checkbox"/> Others			
Type Of Tank			
<input type="checkbox"/> Concrete	<input type="checkbox"/> GRP Panel	<input type="checkbox"/> FRP Tank	<input type="checkbox"/> Galvanized
<input type="checkbox"/> Steel Panel	<input type="checkbox"/> Plastic	<input type="checkbox"/> Concrete Coated	<input checked="" type="checkbox"/> Polyurethane
<input type="checkbox"/> Others			
Condition Of Water before cleaning		Condition Of Water after cleaning	
<input type="checkbox"/> Clean	<input checked="" type="checkbox"/> Dirty	<input type="checkbox"/> Very Dirty	<input checked="" type="checkbox"/> Clean
<input type="checkbox"/> Biofilms	<input checked="" type="checkbox"/> Moulds	<input type="checkbox"/> Slime	<input type="checkbox"/> Dirty
<input type="checkbox"/> Sediments	<input type="checkbox"/> Mud & Sand	<input type="checkbox"/> Rust	<input type="checkbox"/> Very Dirty
		<input type="checkbox"/> Biofilms	<input type="checkbox"/> Moulds
		<input type="checkbox"/> Sediments	<input type="checkbox"/> Slime
		<input type="checkbox"/> Mud & Sand	<input type="checkbox"/> Rust
Size of Tank			
M3:		USG: 1500 GLN	L*B*H:
Quantity Of Water		Manhole	
<input type="checkbox"/> Full	<input checked="" type="checkbox"/> Half	<input type="checkbox"/> Empty	<input checked="" type="checkbox"/> Covered
			<input type="checkbox"/> Damaged
			<input type="checkbox"/> NA
Ladder In		Ladder Out	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Leaks		Leaks	
		<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Drain Line		Valves	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Float Valve		Float Valve	
		<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Tank Cleaned		Tank Disinfected	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Pipes Disinfected		Pipes Disinfected	
		<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Chemicals Used			
Chemical: Carela bio and plus		Quantity: 100 MI	
Chemical:		Quantity:	
Equipments Used			
<input checked="" type="checkbox"/> Submersibel Pump	<input checked="" type="checkbox"/> High/low Pressure Jet	<input checked="" type="checkbox"/> Extension Cords	<input checked="" type="checkbox"/> LED Lights
<input checked="" type="checkbox"/> Foot Bath	<input checked="" type="checkbox"/> Ladder	<input checked="" type="checkbox"/> Ventilating Fan	<input checked="" type="checkbox"/> Oxygen Meter
<input checked="" type="checkbox"/> Vacuum Cleaner	<input checked="" type="checkbox"/> Cleaning Materials	<input checked="" type="checkbox"/> Suction/Discharge Hoses	
Last Cleaning Date		Current Cleaning Date	Next Cleaning Date
-		10 September 2019	10 March 2020
Crystalline Representative		Customer Representative	
			

Sintex water tank 1

Before Photo



After Photo



Before Photo





After Photo



Water tank cleaned and disinfected

Service Report



Customer: Food World		Contact Person: Mr. Karunakar			
Site: Foodworld Restaurant, Al Ain		Contact Number: 0555180198			
Description: Sintex Water Tank 2		Location: Roof Top			
Type Of Building : <input checked="" type="checkbox"/> Commercial <input type="checkbox"/> Residential <input type="checkbox"/> Others					
Type Of Tank					
<input type="checkbox"/> Concrete	<input type="checkbox"/> GRP Panel	<input type="checkbox"/> FRP Tank	<input type="checkbox"/> Galvanized		
<input type="checkbox"/> Steel Panel	<input type="checkbox"/> Plastic	<input type="checkbox"/> Concrete Coated	<input checked="" type="checkbox"/> Polyurethane		
<input type="checkbox"/> Others					
Condition Of Water before cleaning		Condition Of Water after cleaning			
<input type="checkbox"/> Clean	<input checked="" type="checkbox"/> Dirty	<input type="checkbox"/> Very Dirty	<input type="checkbox"/> Very Dirty		
<input type="checkbox"/> Biofilms	<input checked="" type="checkbox"/> Moulds	<input type="checkbox"/> Slime	<input type="checkbox"/> Slime		
<input type="checkbox"/> Sediments	<input type="checkbox"/> Mud & Sand	<input type="checkbox"/> Rust	<input type="checkbox"/> Rust		
Size of Tank					
M3:		USG: 1500 GLN	L*B*H:		
Quantity Of Water		Manhole			
<input type="checkbox"/> Full	<input checked="" type="checkbox"/> Half	<input type="checkbox"/> Empty	<input checked="" type="checkbox"/> Covered <input type="checkbox"/> Damaged <input type="checkbox"/> NA		
Ladder In		Ladder Out		Leaks	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Drain Line		Valves		Float Valve	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Tank Cleaned		Tank Disinfected		Pipes Disinfected	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Chemicals Used					
Chemical: Carela bio and plus				Quantity: 100 MI	
Chemical:				Quantity:	
Equipments Used					
<input checked="" type="checkbox"/> Submersibel Pump	<input checked="" type="checkbox"/> High/low Pressure Jet	<input checked="" type="checkbox"/> Extension Cords	<input checked="" type="checkbox"/> LED Lights		
<input checked="" type="checkbox"/> Foot Bath	<input checked="" type="checkbox"/> Ladder	<input checked="" type="checkbox"/> Ventilating Fan	<input checked="" type="checkbox"/> Oxygen Meter		
<input checked="" type="checkbox"/> Vacuum Cleaner	<input checked="" type="checkbox"/> Cleaning Materials	<input checked="" type="checkbox"/> Suction/Discharge Hoses			
Last Cleaning Date		Current Cleaning Date		Next Cleaning Date	
-		10 September 2019		10 March 2020	
Crystalline Representative			Customer Representative		
					

Sintex Water Tank 2

Before Photo



After Photo



Before Photo



After Photo



Water tank cleaned and disinfected

CRYSTALLINE CLEANING & ENVIRONMENTAL SERVICES

WATER TANK CLEANING & DISINFECTION

CLIENT NAME : FOOD WORLD
CONTACT PERSON : MR. KARUNAKAR
DESIGNATION : ACCOUNTANT
SITE DETAILS : FOODWORLD RESTAURANT, AL AIN
DETAILS : WATER TANK CLEANING & DISINFECTION
DATE OF CLEANING : 10 SEPTEMBER 2019
FREQUENCY OF CLEANING : HALF YEARLY
DATE OF NEXT CLEANING : 10 MARCH 2020

The above water tanks were cleaned and disinfected in accordance with the Code of Practice for the inspection and cleaning of customer water storage tanks.



Tasman Pinto

CRYSTALLINE CLEANING AND ENVIRONMENTAL SERVICES