

**ENVIRONMENTAL
SERVICES FOR
A GREENER
TOMORROW...
ONE STEP AT
A TIME.**



Completion Report for

Sewage Tank/Lifting Station Cleaning

Date: **15 November 2019**
Client Name: **AL BAZZAM FACILITIES MANAGEMENT
GROUP**
Contact Person: **Mr. Prathyush**
Designation: **Site Engineer**
Site Detail: **Al Bateen Airport, Abu Dhabi.**





CRYSTALLINE ENVIROMENTAL SERVICES

2562

MANHOLE, GULLY TRAP, DRAINAGE - AFTER SERVICE REPORT

CUSTOMER: AL BAZZAM FM		CONTACT PERSON: PRATHYUSH V P	
SITE DETAILS: BATEEN AIRPORT		CONTACT NUMBER: 0555216284	
NAME OF MANHOLE: SEWAGE TANK		LOCALISQTION:	
TYPE OF BUILDING: <input checked="" type="checkbox"/> COMMERCIAL <input type="checkbox"/> EDUCATIONAL <input type="checkbox"/> RESIDENCIAL <input type="checkbox"/> INDUSTRIAL			
PART OF DRAINAGE			
<input checked="" type="checkbox"/> MANHOLE <input type="checkbox"/> UNDERGROUND DRAINAGE PIPE <input type="checkbox"/> GULLY TRAP <input type="checkbox"/> GREASE TRAP			
<input checked="" type="checkbox"/> DRAINAGE PIPE <input type="checkbox"/> APPARENT DRAINAGE PIPE <input type="checkbox"/> EMBEDDED DRAINAGE PIPE			
CONDITION OF MANHOLE, GULLY TRAP, DRAINAGE BEFORE CLEANING			
<input type="checkbox"/> LITTLE DIRTY <input checked="" type="checkbox"/> DIRTY <input type="checkbox"/> VERY DIRTY <input type="checkbox"/> RUST <input type="checkbox"/> SEDIMENTS <input checked="" type="checkbox"/> MUD			
<input type="checkbox"/> BIOFILMS <input type="checkbox"/> SLIME <input type="checkbox"/> GREASE <input type="checkbox"/> ROOT <input checked="" type="checkbox"/> SAND <input checked="" type="checkbox"/> MOULDS			
<input type="checkbox"/> OBSTRUCT <input type="checkbox"/> BLOCK <input type="checkbox"/> FLUENT FLOW <input type="checkbox"/> LOW FLOW <input type="checkbox"/> ANOTHER: _____			
MANHOLE BLOCKED		GULLY TRAP BLOCKED	
<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	
DRAINAGE BLOCKED		ALL BLOCKED	
<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	
COMMENTS:			
MANHOLE AND GULLY TRAP COVER: <input checked="" type="checkbox"/> COVERED <input type="checkbox"/> DAMAGED <input type="checkbox"/> BLOCKED <input type="checkbox"/> ADAPTED			
CONDITION OF MANHOLE, GULLY TRAP, DRAINAGE AFTER CLEANING			
<input type="checkbox"/> LITTLE CLEAN <input type="checkbox"/> CLEAN <input checked="" type="checkbox"/> VERY CLEAN <input checked="" type="checkbox"/> FLUENT FLOW <input type="checkbox"/> LOW FLOW <input type="checkbox"/> UNBLOCK			
	MANHOLE	GULLY TRAP	STORM WATER
NUMBER OF MANHOLE CLEANED			
NUMBER OF MANHOLE BLOCKED			
ACCESS			
<input checked="" type="checkbox"/> LADDER IN <input type="checkbox"/> NO LADDER			
MANHOLE CLEANED		GULLY TRAP CLEANED	
<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	
DRAINAGE CLEANED		ALL DISINFECTED	
<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO		<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	
SERVICES OF DATES			
LAST CLEANING DATE	CURRENT CLEANING DATE	NEXT CLEANING DATE	
	15-11-2019	14-11-2020	
CHEMICALS AND EQUIPMENTS USED			
<input type="checkbox"/> PRESSURE MACHINE <input type="checkbox"/> JETTING MACHINE <input type="checkbox"/> MULTIGAS DETECTEUR <input type="checkbox"/> INLET WATER HOSE			
<input type="checkbox"/> EXTENTION CORDS <input type="checkbox"/> VACCUM CLEANER <input type="checkbox"/> VENTILATION FAN <input type="checkbox"/> CLEANING MAT			
<input type="checkbox"/> LED LIGHTS <input type="checkbox"/> PLASTICS ROLL <input type="checkbox"/> PLASTICS BAGS <input type="checkbox"/> SUITABLE PPE			
<input type="checkbox"/> TRIPOD <input type="checkbox"/> AIR REPAIR 7D-A <input type="checkbox"/> DEGREASER CHEMICAL <input type="checkbox"/> LADDER			
COMMENTS AND RECOMMENDATION: Sewage tank cleaned and disinfection completed.			
Crystalline representative:		Signature:	
Customer/Customer representative: PRATHYUSH		Signature:	

Cleaning and Servicing of Sewage Tank

Before Photo



After Photo



Before Photo



After Photo



Cleaning and Servicing of Sewage Tank

CRYSTALLINE CLEANING & ENVIRONMENTAL SERVICES

CLEANING AND SERVICING OF SEWAGE TANKS

CLIENT NAME : AL BAZZAM FACILITIES MANAGEMENT GROUP
CONTACT PERSON : MR. PRATHYUSH
DESIGNATION : SITE ENGINEER
SITE DETAILS : AL BATEEN AIRPORT, ABU DHABI.
DETAILS : SEWAGE TANK/LIFTING STATION CLEANING
DATE OF CLEANING : 15 NOVEMBER 2019
FREQUENCY OF CLEANING : HALF YEARLY
DATE OF NEXT CLEANING : 15 NOVEMBER 2020

The above system is thoroughly cleaned and all the solids and debris removed and disposed.

Regular, preventive maintenance will ensure removal of solids which settle at the bottom, reducing its capacity and efficiency.



Tasman Pinto

CRYSTALLINE CLEANING AND ENVIRONMENTAL SERVICES