

**ENVIRONMENTAL
SERVICES FOR
A GREENER
TOMORROW...
ONE STEP AT
A TIME.**



Completion Report for

Kitchen Hood & Exhaust System Cleaning & Degreasing

Date: **25 January 2020**
Client Name: **Armed Forces Officers Club & Hotel**
Contact Person: **Ms. Shaikha Al Khaabi**
Designation: **CEO**
Site Detail: **PG Flight, Abu Dhabi.**





CRYSTALLINE ENVIROMENTAL SERVICES

KITCHEN EXHAUST SYSTEM - AFTER SERVICE REPORT

1868

| | | | |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--|-------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------|
| CUSTOMER: <u>AEOCH</u> | | CONTACT PERSON: <u>MR SAMEER</u> | |
| SITE DETAILS: <u>PG AIR FORCE</u> | | CONTACT NUMBER: | |
| NAME OF KITCHEN: <u>HOT KITCHEN</u> | | LOCATION: <u>GROUND FLOOR</u> | |
| TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL <input type="checkbox"/> HOTEL <input checked="" type="checkbox"/> RESIDENCIAL <input type="checkbox"/> RESTAURANT | | | |
| Type & Size of Hood: <u>4 MT DOUBLE HOOD</u> | | | |
| Cooking Volume: | | <input checked="" type="checkbox"/> Very High | <input type="checkbox"/> High <input type="checkbox"/> Medium <input type="checkbox"/> Low |
| Type of Filters: | | <input type="checkbox"/> Mesh <input checked="" type="checkbox"/> Baffle | <input type="checkbox"/> N/A |
| Filters in Place: | | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | <input type="checkbox"/> N/A |
| Filter Cleaning Freq. | | <input type="checkbox"/> Daily <input type="checkbox"/> Weekly <input type="checkbox"/> Monthly | <input checked="" type="checkbox"/> Not Known |
| Comments: | | | |
| FIRE PROTECTION SYSTEM | | | |
| Kitchen: | | <input checked="" type="checkbox"/> Powder <input checked="" type="checkbox"/> CO2 | <input type="checkbox"/> Foam <input checked="" type="checkbox"/> Other |
| Cooker Hoods: | | <input checked="" type="checkbox"/> CO2 <input checked="" type="checkbox"/> Sprinkler | <input type="checkbox"/> Dry Powder <input checked="" type="checkbox"/> Other |
| Fire Dampers: | | <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No | Fusible Links: <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No |
| DUCTWORK | | | |
| Duct Made of: | | <input checked="" type="checkbox"/> Galvanized Steel <input type="checkbox"/> Stainless Steel | <input type="checkbox"/> Other |
| Physical Entry: | | <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No | <input checked="" type="checkbox"/> Partly |
| Access with Tools only: | | <input type="checkbox"/> Yes <input type="checkbox"/> No | <input checked="" type="checkbox"/> Partly |
| Vertical Access: | | <input type="checkbox"/> Rope access <input checked="" type="checkbox"/> Safety Harness | <input type="checkbox"/> N/A |
| Entire System Cleaned | | <input type="checkbox"/> Yes <input type="checkbox"/> No if No, give details | |
| Comments: | | | |
| Doors/Plates Present: | | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | <input type="checkbox"/> No. of doors <input type="checkbox"/> No of Panels |
| Doors/Plates Installed: | | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | <input type="checkbox"/> No. of doors <input type="checkbox"/> No of Panels |
| Where Installed: | | | |
| Duct Size & Approx. Length: <u>5 MT</u> | | Insulated: <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | |
| Condition of Ducts: | | <input checked="" type="checkbox"/> Clean <input type="checkbox"/> Dirty | <input type="checkbox"/> Very Dirty |
| Damaged: | | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | <input type="checkbox"/> Where <input type="checkbox"/> N/A |
| Exhaust Fans: | | <input checked="" type="checkbox"/> Upblast <input type="checkbox"/> Inline | <input type="checkbox"/> Utility <input type="checkbox"/> Others |
| Location: <u>ROOF TOP</u> | | Condition of Roof: <u>NORMAL</u> | |
| LAST CLEANING DATE | | CURRENT CLEANING DATE | NEXT CLEANING DATE |
| | | <u>24-01-2020</u> | <u>23-01-2021</u> |
| CHEMICALS AND EQUIPMENTS USED | | | |
| <input type="checkbox"/> JETTING MACHINE <input type="checkbox"/> INLET WATER HOSE <input checked="" type="checkbox"/> EXTENTION CORDS <input type="checkbox"/> VACCUM CLEANER <input checked="" type="checkbox"/> LED LIGHTS <input checked="" type="checkbox"/> PLASTICS ROLL/BAGS <input checked="" type="checkbox"/> SUITABLE PPE <input checked="" type="checkbox"/> DEGREASER CHEMICAL <input type="checkbox"/> LADDER | | | |
| COMMENTS AND RECOMMENDATION: | | | |
| <u>KITCHEN HOOD DUCT & EXHAUST FAN CLEANING COMPLETED.</u> | | | |
| Crystalline Representative: <u>G. ANSARI</u> | | Signature: <u>[Signature]</u> | |
| Customer Representative: <u>SK RIYASAT</u> | | Signature: <u>Sa Riyasat</u> | |

RESIDENTIAL
2020

Date: 24-01-2020
 PO/PR Number: 2020/1100
 Invoice No. 2020/1100
 PR Number: 2020/1100
 Item Number: 2020/1100
 Price Verified: [Signature]
 Signature: [Signature]

CRYSTALLINE CLEANING & ENVIRONMENTAL SERVICES

KITCHEN HOOD CLEANING AND DEGREASING

CLIENT NAME : ARMED FORCES OFFICERS CLUB & HOTEL
CONTACT PERSON : MS. SHAIKHA AL KHAABI
DESIGNATION : CEO
SITE DETAILS : PG FLIGHT, ABU DHABI.
DETAILS : KITCHEN HOOD & EXHAUST SYSTEM
CLEANING & DEGREASING
DATE OF CLEANING : 24 JANUARY 2020
FREQUENCY OF CLEANING : HALF YEARLY
DATE OF NEXT CLEANING : 23 JULY 2020

The above kitchen were cleaned in accordance with NFPA 96 Standard for Ventilation Control and Fire Protection of Commercial Cooking Operations.

The kitchen exhaust systems must be cleaned and degreased every Six-Monthly.



Tasman Pinto

CRYSTALLINE CLEANING AND ENVIRONMENTAL SERVICES