

**ENVIRONMENTAL
SERVICES FOR
A GREENER
TOMORROW...
ONE STEP AT
A TIME.**




Completion Report for

AC Duct Cleaning & Sanitization

Date: **24 October 2020**
Client Name: **Al Nasser Properties LLC**
Contact Person: **Mr.Mohammed Rafi**
Designation: **Senior Purchasing Officer**
Site Detail: **Saadiyat Tower- Abu Dhabi**



Address: PO BOX 131463, Abu Dhabi, UAE | Phone: +971 2 650 8930, +971 55 716 7017
E-mail: info@crystalline-uae.com | Website: www.crystalline-uae.com

Customer: Al Nasser Properties LLC		Contact Person: Mr. Mohammed Rafi	
Site: Saadiyat Tower - Abu Dhabi		Contact Number: -	
Description: AC Duct Cleaning & Sanitizing		Location: Saadiyat Tower	
Type Of Building: <input type="checkbox"/> Commercial <input checked="" type="checkbox"/> Residential <input type="checkbox"/> Others			
AIR CONDITIONING MACHINE			
Tilted Correctly <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No		Drip Tray Accessible <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	
Drip Tray <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No		Direct Drain <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	
Type Of AC <input type="checkbox"/> Package Unit <input type="checkbox"/> AHU <input checked="" type="checkbox"/> Fan Coil/Split unit		Condition of Drip Tray Cleaned <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Slime <input type="checkbox"/> mould <input type="checkbox"/> Rusty <input type="checkbox"/> Damage	
FILTERS		DUCT WORK	
Filters <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No		Physical Entry <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Partly	
Location of Filters <input type="checkbox"/> Duct <input checked="" type="checkbox"/> Machine		Access with Tools only <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Partly	
SUPPLY GRILLS			
Type of Grill <input type="checkbox"/> Square <input checked="" type="checkbox"/> Rectangle <input type="checkbox"/> Slot <input type="checkbox"/> Round		Fresh Air Inlet <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Open <input type="checkbox"/> Closed	
Return Air <input type="checkbox"/> Ducts <input checked="" type="checkbox"/> Cavity		Flow Dumpers <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	
Damaged <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		Sensors <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	
Internal Acoustic Insulat <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No		External Insulation <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	
Covering Insulation <input type="checkbox"/> Canvas <input type="checkbox"/> Aluminum <input checked="" type="checkbox"/> Others		Sanitization of Ducts <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	
Door / Plates Fitted <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No How Many:		Type <input type="checkbox"/> Polystyrene <input type="checkbox"/> Rockwood <input checked="" type="checkbox"/> Foam	
Ducts Damaged <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No Where:		Door / Plates Present <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No How Many:	
		Entire System Cleaned <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No If NO details: 2 nos	
		Where Installed	
		Duct Size and Approximate Length 2.0 meters	
Chemicals Used			
Chemical: Sanitizer		Quantity: 1.5 liter	
Last Cleaning Date -		Current Cleaning Date 24 October 2020	Next Cleaning Date 24 October 2021
Crystalline Representative		Customer Representative	
			



AC Duct Cleaning & Sanitizing

Before Photo



After Photo



Before Photo



After Photo



AC Duct Cleaned and Sanitized

AC Duct Cleaning & Sanitizing

Before Photo




After Photo



Before Photo



After Photo



AC Duct Cleaned and Sanitized

AC Duct Cleaning & Sanitizing


Before Photo



After Photo



Before Photo



After Photo



AC Duct Cleaned and Sanitized

AC Duct Cleaning & Sanitizing

Before Photo



After Photo



Before Photo



After Photo



AC Duct Cleaned and Sanitized

CRYSTALLINE CLEANING & ENVIRONMENTAL SERVICES

AC DUCT CLEANING & SANITIZING

CLIENT NAME : AL NASSER PROPERTIES LLC
CONTACT PERSON : MR. MOHAMMED RAFI
DESIGNATION : SENIOR PURCHASING OFFICER
SITE DETAILS : SAADIYAT TOWER- ABU DHABI
DETAILS : AC DUCT CLEANING & SANITIZING
DATE OF CLEANING : 24 OCTOBER 2020
FREQUENCY OF CLEANING : YEARLY
DATE OF NEXT CLEANING : 24 OCTOBER 2021

The HVAC system was cleaned and sanitized in accordance with NADCA ACR 2013 Standards for the HVAC Inspection, Cleaning and Restoration Association.



Tasmans Pinto

CRYSTALLINE CLEANING AND ENVIRONMENTAL SERVICES