

SUMP PIT, MANHOLES & DRAINLINE CLEANING

COMPLETION REPORT

For

Dusit Thani
ABU DHABI

Client : Dusit Thani Abu Dhabi
Contact Person: Mr. Prynzes Bumatay
Engineer Coordinator
Site Details : Dusit Thani Hotel,
Abu Dhabi, UAE.
Date : 08 April 2019

**Crystalline environmental
services**

P.O. Box 131463, Abu Dhabi, U.A.E.

Tel: 02 6508930 Fax: 02 6508942

info@crystalline-uae.com

www.crystalline-uae.com



CRYSTALLINE
ENVIRONMENTAL SERVICES



CRYSTALLINE ENVIRONMENTAL SERVICES

1412

MANHOLE, GULLY TRAP, DRAINAGE - AFTER SERVICE REPORT

CUSTOMER: DUSIT THANI HOTEL	CONTACT PERSON: MR. SAJU
SITE DETAILS: DUSIT THANI	CONTACT NUMBER: 02-6988313
NAME OF MANHOLE: PARKING	LOCALISATION: B.3
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL <input type="checkbox"/> EDUCATIONAL <input checked="" type="checkbox"/> RESIDENCIAL <input type="checkbox"/> INDUSTRIAL	

PART OF DRAINAGE

MANHOLE UNDERGROUND DRAINAGE PIPE GULLY TRAP GREASE TRAP

DRAINAGE PIPE APPARENT DRAINAGE PIPE EMBEDDED DRAINAGE PIPE

CONDITION OF MANHOLE, GULLY TRAP, DRAINAGE BEFORE CLEANING

LITTLE DIRTY DIRTY VERY DIRTY RUST SEDIMENTS MUD

BIOFILMS SLIME GREASE ROOT SAND MOULDS

OBSTRUCT BLOCK FLUENT FLOW LOW FLOW ANOTHER: _____

MANHOLE BLOCKED	GULLY TRAP BLOCKED	DRAINAGE BLOCKED	ALL BLOCKED
<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO			

COMMENTS: MANHOLE CLEANED. ALL PIPELINES CLEANED.

MANHOLE AND GULLY TRAP COVER: COVERED DAMAGED BLOCKED ADAPTED

CONDITION OF MANHOLE, GULLY TRAP, DRAINAGE AFTER CLEANING

LITTLE CLEAN CLEAN VERY CLEAN FLUENT FLOW LOW FLOW UNBLOCK

	MANHOLE	GULLY TRAP	STORM WATER	DRAINAGE	TOTAL
NUMBER OF MANHOLE CLEANED	21				
NUMBER OF MANHOLE BLOCKED					

ACCESS

LADDER IN NO LADDER

MANHOLE CLEANED	GULLY TRAP CLEANED	DRAINAGE CLEANED	ALL DISINFECTED
<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO

SERVICES OF DATES

LAST CLEANING DATE	LAST CLEANING DATE	LAST CLEANING DATE
	01-04-2019	01-04-2020

CHEMICALS AND EQUIPMENTS USED

PRESSURE MACHINE JETTING MACHINE MULTIGAS DETECTEUR INLET WATER HOSE

EXTENTION CORDS VACCUM CLEANER VENTILATION FAN CLEANING MAT

LED LIGHTS PLASTICS ROLL PLASTICS BAGS SUITABLE PPE

TRIPOD AIR REPAIR 7D-A DEGREASER CHEMICAL LADDER

COMMENTS AND RECOMMENDATION: 21 NOS. MANHOLE CLEANING & PIPELINES CLEANING FLASHING COMPLETED.

Crystalline representative: KANSARI	Signature: [Signature]
Customer/Customer representative: Pradeep	Signature: [Signature]

Date of Cleaning: 01-04-2019

PHOTOGRAPHS
MANHOLE CLEANING & PIPELINES FLUSHING- DUSIT THANI HOTEL

BEFORE CLEANING



AFTER CLEANING



CLEANER WATER GREENER TOMORROW



Date of Cleaning: 01-04-2019

PHOTOGRAPHS
MANHOLE CLEANING & PIPELINES FLUSHING- (DUSIT THANI HOTEL)

BEFORE CLEANING



AFTER CLEANING





CRYSTALLINE
ENVIRONMENTAL SERVICES

Date of Cleaning: 01-04-2019

PHOTOGRAPHS
MANHOLE CLEANING & PIPELINES FLUSHING- (DUSIT THANI HOTEL)

BEFORE CLEANING



AFTER CLEANING



CLEANER WATER GREENER TOMORROW

Date of Cleaning: 01-04-2019

PHOTOGRAPHS
MANHOLE CLEANING & PIPELINES FLUSHING- (DUSIT THANI HOTEL)

BEFORE CLEANING



AFTER CLEANING





CRYSTALLINE ENVIRONMENTAL SERVICES

1413

MANHOLE, GULLY TRAP, DRAINAGE - AFTER SERVICE REPORT

CUSTOMER: DUSIT THANI HOTEL	CONTACT PERSON: MR. SAJU
SITE DETAILS: DUSIT THANI	CONTACT NUMBER: 02 6988313
NAME OF MANHOLE: SUMPIT NO. 1	LOCALISATION: B13
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL <input type="checkbox"/> EDUCATIONAL <input checked="" type="checkbox"/> RESIDENCIAL <input type="checkbox"/> INDUSTRIAL	

PART OF DRAINAGE

MANHOLE UNDERGROUND DRAINAGE PIPE GULLY TRAP GREASE TRAP

DRAINAGE PIPE APPARENT DRAINAGE PIPE EMBEDDED DRAINAGE PIPE

CONDITION OF MANHOLE, GULLY TRAP, DRAINAGE BEFORE CLEANING

LITTLE DIRTY DIRTY VERY DIRTY RUST SEDIMENTS MUD

BIOFILMS SLIME GREASE ROOT SAND MOULDS

OBSTRUCT BLOCK FLUENT FLOW LOW FLOW ANOTHER: _____

MANHOLE BLOCKED	GULLY TRAP BLOCKED	DRAINAGE BLOCKED	ALL BLOCKED
<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO			

COMMENTS: 1x1x2 SUMPIT 1 NOS CLEANED

MANHOLE AND GULLY TRAP COVER: COVERED DAMAGED BLOCKED ADAPTED

CONDITION OF MANHOLE, GULLY TRAP, DRAINAGE AFTER CLEANING

LITTLE CLEAN CLEAN VERY CLEAN FLUENT FLOW LOW FLOW UNBLOCK

	MANHOLE	GULLY TRAP	STORM WATER	DRAINAGE	TOTAL
NUMBER OF MANHOLE CLEANED					
NUMBER OF MANHOLE BLOCKED					

ACCESS

LADDER IN NO LADDER

MANHOLE CLEANED	GULLY TRAP CLEANED	DRAINAGE CLEANED	ALL DISINFECTED
<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO

SERVICES OF DATES

LAST CLEANING DATE	LAST CLEANING DATE	LAST CLEANING DATE
	02-04-2019	02-04-2020

CHEMICALS AND EQUIPMENTS USED

PRESSURE MACHINE JETTING MACHINE MULTIGAS DETECTEUR INLET WATER HOSE

EXTENTION CORDS VACCUM CLEANER VENTILATION FAN CLEANING MAT

LED LIGHTS PLASTICS ROLL PLASTICS BAGS SUITABLE PPE

TRIPOD AIR REPAIR 7D-A DEGREASER CHEMICAL LADDER

COMMENTS AND RECOMMENDATION: SUMPIT CLEANING & DISINFECTION COMPLETED

Crystalline representative: KANSARI	Signature:
Customer/Customer representative: Pradeep	Signature:

Date of Cleaning: 02-04-2019

PHOTOGRAPHS
SUMP PIT CLEANING – 01 (DUSIT THANI HOTEL)

BEFORE CLEANING



AFTER CLEANING



CLEANER WATER GREENER TOMORROW



CRYSTALLINE ENVIRONMENTAL SERVICES

1416

MANHOLE, GULLY TRAP, DRAINAGE - AFTER SERVICE REPORT

CUSTOMER: DUSIT THANI HOTEL	CONTACT PERSON: MR-SATV
SITE DETAILS: DUSIT THANI	CONTACT NUMBER: 02-6982313
NAME OF MANHOLE: SUMPIT NO: 2	LOCALISQTION: B.3
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL <input type="checkbox"/> EDUCATIONAL <input checked="" type="checkbox"/> RESIDENCIAL <input type="checkbox"/> INDUSTRIAL	

PART OF DRAINAGE

MANHOLE UNDERGROUND DRAINAGE PIPE GULLY TRAP GREASE TRAP

DRAINAGE PIPE APPARENT DRAINAGE PIPE EMBEDDED DRAINAGE PIPE

CONDITION OF MANHOLE, GULLY TRAP, DRAINAGE BEFORE CLEANING

LITTLE DIRTY DIRTY VERY DIRTY RUST SEDIMENTS MUD

BIOFILMS SLIME GREASE ROOT SAND MOULDS

OBSTRUCT BLOCK FLUENT FLOW LOW FLOW ANOTHER: _____

MANHOLE BLOCKED	GULLY TRAP BLOCKED	DRAINAGE BLOCKED	ALL BLOCKED
<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO			

COMMENTS: SUMPIT SIZE: 1x1x2 - NOT CLEANED

MANHOLE AND GULLY TRAP COVER: COVERED DAMAGED BLOCKED ADAPTED

CONDITION OF MANHOLE, GULLY TRAP, DRAINAGE AFTER CLEANING

LITTLE CLEAN CLEAN VERY CLEAN FLUENT FLOW LOW FLOW UNBLOCK

	MANHOLE	GULLY TRAP	STORM WATER	DRAINAGE	TOTAL
NUMBER OF MANHOLE CLEANED			1		
NUMBER OF MANHOLE BLOCKED					

ACCESS

LADDER IN NO LADDER

MANHOLE CLEANED	GULLY TRAP CLEANED	DRAINAGE CLEANED	ALL DISINFECTED
<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO

SERVICES OF DATES

LAST CLEANING DATE	LAST CLEANING DATE	LAST CLEANING DATE
	02-04-2019	02-04-2020

CHEMICALS AND EQUIPMENTS USED

PRESSURE MACHINE JETTING MACHINE MULTIGAS DETECTEUR INLET WATER HOSE

EXTENTION CORDS VACCUM CLEANER VENTILATION FAN CLEANING MAT

LED LIGHTS PLASTICS ROLL PLASTICS BAGS SUITABLE PPE

TRIPOD AIR REPAIR 7D-A DEGREASER CHEMICAL LADDER

COMMENTS AND RECOMMENDATION: SUMPIT CLEANING & DISINFECTION COMPLETED.


Crystalline representative: ICANDARI	Signature:
Customer/Customer representative: Paradise	Signature:



Date of Cleaning: 02-04-2019

PHOTOGRAPHS
SUMP PIT CLEANING – 02 (DUSIT THANI HOTEL)

BEFORE CLEANING



AFTER CLEANING





CRYSTALLINE ENVIRONMENTAL SERVICES

1417

MANHOLE, GULLY TRAP, DRAINAGE - AFTER SERVICE REPORT

CUSTOMER: DUSIT THANI HOTEL	CONTACT PERSON: MR. SAJU
SITE DETAILS: DUSIT THANI	CONTACT NUMBER: 02-6988313
NAME OF MANHOLE: SUMPIT NO: 3	LOCALISQTION:
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL <input type="checkbox"/> EDUCATIONAL <input checked="" type="checkbox"/> RESIDENCIAL <input type="checkbox"/> INDUSTRIAL	

PART OF DRAINAGE

MANHOLE UNDERGROUND DRAINAGE PIPE GULLY TRAP GREASE TRAP

DRAINAGE PIPE APPARENT DRAINAGE PIPE EMBEDDED DRAINAGE PIPE

CONDITION OF MANHOLE, GULLY TRAP, DRAINAGE BEFORE CLEANING

LITTLE DIRTY DIRTY VERY DIRTY RUST SEDIMENTS MUD

BIOFILMS SLIME GREASE ROOT SAND MOULDS

OBSTRUCT BLOCK FLUENT FLOW LOW FLOW ANOTHER: _____

MANHOLE BLOCKED	GULLY TRAP BLOCKED	DRAINAGE BLOCKED	ALL BLOCKED
<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO			

COMMENTS: SUMPIT SIZE: 1x1x2 INOS CLEANED

MANHOLE AND GULLY TRAP COVER: COVERED DAMAGED BLOCKED ADAPTED

CONDITION OF MANHOLE, GULLY TRAP, DRAINAGE AFTER CLEANING

LITTLE CLEAN CLEAN VERY CLEAN FLUENT FLOW LOW FLOW UNBLOCK

	MANHOLE	GULLY TRAP	STORM WATER	DRAINAGE	TOTAL
NUMBER OF MANHOLE CLEANED			1		
NUMBER OF MANHOLE BLOCKED					

ACCESS

LADDER IN NO LADDER

MANHOLE CLEANED	GULLY TRAP CLEANED	DRAINAGE CLEANED	ALL DISINFECTED
<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO

SERVICES OF DATES

LAST CLEANING DATE	LAST CLEANING DATE	LAST CLEANING DATE
	03-04-2019	03-04-2020

CHEMICALS AND EQUIPMENTS USED

PRESSURE MACHINE JETTING MACHINE MULTIGAS DETECTEUR INLET WATER HOSE

EXTENTION CORDS VACCUM CLEANER VENTILATION FAN CLEANING MAT

LED LIGHTS PLASTICS ROLL PLASTICS BAGS SUITABLE PPE

TRIPOD AIR REPAIR 7D-A DEGREASER CHEMICAL LADDER

COMMENTS AND RECOMMENDATION: SUMPIT CLEANING & DISINFECTION COMPLETED.

Crystalline representative: LEANBARI	Signature:
Customer/Customer representative: Pradeep	Signature:

Date of Cleaning: 03-04-2019

PHOTOGRAPHS
SUMP PIT CLEANING – 03 (DUSIT THANI HOTEL)

BEFORE CLEANING



AFTER CLEANING





CRYSTALLINE ENVIRONMENTAL SERVICES

1418

MANHOLE, GULLY TRAP, DRAINAGE - AFTER SERVICE REPORT

CUSTOMER: DUSIT THANI HOTEL		CONTACT PERSON: MR-SAJU	
SITE DETAILS: DUSIT THANI		CONTACT NUMBER: 02-6988313	
NAME OF MANHOLE: SUMPIT NO. 4		LOCALISATION: B, 3	
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL <input type="checkbox"/> EDUCATIONAL <input checked="" type="checkbox"/> RESIDENCIAL <input type="checkbox"/> INDUSTRIAL			
PART OF DRAINAGE			
<input checked="" type="checkbox"/> MANHOLE <input checked="" type="checkbox"/> UNDERGROUND DRAINAGE PIPE <input type="checkbox"/> GULLY TRAP <input type="checkbox"/> GREASE TRAP			
<input type="checkbox"/> DRAINAGE PIPE <input type="checkbox"/> APPARENT DRAINAGE PIPE <input type="checkbox"/> EMBEDDED DRAINAGE PIPE			
CONDITION OF MANHOLE, GULLY TRAP, DRAINAGE BEFORE CLEANING			
<input type="checkbox"/> LITTLE DIRTY <input type="checkbox"/> DIRTY <input checked="" type="checkbox"/> VERY DIRTY <input type="checkbox"/> RUST <input type="checkbox"/> SEDIMENTS <input type="checkbox"/> MUD			
<input type="checkbox"/> BIOFILMS <input type="checkbox"/> SLIME <input type="checkbox"/> GREASE <input type="checkbox"/> ROOT <input checked="" type="checkbox"/> SAND <input type="checkbox"/> MOULDS			
<input type="checkbox"/> OBSTRUCT <input type="checkbox"/> BLOCK <input type="checkbox"/> FLUENT FLOW <input checked="" type="checkbox"/> LOW FLOW <input type="checkbox"/> ANOTHER: _____			
MANHOLE BLOCKED		GULLY TRAP BLOCKED	
<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	
DRAINAGE BLOCKED		ALL BLOCKED	
<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	
COMMENTS: SUMPIT SIZE: 1X1X2 1 NOS CLEANED			
MANHOLE AND GULLY TRAP COVER: <input checked="" type="checkbox"/> COVERED <input type="checkbox"/> DAMAGED <input type="checkbox"/> BLOCKED <input type="checkbox"/> ADAPTED			
CONDITION OF MANHOLE, GULLY TRAP, DRAINAGE AFTER CLEANING			
<input type="checkbox"/> LITTLE CLEAN <input type="checkbox"/> CLEAN <input checked="" type="checkbox"/> VERY CLEAN <input checked="" type="checkbox"/> FLUENT FLOW <input type="checkbox"/> LOW FLOW <input checked="" type="checkbox"/> UNBLOCK			
	MANHOLE	GULLY TRAP	STORM WATER
NUMBER OF MANHOLE CLEANED			1
NUMBER OF MANHOLE BLOCKED			
ACCESS			
<input checked="" type="checkbox"/> LADDER IN <input type="checkbox"/> NO LADDER			
MANHOLE CLEANED		GULLY TRAP CLEANED	
<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO		<input type="checkbox"/> YES <input type="checkbox"/> NO	
DRAINAGE CLEANED		ALL DISINFECTED	
<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO		<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	
SERVICES OF DATES			
LAST CLEANING DATE	LAST CLEANING DATE	LAST CLEANING DATE	
	03-04-2019	03-04-2020	
CHEMICALS AND EQUIPMENTS USED			
<input checked="" type="checkbox"/> PRESSURE MACHINE <input checked="" type="checkbox"/> JETTING MACHINE <input checked="" type="checkbox"/> MULTIGAS DETECTEUR <input checked="" type="checkbox"/> INLET WATER HOSE			
<input checked="" type="checkbox"/> EXTENTION CORDS <input checked="" type="checkbox"/> VACCUM CLEANER <input checked="" type="checkbox"/> VENTILATION FAN <input checked="" type="checkbox"/> CLEANING MAT			
<input checked="" type="checkbox"/> LED LIGHTS <input checked="" type="checkbox"/> PLASTICS ROLL <input checked="" type="checkbox"/> PLASTICS BAGS <input checked="" type="checkbox"/> SUITABLE PPE			
<input type="checkbox"/> TRIPOD <input type="checkbox"/> AIR REPAIR 7D-A <input type="checkbox"/> DEGREASER CHEMICAL <input type="checkbox"/> LADDER			
COMMENTS AND RECOMMENDATION: SUMPIT CLEANING & DISINFECTION COMPLETED.			
Crystalline representative: K. ANSARI		Signature:	
Customer/Customer representative: Pradeep		Signature:	

Date of Cleaning: 03-04-2019

PHOTOGRAPHS
SUMP PIT CLEANING – 04 (DUSIT THANI HOTEL)

BEFORE CLEANING



AFTER CLEANING



CLEANER WATER GREENER TOMORROW



CRYSTALLINE ENVIRONMENTAL SERVICES

1419

MANHOLE, GULLY TRAP, DRAINAGE - AFTER SERVICE REPORT

CUSTOMER: DUSIT THANI HOTEL	CONTACT PERSON: MR. SAJU
SITE DETAILS: DUSIT THANI	CONTACT NUMBER: 02-6988313
NAME OF MANHOLE: SUMPIT NO: 5	LOCALISATION: B.3
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL <input type="checkbox"/> EDUCATIONAL <input checked="" type="checkbox"/> RESIDENCIAL <input type="checkbox"/> INDUSTRIAL	

PART OF DRAINAGE

MANHOLE UNDERGROUND DRAINAGE PIPE GULLY TRAP GREASE TRAP

DRAINAGE PIPE APPARENT DRAINAGE PIPE EMBEDDED DRAINAGE PIPE

CONDITION OF MANHOLE, GULLY TRAP, DRAINAGE BEFORE CLEANING

LITTLE DIRTY DIRTY VERY DIRTY RUST SEDIMENTS MUD

BIOFILMS SLIME GREASE ROOT SAND MOULDS

OBSTRUCT BLOCK FLUENT FLOW LOW FLOW ANOTHER: _____

MANHOLE BLOCKED	GULLY TRAP BLOCKED	DRAINAGE BLOCKED	ALL BLOCKED
<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO			

COMMENTS: Sumpit size: 2x2x2

MANHOLE AND GULLY TRAP COVER: COVERED DAMAGED BLOCKED ADAPTED

CONDITION OF MANHOLE, GULLY TRAP, DRAINAGE AFTER CLEANING

LITTLE CLEAN CLEAN VERY CLEAN FLUENT FLOW LOW FLOW UNBLOCK

	MANHOLE	GULLY TRAP	STORM WATER	DRAINAGE	TOTAL
NUMBER OF MANHOLE CLEANED			4		
NUMBER OF MANHOLE BLOCKED					

ACCESS

LADDER IN NO LADDER

MANHOLE CLEANED	GULLY TRAP CLEANED	DRAINAGE CLEANED	ALL DISINFECTED
<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO

SERVICES OF DATES

LAST CLEANING DATE	LAST CLEANING DATE	LAST CLEANING DATE
	04-04-2019	04-04-2020

CHEMICALS AND EQUIPMENTS USED

PRESSURE MACHINE JETTING MACHINE MULTIGAS DETECTEUR INLET WATER HOSE

EXTENTION CORDS VACCUM CLEANER VENTILATION FAN CLEANING MAT

LED LIGHTS PLASTICS ROLL PLASTICS BAGS SUITABLE PPE

TRIPOD AIR REPAIR 7D-A DEGREASER CHEMICAL LADDER


COMMENTS AND RECOMMENDATION: Sumpit cleaning & disinfection completed.

Crystalline representative: LIANSAKI	Signature:
Customer/Customer representative: Pradeep	Signature:

Date of Cleaning: 04-04-2019

PHOTOGRAPHS
SUMP PIT CLEANING – 05 (DUSIT THANI HOTEL)

BEFORE CLEANING



AFTER CLEANING



CLEANER WATER GREENER TOMORROW



CRYSTALLINE ENVIRONMENTAL SERVICES

1420

MANHOLE, GULLY TRAP, DRAINAGE - AFTER SERVICE REPORT

CUSTOMER: <u>DUSIT THANI HOTEL</u>	CONTACT PERSON: <u>MR: SAJU</u>
SITE DETAILS: <u>DUSIT THANI</u>	CONTACT NUMBER: <u>02-6988313</u>
NAME OF MANHOLE: <u>SUMPIT NO: 6</u>	LOCALISATION:
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL <input type="checkbox"/> EDUCATIONAL <input checked="" type="checkbox"/> RESIDENCIAL <input type="checkbox"/> INDUSTRIAL	

PART OF DRAINAGE

MANHOLE UNDERGROUND DRAINAGE PIPE GULLY TRAP GREASE TRAP

DRAINAGE PIPE APPARENT DRAINAGE PIPE EMBEDDED DRAINAGE PIPE

CONDITION OF MANHOLE, GULLY TRAP, DRAINAGE BEFORE CLEANING

LITTLE DIRTY DIRTY VERY DIRTY RUST SEDIMENTS MUD

BIOFILMS SLIME GREASE ROOT SAND MOULDS

OBSTRUCT BLOCK FLUENT FLOW LOW FLOW ANOTHER: _____

MANHOLE BLOCKED	GULLY TRAP BLOCKED	DRAINAGE BLOCKED	ALL BLOCKED
<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO			

COMMENTS: SUMPIT SIZE: (2x2x2) 1 NOS CLEANED.

MANHOLE AND GULLY TRAP COVER: COVERED DAMAGED BLOCKED ADAPTED

CONDITION OF MANHOLE, GULLY TRAP, DRAINAGE AFTER CLEANING

LITTLE CLEAN CLEAN VERY CLEAN FLUENT FLOW LOW FLOW UNBLOCK

	MANHOLE	GULLY TRAP	STORM WATER	DRAINAGE	TOTAL
NUMBER OF MANHOLE CLEANED			<u>1</u>		
NUMBER OF MANHOLE BLOCKED					

ACCESS

LADDER IN NO LADDER

MANHOLE CLEANED	GULLY TRAP CLEANED	DRAINAGE CLEANED	ALL DISINFECTED
<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO

SERVICES OF DATES

LAST CLEANING DATE	LAST CLEANING DATE	LAST CLEANING DATE
	<u>04-04-2019</u>	<u>04-04-2020</u>

CHEMICALS AND EQUIPMENTS USED

PRESSURE MACHINE JETTING MACHINE MULTIGAS DETECTEUR INLET WATER HOSE

EXTENTION CORDS VACCUM CLEANER VENTILATION FAN CLEANING MAT

LED LIGHTS PLASTICS ROLL PLASTICS BAGS SUITABLE PPE

TRIPOD AIR REPAIR 7D-A DEGREASER CHEMICAL LADDER

COMMENTS AND RECOMMENDATION: SUMPIT CLEANING & DISINFECTION COMPLETED.

Crystalline representative: <u>K. ANBARI</u>	Signature: <u>[Signature]</u>
Customer/Customer representative: <u>[Signature]</u>	Signature: <u>[Signature]</u>

CLEANER WATER GREENER TOMORROW

0502489905

Web: www.crystalline-uae.com
E-mail: info@crystalline-uae.com
Tel.: +971 55 7167017



CRYSTALLINE
ENVIRONMENTAL SERVICES

Date of Cleaning: 04-04-2019

PHOTOGRAPHS
SUMP PIT CLEANING – 06 (DUSIT THANI HOTEL)

BEFORE CLEANING



AFTER CLEANING



CLEANER WATER GREENER TOMORROW


CRYSTALLINE CLEANING & ENVIRONMENTAL SERVICES

CLEANING & DISINFECTION CERTIFICATE

CLIENT NAME : DUSIT THANI ABU DHABI.
CLIENT ADDRESS : P.O.BOX: 52799, ABU DHABI, UAE.
CONTACT PERSON : MR. PRYNZES BUMATAY.
SITE DETAILS : BASEMENT 3, DUSIT THANI HOTEL,
ABU DHABI, UAE.
DETAILS : MANHOLE & SUMP PIT CLEANING
DATE OF CLEANING : APRIL 2019
FREQUENCY OF CLEANING : EVERY ONE (1) YEAR
DATE OF NEXT CLEANING : APRIL 2020

The procedures employed in this cleaning and disinfection comply with Abu Dhabi Municipality guidelines

The entire Manhole & Sump Pit should be cleaned and disinfected minimum every Year depending upon the condition.



CRYSTALLINE CLEANING AND ENVIRONMENTAL SERVICES