


**ENVIRONMENTAL  
SERVICES FOR  
A GREENER  
TOMORROW...  
ONE STEP AT  
A TIME.**



Completion Report for

## **Water Tank Cleaning & Disinfection**

Date: **26 February 2020**  
Client Name: **Engineering Office**  
Contact Person: **Mr. Narayan MC**  
Designation: **MEP Supervisor**  
Site Detail: **FM-2073 - Dubai**





# CRYSTALLINE ENVIRONMENTAL SERVICES

## WATER TANK - AFTER SERVICE REPORT

17671

CUSTOMER: <u>EO 2073</u>		CONTACT PERSON: <u>Mr: Muzali</u>	
SITE DETAILS: <u>shk Harodan</u> <u>AL Manara Villa Dubai</u>		CONTACT NO: <u>052-6928472</u>	
TANK DETAILS: <u>GRP water Tank-1</u>		LOCATION DETAILS: <u>Basement-1</u>	
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL		<input checked="" type="checkbox"/> RESIDENTIAL <input type="checkbox"/> OTHERS	
<b>TYPE OF TANK</b>			
<input type="checkbox"/> CONCRETE	<input checked="" type="checkbox"/> GRP PANEL	<input type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED
<input type="checkbox"/> CONCRETE COATED	<input type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS	<input type="checkbox"/> STEEL PANEL <input type="checkbox"/> PLASTIC
SIZE OF TANK <u>4000 GEN</u>		QUANTITY OF WATER	
M3	USG	L*B*H	<input type="checkbox"/> FULL <input checked="" type="checkbox"/> HALF <input type="checkbox"/> EMPTY
<b>CONDITION OF WATER TANK BEFORE CLEANING</b>		<b>CONDITION OF WATER TANK AFTER CLEANING</b>	
<input type="checkbox"/> CLEAN	<input checked="" type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN
<input type="checkbox"/> BIOFILMS	<input checked="" type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> DIRTY <input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> BIOFILMS <input type="checkbox"/> MOULDS <input type="checkbox"/> SLIME
<b>ACCESS</b>		<b>MANHOLE</b>	<input type="checkbox"/> COVERED <input type="checkbox"/> DAMAGED <input type="checkbox"/> NA
<b>LADDER IN</b>	<b>LADDER OUT</b>	<b>LEAKS</b>	<b>DRAIN LINE</b>
<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO
<b>TANK CLEANED</b>	<b>TANK DISINFECTED</b>	<b>PIPES DISINFECTED</b>	<b>VALVES</b>
<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO <input type="checkbox"/> NA	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO <input type="checkbox"/> NA
<b>LAST CLEANING DATE</b>	<b>CURRENT CLEANING DATE</b>	<b>NEXT CLEANING DATE</b>	
	<u>25/02/2020</u>	<u>25/08/2020</u>	
<b>CHEMICALS &amp; EQUIPMENTS USED</b>			
1. <u>Corda bio and plus</u> Quantity <u>200 ML</u>			
2. _____ Quantity _____			
<input checked="" type="checkbox"/> Submersibel Pump <input checked="" type="checkbox"/> High/Low Pressure Jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED Lights <input checked="" type="checkbox"/> Foot Bath <input checked="" type="checkbox"/> Ladder			
<input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Meter <input checked="" type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials			
<b>COMMENTS AND RECOMMENDATION:</b>			
<u>GRP water Tank Cleaning and Disinfected</u>			
Crystalline representative: <u>Bishel Raj</u>		Signature: <u>[Signature]</u>	
Customer/Customer representative:		Signature:	



# CRYSTALLINE ENVIRONMENTAL SERVICES

## WATER TANK - AFTER SERVICE REPORT

17670

CUSTOMER: <u>EO 2073</u>			CONTACT PERSON: <u>Mr: Murali</u>		
SITE DETAILS: <u>Shk Hamdan Al Manara Villa Dubai</u>			CONTACT NO: <u>0526028072</u>		
TANK DETAILS: <u>Sintex Chilar water Tank</u>			LOCATION DETAILS: <u>Basement-1</u>		
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL <input checked="" type="checkbox"/> RESIDENTIAL <input type="checkbox"/> OTHERS					
<u>TYPE OF TANK</u>					
<input type="checkbox"/> CONCRETE	<input type="checkbox"/> GRP PANEL	<input checked="" type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED		<input type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS		
<u>SIZE OF TANK</u> <u>200 Gall</u>			<u>QUANTITY OF WATER</u>		
M3	USG	L*B*H	<input type="checkbox"/> FULL	<input checked="" type="checkbox"/> HALF	<input type="checkbox"/> EMPTY
<u>CONDITION OF WATER TANK BEFORE CLEANING</u>			<u>CONDITION OF WATER TANK AFTER CLEANING</u>		
<input type="checkbox"/> CLEAN	<input checked="" type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input checked="" type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
<u>ACCESS</u>		<u>MANHOLE</u>			
<input type="checkbox"/> COVERED		<input type="checkbox"/> DAMAGED		<input type="checkbox"/> NA	
<u>LADDER IN</u>	<u>LADDER OUT</u>	<u>LEAKS</u>	<u>DRAIN LINE</u>	<u>VALVES</u>	<u>FLOAT VALVE</u>
<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO
<u>TANK CLEANED</u>		<u>TANK DISINFECTED</u>		<u>PIPES DISINFECTED</u>	
<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO		<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO		<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO <input type="checkbox"/> NA	
<u>LAST CLEANING DATE</u>		<u>CURRENT CLEANING DATE</u>		<u>NEXT CLEANING DATE</u>	
		<u>25/02/2020</u>		<u>25/08/2020</u>	
<u>CHEMICALS &amp; EQUIPMENTS USED</u>					
1. <u>Carda bio and plus</u> Quantity <u>100 ML</u>					
2. _____ Quantity _____					
<input checked="" type="checkbox"/> Submersibel Pump <input checked="" type="checkbox"/> High/Low Pressure Jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED Lights <input checked="" type="checkbox"/> Foot Bath <input checked="" type="checkbox"/> Ladder <input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Meter <input checked="" type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials					
<u>COMMENTS AND RECOMMENDATION:</u>					
<u>Sintex Chilar water Tank Cleaning and Disinfected</u>					
Crystalline representative: <u>Bishal Rai</u>			Signature: <u>[Signature]</u>		
Customer/Customer representative:			Signature:		



# CRYSTALLINE ENVIRONMENTAL SERVICES

17669

## WATER TANK - AFTER SERVICE REPORT

CUSTOMER: <i>FO 2073</i>			CONTACT PERSON: <i>Mr: Murali</i>		
SITE DETAILS: <i>shik Hamdan Al Manara Villa Dubai</i>			CONTACT NO: <i>0526978472</i>		
TANK DETAILS: <i>Rec Raw Water Tank-1</i>			LOCATION DETAILS: <i>Basement-1</i>		
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL		<input checked="" type="checkbox"/> RESIDENTIAL		<input type="checkbox"/> OTHERS	
<b>TYPE OF TANK</b>					
<input checked="" type="checkbox"/> CONCRETE	<input type="checkbox"/> GRP PANEL	<input type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED	<input type="checkbox"/> POLYURETHANE	<input type="checkbox"/> OTHERS			
SIZE OF TANK <i>8000 GLN</i>			QUANTITY OF WATER		
M3	USG	L*B*H	<input type="checkbox"/> FULL	<input checked="" type="checkbox"/> HALF	<input type="checkbox"/> EMPTY
CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK AFTER CLEANING		
<input type="checkbox"/> CLEAN	<input checked="" type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input checked="" type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
ACCESS		MANHOLE	<input type="checkbox"/> COVERED	<input type="checkbox"/> DAMAGED	<input type="checkbox"/> NA
LADDER IN	LADDER OUT	LEAKS	DRAIN LINE	VALVES	FLOAT VALVE
<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO
TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO <input type="checkbox"/> NA
LAST CLEANING DATE		CURRENT CLEANING DATE		NEXT CLEANING DATE	
		<i>25/02/2020</i>		<i>23/08/2020</i>	
<b>CHEMICALS &amp; EQUIPMENTS USED</b>					
1. <i>Coada bio and plus</i> Quantity <i>200 ML</i>					
2. _____ Quantity _____					
<input checked="" type="checkbox"/> Submersibel Pump <input checked="" type="checkbox"/> High/Low Pressure Jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED Lights <input checked="" type="checkbox"/> Foot Bath <input checked="" type="checkbox"/> Ladder <input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Meter <input checked="" type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials					
<b>COMMENTS AND RECOMMENDATION:</b>					
<i>Rec Raw water Tank cleaning and Disinfected</i>					
Crystalline representative: <i>Bishal Rai</i>			Signature: <i>[Signature]</i> <i>25/02/2020</i>		
Customer/Customer representative:			Signature:		

# CRYSTALLINE CLEANING & ENVIRONMENTAL SERVICES

## WATER TANK CLEANING & DISINFECTION

**CLIENT NAME** : ENGINEERING OFFICE  
**CONTACT PERSON** : MR. NARAYAN MC  
**DESIGNATION** : MEP SUPERVISOR  
**SITE DETAILS** : FM-2073 - DUBAI  
**DETAILS** : WATER TANK CLEANING & DISINFECTION  
**DATE OF CLEANING** : 25 FEBRUARY 2020  
**FREQUENCY OF CLEANING** : HALF YEARLY  
**DATE OF NEXT CLEANING** : 25 AUGUST 2020

*The above water tanks were cleaned and disinfected in accordance with the Code of Practice for the inspection and cleaning of customer water storage tanks.*



*Tasman Pinto*

**CRYSTALLINE CLEANING AND ENVIRONMENTAL SERVICES**