

**KITCHEN EXHAUST SYSTEM
CLEANING
&
DISINFECTION

COMPLETION REPORT**

For

THE ECLIPSE
BOUTIQUE SUITES

Client: THE ECLIPSE HOTEL APARTMENTS.
Contact Person: Mr. Abdul Malek
Site Details: The Eclipse Hotel Apartments,
Abu Dhabi, UAE.
Date: 20 December 2018



CRYSTALLINE
ENVIRONMENTAL SERVICES

**Crystalline environmental
services**

P.O. Box 131463, Abu Dhabi, U.A.E.

Tel: 02 6508930 Fax: 02 6508942

info@crystalline-uae.com

www.crystalline-uae.com



CRYSTALLINE ENVIROMENTAL SERVICES

KITCHEN EXHAUST SYSTEM - AFTER SERVICE REPORT

1012

CUSTOMER: <i>Eclipse Hotel</i>		CONTACT PERSON: <i>Mabe</i>	
SITE DETAILS: <i>The Eclipse Hotel Abu Dhabi</i>		CONTACT NUMBER: <i>055-708020</i>	
NAME OF KITCHEN: <i>main kitchen hood-1</i>		LOCATION: <i>level-19th Abu Dhabi</i>	
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL <input checked="" type="checkbox"/> HOTEL <input type="checkbox"/> RESIDENCIAL <input type="checkbox"/> RESTAURANT			
Type & Size of Hood: <i>Big kitchen hood-1</i>			
Cooking Volume:	<input checked="" type="checkbox"/> Very High	<input type="checkbox"/> High	<input type="checkbox"/> Medium <input type="checkbox"/> Low
Type of Filters:	<input checked="" type="checkbox"/> Mesh	<input type="checkbox"/> Baffle	<input type="checkbox"/> N/A
Filters in Place:	<input type="checkbox"/> Yes	<input type="checkbox"/> No	<input type="checkbox"/> N/A
Filter Cleaning Freq.	<input type="checkbox"/> Daily	<input type="checkbox"/> Weekly	<input checked="" type="checkbox"/> Monthly <input type="checkbox"/> Not Known
Comments:			

FIRE PROTECTION SYSTEM

Kitchen:	<input type="checkbox"/> Powder	<input checked="" type="checkbox"/> CO2	<input type="checkbox"/> Foam	<input type="checkbox"/> Other
Cooker Hoods:	<input checked="" type="checkbox"/> CO2	<input type="checkbox"/> Sprinkler	<input type="checkbox"/> Dry Powder	<input type="checkbox"/> Other
Fire Dampers:	<input type="checkbox"/> Yes	<input type="checkbox"/> No	Fusible Links:	<input type="checkbox"/> Yes <input type="checkbox"/> No

DUCTWORK

Duct Made of:	<input type="checkbox"/> Galvanized Steel	<input checked="" type="checkbox"/> Stainless Steel	<input type="checkbox"/> Other
Physical Entry:	<input type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Partly
Access with Tools only:	<input type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Partly
Vertical Access:	<input type="checkbox"/> Rope access	<input type="checkbox"/> Safety Harness	<input checked="" type="checkbox"/> N/A
Entire System Cleaned	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No if No, give details	

Comments

Doors/Plates Present:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> No. of doors	<input checked="" type="checkbox"/> No of Panels
Doors/Plates Installed:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	<input checked="" type="checkbox"/> No. of doors	<input checked="" type="checkbox"/> No of Panels

Where Installed:

Duct Size & Approx. Length:	Insulated:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Condition of Ducts:	<input type="checkbox"/> Clean	<input checked="" type="checkbox"/> Dirty	<input type="checkbox"/> Very Dirty
Damaged:	<input checked="" type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	<input type="checkbox"/> Where <input type="checkbox"/> N/A
Exhaust Fans:	<input checked="" type="checkbox"/> Upblast	<input type="checkbox"/> Inline	<input type="checkbox"/> Utility <input type="checkbox"/> Others

Location: *Roof Top Abu Dhabi* Condition of Roof:

LAST CLEANING DATE	CURRENT CLEANING DATE	NEXT CLEANING DATE
	<i>15-12-2018</i>	<i>13-06-2019</i>

CHEMICALS AND EQUIPMENTS USED

<input checked="" type="checkbox"/> JETTING MACHINE	<input checked="" type="checkbox"/> INLET WATER HOSE	<input checked="" type="checkbox"/> EXTENTION CORDS	<input checked="" type="checkbox"/> VACCUM CLEANER
<input checked="" type="checkbox"/> LED LIGHTS	<input checked="" type="checkbox"/> PLASTICS ROLL/BAGS	<input checked="" type="checkbox"/> SUITABLE PPE	<input checked="" type="checkbox"/> DEGREASER CHEMICAL
<input checked="" type="checkbox"/> LADDER			

COMMENTS AND RECOMMENDATION:

Kitchen hood cleaned and dat cleaned disinfected

Crystalline Representative: <i>Bishal Rai</i>	Signature: <i>Bishal Rai</i>
Customer Representative: <i>Shripa</i>	Signature: <i>Shripa</i>



CRYSTALLINE
ENVIRONMENTAL SERVICES



Date of Cleaning: 13-12-2018

PHOTOGRAPHS
KITCHEN HOOD CLEANING- ECLIPSE HOTEL

BEFORE



AFTER



CLEANER WATER GREENER TOMORROW




CRYSTALLINE
ENVIRONMENTAL SERVICES


Date of Cleaning: 13-12-2018

PHOTOGRAPHS
KITCHEN HOOD CLEANING

BEFORE



AFTER



CLEANER WATER GREENER TOMORROW




CRYSTALLINE
ENVIRONMENTAL SERVICES


Date of Cleaning: 13-12-2018

PHOTOGRAPHS
KITCHEN HOOD CLEANING

BEFORE



AFTER



CLEANER WATER GREENER TOMORROW

Date of Cleaning: 13-12-2018

PHOTOGRAPHS
KITCHEN EXHAUST FAN & DUCT CLEANING

BEFORE



AFTER







CRYSTALLINE
ENVIRONMENTAL SERVICES


Date of Cleaning: 13-12-2018

PHOTOGRAPHS
KITCHEN EXHAUST FAN & DUCT CLEANING

BEFORE



AFTER



CLEANER WATER GREENER TOMORROW



METHODOLOGY:

- ✓ Preliminary site visit. To choose the effective procedure.
- ✓ Live Camera Inspection for the internal duct.
- ✓ Safety clothing/equipment required: overalls, safety boots, eye protection, gloves and correct respirators.
- ✓ Conduct safety briefing with client's representative to ensure all possible hazards are identified and reported immediately if assistance is required for the control of hazards.
- ✓ Ensure spill control Kit and fire extinguisher is available.
- ✓ Digital photo taken for the proof of cleaning process.
- ✓ Access holes in ducts shall be cut if required.
- ✓ Fans shall be isolated and warning labels should be placed on isolation switches.
- ✓ Areas of duct to be cleaned to bare metal.
- ✓ Toxic or flammable products shall not be used.
- ✓ Waste rags and lint will be disposed of in the client's waste disposal facilities.
- ✓ Record any areas unable to be cleaned giving exact reasons.

If you have any queries concerning our services, please contact: +971 2 6508930

Thank you for your business!

Crystalline Cleaning & Environmental Services

CRYSTALLINE CLEANING & ENVIRONMENTAL SERVICES

CLEANING & DISINFECTION CERTIFICATE

CLIENT NAME : THE ECLIPSE HOTEL APARTMENTS.
CLIENT ADDRESS : P.O BOX: 113499, ABU DHABI, UAE.
CONTACT PERSON : MR. ABDUL MALEK.
SITE DETAILS : THE ECLIPSE HOTEL APARTMENTS,
ABU DHABI, UAE.
DETAILS : KITCHEN EXHAUST SYSTEM CLEANING
DATE OF CLEANING : 13 DECEMBER 2018
FREQUENCY OF CLEANING : EVERY SIX (6) MONTHS
DATE OF NEXT CLEANING : 13 JUNE 2019

The procedures employed in this cleaning and disinfection comply with Abu Dhabi Municipality guidelines

The entire Kitchen Duct should be cleaned and disinfected minimum every six (6) months depending upon the condition.



CRYSTALLINE CLEANING AND ENVIRONMENTAL SERVICES