


# WATER TANK CLEANING & DISINFECTION

## COMPLETION REPORT

FOR



Client : FOOD WORLD

Contact Person: Mr. Raheem

Site Details : Food World Restaurant, Al Ain.

Date : 09 August 2018



**CRYSTALLINE**  
ENVIRONMENTAL SERVICES

CRYSTALLINE ENVIRONMENTAL  
SERVICES

P.O. BOX 131463, Abu Dhabi, U.A.E.

TEL: 02 6508930 FAX: 02 6508942

[info@crystalline-uae.com](mailto:info@crystalline-uae.com)

[www.crystalline-uae.com](http://www.crystalline-uae.com)





# CRYSTALLINE ENVIRONMENTAL SERVICES

## WATER TANK - AFTER SERVICE REPORT

15630

CUSTOMER: <b>FOOD WORLD RESTORANT</b>			CONTACT PERSON: <b>To, Mrs. Jeeva.</b>		
SITE DETAILS: <b>AL AIN</b>			CONTACT NO: <b>0557628760</b>		
TANK DETAILS: <b>SINTEX W. TANK 02</b>			LOCATION DETAILS: <b>ROOF TOP</b>		
TYPE OF BUILDING: <input checked="" type="checkbox"/> COMMERCIAL		<input type="checkbox"/> RESIDENTIAL		<input type="checkbox"/> OTHERS	
<b>TYPE OF TANK</b>					
<input type="checkbox"/> CONCRETE	<input type="checkbox"/> GRP PANEL	<input type="checkbox"/> FRP TANK	<input checked="" type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED		<input type="checkbox"/> POLYURETHANE		<input type="checkbox"/> OTHERS	
<b>SIZE OF TANK</b>			<b>QUANTITY OF WATER</b>		
M3	USG	L*B*H	<input type="checkbox"/> FULL	<input checked="" type="checkbox"/> HALF	<input type="checkbox"/> EMPTY
<b>CONDITION OF WATER TANK BEFORE CLEANING</b>			<b>CONDITION OF WATER TANK AFTER CLEANING</b>		
<input type="checkbox"/> CLEAN	<input checked="" type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input checked="" type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
<b>ACCESS</b>		<b>MANHOLE</b>		<input type="checkbox"/> COVERED	<input type="checkbox"/> DAMAGED
<input type="checkbox"/> NA					
<b>LADDER IN</b>		<b>LADDER OUT</b>		<b>LEAKS</b>	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO
<b>TANK CLEANED</b>		<b>TANK DISINFECTED</b>		<b>PIPES DISINFECTED</b>	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> YES	<input type="checkbox"/> NO <input checked="" type="checkbox"/> NA
<b>LAST CLEANING DATE</b>		<b>CURRENT CLEANING DATE</b>		<b>NEXT CLEANING DATE</b>	
		<b>29-07-2018</b>		<b>29-01-2019</b>	
<b>CHEMICALS &amp; EQUIPMENTS USED</b>					
1. <b>CARECO BPO</b> Quantity <b>600ML</b>					
2. <b>CARECO BPO plus</b> Quantity _____					
<input checked="" type="checkbox"/> Submersibel Pump <input checked="" type="checkbox"/> High/Low Pressure Jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED lights <input checked="" type="checkbox"/> Foot Bath <input checked="" type="checkbox"/> Ladder <input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Meter <input checked="" type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials					
<b>COMMENTS &amp; RECOMMENDATIONS:</b>					
<b>MENTIONED WATER TANK ARE CLEANED AND DISINFECTED</b>					
Crystalline Representative: <b>HARIS</b>			Signature: <b>HARIS</b>		



**CRYSTALLINE**  
ENVIRONMENTAL SERVICES



Date of Cleaning: 29-07-2018

**PHOTOGRAPHS**  
**GRP WATER TANK -02 (ROOFTOP)**

**BEFORE**



**AFTER**



**CLEANER WATER GREENER TOMORROW**



# CRYSTALLINE ENVIRONMENTAL SERVICES

## WATER TANK - AFTER SERVICE REPORT


15629

CUSTOMER: <u>FOOD WORLD RESTORENT</u>			CONTACT PERSON: <u>Ms. Tevan.</u>		
SITE DETAILS: <u>AL AIN</u>			CONTACT NO: <u>0557628960.</u>		
TANK DETAILS: <u>CINTEX W. TANK. 01</u>			LOCATION DETAILS: <u>ROOF TOP</u>		
TYPE OF BUILDING: <input checked="" type="checkbox"/> COMMERCIAL		<input type="checkbox"/> RESIDENTIAL		<input type="checkbox"/> OTHERS	
<b>TYPE OF TANK</b>					
<input type="checkbox"/> CONCRETE	<input type="checkbox"/> GRP PANEL	<input type="checkbox"/> FRP TANK	<input checked="" type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED		<input type="checkbox"/> POLYURETHANE		<input type="checkbox"/> OTHERS	
<b>SIZE OF TANK</b>			<b>QUANTITY OF WATER</b>		
M3	USG	L*B*H	<input type="checkbox"/> FULL	<input checked="" type="checkbox"/> HALF	<input type="checkbox"/> EMPTY
<b>CONDITION OF WATER TANK BEFORE CLEANING</b>			<b>CONDITION OF WATER TANK AFTER CLEANING</b>		
<input type="checkbox"/> CLEAN	<input checked="" type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input checked="" type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
<b>ACCESS</b>		<b>MANHOLE</b>		<input type="checkbox"/> COVERED	
<input type="checkbox"/> DAMAGED		<input type="checkbox"/> NA			
<b>LADDER IN</b>		<b>LADDER OUT</b>		<b>LEAKS</b>	
<b>DRAIN LINE</b>		<b>VALVES</b>		<b>FLOAT VALVE</b>	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> YES	<input type="checkbox"/> NO
<input type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO
<b>TANK CLEANED</b>		<b>TANK DISINFECTED</b>		<b>PIPES DISINFECTED</b>	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> YES	<input type="checkbox"/> NO <input checked="" type="checkbox"/> NA
<b>LAST CLEANING DATE</b>		<b>CURRENT CLEANING DATE</b>		<b>NEXT CLEANING DATE</b>	
		<u>29.07.2018</u>		<u>29.01.2019</u>	
<b>CHEMICALS &amp; EQUIPMENTS USED</b>					
1. <u>CARELO BIO</u> Quantity <u>500ML</u>					
2. <u>CARELO BIO plus</u> Quantity _____					
<input checked="" type="checkbox"/> Submersibel Pump <input checked="" type="checkbox"/> High/Low Pressure Jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED lights <input type="checkbox"/> Foot Bath <input checked="" type="checkbox"/> Ladder <input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Meter <input checked="" type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials					
<b>COMMENTS &amp; RECOMMENDATIONS:</b>					
<u>MENTIONED WATER TANK ARE CLEANED AND DISINFECTED</u>					
Crystalline Representative: <u>HARIS</u>			Signature: <u>[Signature]</u>		


Date of Cleaning: 29-07-2018

**PHOTOGRAPHS**  
**GRP WATER TANK 01 (ROOFTOP)**

**BEFORE**



**AFTER**





# CRYSTALLINE ENVIRONMENTAL SERVICES

## WATER TANK - AFTER SERVICE REPORT

15628

CUSTOMER: <u>FOOD WORLD RESTORANT</u>			CONTACT PERSON: <u>MR. JEEVAN</u>		
SITE DETAILS: <u>AL AIN</u>			CONTACT NO: <u>0557628760</u>		
TANK DETAILS: <u>R.C.W. TANK</u>			LOCATION DETAILS: <u>BASEMENT</u>		
TYPE OF BUILDING: <input checked="" type="checkbox"/> COMMERCIAL		<input type="checkbox"/> RESIDENTIAL		<input type="checkbox"/> OTHERS	
<b>TYPE OF TANK</b>					
<input checked="" type="checkbox"/> CONCRETE	<input type="checkbox"/> GRP PANEL	<input type="checkbox"/> FRP TANK	<input type="checkbox"/> GALVANIZED	<input type="checkbox"/> STEEL PANEL	<input type="checkbox"/> PLASTIC
<input type="checkbox"/> CONCRETE COATED		<input type="checkbox"/> POLYURETHANE		<input type="checkbox"/> OTHERS	
<b>SIZE OF TANK</b>			<b>QUANTITY OF WATER</b>		
M3	USG	L*B*H	<input type="checkbox"/> FULL	<input checked="" type="checkbox"/> HALF	<input type="checkbox"/> EMPTY
<b>CONDITION OF WATER TANK BEFORE CLEANING</b>			<b>CONDITION OF WATER TANK AFTER CLEANING</b>		
<input type="checkbox"/> CLEAN	<input checked="" type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME	<input type="checkbox"/> BIOFILMS	<input type="checkbox"/> MOULDS	<input type="checkbox"/> SLIME
<input type="checkbox"/> SEDIMENTS	<input checked="" type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST	<input type="checkbox"/> SEDIMENTS	<input type="checkbox"/> MUD & SAND	<input type="checkbox"/> RUST
<b>ACCESS</b>		<b>MANHOLE</b>		<input type="checkbox"/> COVERED	<input type="checkbox"/> DAMAGED
<input type="checkbox"/> NA					
<b>LADDER IN</b>		<b>LADDER OUT</b>		<b>LEAKS</b>	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO
<b>TANK CLEANED</b>		<b>TANK DISINFECTED</b>		<b>PIPES DISINFECTED</b>	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> YES	<input type="checkbox"/> NO <input checked="" type="checkbox"/> NA
<b>LAST CLEANING DATE</b>		<b>CURRENT CLEANING DATE</b>		<b>NEXT CLEANING DATE</b>	
		<u>29-07-2018</u>		<u>29.01.2019</u>	
<b>CHEMICALS &amp; EQUIPMENTS USED</b>					
1. <u>CARELO BIO</u> Quantity <u>500 ML</u>					
2. <u>CARELO BIO PLUS</u> Quantity _____					
<input checked="" type="checkbox"/> Submersibel Pump <input checked="" type="checkbox"/> High/Low Pressure Jet <input type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED lights <input checked="" type="checkbox"/> Foot Bath <input type="checkbox"/> Ladder <input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Suction/Discharge Hoses <input type="checkbox"/> Oxygen Meter <input type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials					
<b>COMMENTS &amp; RECOMMENDATIONS:</b>					
<u>MENTIONED WATER TANK ARE CLEANED AND DISINFECTED</u>					
Crystalline Representative: <u>HARIS</u>			Signature: <u>HARIS</u>		

Jeevan




**CRYSTALLINE**  
ENVIRONMENTAL SERVICES

Date of Cleaning: 29-07-2018

**PHOTOGRAPHS**  
**RCC WATER TANK**

**BEFORE**



**AFTER**



**CLEANER WATER GREENER TOMORROW**

# CRYSTALLINE CLEANING & ENVIRONMENTAL SERVICES

## CLEANING & DISINFECTION CERTIFICATE

### POTABLE WATER TANKS

CLIENT NAME : FOOD WORLD.  
CLIENT ADDRESS : P.O.BOX: 87297, AL AIN, ABU DHABI, UAE.  
CONTACT PERSON : MR. RAHEEM.  
SITE DETAILS : FOOD WORLD RESTAURANT, AL AIN.  
DETAILS : WATER TANK CLEANING  
DATE OF CLEANING : 29 JULY 2018  
FREQUENCY OF CLEANING : EVERY SIX MONTHS  
DATE OF NEXT CLEANING : 29 JANUARY 2019

*The procedures employed in this cleaning and disinfection comply with HS (G) 70 health and safety guidelines for prevention of legionella as well as BS6700 and CARELA BIO PLUS method statement.*

*The entire water storage tank should be cleaned and disinfected minimum every six (6) months depending upon the condition.*



CRYSTALLINE CLEANING AND ENVIRONMENTAL SERVICES



**KITCHEN EXHAUST SYSTEM – AFTER SERVICE REPORT**

CUSTOMER: <b>FOOD WORLD RESTORENT</b>		CONTACT PERSON: <b>To Mr. Jeevan</b>	
SITE DETAILS: <b>Al Ain</b>		CONTACT NO: <b>0557628760</b>	
NAME OF KITCHEN/DETAILS: <b>FOOD WORLD KITCHEN</b>		LOCATION OF KITCHEN:	
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL <input type="checkbox"/> RESIDENTIAL <input type="checkbox"/> EDUCATIONAL <input type="checkbox"/> INDUSTRIAL			
<b>KITCHEN NO 1 2 3 4 5 6 7 AND EXHUST FAN DUCT</b>			
COOKING VOLUME	<input checked="" type="checkbox"/> HIGH	<input type="checkbox"/> MEDIUM	<input type="checkbox"/> LOW
TYPE OF FILTERS	<input checked="" type="checkbox"/> MESH	<input type="checkbox"/> BAFFLE	<input type="checkbox"/> N/A
FILTERS IN PLACE	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> N/A
EXHAUST FAN	<input checked="" type="checkbox"/> UPBLAST	<input type="checkbox"/> INLINE	<input type="checkbox"/> UTILITY
CONDITION OF DUCT	<input type="checkbox"/> DAMAGED	<input type="checkbox"/> NOT DAMAGED	<input checked="" type="checkbox"/> N/A
FILTER CLEANING FREQUENCY	<input type="checkbox"/> DAILY	<input type="checkbox"/> WEEKLY	<input type="checkbox"/> MONTHLY
	<input type="checkbox"/> BIMONTHLY	<input checked="" type="checkbox"/> QUARTERLY	HALF YEARLY
DOORS/PLATES PRESENT	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	HOW MANY DOORS _____ HOW MANY PANELS _____
DOORS/PANELS INSTALLED	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	HOW MANY DOORS _____ HOW MANY PANELS _____
CONDITION OF ROOF/WALL	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<b><u>CONDITION OF KITCHEN DUCT BEFORE CLEANING</u></b>		<b><u>CONDITION OF KITCHEN DUCT AFTER CLEANING</u></b>	
<input type="checkbox"/> CLEAN	<input checked="" type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN
			<input type="checkbox"/> DIRTY <input type="checkbox"/> VERY DIRTY
<b><u>LAST CLEANING DATE</u></b>		<b><u>CURRENT CLEANING DATE</u></b>	
		<b>30-07-2018</b>	
		<b>30-01-2019</b>	
<b><u>CHEMICALS &amp; EQUIPMENTS USED</u></b>			
<input type="checkbox"/> High/Low Pressure Jet <input type="checkbox"/> Extension Cords <input type="checkbox"/> LED Lights <input type="checkbox"/> Ladder <input type="checkbox"/> Ventilating Fan <input type="checkbox"/> Degreaser Chemical <input type="checkbox"/> Plastic Roll <input type="checkbox"/> Vacuum Cleaner <input type="checkbox"/> Cleaning Materials.			
TEAM	Crystalline	TEAM LEADER	Harish Ahmed
<b><u>COMMENTS &amp; RECOMMENDATIONS:</u></b>			
The above kitchen exhaust duct was successfully degreased and cleaned as per local municipality guidelines.			
Crystalline Representative:	<b>HARIS</b>	Signature:	<b>JEEVAN</b>

Date of Cleaning: 30.07.2018


**PHOTOGRAPHS**  
**KITCHEN HOOD 1 – FOOD WORLD RESTAURANT**

**KITCHEN HOOD CLEANING**

**BEFORE**



**AFTER**



**CLEANER WATER GREENER TOMORROW**

Date of Cleaning: 30.07.2018

**PHOTOGRAPHS**  
**KITCHEN HOOD 2 – FOOD WORLD RESTAURANT**

**KITCHEN HOOD CLEANING**

**BEFORE**



**AFTER**



Date of Cleaning: 30.07.2018


**PHOTOGRAPHS**  
**KITCHEN HOOD 3 – FOOD WORLD RESTAURANT**

**KITCHEN HOOD CLEANING**

**BEFORE**



**AFTER**



Date of Cleaning: 30.07.2018

**PHOTOGRAPHS**  
**KITCHEN HOOD 4 – FOOD WORLD RESTAURANT**

**KITCHEN HOOD CLEANING**

**BEFORE**



**AFTER**



Date of Cleaning: 30.07.2018

**PHOTOGRAPHS**  
**KITCHEN HOOD 5 – FOOD WORLD RESTAURANT**

**KITCHEN HOOD CLEANING**

**BEFORE**



**AFTER**



Date of Cleaning: 30.07.2018

**PHOTOGRAPHS**  
**KITCHEN HOOD 6 – FOOD WORLD RESTAURANT**

**KITCHEN HOOD CLEANING**

**BEFORE**



**AFTER**



Date of Cleaning: 30.07.2018

**PHOTOGRAPHS**  
**KITCHEN HOOD 7 – FOOD WORLD RESTAURANT**

**KITCHEN HOOD CLEANING**

**BEFORE**



**AFTER**





**KITCHEN EXHAUST SYSTEM – AFTER SERVICE REPORT**

<b>CUSTOMER:</b> FOOD WORLD RESTORENT	<b>CONTACT PERSON:</b>
<b>SITE DETAILS:</b> AL AIN	<b>CONTACT NO:</b>
<b>NAME OF KITCHEN/DETAILS:</b> FOOD WORLD KITCHEN	<b>LOCATION OF KITCHEN:</b>
<b>TYPE OF BUILDING:</b> <input checked="" type="checkbox"/> COMMERCIAL <input type="checkbox"/> RESIDENTIAL <input type="checkbox"/> EDUCATIONAL <input type="checkbox"/> INDUSTRIAL	

<b>COOKING VOLUME</b>	<input checked="" type="checkbox"/> HIGH	<input type="checkbox"/> MEDIUM	<input type="checkbox"/> LOW
<b>TYPE OF FILTERS</b>	<input checked="" type="checkbox"/> MESH	<input type="checkbox"/> BAFFLE	<input type="checkbox"/> N/A
<b>FILTERS IN PLACE</b>	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> N/A
<b>EXHAUST FAN</b>	<input checked="" type="checkbox"/> UPBLAST	<input type="checkbox"/> INLINE	<input type="checkbox"/> UTILITY
<b>CONDITION OF DUCT</b>	<input type="checkbox"/> DAMAGED	<input type="checkbox"/> NOT DAMAGED	<input checked="" type="checkbox"/> N/A
<b>FILTER CLEANING FREQUENCY</b>	<input type="checkbox"/> DAILY	<input type="checkbox"/> WEEKLY	<input type="checkbox"/> MONTHLY
	<input type="checkbox"/> BIMONTHLY	<input checked="" type="checkbox"/> QUARTERLY	HALF YEARLY
<b>DOORS/PLATES PRESENT</b>	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	HOW MANY DOORS _____ HOW MANY PANELS _____
<b>DOORS/PANELS INSTALLED</b>	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	HOW MANY DOORS _____ HOW MANY PANELS _____
<b>CONDITION OF ROOF/WALL</b>	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY

CONDITION OF KITCHEN DUCT BEFORE CLEANING			CONDITION OF KITCHEN DUCT AFTER CLEANING		
<input type="checkbox"/> CLEAN	<input checked="" type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY

LAST CLEANING DATE	CURRENT CLEANING DATE	NEXT CLEANING DATE
	31.07.2018	31.01.2019

**CHEMICALS & EQUIPMENTS USED**

High/Low Pressure Jet     Extension Cords     LED Lights     Ladder     Ventilating Fan     Degreaser Chemical     Plastic Roll

Vacuum Cleaner     Cleaning Materials.

<b>TEAM</b>	Crystalline	<b>TEAM LEADER</b>	Harish Ahmed
-------------	-------------	--------------------	--------------

**COMMENTS & RECOMMENDATIONS:**

The above kitchen exhaust duct was successfully degreased and cleaned as per local municipality guidelines.

<b>Crystalline Representative:</b> HARIS	<b>Signature:</b>



**CRYSTALLINE**  
ENVIRONMENTAL SERVICES

Date of Cleaning: 31.07.2018


**PHOTOGRAPHS**  
**KITCHEN HOOD – FOOD WORLD RESTAURANT**

**KITCHEN HOOD CLEANING**

**BEFORE**



**AFTER**



**CLEANER WATER GREENER TOMORROW**



**KITCHEN EXHAUST SYSTEM – AFTER SERVICE REPORT**

CUSTOMER: <u>FOOD WORLD RESTORIENT</u>		CONTACT PERSON: <u>MR. JEEVAN</u>	
SITE DETAILS: <u>AL AIN</u>		CONTACT NO: <u>0557628760</u>	
NAME OF KITCHEN/DETAILS: <u>FOOD WORLD KITCHEN</u>		LOCATION OF KITCHEN:	
TYPE OF BUILDING: <input type="checkbox"/> COMMERCIAL <input type="checkbox"/> RESIDENTIAL <input type="checkbox"/> EDUCATIONAL <input type="checkbox"/> INDUSTRIAL			
COOKING VOLUME	<input checked="" type="checkbox"/> HIGH	<input type="checkbox"/> MEDIUM	<input type="checkbox"/> LOW
TYPE OF FILTERS	<input checked="" type="checkbox"/> MESH	<input type="checkbox"/> BAFFLE	<input type="checkbox"/> N/A
FILTERS IN PLACE	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> N/A
EXHAUST FAN	<input checked="" type="checkbox"/> UPBLAST	<input type="checkbox"/> INLINE	<input type="checkbox"/> UTILITY
CONDITION OF DUCT	<input type="checkbox"/> DAMAGED	<input type="checkbox"/> NOT DAMAGED	<input checked="" type="checkbox"/> N/A
FILTER CLEANING FREQUENCY	<input type="checkbox"/> DAILY	<input type="checkbox"/> WEEKLY	<input type="checkbox"/> MONTHLY
	<input type="checkbox"/> BIMONTHLY	<input checked="" type="checkbox"/> QUARTERLY	HALF YEARLY
DOORS/PLATES PRESENT	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	HOW MANY DOORS _____ HOW MANY PANELS _____
DOORS/PANELS INSTALLED	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	HOW MANY DOORS _____ HOW MANY PANELS _____
CONDITION OF ROOF/WALL	<input checked="" type="checkbox"/> CLEAN	<input type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY
<b>CONDITION OF KITCHEN DUCT BEFORE CLEANING</b>		<b>CONDITION OF KITCHEN DUCT AFTER CLEANING</b>	
<input type="checkbox"/> CLEAN	<input checked="" type="checkbox"/> DIRTY	<input type="checkbox"/> VERY DIRTY	<input checked="" type="checkbox"/> CLEAN
			<input type="checkbox"/> DIRTY
			<input type="checkbox"/> VERY DIRTY
<b>LAST CLEANING DATE</b>		<b>CURRENT CLEANING DATE</b>	<b>NEXT CLEANING DATE</b>
		<u>01-08-2018</u>	<u>01-02-2019</u>
<b><u>CHEMICALS &amp; EQUIPMENTS USED</u></b>			
<input checked="" type="checkbox"/> High/Low Pressure Jet <input checked="" type="checkbox"/> Extension Cords <input type="checkbox"/> LED Lights <input checked="" type="checkbox"/> Ladder <input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Degreaser Chemical <input checked="" type="checkbox"/> Plastic Roll <input checked="" type="checkbox"/> Vacuum Cleaner <input type="checkbox"/> Cleaning Materials.			
TEAM	Crystalline	TEAM LEADER	Harish Ahmed
<b>COMMENTS &amp; RECOMMENDATIONS:</b>			
The above kitchen exhaust duct was successfully degreased and cleaned as per local municipality guidelines.			
Crystalline Representative:	<u>HARIS</u>	Signature:	<u>Jeevan</u>

Jeevan

Date of Cleaning: 01.08.2018

**PHOTOGRAPHS**  
**KITCHEN HOOD – FOOD WORLD RESTAURANT**

**KITCHEN HOOD CLEANING**

**BEFORE**



**AFTER**





**METHODOLOGY:**

- ✓ Preliminary site visit. To choose the effective procedure.
- ✓ Live Camera Inspection for the internal duct.
- ✓ Safety clothing/equipment required: overalls, safety boots, eye protection, gloves and correct respirators.
- ✓ Conduct safety briefing with client's representative to ensure all possible hazards are identified and reported immediately if assistance is required for the control of hazards.
- ✓ Ensure spill control Kit and fire extinguisher is available.
- ✓ Digital photo taken for the proof of cleaning process.
- ✓ Access holes in ducts shall be cut if required.
- ✓ Fans shall be isolated and warning labels should be placed on isolation switches.
- ✓ Areas of duct to be cleaned to bare metal.
- ✓ Toxic or flammable products shall not be used.
- ✓ Waste rags and lint will be disposed of in the clients waste disposal facilities.
- ✓ Record any areas unable to be cleaned giving exact reasons.

If you have any queries concerning our services, please contact: +971 2 6508930

Thank you for your business!

Crystalline Cleaning & Environmental Services

# CRYSTALLINE CLEANING & ENVIRONMENTAL SERVICES

## CLEANING & DISINFECTION CERTIFICATE

CLIENT NAME : FOOD WORLD.  
CLIENT ADDRESS : AL AIN, ABU DHABI, UAE.  
CONTACT PERSON : MR. RAHEEM.  
SITE DETAILS : FOOD WORLD RESTAURANT, AL AIN.  
DETAILS : KITCHEN HOOD CLEANING  
DATE OF CLEANING : JULY 2018  
FREQUENCY OF CLEANING : EVERY SIX (6) MONTHS  
DATE OF NEXT CLEANING : JANUARY 2019

*The procedures employed in this cleaning and disinfection comply with Abu Dhabi Municipality guidelines*

*The entire Kitchen Hood should be cleaned and disinfected minimum every six (6) months depending upon the condition.*



CRYSTALLINE CLEANING AND ENVIRONMENTAL SERVICES