


**ENVIRONMENTAL  
SERVICES FOR  
A GREENER  
TOMORROW...  
ONE STEP AT  
A TIME.**



Completion Report for  
**Grease Trap Cleaning**

Date: **03 November 2019**  
Client Name: **Tafawuq Facility Management**  
Contact Person: **Mr. Sarjun Hussain**  
Designation: **CAFM Agent**  
Site Detail: **Al Rayyana**




<b>Customer:</b> Tafawuq Facility Management		<b>Contact Person:</b> Mr. Sarjun Hussain	
<b>Site:</b> Al Rayyana Development, Abu Dhabi		<b>Contact Number:</b> 0543061256	
<b>Description:</b> RCC_Grease Trap Cleaning		<b>Location:</b> CLUB HOUSE	
<b>Type Of Building</b> <input checked="" type="checkbox"/> Commercial <input type="checkbox"/> Educational <input type="checkbox"/> Residential <input type="checkbox"/> Others			
<b>Type of Grease Trap</b>			
<b>Type A</b> <input type="checkbox"/> Yes <input type="checkbox"/> No	<b>Type B</b> <input type="checkbox"/> Yes <input type="checkbox"/> No	<b>Type C</b> <input type="checkbox"/> Yes <input type="checkbox"/> No	<b>Other</b> <input type="checkbox"/> Yes <input type="checkbox"/> No
<b>Condition Of Grease Trap</b>			
<input type="checkbox"/> Little Dirty	<input type="checkbox"/> Dirty	<input checked="" type="checkbox"/> Very Dirty	<input type="checkbox"/> Sludge
<input checked="" type="checkbox"/> Fat	<input checked="" type="checkbox"/> Oil	<input checked="" type="checkbox"/> Grease	<input checked="" type="checkbox"/> Solid
<b>Condition Of Strainers</b>		<b>Condition Of Baffels</b>	
<input checked="" type="checkbox"/> Good	<input type="checkbox"/> Faulty	<input checked="" type="checkbox"/> Good	<input type="checkbox"/> Faulty
<b>Condition Of Pipes</b>			
<b>Inlet Pipes</b>		<b>Outlet Pipes</b>	
<input checked="" type="checkbox"/> Good	<input type="checkbox"/> Leakage	<input type="checkbox"/> Blockage	<input checked="" type="checkbox"/> Good
			<input type="checkbox"/> Leakage
			<input type="checkbox"/> Blockage
<b>Grease Trap Cover</b>			
<input checked="" type="checkbox"/> Covered	<input type="checkbox"/> Open	<input type="checkbox"/> Damaged	<input type="checkbox"/> Adapted
<b>Condition Of Grease Trap after cleaning</b>			
<b>Clean</b>		<b>Flow</b>	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
<b>Number of Grease Trap Cleaned</b>			
<b>Type A:</b> 1	<b>Type B:</b>	<b>Type C:</b>	<b>Other:</b>
			<b>Total:</b> 1
<b>Equipments Used</b>			
<input type="checkbox"/> Jetting Machine	<input checked="" type="checkbox"/> Inlet Water Hose	<input type="checkbox"/> Vacuum Cleaner	<input checked="" type="checkbox"/> Extension Cords
<input type="checkbox"/> Degreaser	<input checked="" type="checkbox"/> Garbage Bags	<input checked="" type="checkbox"/> Cleaning Cloth	<input checked="" type="checkbox"/> LED Lights
<input checked="" type="checkbox"/> Ventilation Fan	<input checked="" type="checkbox"/> Hand Gloves	<input checked="" type="checkbox"/> Suitable PPE	
<b>Last Cleaning Date</b>		<b>Current Cleaning Date</b>	<b>Next Cleaning Date</b>
-		02 November 2019	02 May 2020
<b>Crystalline Representative</b>		<b>Customer Representative</b>	
			

## RCC\_Grease Trap Cleaning

Before Photo



After Photo




Before Photo



After Photo



We removed grease from the above mentioned by use of tanker and well cleaned.

<b>Customer:</b> Tafawuq Facility Management		<b>Contact Person:</b> Mr. Sarjun Hussain	
<b>Site:</b> Al Rayyana Development, Abu Dhabi		<b>Contact Number:</b> 0543061256	
<b>Description:</b> RCC_Grease Trap Cleaning		<b>Location:</b> CLUB HOUSE	
<b>Type Of Building</b> <input checked="" type="checkbox"/> Commercial <input type="checkbox"/> Educational <input type="checkbox"/> Residential <input type="checkbox"/> Others			
<b>Type of Grease Trap</b>			
<b>Type A</b> <input type="checkbox"/> Yes <input type="checkbox"/> No	<b>Type B</b> <input type="checkbox"/> Yes <input type="checkbox"/> No	<b>Type C</b> <input type="checkbox"/> Yes <input type="checkbox"/> No	<b>Other</b> <input type="checkbox"/> Yes <input type="checkbox"/> No
<b>Condition Of Grease Trap</b>			
<input type="checkbox"/> Little Dirty	<input type="checkbox"/> Dirty	<input checked="" type="checkbox"/> Very Dirty	<input type="checkbox"/> Sludge
<input checked="" type="checkbox"/> Fat	<input checked="" type="checkbox"/> Oil	<input checked="" type="checkbox"/> Grease	<input checked="" type="checkbox"/> Solid
<b>Condition Of Strainers</b>		<b>Condition Of Baffels</b>	
<input checked="" type="checkbox"/> Good	<input type="checkbox"/> Faulty	<input checked="" type="checkbox"/> Good	<input type="checkbox"/> Faulty
<b>Condition Of Pipes</b>			
<b>Inlet Pipes</b>		<b>Outlet Pipes</b>	
<input checked="" type="checkbox"/> Good	<input type="checkbox"/> Leakage	<input type="checkbox"/> Blockage	<input checked="" type="checkbox"/> Good
<input type="checkbox"/> Leakage	<input type="checkbox"/> Blockage	<input type="checkbox"/> Leakage	<input type="checkbox"/> Blockage
<b>Grease Trap Cover</b>			
<input checked="" type="checkbox"/> Covered	<input type="checkbox"/> Open	<input type="checkbox"/> Damaged	<input type="checkbox"/> Adapted
<b>Condition Of Grease Trap after cleaning</b>			
<b>Clean</b>		<b>Flow</b>	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
<b>Number of Grease Trap Cleaned</b>			
<b>Type A:</b>	<b>Type B:</b> 1	<b>Type C:</b>	<b>Other:</b>
			<b>Total:</b> 1
<b>Equipments Used</b>			
<input type="checkbox"/> Jetting Machine	<input checked="" type="checkbox"/> Inlet Water Hose	<input type="checkbox"/> Vacuum Cleaner	<input checked="" type="checkbox"/> Extension Cords
<input type="checkbox"/> Degreaser	<input checked="" type="checkbox"/> Garbage Bags	<input checked="" type="checkbox"/> Cleaning Cloth	<input checked="" type="checkbox"/> LED Lights
<input type="checkbox"/> Ventilation Fan	<input checked="" type="checkbox"/> Hand Gloves	<input checked="" type="checkbox"/> Suitable PPE	
<b>Last Cleaning Date</b>		<b>Current Cleaning Date</b>	<b>Next Cleaning Date</b>
-		02 November 2019	02 May 2020
<b>Crystalline Representative</b>		<b>Customer Representative</b>	
			

## RCC\_Grease Trap Cleaning


Before Photo




After Photo




Before Photo



After Photo



We removed grease from the above mentioned by use of tanker and well cleaned.

<b>Customer:</b> Tafawuq Facility Management		<b>Contact Person:</b> Mr. Sarjun Hussain	
<b>Site:</b> Al Rayyana Development, Abu Dhabi		<b>Contact Number:</b> 0543061256	
<b>Description:</b> RCC_Grease Trap Cleaning		<b>Location:</b> CLUB HOUSE	
<b>Type Of Building</b> <input checked="" type="checkbox"/> Commercial <input type="checkbox"/> Educational <input type="checkbox"/> Residential <input type="checkbox"/> Others			
<b>Type of Grease Trap</b>			
<b>Type A</b> <input type="checkbox"/> Yes <input type="checkbox"/> No	<b>Type B</b> <input type="checkbox"/> Yes <input type="checkbox"/> No	<b>Type C</b> <input type="checkbox"/> Yes <input type="checkbox"/> No	<b>Other</b> <input type="checkbox"/> Yes <input type="checkbox"/> No
<b>Condition Of Grease Trap</b>			
<input type="checkbox"/> Little Dirty	<input checked="" type="checkbox"/> Dirty	<input type="checkbox"/> Very Dirty	<input type="checkbox"/> Sludge
<input checked="" type="checkbox"/> Fat	<input checked="" type="checkbox"/> Oil	<input checked="" type="checkbox"/> Grease	<input checked="" type="checkbox"/> Solid
<b>Condition Of Strainers</b>		<b>Condition Of Baffels</b>	
<input checked="" type="checkbox"/> Good	<input type="checkbox"/> Faulty	<input checked="" type="checkbox"/> Good	<input type="checkbox"/> Faulty
<b>Condition Of Pipes</b>			
<b>Inlet Pipes</b>		<b>Outlet Pipes</b>	
<input checked="" type="checkbox"/> Good	<input type="checkbox"/> Leakage	<input type="checkbox"/> Blockage	
		<input checked="" type="checkbox"/> Good	<input type="checkbox"/> Leakage
			<input type="checkbox"/> Blockage
<b>Grease Trap Cover</b>			
<input checked="" type="checkbox"/> Covered	<input type="checkbox"/> Open	<input type="checkbox"/> Damaged	<input type="checkbox"/> Adapted
<b>Condition Of Grease Trap after cleaning</b>			
<b>Clean</b>		<b>Flow</b>	
<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
<b>Number of Grease Trap Cleaned</b>			
<b>Type A:</b>	<b>Type B:</b>	<b>Type C 1</b>	<b>Other:</b>
			<b>Total: 1</b>
<b>Equipments Used</b>			
<input type="checkbox"/> Jetting Machine	<input checked="" type="checkbox"/> Inlet Water Hose	<input type="checkbox"/> Vacuum Cleaner	<input checked="" type="checkbox"/> Extension Cords
<input type="checkbox"/> Degreaser	<input checked="" type="checkbox"/> Garbage Bags	<input checked="" type="checkbox"/> Cleaning Cloth	<input checked="" type="checkbox"/> LED Lights
<input type="checkbox"/> Ventilation Fan	<input checked="" type="checkbox"/> Hand Gloves	<input checked="" type="checkbox"/> Suitable PPE	
<b>Last Cleaning Date</b>		<b>Current Cleaning Date</b>	<b>Next Cleaning Date</b>
-		02 November 2019	02 May 2020
<b>Crystalline Representative</b>		<b>Customer Representative</b>	
			

## RCC\_Grease Trap Cleaning


Before Photo



After Photo



Before Photo



After Photo



We removed grease from the above mentioned by use of tanker and well cleaned.

# CRYSTALLINE CLEANING & ENVIRONMENTAL SERVICES

## GREASE TRAP CLEANING

CLIENT NAME : TAFAWUQ FACILITY MANAGEMENT  
CONTACT PERSON : MR. SARJUN HUSSAIN  
DESIGNATION : CAFM AGENT  
SITE DETAILS : AL RAYYANA  
DETAILS : GREASE TRAP CLEANING  
DATE OF CLEANING : 02 NOVEMBER 2019  
FREQUENCY OF CLEANING : HALF YEARLY  
DATE OF NEXT CLEANING : 02 MAY 2020

*The above system is thoroughly cleaned and all the solids and debris removed and disposed.  
Regular, preventive maintenance will ensure system operating at maximum efficiency.*



*Tasman Pinto*

CRYSTALLINE CLEANING AND ENVIRONMENTAL SERVICES