

# WATER TANK CLEANING & DISINFECTION

## COMPLETION REPORT

FOR



Client : COFELY BESIX FACILITY  
MANAGEMENT  
Contact Person: Mr. P.R. Xavier  
Senior MEP Supervisor  
Site Details : HCT - Al Ain Men's & Women's  
College, Al Ain and Abu Dhabi  
Khalifa Campus, Abu Dhabi.  
Date : 15 August 2018



**CRYSTALLINE**  
ENVIRONMENTAL SERVICES

CRYSTALLINE ENVIRONMENTAL  
SERVICES

P.O. BOX 131463, Abu Dhabi, U.A.E.

TEL: 02 6508930 FAX: 02 6508942

[info@crystalline-uae.com](mailto:info@crystalline-uae.com)

[www.crystalline-uae.com](http://www.crystalline-uae.com)





# CRYSTALLINE ENVIRONMENTAL SERVICES

## WATER TANK - AFTER SERVICE REPORT

15953

|   |   |   |   |   |  |
|---|---|---|---|---|--|
| CUSTOMER: <b>COFELY BESIX</b>   |   |   | CONTACT PERSON: <b>MR XAVIAR</b>              |   |  |
| SITE DETAILS:<br><b>HCT WOMEN'S SCHOOL ALHAIN</b>   |   |   | CONTACT NO:<br><b>0561883075</b>              |   |  |
| TANK DETAILS: <b>RCC MAIN TANK N. 01</b>  |   |   | LOCATION DETAILS: <b>PUMP ROOM UNDER G.</b>   |   |  |
| TYPE OF BUILDING: <input checked="" type="checkbox"/> COMMERCIAL  |   | <input type="checkbox"/> RESIDENTIAL    |   | <input type="checkbox"/> OTHERS         |  |
| <b>TYPE OF TANK</b>   |   |   |   |   |  |
| <input checked="" type="checkbox"/> CONCRETE  | <input type="checkbox"/> GRP PANEL        | <input type="checkbox"/> FRP TANK       | <input type="checkbox"/> GALVANIZED           | <input type="checkbox"/> STEEL PANEL    | <input type="checkbox"/> PLASTIC                                   |
| <input type="checkbox"/> CONCRETE COATED  |   | <input type="checkbox"/> POLYURETHANE   |   | <input type="checkbox"/> OTHERS         |  |
| <b>SIZE OF TANK</b>   |   |   | <b>QUANTITY OF WATER</b>                      |   |  |
| M3  | USG                                       | L*B*H                                   | <input checked="" type="checkbox"/> FULL      | <input type="checkbox"/> HALF           | <input type="checkbox"/> EMPTY                                     |
| <b>CONDITION OF WATER TANK BEFORE CLEANING</b>  |   |   | <b>CONDITION OF WATER TANK AFTER CLEANING</b> |   |  |
| <input type="checkbox"/> CLEAN  | <input checked="" type="checkbox"/> DIRTY | <input type="checkbox"/> VERY DIRTY     | <input checked="" type="checkbox"/> CLEAN     | <input type="checkbox"/> DIRTY          | <input type="checkbox"/> VERY DIRTY                                |
| <input type="checkbox"/> BIOFILMS   | <input type="checkbox"/> MOULDS           | <input type="checkbox"/> SLIME          | <input type="checkbox"/> BIOFILMS             | <input type="checkbox"/> MOULDS         | <input type="checkbox"/> SLIME                                     |
| <input type="checkbox"/> SEDIMENTS  | <input type="checkbox"/> MUD & SAND       | <input type="checkbox"/> RUST           | <input type="checkbox"/> SEDIMENTS            | <input type="checkbox"/> MUD & SAND     | <input type="checkbox"/> RUST                                      |
| <b>ACCESS</b>   |   | <b>MANHOLE</b>                          |   | <input type="checkbox"/> COVERED        |  |
| <input type="checkbox"/> DAMAGED  |   | <input type="checkbox"/> NA             |   |   |  |
| <b>LADDER IN</b>  |   | <b>LADDER OUT</b>                       |   | <b>LEAKS</b>                            |  |
| <b>DRAIN LINE</b>   |   | <b>VALVES</b>                           |   | <b>FLOAT VALVE</b>                      |  |
| <input checked="" type="checkbox"/> YES   | <input type="checkbox"/> NO               | <input checked="" type="checkbox"/> YES | <input type="checkbox"/> NO                   | <input type="checkbox"/> YES            | <input checked="" type="checkbox"/> NO                             |
| <input type="checkbox"/> YES  | <input type="checkbox"/> NO               | <input type="checkbox"/> YES            | <input checked="" type="checkbox"/> NO        | <input checked="" type="checkbox"/> YES | <input type="checkbox"/> NO  |
| <b>TANK CLEANED</b>   |   | <b>TANK DISINFECTED</b>                 |   | <b>PIPES DISINFECTED</b>                |  |
| <input checked="" type="checkbox"/> YES   | <input type="checkbox"/> NO               | <input checked="" type="checkbox"/> YES | <input type="checkbox"/> NO                   | <input type="checkbox"/> YES            | <input type="checkbox"/> NO <input checked="" type="checkbox"/> NA |
| <b>LAST CLEANING DATE</b>   |   | <b>CURRENT CLEANING DATE</b>            |   | <b>NEXT CLEANING DATE</b>               |  |
|   |   | <b>13-07-2018</b>                       |   | <b>13-01-2019</b>                       |  |
| <b>CHEMICALS &amp; EQUIPMENTS USED</b>  |   |   |   |   |  |
| 1. <b>CAECLA No 8 PLUS</b> Quantity <b>400cc</b>  |   |   |   |   |  |
| 2. _____ Quantity _____   |   |   |   |   |  |
| <input checked="" type="checkbox"/> Submersibel Pump <input checked="" type="checkbox"/> High/Low Pressure Jet <input type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED lights <input checked="" type="checkbox"/> Foot Bath <input checked="" type="checkbox"/> Ladder<br><input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Meter <input checked="" type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials |   |   |   |   |  |
| <b>COMMENTS &amp; RECOMMENDATIONS:</b>  |   |   |   |   |  |
| <b>TANK CLEANED AND DISINFECTED</b>   |   |   |   |   |  |
| Crystalline Representative: <b>YETAUST</b>  |   |   | Signature: <b>[Signature]</b>                 |   |  |

Date of Cleaning: 13-07-2018

**PHOTOGRAPHS**  
**UNDER GROUND RCC WATER TANK - 01**

**BEFORE**



**AFTER**



**CLEANER WATER GREENER TOMORROW**



# CRYSTALLINE ENVIRONMENTAL SERVICES

## WATER TANK - AFTER SERVICE REPORT

15955

| CUSTOMER: <u>COFELY BESIX</u>                                       |   |   | CONTACT PERSON: <u>MR XAVIAR</u>                                    |   |   |
|---|---|---|---|---|---|
| SITE DETAILS: <u>HCT WOMEN'S SCHOOL ALAIN</u>                       |   |   | CONTACT NO: <u>05-61883073</u>                                      |   |   |
| TANK DETAILS: <u>GRP DOMESTIC TANK N.01</u>                         |   |   | LOCATION DETAILS: <u>BLOCK A. ROOF TOP</u>                          |   |   |
| TYPE OF BUILDING: <input checked="" type="checkbox"/> COMMERCIAL    |   | <input type="checkbox"/> RESIDENTIAL                                |   | <input type="checkbox"/> OTHERS                                     |   |
| TYPE OF TANK  |   |   |   |   |   |
| <input type="checkbox"/> CONCRETE                                   | <input checked="" type="checkbox"/> GRP PANEL                       | <input type="checkbox"/> FRP TANK                                   | <input type="checkbox"/> GALVANIZED                                 | <input type="checkbox"/> STEEL PANEL                                | <input type="checkbox"/> PLASTIC                                    |
| <input type="checkbox"/> CONCRETE COATED                            |   | <input type="checkbox"/> POLYURETHANE                               | <input type="checkbox"/> OTHERS                                     |   |   |
| SIZE OF TANK  |   |   | QUANTITY OF WATER   |   |   |
| M3  | USG   | L*B*H   | <input checked="" type="checkbox"/> FULL                            | <input type="checkbox"/> HALF                                       | <input type="checkbox"/> EMPTY                                      |
| CONDITION OF WATER TANK BEFORE CLEANING                             |   |   | CONDITION OF WATER TANK AFTER CLEANING                              |   |   |
| <input type="checkbox"/> CLEAN                                      | <input checked="" type="checkbox"/> DIRTY                           | <input type="checkbox"/> VERY DIRTY                                 | <input checked="" type="checkbox"/> CLEAN                           | <input type="checkbox"/> DIRTY                                      | <input type="checkbox"/> VERY DIRTY                                 |
| <input type="checkbox"/> BIOFILMS                                   | <input type="checkbox"/> MOULDS                                     | <input type="checkbox"/> SLIME                                      | <input type="checkbox"/> BIOFILMS                                   | <input type="checkbox"/> MOULDS                                     | <input type="checkbox"/> SLIME                                      |
| <input type="checkbox"/> SEDIMENTS                                  | <input type="checkbox"/> MUD & SAND                                 | <input type="checkbox"/> RUST                                       | <input type="checkbox"/> SEDIMENTS                                  | <input type="checkbox"/> MUD & SAND                                 | <input type="checkbox"/> RUST                                       |
| ACCESS  |   | MANHOLE   |   | <input type="checkbox"/> COVERED                                    | <input type="checkbox"/> DAMAGED                                    |
| <input type="checkbox"/> LADDER IN                                  | <input type="checkbox"/> LADDER OUT                                 | <input type="checkbox"/> LEAKS                                      |   | <input type="checkbox"/> VALVES                                     | <input type="checkbox"/> FLOAT VALVE                                |
| <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO |
| TANK CLEANED  |   | TANK DISINFECTED  |   | PIPES DISINFECTED   |   |
| <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO | <input type="checkbox"/> YES <input type="checkbox"/> NO            | <input checked="" type="checkbox"/> NA                              |
| LAST CLEANING DATE  |   | CURRENT CLEANING DATE   |   | NEXT CLEANING DATE  |   |
|   |   | <u>14-07-2018</u>   |   | <u>14-01-2019</u>   |   |
| CHEMICALS & EQUIPMENTS USED   |   |   |   |   |   |
| 1. <u>CARELA Bio 8 PLUS</u> Quantity <u>200cc</u>                   |   |   |   |   |   |
| 2. _____ Quantity _____   |   |   |   |   |   |
| <input checked="" type="checkbox"/> Submersibel Pump                | <input checked="" type="checkbox"/> High/Low Pressure Jet           | <input checked="" type="checkbox"/> Extension Cords                 | <input checked="" type="checkbox"/> LED lights                      | <input type="checkbox"/> Foot Bath                                  | <input checked="" type="checkbox"/> Ladder                          |
| <input checked="" type="checkbox"/> Ventilating Fan                 | <input checked="" type="checkbox"/> Suction/Discharge Hoses         | <input checked="" type="checkbox"/> Oxygen Meter                    | <input checked="" type="checkbox"/> Vacuum Cleaner                  | <input checked="" type="checkbox"/> Cleaning Materials              |   |
| COMMENTS & RECOMMENDATIONS:   |   |   |   |   |   |
| <u>TANK CLEANED AND DISINFECTED</u>                                 |   |   |   |   |   |
| Crystalline Representative: <u>VE TALUST</u>                        |   |   | Signature: <u>[Signature]</u>                                       |   |   |




**CRYSTALLINE**  
ENVIRONMENTAL SERVICES

Date of Cleaning: 14-07-2018


**PHOTOGRAPHS**  
**ROOF TOP GRP WATER TANK (A) - I & II - 01**

**BEFORE**

**GRP WATER TANK - I**



**GRP WATER TANK - II**



**AFTER**



**CLEANER WATER GREENER TOMORROW**



# CRYSTALLINE ENVIRONMENTAL SERVICES

## WATER TANK - AFTER SERVICE REPORT

15956

| CUSTOMER: <u>COTELY BEST</u>  |   |   | CONTACT PERSON: <u>MR LAVIAR</u>                                    |   |   |
|---|---|---|---|---|---|
| SITE DETAILS:<br><u>HCT WOMEN'S SCHOOL ALDHI</u>                    |   |   | CONTACT NO:<br><u>0561883075</u>                                    |   |   |
| TANK DETAILS: <u>GRP DOMESTIC TANK N.02</u>                         |   |   | LOCATION DETAILS: <u>BLOCK B. ROOF TOP</u>                          |   |   |
| TYPE OF BUILDING: <input checked="" type="checkbox"/> COMMERCIAL    |   |   | <input type="checkbox"/> RESIDENTIAL                                |   | <input type="checkbox"/> OTHERS                                     |
| TYPE OF TANK  |   |   |   |   |   |
| <input type="checkbox"/> CONCRETE                                   | <input checked="" type="checkbox"/> GRP PANEL                       | <input type="checkbox"/> FRP TANK                                   | <input type="checkbox"/> GALVANIZED                                 | <input type="checkbox"/> STEEL PANEL                                | <input type="checkbox"/> PLASTIC                                    |
| <input type="checkbox"/> CONCRETE COATED                            |   | <input type="checkbox"/> POLYURETHANE                               | <input type="checkbox"/> OTHERS                                     |   |   |
| SIZE OF TANK  |   |   | QUANTITY OF WATER   |   |   |
| M3  | USG   | L*B*H   | <input checked="" type="checkbox"/> FULL                            | <input type="checkbox"/> HALF                                       | <input type="checkbox"/> EMPTY                                      |
| CONDITION OF WATER TANK BEFORE CLEANING                             |   |   | CONDITION OF WATER TANK AFTER CLEANING                              |   |   |
| <input type="checkbox"/> CLEAN                                      | <input checked="" type="checkbox"/> DIRTY                           | <input type="checkbox"/> VERY DIRTY                                 | <input checked="" type="checkbox"/> CLEAN                           | <input type="checkbox"/> DIRTY                                      | <input type="checkbox"/> VERY DIRTY                                 |
| <input type="checkbox"/> BIOFILMS                                   | <input type="checkbox"/> MOULDS                                     | <input type="checkbox"/> SLIME                                      | <input type="checkbox"/> BIOFILMS                                   | <input type="checkbox"/> MOULDS                                     | <input type="checkbox"/> SLIME                                      |
| <input type="checkbox"/> SEDIMENTS                                  | <input type="checkbox"/> MUD & SAND                                 | <input type="checkbox"/> RUST                                       | <input type="checkbox"/> SEDIMENTS                                  | <input type="checkbox"/> MUD & SAND                                 | <input type="checkbox"/> RUST                                       |
| ACCESS  |   | MANHOLE   | <input type="checkbox"/> COVERED                                    | <input type="checkbox"/> DAMAGED                                    | <input type="checkbox"/> NA   |
| LADDER IN   | LADDER OUT  | LEAKS   | DRAIN LINE  | VALVES  | FLOAT VALVE   |
| <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO |
| TANK CLEANED  |   | TANK DISINFECTED  |   | PIPES DISINFECTED   |   |
| <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO | <input type="checkbox"/> YES <input type="checkbox"/> NO            | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO | <input type="checkbox"/> YES <input type="checkbox"/> NO            | <input type="checkbox"/> YES <input type="checkbox"/> NO            | <input checked="" type="checkbox"/> NA                              |
| LAST CLEANING DATE  |   | CURRENT CLEANING DATE   |   | NEXT CLEANING DATE  |   |
|   |   | <u>14-07-2018</u>   |   | <u>14-01-2019</u>   |   |
| CHEMICALS & EQUIPMENTS USED   |   |   |   |   |   |
| 1. <u>CHARLTA BUD 8 PLUS</u> Quantity <u>300 CC</u>                 |   |   |   |   |   |
| 2. _____ Quantity _____   |   |   |   |   |   |
| <input checked="" type="checkbox"/> Submersibel Pump                | <input checked="" type="checkbox"/> High/Low Pressure Jet           | <input checked="" type="checkbox"/> Extension Cords                 | <input checked="" type="checkbox"/> LED lights                      | <input checked="" type="checkbox"/> Foot Bath                       | <input checked="" type="checkbox"/> Ladder                          |
| <input checked="" type="checkbox"/> Ventilating Fan                 | <input checked="" type="checkbox"/> Suction/Discharge Hoses         | <input checked="" type="checkbox"/> Oxygen Meter                    | <input checked="" type="checkbox"/> Vacuum Cleaner                  | <input checked="" type="checkbox"/> Cleaning Materials              |   |
| COMMENTS & RECOMMENDATIONS:   |   |   |   |   |   |
| <u>TANK CLEANED AND DISINFECTED</u>                                 |   |   |   |   |   |
| Crystalline Representative: <u>VETALIST</u>                         |   |   | Signature: <u>[Signature]</u>                                       |   |   |



**CRYSTALLINE**  
ENVIRONMENTAL SERVICES

Date of Cleaning: 14-07-2018

**PHOTOGRAPHS**  
**ROOF TOP GRP WATER TANK (B) - I & II - 02**

**BEFORE**

**GRP WATER TANK - I**



**GRP WATER TANK - II**



**AFTER**



**CLEANER WATER GREENER TOMORROW**



# CRYSTALLINE ENVIRONMENTAL SERVICES

## WATER TANK - AFTER SERVICE REPORT

15957

|  |   |  |   |                                      |  |
|--|---|--|---|--------------------------------------|--|
| CUSTOMER: <u>COFELY BESIDE</u>   |   |  | CONTACT PERSON: <u>MR LAVIAR</u>              |                                      |  |
| SITE DETAILS:<br><u>HCT WOMEN'S SCHOOL KALIAN</u>  |   |  | CONTACT NO:<br><u>05-61883075</u>             |                                      |  |
| TANK DETAILS: <u>SINTEX DOMESTIC T. 03</u>   |   |  | LOCATION DETAILS: <u>BLOCK B. ROOF TOP</u>    |                                      |  |
| TYPE OF BUILDING: <input checked="" type="checkbox"/> COMMERCIAL   |   | <input type="checkbox"/> RESIDENTIAL             |   | <input type="checkbox"/> OTHERS      |  |
| <u>TYPE OF TANK</u>  |   |  |   |                                      |  |
| <input type="checkbox"/> CONCRETE  | <input type="checkbox"/> GRP PANEL        | <input type="checkbox"/> FRP TANK                | <input type="checkbox"/> GALVANIZED           | <input type="checkbox"/> STEEL PANEL | <input type="checkbox"/> PLASTIC       |
| <input type="checkbox"/> CONCRETE COATED   |   | <input checked="" type="checkbox"/> POLYURETHANE | <input type="checkbox"/> OTHERS               |                                      |  |
| <u>SIZE OF TANK</u>  |   |  | <u>QUANTITY OF WATER</u>                      |                                      |  |
| M3   | USG                                       | L*B*H  | <input checked="" type="checkbox"/> FULL      | <input type="checkbox"/> HALF        | <input type="checkbox"/> EMPTY         |
| <u>CONDITION OF WATER TANK BEFORE CLEANING</u>   |   |  | <u>CONDITION OF WATER TANK AFTER CLEANING</u> |                                      |  |
| <input type="checkbox"/> CLEAN   | <input checked="" type="checkbox"/> DIRTY | <input type="checkbox"/> VERY DIRTY              | <input checked="" type="checkbox"/> CLEAN     | <input type="checkbox"/> DIRTY       | <input type="checkbox"/> VERY DIRTY    |
| <input type="checkbox"/> BIOFILMS  | <input type="checkbox"/> MOULDS           | <input type="checkbox"/> SLIME                   | <input type="checkbox"/> BIOFILMS             | <input type="checkbox"/> MOULDS      | <input type="checkbox"/> SLIME         |
| <input type="checkbox"/> SEDIMENTS   | <input type="checkbox"/> MUD & SAND       | <input type="checkbox"/> RUST                    | <input type="checkbox"/> SEDIMENTS            | <input type="checkbox"/> MUD & SAND  | <input type="checkbox"/> RUST          |
| <u>ACCESS</u>  |   | <u>MANHOLE</u>                                   |   | <input type="checkbox"/> COVERED     | <input type="checkbox"/> DAMAGED       |
| <input type="checkbox"/> NA  |   |  |   |                                      |  |
| <u>LADDER IN</u>   |   | <u>LADDER OUT</u>                                |   | <u>LEAKS</u>                         |  |
| <input checked="" type="checkbox"/> YES  | <input type="checkbox"/> NO               | <input checked="" type="checkbox"/> YES          | <input type="checkbox"/> NO                   | <input type="checkbox"/> YES         | <input checked="" type="checkbox"/> NO |
| <u>TANK CLEANED</u>  |   | <u>TANK DISINFECTED</u>                          |   | <u>PIPES DISINFECTED</u>             |  |
| <input checked="" type="checkbox"/> YES  | <input type="checkbox"/> NO               | <input checked="" type="checkbox"/> YES          | <input type="checkbox"/> NO                   | <input type="checkbox"/> YES         | <input type="checkbox"/> NO            |
| <u>LAST CLEANING DATE</u>  |   | <u>CURRENT CLEANING DATE</u>                     |   | <u>NEXT CLEANING DATE</u>            |  |
|  |   | <u>14-07-2018</u>                                |   | <u>14-01-2019</u>                    |  |
| <u>CHEMICALS &amp; EQUIPMENTS USED</u>   |   |  |   |                                      |  |
| 1. <u>CARELAB 300 &amp; PLUS</u> Quantity <u>200cc</u>   |   |  |   |                                      |  |
| 2. _____ Quantity _____  |   |  |   |                                      |  |
| <input checked="" type="checkbox"/> Submersibel Pump <input checked="" type="checkbox"/> High/Low Pressure Jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED lights <input checked="" type="checkbox"/> Foot Bath <input checked="" type="checkbox"/> Ladder<br><input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Meter <input checked="" type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials |   |  |   |                                      |  |
| <u>COMMENTS &amp; RECOMMENDATIONS:</u>   |   |  |   |                                      |  |
| <u>TANK CLEANED AND DISINFECTED</u>  |   |  |   |                                      |  |
| Crystalline Representative: <u>VEITALIST</u>   |   |  | Signature: <u>[Signature]</u>                 |                                      |  |



# CRYSTALLINE ENVIRONMENTAL SERVICES

## WATER TANK - AFTER SERVICE REPORT

15958

|   |   |  |   |  |  |
|---|---|--|---|--|--|
| CUSTOMER: <u>COFELY BESIR</u>   |   |  | CONTACT PERSON: <u>MR. LAVIAR</u>             |  |  |
| SITE DETAILS: <u>ACT WOMEN'S SCHOOL ALAIN</u>   |   |  | CONTACT NO: <u>05-61883075</u>                |  |  |
| TANK DETAILS: <u>SINTEL DOMESTIC T. 04</u>  |   |  | LOCATION DETAILS: <u>BLOCK A ROOF TOP</u>     |  |  |
| TYPE OF BUILDING: <input checked="" type="checkbox"/> COMMERCIAL  |   | <input type="checkbox"/> RESIDENTIAL             |   | <input type="checkbox"/> OTHERS          |  |
| <b>TYPE OF TANK</b>   |   |  |   |  |  |
| <input type="checkbox"/> CONCRETE   | <input type="checkbox"/> GRP PANEL        | <input type="checkbox"/> FRP TANK                | <input type="checkbox"/> GALVANIZED           | <input type="checkbox"/> STEEL PANEL     | <input type="checkbox"/> PLASTIC                                   |
| <input type="checkbox"/> CONCRETE COATED  |   | <input checked="" type="checkbox"/> POLYURETHANE | <input type="checkbox"/> OTHERS               |  |  |
| <b>SIZE OF TANK</b>   |   |  | <b>QUANTITY OF WATER</b>                      |  |  |
| M3  | USG                                       | L*B*H  | <input type="checkbox"/> FULL                 | <input checked="" type="checkbox"/> HALF | <input type="checkbox"/> EMPTY                                     |
| <b>CONDITION OF WATER TANK BEFORE CLEANING</b>  |   |  | <b>CONDITION OF WATER TANK AFTER CLEANING</b> |  |  |
| <input type="checkbox"/> CLEAN  | <input checked="" type="checkbox"/> DIRTY | <input type="checkbox"/> VERY DIRTY              | <input checked="" type="checkbox"/> CLEAN     | <input type="checkbox"/> DIRTY           | <input type="checkbox"/> VERY DIRTY                                |
| <input type="checkbox"/> BIOFILMS   | <input type="checkbox"/> MOULDS           | <input type="checkbox"/> SLIME                   | <input type="checkbox"/> BIOFILMS             | <input type="checkbox"/> MOULDS          | <input type="checkbox"/> SLIME                                     |
| <input type="checkbox"/> SEDIMENTS  | <input type="checkbox"/> MUD & SAND       | <input type="checkbox"/> RUST                    | <input type="checkbox"/> SEDIMENTS            | <input type="checkbox"/> MUD & SAND      | <input type="checkbox"/> RUST                                      |
| <b>ACCESS</b>   |   | <b>MANHOLE</b>                                   |   | <input type="checkbox"/> COVERED         | <input type="checkbox"/> DAMAGED                                   |
| <input type="checkbox"/> NA   |   |  |   |  | <input type="checkbox"/> NA  |
| <b>LADDER IN</b>  |   | <b>LADDER OUT</b>                                |   | <b>LEAKS</b>                             |  |
| <input checked="" type="checkbox"/> YES   | <input type="checkbox"/> NO               | <input checked="" type="checkbox"/> YES          | <input type="checkbox"/> NO                   | <input type="checkbox"/> YES             | <input checked="" type="checkbox"/> NO                             |
| <b>DRAIN LINE</b>   |   | <b>VALVES</b>                                    |   | <b>FLOAT VALVE</b>                       |  |
| <input type="checkbox"/> YES  | <input checked="" type="checkbox"/> NO    | <input checked="" type="checkbox"/> YES          | <input type="checkbox"/> NO                   | <input checked="" type="checkbox"/> YES  | <input type="checkbox"/> NO  |
| <b>TANK CLEANED</b>   |   | <b>TANK DISINFECTED</b>                          |   | <b>PIPES DISINFECTED</b>                 |  |
| <input checked="" type="checkbox"/> YES   | <input type="checkbox"/> NO               | <input checked="" type="checkbox"/> YES          | <input type="checkbox"/> NO                   | <input type="checkbox"/> YES             | <input type="checkbox"/> NO <input checked="" type="checkbox"/> NA |
| <b>LAST CLEANING DATE</b>   |   | <b>CURRENT CLEANING DATE</b>                     |   | <b>NEXT CLEANING DATE</b>                |  |
|   |   | <u>14-07-2018</u>                                |   | <u>14-01-2019</u>                        |  |
| <b>CHEMICALS &amp; EQUIPMENTS USED</b>  |   |  |   |  |  |
| 1. <u>CARELA PRO 8 PLUS</u> Quantity <u>200 CC</u>  |   |  |   |  |  |
| 2. _____ Quantity _____   |   |  |   |  |  |
| <input checked="" type="checkbox"/> Submersibel Pump <input type="checkbox"/> High/Low Pressure Jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED lights <input checked="" type="checkbox"/> Foot Bath <input checked="" type="checkbox"/> Ladder<br><input checked="" type="checkbox"/> Ventilating Fan <input type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Meter <input checked="" type="checkbox"/> Vacuum Cleaner <input type="checkbox"/> Cleaning Materials |   |  |   |  |  |
| <b>COMMENTS &amp; RECOMMENDATIONS:</b>  |   |  |   |  |  |
| <u>TANK CLEANED AND DISINFECTED</u>   |   |  |   |  |  |
| Crystalline Representative: <u>NETALIST</u>   |   |  | Signature: <u>[Signature]</u>                 |  |  |



Date of Cleaning: 14-07-2018

**PHOTOGRAPHS**  
**ROOF TOP SINTEX WATER TANK (A &B) - 03 & 04**

**BEFORE**


**SINTEX WATER TANK(B) - 03**



**SINTEX WATER TANK(A) - 04**



**AFTER**





# CRYSTALLINE ENVIRONMENTAL SERVICES

## WATER TANK - AFTER SERVICE REPORT

15959

|  |   |  |   |   |  |
|--|---|--|---|---|--|
| CUSTOMER: <u>COFFELY BEST</u>  |   |  | CONTACT PERSON: <u>MR. JAVIER</u>             |   |  |
| SITE DETAILS: <u>HCT WOMEN'S SCHOOL ALHAIH</u>   |   |  | CONTACT NO: <u>0561883075</u>                 |   |  |
| TANK DETAILS: <u>POLYCON DOMESTIC TANK 05</u>  |   |  | LOCATION DETAILS: <u>BLOCK A- ROOF TOP</u>    |   |  |
| TYPE OF BUILDING: <input checked="" type="checkbox"/> COMMERCIAL   |   | <input type="checkbox"/> RESIDENTIAL             |   | <input type="checkbox"/> OTHERS         |  |
| <b>TYPE OF TANK</b>  |   |  |   |   |  |
| <input type="checkbox"/> CONCRETE  | <input type="checkbox"/> GRP PANEL        | <input type="checkbox"/> FRP TANK                | <input type="checkbox"/> GALVANIZED           | <input type="checkbox"/> STEEL PANEL    | <input type="checkbox"/> PLASTIC                                   |
| <input type="checkbox"/> CONCRETE COATED   |   | <input checked="" type="checkbox"/> POLYURETHANE | <input type="checkbox"/> OTHERS               |   |  |
| <b>SIZE OF TANK</b>  |   |  | <b>QUANTITY OF WATER</b>                      |   |  |
| M3   | USG                                       | L*B*H  | <input checked="" type="checkbox"/> FULL      | <input type="checkbox"/> HALF           | <input type="checkbox"/> EMPTY                                     |
| <b>CONDITION OF WATER TANK BEFORE CLEANING</b>   |   |  | <b>CONDITION OF WATER TANK AFTER CLEANING</b> |   |  |
| <input type="checkbox"/> CLEAN   | <input checked="" type="checkbox"/> DIRTY | <input type="checkbox"/> VERY DIRTY              | <input checked="" type="checkbox"/> CLEAN     | <input type="checkbox"/> DIRTY          | <input type="checkbox"/> VERY DIRTY                                |
| <input type="checkbox"/> BIOFILMS  | <input type="checkbox"/> MOULDS           | <input type="checkbox"/> SLIME                   | <input type="checkbox"/> BIOFILMS             | <input type="checkbox"/> MOULDS         | <input type="checkbox"/> SLIME                                     |
| <input type="checkbox"/> SEDIMENTS   | <input type="checkbox"/> MUD & SAND       | <input type="checkbox"/> RUST                    | <input type="checkbox"/> SEDIMENTS            | <input type="checkbox"/> MUD & SAND     | <input type="checkbox"/> RUST                                      |
| <b>ACCESS</b>  |   | <b>MANHOLE</b>                                   |   | <input type="checkbox"/> COVERED        | <input type="checkbox"/> DAMAGED                                   |
| <input type="checkbox"/> NA  |   |  |   |   | <input type="checkbox"/> NA  |
| <b>LADDER IN</b>   |   | <b>LADDER OUT</b>                                |   | <b>LEAKS</b>                            |  |
| <input checked="" type="checkbox"/> YES  | <input type="checkbox"/> NO               | <input checked="" type="checkbox"/> YES          | <input type="checkbox"/> NO                   | <input type="checkbox"/> YES            | <input checked="" type="checkbox"/> NO                             |
| <b>DRAIN LINE</b>  |   | <b>VALVES</b>                                    |   | <b>FLOAT VALVE</b>                      |  |
| <input type="checkbox"/> YES   | <input checked="" type="checkbox"/> NO    | <input checked="" type="checkbox"/> YES          | <input type="checkbox"/> NO                   | <input checked="" type="checkbox"/> YES | <input type="checkbox"/> NO  |
| <b>TANK CLEANED</b>  |   | <b>TANK DISINFECTED</b>                          |   | <b>PIPES DISINFECTED</b>                |  |
| <input checked="" type="checkbox"/> YES  | <input type="checkbox"/> NO               | <input checked="" type="checkbox"/> YES          | <input type="checkbox"/> NO                   | <input type="checkbox"/> YES            | <input type="checkbox"/> NO <input checked="" type="checkbox"/> NA |
| <b>LAST CLEANING DATE</b>  |   | <b>CURRENT CLEANING DATE</b>                     |   | <b>NEXT CLEANING DATE</b>               |  |
|  |   | <u>14-07-2018</u>                                |   | <u>14-01-2019</u>                       |  |
| <b>CHEMICALS &amp; EQUIPMENTS USED</b>   |   |  |   |   |  |
| 1. <u>GAAGLA PRO 8 PLUS</u> Quantity <u>200cc</u>  |   |  |   |   |  |
| 2. _____ Quantity _____  |   |  |   |   |  |
| <input checked="" type="checkbox"/> Submersibel Pump <input checked="" type="checkbox"/> High/Low Pressure Jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED lights <input checked="" type="checkbox"/> Foot Bath <input checked="" type="checkbox"/> Ladder<br><input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Meter <input checked="" type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials |   |  |   |   |  |
| <b>COMMENTS &amp; RECOMMENDATIONS:</b>   |   |  |   |   |  |
| <u>TANK CLEANED AND DISINFECTED</u>  |   |  |   |   |  |
| Crystalline Representative: <u>VETALIST</u>  |   |  | Signature: <u>[Signature]</u>                 |   |  |



# CRYSTALLINE ENVIRONMENTAL SERVICES

## WATER TANK - AFTER SERVICE REPORT

15960


|  |   |  |   |   |  |
|--|---|--|---|---|--|
| CUSTOMER: <u>COFELY BESIR</u>  |   |  | CONTACT PERSON: <u>MIR XAVIAR</u>             |   |  |
| SITE DETAILS:<br><u>HCT WOMAN'S SCHOOL KALAM</u>   |   |  | CONTACT NO:<br><u>0561883075</u>              |   |  |
| TANK DETAILS: <u>POLYCON DOMESTIC TANK 06</u>  |   |  | LOCATION DETAILS: <u>BLOCK 14 ROOF TOP</u>    |   |  |
| TYPE OF BUILDING: <input checked="" type="checkbox"/> COMMERCIAL   |   | <input type="checkbox"/> RESIDENTIAL             |   | <input type="checkbox"/> OTHERS         |  |
| <b>TYPE OF TANK</b>  |   |  |   |   |  |
| <input type="checkbox"/> CONCRETE  | <input type="checkbox"/> GRP PANEL        | <input type="checkbox"/> FRP TANK                | <input type="checkbox"/> GALVANIZED           | <input type="checkbox"/> STEEL PANEL    | <input type="checkbox"/> PLASTIC                                   |
| <input type="checkbox"/> CONCRETE COATED   |   | <input checked="" type="checkbox"/> POLYURETHANE | <input type="checkbox"/> OTHERS               |   |  |
| <b>SIZE OF TANK</b>  |   |  | <b>QUANTITY OF WATER</b>                      |   |  |
| M3   | USG                                       | L*B*H  | <input checked="" type="checkbox"/> FULL      | <input type="checkbox"/> HALF           | <input type="checkbox"/> EMPTY                                     |
| <b>CONDITION OF WATER TANK BEFORE CLEANING</b>   |   |  | <b>CONDITION OF WATER TANK AFTER CLEANING</b> |   |  |
| <input type="checkbox"/> CLEAN   | <input checked="" type="checkbox"/> DIRTY | <input type="checkbox"/> VERY DIRTY              | <input checked="" type="checkbox"/> CLEAN     | <input type="checkbox"/> DIRTY          | <input type="checkbox"/> VERY DIRTY                                |
| <input type="checkbox"/> BIOFILMS  | <input type="checkbox"/> MOULDS           | <input type="checkbox"/> SLIME                   | <input type="checkbox"/> BIOFILMS             | <input type="checkbox"/> MOULDS         | <input type="checkbox"/> SLIME                                     |
| <input type="checkbox"/> SEDIMENTS   | <input type="checkbox"/> MUD & SAND       | <input type="checkbox"/> RUST                    | <input type="checkbox"/> SEDIMENTS            | <input type="checkbox"/> MUD & SAND     | <input type="checkbox"/> RUST                                      |
| <b>ACCESS</b>  |   | <b>MANHOLE</b>                                   |   | <input type="checkbox"/> COVERED        | <input type="checkbox"/> DAMAGED                                   |
| <input type="checkbox"/> NA  |   |  |   |   | <input type="checkbox"/> NA  |
| <b>LADDER IN</b>   |   | <b>LADDER OUT</b>                                |   | <b>LEAKS</b>                            |  |
| <input checked="" type="checkbox"/> YES  | <input type="checkbox"/> NO               | <input checked="" type="checkbox"/> YES          | <input type="checkbox"/> NO                   | <input type="checkbox"/> YES            | <input checked="" type="checkbox"/> NO                             |
| <b>DRAIN LINE</b>  |   | <b>VALVES</b>                                    |   | <b>FLOAT VALVE</b>                      |  |
| <input type="checkbox"/> YES   | <input checked="" type="checkbox"/> NO    | <input checked="" type="checkbox"/> YES          | <input type="checkbox"/> NO                   | <input checked="" type="checkbox"/> YES | <input type="checkbox"/> NO  |
| <b>TANK CLEANED</b>  |   | <b>TANK DISINFECTED</b>                          |   | <b>PIPES DISINFECTED</b>                |  |
| <input checked="" type="checkbox"/> YES  | <input type="checkbox"/> NO               | <input checked="" type="checkbox"/> YES          | <input type="checkbox"/> NO                   | <input type="checkbox"/> YES            | <input type="checkbox"/> NO <input checked="" type="checkbox"/> NA |
| <b>LAST CLEANING DATE</b>  |   | <b>CURRENT CLEANING DATE</b>                     |   | <b>NEXT CLEANING DATE</b>               |  |
|  |   | <u>14-07-2018</u>                                |   | <u>14-01-2019</u>                       |  |
| <b>CHEMICALS &amp; EQUIPMENTS USED</b>   |   |  |   |   |  |
| 1. <u>CARELA BIO &amp; PLUS</u> Quantity <u>300 CC</u>   |   |  |   |   |  |
| 2. _____ Quantity _____  |   |  |   |   |  |
| <input checked="" type="checkbox"/> Submersibel Pump <input checked="" type="checkbox"/> High/Low Pressure Jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED lights <input checked="" type="checkbox"/> Foot Bath <input checked="" type="checkbox"/> Ladder<br><input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Meter <input checked="" type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials |   |  |   |   |  |
| <b>COMMENTS &amp; RECOMMENDATIONS:</b>   |   |  |   |   |  |
| <u>TANK CLEANED AND DISINFECTED</u>  |   |  |   |   |  |
| Crystalline Representative: <u>VETRUST</u>   |   |  | Signature: <u>[Signature]</u>                 |   |  |

Date of Cleaning: 14-07-2018

**PHOTOGRAPHS**  
**ROOF TOP SINTEX WATER TANK (A) - 05 & 06**

**BEFORE**


**SINTEX WATER TANK - 05**



**SINTEX WATER TANK - 06**



**AFTER**





# CRYSTALLINE ENVIRONMENTAL SERVICES

## WATER TANK - AFTER SERVICE REPORT

15961

|  |   |   |   |                                      |  |
|--|---|---|---|--------------------------------------|--|
| CUSTOMER: <u>COFFEY BLESIE</u>   |   |   | CONTACT PERSON: <u>MR J PVHAR</u>             |                                      |  |
| SITE DETAILS: <u>HCT WOMEN'S SCHOOL ALAIN</u>  |   |   | CONTACT NO: <u>0561883075-</u>                |                                      |  |
| TANK DETAILS: <u>GRP DOMESTIC TANK OF</u>  |   |   | LOCATION DETAILS: <u>BLOCK'S ROOF TOP</u>     |                                      |  |
| TYPE OF BUILDING: <input checked="" type="checkbox"/> COMMERCIAL   |   | <input type="checkbox"/> RESIDENTIAL    |   | <input type="checkbox"/> OTHERS      |  |
| <b>TYPE OF TANK</b>  |   |   |   |                                      |  |
| <input type="checkbox"/> CONCRETE  | <input checked="" type="checkbox"/> GRP PANEL | <input type="checkbox"/> FRP TANK       | <input type="checkbox"/> GALVANIZED           | <input type="checkbox"/> STEEL PANEL | <input type="checkbox"/> PLASTIC                                   |
| <input type="checkbox"/> CONCRETE COATED   |   | <input type="checkbox"/> POLYURETHANE   | <input type="checkbox"/> OTHERS               |                                      |  |
| <b>SIZE OF TANK</b>  |   |   | <b>QUANTITY OF WATER</b>                      |                                      |  |
| M3   | USG   | L*B*H                                   | <input checked="" type="checkbox"/> FULL      | <input type="checkbox"/> HALF        | <input type="checkbox"/> EMPTY                                     |
| <b>CONDITION OF WATER TANK BEFORE CLEANING</b>   |   |   | <b>CONDITION OF WATER TANK AFTER CLEANING</b> |                                      |  |
| <input type="checkbox"/> CLEAN   | <input checked="" type="checkbox"/> DIRTY     | <input type="checkbox"/> VERY DIRTY     | <input checked="" type="checkbox"/> CLEAN     | <input type="checkbox"/> DIRTY       | <input type="checkbox"/> VERY DIRTY                                |
| <input type="checkbox"/> BIOFILMS  | <input type="checkbox"/> MOULDS               | <input type="checkbox"/> SLIME          | <input type="checkbox"/> BIOFILMS             | <input type="checkbox"/> MOULDS      | <input type="checkbox"/> SLIME                                     |
| <input type="checkbox"/> SEDIMENTS   | <input type="checkbox"/> MUD & SAND           | <input type="checkbox"/> RUST           | <input type="checkbox"/> SEDIMENTS            | <input type="checkbox"/> MUD & SAND  | <input type="checkbox"/> RUST                                      |
| <b>ACCESS</b>  |   | <b>MANHOLE</b>                          |   | <input type="checkbox"/> COVERED     | <input type="checkbox"/> DAMAGED                                   |
| <input type="checkbox"/> NA  | <input type="checkbox"/> NA                   | <input type="checkbox"/> NA             | <input type="checkbox"/> NA                   | <input type="checkbox"/> NA          | <input type="checkbox"/> NA  |
| <b>LADDER IN</b>   |   | <b>LADDER OUT</b>                       |   | <b>LEAKS</b>                         |  |
| <input checked="" type="checkbox"/> YES  | <input type="checkbox"/> NO                   | <input checked="" type="checkbox"/> YES | <input type="checkbox"/> NO                   | <input type="checkbox"/> YES         | <input checked="" type="checkbox"/> NO                             |
| <b>TANK CLEANED</b>  |   | <b>TANK DISINFECTED</b>                 |   | <b>PIPES DISINFECTED</b>             |  |
| <input checked="" type="checkbox"/> YES  | <input type="checkbox"/> NO                   | <input checked="" type="checkbox"/> YES | <input type="checkbox"/> NO                   | <input type="checkbox"/> YES         | <input type="checkbox"/> NO <input checked="" type="checkbox"/> NA |
| <b>LAST CLEANING DATE</b>  |   | <b>CURRENT CLEANING DATE</b>            |   | <b>NEXT CLEANING DATE</b>            |  |
|  |   | <u>14-07-2018</u>                       |   | <u>14-01-2019</u>                    |  |
| <b>CHEMICALS &amp; EQUIPMENTS USED</b>   |   |   |   |                                      |  |
| 1. <u>CARLELA PRO 8 PLUS</u> Quantity <u>300 CC</u>  |   |   |   |                                      |  |
| 2. _____ Quantity _____  |   |   |   |                                      |  |
| <input checked="" type="checkbox"/> Submersibel Pump <input checked="" type="checkbox"/> High/Low Pressure Jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED lights <input checked="" type="checkbox"/> Foot Bath <input checked="" type="checkbox"/> Ladder<br><input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Meter <input checked="" type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials |   |   |   |                                      |  |
| <b>COMMENTS &amp; RECOMMENDATIONS:</b>   |   |   |   |                                      |  |
| <u>TANK CLEANED &amp; DISINFECTED</u>  |   |   |   |                                      |  |
| Crystalline Representative: <u>VE TALIST</u>   |   |   | Signature: <u>[Signature]</u>                 |                                      |  |



**CRYSTALLINE**  
ENVIRONMENTAL SERVICES

Date of Cleaning: 14-07-2018

**PHOTOGRAPHS**  
**ROOF TOP GRP WATER TANK (C) – I & II - 07**

**BEFORE**

**GRP WATER TANK (C) - I**



**GRP WATER TANK(C) - II**



**AFTER**



**CLEANER WATER GREENER TOMORROW**



# CRYSTALLINE ENVIRONMENTAL SERVICES

## WATER TANK - AFTER SERVICE REPORT

15962

| CUSTOMER: <u>COFELY BESI.E</u>                                      |   |   | CONTACT PERSON: <u>MR. ELKVIKAR</u>                                 |   |   |
|---|---|---|---|---|---|
| SITE DETAILS:<br><u>HCT WOMEN'S SCHOOL KALAIN</u>                   |   |   | CONTACT NO:<br><u>0561883075</u>                                    |   |   |
| TANK DETAILS: <u>POLYCON DOMESTIC T. N.08</u>                       |   |   | LOCATION DETAILS: <u>BLOCK D ROOF TOP</u>                           |   |   |
| TYPE OF BUILDING: <input checked="" type="checkbox"/> COMMERCIAL    |   | <input type="checkbox"/> RESIDENTIAL                                |   | <input type="checkbox"/> OTHERS                                     |   |
| TYPE OF TANK  |   |   |   |   |   |
| <input type="checkbox"/> CONCRETE                                   | <input type="checkbox"/> GRP PANEL                                  | <input type="checkbox"/> FRP TANK                                   | <input type="checkbox"/> GALVANIZED                                 | <input type="checkbox"/> STEEL PANEL                                | <input type="checkbox"/> PLASTIC                                    |
| <input type="checkbox"/> CONCRETE COATED                            |   | <input checked="" type="checkbox"/> POLYURETHANE                    | <input type="checkbox"/> OTHERS                                     |   |   |
| SIZE OF TANK  |   |   | QUANTITY OF WATER   |   |   |
| M3  | USG   | L*B*H   | <input checked="" type="checkbox"/> FULL                            | <input type="checkbox"/> HALF                                       | <input type="checkbox"/> EMPTY                                      |
| CONDITION OF WATER TANK BEFORE CLEANING                             |   |   | CONDITION OF WATER TANK AFTER CLEANING                              |   |   |
| <input type="checkbox"/> CLEAN                                      | <input checked="" type="checkbox"/> DIRTY                           | <input type="checkbox"/> VERY DIRTY                                 | <input checked="" type="checkbox"/> CLEAN                           | <input type="checkbox"/> DIRTY                                      | <input type="checkbox"/> VERY DIRTY                                 |
| <input type="checkbox"/> BIOFILMS                                   | <input type="checkbox"/> MOULDS                                     | <input type="checkbox"/> SLIME                                      | <input type="checkbox"/> BIOFILMS                                   | <input type="checkbox"/> MOULDS                                     | <input type="checkbox"/> SLIME                                      |
| <input type="checkbox"/> SEDIMENTS                                  | <input type="checkbox"/> MUD & SAND                                 | <input type="checkbox"/> RUST                                       | <input type="checkbox"/> SEDIMENTS                                  | <input type="checkbox"/> MUD & SAND                                 | <input type="checkbox"/> RUST                                       |
| ACCESS  |   | MANHOLE   |   | <input type="checkbox"/> COVERED                                    | <input type="checkbox"/> DAMAGED                                    |
| <input type="checkbox"/> LADDER IN                                  | <input type="checkbox"/> LADDER OUT                                 | <input type="checkbox"/> LEAKS                                      | <input type="checkbox"/> DRAIN LINE                                 | <input type="checkbox"/> VALVES                                     | <input type="checkbox"/> FLOAT VALVE                                |
| <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO |
| TANK CLEANED  |   | TANK DISINFECTED  |   | PIPES DISINFECTED   |   |
| <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO | <input type="checkbox"/> YES <input type="checkbox"/> NO            | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO | <input type="checkbox"/> YES <input type="checkbox"/> NO            | <input type="checkbox"/> YES <input type="checkbox"/> NO            | <input checked="" type="checkbox"/> NA                              |
| LAST CLEANING DATE  |   | CURRENT CLEANING DATE   |   | NEXT CLEANING DATE  |   |
|   |   | <u>14-07-2018</u>   |   | <u>14-01-2019</u>   |   |
| CHEMICALS & EQUIPMENTS USED   |   |   |   |   |   |
| 1. <u>CHARLEA B20 PLUS</u> Quantity <u>200cc</u>                    |   |   |   |   |   |
| 2. _____ Quantity _____   |   |   |   |   |   |
| <input checked="" type="checkbox"/> Submersibel Pump                | <input checked="" type="checkbox"/> High/Low Pressure Jet           | <input checked="" type="checkbox"/> Extension Cords                 | <input checked="" type="checkbox"/> LED lights                      | <input checked="" type="checkbox"/> Foot Bath                       | <input checked="" type="checkbox"/> Ladder                          |
| <input checked="" type="checkbox"/> Ventilating Fan                 | <input checked="" type="checkbox"/> Suction/Discharge Hoses         | <input checked="" type="checkbox"/> Oxygen Meter                    | <input checked="" type="checkbox"/> Vacuum Cleaner                  | <input checked="" type="checkbox"/> Cleaning Materials              |   |
| COMMENTS & RECOMMENDATIONS:   |   |   |   |   |   |
| <u>TANK CLEANED AND DISINFECTED</u>                                 |   |   |   |   |   |
| Crystalline Representative: <u>VETALUST</u>                         |   |   | Signature: <u>[Signature]</u>                                       |   |   |



# CRYSTALLINE ENVIRONMENTAL SERVICES

## WATER TANK - AFTER SERVICE REPORT

15963


| CUSTOMER: <u>COFFLY BESI</u>  |   |   | CONTACT PERSON: <u>MR LAVIAR</u>                                    |   |   |
|---|---|---|---|---|---|
| SITE DETAILS:<br><u>HCT WOMEN'S SCHOOL PLAIN</u>                    |   |   | CONTACT NO:<br><u>0561883075</u>                                    |   |   |
| TANK DETAILS: <u>POLYCOM DOMESTIC T. 09</u>                         |   |   | LOCATION DETAILS: <u>BLOCK 9 ROOF TOP</u>                           |   |   |
| TYPE OF BUILDING: <input checked="" type="checkbox"/> COMMERCIAL    |   |   | <input type="checkbox"/> RESIDENTIAL                                |   | <input type="checkbox"/> OTHERS                                     |
| TYPE OF TANK  |   |   |   |   |   |
| <input type="checkbox"/> CONCRETE                                   | <input type="checkbox"/> GRP PANEL                                  | <input type="checkbox"/> FRP TANK                                   | <input type="checkbox"/> GALVANIZED                                 | <input type="checkbox"/> STEEL PANEL  | <input type="checkbox"/> PLASTIC                                    |
| <input type="checkbox"/> CONCRETE COATED                            |   | <input checked="" type="checkbox"/> POLYURETHANE                    | <input type="checkbox"/> OTHERS                                     |   |   |
| SIZE OF TANK  |   |   | QUANTITY OF WATER   |   |   |
| M3  | USG   | L*B*H   | <input checked="" type="checkbox"/> FULL                            | <input type="checkbox"/> HALF   | <input type="checkbox"/> EMPTY                                      |
| CONDITION OF WATER TANK BEFORE CLEANING                             |   |   | CONDITION OF WATER TANK AFTER CLEANING                              |   |   |
| <input type="checkbox"/> CLEAN                                      | <input checked="" type="checkbox"/> DIRTY                           | <input type="checkbox"/> VERY DIRTY                                 | <input checked="" type="checkbox"/> CLEAN                           | <input type="checkbox"/> DIRTY  | <input type="checkbox"/> VERY DIRTY                                 |
| <input type="checkbox"/> BIOFILMS                                   | <input type="checkbox"/> MOULDS                                     | <input type="checkbox"/> SLIME                                      | <input type="checkbox"/> BIOFILMS                                   | <input type="checkbox"/> MOULDS   | <input type="checkbox"/> SLIME                                      |
| <input type="checkbox"/> SEDIMENTS                                  | <input type="checkbox"/> MUD & SAND                                 | <input type="checkbox"/> RUST                                       | <input type="checkbox"/> SEDIMENTS                                  | <input type="checkbox"/> MUD & SAND   | <input type="checkbox"/> RUST                                       |
| ACCESS  |   | MANHOLE   | <input type="checkbox"/> COVERED                                    | <input type="checkbox"/> DAMAGED  | <input type="checkbox"/> NA   |
| LADDER IN   | LADDER OUT  | LEAKS   | DRAIN LINE  | VALVES  | FLOAT VALVE   |
| <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO                             | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO |
| TANK CLEANED  |   | TANK DISINFECTED  |   | PIPES DISINFECTED   |   |
| <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO | <input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> NA |   |
| LAST CLEANING DATE  |   | CURRENT CLEANING DATE   |   | NEXT CLEANING DATE  |   |
|   |   | <u>14-07-2018</u>   |   | <u>14-01-2019</u>   |   |
| CHEMICALS & EQUIPMENTS USED   |   |   |   |   |   |
| 1. <u>CARELIA B10 &amp; PLUS</u> Quantity <u>200 cc</u>             |   |   |   |   |   |
| 2. _____ Quantity _____   |   |   |   |   |   |
| <input checked="" type="checkbox"/> Submersibel Pump                | <input checked="" type="checkbox"/> High/Low Pressure Jet           | <input checked="" type="checkbox"/> Extension Cords                 | <input checked="" type="checkbox"/> LED lights                      | <input checked="" type="checkbox"/> Foot Bath   | <input checked="" type="checkbox"/> Ladder                          |
| <input checked="" type="checkbox"/> Ventilating Fan                 | <input checked="" type="checkbox"/> Suction/Discharge Hoses         | <input checked="" type="checkbox"/> Oxygen Meter                    | <input checked="" type="checkbox"/> Vacuum Cleaner                  | <input checked="" type="checkbox"/> Cleaning Materials  |   |
| COMMENTS & RECOMMENDATIONS:   |   |   |   |   |   |
| <u>TANK CLEANED AND DISINFECTED</u>                                 |   |   |   |   |   |
| Crystalline Representative: <u>VEITALIST</u>                        |   |   | Signature: <u>[Signature]</u>                                       |   |   |

Date of Cleaning: 14-07-2018


**PHOTOGRAPHS**  
**ROOF TOP SINTEX WATER TANK(D) - 08 & 09**

**BEFORE**



**SINTEX WATER TANK - 08**



**SINTEX WATER TANK - 09**



**AFTER**





# CRYSTALLINE ENVIRONMENTAL SERVICES

## WATER TANK - AFTER SERVICE REPORT


15964

|  |   |   |  |  |  |
|--|---|---|--|--|--|
| CUSTOMER: <u>COFELY BESIDE</u>                                   |   |   | CONTACT PERSON: <u>MR. S. P. VIKAR</u>         |  |  |
| SITE DETAILS:<br><u>HCT WOMEN'S SCHOOL ALHAIN</u>                |   |   | CONTACT NO: <u>0561883075</u>                  |  |  |
| TANK DETAILS: <u>GRP DOMESTIC TANK: 10</u>                       |   |   | LOCATION DETAILS: <u>CAFETERIA ROOF TOP</u>    |  |  |
| TYPE OF BUILDING: <input checked="" type="checkbox"/> COMMERCIAL |   | <input type="checkbox"/> RESIDENTIAL                |  | <input type="checkbox"/> OTHERS                        |  |
| <b>TYPE OF TANK</b>  |   |   |  |  |  |
| <input type="checkbox"/> CONCRETE                                | <input checked="" type="checkbox"/> GRP PANEL             | <input type="checkbox"/> FRP TANK                   | <input type="checkbox"/> GALVANIZED            | <input type="checkbox"/> STEEL PANEL                   | <input type="checkbox"/> PLASTIC                                   |
| <input type="checkbox"/> CONCRETE COATED                         |   | <input type="checkbox"/> POLYURETHANE               | <input type="checkbox"/> OTHERS                |  |  |
| <b>SIZE OF TANK</b>  |   |   | <b>QUANTITY OF WATER</b>                       |  |  |
| M3   | USG   | L*B*H   | <input checked="" type="checkbox"/> FULL       | <input type="checkbox"/> HALF                          | <input type="checkbox"/> EMPTY                                     |
| <b>CONDITION OF WATER TANK BEFORE CLEANING</b>                   |   |   | <b>CONDITION OF WATER TANK AFTER CLEANING</b>  |  |  |
| <input type="checkbox"/> CLEAN                                   | <input checked="" type="checkbox"/> DIRTY                 | <input type="checkbox"/> VERY DIRTY                 | <input checked="" type="checkbox"/> CLEAN      | <input type="checkbox"/> DIRTY                         | <input type="checkbox"/> VERY DIRTY                                |
| <input type="checkbox"/> BIOFILMS                                | <input type="checkbox"/> MOULDS                           | <input type="checkbox"/> SLIME                      | <input type="checkbox"/> BIOFILMS              | <input type="checkbox"/> MOULDS                        | <input type="checkbox"/> SLIME                                     |
| <input type="checkbox"/> SEDIMENTS                               | <input type="checkbox"/> MUD & SAND                       | <input type="checkbox"/> RUST                       | <input type="checkbox"/> SEDIMENTS             | <input type="checkbox"/> MUD & SAND                    | <input type="checkbox"/> RUST                                      |
| <b>ACCESS</b>  |   | <b>MANHOLE</b>                                      |  | <input type="checkbox"/> COVERED                       | <input type="checkbox"/> DAMAGED                                   |
| <input type="checkbox"/> NA                                      |   |   |  |  | <input type="checkbox"/> NA  |
| <b>LADDER IN</b>   |   | <b>LADDER OUT</b>                                   |  | <b>LEAKS</b>   |  |
| <input checked="" type="checkbox"/> YES                          | <input type="checkbox"/> NO                               | <input checked="" type="checkbox"/> YES             | <input type="checkbox"/> NO                    | <input type="checkbox"/> YES                           | <input checked="" type="checkbox"/> NO                             |
| <b>TANK CLEANED</b>  |   | <b>TANK DISINFECTED</b>                             |  | <b>PIPES DISINFECTED</b>                               |  |
| <input checked="" type="checkbox"/> YES                          | <input type="checkbox"/> NO                               | <input checked="" type="checkbox"/> YES             | <input type="checkbox"/> NO                    | <input type="checkbox"/> YES                           | <input type="checkbox"/> NO <input checked="" type="checkbox"/> NA |
| <b>LAST CLEANING DATE</b>  |   | <b>CURRENT CLEANING DATE</b>                        |  | <b>NEXT CLEANING DATE</b>                              |  |
|  |   | <u>14-07-2018</u>                                   |  | <u>14-01-2019</u>                                      |  |
| <b>CHEMICALS &amp; EQUIPMENTS USED</b>                           |   |   |  |  |  |
| 1. <u>CHARLETA B20 &amp; PLUS</u> Quantity <u>1000cc</u>         |   |   |  |  |  |
| 2. _____ Quantity _____  |   |   |  |  |  |
| <input checked="" type="checkbox"/> Submersibel Pump             | <input checked="" type="checkbox"/> High/Low Pressure Jet | <input checked="" type="checkbox"/> Extension Cords | <input checked="" type="checkbox"/> LED lights | <input checked="" type="checkbox"/> Foot Bath          | <input checked="" type="checkbox"/> Ladder                         |
| <input checked="" type="checkbox"/> Ventilating Fan              | <input type="checkbox"/> Suction/Discharge Hoses          | <input type="checkbox"/> Oxygen Meter               | <input type="checkbox"/> Vacuum Cleaner        | <input checked="" type="checkbox"/> Cleaning Materials |  |
| <b>COMMENTS &amp; RECOMMENDATIONS:</b>                           |   |   |  |  |  |
| <u>TANK CLEANED &amp; DISINFECTED</u>                            |   |   |  |  |  |
| Crystalline Representative: <u>NETALIST</u>                      |   |   | Signature: <u>[Signature]</u>                  |  |  |

Date of Cleaning: 14-07-2018

**PHOTOGRAPHS**  
**ROOF TOP GRP WATER TANK - 10**

**BEFORE**



**AFTER**





# CRYSTALLINE ENVIRONMENTAL SERVICES

## WATER TANK - AFTER SERVICE REPORT

15965

|  |   |   |  |  |  |
|--|---|---|--|--|--|
| CUSTOMER: <u>COFELY BESI X</u>   |   |   | CONTACT PERSON: <u>MR. BLAVIAR</u>             |  |  |
| SITE DETAILS:<br><u>HCT WOMEN'S SCHOOL KILAIN</u>  |   |   | CONTACT NO:<br><u>0561883075</u>               |  |  |
| TANK DETAILS: <u>FIBER DOMESTIC T. #11</u>   |   |   | LOCATION DETAILS: <u>SECURITY G. ROOF TOP</u>  |  |  |
| TYPE OF BUILDING: <input checked="" type="checkbox"/> COMMERCIAL   |   | <input type="checkbox"/> RESIDENTIAL    | <input type="checkbox"/> OTHERS                |  |  |
| <u>TYPE OF TANK</u>  |   |   |  |  |  |
| <input type="checkbox"/> CONCRETE  | <input type="checkbox"/> GRP PANEL        | <input type="checkbox"/> FRP TANK       | <input checked="" type="checkbox"/> GALVANIZED | <input type="checkbox"/> STEEL PANEL     | <input type="checkbox"/> PLASTIC       |
| <input type="checkbox"/> CONCRETE COATED   |   | <input type="checkbox"/> POLYURETHANE   | <input type="checkbox"/> OTHERS                |  |  |
| <u>SIZE OF TANK</u>  |   |   | <u>QUANTITY OF WATER</u>                       |  |  |
| M3   | USG                                       | L*B*H                                   | <input type="checkbox"/> FULL                  | <input checked="" type="checkbox"/> HALF | <input type="checkbox"/> EMPTY         |
| <u>CONDITION OF WATER TANK BEFORE CLEANING</u>   |   |   | <u>CONDITION OF WATER TANK AFTER CLEANING</u>  |  |  |
| <input type="checkbox"/> CLEAN   | <input checked="" type="checkbox"/> DIRTY | <input type="checkbox"/> VERY DIRTY     | <input checked="" type="checkbox"/> CLEAN      | <input type="checkbox"/> DIRTY           | <input type="checkbox"/> VERY DIRTY    |
| <input type="checkbox"/> BIOFILMS  | <input type="checkbox"/> MOULDS           | <input type="checkbox"/> SLIME          | <input type="checkbox"/> BIOFILMS              | <input type="checkbox"/> MOULDS          | <input type="checkbox"/> SLIME         |
| <input type="checkbox"/> SEDIMENTS   | <input type="checkbox"/> MUD & SAND       | <input type="checkbox"/> RUST           | <input type="checkbox"/> SEDIMENTS             | <input type="checkbox"/> MUD & SAND      | <input type="checkbox"/> RUST          |
| <u>ACCESS</u>  |   | <u>MANHOLE</u>                          |  | <input type="checkbox"/> COVERED         | <input type="checkbox"/> DAMAGED       |
| <input type="checkbox"/> NA  |   |   |  |  |  |
| <u>LADDER IN</u>   |   | <u>LADDER OUT</u>                       |  | <u>LEAKS</u>                             |  |
| <input type="checkbox"/> YES   | <input checked="" type="checkbox"/> NO    | <input type="checkbox"/> YES            | <input checked="" type="checkbox"/> NO         | <input type="checkbox"/> YES             | <input checked="" type="checkbox"/> NO |
| <u>TANK CLEANED</u>  |   | <u>TANK DISINFECTED</u>                 |  | <u>PIPES DISINFECTED</u>                 |  |
| <input checked="" type="checkbox"/> YES  | <input type="checkbox"/> NO               | <input checked="" type="checkbox"/> YES | <input type="checkbox"/> NO                    | <input type="checkbox"/> YES             | <input type="checkbox"/> NO            |
| <u>LAST CLEANING DATE</u>  |   | <u>CURRENT CLEANING DATE</u>            |  | <u>NEXT CLEANING DATE</u>                |  |
|  |   | <u>14-07-2018</u>                       |  | <u>14-01-2019</u>                        |  |
| <u>CHEMICALS &amp; EQUIPMENTS USED</u>   |   |   |  |  |  |
| 1. <u>CARELA BIO 8 PLUS</u> Quantity <u>200cc</u>  |   |   |  |  |  |
| 2. _____ Quantity _____  |   |   |  |  |  |
| <input checked="" type="checkbox"/> Submersibel Pump <input checked="" type="checkbox"/> High/Low Pressure Jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED lights <input checked="" type="checkbox"/> Foot Bath <input checked="" type="checkbox"/> Ladder |   |   |  |  |  |
| <input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Meter <input checked="" type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials                                 |   |   |  |  |  |
| <u>COMMENTS &amp; RECOMMENDATIONS:</u>   |   |   |  |  |  |
| <u>TANK CLEANED AND DISINFECTED</u>  |   |   |  |  |  |
| Crystalline Representative: <u>VICTOR LUST</u>   |   |   | Signature: <u>[Signature]</u>                  |  |  |



# CRYSTALLINE ENVIRONMENTAL SERVICES

## WATER TANK - AFTER SERVICE REPORT

15966

|  |   |   |  |   |                                     |
|--|---|---|--|---|-------------------------------------|
| CUSTOMER: <u>COFELY BESIDE</u>   |   |   | CONTACT PERSON: <u>MR. JAVIAR</u>              |   |                                     |
| SITE DETAILS:<br><u>HCT WOMEN'S SCHOOL ALHAIN</u>  |   |   | CONTACT NO: <u>0561883075</u>                  |   |                                     |
| TANK DETAILS: <u>FIBER DOMESTIC T-N-12</u>   |   |   | LOCATION DETAILS: <u>SECURITY G- ROOF.T</u>    |   |                                     |
| TYPE OF BUILDING: <input checked="" type="checkbox"/> COMMERCIAL   |   | <input type="checkbox"/> RESIDENTIAL                                |  | <input type="checkbox"/> OTHERS   |                                     |
| <b>TYPE OF TANK</b>  |   |   |  |   |                                     |
| <input type="checkbox"/> CONCRETE  | <input type="checkbox"/> GRP PANEL        | <input type="checkbox"/> FRP TANK                                   | <input checked="" type="checkbox"/> GALVANIZED | <input type="checkbox"/> STEEL PANEL  | <input type="checkbox"/> PLASTIC    |
| <input type="checkbox"/> CONCRETE COATED   |   | <input type="checkbox"/> POLYURETHANE                               |  | <input type="checkbox"/> OTHERS   |                                     |
| <b>SIZE OF TANK</b>  |   |   | <b>QUANTITY OF WATER</b>                       |   |                                     |
| M3   | USG                                       | L*B*H   | <input type="checkbox"/> FULL                  | <input checked="" type="checkbox"/> HALF  | <input type="checkbox"/> EMPTY      |
| <b>CONDITION OF WATER TANK BEFORE CLEANING</b>   |   |   | <b>CONDITION OF WATER TANK AFTER CLEANING</b>  |   |                                     |
| <input type="checkbox"/> CLEAN   | <input checked="" type="checkbox"/> DIRTY | <input type="checkbox"/> VERY DIRTY                                 | <input checked="" type="checkbox"/> CLEAN      | <input type="checkbox"/> DIRTY  | <input type="checkbox"/> VERY DIRTY |
| <input type="checkbox"/> BIOFILMS  | <input type="checkbox"/> MOULDS           | <input type="checkbox"/> SLIME                                      | <input type="checkbox"/> BIOFILMS              | <input type="checkbox"/> MOULDS   | <input type="checkbox"/> SLIME      |
| <input type="checkbox"/> SEDIMENTS   | <input type="checkbox"/> MUD & SAND       | <input type="checkbox"/> RUST                                       | <input type="checkbox"/> SEDIMENTS             | <input type="checkbox"/> MUD & SAND   | <input type="checkbox"/> RUST       |
| <b>ACCESS</b>  |   | <b>MANHOLE</b>  |  | <input type="checkbox"/> COVERED  |                                     |
| <input type="checkbox"/> DAMAGED   |   | <input type="checkbox"/> NA   |  |   |                                     |
| <b>LADDER IN</b>   |   | <b>LADDER OUT</b>   |  | <b>LEAKS</b>  |                                     |
| <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO  |   | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |  | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO                             |                                     |
| <b>DRAIN LINE</b>  |   | <b>VALVES</b>   |  | <b>FLOAT VALVE</b>  |                                     |
| <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO  |   | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO |  | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO                             |                                     |
| <b>TANK CLEANED</b>  |   | <b>TANK DISINFECTED</b>   |  | <b>PIPES DISINFECTED</b>  |                                     |
| <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO  |   | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO |  | <input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> NA |                                     |
| <b>LAST CLEANING DATE</b>  |   | <b>CURRENT CLEANING DATE</b>  |  | <b>NEXT CLEANING DATE</b>   |                                     |
|  |   | <u>14-07-2018</u>   |  | <u>14-01-2019</u>   |                                     |
| <b>CHEMICALS &amp; EQUIPMENTS USED</b>   |   |   |  |   |                                     |
| 1. <u>CARELA B20 8 PLUS</u> Quantity <u>200 cc</u>   |   |   |  |   |                                     |
| 2. _____ Quantity _____  |   |   |  |   |                                     |
| <input checked="" type="checkbox"/> Submersibel Pump <input checked="" type="checkbox"/> High/Low Pressure Jet <input checked="" type="checkbox"/> Extension Cords <input checked="" type="checkbox"/> LED lights <input checked="" type="checkbox"/> Foot Bath <input checked="" type="checkbox"/> Ladder<br><input checked="" type="checkbox"/> Ventilating Fan <input checked="" type="checkbox"/> Suction/Discharge Hoses <input checked="" type="checkbox"/> Oxygen Meter <input checked="" type="checkbox"/> Vacuum Cleaner <input checked="" type="checkbox"/> Cleaning Materials |   |   |  |   |                                     |
| <b>COMMENTS &amp; RECOMMENDATIONS:</b>   |   |   |  |   |                                     |
| <u>TANK CLEANED AND DISINFECTED</u>  |   |   |  |   |                                     |
| Crystalline Representative: <u>METALLIST</u>   |   |   | Signature: <u>[Signature]</u>                  |   |                                     |

Date of Cleaning: 14-07-2018

**PHOTOGRAPHS**  
**ROOF TOP FRP WATER TANK- 11 & 12**

**BEFORE**

**FRP WATER TANK - 11**



**FRP WATER TANK - 12**



**AFTER**



**CLEANER WATER GREENER TOMORROW**

# CRYSTALLINE CLEANING & ENVIRONMENTAL SERVICES

## CLEANING & DISINFECTION CERTIFICATE

### POTABLE WATER TANKS

CLIENT NAME : COFELY BESIX FACILITY MANAGEMENT.  
CLIENT ADDRESS : P.O. BOX: 43139, ABU DHABI, UAE.  
CONTACT PERSON : MR. ABDUL SALAM.  
SITE DETAILS : HCT – AL AIN WOMEN'S COLLEGE,  
AL AIN, UAE.  
DETAILS : WATER TANK CLEANING  
DATE OF CLEANING : JULY 2018  
FREQUENCY OF CLEANING : EVERY SIX MONTHS  
DATE OF NEXT CLEANING : JANUARY 2019

*The procedures employed in this cleaning and disinfection comply with HS (G) 70 health and safety guidelines for prevention of legionella as well as BS6700 and CARELA BIO PLUS method statement.*

*The entire water storage tank should be cleaned and disinfected minimum every six (6) months depending upon the condition.*



CRYSTALLINE CLEANING AND ENVIRONMENTAL SERVICES