WATER TANK CLEANING
&
DISINFECTION

COMPLETION REPORT

FOR

COFELY BESIX
facility management

Client	:	COFELY BESIX FACILITY MANAGEMENT
Contact Person:		Mr. P.R.Xavier Senior MEP Supervisor
Site Details	:	HCT – Al Ain Men's & Women's College, Al Ain and Abu Dhabi Khalifa Campus, Abu Dhabi.
Date	:	15 August 2018

CRYSTALLINE
ENVIRONMENTAL SERVICES

CRYSTALLINE ENVIRONMENTAL SERVICES

P.O. BOX 131463, Abu Dhabi, U.A.E.

TEL: 02 6508930 FAX: 02 6508942

info@crystalline-uae.com

www.crystalline-uae.com

CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT

15954

CUSTOMER: COFELY BESIX	CONTACT PERSON: MR. XAVIAR
SITE DETAILS: HCT MEN'S CHALOOL ALAIN	CONTACT NO: 0561883075
TANK DETAILS: RCC MAIN TANK N: 01	LOCATION DETAILS: PUMP ROOM UNDER G.

TYPE OF BUILDING: ☑ COMMERCIAL ☐ RESIDENTIAL ☐ OTHERS

TYPE OF TANK

☑ CONCRETE	☐ GRP PANEL	☐ FRP TANK	☐ GALVANIZED	☐ STEEL PANEL	☐ PLASTIC
☐ CONCRETE COATED		☐ POLYURETHANE	☐ OTHERS		

SIZE OF TANK			QUANTITY OF WATER		
M3	USG	L*B*H	☐ FULL	☑ HALF	☐ EMPTY

CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK AFTER CLEANING		
☐ CLEAN	☑ DIRTY	☐ VERY DIRTY	☑ CLEAN	☐ DIRTY	☐ VERY DIRTY
☐ BIOFILMS	☐ MOULDS	☐ SLIME	☐ BIOFILMS	☐ MOULDS	☐ SLIME
☐ SEDIMENTS	☐ MUD & SAND	☐ RUST	☐ SEDIMENTS	☐ MUD & SAND	☐ RUST

ACCESS	MANHOLE			
	☐ COVERED	☐ DAMAGED	☐ NA	

LADDER IN		LADDER OUT		LEAKS		DRAIN LINE		VALVES		FLOAT VALVE	
☐ YES	☑ NO	☐ YES	☑ NO	☐ YES	☑ NO	☐ YES	☑ NO	☑ YES	☐ NO	☑ YES	☐ NO

TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED		
☑ YES	☐ NO	☑ YES	☐ NO	☐ YES	☐ NO	☑ NA

LAST CLEANING DATE	CURRENT CLEANING DATE	NEXT CLEANING DATE
	13-07-2018	13-01-2019

CHEMICALS & EQUIPMENTS USED

1. CAALFA BIO 8 PLUS — Quantity 4000 cc

2. _____ — Quantity _____

☑ Submersibel Pump ☑ High/Low Pressure Jet ☑ Extension Cords ☑ LED lights ☑ Foot Bath ☑ Ladder

☑ Ventilating Fan ☑ Suction/Discharge Hoses ☑ Oxygen Meter ☑ Vacuum Cleaner ☑ Cleaning Materials

COMMENTS & RECOMMENDATIONS:

TANK CLEANED AND DISINFECTED

Crystalline Representative: VITALIST — Signature:

Web: www.crystalline-uae.com
E-mail: info@crystalline-uae.com
Tel.: +971 55 7167017

CRYSTALLINE
ENVIRONMENTAL SERVICES

Date of Cleaning: 13-07-2018

PHOTOGRAPHS
UNDER GROUND RCC RCC WATER TANK - 01

BEFORE

AFTER

CLEANER WATER GREENER TOMORROW

CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT

15951

CUSTOMER: COFELY BESIX	CONTACT PERSON: MR. XAVIAR
SITE DETAILS: HCT MEN'S SCHOOL ALAIN	CONTACT NO: 0561883075
TANK DETAILS: GRP DOMESTIC TANK N.01	LOCATION DETAILS: SPOT COMPLEX ROOF TOP

TYPE OF BUILDING: ☑ COMMERCIAL ☐ RESIDENTIAL ☐ OTHERS

TYPE OF TANK

☐ CONCRETE	☑ GRP PANEL	☐ FRP TANK	☐ GALVANIZED	☐ STEEL PANEL	☐ PLASTIC
☐ CONCRETE COATED		☐ POLYURETHANE	☐ OTHERS		

SIZE OF TANK			QUANTITY OF WATER		
M3	USG	L*B*H	☑ FULL	☐ HALF	☐ EMPTY

CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK AFTER CLEANING		
☐ CLEAN	☑ DIRTY	☐ VERY DIRTY	☑ CLEAN	☐ DIRTY	☐ VERY DIRTY
☐ BIOFILMS	☐ MOULDS	☐ SLIME	☐ BIOFILMS	☐ MOULDS	☐ SLIME
☐ SEDIMENTS	☐ MUD & SAND	☐ RUST	☐ SEDIMENTS	☐ MUD & SAND	☐ RUST

ACCESS	MANHOLE			
		☐ COVERED	☐ DAMAGED	☐ NA

LADDER IN		LADDER OUT		LEAKS		DRAIN LINE		VALVES		FLOAT VALVE	
☑ YES	☐ NO	☑ YES	☐ NO	☐ YES	☑ NO	☑ YES	☐ NO	☑ YES	☐ NO	☑ YES	☐ NO

TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED		
☑ YES	☐ NO	☑ YES	☐ NO	☐ YES	☐ NO	☑ NA

LAST CLEANING DATE	CURRENT CLEANING DATE	NEXT CLEANING DATE
	15-07-2018	15-01-2019

CHEMICALS & EQUIPMENTS USED

1. CARELA BIO 8 PLUS — Quantity 300cc

2. _____ — Quantity _____

☑ Submersibel Pump ☑ High/Low Pressure Jet ☑ Extension Cords ☑ LED lights ☑ Foot Bath ☑ Ladder

☑ Ventilating Fan ☑ Suction/Discharge Hoses ☑ Oxygen Meter ☑ Vacuum Cleaner ☑ Cleaning Materials

COMMENTS & RECOMMENDATIONS:

TANK CLEANED AND DISINFECTED

Crystalline Representative: VETHUST — Signature:

Web: www.crystalline-uae.com
E-mail: info@crystalline-uae.com
Tel.: +971 55 7167017

CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT

15967

CUSTOMER: COFELY BESIX	CONTACT PERSON: MR. JAVIER
SITE DETAILS: HCT MEN'S SCHOOL AL AIN	CONTACT NO: 0561883075
TANK DETAILS: GRP DOMESTIC TANK N.02	LOCATION DETAILS: SPORT COMPLEX ROOF-T.

TYPE OF BUILDING: ☑ COMMERCIAL ☐ RESIDENTIAL ☐ OTHERS

TYPE OF TANK

☐ CONCRETE	☑ GRP PANEL	☐ FRP TANK	☐ GALVANIZED	☐ STEEL PANEL	☐ PLASTIC
☐ CONCRETE COATED		☐ POLYURETHANE	☐ OTHERS		

SIZE OF TANK			QUANTITY OF WATER		
M3	USG	L*B*H	☑ FULL	☐ HALF	☐ EMPTY

CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK AFTER CLEANING		
☐ CLEAN	☑ DIRTY	☐ VERY DIRTY	☑ CLEAN	☐ DIRTY	☐ VERY DIRTY
☐ BIOFILMS	☐ MOULDS	☐ SLIME	☐ BIOFILMS	☐ MOULDS	☐ SLIME
☐ SEDIMENTS	☐ MUD & SAND	☐ RUST	☐ SEDIMENTS	☐ MUD & SAND	☐ RUST

ACCESS	MANHOLE			
	☐ COVERED	☐ DAMAGED	☐ NA	

LADDER IN		LADDER OUT		LEAKS		DRAIN LINE		VALVES		FLOAT VALVE	
☑ YES	☐ NO	☑ YES	☐ NO	☐ YES	☑ NO	☑ YES	☐ NO	☑ YES	☐ NO	☑ YES	☐ NO

TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED		
☑ YES	☐ NO	☑ YES	☐ NO	☐ YES	☐ NO	☑ NA

LAST CLEANING DATE	CURRENT CLEANING DATE	NEXT CLEANING DATE
	15-07-2018	15-01-2019

CHEMICALS & EQUIPMENTS USED

1. CARELA BIO 8 PLUS — Quantity 3 DOCE

2. _____ — Quantity _____

☑ Submersibel Pump ☑ High/Low Pressure Jet ☑ Extension Cords ☑ LED lights ☑ Foot Bath ☑ Ladder

☑ Ventilating Fan ☑ Suction/Discharge Hoses ☑ Oxygen Meter ☑ Vacuum Cleaner ☑ Cleaning Materials

COMMENTS & RECOMMENDATIONS:

TANK CLEANED AND DISINFECTED

Crystalline Representative: VETHAST	Signature:

Web: www.crystalline-uae.com
E-mail: info@crystalline-uae.com
Tel.: +971 55 7167017

CRYSTALLINE
ENVIRONMENTAL SERVICES

Date of Cleaning: 15-07-2018

PHOTOGRAPHS
ROOF TOP GRP WATER TANK - 01 & 02

BEFORE

GRP WATER TANK - 01



GRP WATER TANK - 02

AFTER



CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT

15968

CUSTOMER: COFELY BESIX	CONTACT PERSON: MR. XAVIAR
SITE DETAILS: HCT MEN'S SCHOOL AL AIN	CONTACT NO: 0561883075
TANK DETAILS: GRP DOMESTIC TANK N.03	LOCATION DETAILS: FOUNDATION B. ROOF TOP

TYPE OF BUILDING: ☑ COMMERCIAL ☐ RESIDENTIAL ☐ OTHERS

TYPE OF TANK

☐ CONCRETE	☑ GRP PANEL	☐ FRP TANK	☐ GALVANIZED	☐ STEEL PANEL	☐ PLASTIC
☐ CONCRETE COATED		☐ POLYURETHANE	☐ OTHERS		

SIZE OF TANK			QUANTITY OF WATER		
M3	USG	L*B*H	☐ FULL	☑ HALF	☐ EMPTY

CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK AFTER CLEANING		
☐ CLEAN	☑ DIRTY	☐ VERY DIRTY	☑ CLEAN	☐ DIRTY	☐ VERY DIRTY
☐ BIOFILMS	☐ MOULDS	☐ SLIME	☐ BIOFILMS	☐ MOULDS	☐ SLIME
☐ SEDIMENTS	☐ MUD & SAND	☐ RUST	☐ SEDIMENTS	☐ MUD & SAND	☐ RUST

ACCESS	MANHOLE			
		☐ COVERED	☐ DAMAGED	☐ NA

LADDER IN		LADDER OUT		LEAKS		DRAIN LINE		VALVES		FLOAT VALVE	
☑ YES	☐ NO	☑ YES	☐ NO	☐ YES	☑ NO	☑ YES	☐ NO	☑ YES	☐ NO	☑ YES	☐ NO

TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED		
☑ YES	☐ NO	☑ YES	☐ NO	☐ YES	☐ NO	☑ NA

LAST CLEANING DATE	CURRENT CLEANING DATE	NEXT CLEANING DATE
	15-07-2018	15-01-2019

CHEMICALS & EQUIPMENTS USED

1. CARELA BIO 8 PLUS — Quantity 300 cc

2. _____ — Quantity _____

☑ Submersibel Pump ☑ High/Low Pressure Jet ☑ Extension Cords ☑ LED lights ☑ Foot Bath ☑ Ladder

☑ Ventilating Fan ☑ Suction/Discharge Hoses ☑ Oxygen Meter ☑ Vacuum Cleaner ☑ Cleaning Materials

COMMENTS & RECOMMENDATIONS:

TANK CLEANED AND DISINFECTED

Crystalline Representative: VETRIVEL — Signature:

Web: www.crystalline-uae.com
E-mail: info@crystalline-uae.com
Tel.: +971 55 7167017

CRYSTALLINE
ENVIRONMENTAL SERVICES

Date of Cleaning: 15-07-2018

PHOTOGRAPHS
ROOF TOP GRP WATER TANK - 03

BEFORE

AFTER



CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT

15969

CUSTOMER: COFELY BESIX	CONTACT PERSON: MR. SAMIAR
SITE DETAILS: HCT MEN'S SCHOOL ALAIN	CONTACT NO: 0561883075
TANK DETAILS: SINTEX DOMESTIC TANK 04	LOCATION DETAILS: MCK BUILDING R. TOP

TYPE OF BUILDING: ☑ COMMERCIAL ☐ RESIDENTIAL ☐ OTHERS

TYPE OF TANK

☐ CONCRETE	☐ GRP PANEL	☐ FRP TANK	☐ GALVANIZED	☐ STEEL PANEL	☐ PLASTIC
☐ CONCRETE COATED		☑ POLYURETHANE	☐ OTHERS		

SIZE OF TANK			QUANTITY OF WATER		
M3	USG	L*B*H	☑ FULL	☐ HALF	☐ EMPTY

CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK AFTER CLEANING		
☐ CLEAN	☑ DIRTY	☐ VERY DIRTY	☑ CLEAN	☐ DIRTY	☐ VERY DIRTY
☐ BIOFILMS	☐ MOULDS	☐ SLIME	☐ BIOFILMS	☐ MOULDS	☐ SLIME
☐ SEDIMENTS	☐ MUD & SAND	☐ RUST	☐ SEDIMENTS	☐ MUD & SAND	☐ RUST

ACCESS	MANHOLE			
	☐ COVERED	☐ DAMAGED	☐ NA	

LADDER IN		LADDER OUT		LEAKS		DRAIN LINE		VALVES		FLOAT VALVE	
☐ YES	☑ NO	☐ YES	☑ NO	☐ YES	☑ NO	☐ YES	☑ NO	☑ YES	☐ NO	☑ YES	☐ NO

TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED		
☑ YES	☐ NO	☑ YES	☐ NO	☐ YES	☐ NO	☑ NA

LAST CLEANING DATE	CURRENT CLEANING DATE	NEXT CLEANING DATE
	15-07-2018	15-01-2019

CHEMICALS & EQUIPMENTS USED

1. CARELA BIO 8 PLUS — Quantity 300cc

2. _____ — Quantity _____

☑ Submersibel Pump ☑ High/Low Pressure Jet ☑ Extension Cords ☑ LED lights ☑ Foot Bath ☑ Ladder

☑ Ventilating Fan ☑ Suction/Discharge Hoses ☑ Oxygen Meter ☑ Vacuum Cleaner ☑ Cleaning Materials

COMMENTS & RECOMMENDATIONS:

TANK CLEANED AND DISINFECTED

Crystalline Representative: VETRIVEL — Signature:

Web: www.crystalline-uae.com
E-mail: info@crystalline-uae.com
Tel.: +971 55 7167017

CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT

15970

CUSTOMER: COFELY BESIX	CONTACT PERSON: MR. XAVIAR
SITE DETAILS: HCT MEN'S SCHOOL AL AIN	CONTACT NO: 0561883075
TANK DETAILS: SINTEX DOMESTIC TANK 05	LOCATION DETAILS: MCK BUILDING R.TOP

TYPE OF BUILDING: ☑ COMMERCIAL ☐ RESIDENTIAL ☐ OTHERS

TYPE OF TANK

☐ CONCRETE	☐ GRP PANEL	☐ FRP TANK	☐ GALVANIZED	☐ STEEL PANEL	☐ PLASTIC
☐ CONCRETE COATED		☑ POLYURETHANE	☐ OTHERS		

SIZE OF TANK			QUANTITY OF WATER		
M3	USG	L*B*H	☑ FULL	☐ HALF	☐ EMPTY

CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK AFTER CLEANING		
☐ CLEAN	☑ DIRTY	☐ VERY DIRTY	☑ CLEAN	☐ DIRTY	☐ VERY DIRTY
☐ BIOFILMS	☐ MOULDS	☐ SLIME	☐ BIOFILMS	☐ MOULDS	☐ SLIME
☐ SEDIMENTS	☐ MUD & SAND	☐ RUST	☐ SEDIMENTS	☐ MUD & SAND	☐ RUST

ACCESS	MANHOLE			
	☐ COVERED	☐ DAMAGED	☐ NA	

LADDER IN		LADDER OUT		LEAKS		DRAIN LINE		VALVES		FLOAT VALVE	
☐ YES	☑ NO	☐ YES	☑ NO	☐ YES	☑ NO	☐ YES	☑ NO	☑ YES	☐ NO	☑ YES	☐ NO

TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED		
☑ YES	☐ NO	☑ YES	☐ NO	☐ YES	☐ NO	☑ NA

LAST CLEANING DATE	CURRENT CLEANING DATE	NEXT CLEANING DATE
	15-07-2018	15-01-2019

CHEMICALS & EQUIPMENTS USED

1. CARELA BIO 8 PLUS Quantity 300 cc

2. _____ Quantity _____

☑ Submersibel Pump ☑ High/Low Pressure Jet ☑ Extension Cords ☑ LED lights ☑ Foot Bath ☑ Ladder

☑ Ventilating Fan ☑ Suction/Discharge Hoses ☑ Oxygen Meter ☑ Vacuum Cleaner ☑ Cleaning Materials

COMMENTS & RECOMMENDATIONS:

TANK CLEANED & DISINFECTED

Crystalline Representative: VETRALIST Signature:

Web: www.crystalline-uae.com
E-mail: info@crystalline-uae.com
Tel.: +971 55 7167017

CRYSTALLINE
ENVIRONMENTAL SERVICES

Date of Cleaning: 15-07-2018

PHOTOGRAPHS
ROOF TOP SINTEX WATER TANK - 04 & 05

BEFORE

SINTEX WATER TANK - 04



SINTEX WATER TANK - 05



AFTER





CLEANER WATER GREENER TOMORROW

CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT

15971

CUSTOMER: COFELY BESIX	CONTACT PERSON: MR. JANIAR
SITE DETAILS: HCT MEN'S SCHOOL AL AIN	CONTACT NO: 0561883075
TANK DETAILS: SINTEX DOMESTIC T. N.06	LOCATION DETAILS: CERT BUILDING R. TOP

TYPE OF BUILDING: ☑ COMMERCIAL ☐ RESIDENTIAL ☐ OTHERS

TYPE OF TANK

☐ CONCRETE	☐ GRP PANEL	☐ FRP TANK	☐ GALVANIZED	☐ STEEL PANEL	☐ PLASTIC
☐ CONCRETE COATED		☑ POLYURETHANE	☐ OTHERS		

SIZE OF TANK			QUANTITY OF WATER		
M3	USG	L*B*H	☐ FULL	☑ HALF	☐ EMPTY

CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK AFTER CLEANING		
☐ CLEAN	☑ DIRTY	☐ VERY DIRTY	☑ CLEAN	☐ DIRTY	☐ VERY DIRTY
☐ BIOFILMS	☐ MOULDS	☐ SLIME	☐ BIOFILMS	☐ MOULDS	☐ SLIME
☐ SEDIMENTS	☐ MUD & SAND	☐ RUST	☐ SEDIMENTS	☐ MUD & SAND	☐ RUST
ACCESS		**MANHOLE**	☐ COVERED	☐ DAMAGED	☐ NA

LADDER IN		LADDER OUT		LEAKS		DRAIN LINE		VALVES		FLOAT VALVE	
☐ YES	☑ NO	☐ YES	☑ NO	☐ YES	☑ NO	☐ YES	☑ NO	☑ YES	☐ NO	☑ YES	☐ NO

TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED		
☑ YES	☐ NO	☑ YES	☐ NO	☐ YES	☐ NO	☑ NA

LAST CLEANING DATE	CURRENT CLEANING DATE	NEXT CLEANING DATE
	15-07-2018	15-01-2019

CHEMICALS & EQUIPMENTS USED

1. CARELA BIO 8 PLUS — Quantity 200 cc

2. _____ — Quantity _____

☑ Submersibel Pump ☑ High/Low Pressure Jet ☑ Extension Cords ☑ LED lights ☑ Foot Bath ☑ Ladder

☑ Ventilating Fan ☑ Suction/Discharge Hoses ☑ Oxygen Meter ☑ Vacuum Cleaner ☑ Cleaning Materials

COMMENTS & RECOMMENDATIONS:

TANK CLEANED AND DISINFECTED

Crystalline Representative: VETRIVEL — Signature:

Web: www.crystalline-uae.com
E-mail: info@crystalline-uae.com
Tel.: +971 55 7167017

CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT

15972

CUSTOMER: COFELY BESIX	CONTACT PERSON: MR RAVIAR
SITE DETAILS: HCT MEN'S SCHOOL AL AIN	CONTACT NO: 0561883075
TANK DETAILS: SINTEX DOMESTEC T. 07	LOCATION DETAILS: CERT BUILDING ROOF TOP

TYPE OF BUILDING: ☑ COMMERCIAL ☐ RESIDENTIAL ☐ OTHERS

TYPE OF TANK

☐ CONCRETE	☐ GRP PANEL	☐ FRP TANK	☐ GALVANIZED	☐ STEEL PANEL	☐ PLASTIC
☐ CONCRETE COATED		☐ POLYURETHANE	☐ OTHERS		

SIZE OF TANK			QUANTITY OF WATER		
M3	USG	L*B*H	☐ FULL	☑ HALF	☐ EMPTY

CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK AFTER CLEANING		
☐ CLEAN	☑ DIRTY	☐ VERY DIRTY	☑ CLEAN	☐ DIRTY	☐ VERY DIRTY
☐ BIOFILMS	☐ MOULDS	☐ SLIME	☐ BIOFILMS	☐ MOULDS	☐ SLIME
☐ SEDIMENTS	☐ MUD & SAND	☐ RUST	☐ SEDIMENTS	☐ MUD & SAND	☐ RUST

ACCESS	MANHOLE			
	☐ COVERED	☐ DAMAGED	☐ NA	

LADDER IN		LADDER OUT		LEAKS		DRAIN LINE		VALVES		FLOAT VALVE	
☐ YES	☑ NO	☐ YES	☑ NO	☐ YES	☑ NO	☐ YES	☑ NO	☑ YES	☐ NO	☑ YES	☐ NO

TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED		
☑ YES	☐ NO	☑ YES	☐ NO	☐ YES	☐ NO	☑ NA

LAST CLEANING DATE	CURRENT CLEANING DATE	NEXT CLEANING DATE
	15-07-2018	15-01-2019

CHEMICALS & EQUIPMENTS USED

1. CARELA BIO 8 PLUS Quantity 300 ce

2. _____ Quantity _____

☑ Submersibel Pump ☑ High/Low Pressure Jet ☑ Extension Cords ☑ LED lights ☑ Foot Bath ☑ Ladder

☑ Ventilating Fan ☑ Suction/Discharge Hoses ☑ Oxygen Meter ☑ Vacuum Cleaner ☑ Cleaning Materials

COMMENTS & RECOMMENDATIONS:

TANK CLEANED & DISINFECTED

Crystalline Representative: VETALIST Signature:

Web: www.crystalline-uae.com
E-mail: info@crystalline-uae.com
Tel.: +971 55 7167017

CRYSTALLINE
ENVIRONMENTAL SERVICES

Date of Cleaning: 15-07-2018

PHOTOGRAPHS
ROOF TOP SINTEX WATER TANK - 06 & 07

BEFORE

SINTEX WATER TANK - 06

SINTEX WATER TANK - 07



AFTER





CLEANER WATER GREENER TOMORROW

CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT

15973

CUSTOMER: COFELY BESIX	CONTACT PERSON: MR. JAVIER
SITE DETAILS: ACT MEN'S SCHOOL AL AIN	CONTACT NO: 0561883077
TANK DETAILS: FIBER DOMESTIC TANK 8	LOCATION DETAILS: MOSQUE ROOF TOP

TYPE OF BUILDING: ☑ COMMERCIAL ☐ RESIDENTIAL ☐ OTHERS

TYPE OF TANK

☐ CONCRETE	☐ GRP PANEL	☐ FRP TANK	☑ GALVANIZED	☐ STEEL PANEL	☐ PLASTIC
☐ CONCRETE COATED		☐ POLYURETHANE	☐ OTHERS		

SIZE OF TANK			QUANTITY OF WATER		
M3	USG	L*B*H	☐ FULL	☑ HALF	☐ EMPTY

CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK AFTER CLEANING		
☐ CLEAN	☑ DIRTY	☐ VERY DIRTY	☑ CLEAN	☐ DIRTY	☐ VERY DIRTY
☐ BIOFILMS	☐ MOULDS	☐ SLIME	☐ BIOFILMS	☐ MOULDS	☐ SLIME
☐ SEDIMENTS	☐ MUD & SAND	☐ RUST	☐ SEDIMENTS	☐ MUD & SAND	☐ RUST

ACCESS	MANHOLE			
		☐ COVERED	☐ DAMAGED	☐ NA

LADDER IN		LADDER OUT		LEAKS		DRAIN LINE		VALVES		FLOAT VALVE	
☑ YES	☐ NO	☑ YES	☐ NO	☐ YES	☑ NO	☐ YES	☑ NO	☑ YES	☐ NO	☑ YES	☐ NO

TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED		
☑ YES	☐ NO	☑ YES	☐ NO	☐ YES	☐ NO	☑ NA

LAST CLEANING DATE	CURRENT CLEANING DATE	NEXT CLEANING DATE
	15-07-2018	15-01-2019

CHEMICALS & EQUIPMENTS USED

1. CHARELA BIO 8 PLUS Quantity 2000cc

2. _____ Quantity _____

☑ Submersibel Pump ☑ High/Low Pressure Jet ☑ Extension Cords ☑ LED lights ☑ Foot Bath ☑ Ladder

☑ Ventilating Fan ☑ Suction/Discharge Hoses ☑ Oxygen Meter ☑ Vacuum Cleaner ☑ Cleaning Materials

COMMENTS & RECOMMENDATIONS:

TANK CLEANED & DISINFECTED

Crystalline Representative: VETALIST	Signature:

Web: www.crystalline-uae.com
E-mail: info@crystalline-uae.com
Tel.: +971 55 7167017

CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT

15974

CUSTOMER: COFELY BESIX	CONTACT PERSON: MR. JAVIER
SITE DETAILS: HCT MENS SCHOOL ALAIN	CONTACT NO: 0561883075
TANK DETAILS: SINTEX DOMESTIC T. 09	LOCATION DETAILS: MAIN BUILDING ROOF TOP

TYPE OF BUILDING: ☑ COMMERCIAL ☐ RESIDENTIAL ☐ OTHERS

TYPE OF TANK

☐ CONCRETE	☐ GRP PANEL	☐ FRP TANK	☐ GALVANIZED	☐ STEEL PANEL	☐ PLASTIC
☐ CONCRETE COATED		☑ POLYURETHANE	☐ OTHERS		

SIZE OF TANK			QUANTITY OF WATER		
M3	USG	L*B*H	☑ FULL	☐ HALF	☐ EMPTY

CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK AFTER CLEANING		
☐ CLEAN	☑ DIRTY	☐ VERY DIRTY	☑ CLEAN	☐ DIRTY	☐ VERY DIRTY
☐ BIOFILMS	☐ MOULDS	☐ SLIME	☐ BIOFILMS	☐ MOULDS	☐ SLIME
☐ SEDIMENTS	☐ MUD & SAND	☐ RUST	☐ SEDIMENTS	☐ MUD & SAND	☐ RUST

ACCESS	MANHOLE			
		☐ COVERED	☐ DAMAGED	☐ NA

LADDER IN		LADDER OUT		LEAKS		DRAIN LINE		VALVES		FLOAT VALVE	
☑ YES	☐ NO	☑ YES	☐ NO	☐ YES	☑ NO	☐ YES	☑ NO	☑ YES	☐ NO	☑ YES	☐ NO

TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED		
☑ YES	☐ NO	☑ YES	☐ NO	☐ YES	☐ NO	☑ NA

LAST CLEANING DATE	CURRENT CLEANING DATE	NEXT CLEANING DATE
	15-07-2018	15-01-2019

CHEMICALS & EQUIPMENTS USED

1. CARELA BIO 8 PLUS — Quantity 300 cc

2. _____ — Quantity _____

☑ Submersibel Pump ☑ High/Low Pressure Jet ☑ Extension Cords ☑ LED lights ☑ Foot Bath ☑ Ladder

☑ Ventilating Fan ☑ Suction/Discharge Hoses ☑ Oxygen Meter ☑ Vacuum Cleaner ☑ Cleaning Materials

COMMENTS & RECOMMENDATIONS:

TANK CLEANED AND DISINFECTED

Crystalline Representative: VETRLIST	Signature:

Web: www.crystalline-uae.com
E-mail: info@crystalline-uae.com
Tel.: +971 55 7167017

CRYSTALLINE
ENVIRONMENTAL SERVICES

Date of Cleaning: 15-07-2018

PHOTOGRAPHS

ROOF TOP FIBER & SINTEX WATER TANK – 08 & 09

BEFORE

FIBER WATER TANK - 08



SINTEX WATER TANK - 09



AFTER





CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT

15975

CUSTOMER: COFELY BESIX	CONTACT PERSON: MR. JAVIAR
SITE DETAILS: HCT MEN'S SCHOOL AL AIN	CONTACT NO: 0561883075
TANK DETAILS: SINTEX DOMESTIC TANK 10	LOCATION DETAILS: MAIN BUILDING R. TOP

TYPE OF BUILDING: ☑ COMMERCIAL ☐ RESIDENTIAL ☐ OTHERS

TYPE OF TANK

☐ CONCRETE	☐ GRP PANEL	☐ FRP TANK	☐ GALVANIZED	☐ STEEL PANEL	☐ PLASTIC
☐ CONCRETE COATED		☑ POLYURETHANE	☐ OTHERS		

SIZE OF TANK			QUANTITY OF WATER		
M3	USG	L*B*H	☑ FULL	☐ HALF	☐ EMPTY

CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK AFTER CLEANING		
☐ CLEAN	☑ DIRTY	☐ VERY DIRTY	☑ CLEAN	☐ DIRTY	☐ VERY DIRTY
☐ BIOFILMS	☐ MOULDS	☐ SLIME	☐ BIOFILMS	☐ MOULDS	☐ SLIME
☐ SEDIMENTS	☐ MUD & SAND	☐ RUST	☐ SEDIMENTS	☐ MUD & SAND	☐ RUST

ACCESS	MANHOLE			
		☐ COVERED	☐ DAMAGED	☐ NA

LADDER IN		LADDER OUT		LEAKS		DRAIN LINE		VALVES		FLOAT VALVE	
☑ YES	☐ NO	☑ YES	☐ NO	☐ YES	☑ NO	☐ YES	☑ NO	☑ YES	☐ NO	☑ YES	☐ NO

TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED		
☑ YES	☐ NO	☑ YES	☐ NO	☐ YES	☐ NO	☑ NA

LAST CLEANING DATE	CURRENT CLEANING DATE	NEXT CLEANING DATE
	15-07-2018	05-01-2019

CHEMICALS & EQUIPMENTS USED

1. CARELA BIO 8 PLUS — Quantity 300 cc

2. _____ — Quantity _____

☑ Submersibel Pump ☑ High/Low Pressure Jet ☑ Extension Cords ☑ LED lights ☑ Foot Bath ☑ Ladder

☑ Ventilating Fan ☑ Suction/Discharge Hoses ☑ Oxygen Meter ☑ Vacuum Cleaner ☑ Cleaning Materials

COMMENTS & RECOMMENDATIONS:

TANK CLEANED & DISINFECTED

Crystalline Representative: VETALIST	Signature:

Web: www.crystalline-uae.com
E-mail: info@crystalline-uae.com
Tel.: +971 55 7167017

CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT

15976

CUSTOMER: COFELY BESIX	CONTACT PERSON: MR. JAVIAR
SITE DETAILS: HCT MEN'S SCHOOL AL AIN	CONTACT NO: 0561883075
TANK DETAILS: SINTEX DOMESTIC T.N.41	LOCATION DETAILS: MAIN BUILDING R. TOP

TYPE OF BUILDING: ☑ COMMERCIAL ☐ RESIDENTIAL ☐ OTHERS

TYPE OF TANK

☐ CONCRETE	☐ GRP PANEL	☐ FRP TANK	☐ GALVANIZED	☐ STEEL PANEL	☐ PLASTIC
☐ CONCRETE COATED		☑ POLYURETHANE	☐ OTHERS		

SIZE OF TANK			QUANTITY OF WATER		
M3	USG	L*B*H	☐ FULL	☐ HALF	☐ EMPTY

CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK AFTER CLEANING		
☐ CLEAN	☑ DIRTY	☐ VERY DIRTY	☑ CLEAN	☐ DIRTY	☐ VERY DIRTY
☐ BIOFILMS	☐ MOULDS	☐ SLIME	☐ BIOFILMS	☐ MOULDS	☐ SLIME
☐ SEDIMENTS	☐ MUD & SAND	☐ RUST	☐ SEDIMENTS	☐ MUD & SAND	☐ RUST

ACCESS	MANHOLE			
		☐ COVERED	☐ DAMAGED	☐ NA

LADDER IN		LADDER OUT		LEAKS		DRAIN LINE		VALVES		FLOAT VALVE	
☑ YES	☐ NO	☑ YES	☐ NO	☐ YES	☑ NO	☐ YES	☑ NO	☑ YES	☐ NO	☑ YES	☐ NO

TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED		
☑ YES	☐ NO	☑ YES	☐ NO	☐ YES	☐ NO	☑ NA

LAST CLEANING DATE	CURRENT CLEANING DATE	NEXT CLEANING DATE
	15-07-2018	15-07-2019

CHEMICALS & EQUIPMENTS USED

1. CHARLA BIO 8 PLUS — Quantity 200 cc

2. _____ — Quantity _____

☑ Submersibel Pump ☑ High/Low Pressure Jet ☑ Extension Cords ☑ LED lights ☑ Foot Bath ☑ Ladder

☑ Ventilating Fan ☑ Suction/Discharge Hoses ☑ Oxygen Meter ☑ Vacuum Cleaner ☑ Cleaning Materials

COMMENTS & RECOMMENDATIONS:

TANK CLEANED & DISINFECTED

Crystalline Representative: VETALIST — Signature:

Web: www.crystalline-uae.com
E-mail: info@crystalline-uae.com
Tel.: +971 55 7167017

CRYSTALLINE
ENVIRONMENTAL SERVICES

Date of Cleaning: 15-07-2018

PHOTOGRAPHS
ROOF TOP SINTEX WATER TANK - 10 & 11

BEFORE

SINTEX WATER TANK - 10



SINTEX WATER TANK - 11



AFTER





CLEANER WATER GREENER TOMORROW

CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT

15977

CUSTOMER: COTELY BESIX	CONTACT PERSON: MR. JAVIAR
SITE DETAILS: HCT MEN'S SCHOOL ALAIN	CONTACT NO: 0561883075
TANK DETAILS: SINTEX DOMESTIC T. 12	LOCATION DETAILS: MAIN BUILDING ROOF TOP

TYPE OF BUILDING: ☑ COMMERCIAL ☐ RESIDENTIAL ☐ OTHERS

TYPE OF TANK

☐ CONCRETE	☐ GRP PANEL	☐ FRP TANK	☐ GALVANIZED	☐ STEEL PANEL	☐ PLASTIC
☐ CONCRETE COATED		☑ POLYURETHANE	☐ OTHERS		

SIZE OF TANK			QUANTITY OF WATER		
M3	USG	L*B*H	☐ FULL	☑ HALF	☐ EMPTY

CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK AFTER CLEANING		
☐ CLEAN	☑ DIRTY	☐ VERY DIRTY	☑ CLEAN	☐ DIRTY	☐ VERY DIRTY
☐ BIOFILMS	☐ MOULDS	☐ SLIME	☐ BIOFILMS	☐ MOULDS	☐ SLIME
☐ SEDIMENTS	☐ MUD & SAND	☐ RUST	☐ SEDIMENTS	☐ MUD & SAND	☐ RUST

ACCESS	MANHOLE			
		☐ COVERED	☐ DAMAGED	☐ NA

LADDER IN		LADDER OUT		LEAKS		DRAIN LINE		VALVES		FLOAT VALVE	
☑ YES	☐ NO	☑ YES	☐ NO	☐ YES	☑ NO	☐ YES	☑ NO	☑ YES	☐ NO	☑ YES	☐ NO

TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED		
☑ YES	☐ NO	☑ YES	☐ NO	☐ YES	☐ NO	☑ NA

LAST CLEANING DATE	CURRENT CLEANING DATE	NEXT CLEANING DATE
	15-07-2018	15-01-2019

CHEMICALS & EQUIPMENTS USED

1. CARELA BIO 8 PLUS — Quantity 300 cc

2. _____ — Quantity _____

☑ Submersibel Pump ☑ High/Low Pressure Jet ☑ Extension Cords ☑ LED lights ☑ Foot Bath ☑ Ladder

☑ Ventilating Fan ☑ Suction/Discharge Hoses ☑ Oxygen Meter ☑ Vacuum Cleaner ☑ Cleaning Materials

COMMENTS & RECOMMENDATIONS:

TANK CLEANED AND DISINFECTED

Crystalline Representative: VETALIST — Signature:

Web: www.crystalline-uae.com
E-mail: info@crystalline-uae.com
Tel.: +971 55 7167017

CRYSTALLINE ENVIRONMENTAL SERVICES

WATER TANK - AFTER SERVICE REPORT

15978

CUSTOMER: COFELY BESIX	CONTACT PERSON: MR. JAVIAR
SITE DETAILS: HCT MEN'S SCHOOL AL AIN	CONTACT NO: 0561883075
TANK DETAILS: FIBER DOMESTIC TANK. 13	LOCATION DETAILS: SECURITY G. ROOF TOP

TYPE OF BUILDING: ☑ COMMERCIAL ☐ RESIDENTIAL ☐ OTHERS

TYPE OF TANK

☐ CONCRETE	☐ GRP PANEL	☐ FRP TANK	☑ GALVANIZED	☐ STEEL PANEL	☐ PLASTIC
☐ CONCRETE COATED		☐ POLYURETHANE	☐ OTHERS		

SIZE OF TANK			QUANTITY OF WATER		
M3	USG	L*B*H	☐ FULL	☑ HALF	☐ EMPTY

CONDITION OF WATER TANK BEFORE CLEANING			CONDITION OF WATER TANK AFTER CLEANING		
☐ CLEAN	☑ DIRTY	☐ VERY DIRTY	☑ CLEAN	☐ DIRTY	☐ VERY DIRTY
☐ BIOFILMS	☐ MOULDS	☐ SLIME	☐ BIOFILMS	☐ MOULDS	☐ SLIME
☐ SEDIMENTS	☐ MUD & SAND	☐ RUST	☐ SEDIMENTS	☐ MUD & SAND	☐ RUST

ACCESS	MANHOLE			
		☐ COVERED	☐ DAMAGED	☐ NA

LADDER IN		LADDER OUT		LEAKS		DRAIN LINE		VALVES		FLOAT VALVE	
☐ YES	☑ NO	☐ YES	☑ NO	☐ YES	☑ NO	☐ YES	☑ NO	☑ YES	☐ NO	☑ YES	☐ NO

TANK CLEANED		TANK DISINFECTED		PIPES DISINFECTED		
☑ YES	☐ NO	☑ YES	☐ NO	☐ YES	☐ NO	☑ NA

LAST CLEANING DATE	CURRENT CLEANING DATE	NEXT CLEANING DATE
	15-07-2018	15-01-2019

CHEMICALS & EQUIPMENTS USED

1. CARELA BIO 8 PLUS Quantity 200 cc

2. _____ Quantity _____

☑ Submersibel Pump ☑ High/Low Pressure Jet ☑ Extension Cords ☑ LED lights ☑ Foot Bath ☑ Ladder

☑ Ventilating Fan ☑ Suction/Discharge Hoses ☑ Oxygen Meter ☑ Vacuum Cleaner ☑ Cleaning Materials

COMMENTS & RECOMMENDATIONS:

TANK CLEANED AND DISINFECTED

Crystalline Representative: VETALIST Signature:

Web: www.crystalline-uae.com
E-mail: info@crystalline-uae.com
Tel.: +971 55 7167017

CRYSTALLINE
ENVIRONMENTAL SERVICES

Date of Cleaning: 15-07-2018

PHOTOGRAPHS
ROOF TOP SINTEX & FIBER WATER TANK - 12 & 13

BEFORE

SINTEX WATER TANK - 12



FIBER WATER TANK - 13



AFTER





CRYSTALLINE CLEANING & ENVIRONMENTAL SERVICES

CLEANING & DISINFECTION CERTIFICATE

POTABLE WATER TANKS

CLIENT NAME	: COFELY BESIX FACILITY MANAGEMENT.
CLIENT ADDRESS	: P.O. BOX: 43139, ABU DHABI, UAE.
CONTACT PERSON	: MR. ABDUL SALAM.
SITE DETAILS	: HCT – AL AIN MEN'S COLLEGE, AL AIN, UAE.
DETAILS	: WATER TANK CLEANING
DATE OF CLEANING	: JULY 2018
FREQUENCY OF CLEANING	: EVERY SIX MONTHS
DATE OF NEXT CLEANING	: JANUARY 2019

The procedures employed in this cleaning and disinfection comply with HS (G) 70 health and safety guidelines for prevention of legionella as well as BS6700 and CARELA BIO PLUS method statement.

The entire water storage tank should be cleaned and disinfected minimum every six (6) months depending upon the condition.

CRYSTALLINE CLEANING AND ENVIRONMENTAL SERVICES